DATE LABEL.

Department of Industries.

LIBRARY.

96.0 Aluminut 144,27 N.B.—Under the rules of the Library. Antimony •20.2 Argon this book is to be returned WITHIN 58.69 Arsenic 2 MONTHS from the date of Issue. 15 DAYS 14.008 Barium 190.8 Berylliuq 16.000 Bismuth 106.7 Boron Date of Date of Date of Date of 31.027 Bromine issue. issue. issue. issue. 195.23Cadmiun 39.096 Calcium 140.92 Carbon 225.95 Cerium 222. Cesium 102.91 Chlorine 85.44 Chromiu 101.7 Cobalt 150.43 Columbia 45.10 Copper 79.2Dysprosi 28.06 Erbium 107.880 Europius 22.997 Fluorine 87.63 Gadolini -32.064Gallium 181.5 Germani Gold 127.5 WBGP-51/2-10280E-1M 159.2 . Helluim 204:39 Holmiur 232.15Hydrogen 49 Tm69 169.4 Thulium Ιn 114.8, Indfuni 50 118.70 126.932 Tin Sn^{i} 53 Iodine Ι Ti∤ 22 48.1 Titanium 77 193.1 Iridium Ir W 74 184.0 26 55.84 Tungsten Iron Fe 238.17 U 92 Uranium 82.9 36 Kr Krypton ٧ 23 50,96 Vanadium 138.90 La 57 Lanthanum 130.2 Xe 54207.20 Xenon 82 Lead Pb 173.6 Yb 70 6.940 Ytterbium Li 3 Lithium 88.9 39 ·Y Yttrium 71 175.0 Lu Lutecium 65.38 30 Zinc $\mathbf{Z}\mathbf{n}$ 24.32 12 Magnesium Mg 91. 40 Zirconium · Manganese Mercury Mn. 25 54.93

80

Hg

200.61

THE

¹ NOTE BY THE EDITOR.—The Table of Atomic Weights as issued by the International Committee lists the elements alphabetically according to their symbols. It is rearranged arphabetically according to the names of the elements. The table does not include element No. 72, Hafnium or Celtium, atomic weight 180.8.

STANDARD METHODS OF CHEMICAL ANALYSIS

A Manual of Analytical Methods and General Reference for the Analytical Chemist and for the Advanced Student

EDITED BY

WILFRED W. SCOTT, Sc.D.

Professor of Analytical Chemistry, University of Southern California. Author of "Qualitative Chemical Analysis," "Technical Methods in Analysis of Metallurgical and Allied Products."

IN COLLABORATION WITH EMINENT SPECIALISTS

In Two Volumes, Illustrated

VOLUME ONE-THE ELEMENTS

FOURTH EDITION

Total Issue, Twelve Thousand



NEW YORK D. VAN NOSTRAND COMPANY

EIGHT WARREN STREET

1925

Copyright, 1917, 1922, 1925, by D. VAN NOSTRAND COMPANY

All rights reserved, including that of translation into the Scandinavian and other foreign languages.

THIS BOOK IS AFFECTIONATELY DEDICATED TO MY FATHER,

Ren. Thomas Jefferson Scott, B.D.



PREFACE TO THE FOURTH EDITION

In this fourth edition the writer and his colleagues have made changes throughout the work in presenting standar I methods that have been adopted as such by the American Chemical Society, by the American Society for Testing Materials, and other organizations conducting method investigations. The large amount of work done in this line since the publication of the last edition of Standard Methods has necessitated addition of considerable matter and the deletion of obsolete methods. To accomplish this work we have increased our staff from thirty-seven to fifty-two members.

The following brief survey takes up the more important additions and changes of the fourth edition—Dr. H. V. Churchill, Chief Chemist of the Aluminum Company of America, has contributed towards the chapter on Aluminum and has revised this section; Dr. W. R. Schoeller and A. R. Powell, authors of The Analysis of Minerals and Ores of the Rarer Elements, have rewritten the chapter on Cerium and the Rare Earths and have added a chapter on Indium, Thallium and Other Rare Elements; the writer has contributed a new method for the determination of Fluorine in the chapter on the subject and has added to the chapter on Iron, including the diphenylamine internal indicator method for dichromate titrations; the section on steel analysis has been largely transferred to a special chapter in Vol. 2; additional methods have been added to the chapter on Lead and the A.S.T.M. method for the analysis of pig lead has been included; in the chapter on Manganese, in addition to approved A.S.T.M. methods, we have included the bismuthate method as modified by R. W. Coltman and T. R. Cunningham, which makes this method applicable to large amounts of manganese as well as the minute amounts for which it was originally recommended; the thiocyanate method for mercury as recommended by A. H. Low has been included in the chapter on Mercury. Dr. Paul D. Mercia, Director xii PREFACE

of Research, and Mr. T. Fudge, Chief Chemist, The International Nickel Company, have contributed to the chapter on Nickel. Mr. L. E. Barton has contributed his paper on the subject of the determination of nitrogen in steel to the chapter on Nitrogen and has revised the chapter on Titanium. The writer has added to the chapter on Phosphorus and has rewritten a portion of this The chapters on Platinum, Palladium and the Rarer Elements of the Platinum Group have been carefully revised by Mr. R. E. Hickman and contributions made to this section by Edward Wichers, U. S. Bureau of Standards. The chapter on Radium, by Professor L. D. Roberts, has been placed in Volume 1. We are grateful to Dr. Victor Lenher, Head of the Analytical Department, University of Wisconsin, for the complete revision of the chapter on Selenium and Tellurium. Some attention has been given to the chapter on silver, a portion of this being rewritten and the U.S. Mints method being added, together with tables for rapid calculating of results, for which we are indebted to Mr. A. E. Moynahan, Chief Assayer, Denver Mint. A new chapter on the Fire Assay of Gold and Silver, by Professor Irving A. Palmer, follows the chapter on Silver. Mr. C. A. Newhall, Consulting Chemist, Seattle, Washington, has contributed several methods of the determination of Sulphur. The chapters on Thorium and Zirconium have been completely rewritten by Dr. H. M. P. Brinton, Head of the Division of Analytical Chemistry, University of Minnesota. All the chapters have been reviewed by their respective contributors and revised where necessary.

In Volume 2 some of the subject matter has been rearranged on account of the growth of certain sections to avoid repaging of the entire volume. The volume opens with the chapter on Sampling by Mr. J. B. Barnitt, Chief of Development Division, Aluminum Company of America, replacing the chapter on Acidimetry and Alkalimetry which has been placed in the latter portion of the volume. The writer has contributed a few pages on methods of decomposition of material for analysis. Mr. W. B. Price, author of Technical Analysis of Brass and Non-Ferrous Alloys, has completely rewritten the chapter on Alloys, adding a number of methods, approved as Standards by the American Society of Testing Materials. We are indebted to Dr. A. Campbell, President of the Globe Soap Company, for the latest Standard

method in the analysis of Soap and Soap Products; the chapter has been placed later in the volume owing to expansion. Mr. R. K. Meade has completely rewritten his chapter on Cement and has included the latest approved methods recommended by the American Engineering Standards Committee. The chapter on Paint and Paint Pigments has been revised by the authors-Mr. H. A. Gardner, Director of the Institute of Paint and Varnish Research, and Dr. J. A. Schaeffer, Vice-President and Chief Chemist, Eagle-Picher Lead Company. Professor A. H. Gill, Massachusetts Institute of Technology, has thoroughly revised his chapters on Fixed Oils, Fats and Waxes and Gas Analysis. Dr. G. A. Burrell and Mr. J. M. Morehead have contributed to the chapter on Gas Analysis. A number of new methods have been included in these sections. Mr. S. Collier, Chemist in Charge of the Rubber Laboratory, Waukegan Plant, Johns-Manville, Inc., and Chairman of the Committee on Revision of method for rubber analysis, has given us the latest American Standard Methods on this subject; Mr. L. E. Salas has presented the latest English procedures. has added a chapter on the Analysis of Iron and Steel and a chapter on Slag Analysis to the latter portion of the work. The methods adopted as Standards by the A.S.T.M. for analysis of Steel have been followed in the subject on Steel. The methods for Slag Analysis are largely those of the Anaconda Copper Company. The chapters on Water Analysis have been revised and portions rewritten by their authors Mr. D. K. French and Dr. F. E. Hale. Mr. H. Abraham has brought his chapter on Bituminous Substances to date. A new chapter on Standard Apparatus, by Mr. R. M. Meiklejohn, Chief Chemist, General Chemical Company, is included in Volume 2. Drs. G. L. Kelley and J. S. Coye have added to their chapter on Electrometric Titrations. A number of procedures, which could not well be classed under chapters mentioned, have been included by the writer in the Miscellaneous Chapter. The growth in the importance of Metallography in the analytical laboratory has induced us to include this subject in our work. The chapter is contributed by Mr. Joseph Winlock, Research Chemist, Edward G. Budd Mfg. Co., and includes the latest developments in the subject. chapter on Determination of Poisons has been added by Dr. Arthur R. Maas, Consulting Chemist, Los Angeles, California. Prof. R.

C. Beckstrom, head of the Department of Petroleum Engineering, Colorado School of Mines, has contributed a section dealing with certain chemical and physical tests of oil that are not included in Prof. Gill's chapter on oil analysis.

The excellent cooperation of the contributors to Standard Methods of Chemical Analysis has made this work possible. We have been ably supported by a staff of co-workers, who are recognized specialists in the subjects that they have presented. The names of a number of the staff have become familiar to us through their contributions to chemical literature. Some have published works that are considered standards in their special lines, and have received a wide circulation. It gives us considerable pleasure to offer to our chemical fraternity the reliable information of these men. We are also indebted to those who have called to our attention certain errors appearing in the third edition and those who have offered suggestions and criticisms of previous editions. We are grateful for all such suggestions and criticisms and will welcome these on the present edition. We realize that absolute perfection can not be expected, but in the fourth edition of Standard Methods of Chemical Analysis, we have made an effort to present what is considered thoroughly up to date and reliable.

WILFRED W. SCOTT.

University of Southern California, Los Angeles, California, August, 1925.

PREFACE TO FIRST EDITION

This book is a compilation of carefully selected methods of technical analysis that have proven of practical value to the professional chemist. The subjects have been presented with sufficient detail to enable one with an elementary knowledge of analytical processes to follow the directions; on the other hand, lengthy exposition, theoretical dissertation and experimental data are purposely avoided, in order to include a large amount of information in a compact, accessible form. References to original papers are given when deemed advisable.

For methodical arrangement the material is grouped under three major divisions—Part I. Quantitative determination of the elements. Part II. Special subjects. Part III. Tables of information.

In the first division the elements are generally taken up in their alphabetical order, each chapter being fairly complete in itself, cross-references being given to certain details included elsewhere to avoid repetition. For example, the complete directions for separation of the halogens are given in the chapter on chlorine, and references to these details are given in the chapters dealing with the other members of this group. Occasionally that been deemed advisable to place several related elements together in the same chapter.

Each chapter on the elements is generally arranged according to the following outline:

• Physical Properties. Atomic weight; specific gravity; melting-point; boiling-point; oxides.

Detection. Characteristic reactions leading to the recognition of the element.

Estimation. The subject is introduced with such information as is useful to the analyst.

Preparation and Solution of the Samples. Here directions are given for the preparation and decomposition of characteristic

materials in which the element occurs. Recommendations to the best procedures are included to assist the analyst in his choice.

Separations. This section is devoted to procedures for the removal of substances, commonly occurring with the element, that may interfere with its estimation. In the absence of such substances, or in case methods are to be followed by which a direct estimation of the element may be made in the presence of these substances, this section on separations may be omitted in the course of analysis. Here the discretion of the chemist is necessary, and some knowledge of the substance examined essential.

Methods. The procedures are grouped under gravimetric and volumetric methods. Several processes are generally given to afford the opportunity of selection for particular cases and for economical reasons where special reagents may not be available.

In many of the chapters methods for determining traces of the element are given, and the subjects are concluded by typical examples of complete analysis of substances containing the elements.

The titles to the procedures generally give a clue to the processes. Names of originators are occasionally retained where common usage makes the methods generally known by these.

Although the combined acid radicals are taken up with the elements to which they may be assigned, a chapter is devoted to the more important of the acids in their free state, and is placed with the other special subjects in the second division of the book. Here are found chapters on water, paint, oil, alloys, coal, cement, gas, and such subjects as are best classed in sections apart from simple substances dealt with in the first portion of the work.

The last portion of the book is devoted to tables of the more important arithmetical operations. These are designed to assist the analyst to greater accuracy of calculations, as well as to relieve him of needless expenditure of time and energy.

The material herein included has been carefully selected, an effort having been made to obtain the more trustworthy methods that will meet the general needs of technical chemists.

A list of the majority of publications consulted is given in alphabetical order in the appendix of this volume. Reference to these authorities will be found throughout the book.

W. W. Scott.

New York City, January, 1917.

CONTRIBUTORS TO VOLUME ONE

- Frank G. Breyer, A.B., A.M. Chief of Research Division, New Jersey Zinc Company. Author of a number of technical papers and numerous patents dealing with zinc, lithopone and allied industry. Contribution—Chapter on Zinc.
- Paul H. M. P. Brinton, B.S., M.S., Ph.D. Professor and Head of Division of Analytical Chemistry, University of Minnesota. Author of Analytical and Physical Inorganic Chemistry, Rare Elements and a number of technical papers. Contribution—Chapters on Thorium, Zirconium.
- H. V. Churchill, A.M. Chief Chemist, Aluminum Company of America, Pittsburgh, Pa. Contribution—Chapter on Aluminum.
- B. S. Clark, B.S. Research Chemist, American Can Company. Contribution—Chapter on Tin.
- Wallace G. Derby, A.M. Chemist and Assistant Superintendent, Wells and Richardson Company, Inc., Burlington, Vermont. Contribution— Chapters on Copper, Gold and Silver.
- T. Fudge, B.S. Chief Chemist, The International Nickel Company. Contribution—Chapter on Nickel.
- Harry D. Greenwood, B.S. Chief Chemist, U. S. Metals Refining Company, Carteret, N. J. Author of technical papers. Contribution Chapter on Selenium and Tellurium.
- R. E. Hickman, B.S. Chief Chemist, J. Bishop and Company Platinum Works. Contribution—Chapters on Platinum; Palladium; Rarer Elements of the Allied Platinum Metals.
- William B. Hicks, A.B., A.M., Ph.D. Chief of Analytical Department, Solvay Process Company, Syracuse, N. Y. Author of a number of technical papers on mineralogy; potassium; muds; action of salt solution on clay filters, etc. Contribution—Chapter on Sodium, Potassium and Other Alkalies.
- James A. Holladay. Chief Chemist, Electro Metallurgical Company. Author of technical papers. Advisory Editor. Contribution Chapters on Molybdenum and Tungsten.
- L.S. Holstein, A.M. New Jersey Zinc Company, New York. Contribution—Chapter on Zinc.
- Victor Lenher, Ph.D. Professor of Chemistry, University of Wisconsin. Former chairman of Committee on National Research Council on the uses of selenium and tellurium. Author of Inorganic Chemistry; Rare Elements; Selenium; Tellurium; Rare Earths; Geochemistry, etc. Contribution—Chapter on Selenium and Tellurium.
- Albert H. Low, A.B., Sc.D. Professor of Chemistry, Colorado School of Mines. Author of Technical Methods of Orc Analysis and papers on metallurgical chemistry, analytical methods, poisonous minerals in water, azo colors in butter, etc. Contribution—Chapter on Uranium, and a number of methods in text.

- Paul D. Mercia, Ph.D. Director of Research, The International Nickel Company. Author of Metallography and Physical Chemistry of Ferrous and Non-Ferrous Alloys and Metals. Contribution—Chapter on Nickel.
- John J. Mulligan, B.S. Superintendent, U. S. S. Lead Refinery, Inc., East Chicago, Ind. Contribution--Chapter on Bismuth.
- Charles A. Newhall, B.Sc. Chemical Engineer, Scattle, Washington. Author—Growth of the Cement Industry; Strength of Highway Surfacing, etc. Advisory Editor. Contribution—Chapter on Sulphur.
- R. S. Owens, A.B. Consulting Chemist, New York City. Contribution—Chapter on Cerium.
- Irving A. Palmer, B.S., M.S. Professor of Metallurgy, Colorado School of Mines. Author of a number of papers on chemistry and metallurgy in various technical periodicals. Contribution—Chapter on Fire Assay of Gold and Silver.
- A. R. Powell, A.B. Metallurgical Chemist, London, England. Author of a number of technical papers, and "Analysis of Minerals and Ores of the Rarer Elements." Contribution—Chapter on Cerium and Rare Earths.
- Lewis D. Roberts, A.B., S.M. Associate Professor of Chemistry, Colorado School of Mines. Contribution—Chapter on Radium.
- W. L. Savell, Ph.D. Director and President, Savell, Sayer and Company, Inc. Author—Preparation of Metallic Cobalt from Oxides; Electroplating with Cobalt, etc. Contribution—Chapter on Cobalt and Nickel.
- W. R. Schoeller, Ph.D. Metallurgical Chemist, Daniell C. Griffeth and Company, London, England. Author of a number of scientific papers, The Analysis of Minerals and Ores of the Rarer Elements. Contribution— Chapters on Cerium and the Rare Earths, Thorium, Indium and Other Rare Elements.
- wilfred W. Scott, A.B., A.M., Sc.D. Professor of Analytical Chemistry, University of Southern California. Editor in Chief. Author of a number of technical papers on chemical research and chemical methods of analysis (see also title page). Contribution—A number of chapters throughout the book.
- S. Skowronski, B.S. Research Chemist, Raritan Copper Works, Perth Amboy, N. J. Advisory Editor. Contribution—Analytic Methods for Gold and Silver
- Albert M. Smoot. Technical Director, Ledoux and Company, New York City.

 Author of a number of technical papers on analytical methods. Advisory

 Editor. Contribution—Chapters on Molybdenum and Tungsten.
- L. A. Wilson, M.S. Chief of Testing Dept., New Jersey Zinc Company, Palmerton, Pa. Contribution—Chapter on Zinc; also chapter on Cad-
- Edward Wichers, Ph.D. Chemist, U. S. Bureau of Standards, Washington, D. C. Advisory Editor. Contributions—Chapters on Platinum and the Rarer Elements of the Allied Platinum Metals.

CONTENTS

VOL. I. THE ELEMENTS

ALUMINUM

Detection—with ammonium hydroxide, with sodium thiosulphate, alizarine S test, 3. Estimation, 3. Preparation and solution of the sample-general procedure for ores, sulphide ores, carbonate fusion, bisulphate fusion, solution of alloys, 3-5. Separation of aluminum from-silica, iron, phosphorie acid, chromium, manganese, cobalt, nickel, zinc, alkaline earths, alkalies, titanium, uranium, glueinum, 5, 6. Gravimetric methods -determination of aluminum by hydrolysis with animonium hydroxide; hydrolysis with sodium thiosulphate; precipitation as phosphate; precipitation as aluminum chloride, 10. Volumetrie methods-determination of combined alumina by alkali titration; free alumina or free acid in aluminum salts-potassium fluoride method, 11-13. Minute amounts of aluminum by Atack's Alizarine S method, 14. Bauxite analysis, 14, 15. Available alumina in bauxite and clays, aluminum in bronze, 16. Aluminum in iron and steel, other methods for aluminum, 17. Analysis of metallic aluminum, standard method of the Aluminum Company of America, 17a. Methods of the Aluminum Company of America for analysis of aluminum, aluminum alloys and ores, etc.; determination of silicon, fusion method, solution method; determination of iron, permanganate method, determination of copper, iodide phosphate method, determination of manganese, arsenite method, determination of zine, calcium and magnesium, 17a-17e. Analysis of silicon alloys, determination of silicon. Analysis of bauxite moisture, siliea, iron, titanium oxide, alumina, 17e-17g. Analysis of aluminum hydrate, loss on ignition, silica, iron oxide, sodium oxide, insoluble matter, 17h-17i. Analysis of calcined ore, bisulphate fusion method, preparation of sample, determination risilica, iron oxide-eupferron method, sodium oxide, loss on ignition, 17j-17k. Estimation of metallic aluminum in aluminum dust, 17l.

ANTIMONY

Detection—as sulphide, by hydrolysis, in minerals, traces; distinction between antimonous and antimonic salts, 18. Estimation, 19. Preparation and solution of the sample—sulphide ores, low grado oxides, speisses, slags, mattes, alloys, hard lead rubber goods, 19-21. Separations of antimony from—members of subsequent groups from mercury, copper, bismuth, cadmium, lead, arsenic and tin, 22-23. Gravimetric methods—determination as antimony trisulphide; as metal by electrolysis, 24, 25. Antimony in solder and in alloys with tin and lead, 25. Volumetric methods—determination with potassium bromate; with potassium iodide; by oxidation with iodine; permanganate method; indirect evolution method, 26-28a. Determination of antimony in brass, 28b. Determination of small amounts of antimony, Nichols Copper Company method; procedure for refined copper; determination of antimony in tartar emetic, 29-33.

ARSENIC

Detection—with hydrogen sulphide, volatility of arsenous chloride, traces; distinction between arsenates and arsenites, 34. Estimation, 34. Preparation and solution c the sample—pyrites ore, arseno-pyrites, arsenous oxide, arsenic acid, alkali arsenates arsenic in sulphuric acid, in hydrochloric acid, in organic matter; lead arsenate; zin arsenite; water soluble arsenic in insecticides; arsenic in mispickel; in iron; in copper 31-37. Separations—isolation of arsenic by distillation, Knorr's distillation method separation as sulphide from antimony and tin, etc., 37-40. Gravinetric methods—determination as trisulphide; as magnesium pyroarsenate, 41. Volumetric methods by oxidation with standard iodine; potassium iodate method; precipitation as silver arsenate, 44-45. Small amounts of arsenic by the Gutzeit method—in sulphuric, hydrochloric, and nitric acids; in iron, pyrites, cinders, bauxite, phosphates, phosphoric acid, salts, baking powder, organic matter, cauned goods, meats, etc., standard method of the General Chemical Company, 46-53. Marsh test for arsenic; analysis of commercial arsenic (As_2O_3), 53-55. Arsenic in iron and steel and in copper, 55.

BARIUM

Detection—as harium chromate, with ealcium sulphate or strontium sulphate, by precipitation as fluosilicate, flume test, spectrum, 56. Preparation and solution of the sample—ores, sulphates, sulphides, carbonates; salts soluble in water; organic matter; insoluble residue, 57. Separations—the alkaline earths; introductory, sources of loss, preliminary tests; separation from members of previous groups; separation of the alkaline earths from magnesium and the alkalies by the oxalate and sulphate methods; separation from phosphoric acid, 58–62. Gravimetric methods—determination as chromate; as sulphate; as carbonate, 63–64. Volumetric methods—titration of the barium salt solution with dichromate; reduction with ferrous salt and titration with permanganate; potassium iodide method; acid titration of the carbonate. Analysis of burytes and witherite; commercial valuation of the ores, 65–67.

BERYLLIUM (GLUCINUM)

Detection, 68. Estimation—occurrence, 68. Separations—removal of silica and of the hydrogen sulphide group, separation of glueinum from iron, manganese, zirconium, yttrium, aluminum, chromium, iron, 69. Gravimetric determination of glueinum, 69-69a. Other methods and notes, 69b.

BISMUTH

Detection—as bismuth oxychloride, and by reduction, 70. Estimation, 70. Preparation and solution of the sample—ores, einders; alloys, bearing metal, lead bullion and refined lead, 70–71. Separations from—members of the ammonium hydroxide, sulphide and carbonate groups and from the alkalies; separation from arsenic, antimony, tin, molybdenum, tellurium and selenium; mercury, lead, copper and cadmium, 72–73. Gravimetric methods—by precipitation and determination as the basic chloride, BioCl; as the oxide, Bi₂O₃, (a) by precipitation as the basic nitrate, (b) subcarbonate, (c) hydroxide, determination as bismuth sulphide, Bi₂S₃; as metallic bismuth by reduction with potassium cyanide; by deposition of the metal electrolytically, 73–76. Volumetric methods—by titration of the oxalate with permanganate; einehonine potassium iodide colorimetric method; hismuth iodide colorimetric comparison, 76–78. Bismuth in lead bullion, in alloys, ores, mattes, 78–80.

BORON

Detection—flame test, borax bead and turmeric tests, 81. Estimation, 81. Preparation and solution of the sample—boric acid in silicates and enamels; boronatro-calcite, borocalcite, boracite, calcium borate; borax and boric acid; boric acid in mineral water; in carbonates; in foods—milk, butter, meat, etc., 82-83. Gravimetric methods—distillation of methyl borate and fixation with lime, 84-85. Volumetric methods—titration of boric acid in presence of mannitol or glycerole in evaluation of borax or boric acid. Chapin's method. Robin's test for traces, 86-91.

BROMINE

Detection—by silver nitrate, by absorption in carbon tetrachloride or disulphide, by magenta test, bromates, 92. Estimation, 93. Preparation and solution of the sample—bromides, bromine in organic matter, 93. Separation of bromine from the heavy metals, from silver, cyanides, chlorine and iodine, 93–94. Gravimetric methods—precipitation as silver bromides, (1) hydrobromic acid and bromides of the alkaline earths and alkalies; (2) treatment in presence of heavy metals, 94. Volumetric methods—determination of free bromine with potassium iodide; soluble bromides by chlorine method, Volhard's method; traces of bromine, 94–96. Arsenous acid method for bromates, 96. Analysis of crude potassium bromide and commercial bromine, 96–97. Determination in mineral water; separation from iodine, 97.

CADMIUM

Detection—as sulphide, tube test, blowpipe tests, 99. Estimation, 99. Preparation and solution of the sample, 100. Separations from silica, arsenic, antimony, tin, bismuth, copper, mercury, zine, 100-101. Gravimetric methods—Procedure for ores; determination as sulphate, electrolytic method, 101-103. Volumetric method, 103.

CALCIUM

Detection—as oxalate, flame test, spectrum of calcium, 104. Estimation and occurrence, 104. Preparation and solution of the sample—limestone, dolomite, magnesite, cement, lime, gypsum, Plaster of Paris, sulphates, silicates, chlorides, nitrates and other water soluble salts, sulphides, pyrites ore, 105. Separation of ealcium from—silica, iron, alumina, copper, nickel, cobalt, manganese, zine, barium, strentium and the alkalies, treatment in presence of phosphates of iron and aluminum, decomposition of material, 105, 106. Gravimetric methods—precipitation as calcium oxalate; other methods, 107–108. Volumetric method by titration of the oxalate with standard potassium permanganate solution, 108. Precipitation from acetic acid solution, Builar's rapid iodine method, 108a. Available lime, 108. Methods for analysis of gypsum and gypsum products, 108b–108d.

CARBON

Detection—element, carbon dioxide in carbonates and in gas, free carbonic acid in water, distinction between carbonates and bicarbonates, carbon monoxide, 109. Estimation, 110. Preparation of the sample—iron, steel and alloys; organic matter; carbonates and bicarbonates, 110. Separation of carbon from other substances; separation from iron by the cupric potassium chloride method, 110-111. Gravimetric method—combustion furnaces, types of absorption apparatus, general procedure for determining carbon by combustion, 111-115. Graphitic carbon in iron and steel, 115-116. Combined carbon, 116-117. Determination of carbon in organic substances—organic

matter free of nitrogen, halogens, sulphur and the metals, 117; carbon and hydrogen in nitrogenous substances, 120; organic substances containing halogens, 120; wet combustion process, 120-121. Determination of carbon dioxide in carbonates—gravimetric; hydrometer method for carbonates, method for determining perborates, 121-127. Residual and available carbon dioxide in baking powder, 123-124. Determination of carbon dioxide by measuring the gas, 123 (126, reference). Determination by loss of weight, 124. Volumetric methods, total carbon by barium hydroxide absorption, 127. Direct colorimetric method for determining carbon in iron and steel, Bencker-Eggertz method, 127-130. Analysis of graphite, 130. Volumetric determination of hydrocyanic acid in soluble cyanides, Liebig's method, Volhard's method, determination of cyanide and thiocyanate, 131-133.

CERIUM AND THE OTHER RARE-EARTH METALS

Table of properties, minerals, qualitative tests, detection of cerium, 133–133b. Quantitative analysis, decomposition of minerals, separations—rare earths and thoria from other metals, separation from thoria, separation of cerium from rare earth metals, 134–135. Estimation of cerium—gravimetric and volumetric, 136. Estimation of other rare earths—estimation of the sum of the rare earths other than ceria, estimation of the cerium and yttrium group, estimation of the individual earths, 137. Technical methods—cerium in minerals, ceria in thoria and thorium nitrate, detection of didymium in cerium salts, 138.

CHLORINE

Detection-free chlorine, chlorides by silver nitrate test, free hydrochloric acid, detection of chlorine in presence of cyanate, cyanide, thiocyanate, bromide, iodide, chlorate. Test for hypochlorite, chlorite, chlorate, perchlorate, 142-143. Estimation -occurrence, 143. Preparation and solution of the sample-water-soluble chlorides, water-insoluble chlorides, silver chloride, chlorine in rocks, free chlorine, chlorine in ores and cinders, 143-144. Determination of halogens in organic compounds-Garius method, 145; lime method, 146; sodium peroxide method, 146. Separations-chlorine and the halides from the heavy metals, the halides from silver and silver cyanide; separation of the halides from one another, chlorine from iodine, and from bromine and iodine, 148. Gravimetric method-determination of chloride by precipitation as silver salt, 148a. Volumetric methods—silver thiocyanate ferric alum method of Volhard, silver chromate method of Mohr, volumetric method for determination of free chlorine, 149-151. Determination of hypochlorous acid in presence of chlorine, 151. Gravimetric method for determination of chloric acid, 152. Gravimetric determination of perchloric acid, 152. Determination of chlorates and perchlorates in presence of one another, 153. Determination of hydrochloric, chloric, and perchloric acids in presence of one another, 153. Estimation of chlorine, bromine and iodine in presence of each other, 154. Chloride and cyanide in a mixture, chloride, cyanide, thiocyanate in presence of each other, 154-155. Evaluation of bleaching powder, chloride of lime, for available chlorine, 155.

CHROMIUM

Detection—test with barium salt, hydrogen peroxide, reducing agents, ether, diphenyl carbazide, 156. Estimation, 156. Preparation and solution of the sample—general procedures for decomposition of refractory materials, special procedures—high silica ores, chrome iron ores, iron and steel, 157–158. Separations—chromium from iron and aluminum, 134. Gravimetric methods—precipitation of chromic hydroxide

and ignition to Cr₂O₃, determination as barium chromate, 159-160. Volumetric methods—potassium iodide method, procedure by reduction with ferrous salts, 161-162. Determination of small amounts of chromium, diphenyl-carbazide method, 162-163. Determination of chromium in soluble chromate; chromite, steel, 164. Dichromate-diphenylamine method for chromium in iron ores and alloys; Duboseq Colorimeter, chlorate method for chromium in steel, 164-165.

CORALT

Detection—general procedure, potassium sulphocyanate, potassium nitrite, 166. Estimation, 167. Preparation and solution of the sample—general procedure for ores, cobalt oxides, metallic cobalt, niekel and cobalt alloys, 167. Separations—annonium sulphide group from hydrogen sulphide, ammonium sulphide group from the alkalies, cobalt and nickel from manganese, cobalt from nickel, cobalt from zime, 168. Gravimetric methods—precipitation of cobalt with potassium nitrite, nitrosobeta-naphthol method, electrolytic deposition of netallic cobalt, 169. Determination of cobalt in cobalt oxide, 171. Cobalt in the commercial metal and in ferrocobalt, 172. Cobalt in metallic nickel, 172. Cobalt in ores and in cnamels, 173. Determination of cobalt in steel, Dufty's sulphide pyrophosphate method, 174. Volumetric methods, 175.

COPPER

Detection-general procedure, flame test, wet tests, hydrogen sulphide test, other methods, 177. Estimation-ocentrence, 177. Preparation and solution of the samplesolubilities, decomposition of copper ores, sulphide ores, copper pyrites, copper glance, iron pyrites, matte, oxidized ores, oxides, treatment of matte slag, metals, iron ores and iron ore briquettes, steel, east iron and alloy steels, 178-181. Separations--precipitation of copper as sulphocyanate, separation of copper by precipitation in metallic form by a more positive element, separation from members of the ammonium sulphide and subsequent groups: removal of silver, removal of bismuth, lead, mercury, arsenic, antimony and tin; separation from cadmium, 181-182b. Gravimetric methodsdetermination as euprous sulphocyanate, determination as copper oxide. Deposition of metallic copper by electrolysis-introduction. Rapid methods-solenoid method of Heath, deposition from nitric acid solutioo, deposition from ammoniacal solution. Slow methods-electrolytic determination of copper in blister copper, standard proeedure of Nichols Copper Company, large portion and small portion methods, traces of copper in the electrolyte, notes and precantions for the electrolytic deposition of copper, 183-192. Volumetric methods for determining copper based on precipitation copper as cuprous thiocyanate-iodide methods, permanganate method, Demorest's method, Volhard's method, Garrigues' method, 193-196. Colorimetric determination of small amounts of copper-potassium ethyl xanthate method, ferrocyanide method, ammonia method, hydrogen sulphide method, 197-199. Determination of impurities in blister copper-bismuth, iron, lead, zinc, nickel, cobalt, arsenic, antimony, selenium, tellurium, oxygen, sulphur, phosphorus, 199-205. Determination of copper in refined copper, 205. Chlorinc in cement copper and copper orcs, 206. Copper in blue vitriol, 207. Copper and lead determination in brass, 207. Methods for determining the combinations of copper in ores and furnace products. The silver sulphate sulphuric method, phosphoric acid, ammonium chloride method, caustic soda sodium tartrate method, sulphuric acid mercury method, copper in brass, 208-211.

CONTENTS

FLUORINE

Detection—etching test, hanging drop test, black filter paper test, 212–214. Estimation—occurrence, 214. Preparation and solution of the sample—solubilities, organic substances, silicious ores and slags, calcium fluoride, soluble fluorides, hydrofluoric acid, fluorspar, 214–215. Separations—removal of silicic acid from fluorides, separation of hydrofluoric and phosphoric acids, separation of hydrofluoric from hydrochloric and loric acids, 215–216. Gravimetric methods—precipitation as calcium fluoride, as lead chlorofluoride, 216–217. Volumetric methods—Offernan's method, ferric chloride method, Steiger and Merwin colorimetric method, Scott's calcium acctate method for fluorine in fluorspar and alkali fluorides, 218–236. Valuation of fluorspar, standard method of the Fairview Fluorspar and Lead Company, 225. Analysis of sodium fluoride, 226. Determination of traces of fluorine, 227.

GOLD

Detection of gold in alloys, test for gold in minerals, benzidine acetate tests, phenylhydrazine acetate test, 228–229. Estimation—solubility, 229. Gravimetric methods—wet gold assay of minerals, electrolytic method, 230. Volumetric methods—permanganate and iodide methods, 231–232. Colorimetric methods—procedures of Prister, Cassel, Moir, 233–234. Preparation of proof gold, Furnace method—reference, 234–235.

INDIUM, SCANDIUM, THALLIUM

Occurrence, detection and quantitative analysis of indium, 139. Occurrence, detection and quantitative analysis of scandium, 140. Occurrence, detection and methods of separation and determination of thallium, 140b. Volumetric method, electrolytic method, uses, 141.

IODINE.

Detection—element, free iodine characteristics, iodide, iodate, 236. Estimation—occurrence, 236. Preparation and solution of the sample, iodides of silver, copper, mercury, lead, etc., iodates, free iodine (commercial crystals), iodine or iodides in water, organic substances, mineral phosphates, 236–237. Separations—iodine from heavy metals, from bromine or from chlorine, separation from chlorine and bromine—palladous iodide method, 238–239. Gravimetric methods—precipitation of silver iodide, determination as palladous iodide, 239. Volumetric methods—hydriodic acid and iodides by thiosulphate or by arsenite titration, decomposition by ferric salts, decomposition with potassium iodate, nitrous acid method of Fresenius, hydrogen peroxide—phosphoric acid method, chlorine method of Mohr, Volhard's method, 239–243. Determination of iodates, periodates, and iodates with periodates in a mixture, 244–245. Determination of iodine in mineral waters, 245.

TRON

Detection—ferric iron, hydrochloric acid solution, sulphocyanate, ferrocyanide, salicylic acid, sodium peroxide tests; distinction between ferrous and ferric salts, 246. Estimation—occurrence, 246. Preparation and solution of the sample—solubilities, soluble iron salts, sulphide and oxide ores, iron ore briquettes, silicates, iron and steel, separations—general procedure; special cases, ether method, 247–248. Gravimetric methods—determination as oxide, Fe₂O₃; Cupferron method, 249–250. Volumetric methods—general considerations, by oxidation, the iron having been reduced—titration with potassium dichromate, dichromate diphenylamine method for iron, 255.

Potassium permanganate, Jones reductor method, 251–257. Optional permanganate method, 257a. Permanganate method with diphenylamine—Scott, 257b. Titanous ehloride method for ferrie iron, 258. Stannous chloride method for determining ferrie iron, 260. Colorimetrie methods for determining small amounts of iron—with sulpric vanate, with salicylic acid, 260–261. Technical analysis of iron and steel—with specifications of Baldwin Locomotive Works. Introduction; preparation of the sample, combined or carbide carbon-colorimetric method, specifications for combined carbon; total carbon by combustion; graphite in iron; manganese hy persulphate method, lead oxide procedure of Deshey, method by U. S. Bureau of Standards—manganese by the bismuthate method; specifications for manganese; determination of phosphorus by the alkalimetric and molybdate methods; specifications for phosphorus; determination of sulphur by the evolution method; method by the U. S. Bureau of Standards; specifications for sulphur in iron and steel; determination of silicon, rapid foundry method, method by the U. S. Bureau of Standards; specifications for silicon in iron and steel, 263–270.

LEAD

Detection—hydrochloric acid test, hydrogen sulphide test, confirmations of tests, 271. Estimation—occurrence, 271. Preparation and solution of the sample—solubilities, decomposition of ores, minerals of lead, iron pyrites, alloys, 272. Separations—isolation of lead as sulphate, separation from barium, isolation as lead chloride, ammonium acetate extraction of lead from the impure sulphate, 273. Gravimetric methods—determination of lead as sulphate, as enromate, as molybdate, electrolytic determination as peroxide, PbO₂, 274–275b. Volumetric methods—ferrocyanide method, unolybdate method, chromate method, permanganate method of Low, colorinetric chromate method, 276–278. Determination of small amounts of lead—gravimetric methods—by ammonium acetate extraction, by occlusion with iron hydroxide, Seeker-Clayton method modified; colorimetric estimation, 281–285. Analysis of metallic lead, method of the National Load Company, modified, 286–290c. Determination of lead peroxide in minium, 290d.

MAGNESIUM

Detection—general procedure, test with baryta or lime water, 291. Estimation—occurrence, 291. Preparation and solution of the sample—solubilities, general procedure for ores, 292. Separations—removal of members of the hydrogen sulphide group, annonium sulphide group, separation from the alkaline earths, 292. Gravimetric determination by precipitation as ammonium magnesium phosphate, 293. Volumetric determination by titration of ammonium magnesium phosphate with standard acid, 294.

MANGANESE

Detection—general procedure, manganese in soils, mincrals, vegetables, etc., borax test, sodium carbonate and nitrate tests, 295. Estimation—occurrence, 295. Preparation and solution of the sample—solubilities, decomposition of ores, sulphides, slags, iron ores, alloys, manganese bronze, ferro-titanium alloy, ferro-chromium, metallic chromium, ferro-aluminum, vanadium alloys, molybdenum alloys, tungsten alloys, silicon alloys, iron, steel and pig iron, 296-297. Separations—removal of the members of the hydrogen sulphide group, separation of manganese from the alkaline carths and the alkalies, from nickel and cobalt; basic accetate method for removal of iron and aluminum, 298-300. Gravimetric method—isolation of manganese as the dioxide,

MnO₃, determination as manganese pyrophosphate, 300. Volumetric methods—Volhard's method, bismuthate method, manganese in ores, ferro-manganese, manganese metal, manganese sulphate standard, ammonium persulphate colorimetric method, oxidation of manganese with oxides of lead, William Ford's method, 301–306. Analysis of spiegel iron for manganese, Low's oxalate method for ores, 307.

MERCURY

Detection—general procedures, 308. Estimation—occurrence, 308. Preparation and solution of the sample—solubilities, decomposition of ores, 308–309. Separations—removal of mercury in presence of members of the ammonium sulphide, ammonium carbonate and soluble groups; separation of mercury from arsenic, antimony, tin, lead, bismuth, copper, cadmium, selenium, tellurium, organic substances, 309. Gravimetric methods—precipitation as sulphide, determination by electrolysis, Holloway-Eschka process, 310–312. Volumetric process by Scamon's method, thiocyanate method, 312. Thiocyanate method, 312a. Mercury in organic matter, 312b.

MOLYBDENUM

Detection—general procedure, sodium thiosulphate test, sulphur dioxide test, phosphate test, detection in minerals, characteristics of molybdenite, 313. Estimation—occurrence, 313. Preparation and solution of the sample—solubilities, decomposition of ores, steel and iron, 314. Separations—molybdenium from iron in presence of large amounts of iron, separation from the alkalies, alkaline earths, lead, copper, cadmium, bismuth, vanadium, arsenic, phosphoric acid, titanium and tungsten, 314–315. Gravimetric methods—precipitation as lead molybdate, determination as oxide, MoO₃, after precipitating with mercurous oxide, determination as sulphide, 316–317. Volumetric methods—iodometric reduction method, estimation by reduction with Jones reductor and subsequent permanganate titration, determination of molybdenum and vanadium in a mixture of the two. Determination of molybdenum in ores, 318–320. Determination of commonly occurring substances in molybdenum ores—arsenic, copper, phosphorus, 321–328.

NICKEL

Detection—general procedure, dimethylglyoxime test, alpha benzildioxime test, 329. Estimation, 330. Preparation and solution of the sample, solubilities, general procedure for decomposing ores, fusion methods, solution of metallic nickel and its alloys, 330–331. Separations—animonium sulphide group from hydrogen sulphide and from the alkaline earths and alkalies; separation of nickel from cobalt, manganese, zinc, iron, aluminum, chromium, 331–332. Gravimetric methods—precipitation of nickel by alpha benzildioxime, precipitation by dimethylglyoxime, electrolytic deposition of nickel, nickel in metallic nickel, in cobalt and cobalt oxide, 332–336. Volumetric determination of nickel in alloys, determination in nickel-plating solutions, 336. Method for nickel in steel, 336a. Ether-extraction-cyanide method, 336b. Methods of the International Nickel Company for determining impurities in nickel, 336e–336f.

NITROGEN

Detection—organic nitrogen, nitrogen in gas mixtures. Ammonia, free and combined, tests for. Nitric acid—ferrous sulphate test, diphenylamine test, copper test, phenolsulphonic acid test. Detection of nitrous acid—by acetic acid, by potassium permanganate, 337-338. Estimation—occurrence, composition of air; free nitrogen,

total nitrogen, combined nitrogen, 338-339. Preparation of the sample-organic substances-method in absence of nitrates, method in presence of nitrates; soilsavailable nitrate, ammonium salts, nitrates, nitrites, mixtures of ammonium salts, nitrates and nitrites; nitric acid in mixed acid, 339-341. Separations—ammonia, nitric acid, removal of nitrous, chromic, hydrobromic and hydriodic acids, 341-342. Procedures for the determination of combined nitrogen-ammonia-grayimetric determination of ammonia hy precipitation as ammonium platinochloride, 342. Volumetric methods-analysis of aqua ammonia, combined ammonia in ammonium salts; analysis of ammoniacal liquor-ammonia, carbon dioxide, hydrochloric acid, hydrogen sulphide, sulphuric acid; determination of traces of ammonia (ref.), 342-345. Nitric acid-gravimetric determination by precipitation as nitron nitrate, 345. Volumetric methods-direct estimation of nitrates by reduction to ammonia by the Allen-Devarda method, 346. Analysis of nitrate of soda—moisture, insoluble matter, sodium sulphate, iron, alumina, lime, magnesia, sodium chloride and carbonates, 349-350. Nitric nitrogen in soil extracts by Vamari-Mitscherlich-Devarda method, 350. Determination of hydroxyl amine, 351. Iodometric determination of nitrates, 352-353. Determination of nitrogen of nitrates and nitrites by means of the nitrometer—general procedure, duPont nitronicter method, 351-357. Determination of nitric acid in olcum by duPont nitrometer method, 357. Combined (reference to ferrous sulphate method) and free HNO₃, 357. Determination of nitrites. Bouvold's gravimetric method, permanganate volumetric method, 358. Detection of a nitrate in a nitrite salt, 359. Determination of pyridine in ammonium nitrate, nitrogen in steel, Barton's niethod, 358-361.

PHOSPHORUS

Detection—element, acids—hypophosphorous, phosphorous, orthophosphoric, metaphosphoric, pyrophosphoric, comparative table, 362–363. Estimation—occurrence, typical ores, 363. Preparation and solution of the sample—iron ores, phosphate rocks, minerals, iron and steel, cust iron, ferrous alloys, ores with titanium, soluble phosphates, baking powder, 364–365. Gravimetric methods—direct weighing of ammonium phosphomolybdate, determination as magnesium pyrophosphate; direct precipitation of magnesium ammonium phosphate, 366–367. Volumetric methods—by titration with an alkali, by titration of the reduced molybdate with potassium permanganate, 368–370. Special procedures for alloys, 370a–370b. Phosphate rock analysis—(tentative methods of the committee on standard methods), sampling and determination of moisture, phosphoric acid, iron and aluminum phosphates, iron, 371–375. Volumetric determination of free phosphoric acid, 375.

PLATINUM

Detection—general characteristics, tests with potassium iodide, hydrogen sulphide, ammonium chloride, potassium chloride, ferrous sulphate, stannous chloride, oxalic acid, sodium hydroxide with glycerine, formic acid, etc., 376–377. Estimation—characteristic substances containing platinum, 377. Preparation and solution of the sample—solubilities, decomposition of ores, platinum scrap, substances containing small amounts of platinum, 377–379. Separations—platinum from gold, from iridium, palladium, ruthenium, rhodium, osmium, 379–380. Gravimetric methods—weighing as metallic platinum, weighing as a salt, electrolytic method, 380–381.

Palladium.—Detection—tests with alkalies, ammonia, mercuric cyanide, potassium iodide, hydrogen sulphide, etc., 382-383. Estimation—Preparation and solution of the sample. Separations—palladium from platinum and iridium, from silver and gold,

383-384. Gravimetric methods, 384. Determination of platinum and palladium in gold bars, 385. Platinum and palladium in refined silver, in copper slimes and in gold bars, 386-388.

RARER ELEMENTS OF THE ALLIED PLATINUM METALS

Indicem.—Detection—tests with caustic alkalies, potassium chloride, ammonium chloride, hydrogen sulphide, metallic zine, formic and sulphurous acids, 388. Estimation—Preparation and solution of the sample, 389. Separations—iridium from platinum, 389. Gravimetric methods, reduction with zine, ignition of the ammonium salt, insoluble residue, 390. Method of Deville and Stas modified by Gilchrist, 390.

RUTHENIUM.—Detection—potassium hydroxide, hydrogen sulphide, ammonium sulphide, metallic zinc, 390b. Estimation—Preparation and solution of the sample. Separations—ruthenium from platinum, from iridium, from rhodium, 391. Gravimetric methods, 392.

Rhodium.—Detection—tests with hydrogen sulphide, potassium hydroxide, ammonium hydroxide, potassium nitrite, reducing agents, 393. Estimation—Preparation and solution of the sample. Separations—rhodium from platinum, from iridium, from ruthenium, 394. Gravimetric methods, 395b.

Osmium.—Detection—characteristics, tests with hydrogen sulphide, potassium hydroxide, ammonium hydroxide, reducing agents, 396. Estimation—Preparation and solution of the sample. Gravimetric methods, 397–398.

Assay Methods for Platinum Ores, 399.

Comparative reaction table, 400.

POTASSIUM, SODIUM AND OTHER ALKALIES

Detection-sodium, potassium, 401; lithium, rubidium and cæsium, 402-403, Estimation, 404. Solution of the sample-procedure for rocks and other insoluble mineral products, procedure for soils, fertilizers, organic compounds, ashes of plants, saline residues, soluble salts and brines, 404-405. Separations--alkali metals from other constituents-hydrogen sulphide and ammonium sulphide groups of metals; separation from silica; from iron, alumina, chromium, titanium, uranium, phosphorie acid; separation from sulphates; from barium, caleium, strontium; separation from iron, alumina, chromium, barium, calcium, strontium, phosphates, sulphates, etc., in one operation; separation from boric acid; separation from magnesium-mercuric oxide method, barium hydroxide method, ammonium phosphate method; separation of the alkali metals from one another-separation of sodium from potassium; lithium from sodium and potassium; lithium and sodium from potassium, rubidium and cæsium, 405-408. Methods for the determination of sodium—as sodium chloride, as sodium sulphate, difference method, 409-410. Methods for the determination of potassiumas chloroplatinate, modified ehloroplatinate method, Lindo-Gladding method, perchlorate method, other methods, 410-413. Determination of sodium and potassium by indirect method. Determination of magnesium, sodium and potassium in presence of one another, 413. Methods for determining lithium-determination as lithium chloride, as lithium sulphate, Gooch method, Rammelsberg method, spectroscopic method, 413-414. Determination of sodium, potassium, and lithium in the presence of one another. Determination of the alkalies in silicates by J. Lawrence Smith method, 416. Hydrofluoric method, 417. Alkalies in alunite, 417. Volumetric methods, 418.

RADIUM

General outline, 419. Detection, electroscope, 419. Estimation—alpha ray method, 420. Em mation method, 420. Gamma ray method, 426. Carbonate fusion, bisulphate fusion, other fusions, methods of testing, calculations, 420-429.

SELENIUM AND TELLURIUM

Detection—general procedure; detection of sclenium—tests with sulphuric and hydrochlorie acids, barium chloride, llydrogen sulphide, detection of tellurium-fusion test, tests with hydrogen sulphide, potassium iodide and reducing agents, 430-431. Estimation—occurrence of selenium and tellurium, 434. Preparation and solution of the sample, selenium and tellurium solubilities, decomposition of ores, 438. Separations—selenium and tellurium from the iron and zine group metals, from alkalies and alkaline earths, from cadmium, copper and bismuth, separation from silver and gold, separation of sclenium from tellurium by direct precipitation and by distillation methods, 432-434. Estimation—the two elements by the distillation of separation, 432-434. Gravimetric methods—determination of selenium by precipitation with sulphur dioxide, precipitation of tellurium by sulphur dioxide, potassium iodide reduction method, for determination as tellurium, 435-436. Quantitative methods for tellurium, hydrazine hydrochlorie-sulphur dioxide method, precipitation as dioxide, 437-438. Methods at refineries, 439. Commercial selenium, analysis of, 439. Sclenium in slines, flue dustglass, refined copper, etc., 439-440c. Volumetric methods-iodometric method for sclenic and telluric acids, 440d.

SILICON

Detection, 441. Estimation—occurrence—solubilities, 441–442. Preparation and solution of the sample—general considerations, preparation of the substance for decomposition, general procedure for decomposing the material, silicates not decomposed by acids—carbonate fusion, fluorides; special procedures for decomposing the sample—ferrosilicons, steels containing tungsten, chromium, vamadium and molybdenum; silicon carbide, carborundum; sulphides, iron pyrites, slags and roasted ores, 442–445, Procedure for determination of silicon and silica, 446. Analysis of silicate of soda. 447. Analysis of sand, commercial valuation, 448. Silicon in cast iron and steel, rapid method, standard method, 449. Silicon in ferro-silicon, 450.

SILVER

Detection—wet method, silver chloride, characteristics, sundry tests, 451. Estimation—preliminary considerations, solubility, furnace methods, 452. Gravimetric methods—determination as silver chloride, as eyanide, electrolytic method, 453–455. Volumetric methods—thiocyanate procedure of Volhard, Gay-Lussac method, U. S. Mint method; tables—combination methods, Denigé's cyanide method, miscellaneous volumetric methods, nephelometric method, 456–460. Preparation of pure silver, 463.

THE FIRE ASSAY FOR GOLD AND SILVER

Definitions—fire assaying, metallurgical products. General outline—reagents, furnaces and equipment, the assay—ton system, sampling, balances and weights, the crucible assay; lead reduction with oxidized ores, with sulphide ores; amount of litharge, of carbonate, of borax glass; assay slags, 466–475. Weighing and mixing the charge, fusing the charge, crucible charges, 475–477. The scorification assay, cupellation, parting, 477–481. The assay of bullion, 482. The assay of gold and silver bullion;

silver bullion or Doré bullion assay, lead ratio in cupellation; gold bullion assay, U. S. Mint method, 484-485. The assay of cyanide solutions, evaporation in lead tray, the Chiddey method, special method of assay. General outline, 486-488.

STRONTIUM

Detection—sodium sulphate test, flame test, spectra, 489. Estimation—occurrence and uses, 489. Preparation and solution of the sample—solubilities, 490. Separations—strontium from magnesium, alkalies, calcium and barium, 490. Gravimetric methods—determination as sulphate, carbonate, oxide, 491. Volumetric methods—alkalimetric, indirect method—chloride titration with silver nitrate, 491–492.

SULPHUR

Detection-element: sulphides, sulphites, sulphites; thiosulphates, 493. Estimation-occurrence-element, sulphur dioxide, hydrogen sulphide, sulphide ores, sulphate ores. Preliminary considerations, 494. Preparation and solution of the sample-solubilities-element, sulphide, sulphate, thiosulphate, sulphite; decomposition of sulphur ores; sulphur in coal by Eschka's method; sulphur in rocks, silicates and insoluble sulphates, barium and lead sulphates, 494-496. Separations-substances containing iron, separation of sulphur from metals forming an insoluble sulphate, nitrates and chlorates, silica, ammonium and alkali salts, 496-497. Gravimetric determination of sulphur-precipitation as barium sulphate, general considerations, precipitation from hot solutions, precipitation from cold solutions—large volume, standard method of the General Chemical Company, 497-500. Evolution method for sulphur in steel, ores, cinders, sulphides and metallurgical products, 500. Combustion method for evaluation of sulphide ores, 504. Volumetric methods for determining soluble sulphates—determination of sulphur by Wildenstein's method and by Hinman's method, Benzidine hydrochloride method, 505-507. Determination of persulphatesferrous sulphate and oxalic acid methods, 508. Determination of sulphur in combination as sulphides, sulphites, bisulphites, metabisulphites, thiosulphates, sulphatesavailable hydrogen sulphide in materials high in sulphide sulphur-iron sulphide, sodium sulphide, etc.; hydrogen sulphide and soluble sulphides; sulphide and sulphydrate in presence of each other; thiosulphate in presence of sulphide and sulphydrate; sulphates and sulphides in presence of one another; sulphur in thiocyanic acid and its salts; sulphurous acid free, or combined in sulphites, acid sulphites, metabisulphites and thiosulphates-gravimetric method by oxidation to sulphate and precipitation as barium sulphate, volumetrie methods-iodine titration, acidimetric and alkalimetric methods; determination of sulphites, metabisulphites, thiosulphates, sulphates, ehlorides, and carbonates in presence of one another, 509-515. Determination of hydrosulphites, 516. Determination of free sulphur in a mixture, 517. Evaluation of spent oxide for total, residual and available sulphur, 518. Analysis of brimstone and refined sulphurs, moisture, available sulphur, ash, arsenic, chlorine, Newhall's method for determining mineral and organic impurity, crystalline and amorphous sulphur, determination of fineness and specific volume of Degree Chaucel, 419-419b. Quantitative estimation of small amounts of sulphide sulphur, method of Drushel, 520.

THORIUM

Detection, 522. Estimation—occurrence, 523. Preparation and solution of the sample—monazite, thorianite, gas mantles, residues, ote., 522a. Separations from other elements, pyrophosphute method, thiosulphate method, 523-523b. Gravimetric method for determining thorium, 524.

TIN

Detection of tin, 525. Estimation—preparation of the sample, opening up tin ores—the cyanide process, sodium carbonate method, other methods—fusion with sodium hydrate, reduction by means of hydrogen, fusion with sodium peroxide, 419-527. Separations—general procedure, separation of tin from lead, copper, antimony, phosphorus, iron and alumina, tungstic acid, 527, 528. Gravimetric methods—determination of tin or the oxides of tin by hydrolysis, determination of tin as sulphide, 528, 529. Bichloride of tin—stannic acid method—hot water precipitation; Acker process method; determination as sulphide, 530, 532. Volumetric determination of tin—Lenssen's iodine method as modified by Baker, standard method of the American Can Company, 532. Electrolytic determination of tin, 536. Volumetric method for tin in alloys. Estimation of tin in canned food products, 536.

TITANIUM

Detection-tests with hydrogen peroxide, morphine, zinc, sulphur dioxide and by fusion with microcosmic salt, 538. Occurrence and application, 539. Preparation and solution of the sample--element, oxides, salts of titanium--general considerations -solution of steel, alloys, ores, titaniferous slags, 539, 540. Separations-titanium from the alkaline earths, etc.; separation from copper, zinc, aluminum, iron, manganese, nickel, cobalt, 541. Gravimetric methods—modified procedure of Gooch, 542. Determination of titanium in ferro-carbon titanium, 543. Volumetric methodsreduction of titanic solution, addition of ferric salt and titration of reduced iron with permanganate; reduction of titanic salt and titration with ferric salt, 544-545. Colorimetric determination of titanium with hydrogen peroxide; colorimetric determination in steel treated in ferro-carbon titanium, (a) determination of titanium insoluble in hydrochloric acid, (b) deterioination of titanium soluble in hydrochloric acid, (c) total titarium; determination in presence of interfering elements; colorimetric determination of titanium with thymol solution. Analysis of titaniferous ores-determination of titanium, silica, alumina, phosphorus. Standard methods of the Titanium Alloy Manufacturing Company, 545-553. Analysis of titanium pigments, 553.

TUNGSTEN, TANTALUM AND COLUMBIUM

Tunosten.—Detection—minerals, iron, steel and alloys, 554. Estimation—occurrence and uses, 555. Solution of the sample—solubilities, decomposition of ores, acids, minerals, steel and alloys, steel containing a high percentage of tungsten, ferrotungsten alloys, tungsten bronzes, 555-557. Separations—tungsten from silica, separation of tungsten from tin, antimony by Talbot's process, separation from arsenic and phosphorus, separation from nolybdenum by Hommel's process, volatilization of molybdenum with dry hydrochloric acid gas by Pechard's process; separation from vanadium, titanium, iron, 557-559. Gravimetric procedures—analysis of ores and concentrates, 559-573. Isolation of tungsten, 562. Volumetric method, 564. Determination of commonly occurring substances, 565; phosphorus, 565; sulphur, 565; arsenic, 566; tin, 567; copper, 569; manganese, 570. Analysis of tungsten metal and ferro-tungsten, 571-574. Determination of phosphorus, 571; sulphur, 573; silicon, 573; manganese, 574.

TANTALUM AND COLUMBIUM.—Detection, 575. Estimation—occurrence, application, 575. Solution of the sample—general procedure, tantaliferous minerals, 576. Separations—isolation of columbium and tantalum oxides; removal of tin, antimony, tungsten and silica, 576, 577. Determination of columbium and tantalum, 577.

URANIUM

Detection—general procedure—uranous salts, uranyl salts, 578. Estimation—occurrence, industrial application, 578. Preparation and solution of the sample—solubilities—element, oxide, salts; solution of ores, 579. Separations—uranium from copper, lead, bismuth, arsevic, antimony, and other members of the hydrogen sulphide group; separation of uranium from iron and from elements having water insoluble carbonates; separation from vanadium, 579–580. Gravimetric determinations of uranium as the oxide, U₅O₃, 581. Volumetric determination of uranium by reduction and subsequent oxidation, 581. Determination of uranium in carnotite, 582. Determination of uranium in steel and ferro-uranium, 582a.

VANADIUM

Detection-tests with sulphide, reducing agents, hydrogen peroxide, ammonium chloride, distinction from chromium, detection in steel, 583, 584. Estimation-oecurrence and industrial application, 584. Preparation and solution of the samplesolubility of the element, its oxides and salts; general procedure for decomposition of ores of vanadium, ores high in silica, products low in silica, iron, steel and alloys, 585, 586. Separations—general procedure, removal of arsenie, molybdenum, phosphoric acid, separation of vanadium from chromium, 586, 587. Gravimetric methods—determination of vanadium by precipitation with mercurous nitrate; by precipitation with lead acetate, 587, 588. Volumetric methods-reduction to vanadyl condition and oxidation with potassium permanganate, reduction with zinc followed by permanganate titration; determination of vanadium in steel; determination of molybdenum and vanadium in presence of one another; determination of vanadium, arsenic or antimony in presence of one another by Edgar's method; determination of vanadium and iron in presence of one another; iodometric method for estimation of chromic and vanadic acids in presence of one another; determination of vanadium in ferrovanadium, methods of the Vanadium Company of America—general procedure, vanadium in ores; in steel; in steel containing chromium; uses of vanadium in steel; in enpro-vanadium; in brasses and bronzes, 589-596. Volumetric-phospho-molybdate method, in mine and crude mill samples. Preparation of the Gooch crucible, 596a-596d.

ZINC

Detection of zinc, 597. Estimation, 597. Preparation of the sample-moisture determination in the pulp, 598. Separations—from silica, cadmium, arsenic, antimony, bismuth, copper, iron, alumina, manganese, nickel and cobalt, 598, 599. Methods of analysis-Gravimetric methods-weighing as the oxide, electrolytic procedure, 599. Volumetric methods—ferroeyanide titration of the acid solution, separating iron, aluminum and manganese with ammonia and bromine; titration of the alkaline solution --procedure for common ores; procedure for copper-bearing ores; procedure for material containing cadmium; for material containing carbonaceous matter; procedure for material containing metallics; general notes, 600-603. Standard method of the New Jersey Zine Company—titration in acid solution—separating of zine as sulphide; standardization of the ferrocyanide solution; procedure with material containing insoluble zine; discussion on separating zine as zine sulphide and titrating in acid solution, 603-607. Rapid method for the determination of zinc using an outside indicator of uranium salt, 607a-b. Determination of small amounts of zinc, 607. Special methods -determination of metallic zine in zine dust, 607. Precautions, 608. Determination of impurities in spelter; lead by electrolytic and "lead acid" methods; iron by colorimetric and hydrogen sulphide methods; eadmium by sulphide and electrolytic methods, 610-612. Analysis of zinc chloride solution, 614. Gravity, zinc, SO₃, iron, alumina, manganese, line, magnesia, alkalies, copper, barium, 614-616. Analysis of fused zinc chloride, 617. Annionia, 617.

ZIRCONIUM

Detection, 618. Estimation, 618. Preparation and solution of the sample—materials containing a large amount of silica, general method for minerals, oxides, etc., other methods, 619-620. Separations—from iron, titanium, thorium, carium, the iron group, 621. Gravimetric methods for the determination of zirconium by precipitation with eupferron, 622. By precipitation with selenious acid, and hy ammionium phosphate, 622a. Method for zirconium ores, 622b. Conditions of accuracy, 621. Zirconium in steel (ref.), 621.

PART II

QUALITATIVE TESTS OF SUBSTANCES

Blowpipe and flame tests of solids, 625–627. Microcosmic salt and borax bead tests, 627. Separation of the bases—Analysis of the solution, 628, 629. Tests for acids, 630. Tables of reactions of the bases, 632–645. Tables of reactions of the acids, 646–653. Solubility table, 654.

PART III

TABLES AND USEFUL DATA

I. Melting-points of chemical elements, 658. II, III. Temperature standards, 658. IV. Electromotive arrangement of the elements, 659. Specific Gravity Tables of THE ACIDS AND ALKALIES, 660-677. V. Hydrochloric acid—Ferguson, 660. VI. Hydrochloric acid—Lunge and Marchlewski, 662. Constant boiling-points, 662. VII, Nitric acid—Ferguson, 663. VIII. Nitric acid—Lunge and Rev. 665. IX. Phosphoric acid—Hager. 667. X. Sulphuric acid—Ferguson and Talbot, 668. XI. Sulphuric acid—Bishop, 672. XII. Acctic acid—Oudemans, 674. XIII. Meltingpoints of acetic acid-Rudorff, 674. XIV. Aqua ammonia-Ferguson, 674. XV. Sodium hydroxide-Lunge, 676. XVI. Vapor tension of water in milligrams of mercury, from -2° to +36° C.—Regnault, Broch and Weibe, 678. XVII. Useful data of the mere important inorganic compounds-Meiklejohn, 679. XVIII. Conversion factors -Scott and Meiklejohn, 685. XIX. Comparison of centigrade and Fahrenheit scale, 700. XX. Relation of Banmé degrees to specific gravity and the weight of one U. S. gallon at 60° F., 701. XXI. Comparison of customary units of weight and measure with the metric system, 702. XXII. Table of constants for certain gases and vapors, XXIII. Specific gravity of gases, 706.

Useful memoranda—conversion formulæ for gas volumes, petot formulæ for velocity of gas flow, other data, formulæ for calculating areas of plane figures—triangle, rectangle, parallelogram, trapezoid, circle. Formulæ for calculating volumes, regular prism, right circular cylinder, regular pyramid, right circular cone, sphere, capacity of barrel in gallons, 707. Definitions—terms used as heat units, electrical units, photometry—methods of determining specific gravity of solids and liquids, method of determining candle power, 708. du Pont inter conversion tables, volume, weight, energy, 710–712.

REAGENTS

This chapter includes the common rengents used in analytical procedures arranged alphabetically. The method of standardization is given for the more important solutions. The preparation of indicators is placed in the latter portion of the chapter, 725–746.

GENERAL REFERENCES

INDEA

LIST OF ILLUSTRATIONS

FIG.	PAGE
A1. Generator for Antimony Determination	. 29
1. Apparatus for Distillation of Arsenous Acid	. 39
2. Knors's Arsenic Distillation Apparatus	39a
3. Scott's Hydrogen Sulphide Generator	42
4. Urbasch's Hydrogen Sulphide Generator	43
5. Purification of Hydrochloric Acid	48
6. Gutzeit Apparatus for Arsenic Determination	52
6a. Apparatus for Fluorine Analysis	66b
7. Purification of Carbon Disulphide	75
8. Distillation of Methyl Borate	84
8a. Distillation Apparatus for Determining Boron	88
8b. Apparatus for Determining Bromine	98
8c. Cadmium Apparatus	102
9. Test for Carbonate	109
10. Chilled Steel Mortar	111
11. Geissler Bulb	112
12. Liebig Bulb	112
13. Gerhardt Bulb	112
14. Vanier Bulb	112
15. Fleming's Apparatus for Determination of Carbon by Combustion	113
16. Fleming's Absorption Apparatus	114
17. Boat and Holder for Carbon	116
18. Shimer Combustion Apparatus	116
18a. Stetser and Norton Combustion Train	117
19. Diagrammatic Sketch of Combustion Tube	
20. Apparatus for Determining Carbon Dioxide	122
21. Shroetter's Alkalimeter	124
22. Mohr's Alkalimeter	124
22a. Barker's Hydrometer	125
23, 24. Hot Water Racks for Test Tubes; Color Carbon Determination	128
25. Carbon Tubes	129
26. Color Comparitor or Camera	129
26a'. Electrolytic Analysis Cabinet	132b
26d. Colorimeter	164b
27. Terminal Case Showing Battery of Electrocks	185
28. Solenoid for Rotation of Electrolyte	187
29. Riffle Sampler	189
30. Constant Temperature Bath and Dividing Pipette	190
31. Hydrometer Jar for Electrolysis of Copper	191
32. Special Beaker for Electrolysis of Copper	205
32a. Combustion Furnace, Hinged Type	206
33. Etching Test for Fluorine	212
34. Hanging Drop Test for Fluorine	
35. Black Filter Paper Test for Fluorine	213
36. Adolph's Apparatus for Determining Fluorine	218

xxxvi LIST OF ILLUSTRATIONS

FIG.	PAG
37. Steiger-Merwin Fluorine-Titanium Chart	
38. Merwin's Chart on Ratio of Depth of Color.	
38a. Apparatus for Determing Traces of Fluorine	90
39. Apparatus for Determining Iodine in Iodide	046
40, 49. Jones' Reductor	010
40a. Apparatus for Storing and Using Titanous Salt.	, ore
41. Apparatus for Stannous Chloride Titration of Iron.	200
42. Dividing Pipette	200
43. Hurley's Colorimeter.	203
44. Cooper Hewitt's Mercury Light.	283
44a. Modified Form of Scott Volumeter for Testing Lead Pigments.	285
45. Bell Jar Vacuum Filtering Apparatus.	2901
46. Automatic Measuring Pipette.	303
47. Sulphur Extraction Apparatus.	303
48. Halloway-Eschka Apparatus for Determining Mercury	310
49a. Jones' Reductor	311
50. Apparatus for Determining Nitrogen, Kjeldahl Method.	320
51. Devarda's Apparatus Modified by Allen	340
52. Weighing Bottle and Dropper	347
53. Mitscherlich's Apparatus, Nitrogen in Soils.	348
53a. Davison Scrubber for Ammonia Determination	
53b. Apparatus for Determining Nitrates (Gooch & Gruener)	- - 353
54. Nitrometer	
55. Du Pont's Nitrometer.	255
55a. Apparatus for Determining Pyradine.	
55b. Evacuation and Weighing of Bulbs for Converter Efficiency in Ammonia	000
Oxidation	2614
56. J. Lawrence Smith Apparatus	416
56a, 56b, 56c, 56d, 56e, 56f. Apparatus for Determining Radium,	110
420, 421, 422, 423, 425,	427
57. Apparatus for Separation of Selenium and Tellurium	
58. Lead Cup for Silica Test	441
59. Apparatus for Determining Silver, Gay-Lussac Method	
59a'. A 5 cc. Pipette with 1 cc. Graduated	
59a. Oil Muffle Furnace	468
59b. Assay Furnace	469
59c. Assaying Outfit	
59d, 59e. Apparatus for Fire Assay	
59f. Assay Balances	
60. Evaporation in Sulphur Determination	499
61, 62. Apparatus for Precipitating Sulphur	499
63. Apparatus for Filtering Barium Sulphate	
64. Scott's Apparatus for Determining Sulphur in Iron and Steel	
65. Arrangement for Protecting the Crucible from the Flame	
65a. Apparatus for Determining Hydrosulphite	
66. Sanders' Extraction Apparatus	
66a. Sulphurimeter	
66b. Flowers of Sulphur	
66c. Rhombie Sulphur	519b

LIST OF ILLUSTRATIONS xxxvii FIG. PAGE 67. Seller's Apparatus for Determining Tin. 534 68. Seller's Apparatus, Diagrammatic Sketch. 535 68a. Apparatus for Determination of Tin. 536a 68b, 69, 70. Colorimeter. 545, 546, 548 71. Voit Flask and Distillation Apparatus. 593 71a. Gooch Filtering Apparatus. 596d 72, 73. Apparatus for Determining Zinc. 608, 609 74. Hydrogen Sulphide Generator. 732 PLATE I. Arsenic Stains, Gutzeit Method Facing page 52 PLATE II. Emissions Spectra. Pacing page 59 PLATE III. Diffraction Grating Spectrum and Prismatic Spectrum. Facing page 401

MOSOF IN

II (FR.19 27

VOLUME I

PART I

TECHNICAL METHODS FOR THE DETECTION AND DETERMINATION OF THE MORE IMPORTANT ELEMENTS

ALUMINUM 1

Al, at.wt. 26.96; sp.gr. 2.583; m.p. 658.7°; b.p. 2200°; oxide Al₂O₄.

DETECTION

General Procedure. The sample is prepared by one of the procedures outlined under "Preparation and Solution of the Sample." Silica is removed by taking the solution to dryness, boiling the residue with hydrochloric acid and filtering. The members of the hydrogen sulphide group are removed as usual with H₂S, the filtrate boiled to expel the excess of H₂S, iron oxidized with nitric acid, and aluminum, iron and chromium precipitated as hydroxides by addition of ammonium hydroxide in presence of ammonium chloride. On treating the precipitate with sodium peroxide, aluminum and ehromium hydroxides dissolve, whereas ferric hydroxide remains insoluble. Aluminum hydroxide is precipitated by acidifying the alkaline solution with hydrochlorie or nitric acid, and neutralizing with ammonia; chromium remains in solution.

Cobalt Nitrate Test. The white gelatinous precipitate of aluminum hydroxide may be confirmed by adding a drop of cobalt nitrate solution and burning the filter. The residue will be colored blue by the resulting aluminum

cobalt conmound.

Sodium Thiosulphate Test. Na₂S₂O₃, added to a neutral or slightly acid solution, containing aluminum, precipitates aluminum hydroxide, upon boiling the solution. Sodium sulphite, or ammonium chloride added in large excess, will also cause this precipitation.

Alizarin S Test. The reagent used is a 0.1% filtered solution of commercial alizarin S, the sodium salt of alizarin monosulphonic acid (yellow with acids,

purple with alkalics).

To 5 cc. of the neutral or acid solution under examination is added 1 ec. of the reagent, and then ammonia until the solution is alkaline, as shown by the nurple color. The solution is boiled for a few moments, allowed to eaol, and then acidified with dilute acetic acid, when red coloration or precipitate remaining is conclusive evidence of the presence of aluminum. The red calcium, strontium, barium, zinc and magnesium salts, and salts of other metals later than Group II are readily soluble in cold dilute acetic acid, and do not interfere with the coloration.

Phosphates or chromium do not interfere and comparatively large amounts of iron may be present (0.003 milligram Al in presence of 1 milligram ferric iron, 10 milligrams chromium salt). In presence of greater quantities of iron citric acid is added to keep this in solution. One part of aluminum may be detected in 10 million parts of water.

¹ Also spelled Aluminium.

By W. W. Scott and H. V. Churchill.

ESTIMATION

The determination of aluminum, in terms of alumina, Al_2O_3 , is required in the evaluation of aluminum ores, bauxite, $Al_2O(OH)_4$; diaspore, AlO(OH); alunite, $K_2O.3Al_2O_3.4SO_3.6H.O$, etc. It is determined in the analysis of feldspar, halloysite, clays, granite, gneiss, porphyry, mica schist, slate, obsidian or pumice stone, cryolite, limestone, and in the complete analysis of a large number of mineral substances. The estination of alumina is required in the analysis of cements, plaster, ceramic materials, aluminum salts, and is especially important in the control of processes in the manufacture of aluminum products. As a metal it is determined in commercial aluminum, and its alloys.

Preparation and Solution of the Sample

In dissolving substances containing aluminum it will be recalled that alumina, although ordinarily soluble in acids, is very difficult to dissolve when it is highly heated. It may be best dissolved, in this case, by fusion with sodium carbonate or with acid potassium sulphate, followed by an acid extraction. The metal is searcely acted upon by nitric acid, but is readily soluble in the halogen acids and in lot concentrated sulphuric acids.

General Procedure for Ores. One gram of the finely powdered ore, taken from a representative sample, is placed in a platinum dish, 5 cc. of concentrated sulphuric acid are added, followed by about 20 cc. of strong hydrofluoric acid. The mixture is evaporated over a steam bath as far as possible and then taken to SO, fumes on the hot plate (Hood). Upon cooling, a little dilute hydrochloric acid is added and the mixture warmed. The solution is diluted with distilled water and filtered if any residue remains.

The insoluble residue remaining on the filter may be brought into solution by fusing the ignited residue with sodium carbonate or acid potassium sulphate. If barium is present sodium carbonate fusion is made and the melt extracted with water to remove the sodium sulphate. The residual carbonates may now be dissolved with hydrochloric acid.

SULPHIDE ORES should be oxidized with nitric acid and bromine according to the general procedure for decomposing pyrites in the determination of sulphur.

The solution of the sample having been effected, aluminum is separated from elements that interfere in its estimation. Directions for the removal of these substances are given under "Separations." The element is now in solution in such form that it may be determined gravimetrically or volumetrically.

Fusion Method. Sodium Carbonate. The air-dried material, ground to a fine powder, is placed in a glass-stoppered bottle. If the determination is to be made on the dry basis, moisture is driven out by placing the material in the hot air or steam oven for an hour (100 to 110 °C.). One gram sample, placed in a large platinum erucible, is mixed with 4 to 5 grams of anhydrous sodium carbonate and the material heated to fusion, the heating being continued until the molten mass appears clear. The liquid mass may be poured on a large platinum crucible lid, or if preferred, allowed to cool in the crucible, a platinum prod being held in the fusion until it solidifies. By gently heating the crucible over a flame the fusion loosens from the sides and may be lifted out on the prod. In either case the cooled mass is dissolved by placing it, together with the crucible in which the

fusion was made in a casserole, and treating with hydrychloric acid, the casserole being covered with a clock glass during the reaction.

Silica is removed by evaporating the solution to dryness on the water or steam bath and drying in the oven at 110° C. for an hour or more. The residue is extracted with hot dilute hydrochloric acid and silica filtered off.

If the solution is cloudy upon treatment of the fusion with neid, it indicates either the presence of barium sulphate or incomplete decomposition of the sample. In the latter case the residue is gritty and the fusion of this material should be repeated.

Solution of Metallic Aluminum and its Alloys. The metal may be dissolved in dilute hydrochloric acid, 1:1, or in a solution of sodium hydroxide or potassium hydroxide.

Alloys of aluminum are best brought into solution with a mixture of hydrochlorie and nitric acids.

SEPARATIONS

General Considerations. In the usual course of analysis, aluminum is in solution as a sulphate or as a chloride, silica having been removed by dehydration, as described under "Preparation and Solution of the Sample." The following interfering elements may be present in the solution: iron, manganese, arsenie, antimony, titanium, phosphoric acid, and more rarely chromium and zirconium. In allovs of aluminum other elements may be added to this list. The separation more commonly required is from iron, aluminum and iron being precipitated together as the hydroxides. In usual practice the two are weighed together as Fe₂O₄ and Al₂O₄, after ignition to this form, and iron then determined, either on a separate portion of the sample, or by solution of the precipitate by fusion with sodium carbonate or potassium bisulphate and subsequent extraction with hydrochloric acid.

Removal of Silica. This compound has already been considered under 'Preparation and Solution of the Sample," SiO2 being removed by taking the solution to dryness, dehydrating the oxide by additional heating in the oven, followed by extraction of the soluble constituents with dilute hydrochloric acid and filtration. Under the first procedure for solution of the ore by sulphurie and hydrofluoric acids silica is expelled as gaseous SiF4.

Separation from Iron. 1. Aluminum hydroxide is precipitated by the addition of a salt of a weak acid to the neutral or slightly acid aluminum solution; iron remains in solution. Details of the procedure for precipitation of aluminum hydroxide by means of sodium thiosulphate are given under "Gravimetric Methods for Determination of Aluminum," page 9.

2. Aluminum chloride is precipitated from a concentrated solution of hydrochloric acid and ether saturated with HCl gas. Details of the procedure are given under the gravimetric methods for aluminum, page 10.

Note. The following additional procedures for separation of iron and alumina have been suggested:

(a) Precipitation of iron as FeS in presence of organic acids, citric, tartaric,

salicylic, etc., aluminum remaining in solution.

(b) Precipitating iron by adding sodium peroxide to a cold neutral solution of the elements until the precipitate first formed dissolves, then decomposing the sodium ferrate by boiling, Fe(OH), precipitates, Al remaining in solution. (Glaser, J. S. C. I., 1897, 936.)

(c) The neutral solution of the elements is boiled with freshly precipitated MnO. which causes the precipitation of iron as Fe(OH)3, while aluminum remains in

solution, (chrominm also passes into the filtrate).

(d) Precipitation of iron from acid solutions by means of amino-nitrosophenylhydroxylamine, (cupferron), aluminum remaining in solution. (O. Baudisch, Chem. Ztg., 83, 1298, 1905. Ibid., 35, 913, 1911; O. Baudisch and V. L. King, J. I. E. C., 3, 627, 1911).

(e) Precipitation of almomum (together with phosphoric acid, if present), by phenylhydrazine, added to the reduced, weakly acid or neutral solutions. Iron, cobalt, nickel, calcium, and magnesium remain in solution. (Hess and Campbell. C. N., lxxxi, 158. Engles, J. S. C. I., 1898, 796.)

(f) Electrolytic separation of iron by amalgamation with mercury cathode and

determining aluminum in the solution. (Kretzschmar, J. S. C. I., 1890, 1064; Kolin and Woodgate, J. S. C. I., 1889, 260.)

Phosphoric Acid. In presence of phosphoric acid, the phosphates of iron and alumina together with the phosphates of the other elements of the group and those of the alkaline earths will be precipitated upon making the solution alkaline with ammonia. Should iron and alumina be the only elements of these two groups present in the solution, they may be precipitated together as phosphates, iron determined by titration and calculated to the phosphate salt, and alumina obtained by difference. Occasionally, however, it is necessary to remove phosphoric acid.

Removal of Phosphoric Acid. The material is fused with about six times its weight of a mixture of 4 parts Na2CO2 and 1 part SiO2 (silex), and the melt extracted with water containing ammonium earbonate. Iron and aluminum remain on the filter, upon filtration, while sodium phosphate passes into solution. Both the precipitate and filtrate contain silica. The precipitate of iron and alumina is dissolved in hydrochloric acid and taken to dryness, the residue dehydrated as usual, then treated with dilute hydrochloric acid and silica filtered off. The solution contains iron and aluminum in form of chlorides.

Separation of Aluminum from Chromium. The solution is made strongly alkaline with sodium or potassium hydroxides and chromium oxidized by passing in chlorine gas or by adding bromine. The solution is now acidified with nitrie acid and aluminum hydroxide precipitated by addition of ammonium hydroxide, chromium remaining in solution as a chromate.

Separation of Aluminum from Manganese, Cobalt, Nickel, Zinc, the Alkaline Earths, and Alkalies. Iron and aluminum are precipitated as basic acctates, the other elements passing into solution. Details of the procedure arc given under the basic acctate method on page 298.

In absence of phosphates, these elements do not interfere in the determi-

nation of aluminum by precipitation as the hydroxide.

Separation of Aluminum from Titanium. Details of the procedure are given under "Titanium."

Separation of Aluminum from Uranium. Aluminum is precipitated as Al(OII), in presence of a large amount of ammonium salts by addition of a large excess of ammonium carbonate and ammonium sulphide, while uranium remains in solution as the complex compound UO3(CO3)3(NH4)4.

Separation from Glucinum. Aluminum is soluble in the fixed alkalics and remains in solution on boiling; glucinum also dissolves, but is precipitated on boiling. Glucinum is soluble in an excess of ammonium carbonate, aluminum is not.

For additional separations see chapter on element in question.

GRAVIMETRIC METHODS FOR THE DETERMINATION OF ALUMINUM

There are two general procedures for the gravimetric determination of aluminum. A. Direct determination, when it is possible to precipitate the hydroxide or phosphate of the element, free from impurities. B. Indirect determination when the element is precipitated and weighted along with iron, the latter then determined by titration and aluminum estimated by difference.

Determination by Hydrolysis of an Aluminum Salt with Ammonium Hydroxide

Principle. The method depends upon the hydrolysis of a soluble salt of aluminum by neutralizing the free and combined acid with ammonia. This hydrolysis takes place in presence of ammonium chloride, which prevents the precipitation of magnesium hydroxide by NII₄OH, the common ion, NII₄+, repressing the ionization of the base, NH₄OH. (See Notes.) The direct determination of aluminum by this procedure excludes the presence of elements undergoing hydrolysis with similar conditions. Iron, chromium, titanium, zirconium, thallium, cerium interfere. In their presence a separation must be made.

Reaction. AlCl₂+3NH₄OH = Al(OH)₄+3NH₄Cl.

If phosphoric acid is present in the solution aluminum will be precipitated as the phosphate, AIPO.

Procedure. To the solution, containing aluminum, free from phosphoric acid and the elements precipitated by ammonium hydroxide, are added 10 cc. of ammonium chloride (10%) and 5 cc. of concentrated nitric acid. The solution is diluted to about 150 cc. and heated to boiling. Upon cooling slightly, carbonate-free ammonium hydroxide is added slowly from a burette until a slight permanent precipitate forms, and then drop by drop until the solution reacts alkaline to litmus paper and the odor of ammonia is faintly perceptible. The precipitate is allowed to settle on the water bath for a few minutes, then filtered hot and washed first several times by decantation and finally on the filter with a hot solution of ammonium nitrate. (Twenty cc. strong nitric acid diluted and neutralized with ammonium hydroxide and made to 1000 cc.)

The precipitate is purified, if other members of the ammonium sulphide group and following groups are present, as the gelatinous precipitate is apt to oeclude some of these. This is accomplished by dissolving the precipitate in a small amount of hot, dilute hydrochloric acid, 1:1, the solution being eaught in the beaker in which the first precipitation was made. The precipitation of the hydroxide is repeated exactly as is stated above. The precipitate, washed free of chlorides (AgNO, test), is drained of water and placed together with the filter paper in a platinum erucible.

The ignition of the precipitate is conducted slowly at first until the paper is thoroughly charred, the heat is now increased to the full power of the Mcker blast, the crucible being covered to prevent mechanical loss. Blasting for thirty minutes is generally sufficient to dehydrate the oxide, Al₂O₄. It is advisable, however, to repeat the heating until the weight becomes constant. The residue is weighed as Al₂O₄.

 $Al_2O_4 \times 0.5303 = Al.$

Notes. Ammonia should be free from carbonates. Upon long standing with frequent exposure to air the ammonia takes up CO2, forming carbonate of ammonia. Freshly distilled ammonia will be pure, the carbonate being precipitated by addition of lime in the distilling flask. Ammonia is best kept in a ceresine or paraffine bottle. It will then remain free from siliea, which it invariably contains when confined in glass bottles.

Long heating of the mixture containing the aluminum precipitate is objectionable.

I. The solution is apt to become acid owing to the decomposition of ammonium salts and the volatilization of anunonia.

2. The precipitate will become slimy and will be difficult to wash and filter. It is preferable to redissolve and again precipitate if this condition occurs.

3. The C()2 of the air is apt to be absorbed by the solution, causing the precipitation of calcium enrhonate, etc., should the solution be exposed for any length of time.

4. Silica from the beaker will contaminate the precipitate.

Hence it is advisable to filter as soon as possible after making the precipitation

of Al(OH):

S. and S. No. 589, black band filter paper filters well and may be used to advantage with precipitates of the nature of aluminum hydroxide. B. and A. No. B. filter is also good.

Washing the precipitate with ammonium nitrate prevents the aluminum from passing through the filter and keeps it from packing. It favors the formation of the insoluble hydrogel form of the hydrate while preventing the formation of the soluble hydrosol. Ammonium chloride may be used in place of nitrate.

Aluminum hydroxide is soluble in acids and nikalies. The ignited oxide, Al₂O₃, is insoluble in acctic acid but is soluble in mineral acids and the fixed alkalies, It is rendered very difficultly soluble in acids by strong ignition, generally requiring fusion with sodium carbonate or potassium bisulphate with subsequent acid treatment to effect solution.

Al₃O₃, m.w., 102.2; sp.gr., 3.73 to 3.99; m.p., 2020° C.

A yellow or reddish precipitate indicates the presence of iron, an element frequently present with aluminum. Should this be the ease, iron must be determined by the case of mined, either in a separate portion of the sample, or in the residue obtained by the procedure outlined. The amour and Al₂O₄ obtained by difference. The amount of Fe₂O₂ is subtracted from the total residue,

If phosphoric acid is present the phosphate of alumina will precipitate together with the phosphates of elements insoluble in alkaline solutions. Should phosphoric acid be present either its removal is essential, or the phosphate method for alumina

should be followed.

Fluorides hinder the precipitation of aluminum.2 Evnporation to dryness and heating the residue to reduess will transform fluorides to oxides and overcome this

difficulty.

Sulphates tends to hold up aluminum from precipitation and a certain amount of sulphuric acid is occluded by the aluminum hydroxide precipitate. Magnesium is more apt to precipitate with alumina in presence of sulphates.* Anunonium chloride greatly lessens this difficulty.

Traces of alumina may be recovered from the filtrate by evaporation to dryness, ignition and resolution with IICl. The $Al(OH)_3$ is now precipitated with NH_4OH .

Since nluming absorbs moisture from the air, the crueible containing this compound

should be kept covered in a desiceator until weighed

Anmonium hydroxide, in presence of sufficient NH₄Cl, will not precipitate Mg(OH)₂, since the addition of NH₄Cl increases the ammonium ions in the solution and, by the common ion effect, represses the hydroxyl ions of the lone, NH₄OH, so that there are insufficient hydroxyl ions for the solubility product of Mg(OH)₂ to be exceeded; therefore magnesium remains in solution. A discussion of the theory of solubility product and law of mass action may be found in the nuthor's work on Qualitative Chemical Analysis, published by D. Van Nostrand Co. Reference is also made to Vol. I of The Elements of Qualitative Chemical Analysis, by Julius Stieglitz, publ. by the Century Co.

¹ W. Blum, Jour. Am. Chem. Soc., 38, 7, 1282, 1916. C. F. Sidener and Earl Pettijohn, Jour Ind. Eng. Chem. 8, 8, 714, Aug., 1916.

² E. P. Veiteh, Jour. Am. Chem. Soc., 22, 246, 1900. W. R. Bloor, ibid., 29, 1603, 1907. L. P. Curtman and H. Dubin, ibid., 34, 1485, 1912.

Determination of Aluminum by Hydrolysis, Neutralizing the Mineral Acid by Addition of a Salt of a Weak Acid. Sodium Thiosulphate Method

If a salt of a weak acid and strong base is added to a neutral or slightly acid solution of an aluminum salt containing a mineral acid, transposition takes place and aluminum is hydrolyzed.

Reaction. $2AICI_3+3Na_2S_2O_3+3H_2O=2AI(OII)_3+6NaCI+3SO_2+3S$.

Procedure. If the solution is acid, dilute ammonia is added until a precipitate forms that dissolves with difficulty, but not enough ammonium hydroxide to cause a permanent precipitation. The solution is diluted so that it contains about 0.1 g. Al per 200 ee., then an excess of sodium thiosulphate is added, and the solution is boiled free of SO₂. Al(OH), precipitates along with free sulphur. If iron is absent it is advisable to add a few drops of annionium hydroxide until the solution has a slight odor of annuonia. The mixture again boiled is filtered and the residue of Al(OH), and sulphur washed with hot water containing ammonium chloride or nitrate. The precipitate is dried, separated from the filter, the latter ignited and the ash added to the main precipitate. Alumina is now determined by blasting to constant weight, the residue being weighed as Al₂O₂.

Notes. The above method may be employed for separation of aluminum from iron, the addition of ammonia, following the neutralization of the unineral acid by thiosulphate being omitted. The precipitation of Al(OII), by this procedure gives a more dense and better filtering precipitate than does ammonia alone.

Note. G. Wynkoop suggests the use of sodium nitrite as the salt of a weak acid for neutralizing the mineral acid. (J. Am. Ch. Soc., 19, 434 (1897).

I. Ivanov recommends neutralizing the aluminum solution with sodium thiosulplute then diluting to 100 ee, and adding potassium iodide, followed by a 3% solution of KlO₃ and additional KI (10% sol.) until precipitation is complete. The excess of iodine is expelled by boiling. The Al(OII)₃ is filtered and washed with NH₄NO₃ sol. (2% sol.) and then ignited to Al₂O₃.

Precipitation of Aluminum as a Phosphate

Principle. This procedure, developed by Carnot, is of special value in determination of aluminum in iron and steel. It is founded on the reaction that aluminum is precipitated as the neutral phosphate, from a hoiling solution faintly acid with acetic acid. Iron, reduced to the ferrous condition by addition of sodium hyposulphite, does not interfere.

Procedure. A sample of 10 grams of iron or steel, in a platinum dish, covered with a piece of platinum foil, is dissolved by addition of hydrochloric acid. The solution is diluted to about 100 cc. and filtered into a flask, the residue of carbon, silica, etc., is washed thoroughly and the filtrate is neutralized by addition of ammonium hydroxide and ammonium carbonate; no permanent precipitate should form. A little sodium hyposulphite is added, and when the liquid, at first violet, becomes colorless, 2 or 3 cc. of a saturated solu-

E. Schum (Chem. Zeit., 1909, XXXIII, 877) recommends neutralizing the solution of aluminum with NH₄OH, just avoiding a precipitation of Al(OH)₃. After diluting to 250 ce. the aluminum is precipitated by adding 20 ce. of a 6% sol. NH₄NO₂. The oxides of nitrogen are expelled by boiling and the Al(OH)₂ settled on hot water bath 20 min. The sol. is decanted and the precipitate washed with neutral (2% sol.) ammonium nitrite and ignited as usual. The method is considered very accurate.

tion of sodium phosphate and 5 or 6 grams of sodium acetate, dissolved in solitile water, are added. The solution is boiled until free of sulphurous acid odor (about three-quarters of an hour). The solution is filtered off from the precipitated aluminum phosphate (mixed with a little silica and ferric phosphate) and washed with boiling water. The precipitate on the filter is treated with hot dilute hydrochloric acid the filtrate caught in a platinum dish, and then evaporated to dryness and heated at 110° C. for an hour to dehydrate silica. The residue is taken up with dilute hydrochloric acid and the solution filtered free of silica. Upon dilution to about 100 ec. with cold water, the solution is neutralized as before, a little hyposulphite is added to the cold solution and then a mixture of 2 grams of sodium hyposulphite and 2 grams of sodium acetate. The material is boiled for half an hour or more, filtered and the aluminum phosphate residue washed with hot water, then dried, ignited and weighed as aluminum phosphate. The residue contains 22.19% Al.

$AlPO_4 \times 0.2219 = Al$. $AlPO_4 \times 0.4185 = Al_2O_4$.

Note. Properties of AIPO₄, m.w., 122.14; sp.gr., 2.59; infusible, insoluble, in H₂O and in HC₂H₃O₃, soluble in mineral acids and in alkalies; white, amorphous salt.

Precipitation of Aluminum as Aluminum Chloride¹

Principle. Gooch and Havens found that aluminum chloride is practically insoluble in a mixture of concentrated hydrochloric acid and other saturated with HCl gas, 5 parts of AlCl_a.6ll_aO equivalent to 1 part of Al₂O₄ dissolving in 125,000 parts of the mixture. The method serves for a separation of aluminum from ron, berillium, zinc, copper, mercury and bismuth, the chlorides of these elements being soluble under the above conditions. Barium, however, is precipitated as a chloride with aluminum, if it is present in the solution.

Procedure. To the concentrated aqueous solution of aluminum is added a convenient volume of strong hydrochloric acid (15 to 25 cc.) and an equal volume of ether. The mixture is best placed in a large platinum crucible, which is kept cool in running water. HCl gas is passed into the solution to saturation. The precipitated chloride of aluminum is filtered upon asbestos in a weighed Gooch crucible and then washed with a mixture of ether and water 1:1, saturated with HCl gas. The precipitate is dried for half an hour at 150° C., then covered with a layer of C.P. Dercuric oxide (1 gram) and heated at first, gently over a low flame (hood) and then blasted to constant, weight. The residue is weighed as Al₂O₄.

Notes. HCl gas is generated by dropping strong sulphuric acid into concentrated hydrochloric acid according to the procedure described under the determination of arsenic by volatilization as arsenious chloride. The gas may be produced in a Kipp generator by the action of concentrated sulphuric acid on ammonium chloride.

The filtrate from aluminum contains iron, berillium, copper, zinc, etc., if these are present in the original solution. If much iron is present it is necessary to increase the amount of ether to prevent precipitation of the ferric salt.

¹ F. A. Gooch and F. S. Havens, Am. Jour. Sci. (4), 11, 416. F. A. Gooch "Methods in Chemical Analysis."

VOLUMETRIC METHODS FOR THE DETERMINATION OF ALUMINUM

Volumetric Determination of Combined Alumina in Aluminum Sulphate and Aluminum Salts

Introduction. Aluminum salts dissociate in hot solutions and react acid to phenolphthalein indicator; the acid readily combines with fixed alkalies, forming the neutral alkali salt. The end point of the reaction is indicated by the pink color produced upon phenolphthalcin by the excess of alkali. From the amount of caustic required the percentage of combined Al₂O₃ may be ealculated. The following reaction takes place:

$$Al_2(SO_4)_4+6NaOH=2Al(OH)_4+3Na_2SO_4$$

Procedure. The factor weight, 3.4067 grams, is dissolved in a 4-in. casserole with 100 ec. of distilled water, 1 ce. of phenolphthalein indicator added, and the sample titrated boiling hot 2 with N/2 NaOH, added from a chamber burette, graduated from 50 to 100 ec. in tenths of a ee.1 The solution is kept boiling during the titration and is constantly stirred. Towards the end of the reaction the alkali is added cautiously drop by drop until a permanent pink color is

Cc. of NaOH required divided by 4 = per cent combined Al₂O₃.² Combined Al₂O₃+free Al₂O₃ = total Al₃O₃.

Notes. If iron is present a correction must be made for it after determining the

ferrous and ferric forms as given below.

The amount of phenolphthalein indicator used should be the same in each determination. An excess of indicator causes low results. It has been noted in case of alums where iron does not interfere that best results are obtained with three or four drops of phenolphthalein solution. Iron tends to mask the end point, hence a larger amount of indicator is necessary if this is present.

Correction for Iron if Present. Since iron salts will also dissociate and titrate with aluminum salts, by this method a correction has to be made for iron if present. Total Al₂O₂ in presence of iron =

combined Al₂O₂-(FeO×.47+Fc₂O₂×.64)+basic Al₂O₂+an additive factor.

The additive factor is obtained by subtracting

(Combined Al₂O₂+basic Al₂O₂) - (FeO×.47+Fe₂O₂×.64) volumetrie. from total Al₂O₂ obtained by gravimetric analysis of an average sample,

Large samples must be taken for salts containing less than 13 per cent Al₂O₂ if

the chamber burette is to be used. E.g., potash alum twice this amount is advisable.

Otto Schmatolla, Berichte, xxxviii, No. 4. C. N., 91-2375-236 (1905).

If free acid is present (see next method), the equivalent volume in terms of 1 N acid must be deducted from the total titration for combined alumina before dividing by 4.

Ferrous Iron, Ferric Iron, and Total Iron A five-gram sample is dissolved in water and the iron oxidized with a few drops of strong potassium permanganate solution; the solution should be pink; the excess of permanganate is destroyed by a drop or so of normal oxalic acid solution and the total iron determined by stannous chloride solution method for iron. On a separate sample ferrie iron is determined. Ten grains of the sample are dissolved in an Erlenmeyer flask by boiling with hydrochloric acid, 2:1, in an atmosphere of CO, to prevent exidation, and the iron titrated with standard stannous chloride. The difference between total iron as Fc₂O₃ and ferrie oxide = ferrous iron in terms of Fe₂O₄. This multiplied by .9 = FeO.

Combined Sulphuric Acid

Provided no free acid is present, the per cent combined sulphuric acid in aluminum sulphate is obtained by multiplying the ec. caustic titration for total alumina by 0.72.

In case free acid is present, the per cent free acid deducted from total acid found by titration gives combined acid.

Sulphuric acid combined with the fixed alkalies is not titrated.

Determination of Free Alumina or Free Acid by the Potassium Fluoride Method

Introduction. The method suggested by T. J. I. Craig (J. S. C. I., 1911, 30, 185), has been modified by the author, after a personal investigation of the details involved. In this modified form it has been used successfully as a rapid works method. Frequent gravimetric cheeks on a large number of determinations have shown it to be accurate.

The procedure is based upon the fact that an excess of neutral potassium fluoride decomposes aluminum salts, forming two stable compounds, which react neutral to phenolphthalein, while the free acid remains unaltered, the following reaction taking place:

$Al_2(SO_4)_4 + 12KF + xII_2SO_4 = 2AlF_33KF + 3K_2SO_4 + xH_2SO_4$

The precipitate AIF3KF is insoluble in an excess of the potassium fluoride reagent and is not appreciably attacked by acids or alkalics. theoretically about 7 parts by weight of potassium fluoride is sufficient to combine with 1 part of aluminum sulphate, in practice it is advisable to use twice this amount.

Reagents Required. Half Normal solutions of sulphuric acid and potassium hydroxide.

Phenolpht haleln indicator, 0.1% alcoholic solution.

Potassium fluoride solution; made by dissolving 1000 grams of potassium fluoride Potassium nuoriae solution; made by dissolving 1000 grains of potassium fluoride in about 1200 cc. of hot, CO₂-free water, then neutralizing the solution with hydro-fluoric acid or potassium hydroxide as the reagent may require, using 5 cc. of phenolphthalein as indicator. Dilute sulphuric acid may be used in place of hydrofluoric acid in the final acid adjustment to get a neutral product. One cc. of the solution in 10 cc. of CO₂-free water should appear a faint pink. The concentrated mix is filtered if necessary and then diluted to 2000 cc. with CO₂-free water. The gravity will now be approximately 1.32 or about 35° Bé. One cc. contains 0.5 g. potassium fluoride.

¹ W. W. Scott, Jour. Ind. Eng. Chem., 7, 1059, 1915.

Method of Procedure

Solids. 3.4067 g. of the finely ground sample, or an equivalent amount in solution (100 cc. of sample containing 34.067 g. per liter), are taken for analysis The powder is dissolved by boiling with 100 cc. of distilled water in a 4-in-casserole with clock glass cover. To the hot solution 10 cc. of N/2 H₂SO₄ are added and after cooling to room temperature, 20° C., 18 to 20 cc. of the potassium fluoride reagent are added and 0.5 cc. of phenolphthalein. The solution is now titrated with N/2 KOH, added drop by drop until a delicate pink color, persisting for one minute, is obtained. This titration shows whether the product is basic or acid.

Basic Alumina. This is indicated when the alkali back-titration is less than the amount of acid added. Free Al₂O₃ = (cc. H₂SO₄ - cc. KOH) \div 4.

Free Acid. In case the back-titration of the alkali is greater than the ec. of acid added, free acid is present. Free acid = (cc. KOII - cc. 11_2 SO₄)×0.72.

Liquors. In works control it is necessary to test the concentrated liquors to ascertain whether these are basic or acidic. The Bé. or sp.gr. of the solution having been taken, 5 cc. is diluted to 100 cc. with distilled, CO₂-free water. If H₂S is present, it is expelled by boiling the solution, which should be acid, 10 cc. of N/2 H₂SO₄ is added, the solution cooled, and KF and phenolphthalein added and the titration made as in case of solids.

If basic (cc. H_2SO_4 —ee. $KOH)\times (.0245\times.3473\times100)\div (5\times sp.gr.)=Al_2O_4$. If acid (cc. KOH—cc. $H_2SO_4\times2.45)\div$ wt. of sample =per cent free acid (H_2SO_4). If neutral, the back titration of the alkali is the same as the cc. acid

Notes. CO₂-free water must always be used when phenolphthalein indicator is necessary. This may be obtained by boiling distilled water for several minutes to expel CO₂. This reagent is very sensitive to carbonic acid.

added.

If the sample does not dissolve clear, a prolonged digestion with previous addition of the required amount of standard acid, 10 cc., is advisable. This is best accomplished in an Earlanneyer flask with a return condenser.

Darkening of the solution during the back titration with the alkali, indicates that an insufficient amount of fluoride has been added. If this is the case it will be necessary to make a fresh determination.

The fluoride method has the following advantages. Determinations may be made by gas or electric light. The end point is easily detected. No neutral standard is necessary as in ease of the tint method.

Ammonium salts, if present, must be expelled by boiling the sample with an excess of standard KOH and this excess determined.

3.4067 = 2.45225 \times .3473 \times 4 (i.e. gins. H₂SO₄ per 100 ec. N/2 acid multiplied by 4 times factor to equivalent Al₂O₃). Derived directly from mol. wt. of Al₂O₃ = (.1022 \times 100 \times 4) \div (6. \times 2). 0.72 = 2.8792 \div 4 (i.e. factor Al₂O₃ to H₂SO₄+4).

The main details of the above volumetric procedures were worked out at the Laurel Hill Laboratory, General Clienical Company, and are published by courtesy of this company.

Colorimetric Estimation of Minute Amounts of Aluminum with Alizarin S. -- Atack's Method¹

Reagent. Sec page 3.

Procedure. The original solution (5 to 20 cc.) is acidified with hydrochloric or sulphuric acid. Ten cc. of glycerin and 5 cc. of a 0.1% solution of alizarin S are added, the solution made up to about 40 cc. with water (in presence of much iron or chronnum citric acid is added to form the double citrates) and then rendered slightly annuouiaeal. After standing for five minutes, the cold solution is acidified with dilute acetic acid, the alizarin S acting as indicator (red coloration) until no further change in the coloration occurs. The liquid is then made up to 50 cc. and compared with a standard. Suitable amounts of aluminum for estimation are 0.005 to 0.05 milligrams, the solution under examination being suitably diluted if necessary.

BAUXITE ANALYSIS²

Characteristic bauxites Arkansas Georgia	36%	SiO ₂ 6.4% 9~15	Fe ₂ O ₂ 1.43%	Al ₂ O ₂ 87,3%	TiO ₂ 3.99%
Tennessee	27.6	9~15 18.4	1-14 4.1	42-62	1.8-2.3

Sampling. The bauxite received in cars is sampled during the unloading according to the standard procedure for ores. If the sample is a composite aliquot parts of the total weights are taken and mixed, e.g., suppose three cars contained respectively 23,000, 32,500, and 26,340 pounds, then the aliquots would be 23, 32.5 and 26.34 pounds, which mixed, would make a representative sample of the shipment. The ore is broken down, quartered, ground down and again quartered. The moisture is determined on 1000 grams, dried in the oven at 100° C. for one hour, the sample being spread out on a sheet of manilla paper. The dried sample is placed in a large bottle for analysis.

Extraction of Ores of Aluminum for Their Commercial Valuation. Twenty-five grams of bauxite, alunite or clay, placed in an 600 cc. Kjeldahl flask with reflux condenser are digested for one hour with 60 cc. 10 N (48%) sulphuric acid. Time being taken when the mix begins to boil. The flame is so regulated that the water drips back into the flask from the condenser at the rate of 12 to 15 drops per minute. When the digestion is completed 150 cc. of hot water are introduced through the condenser. The mixture is now filtered using a Buchner funnel and suction. The residue is washed with six 100 cc. portions of water and the filtrate made up to 1000 cc. A 200 cc. aliquot is made up to 1000 cc. and 100 cc. of this taken for determination of alumina as stated on next page.

¹ F. W. Atack, Jour. Soc. Chem. Ind.; 34, 936 (1915); C. A. 9; 23; 3186 (1915).

² Bauxite and kaolin are two sources of alumina of commercial importance. The alumina of certain grades of clay, is made available for acid extraction by roasting at a definite temperature. 550°-700° C.

Insoluble Residue. The residue on the filter paper is ignited in a platinum dish over a low flame until the paper chars, and then over a good Meker blast for 15 to 20 minutes.

Weight of the residue × 4 = per cent insoluble residue.

Soluble Alumina. 100 cc. of the above solution (0.5 g.) is diluted with an equal volume of water, 10 cc. of hydrochloric and 2 cc. of nitric acids added and the solution boiled. Iron and alumina are now precipitated and determined in the usual way.

Soluble Iron. 200 cc. of the solution (1.0 g.), is oxidized by adding a few crystals of potassium chlorate and the solution taken to dryness. The residuc is taken up with 10 to 15 cc. of concentrated hydrochloric acid and again evaporated to dryness to expel chlorine. Then taken up with 25 cc. hydrochloric acid and the iron determined by titration. The stannous chloride method is used for samples containing less than 5% iron and the dichromate method for ores containing over 5%.

Determination of Total Silica, Titanium Oxide, Ferrie Oxide and Alumina

The method by the Aluminum Company of America is to digest 1 gram of the dried bauxite in 90 cc. of an acid mixture containing 12 parts of dilute sulphuric acid, 1:3, together with 6 parts of strong hydrochloric acid and 2 parts of nitric by volume, to this are added 10 cc. of concentrated sulphuric acid. The mixture is heated until sulphuric acid fumes are evolved, then diluted with water and filtered.

Silica. The residue is ignited and the ash fused with potassium bisulphate. The cooled fusion is taken up with 5 cc. sulphuric acid and 20 cc. of water and digested until only a white residue remains. This filtered off, washed and ignited = SiO₂.

Titanium Oxide. This is best determined colorometrically on a 0.1 gram sample according to the procedure outlined in the chapter on Titanium.

Iron and Alumina. These are determined by the usual procedure;—oxidation with potassium chlorate, precipitation with ammonium hydroxido and ignition. Iron may be determined in a separate sample (100 cc. = 0.5 g.) by titration. Al₂O₂ = difference between weighed oxides and Fc₂O₂, after subtracting TiO₂ if present.

VOLUMETRIC DETERMINATION OF THE AVAILABLE ALUMINA IN BAUXITE AND CLAYS1

This method is based on the solution of the sample in a known amount of sulphuric acid, and the titration of the excess acid with standard sodium hydroxide solution, and the alumina estimated from the amount of acid used to combine with it. It has been proven with long practice that this inethod is accurate within 0.5%, and is very satisfactory as a works control method. It is much more rapid than the regular gravimetric

procedure.

Take a five gram sample that has been ground to pass through a 60-mesh sieve and put it into a 300 cc. Kjedahl flask with about 28 to 30 grams of 40° B6 sulphuric acid, which is weighed from a weighing hurette. (This acid may be measured with a hurette and the weight calculated if so desired with a reasonable chance of error introduced.) Digest this at a gentle boil for one hour, giving the flask an occasional shaking. Care must be taken that good condensation is effected, otherwise a loss in acid will give high results. After the digestion wash down the condenser and filter the insoluble residue off on a Bucckner funnel with suction, washing the residue acid free. Make the filtrate up to 2000 cc. in a volumetric flask. To a 200-cc. aliquot add 20 cc. KF reagent, and 1 cc. phenolphthalcin indicator and titrate to a permanent pink with standard N/10 NaOH.

Reagents: The 40° acid must be made up very accurately and standardized against standard caustic.

1000 grains of potassium fluoride are dissolved in 1200 cc. of hot CO₂ free water, and then neutralized with HF or KOH as may be necessary, using phenolphthalein indicator. Filter this solution and dilute to 2000 cc. This solution should be kept in a wax-lined bottle.

Take 20 cc. of KF reagent and add 5 cc. of N/2 NaOH and one cc. of phenolphthalein indicator, and titrate with N/2 II₂SO₄. Apply this correction to the titration of the sample.

(cc. N/10
$$\text{H}_2\text{SO}_4$$
 – cc. N/10 NaOH) × .3473 × 100 = % Al_2O_3 + Fe_2O_3 weight of sample

% Fe₂O₂ × .64 = Fe₂O₃ equivalent to Al₂O₃ which can be subtracted from the total oxides above, the result being the available alumina.

Determination of Aluminum in Bronze. A sample weighing 0.5 to 1.0 g. is dissolved in 10 cc. of IINO₃ (2:1) and heated to expel nitrogen exides. 50 cc. of water are added and the precipitate allowed to settle (exide of Su, P₂O₃ and some Cu) and then filtered. The filtrate is treated with 5 cc. H₂SO₄ and evaporated to furnes, then then interest. The interest is treated with 3 ec. 11_250_4 and evaporated to turnes, the taken up with about 50 ec. of water and saturated with H_2S , and the precipitate filtered off. The filtrate containing the iron aluminum, zine, etc. is boiled to expel H_2S and oxidized by boiling with 5 cc. If NO_4 . Iron and aluminum are now precipitated as hydroxides by addition of NH_4OH and filtered off and washing as usual. Iron and aluminum are separated by dissolving the hydroxides in a little HCl and neutralizing the free acid with Na_2CO_3 solution. Any permanent precipitate is dissolved by a few drops of IICl. For each 0.1-0.2 g. of the metals present the solution is diluted to about arops of 1701. For each 0.1-0.2 g, or the means present the solution is access of $Na_5 S_1 O_3$ is added. Aluminum hydroxide is precipitated, iron remains in solution in the ferrous form. $2A|C|_1+3Na_5 S_1 O_3+3H_4 O=2A|(OH)_2+3SO_2+3S+6NaCl$. The $Al(OH)_3$ is filtered off and washed with hot water, then dried and the hydroxide and filter ignited separately, the ash of the paper added to the alumina and the ignition continued until a constant weight is obtained. An electric furnace of a Meker burner may be used to expel the combined water. Weigh as Al₂O₃.

> $Al_1O_1 \times 0.5303 = Al.$ 1 By Harold E. Martin.

DETERMINATION OF ALUMINUM IN IRON AND STEEL!,

The method is especially adapted for determination of aluminum in iron and steel, but may be extended to iron ores and materials high in iron.

Procedure. Solution. Ten grams of iron or steel are dissolved by adding about 50 cc. of hot hydrochloric acid, 1:1, preferably in a platinum dish, covered with a platinum foil.

Precipitation. When the solution of iron is complete, it is diluted to about 100 cc. and filtered free of carbon, silica, ctc. Two grams of sodium phosphate are added and the solution neutralized with ammonium hydroxide or carbonate, then cleared by hydroehloric acid with about 1 cc. excess. Twenty cc. of acetic acid are now added and the solution diluted to 300 to 400 cc. with hot water and, on boiling, 10 grams of sodium thiosulphate added. The solution is boiled free of sulphurous acid, (no odor of SO₂) about 20 to 30 minutes being necessary. The phosphate is filtered off and washed with hot water. It is again dissolved in a little hydrochloric acid and aluminum reprecipitated by neutralizing with ammonium hydroxide and adding about 1 gram of sodium phosphate together with 10 grams of sodium thiosulphate, following the above procedure. The precipitate will now be free of iron.

Ignition and Calculation. The precipitate and filter are ignited wet, first over a low flame, then gradually increasing the heat to full blast of a Mcker burner. The residue contains 22.19% Al or 41.85% of Al₂O₃.

Factor AlPO₄ to Al = .2219.

Factor AlPO to Al $_2$ O = .4185.

Notes. Interfering substances. Copper may be removed by H₂S. Other members of this group will also be eliminated.

Manganese and nickel are eliminated together with small amounts of iron at the second precipitation.

Titanium may be estimation colorimetrically or separated from alumina.

Vanadium, if present, may be separated according to directions given in the chapter on Vanadium.

Chromium is eliminated by fusion of the mixed phosphates with Na₂CO₃, extraction with water, and precipitation of aluminum phosphate by adding animonium acetate and sodium phosphate. Chromium remains in solution.

Other Methods. L. Belasio adds crystalline tartarie acid to hold up the precipitation of other netals that commonly interfere. I. Ivanov neutralizes the slightly acid solution of aluminum with Na₂S₂O₃, then dilutes to 100 ee. adds KI in excess, then a 3% sol. of KIO₃ with additional KI until precipitation is complete. The excess of iodine is expelled by loiling and the Al(OH)₃ washed with neutral 3% NH₄NO₄ sol. and ignited as usual, to Al₂O₃. E. Schum (Chem. Zeit., 32, 877, 1909) neutralizes the solution with NH₄OH just avoiding precipitation of Al(OH)₃. After dilution to 250 cc. 20 cc. 6% ammonium nitrite sol. are added, the solution boiled to expel NO₄, the Al(OH)₃ esttled 20 min. and filtered and washed with ammonium nitrite solution and the precipitate ignited as usual to Al₂O₃.

¹ Arnold and Ibbotson, "Steel Works Materials." Stillman, "Engineering Chemistry." "A Rapid Method for the Determination of Aluminum in Iron and Steel." C. N., 61, 313. "On the Determination of Minute Quantities of Al in Iron and Steel," J. E. Stead, J. S. C. I., 1889, 956.

ANALYSIS OF ALUMINUM AND ALUMINUM ALLOYS. METHODS OF THE ALUMINUM COMPANY OF AMERICA1

Determination of Silicon Fusion Method

In some eases a portion of the silicon in aluminum and its alloys is not oxidized when the metal is dissolved in acids. This is more frequently observed when the silicon is higher than regularly found as an impurity. It is made evident by a brown or dark gray film coating the liquid and container after dissolving the metal in acid mixture, and has been referred to as graphitic silicon. In such a case a fusion of the residue is needed to give a complete oxidation. A fusion is useful also for eleaning up residues contaminated with insoluble material other than SiO2.

Dissolve 1 gram of well-mixed drillings in 35 ec. of acid mixture No. 1 (450 cc. water, 150 cc. conc. H₂SO₄, 300 cc. conc. HCl, 100 cc. conc. HNO₃), using a 250-ee. flat bottom casserole or Pyrex beaker and cover glass. the drillings are completely dissolved, place on a moderately heated plate and boil the solution to dryness, then increase the heat till the H2SO4 distills as shown by flowing on the cover. Continue till a few drops have fallen from the center of the glass. This insures the complete removal of HCl and HNO₃ and the dehydration of SiO₂. These effects can also be secured by heating at the moderate temperature for an hour after boiling dry. Cool, add 10 cc. 1:3 H₂SO₄ and about 100 cc. water, boil to complete solution of the sulphate, filter, wash well and ignite in a platinum erucible.

Fuse the residue with 8 to 10 times its weight of Na₂CO₃ and treat the fused mass in a casserole or beaker with 20 cc. 1:3 H₂SO₄, washing out the erueible. Evaporate the solution until it fumes strongly to separate the SiO₂. Cool, dilute to about 100 cc., boil till the salts are dissolved, filter, wash well, ignite in a platinum crueible and weigh. Treat the ash with HF and a few drops

of H2SO4, evaporate till dry, ignite and weigh.

From the difference between the two weights deduct a blank obtained from the reagents and filter. The rest of the loss in weight represents SiO2 corresponding to the Si in the metal.

 $SiO_2 \times .4676 = Si$.

Solution Method

When only a small amount of silicon is present such as the few tenths per cent commonly found in commercial aluminum, it is practically all oxidized by the acid treatment, and a direct weight of the ignited insoluble residue considered as SiO, gives a measure of the original Si sufficiently accurate for general use.

Proceed as in the fusion method until the first insoluble residue has been filtered and washed. Ignite it in a crucible, allow to cool, brush the residue on the balance pan and weigh directly. Deduct a determined blank. Consider the remainder SiO₂ and calculate to Si as above.

¹ By courtesy of the Aluminum Company of America, E. Blough, Technical Director, H. V. Churchill, Chief Chemist.

Determination of Iron Permanganate Method

Cool the filtrate from the insoluble residue obtained in the determination of silicon. It should contain 3 to 5% H₂SO₄. Add KMnO₄ solution till a pink color persists. Reduce the iron present by passing the solution through a Jones reductor. See chapter on Iron. Titrate immediately with a solution of KMnO₄ of such strength that 1 cc. = .001 gram Fc. A blank, determined by carrying out the procedure without a sample, is deducted from each titration.

Cautions. (1) The KMnO₄ solution should not be permitted to come in contact with organic substances. It should be kept in a glass-stoppered bottle in a dark closet. Glass-stoppered burettes should be used.

- (2) Always have the iron solution cool before reduction.
- (3) There should be a solid column of solution or water passing during use. The zinc should be kept covered with water when not in use.
- (4) When the sample contains copper, the reductor will be kept cleaner if the copper is precipitated with a little granulated zinc, and the solution decanted from the precipitated copper before passing through the reductor.

Determination of Copper

Iodide Phosphate Method: Cu up to 1%

Dissolve 2 grams of well-mixed drillings in a tall 300-ce. beaker with 40 cc. of 25% caustie soda solution. When the aluminum is completely dissolved, dilute to 200 cc. with hot water that has been boiled. Allow the residue to settle, filter and wash thoroughly with hot water.

Using as small amount as possible of hot 1:1 nitric acid, completely dissolve the residue from filter paper into a 250-cc. wide mouth Erlenmeyer flask containing 0.1 cc. of concentrated sulphuric acid. If much manganese or iron is present, more concentrated sulphuric acid (about 0.5 cc.) should be used to prevent the formation of MnO_2 or Fe_2O_3 which will obscure the end point. Place the flask on a hot plate and evaporate to complete dryness. Cool. Add 25 cc. water and 3 cc. 99.5% acetic acid. Heat to complete solution.

Remove flask from hot plate, at the same time adding 5 cc. of a saturated solution of Na₂IIPO₄, shake thoroughly and cool in any convenient manner.

The ferric sulphate which later would react with potassium iodide thus:

$$Fe_2(SO_4)_3 + 2KI = 2FeSO_4 + K_2SO_4 + I_2$$

will be precipitated and rendered inactive by the reaction,

$$Fe_2(SO_4)_3 + 2Na_2HPO_4 = 2FePO_4 + 2NaHSO_4 + Na_2SO_4$$

To the cooled solution add 5 ec. potassium iodide solution (30 grams of potassium iodide to 100 cc. water) and shake thoroughly to mix solutions.

$$2Cu(C_2H_2O_2)_2+4KI=Cu_2I_2+4KC_2H_2O_2+I_2$$

Titrate the free iodine with a solution of sodium thiosulphate of 0.001 copper value which has been standardized by the copper sulphate method. A few drops of fresh starch solution, which is used as an indicator, are added near the end of the titration. This solution is prepared by dissolving 1 gram of soluble starch in 150 cc. of water.

Copper Percentage = No. of ec. Thiosulphate × Copper Value per ec. × 100 ÷ Weight of Sample (2 grams).

Note. In case the residue has not been carefully washed or when the iron content is high, an additional amount of Nu_2IIPO_4 may be required, and must be added until all iron and aluminum salts have been precipitated.

Determination of Manganese Sodium Arsenite Method: Mn up to 2%

Weigh out accurately a 0.2-grain sample and place in a 200-cc. Erlenmeyer flask. Add 15 cc. of acid mixture No. 2 (400 cc. conc. H₂SO₄—400 cc. conc. HNO₃—200 cc. H₂O). Place upon a hot plate and hoil until solution is complete. Add 5 cc. more of acid mixture No. 2 and boil for 2 or 3 minutes to drive off nitrous finnes. Remove from the source of heat, cool, add 10 cc. of AgNO₃ solution (3 grains per liter) and 90 cc. of warm water containing 1 gram of ammonium persulphate. Heat gently until the permanganic acid is fully developed as indicated by a ring of bubbles forming around the surface. Cool to room temperature and titrate with standard sodium arsenite solution, the approximate value of 1 cc. being equal to 0.0002 gram or 0.10% Mu.

If desired, the silver may be precipitated before titration by adding 5 cc. of NaCl solution (2 grams to 1 liter). The titration in standardizing must be done the same way as in working the samples.

Preparation of Standard Arsenite Solution

For standardizing the sodium ursenite solution for the determination of manganese a standard alloy of known manganese content must be used.

Procedure. (I) Stock Solution -stock solution is prepared by dissolving 10 grams As₂O₃ and 30 grams Nn₂CO₃ in a small amount of hot water, filtering and making up to 1000 cc.

(2) Standard Solution—the standard solution is prepared by taking required amount of stock solution (about 65 cc.) and diluting to 1000 cc. After 24 hours, this solution is carefully standardized by using it to titrate the manganese in the standard sample. Three determinations should be made using exact procedure as given above.

Note. (1) By adding the acid mixture in two portions it is made more certain that the proper amount is present when peroxidizing the manganese.

(2) When dissolving the sample it should not be allowed to go to dryness, as some manganese oxide might be made insoluble.

Determination of Zinc—0.50% or Less ZnO Method

Place 2 grams of sample in a 400-cc. beaker or easserole with 10 grams NaOH and 50 cc. water. When violent reaction is over, wash down and heat to near boiling till no more action can be seen. Add boiling water to make 200 cc. and bring to boil. Let settle, then filter. The filtrate is allowed to stand for several hours or is boiled a few minutes with about .5 gram Na₂O₂ to insure removal of manganese. If any precipitate forms, it is filtered out. 5 grams NaOH is added to the filtrate which is then heated to boiling and treated with H₂S for about 3 minutes. The solution is boiled for 10 minutes

and filtered through a dry double filter, keeping the filter full. Do not wash. The zine sulphide is then dissolved off the filter with warm dilute hydroehlorie acid (1:10) and the filter washed three times with hot water. The filtrate is boiled free from hydrogen sulphide, a few drops of bromine water are added to oxidize any iron present and the solution is made slightly alkaline with ammonia, boiled and filtered. Hydrogen sulphide is then passed into the filtrate until saturated. The solution is then boiled for ten minutes and filtered through a small filter without washing. The filter is burned at low temperature in a porcelain crucible. Dissolve the residue using HCl and transfer to a beaker. Make just ammoniaeal to methyl red, filter und wash. Add 10 drops of ammonia to the filtrate, heat solution to near boiling, saturate with 11₂S, filter, burn the paper and precipitate in a weighed porcelain crucible. Calculate the weight of zine oxide to zine.

 $ZnO \times 0.8034 = Zn$.

Determination of Calcium and Magnesium

Calcium: Permanganate Method

Place one grain of the alloy together with 5 grams of solid sodium or potassium hydrate in a porcelain dish and add just enough water to cover; when violent action has ceased, dilute to 200-250 cc, with hot water and boil nntil solution is complete. Filter while hot and wash the residue until free from alkali. The aluminum and most of the zine dissolve, while the other metals remain in the metallic state.

Using a few drops of nitrie acid and 40 cc. of hot 1:1 hydrochloric acid completely dissolve the residue obtained from the sodium hydrate solution into a 250-cc. beaker, or flask. Neutralize with ammonia and add 5 cc. excess. Precipitate with hydrogen sulphide. Filter and wash with hot water. Discard the precipitate.

Note. The hydrogen sulphide metals which are here discarded can be used for the determination of copper by the iodide phosphate method.

Boil off the hydrogen sulphide from the filtrate, adding a little bromine water toward the latter part of the boiling to oxidize the sulphur. Boil off the excess of bromine. Add methyl red indicator and then ammonia drop by drop until the solution is just ammoniaeal; then add 2 drops excess. Add 10 ee. of saturated solution of ammonium oxalate, allow the solution to digest for 5 minutes, remove from the hot plate and filter. Wash eight times with hot water.

More or less magnesium will be precipitated with the calcium oxalate depending on the ratio in which these metals are present. If very accurate results are desired, it will be necessary to reprecipitate the calcium oxalate.

Return the paper containing the thoroughly washed calcium oxalate to the original beaker. Add 150 cc. of boiling water and 10 cc. (1:1) sulphurie acid and titrate with standard potassium permanganate.

Potassium permanganate in the presence of sulphuric acid reacts with calcium oxalate thus:

 $5CaC_{2}O_{4} + 2KMnO_{4} + 8H_{2}SO_{4} = 5CaSO_{4} + K_{2}SO_{4} + 2MnSO_{4} + 10CO_{2} + 8H_{2}O.$

The iron value $\times 0.3588$ = the calcium value.

Magnesium: Mg₂P₂O₇ Method

The filtrate from the calcium oxalate which has been received into a 250-cc. beaker is made just acid with hydrochloric acid. Add 30 cc. of a saturated solution of microcosmic salt. Add ammonia drop by drop, stirring vigorously to make the precipitate crystalline. Then add an excess of ammonia equal to ten per cent by volume, and let stand for at least three hours. Filter, wash with cold water containing 5% of strong ammonia, and 5% of ammonium nitrate. Ignite until completely white, weigh as Mg₂P₂O₇.

$Mg_2P_2O_7 \times 0.2185 = grams Magnesium.$

For very accurate results the Mg₂P₂O₇ precipitate should be dissolved and reprecipitated, and the final precipitate should be examined for manganese or other impurities and corrected accordingly.

ANALYSIS OF SILICON ALLOYS

Determination of Silicon

Place convenient weight (1.0 gram up to 10% Si, 0.5 gram above 10% Si) of well-mixed drillings in a 250-ec. casserole and cover with a watch glass. Add 25 ec. of acid mixture No. 1 (1200 ec. 25% sulphuric acid, 600 ec. conc. hydrochloric acid, 200 ec. conc. nitric acid) from an acid burette, keeping the casserole covered and adding the acid very slowly at first until violent action has subsided. Digest on the hot plate and evaporate to dryness, taking care to prevent spattering. Cool, moisten with 5 ec. of 1:1 sulphuric acid, add 100 ec. water, and boil to solution of soluble salts. Filter, using a double quantitative filter paper, and filter pulp. Wash the residue six times in hot water to insure the removal of all iron salts.

Ignite the residue in a large platinum crucible. Cool. Add 5–8 grams of a mixture of 1:1 anhydrous sodium carbonate and sodium bicarbonate. Stir thoroughly and cover with a layer of the fusion mixture. Fuse the mixture over a Meker flame, keeping the crucible covered, until reaction is complete. This will require about 15 minutes. Cool. Place the crucible in a casserole and add 60 cc. of 1:3 sulphuric acid. When the fusion cake has dissolved, remove the crucible. Evaporate to heavy fumes. Cool. Take up with 100 cc. water. Heat to complete solution of soluble salts.

Filter through a quantitative paper, wash thoroughly, dry and ignite in a small platinum encible. Weigh, moisten the residue with water, treat with a drop of H₂SO₄, and then with an excess of HF. Take down to dryness, ignite, cool, weigh again. The loss in weight is SiO₂, which multiplied by 0.4676=Silicon.

ANALYSIS OF BAUXITE (R. Z. Method)

Methods used by the Aluminum Company of America, Technical Direction Bureau, Standard Methods of Analysis

Determination of Moisture

If the bauxite has not been previously dried, the moisture is determined at 105° C.

Determination of Loss on Ignition

Place one gram of dried sample in a weighed crucible and cover with platinum lid. Heat slowly to a red heat for one hour. Remove cover and heat for one hour at the hottest temperature obtainable on a blast lamp. Cool and weigh. The loss in weight represents combined water and organic matter.

Determination of SiO2

Place in a 250-cc. easserole one gram of dried sample and moisten with 5 ec. of water. Add 90 cc. of acid mixture (900 cc. water, 300 ec. H₂SO₄, 600 ec. HCl and 200 cc. HNO₃) and 10 cc. concentrated H₂SO₄. Cover with watch glass and boil until H₂SO₄ fumes are given off copiously. Cool, and dilute earefully to 150 cc. volume, washing cover glass and sides of dish. Replace cover glass and boil the solution carefully until the solution has a clear appearance. Filter the solution through an ashless filter into a 250-cc. flask and wash the residue with hot water until free from acid. Ignite the filter in a platinum crucible, cool in desicentor and weigh. Moisten the residue in crucible with two or three drops of water, 3 drops conc. H₂SO₄, and 2–3 cc. HF. Evaporate slowly to dryness to avoid spattering, ignite, cool and weigh. The difference between the two weights obtained gives the silica content of sample.

Determination of Fe₂O₃

If any appreciable residue remains in the crucible, it is brought into solution by fusing it with a little potassium bisulphate and dissolving the resultant fusion in very dilute sulphuric acid. This solution is then added to the original filtrate, the whole cooled to room temperature and made up to a volume of 250 cc.

25 ee, of this solution is then transferred with a pipette to a 100-cc. Nessler comparison tube for use in the determination of titanium.

The remainder of the solution is transferred to a 400-ee, beaker and evaporated to approximately 100 ee., 20 ee. of cone. HCl are then added and the solution brought to boiling. The iron is reduced by adding drop by drop to the boiling lot solution a concentrated solution of stannous chloride until the solution is colorless. The end point is sharp and not more than two drops of stannous chloride should be added in excess. Cool the solution to the room temperature and add while stirring 5 ec. of a saturated solution of

mercuric chloride. Stir solution for about thirty seconds. The iron must be titrated either with bichromate solution, using potassium ferricyanide as an external indicator, or with permanganate solution according to the Reinhart-Zimmerman method which is as follows:

Place 50 cc. of a preventative solution in a wide neck liter flask containing 350 cc. water. Pour the reduced iron solution into the flask and while whirling the flask, titrate with permanganate solution to the appearance of a pink tinge. The end point is sharp, but only lasts for a moment.

The preventative solution contains:

1750 cc. water, 160 grams manganous sulfate, 330 cc. 85% phosphoric acid, 320 cc. H₂SO₄ sp.gr. 1.84.

Determination of TiO₂

To the 25-cc. solution in the Nessler comparison tube add 20 cc. 25% H_2SO_4 and 3 cc. 3% hydrogen peroxide, fill to the mark with water and mix. In a similar tube place 20 cc. 25% H_2SO_4 , 3 cc. hydrogen peroxide and water to slightly below the mark. To this tube add standard titanic acid solution from a burette, mixing and comparing after each addition, and continue till its color matches that of the tube containing sample. From the amount of the standard used the titanium content of the sample may be calculated, remembering that the sample taken for the titanium determination represents one-tenth of the entire sample.

If a colorimeter is at hand, it may be used in place of the second Nessler tube for comparison.

Determination of Al₂O₃

The alumina is obtained by the difference between the sum of the silica, titauium oxide, iron oxide and loss on ignition calculated as percentages and 100%.

When it is required to determine whether a material is bauxite or not, some modifications are necessary. If the unvolatilized residue from silica determination amounts to more than a few milligrams, it should be fused with sodium carbonate and examined for additional silica. Absence of any considerable amount of phosphate in the sample should be established. Also the alumina should be determined in a portion of the filtrate from silica by precipitation with animonia, deducting from the ignited oxides the iron and titanium oxides which have been directly determined.

ANALYSIS OF ALUMINUM HYDRATE

Determination of Loss on Ignition

A one-gram sample is weighed into a platinum crucible and placed over a low flame of the bunsen burner. The temperature is gradually raised until the crucible is a bright red, when it is transferred to a muffle furnace at 1100° C. for one hour. Place in desiceator, cool and weigh. The loss in weight equals the per cent loss on ignition. This value of loss on ignition is the total of free and combined water.

Note. A great deal of eare is necessary when starting to heat the hydrate. The temperature should be slowly increased because if the hydrate is heated too rapidly, the high rate at which the moisture is driven off will force the particles of hydrate out of the enicible.

Determination of SiO₂

A ten-gram sample is weighed into a casserole. Enough H₂O is added to make a thin paste, then 25 ce. conc. II₂SO₄ are quickly added and easserole covered. Casserole is placed on the hot plate and taken down to considerable fuming. Allow contents to cool and dilute with 150 ce. H₂O, boil until clear. Filter and wash with hot water. Place the filter paper in a platinum erueible and ignite. Cool and weigh. Add a few drops of conc. H₂SO₄ and 1 cc. of IF. Heat on hot plate until SO₂ fumes have disappeared. Then ignite for 15 minutes; cool and weigh. Difference in weights × 10= per cent SiO₂.

Note. Considerable attention is required in placing the hydrate in a solution of H₂SO₄. When the mixture of hydrate and H₂SO₄ is hented slightly, violent action takes place which is caused by the reaction of hydrate of alumina and H₂SO₄ to form aluminum sulphate. After this reaction, continue to heat for one minute and cool. On taking up with water it seems to go in solution quite readily.

Determination of Fe₂O₃

To the filtrate from the silica determination add 5 ec. of cone. HCl; cool to room temperature. Make up a solution of 0.5 gram sample of cupferron in 25 ec. $\rm H_2O$. Filter and add filtrate slowly to the acidified filtrate from the silica determination, stirring well. Set aside to complete precipitation for 30 minutes. Filter precipitate with gentle suction and be sure the filtrate is crystal clear. Wash 1:1 HCl solution; ignite, precipitate and weigh.

Per cent $Fe_2O_3 = 10 \times weight$ of ppt.

Note. It is important that the solution be thoroughly cooled before adding the cupferron. Also in making the cupferron solution cool water is necessary. After adding the cupferron, place the solution in a cool place such as a vessel containing circulating tap water for at least 30 minutes to complete the precipitation.

Determination of Na₂O

Weigh a 10-gram sample into a platinum dish and add 30 cc. conc. HCl. Take to dryness on a steam bath or in a hot oven 110° C. Remove to muffle furnace at 500° C. to burn off free HCl. Cool and add 50 cc. hot water; boil ten minutes and add 25 cc. saturated ammonium carbonate solution; allow to stand for ouc hour or longer on hot plate but not boiling; filter and wash residue with hot water. Transfer filtrate to platinum dish, cover with watel glass and evaporate to dryness. Place in muffle at 500° C. to drive off NH₂ salts. Remove, cool, and add 5 cc. hot water. Filter contents of dish, catching filtrate in a 250-cc. bcaker, wash to a volume of 25 cc. of filtrate; allow to cool and add a crystal of potassium chromate and titrate with N/20 silver nitrate.

Cc. N/20 AgNO₃×value of AgNO₃ solution in grams Na₂O per cc. ×10=per cent Na₂O in hydrate.

Note. When taking the hydrate sample down to dryness with HCl, caution has to be taken so as not to heat it at too high a temperature. The use of a muffle furnace at 500° C. will prevent this. The same precaution is necessary when driving off the NH, salts. Too high a temperature will volatilize some of the NaCl. Always have a solution cool before titrating with N/20 silver nitrate.

Determination of Insoluble

Weigh a 10-gram sample into a casserolo and add 50 cc. H₂SO₄ 50° Be, and boil until solution is clear. Be careful not to boil down until fumes come off. Filter and place filter paper in platinum crucible and ignite for one hour in muffic furnace at 1100° C. Cool and weigh. This weight less weight of crucible × 10 = per cent of insoluble.

ANALYSIS OF CALCINED ORE

Bisulphate Fusion Methods

Preparation of Sample

The portion of ore collected is well mixed and cut down to the amount which it is wished to reserve for the determination of impurities, ordinarily about 4 oz. A separate part should be kept for mesh test, and may be used also for loss on ignition. The 4-oz. lot is quickly sifted through a 60-mesh sieve, the part retained ground till it passes the sieve and the whole thoroughly remixed. In the above grinding it is well to cover the coarse particles with a little of the sifted ore to prevent flying out and also to rinse the mortar with some of this fine part. No further grinding is to be done on the sample as there is danger of disproportionate contamination.

Determination of SiO₂

"A" (General Laboratory). Twenty-two grams of bisulfate are considered ample to make the fusion by this procedure. Weigh two-gram sample into 50 cc. platinum crucible, add about 17 grams of bisulfate and carefully fuse until violent action is over. Cool the fusion, running it up the sides of the crucible. Add the remaining 5 grams of bisulfate to be used and continue fusion until decomposition of the ore is complete.

Using procedure "A" continue from this point by cooling the erucible with air blast. Place the fused cake, which is easily removed, in a 250-ec. casserole and add 25 cc. concentrated sulfuric acid. Heat gently until the fused cake is completely broken up and copious fumes are evolved. Cool and take up with about 200 cc. of hot water. Heat gently to complete solution of soluble sults. Filter off the SiO₂, using approved quantitative filter paper, and wash with a small amount of hot water. Set uside the strong filtrate and wash the SiO₂ thoroughly until washings give no test for sulfate with barium chloride.

Ignite the filter paper in a platinum erucible at approximately 950° C. for one hour. Cool and weigh accurately on an approved balance. Treat with IHF, a few drops of H₂SO₄, and evaporate to dryness. Ignite and weigh. Loss in weight is SiO₂. Corrections must be made for SiO₂ derived from reagents or apparatus.

Per cent $SiO_2 = \frac{Loss \text{ in Weight} \times 100}{\text{Weight of Sample (2 grams)}}$

Determinations of Fe₂O₃ (Cupferron Method)

Receive the filtrate from SiO₂ determination in a 600-cc. beaker and bring to a volume of 250 cc. to 300 cc. The solution must have sufficient volume to prevent any crystallization of salts upon cooling. Add 10 cc. concentrated HCl. To the cold solution add drop-wise—at the same time stirring vigorously—30 cc. of a 1% water solution of "Cupferron." The cloudy brown solution is filtered. Wash with 20 per cent cold HCl until the paper is free from soluble salts, then wash with cold water. Ignite the paper in platinum crucible, cool and weigh. All results must be corrected by running blank.

 $\label{eq:Per_equal_Per_equal} \text{Per eent Fe}_2\text{O}_3 = \frac{\text{Weight of Residue} \times 100}{\text{Weight of Sample}}.$

Determination of Na₂O

Weigh 5 grams from sample which has been pulverized in an agate mortar into a 250-ce. casserole. Add 20 cc. of concentrated HCl and evaporate on hot plate to dryness. Care should be taken at this point not to heat the residue too high so that a minimum amount of cake will be formed. Take up with hot water and digest until all soluble salts are in solution. This operation should be assisted by thoroughly breaking up any eake that has formed. Add 50 cc. of saturated (NII₁)₂CO₂. Let stand for half an hour and filter with suction. Transfer the filtrate to casserole, evaporate to dryness and heat until all white fumes of (NII₄)₂CO₂ are driven off (500° C. to 600° C.). Cool, take up with hot water, add 5 cc. of saturated solution of (NH₄)₂CO₃, filter and wash into a platinum dish of 125–150 cc. capacity. Evaporate to dryness and ignite at 500° C. until all anunonium salts are driven off. Cool. Dissolve in a little water, filter and wash into a 200-cc. Erleumeyer flask. Bring volume of solution to 150 cc. Add 6 to 8 drops of saturated solution of K₂CrO₄ and titrate with standard silver nitrate solution.

Determination of Loss on Ignition

Prepare a 10 or 15 cc. platinum crneible provided with a close-fitting cover by igniting, cooling in desiccator and weighing. Weigh into it one gram of ore. Place in an electric furnace heated to 1050-1100° C, or in a flame giving that temperature for 45 minutes. Transfer to a sulphuric acid desiccator and as soon as cool weigh quickly. The loss in weight×100=per cent loss on ignition.

Estimating Metallic Aluminum in Aluminum Dust¹

The value of aluminum dust for technical purposes depends chiefly upon the amount of metallic aluminum contained. A rapid method of estimating this constituent is therefore highly desirable. A modification of Wahl's method for the determination of metallic sine by highly desirable. A modification of Wald's method for the determination of metallic sine by the reduction of ferric sulphate in cold neutral solution has been found to be rapid and simple. It does not require special skill in manipulation and gives results that are of value for comparative purposes at least.

The reduction of ferrie sulphate by metallic aluminum does not take place in cold neutral aqueous solution. If, however, sufficient free sulphuric acid be added and the liquid be heated, ferrous sulphute is formed proportionally to the amount of metallic aluminum present.

The results obtained with samples of known composition were usually about 5% lower

than those indicated by the supposed reaction

$$3Fe_2(SO_4)_3 + 2 AI = Al_2(SO_4)_3 + 6FeSO_4$$
 (1)

so that for accurate results it is necessary to standardize on a sample of pure metallic aluminum or on a sample of which the aluminum contents have been exactly determined by some other method. From equation (1) above, it follows that 1 part Al = 6.182 parts Fe reduced from ferric to ferrous iron, or 1 part Fe = 0.16177 parts Al, assuming Al = 27.1 and Fe = 55.84. The test as generally made is as follows: 100 mg. of the aluminum dust is accurately

weighted and placed in a conical flask provided with stopper and Bunsen valve to reduce risk of oxidation, together with 50 cc. of a standard solution of acid ferric sulphate z and the mixture leated gradually until the liquid is boiling gently. If the aluminum dissolves completely with moderate heat, it is not essential to boil. The flask is then cooked to room temperature by placing under a running tap, and 50 cc. of cold distilled water is added. The liquid is then titrated with standard permanganate.

A convenient standard solution contains 3.35 grams KMnO4 per liter of this solution;

1 cc. = 1° c Al, approximately.

With samples of ordinary aluminant dust the reaction takes place without visible evolution of hydrogen. When the powder contains coarse flakes or granules, some effervescence can be observed. In such cases, it would seem that the titration must indicate a result too low, as part of the Al has been dissolved according to the reaction

$$3H_2SO_4 + 2AI = Al_2(SO_4)_2 + 6II,$$
 (2)

without reducing its equivalent of ferric sulphate.

Another source of error, which acts in the opposite direction, is the presence of iron, zine or other metal capable of reacting with ferrie sulphate. For accurate work, therefore, these metals must be determined and their effect allowed for. When, however, comparative results only are required, as in checking the quality of factory products from day to day, the rapid test described is sufficient. For some purposes also metallic iron, zinc, etc., would be as effective as their equivalent of aluminum, in which case no correction ought to be applied. The reactions in the case of iron and zinc are presumably:

$$Fe + Fe2(SO4)3 = 3FeSO4, (3)$$

$$Zn + Fe2(SO4)4 = 2FeSO4 + ZnSO4,$$
 (4)

Assuming Al = 27.1; Fe = 55.84; Zn = 65.37, 1 part inetallic Fe has the same reducing power as 0.4853 part metallic Al, and 1 part metallic Zu has the same reducing power as 0.2763 part metallic Al.

In making the ordinary tests for controlling plant operations, a sample of the purest obtainable aluminum dust is accepted as a standard. Tests are then made concurrently with the standard dust and with the sample to be examined, the result of the latter being expressed as a percentage of the standard.

¹ By J. E. Clennell, Eng. and Mining Journal, May 6, 1916. ² To 100 grams of pure ferric sulphate distilled water is added, then 250 cc. of concentrated sulphuric acid. This mixture is heated to boiling until the ferric sulphate has completely dissolved, then cooled and finally made up to a liter with distilled water.

The revised atomic weights of Al and Zn changes slightly the ratios above.—Editor.

ANTIMONY

Sb₁ at.wt. 121.77; sp.gr. 6.62¹; m.p. 630°C²; b.p. 1440°C¹; oxides, Sb₂O₄, Sb₂O₄, Sb₂O₅.

DETECTION

Hydrogen Sulphide precipitates the orange-colored sulphide of antimony from fairly strong hydrochloric acid solutions (1:4) in which several members of the group remain dissolved. Arsenic is also precipitated. The latter may be removed by boiling the solution containing the triehloride, AsCl₃ being volatile.

If antimony is already present as a sulphide, together with other elements of the hydrogen sulphide group, it may be dissolved out by treating the precipitate with solium hydroxide, potassium hydroxide, sodium sulphide, ammonium polysulphide in solution. Antimony sulphide is reprecipitated upon acidifying the filtrate. Arsenic and tin will also be precipitated with antimony if they are present in the original precipitate. Should a separation be necessary, the precipitate is dissolved with hot concentrated hydrochloric acid, with the addition of crystals of potassium chlorate, from time to time, until the sulphides dissolve. The solution is placed in a Marsh apparatus, pure zinc added and the evolved gases passed into a neutral solution of silver nitrate. The black precipitate of silver antimonide and netallic silver are filtered off, washed free of arsenous acid, and the antimonide dissolved in strong hydrochloric acid (silver remains insoluble). The orange-colored antimony sulphide may now be precipitated by diluting the solution with water and passing in $\mathbf{H}_2\mathbf{S}$ gas to saturation.

Minerals which contain antimony, when heated alone or with 3 to 4 parts of fusion mixture (K₂CO₃ and Na₂CO₃), on charcoal, yield dense white fumes, a portion of the oxide remaining as a white increstation on the charcoal. A drop of ammonium sulphide placed upon this sublimate gives a deep orange stain.

Hydrolysis. Most of the inorganic antimony salts are decomposed by water, forming insoluble basic salts, which in turn break down to the oxide of antimony and free acid. An excess of tartaric acid prevents this precipitation.

Traces of Antimony. Nascent hydrogen liberated by the action of zinc and hydrochloric or sulphuric acid reacts upon antimony compounds with the formation of stibine. This gas produces a black stain on mereuric chloride or silver nitrate paper. Details of the procedure are given under the quantitative method for determining minute amounts of antimony.

Distinction between Antimonous and Antimonic Salts.

Chromates form with antimonous salts green chromic salts and antimonic salts.

Potassium Iodide reduces antimonic salts, free iodine being liberated.

¹ Van Nostrand's Chem. Annual, Olsen, 3d Ed.

Cir. 35, U. S. Bureau of Standards.

Contributed by Wilfred W. Scott.

ESTIMATION

The determination of antimony is required in the evaluation of antimony pres—stibute, Sb₂S₃; valentinite, Sb₂O₃, etc. It is generally required in the complete analysis of minerals of nickel, lead, copper, silver, in which antimony generally occurs as a sulphide. The determination is required in the analysis of Britannia metal, bearing and antifriction metals, type metal and hard lead; n the analysis of certain mordants, antimony salts, vulcanized rubber, etc. It s looked for as an undesirable impurity in certain food products.

Preparation and Solution of the Sample

In dissolving the substance containing antimony it must be remembered that metallic antimony is practically insoluble in cold dilute hydrochloric, nitrie or sulphuric acid and the oxides, Sb₂O₃ or Sb₂O₅, are precipitated in strong nitric acid. The element, however, is readily soluble in hydrochloric acid containing an oxidizing agent, such as nitric acid, potassium chlorate, eblorine, bromine, etc. The oxides of antimony are soluble in hydrochloric acid and the caustic alkalies.

Solution of Sulphide Ores, Low-grade Oxides, etc.1

0.5 to 1 gram of the finely ground ore, placed in a Kjeldahl flask, is mixed with 5 to 7 grams of granular or powdered potassium sulphate, and 10 cc. of strong sulphuric acid. About 0.5 gram of tartaric acid, or a piece of filter paper, is added to reduce arsenic and antimony and the mixture heated, gradually at first, and then with the full Bunsen flame. The heating is continued until the carbon is completely oxidized and most of the free acid driven off, leaving a clean fusion but not to complete expulsion of 11₈SO₄. The melt is now couled over the bottom and sides of the flask by gently rotating during the cooling.

About 50 ec. of dilute hydrochloric acid (I:1) are added and the melt dissalved by warming gently. The contents of the Kjeldahl flask are transferred to an Erlemneyer flask, the Kjeldahl being riused out with 25 cc. of strong hydrochloric acid. Arsenic sulphide may now be precipitated with H₂S from the strongly acid solution, whereas antimony, etc., remain in solution. The sulphide is filtered off through a double filter, that has been moistened with hydrochloric acid (2:1), a platinum cone supporting the filter to prevent its breaking. The flask is rinsed out with hydrochloric acid (2:1). The precipitate is washed at least six times with the acid. Antimony pusses into the filtrate together with other elements of the ore.

The filtrate is diluted with double its volume of warm water and then is saturated with hydrogen sulphide. Antimony sulphide, together with other elements of the Hydrogen Sulphide Group, will precipitate. These are washed with hydrogen sulphide water. Antimony sulphide may now be dissolved by addition of sodium sulphide and caustic solution (separation from Cu, Pb, Cd, Bi, etc.) (5 to 10 cc. of a mix of 60 grams Na₂S with 40 grams of NaOH diluted to 1000 cc.).

The solution containing the antimony is treated with about 2 grams of potassium sulphate and 10 cc. of strong sulphuric acid and heated as before, to destroy liberated sulphur and expel most of the free acid. The melt is dissolved in hydrochloric acid, and the antimony titrated according to one of the volumetric procedures given under "Volumetric Methods."

Note. An insoluble residue remaining from the acid extraction of the first melt may be dissolved by fusion with sodium hydroxide and extraction of the melt with hot water. If a precipitate forms when this alkaline solution is acidified with hydrochloric acid, the presence of barium sulphate is indicated.

Decomposition of the Ores by Fusion with Sodium Hydroxide.

Oxides. 0.5 to 1 gram of the powdered ore is mixed with about 10 grams of sodium hydroxide and placed in a thin-walled iron crucible of 60 ec. capacity. It is advisable to fuse a portion of the alkali hydroxide in the erucible with a pinch of potassium nitrate and then add the ore mixed with the remainder of the sodium hydroxide. The covered crucible is heated until the fusion becomes homogeneous. The melt is poured out on a large nickel crucible cover or shallow dish. On cooling, the cake is detached and placed in a casserole containing water, any adhering eake on the cover, or melt remaining in the iron crucible, being dissolved with dilute hydrochloric acid and added to the sample in the casserole. About 30 to 40 ec. of strong hydrochloric acid are now added and the mixture heated (casserole covered) until the melt has dissolved. Two to 3 grams of tartaric acid having been added to keep antimony dissolved, the solution is diluted to about 300 ec., and antimony is then precipitated as the sulphide with hydrogen sulphide. The treatment of the precipitate at this stage has been given in the "Solution of Sulphide Ores."

Sulphides. Howard and Harrison recommend the following procedure for fusion of sulphide ores with emistic: 0.5 gram of the powdered ore is fused with a mixture of 8 grams of sodium carbonate and sodium peroxide, 1:1, in a niekel crucible. The cooled melt is dissolved with sufficient hydrochloric acid to nentralize the alkali and about 15 cc. of strong acid added in excess. The solution is diluted to 250 cc., antimony being kept in solution by addition of potassium chlorate. An aliquot portion of the solution is taken, antimony reduced by metabisulphite and titrated with iodine.

Treatment of Speisses, Slags, Mattes, etc.² 0.5 to 2 grams of the sample is treated with 10 to 15 cc. of strong nitric acid and the mixture taken to dryness. Fifteen ec. of strong hydrochloric acid are added and the sample transferred to a 350-cc. flask, additional hydrochloric acid being used to wash out the beaker. Arsenic is precipitated from the strong acid solution as the sulphide, and antimony determined in the filtrate.

Solution of Alloys. Alloys are generally decomposed by treatment with mixtures of hydrochloric acid together with an oxidizing agent—nitric acid, potassium chlorate, bromine, etc. The subject is taken up in detail in the chapter on alloys.

The alloy drillings are treated with strong hydrochloric acid, a little bromine added, and the mixture heated until the alloy dissolves, additional bromine being added from time to time if necessary. The excess bromine is removed by heating gently to boiling. The higher oxides are reduced by addition of

¹ Phar. Jour., 1909, 83, 147.

³ H. E. Hooper's method.


sodium metabisulphite and the sulphides precipitated, as usual, with hydrogen sulphide. Arsenie may now be volatilized by boiling, and antimony titrated with iodine or potassium bromate.

Alloys of Antimony, Lead and Tin. 0.5 to 1 gram of the finely divided alloy is warmed with 100 cc. of strong hydrochloric acid until the action subsides. Solid lodine is now added, in small quantities at a time, until the alloy completely dissolves. The excess of iodine is now removed by boiling and the small amount of free iodine remaining neutralized with a few drops of a weak solution of sodium thiosulphate. Although tin is oxidized to the higher state, antimony is not oxidized by iodine in acid solution beyond the trivalent form. The solution may now be titrated with standard iodine in presence of an excess of sodium blearbonate according to the procedure given under the volumetric methods.

Hard Lead. The method of solution and titration are given under "Potassium Bromate Method for Determining Antimony."

Antimony in Rubber Goods.¹ Three grams of the finely rasped rubber are treated in a Kjeldahl flask with 40 to 45 cc. of strong sulphuric acid. A small quantity of mercury or mercury salt is added, together with a small piece of paraffine wax. The mixture is heated until the rubber is dissolved and the black liquid begins to clear. Two to 4 grams of potassium sulphate are then added and the heating continued until a colorless or pale yellow liquid is obtained. After cooling, 1 to 2 grams of potassium metabisulphite are added and an excess of tartaric acid. The liquid is diluted sufficiently to prevent the charring of the tartaric acid and boiled until the odor of sulphurous acid has disappeared. A few cc. of dilute hydrochioric acid are added, the liquid diluted to 200 ec., filtered through a dry filter, and 195 cc. titrated either with iodine or with potassium bromate (the latter in acid solution), as described under the volumetric procedures.

¹ W. Schmitz, Chem. Zentralbl., 1911, ii, 1710. Analyst, 1912, p. 64.



SEPARATIONS

Separation of Antimony (together with Members of the Hydrogen Sulphide Group), from Iron, Chromium, Aluminum, Cobalt, Nickel, Manganese, Zinc, the Alkaline Earths, and Alkalies. The acid solution of the elements is saturated with hydrogen sulphide, the elements of the Hydrogen Sulphide Group are precipitated as sulphides, the other elements remaining in solution. Antimony sulphide may be precipitated from an hydrochloric acid solution containing 15 cc. of strong acid per 100 cc. of solution; lead and cadmium are incompletely precipitated.

Separation of Antimony (together with Arsenic and Tin), from Mercury, Copper, Blsmuth, Cadmium and Lead. The sulphides of antimony, arsenic, and tin are soluble in a mixture of sodium hydroxide and sodium sulphide, the soluble sulpho salts being formed, mercury, copper, bismuth, cadmium, and lead remaining as insoluble sulphides. The following procedure may be used for alloys free from members of other groups. The neid solution is treated with 3 to 5 grams of tartaric acid and diluted slightly (more tartaric acid being added if the solution becomes turbid), then poured into 300 cc. of a mixture of sodium sulphide and sodium hydroxide (150 cc. of the mix described under "Solution of Sulphide Ores" diluted to 300 cc.). The mixture is warmed and the insoluble sulphides allowed to settle out. The solution is filtered free of the precipitate and the latter washed. The filtrate is acidified with hydrochloric or sulpharic acid and saturated with hydrogen sulphide. The sulphides of arsenic, antimony and tin are now filtered off and treated as described later.

Separation of Arsenic, Antimony, and Tin. The sulphides may be dissolved in concentrated hydrochlorie acid by addition of potassium chlorate to oxidize the sulphur to sulphuric acid. This oxidation may be effected in the alkaline solution of the sulpho salts by addition of 30% bydrogen peroxide in small portions until the yellow solution is completely decolorized and then 1 to 2 cc. in excess, the solution then boiled to completely oxidize the sulphides to sulphates and to remove the excess of peroxide. The solution is then acidified, the precipitation of the sulphides and the subsequent filtration and resolution being avoided.

Removal of Arsenic. This may be accomplished by volatilizing arsenic as arsenic trichloride in a strong hydrochloric solution by boiling. If arsenic is to be determined the procedure given under the elapter on arsenic is followed, the arsenic being distilled in a current of hydrochloric acid gas. If arsenic is not desired it may be expelled by reducing the solution with sodium metabisulphite or potassium iodide and boiling. Antimony and tin remain in the concentrated acid solution.

The separation of arsenic from antimony and tin may be effected by removal of the former in a strong hydrochlorie acid solution as described under the section "Preparation and Solution of the Sample," arsenic being precipitated by hydrogen sulphide, whereas antimony and tin remain in solution.

Separation of Antimony from Tin. Upon the removal of arsenic, antimony may be determined directly in the presence of tin by one of the volumetric methods given later. If a gravimetric separation is desired, it may be made according to a modification of Clark's method, which depends upon the

'fact that antimony is completely precipitated from a solution containing oxalic acid, by hydrogen sulphide, whereas tin is not. The tin must be in the stannic form, otherwise the insoluble crystalline stannous oxalate will form.

If the mixture is acid, it is neutralized with caustic and twenty times the weight of the Sn and Sb present added in excess, e.g., 2 grams potassium hydroxide in excess for every 0.1 gram of tin and antimony present in the solution. About ten times as much of tartarie acid is now added as the maximum weight of the two metals, followed by 30% hydrogen peroxide to oxidize the tin. The excess of peroxide is removed by boiling. To the slightly cooled solution a hot solution of pure oxalic acid is added, 5 grams of oxalic acid for each 0.1 gram of the mixed elements. ('O2+O2 are evolved. The solution is boiled for about ten minutes and the volume made up to about 100 cc. Hydrogen sulphide is rapidly passed into the boiling solution until a change from a white turbidity to an orange color takes place and antimony begins to precipitate. The passage of the gas is continued for fifteen minutes, the solution diluted with hot water to a volume of 250 ee. and hydrogen sulphide passed into the boiling solution for another fifteen minutes. The flame is now removed and the H2S "gasing" continued for ten minutes longer. The precipitated antimony pentasulphide is filtered off in a weighed Gooch crucible. It may be determined gravimetrically as Sb₂S₃, according to the procedure given later, by washing with 1% oxalic acid and dilute acetic acid, by decantation, the solutions being hot and saturated with hydrogen sulphide. The precipitate washed into the crucible is dried in a current of CO₂ at a heat of 280 to 300° and weighed as Sb₂S₃.

Tin may be determined electrolytically in the filtrate evaporated to about 150 cc., the oxalic acid being nearly neutralized with annuonia. See Electrolytic Determination of Tin.

Antimony may be separated from tin in a hot hydrochloric acid solution by addition of pure iron. The iron and tin sulphides are dissolved in concentrated hydrochloric acid plus a few crystals of potassium chlorate. The solution should contain about 10% hydrochloric acid, more hydrochloric acid being added as the iron dissolves. Antimony is precipitated as a metal.

¹ The Original procedure may be found in Chem. News, Vol. XXI, p. 124.

GRAVIMETRIC METHODS FOR THE DETERMINATION OF . ANTIMONY

The accuracy and rapidity of volumetric methods for the determination of antimony leave little to be desired in the estimation of this element, so that the more tedious gravimetric methods are less frequently used. The following procedures are given in view of possible utility in certain analyses.

Determination of Antimony as the Trisulphide, Sb₂S₃ ¹

Although hydrogen sulphide passed into a cold solution tends to precipitate Sb₂S₄, in hot strongly acid solutions, the lower sulphide, Sb₂S₃, tends to form. The higher sulphide is decomposed at 230° C, with formation of Sb₂S₄ and the volatilization of sulphur. A temperature of 280 to 300° is even more favorable for this transformation. The method takes advantage of these conditions for formation of antimony trisulphide, in which form it is weighed.

Procedure. The solution of antimony, free from arsenic, is treated in an Erlenmeyer flask with strong hydrochloric acid until the solution contains about 20% of the concentrated acid. The mixture is heated to boiling and a slow current of hydrogen sulphide is passed into the hot solution until the precipitate passes from a yellow color through an orange and finally becomes a dark red to black color. The flask is agitated gently to coagulate the precipitate, which settles in a crystalline form. The solution is diluted with an equal volume of water, washing down the walls of the flask. A slight turbidity is generally seen, due to precipitation of a small amount of antimony that remains in solution in a strong acid solution. Il-S is now passed into the diluted solution until it becomes clear, thirty-five to forty minutes are usually sufficient to precipitate all of the antimony. The precipitate is transferred to a weighed Gooch crucible, washed with small portions of water containing hydrogen sulphide, and finally with pure water.

It is a common practice, at this juncture, to wash the precipitate with earbon disulphide or carbon tetrachloride to remove precipitated sulphur. Alcohol is now used, followed by ether, and the precipitate sucked dry.

The Gooch erneible is placed in a large combustion tube and heated in a current of dry, pure CO2 at 130° C. for an hour. The temperature is now raised to 280 to 300° C, and the heating continued for two hours. The residue will consist of pure Sb₂S₃.

$$Sb_2S_3 \times 0.7112 = Sb_1 \text{ or } Sb_2S_3 \times 0.8568 = Sb_2O_3.$$

Antimony may be determined by oxidation of the sulphide precipitate f fuming nitric acid. The mixture evaporated to dryness is ignited and hy means of fuming nitrie acid. The mixture evaporated to dryness is ignited and the residue weighed as $8b_2O_4$. The temperature of the ignition should be between 750 to 800° C. The volatile trioxide forms at a little above 950° . The procedure requires greater care than the sulphido method and possesses no advantages.

Pure earbon dioxide may be obtained from limestone placed in a Kipp generator. The gas is dried by passing it through strong sulphuric acid. It should be free from oxygen of the air. It is advisable to sweep out the air from the generator before attaching it to the combustion train. The air in the tube is awcit out with earbon dioxide before heating the sample,

Property of Sb₂S₃, m.w., 336.61; sp.gr., 4.65; fusible and volatile; solubility, 0.000175 gram per 100 ee. H₂O; decomposed by hot H₂O; soluble in alkalies, NH₄HS, K.S, conc. HCl.

¹ Method of Vortmann and Metzel modified. ² Paul, Z. anal. Chem., 31, 540 (1892).

Electrolytic Determination of Antimony 1

The chief condition for the success of the electrolytic deposition of antimony in metallic form is the absence of polysulphides, since these substances prevent the element from being deposited, $2Sb+3Na_2S_2=2Na_3SbS_3$. The formation of polysulphides may be prevented during electrolysis by addition of potassium eyanide to the solution, $Na_2S_2+KCN=Na_4S+KCNS$.

The results of this method, according to F. Henz, are invariably 1.5 to 2% too high of the total antimony present in the solution. The sample for analysis should contain not over 0.2 grain antimony.

Procedure. Antimony precipitated as the sulphide is washed and then dissolved off the filter by pouring pure sodium sulphide solution (sp.gr. 1.14) over the precipitate, the solution being caught in a weighed platinum dish, with unpolished inner surface. The total volume of the solution should be not over 80 ec. (if less than this, additional Na-S solution is added to make up to 80 ec.). Sixty cc. of water followed by 2 to 3 grams of potassium eyanide (C.P.) are added and the cyanide dissolved by stirring with the rotating anode. The solution heated to 60 to 70° is electrolyzed with a current of 1 to 1.5 amperes, E.M.F. = 2 to 3 volts. Two bours are generally sufficient to deposit all the antimony. The light-gray deposit adheres firmly upon the cuthode. Without breaking the current the solution is siphoned off, while fresh water is being added, until the current ceases to flow through the liquid. The cathode is washed thoroughly with water, followed by alcohol and ether and then dried at about 80°, cooled in a desiceator and weighed.

The antimony deposits may be removed by heating with a solution of alkali polysulphide or by a mixture of equal parts of saturated solution of tartaric acid and nitric acid.

Method first proposed by Parrodi and Mascazzini, Z. anal. Chem., 18, 587 (1879), modified by Luckow, Z. anal. Chem., 19, 13 (1880), and later improved by Classen and Reiss, Berichte, 14, 1629 (1881); 17, 2474 (1884); 18, 408 (1885); 27, 2074 (1894). F. Henz, Z. anorg Chem., 37, 31 (1903).

VOLUMETRIC METHODS

Potassium Bromate Method for Determining Antimony 1

Outline. This method is of special value in determining antimony in hard lead and alloys. It was first suggested by Györy and later modified by Siedler, Nissensen and Rowell.² The process is based upon the oxidation of antimony from the trivalent to the pentavalent form by potassium bromate, the following reaction taking place:

 $KBrO_x+3SbCl_x+6HCl=3SbCl_x+KBr+3H_2O$.

Standard Solutions.

Antimony Chloride Solution. Six grams of the C. P. pulverized metal are dissolved in 500 cc, of concentrated hydrochloric acid together with 100 ee. saturated bromine solution, more acid and bromine added if necessary to effect solution. After expelling the bromine by boiling, about 200 cc. concentrated hydrochloric acid are added and the whole made up to one liter. Fifty ce. =0.3 gram antimony.

N/10 Potassium Bromate Solution. 2.82 grams of C. P. salt are dissolved in water and made up to 1 liter. Theoretically 2.7852 grams are required, but the salt invariably contains potassium bromide as an impurity. The solution is standardized against 50 cc. of the antimony chloride solution, which has been reduced with sodium sulphite according to the standard scheme. One ce. of N/10 KBrO₃ = 0.006 gram Sb.

Methyl Orange. 0.1 grain M. O. per 100 cc. of distilled water. The indicator should be free from sediment.

Saturated Bromine Solution. 500 cc. concentrated hydrochloric acid saturated with 70 cc. of bromine.

Procedure. Solution. One gram of the finely divided alloy is brushed into a 500-ee, beaker, 100 cc. of concentrated bydrochloric acid and 20 ee, of saturated bromine solution are added. The beaker is covered and placed on the steam both until the metal dissolves. It may be necessary to add more bromine and acid to effect complete solution. In case the oxides of antimony and tin separate out and do not redissolve, fusion with sodium hydroxide may be necessary. Bromine is now expelled by boiling the solution down to about 40 cc.

Reduction. One hundred cc. of concentrated hydrochloric acid and 10 cc. of a fresh saturated solution of Na₂SO₂ are added and the solution boiled down to 40 cc., on a sand bath, to expel arsenic and the excess of normal sodium sulphite. Samples high in arsenic may require a repetition of the reduction.

Titration. The cover and sides of the beaker are riosed down with 20 cc. of hydrochloric acid (sp.gr. 1.2) followed by a few cc. of hot water and the solution heated to boiling on a sand bath. The standard bromate solution is now run into the hot solution of antimony to within 2 to 3 ee, of the end-

¹S. Györy, Zeit. Anal. Chem., 32, 415 (1893). J. B. Duncan, Chem. News, 95, 49 (1907).

² H. W. Rowell, Jour. Soc. Chem. Ind., XXV, 1181.

point, this having been determined in a preliminary run with methyl orange added in the beginning, 4 drops of methyl orange are added and the titration completed cautiously until the color of the indicator is destroyed. If iron or copper is present the final product will appear yellow. Since the end-reaction is slow the last portion of the reagent should be added drop by drop with constant stirring.

1 cc. N/10 KBrO₃ = 0.006 gram Sb.

Notes. Since antimony chloride begins to volatilize at 195° C. and boils at 220° C.

it is advisable not to earry the concentration too far while expelling arsenie.

Lead, copper, zinc, tin, silver, chromium, and sulphuric acid have no effect upon the determination, but large quantities of calcium, magnesium, and ammonium salts tend to make the results high. Low' found that copper produced high results, approximately .012% too high for every 0.1% of copper present. The author (W.W.S.) finds, however, that with the procedure given above, amounts of copper as high as 15% produced no difficulty beyond a yellow coloration of the solution. With larger amounts of copper, the end-point became difficult to detect owing to the depth of this yellow color, so that in ease of brass and copper alloys, the method must be modified by a procedure for removal of the copper. Lead up to 95% caused no difficulty. Iron, in amounts such as are commonly met in alloys of lead, does not interfere.

During the course of analysis antimony may be isolated as the sulphide; this is dissolved in strong hydrochloric acid, and reduced and concentrated to expel arsenic that may be present as a contamination, and the resulting solution titrated with potassium bromate as directed above.

Sources of Error. (a) Imperfect volatilization of arsenic. (b) Incomplete expulsion of SO. (c) thus titration if insufficient hydrophleric soid is present.

sion of SO₂. (c) the titration if insufficient hydrochloric acid is present. No loss of antimony occurs at temperatures below 120° C.

Potassium Iodide Method for Determining Antimony

Procedure. To 1 gram of fine sawings or filings in a 16-oz. Erlenmeyer flask add 60 cc. of concentrated hydrochloric acid and heat on an asbestos board or on the water bath just below boiling. When hydrogen is no longer evolved, deeant the liquor and wash twice with concentrated hydrochloric acid, retaining the antimony in the flask. Now dissolve the antimony by adding 15 cc. of concentrated hydrochloric acid and solid potassium chlorate, a few crystals at a time, until the antimony is in solution, the liquid being kept hot. Expel chlorine by boiling, add 50 cc. of concentrated hydrochloric acid and again bring to boiling. Cool and add 20 cc. of 20% potassium iodide solution and 1 cc. of carbon disulphide or tetrachloride. Titrate the liberated iodine with tenth-normal sodium thiosulphate. The brown color will gradually disappear from the solution and the last traces of free iodine will be collected in carbon disulphide or carbon tetrachloride, giving a pink color. When this pink color disappears the end-point has been reached.

One ee. N/10 Na₂S₂O₃ = .006 gram of Sb.

Na₂S₂O₃ is standardized against .3 gram antimony as in case of Potassium Bromate Method, the above procedure, however, being followed. Antimony must be free from copper and arsenic.

NOTES. The following reversible reaction is of interest: "R" representing a trivalent metal with oxidation to pentavalent form.

$$R_2O_3+2I_2+2H_2O=R_2O_3+4HI.$$

The reaction goes to the right when an alkali is present to neutralize the free acid formed; e.g., Mohr's process for determining arsenic by titration of the lower ¹A. H. Low, "Technical Methods of Ore Analysis."

oxide with fodine in presence of sodium bicarbonate. The reaction goes to the left, in presence of strong acid; e.g., Weller's process for the determination of antimony in an acid solution.

The solution should not contain more than $\frac{1}{2}$ of its volume of hydrochloric acid (sp.gr. 1.16), since too much hydrochloric acid gives high results, owing to the action of hydrochloric acid on potassium iodide. Too little acid leads to the separation of basic iodides and chlorides of antimony. The solution is best boiled down to 20% hydrochloric acid (above strength).

Stannous chloride may be used in place of thio-sulphate in titration of iodine.

 $SbCl_4 + 2Kl = SbCl_4 + 2KCl + l_2 \quad \text{and} \quad l_2 + SnCl_2 + 2HCl = SnCl_4 + 2HI.$

Determination of Antimony by Oxidation with Iodine

The procedure originated by Mohr and modified by Clark, depends upon the reaction $Sb_2O_3+2I_2+2II_2O=Sb_2O_5+4III$.

The reaction takes place when iodine is added to a solution of antimonous salt in presence of an excess of alkali bicarbonate. In an acid solution oxidation with iodine does not go beyond Sb_2O_3 .

Procedure. Solution. The sample is brought into solution by one of the procedures given under "Preparation and Solution of the Sample." Alloys of antimony, lead, and tin are treated according to directions given for this combination.

Titration. To the hydrochloric acid solution of antimony is added tartaric acid or Rochelle salts, the excess of the acid neutralized with sodium earbonate, the solution made barely acid with hydrochloric acid and a saturated solution of sodium bicarbonate added in the proportion of 10 ec. bicarbonate solution for each 0.1 gram of Sb_iO_5 . Starch is added as an indicator and the solution titrated with N/10 iodine.

1 ec. N/10 iodine = 0.006 gram Sb.

Note. The titration should be made immediately upon addition of the sodium salts.

Antimony in Solder Metal and Alloys with Tin and Lead 1

Procedure. Dissolve 2 grams of the sample of alloy in concentrated hydrochloric acid. When the metal is all in solution, add crystals of iodine until the solution is thoroughly permeated. The color at this point should be a deep purple. Boil until all of the iodine fames have been driven out. The metallic antimony which did not go into solution in the hydrochloric acid should now be all dissolved. If it is not, add more iodine until the solution is complete. When all is in solution and the color changes to a straw yellow, cool, add a few ee. of starch solution. If a blue color appears, due to an excess of iodine, run in N/10 sodium thiosulphate solution until colorless. In case there is no blue color developed, add N/10 iodine until a faint blue appears. Now add 50 ee. of a saturated solution of Rochelle salts. Make alkaline to litanus by adding 25% sodium hydrate solution. Then make slightly acid with HCl and finally alkaline with sodium bicarbonate. Cool and titrate with N/10 iodine.

Note. "The method gives very good results. I have checked it up when there was one-tenth of a gram known antimony present and the results were within a reasonable limit of accuracy." 1

⁴ Method communicated to author by Mr. B. S. Clark.

Other Procedures

Permanganate Method

Antimonous salts may be titrated with standard potassium permanganate. The iron value for the permanganate multiplied by 1.075 or the oxalic acid $(C_2H_2O_4\cdot 2H_2O)$ value multiplied by 0.9532, will give the antimony value.

Indirect Evolution Method

The method depends upon the evolution of Il₂S from the sulphides of antimony decomposed by strong hydrochloric acid, the amount of hydrogen sulphide being the same for either Sb₂S₁ or Sb₂S₂, the following reactions taking place:

- 1. $Sb_2S_3 + 6HCl = 2SbCl_3 + 3H_2S_3$
- 2. $Sb_2S_4 + 6HC1 = 2SbCl_3 + S_2 + 3H_2S_4$

The details of the method are practically the same as determination of sulphur by the evolution method in the analysis of iron and steel. See Chapter on Sulphur. The antimony sulphide precipitate is placed in the evolution flask, strong hydrochloric acid added with an equal volume of water and the evolved hydrogen sulphide absorbed in an animoniacal solution of cadmium chloride. The precipitated cadmium sulphide is then titrated with iodine in an acid solution.

One cc. N/10 1 = 0.001604 gram S, since 3S = 2Sb, therefore $Sb = S \times 2.499$, hence, 1 cc. N/10 1 = 0.00401 gram Sb.

Preparation of Standard Iodine Solution. An approximate tenth normal solution is made by dissolving 12.7 grams of commercial iodine, roughly weighed on a watch-glass, in 200 cc. of water containing about 25 grams of potassium iodide, solution being effected in a graduated liter flask. After making up to 1000 cc. with distilled water, the reagent is transferred to a dark-colored bottle, to protect it from light. It is advisable to make up 5 to 10 liters at a time for laboratories where the solution is in constant demand. After standing several hours, the reagent is standardized by running a portion from a burette into 100 cc. of tenth normal arsenous acid (see page 240) until a faint yellow color is perceptible. In presence of starch indicator a faint blue color is obtained.

100 divided by the cc. of iodine required gives the factor for a N/10 solution. **Example.** If 98.5 ee. of iodine are required, $100 \div 98.5 = 1.0152$ N/10 or .10152 normal.

Tenth normal arsenous acid solution contains 4.953 grams of As₂O₃, per liter, dissolved in sodium hydroxide and made up according to directions given on page 204. The oxide is seldom pure, so that allowance must be made for impurities. For example, the acid containing 99.56 per cent As₂O₃ would require 4.953 ÷ .9956 = 4.97 grams per liter of solution.

Commercial iodine may contain chlorine, bromine, eyanogen and water. It may be purified by repeated sublimation ("Analytical Chemistry," Treadwell and Hall, IV Ed., page 646, or "A Treatise on Quantitative Inorganie Analysis" (1913), by J. W. Mellor, page 288). There is no advantage in taking the theoretical amount of purified iodine, however, since the reagent changes in strength on standing.

Potassium iodide augments solution of iodine, which is sparingly soluble in water. The iodine may be standardized by titrating a definite volume with N/I0 sodium thiosulphate. See page 240.

VOLUMETRIC

Determination of Antimony in Brass-Permanganate Method

Reagents. Potassium Permanganate. 0.3 g. of KMnO4 is dissolved in water and made to 1000 ec. The reagent is standardized against 25 mg. of pure antimony that has been dissolved in 15 ec. of boiling sulphuric acid and treated as described in the procedure below, under 4 and 5.

Procedure. 1. A sample of 5 grams of brass is dissolved in a 250 cc. beaker in 25 cc. of strong nitric acid (d. 1.42), and after the action has ceased the solution is boiled to expel the oxides of nitrogen. Now 125 cc. of boiling water are added and the solution allowed to settle for an hour or more, keeping the temperature just below boiling. The tin and antimony precipitates are filtered on double 9 cm. closely woven filter papers, keeping the solution hot, and then washed with boiling water. The filtrate is discarded.

- 2. The papers and residue, transferred to a 350 cc. beaker, are treated with 25 ec. of strong nitrie acid (d. 1.42), 5 grams of ammonium persulphate, and 15 cc. of strong sulphurie acid (d. 1.84) and boiled down to strong fumes. (The reaction may be conveniently carried out in a "copper flask" of pyrex glass.) If the solution is brown, 5 ce. of strong nitric acid are added to the cooled solution and about 1 gram additional of persulphate and the boiling to fumes repeated.
- 4. When the solution is colorless, it is cooled, 20 cc. of water added, together with 20 cc. strong hydrochloric acid (d. 1.20) and (cautiously) 1 gram of sodium sulphite and the SO₂ completely expelled by gentle heating for 10 minutes, or longer.
- 5. The solution is diluted with 200 cc. of water, and cooled under running water to 10° to 12° C., then titrated with the standard potassium permanganate solution to a decided pink color.

Notes. Autimony is precipitated quantitatively with meta-stannic acid in alloys containing a large amount of tin.

The filter paper is destroyed by ammonium persulphate and nitric acid, while tin and antimony go into solution with the sulphuric acid. Funning nitric and sulphuric acids may be used, in place of the persulphate and nitric acid, but are not so efficient.

The solution is kept hot to prevent solution of the meta-stannic acid.

Arsenic in the alloy necessitates a correction.

In case of alloys containing considerable amounts of tin and antimony, smaller samples should be taken and stronger potassium permanganate solution than is recommended for brass.

Should the oxides remain undissolved upon furning with sulphuric acid, a small piece of filter paper added (a inch square) will effect reduction and solution of the oxides. The solution should be heated until the earbon of the filter is destroyed and the solution clears and becomes colorless.

Determination of Small Amounts of Antimony

Details of this procedure were worked out by Mr. W. Shelton, under the direction of Mr. W. C. Ferguson, chief chemist, and Mr. E. Fitzpatrick, first assistant chemist, Nichols Copper Company. The method is accurate and is of special value in determining traces of antimony in copper and in alloys. Since arsenie may also be determined a separation by distillation is necessary if the latter is present. (See pages 32, 37.)

Description of Generator

The generator consists of three separate parts:

- I. Glass cap which is placed over funnel A, to hold the disc of test paper in place.
- 2. F-G, this part of the apparatus has two small parts: F, which is a tube of glass $\frac{1}{4}$ " long, $\frac{1}{4}$ " wide, fitted into a rubber tube G, $\frac{1}{4}$ " wide which in turn is fitted into the lower part of funnel A. The part F is a very important one and care should be taken to have exactly the same size glass tubing and that distance from the top of A to top

The cutire apparatus consists of parts, A, B, C, D, E, F, G.

A. The funnel for test paper.

B. Bulb for holding cotton saturated with lead acctate to absorb any H₂S gas

should any be present when generator is operating. Use 0.5 gms, of cotton.

- C. This part extends to E, which has two purposes: No. 1. For introducing acid, II₂O, the test, etc., without opening the apparatus. No. 2. As a safety valve, should D. Upper part acts as condenser. The lower part is ground to fit the buttle No. 3.

 E. This part is explained in C.

 3. This part is the bottle which has 250 cc. capacity with a ground mouth to receive

the No. 2 part of generator.

Note: All generators must be made and assembled as nearly uniform as possible to assure concordant results.

4. This figure shows the manner in which the test is placed on funnel A, Fig. 2, and how the cap, Fig. 1, fits over and holds the test paper in position.




Fig. 1a. Fitzpatrick Apparatus for Determining Traces of Antimony.

Chemicals and Solutions

All chemicals and solutions must be previously tested for arsenic and antimony before using.

HCl-C.P. Cone. redistilled, As and Sb free.

HNO2-C.P. Conc.

NH₄OH-C.P. Conc.

Fe₂(NO₃)₂-5 lbs. to 9 liters, ahout 3% solution.

KClO₁—use dry crystals. FeCl₁—2 lhs. to 2 liters. ZnCl₂—20 lbs. to 9 liters HCl (purified by dissolving 15 gms. zinc in 500 ee, of the above stock solution).

Zinc Shot-Wash in dilute HCl before using.

SnCl₂ solution---52.5 grs. per liter.

5% HgCl₂ used for test paper. 5 gr. to 100 cc. H₂O. (Cut with die into circles of 14" in diameter.)

10% Pb. (C₂H₃(r₂)₄ for cotton. 10 grs. to 100 cc. H₂t). 5% NH₂(OH₂ for developer of test paper, 200 cc. NH₂(OH per liter.

1% AuCl. solution.

Preparation of Test Paper. The paper used must be selected, when purchased, for evenness of thickness and texture in sheets of 24" x 40"

The above sheets are cut in half and saturated with a 5% HgCl, solution—the wet sheet is then placed on a glass plate and the surplus solution is squeezed out with a 10" rubber roller, which is rolled over the paper twice. Care must be exercised to roll the paper evenly and with good pressore using the same conditions for each sheet. The sheet is now hung over a line to dry, in a warm place away from the sunlight or any influence of hydrogen sulphide. Do not dry paper in oven. When dry the paper is cut with die into pieces of 13" in diameter. Keep the discs of test paper in a darkbrown hottle and away from the light until used.

Enough test paper should be made at one time to last for about 3 months.

Each new lot made should be tested with known amounts of As and Sb and compared with standards, before using. Should they not check close it is advisable to make

new set of standards from the test paper just made.

Preparation of Lead Acetate Cotton. A roll of absorbent cotton is opened and saturated with a 10% solution of lead acctate and surplus drained off, then hing on a line to dry in a warm place away from the influence of hydrogen sulphide. Do not dry in oven. When dry, place in stoppered bottle until used.

Precautions

Blank. A blank test should be run with each day's work, using all the reagents used in actual tests.

The stain obtained on test paper from blank is subtracted from the actual test. Limits. The limits of As or Sb that can be determined by this method must be within the following figures:

> As separately from .00002 grs. to .00010 grs. Sb separately from .00002 grs. to .00015 grs.

Checks. A 10 grs. sample of standard copper known to be free from As or Sb is

weighed out and known amounts of As and Sb are introduced.

Distillation. The distilling apparatus should not be used for any other tests when

the As or Sb is known to be higher than the limits for this work.

The zine shot must be cleaned with dilute IICl and washed with distilled Zinc. water each day to insure proper action in generator, and to expel any sulphide present

which would spoil the test

Generator. The presence of nitrates, chlorates, or compounds of copper interfere with generation of arsine and stibine, so care must be exercised to have these compounds elimmated.

Large quantities of ferrous and ferrie compounds interfere atso in the generation of stibine to some degree. The small amount of Fe that gets into the test from the process of distillation is overcome by the addition of 2 ec. stannous chloride—at times more may be required.

Uniformity. Uniformity must be strictly adhered to throughout the test. In the determination of antimony in presence of arsenic the removal of the latter is necessary. This is accomplished by distillation of AsCl₂ according to the procedure outlined on page s 32, 37.

Standard Antimony Solution and Standard Stains

Antimony Solution. A stock solution is made up by weighing out 0.553 gms. KSbO₃C₄H₄O₄ which is dissolved in distilled water and made up to 2000 cc. which represents 1 cc. = .0001 g. Sb.

From the above stock solution take 100 cc. and make up to 1000 cc. this solution now equals 1 cc. = .00001 g. Sb, which is used for making the standard stains and introducing into checks.

Outline of the Method

Preparation of Standard Stains. Extreme eare must be taken when preparing the standard stains.

Wash the generator thoroughly with distilled water, place freshly prepared lead acetate cotton in the bulb, B, No. 2, and see that the top of part F, No. 2, is exactly $\frac{5}{16}$ " from the top of part A, No. 2.

Now introduce into bottle of generator, No. 3, the required amount of As or Sb as desired and then add 50 cc. redistilled HCl, As free, 2 cc. stannous chloride solution and make up to 220 cc. with distilled water.

The disc of mercuric chloride test paper is now placed on top of funnel A, No. 2, and the glass cap, No. 1, is forced over the paper holding it in place.

Now introduce 15 gms. metallic zinc shot and place the No. 2 section with No. 1 attached into the No. 3 or bottle of generator. The apparatus now being assembled, observe that the apparatus is fitted together tightly, because as soon as the zinc is introduced, Arsine and Stibine is generated immediately. Place the generator into the water bath to maintain constant temperature which should be about 70° F. Allow the generator to operate for 1 hour.

The glass cap, No. 1, is now removed and the test paper is developed in a No. 2 beaker with 5% NH₄OH solution for three minutes, then washed 5 times with distilled water. The test paper is now toned with a 1% AuCl₄ solution by allowing the test paper to remain in solution for five minutes. The test paper will now have a violet or purple stain, the intensity depending on the amount of As or Sb introduced. Wash the paper 5 times with distilled water and preserve in 50 cc. glass stoppered bottles containing about 5 cc. water. Keep bottles in dark place, because the stains darken on exposure to light.

Duplicate tests are made, finally selecting of two the one which is the most uniform.

The stains are made to represent the following amounts:

																												Sb
1																												.00002
2	١.																											.00004
																												.00006
																												.00008
																												.00010
U	١.	•		٠	٠		•		•												•						•	.00012
8	•	•	•	٠	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	٠	•	٠	•	•	٠	•	.00014

Procedure for Refined Copper

A blank is run with all tests.

Weigh 10 gms. of the shot or drilled sample into a No. 3 beaker. Add 50 cc. Conc. HNO₂, C.P. As free, let stand covered with watch glass until the action has subsided. Now place beaker on wire gauze over Bunsen flame and heat until all the copper is dissolved.

Remove from flame, dilute to 150 cc. with distilled water (if too basic add a few drops of HCl to clear the solution). Add 2 cc. ferric nitrate solution, stir, then make ammoniacal by adding C.P. ammonium hydrate (As free). Bring to boiling. Remove from flame and filter through a 15 cm. fluted Perfection filter paper. Immediately wash the filter paper free from copper compounds with hot water, using dilute ammonia where necessary to wash out any copper salts that have crystallized.

The precipitate (which contains both As and Sb) is dissolved off the filter with hot dilute hydrochloric acid, by means of a wash bottle into a No. 4 casserole. Wash the filter three times with hot water.

Add a pinch of KClO, to the casserole, cover with watch glass, place the casserolo in an asbestos cut out over Bursen burner and boil the contents down to 10 cc., taking care that it does not roast on the sides.

Distillation. Transfer the contents of the casserole to the distilling apparatus. Add 20 cc. ferrous chloride and 20 cc. zinc chloride solution, and distill until the contents of flask begins to froth. Now add, drop at a time, 35 cc. HCl, through the dropping funnel which is connected to flask. Distil until all the HCl is out of the funnel and out of the flask.

The distillate is received in a No. 4 beaker having 40 cc. H₂O in which both the As and Sb is contained.

The above distillate is now transferred and washed from the beaker into the special designed generator. Add 2 cc. stannous chloride which insures a complete reduction of any ferric compounds present. Dilute the contents of generator to 220 cc. Place disc of HgCl₂ test paper on the funnel top, then put on cap to hold in place. Add 15 gms. metallic zinc or 1 No. 6 porcelain spoonful. Take care that the generating apparatus is properly closed, then place into water bath to maintain constant temperature which should be about 70° F. The apparatus is allowed to operate for one hour during which timo the arsine and stibine generated shall effect the HgCl2 test paper, causing a yellow or orange colored spot which varies in color and size according to the amount of As and Sb present. The paper is now removed from the apparatus and developed in a No. 2 beaker containing 5% ammonium hydrate solution for three minutes. The color of the spot now changes to a brownish black. Wash test paper five times with distilled water. Now cover the test paper with 10 cc. of 1% gold chloride solution which tones the color of the spot to a violet or purple huo that fixes it so comparison can be made with the standard stains or spots to determine the amount of arsenic or antimony in the sample.

Determination of Antimony in Tartar Emetic

Iodine in the presence of sodium bicarbonate oxidizes trivalent antimony to the pentavalent form as shown by the reaction:

$$K(SbO)C_4H_4O_6+6NaHCO_2+I_2$$

= $Na_3SbO_4+KNaC_4H_4O_6+2NaI+H_2O+6CO_2$.

Procedure. 10 grams of tartar emetic are dissolved in water, the solution diluted to 500 cc. and 20 cc. taken for analysis. This is diluted to 100 cc. 25 cc. of 2 per cent sodium bicarbonate are added and the mixture titrated with N/10 iodine reagent.

1 cc. N/10 I = 0.016617 g. $K(SbO)C_4H_4O_6 \cdot \frac{1}{2}H_2O$

ARSENIC

A54 at.wt. 74.96— cryst. sp.gr. $5.73 \atop amorp.$ m.p. $850 \atop 4.72$ b.p. subl. 554° $< 360^{\circ}$ Oxides, As₂O₃, As₂O₃.

DETECTION

Hydrogen sulphide precipitates the yellow sulphide of arsenie, As₂S₂, when passed into its solution made strongly acid with hydroehloric acid. If the solution contains more than 25% hydrochloric acid, (sp.gr. 1.126) the other members of the hydrogen sulphide group do not interfere, as they are not precipitated from strong acid solutions by hydrogen sulphide. Arsenic sulphide is soluble in alkaline carbonates. (Antimony sulphide, Sb₂S₂, reddish yellow, is insoluble in alkaline carbonates.)

Volatility of the chloride, AsCl, is a means of separation and distinction of arsenic. Details of the procedure are given under "Separations." The distillate may be tested for arsenic as directed above.

Traces of arsenic may be detected by either the Gutzeit or Marsh test for arsenic. Directions for the Gutzeit test are given at the close of the volumetric procedures.

Distinction between Arsenates and Arsenites. Magnesia mixture precipitates white, MgNH₄AsO₄, when added to anunoniacal solutions containing arsenates, but it produces no precipitate with arsenites.

Red silver arsenate and yellow silver arsenate are precipitated from neutral solutions by animoniacal silver nitrate. An arsenate gives a yellow precipitate with ammonium molybdate solution.

ESTIMATION

The determination of arsenie is required in the valuation of native arsenie, white arsenie, As₂S₃; ores of arsenie—orpiment, As₂S₃; realgar, As₂S₂; pyrargyrite, As₂Sb₃; arsenopyrite, or mispickel, FeSAs; cobaltite or cobalt glance, CoSAs; emaltite, CoAs₃; niccolite. NiAs. The substance is estimated in copper ores, in speiss, regulus: in iron precipitates (basic arsenate). It is determined in paint pigments, Scheel's green, etc. The element is determined in shot alloy and in many metals. It is estimated in germicides, disinfectants, and insecticides—Paris green, lend arsenate, zine arsenite. Traces are looked for in food products and in substances where its presence is not desired.

Preparation and Solution of the Sample

In dissolving arsenic compounds it will be recalled that the oxide, As₂O₂, is not readily acted upon by dilute acids—hydrochloric or sulphuric. The compound is soluble, however, in alkaline hydroxides and carbonates. Nitric

Van Nostrand's Chem. Annual-Olsen-3d Ed.

Chapter contributed by Wilfred W. Scott.

acid oxidizes As₂O₂ to the higher oxide, As₂O₅, which is soluble in water. The sulphides As₂S₂ and As₂S₅ are practically insoluble in hydrochloric or sulphuric acids, but are dissolved by the fixed alkalics and alkali sulphides. All arsenites, with the exception of the alkali arsenites, require acids to effect solution.

Pyrites Ore and Arseno-pyrites. The amount of the sample may vary from 1 to 20 grains, according to the arsenic content. The finely ground sample in a large easserole is oxidized by adding 10 to 50 cc. of bromine solution (75 cc. KBr+50 cc. liquid Br+450 cc. H₂O) covering and allowing to stand for fifteen minutes, then 20 to 50 cc. of strong nitric acid are added in three or four portions, allowing the action to subside upon each addition. The glass cover is raised by means of riders, and the sample evaporated to dryness on the steam bath; 10 to 25 cc. of hydrochloric acid are now added and the sample again taken to dryness. Again 10 to 25 cc. of hydrochloric acid are added and the sample taken to dryness. Finally 25 cc. of hydrochloric acid and 75 cc. of water are added, and the mixture digested over a low flame until all the gangue, except the silica, is dissolved. The solution is now examined for arsenic by distillation of the arsenic after reduction, the distillate being titrated with standard indine solution according to directions given later.

Arsenous Oxide. The sample may be dissolved in caustic soda, the solution neutralized with hydrochloric acid, and the resulting sample titrated with iodine.

Fusion Method. One gram of the finely powdered mineral is fused in a nickel crucible with about 10 grams of a mixture of potassium carbonate and nitrate, 1:1, and the melt extracted with hot water. Two hundred cc. of a saturated solution of SO₂ is added to the filtrate to reduce the arsenic, the excess of SO₂ then expelled by hoiling, the solution diluted with dilute sulphuric acid, and arsenic determined in the filtrate.

Arsenie in Sulphurie Acid. Arsenous acid may be titrated directly with iodine in a 20- to 50-gram sample, which has been diluted to 200 to 300 cc. with water and nearly neutralized with ammonium hydroxide and then an excess of sodium acid carbonate added, followed by the iodine titration.²

Arsenic Acid in Sulphuric Acid. Twenty-five ce. of the acid containing about 0.1% arsenic or a larger volume in case the percentage of arsenic is less than 0.1% As₂0₃ (the sp.gr. of the acid being known) are measured out into a short-necked Kjeldahl flask. About half a gram of tartaric acid and 2 grams of fused, arsenic-free notassium bisulphate are added and the acid heated over a low flame until the liberated carbon is completely oxidized and the acid again becomes clear, c.g., a pale straw color. It is not advisable to heat to violent funing, as a loss of arsenic is then apt to occur. The cooled acid is poured into about 300 cc. of water, the excess acid nearly neutralized with ammonia, bicarbonate of soda added in excess and the arsenous acid tirated with standard iodine. Total arsenie as As₂O₃ minus arsenous arsenie as As₂O₃ = arsenic arsenic in terms of As₂O₃. This result multiplied by 1.4616 = As₂O₃.

Arsenic in Hydrochloric Acid. The arsenic in 20 to 100 cc. sample is reduced by ferrous chloride, the arsenic distilled according to directions given later, and the distillate titrated with iodine.

¹0 1 arsenie determined on a 20-gram sample.

² SO₂ should be expelled by heat or by a current of air before treating with the alkali.

Arsenic in Organic Matter. 1 0.2 to 0.5 gram of the sample finely powdered is oxidized by mixing with 10 to 15 grams of sodium carbonate and sodium peroxide, 1:1, in a nickel crucible, a portion of the fusion mixture being spread over the charge. After heating gently for fifteen minutes, the fusion is completed by heating to dull redness for five minutes longer. The contents of the crucible are rinsed into an Erlenmeyer flask after extraction with water. and the solution made acid with dilute sulphuric acid, 1:1. The mixture is boiled down to 100 cc., I to 2 grams of potassium iodide added and the solution further concentrated to about 40 cc. lodine is reduced with sulphurous acid or thiosulphate, the solution diluted with hot water and saturated with hydrogen sulphide. Arsenous sulphide is filtered off, washed, dissolved in 15 to 20 ec. of half-normal sodium hydroxide and 30 cc. of hydrogen peroxide (30%) solution added, and the solution boiled. About 12 cc. of dilute sulphuric acid. 1:1, are added, together with I to 2 grams of potassium iodide, the solution concentrated to 40 cc. and free iodione reduced with thiosulphate as before. Arsenic is now titrated, with standard iodine, upon neutralization of the free acid with sodium hydroxide and sodium acid carbonate.

Lead Arsenate. Ten grams of the thoroughly mixed paste or 5 grams of the powder are dissolved by treating with 25 cc. of 10% hot sodium hydroxide solution, and diluted to 250 cc. An aliquot part, 50 cc. (=2 grams paste and 1 gram powder) is placed in an Erlenmeyer flask and 20 cc. of dilute sulphuric acid, 1:1, added, and the solution diluted to 150 cc. About 3 grams of solid potassium iodide are added and the solution boiled down to about 50 cc. (but not to fumes). The liquor will be colored yellow by free iodine! Tenth normal sodium thiosulphate is added drop by drop until the free iodine is neutralized (solution loses its yellow color), it is now diluted to about 250 cc. and the free acid neutralized by ammonium hydroxide (methyl orange indicator), then made slightly acid with dilute sulphuric acid, and an excess of bicarbonate of soda added. The arsenic is titrated with standard iodine.

The arsenic may be reduced by placing the 5t-cc. sample in a Kjeldahl flask, adding 25 cc. of strong sulphuric acid (4.84 sp.gr.), ½ gram tartaric acid and 2 grams acid potassium sulphate, KHSO₄, and digesting over a strong flame until the organic matter is destroyed and the solution is a pale yellow color. The cooled acid is diluted and neutralized, etc., as directed above.

Water-soluble Arsenic in Insecticides. Rapid Works Test. Two grams of the paste is digested with 1000 cc. of water at 90° t! for five minutes, in a graduated 1000-cc. flask. An aliquot portion is filtered and the arsenic determined by the Gutzeit method.

Water-soluble arsenute may be titrated directly with iodine in presence of sodium bicarbonate.

Zinc Arsenlte. About 5 grams of powder or 10 grams of paste are taken and dissolved in a warm solution containing 300 ec. of water and 25 ec. of strong hydrochloric acid. The cooled solution is diluted to 500 ee. and 100-ec. portions taken for analysis. The acid is partly neutralized with ammonium hydroxide and 50 ec. of a saturated solution of ammonium oxalate added (to prevent precipitation of the zinc as ZnCO₂), and an excess of sodium bicarbonate, NaIICO₂. Arsenic is now titrated with iodine as directed later.

Soluble Arsenic in Zinc Arsenite. One gram sample is rubbed into an

¹Organic matter may be destroyed by heating the substance on addition of 10% H_sSO_4 and solid $(NH_4)_sS_2O_4$.

emulsion with several portions of water until the whole is in suspension. cloudy liquor is diluted to 1000 ec. and a portion filtered through a 1-in. asbestos mat on a perforated plate, the asbestos being covered with a layer of filter paper. The first 50 cc. are rejected. One hundred cc. of the clear filtrate (= 0.1 gram) is treated with 10 cc. of strong sulphuric acid, 0.05 gram, Fe₂O₃ (use ferrie ammonium sulphate) and ½ cc. of 80% stannous chloride solution and heated until colorless. Arsenic is now determined by the Gutzeit method, using the larger-sized apparatus.

Arsenic Acid, Alkali Arsenates, etc. The sample is dissolved in 20 to 25 ec. of dilute sulphuric acid, 1:1, in an Erlennieyer flask, and reduced by addition of 3 to 5 grams of potassium iodide, the action being hastened by placing the mixture on a steam bath. The iodine liberated is exactly neutralized with thiosulphate and the arsenous acid titrated with iodine according to the procedure given later.

Arsenic in Steel, Iron, Pig Iron, etc. One to 50 grams of steel, etc., may be treated according to the scheme for pyrites. If a large sample is taken, it is advisable to treat it in a 500-cc. flask, connected with a second flask containing bromine, to guard against loss of arsenic by volatilization. When the sample has dissolved it is taken to dryness (the bromine in the second flask being combined with it) and treated as directed in pyrites. Arsenic chloride, AsCls, is transferred to the distilling flask with strong hydrochloric acid, and arsenic separated from the iron by volatilization of reduced chloride according to the procedure given below.

Arsenic in Copper. Arsenic is precipitated with iron by the basic acetate method, and thus freed from copper. Details of procedure are given under the determination of impurities in copper in the chapter on the subject.

Notes. In the decomposition of the sample Low recommends the addition of a little sodium sulphide to ores containing oxides. To prevent loss of arsenic during the treatment with H2S he uses a flask with a two-hole rubber stopper through which passes an inlet tube reaching to the bottom of the flask and an exit tube, the latter a thistle tube containing a little absorbent cotton soaked with dilute NaOH to retain any arsenic escaping from the flask.

Iron sulphate dissolves slowly, so that if much is present in the ore time must be allowed for this to dissolve.

As arsenous chloride is volatile, great care must be exercised in heating solutions

containing HCl and arsenous sults as a loss will occur. B.p. 113.9°.

The ore may be brought into solution by fusion with a mixture of sodium carbonate, potassium nitrate and zinc oxide, 1:1:2. The fusion being made in a platimum dish. The potassium iodide procedure may be followed for reduction of arsenic. (See Lead Arsenate.)

SEPARATIONS

Isolation of Arsenic by Distillation as Arsenous Chloride 1


By this method arsenic may be separated from antimony, tin, and from other heavy metals. It is of special value in the direct determination of arsenie in iron ores, copper ores, and like products and has a wide application. The procedure depends upon the volatility of arsenous chloride at temperatures lower than the other heavy metals. In a current of HCl gas, arsenous chloride begins to volatilize below 108° C., and is actively volatile at 120° C.; antimony starts to volatilize at 125° C., but is not actively volatile until a temperature of 180° has been reached. The boiling-point of ursenous chloride, AsCl₂, is 130.2°; antimony trichloride, SbCl₃, is 223.5°; and that of stannous ehloride, SnCl₂, is over 603°; other chlorides having still higher boiling-points. Tin in its higher form, SnCl₄, is readily volatile, boiling-point is 114° C., so that it is necessary to have it in its divalent form to effect a separation from arsenic. When heavy metals are present in the residue remaining from the arsenie distillate, or when zine eldoride is added to raise the boiling-point, antimony may also be separated by distillation by carrying the solution to near dryness. adding concentrated HCl by means of a separatory funnel, drop by drop, during further distillation of the concentrate. Arsenic may be determined in the distillate (first portions) either gravinictrically or volumetrically.

Procedure. If arsenic is present as arsenic chloride, as prepared in the method for solution of iron ores, the sample may be transferred directly to the distillation flask by means of concentrated, arsenic-free hydrochloric acid. If a preliminary separation of other metals has been made and arsenic is present (along with antimony and tin) as a sulphide, it is oxidized by addition of concentrated HCl and sufficient potassium chlorate to cause solution and oxidation of free sulphur, and the chlorate decomposed by evaporation to dryness; or if preferred, by evaporation of the alkaline solution to dryness, oxidation with funning nitric and re-evaporation to dryness to expel the nitric acid. The residue is taken up with hydrochloric acid and washed into the flask with strong hydrochloric acid as directed above.

Distillation. The sample, in a half-liter distilling flask (Fig. 1, "5") is made up to about 150 ec. with concentrated hydrochloric acid and about 5 grams of cuprous chloride, Cu₂Cl₂, are added. The apparatus is connected up as shown in the illustration, Fig. 1. The end of the condenser dips into 400 ec. of cold water in a large beaker (1 liter) or flask ("4"). The solution is cooled by placing it in ice-water or cold running water. The sample is saturated with dry hydrogen chloride gas generated by dropping concentrated sulphuric acid into strong hydrochloric acid ("3") and passing the gas through

¹ J. E. Stead's Method, R. C. Roark and C. C. McDonnell, Jour. 1nd. Eng. Chem., VIII, 4, 327 (1916).

sulphurie acid (sp.gr. 1.84) as shown in cut. When the point of saturation is reached the gas begins to bubble through the solution instead of being absorbed by it. When this occurs, heat is applied and the solution brought to boiling, the current of HCl gas being continued. At a temperature of 108 to 110° C. the first 100 ce. will contain practically all of the arsenic. About



F10. 1 -Apparatus for the Distillation of Arsenous Acid.

two-thirds of the solution is distilled off. It is advisable to add more hydrochloric acid to the residue in the flask, together with euprous chloride, and repeat the distillation into a fresh lot of water. This may be done during the estimation of arsenie in the first distillate.

Arsenie may be determined in the distillates either gravimetrically or volumetrically. The volumetric procedures for arsenic, in this isolated form, are generally to be preferred, since they are both rapid and accurate. For amounts over 0.5% arsenic, the iodine method is recommended, for smaller amounts (arsenic in crude copper), precipitation with silver nitrate and titration of the silver salt is best. Exceedingly small amounts are best determined by the Gutzeit method, page 46.

In place of the large bottle shown, a smaller wash bottle may be used filled with eoneentrated hydrochlorie acid, the bottle contains an inlet tube dipping to the bottom and an exit tube eonnected to the distillation flask containing the arsenie. The receiving flask is eonneeted with an aspirator and air drawn through the system. HCl is swept into the distillation flask during the arsenie distillation, keeping the solution concentrated with HCl gas.

The inlet funnel is filled about half full with hydrochloric acid (sp.gr. 1.2).. The outlet of the condenser tube is caused to dip just beneath the surface of 100 ce. of distilled water, containing a lump of ice. The solution in the distillation flask is heated to boiling; concentrated hydrochloric acid is introduced through the funnel drop by drop at the rate sufficient to replace the evaporation. All the arsenic usually distils over in half an hour. At this time the beaker holding the condensate is replaced by another with 100 cc.




Fig. 2.—Knorr Arsenic Distillation Apparatus.

of water. And the distillation continued about 15 minutes. Test this distillate to ascertain whether any arsenic is present. The arsenous chloride thus obtained is titrated with standard iodine according to the procedure described on page 44. The free HCl is first neutralized with a fixed alkali and then made faintly acid with HCl. Sodium bicarbonate is now added in excess and the titration with iodine made according to the customary procedure.

Commercial hydrochloric acid invariably contains arsenie, so this must be purified by redistillation in presence of an oxidizing agent to oxidize the arsenic to the non-volatile arsenic pentachloride, AsCl_b, form, (Fig. 5) or by treatment with H₂S and filtration. A blank run should be made on the reagents used, especially when traces of arsenic are to be determined.

39b

• Cuprous Chloride. This is used to reduce arsenic. At least 2 grams CuCl should be used per each gram of iron present. In the distillation, HCl gas (generated in n flask containing strong sulphuric acid by allowing hydrochloric acid to flow in through a thistle tabe, drop by drop) may be passed into the solution containing the arsenic, in place of adding strong hydrochloric acid.

Hydrazine Distillation Method. Weigh a suitable amount of sample into a 275 ec. Pyrex sulphur flask. Treat with a small amount of HNO₂ (5-10 ec.), and a pinch of potassium chlorate. Take to dryness. Add 3-5 cc. HCl and take again to dryness. Add 20 ec. 1-1 HCl and boil several minutes. Filter, if insoluble is appreciable, into another flask, and wash. Add 30 cc. HCl, ½ gm. NaBr and ½ gm. hydrazine sulphute, (NH₂)₂SO₄. Set the flask on a small electric plate, and at the same time, insert in the flask a two-hole stopper, in one hole of which is a separatory funnel, and in the other a glass tube leading to an 8-in. Allihn condenser, set vertically. The lower end of the condenser is immersed in cold water contained in a No. 3 beaker, which sits on a block of wood. Have the cock of the funnel open. Have a good stream of cold water running through the jacket of the condenser.

Distill until the volume in the flask has been reduced to 20 ec. Close the cock of the funnel, add 20 cc. HCl, remove the block of wood from underneath the beaker and hold the beaker in one hand. Holding the beaker at such a height that no liquid may be sucked back into the flask, open the funnel cock and let the acid run into the flask. Now, place the block under the heaker, and distill until liquid in flask is again reduced to 20 ec.

Remove the flask from the plate, and disconnect it from the condenser. Wash the condenser, allowing washings to run into the distillate. Remove the beaker from under the condenser. Add 8-10 drops of methyl orange (1 gm. of salt per liter of water). Make the solution alkaline with NH₄OH, then just acid with HCl. Cool. Add 10 gm. NaIICt)₃ and 10 ce. starch solution (10 gm. soluble starch boiled in a liter of water; cooled).

Titrate with iodine solution, one cc. of which equals about .005 gm. As₂O₃. Subtract a blank determination which amounts to .4 or .5 cc.

40 ARSENIC

Separation of Arsenic from Antimony and Tin by Precipitation as Suiphide in a Strong Hydrochloric Acid Solution

This procedure for isolation of arsenic depends upon the insolubility of the sulphide of arsenic in strong hydrochloric acid, whereas that of antimony dissolves. The sulphide of tin is also soluble.

Procedure. The metals present in their lower conditions of oxidation are precipitated as sulphides in presence of dilute hydrochloric acid (5% solution) to free them from subsequent groups (Fe, Al, Ca, etc.). The soluble members of the hydrogen sulphide group are now dissolved and separated from copper, lead, etc., by caustic as follows: The greater part of the washed precipitate is transferred to a small casserole, that remaining on the filter paper is dissolved off by adding to it a little hot dilute potash solution, catching the filtrate in the casserole. About 5 grams weight of solid potassium hydroxide or sodium hydroxide is added to the precipitate. Arsenic, antimony, and tin sulphides dissolve. The solution is filtered if a residue remains, and the filter washed. This preliminary treatment is omitted if alkuline earths and alkulies are the only contaminating elements present.

The easserole containing the sample is covered and placed on a steam bath. Chlorine is now conducted into the warm solution for an hour, whereby the alkali is decomposed and antimony and arsenic oxidized to their higher state. Sufficient hydrochloric acid is added to decompose the chlorate formed, and the uncovered solution evaporated to half its volume. An equal volume of hydrochloric acid is added and the evaporation repeated, to expel the last trace of chlorine. The acid solution is washed into an Erlenneyer flask, cooled by ice to 0° C. and two volumes of cooled, concentrated, hydrochloric acid added. H₂S gas is rapidly passes into this solution for an hour and a half. The flask is now stoppered and placed in boiling water for an hour. The yellow arsenic sulphide, As₂S₃, is filtered through a weighed Gooch crucible, washed with hydrochloric acid, 2:1, until free from antimony, i.e., the washing upon dilution remains clear. The residue is now washed with water, followed by alcohol, and may be dried and weighed as As₂S₃, or determined volumetrically. Antimony and tin are determined in the filtrate. McCay recommends washing As₂S₃ with alcohol, CS₂ and finally alcohol.

The sulphide may be dissolved in concentrated sulphuric acid by heating to sulphuric acid funes and until the solution becomes clear. No arsenic is lost, provided the heating is not unduly prolonged. Fifteen to twenty-five minutes is generally sufficient to dissolve the sulphide and expel SO₂, etc. The acid may be neutralized with ammonia or caustic, made again barely acid and then alkaline with bicarbonate of soda, and arsenous acid titrated with iodine.²

² J. and H. S. Pattinson, Jour. Soc. Chem. Ind., 1898, p. 211.

¹ Le Roy W. McCay, Chem. News, 56, 262 (1887).

GRAVIMETRIC METHODS FOR DETERMINATION OF ARSENIC

As in the case of antimony, the accuracy and rapidity of the volumetric methods for the determination of arsenic make these generally preferable to the more tedious gravimetric methods. The following methods, however, are of value in certain analytical procedures.

Determination of Arsenic as the Trisulphide, As₂S₃

Arsenic acid and arsenates should be reduced to the arsenous form before precipitation as the sulphide. The procedure is especially adapted to the isolation of arsenic from other elements, when this substance is present in the solution in appreciable quantities, advantage being taken of the extreme difficulty with which arsenous sulphide, As₂S₃, dissolves in hydrochloric acid solution.

Procedure. The solution containing arsenie in the arsenious form is made strongly acid with hydrochloric acid and hydrogen sulphide passed into the cold solution to complete saturation. The hydrogen sulphide pressure generator is recommended for this treatment. Figs. 3 and 4. The precipitate is filtered into a weighed Gooch crucible (previously dried at 105° C.), the compound dried at 105° C. to constant weight and weighed as As_SS₄.

```
 \begin{split} F_{8}ctors, \quad & As_{2}S_{3}\times 0.6091 = grams \ As, \\ & As_{2}S_{3}\times 0.8042 = grams \ As_{2}O_{3}, \\ & As_{2}O_{3}\times 1.1616 = grams \ As_{2}O_{4}, \\ & As_{2}O_{4}\times 1.3134 = grams \ H_{2}As_{2}O_{4}\cdot \frac{1}{2}H_{2}O, \\ & As_{2}S_{3}\times 1.2606 = grams \ As_{2}S_{4}. \end{split}
```

Note. Arsenic may also be determined as arsenic sulphide by passing a rapid stream of $\rm H_2S$ into a cooled solution of arsenic acid containing at least two parts of concentrated hydrochloric acid for each part of water present in the solution.


Determination of Arsenic as Magnesium Pyroarsenate

The method worked out by Levol depends upon the precipitation of arsenie as MgNH₄AsO₄·6H₄O, when magnesia mixture is added to an ammoniaeal solution of the arsenate. Although 600 parts of water dissolve 1 part of the salt, it is practically insoluble in a 2½ per cent ammonia solution, 1 part of the anhydrous salt requiring 24,558 parts of the ammonia water according to Virgili.¹ The compound loses 5½ molecules of water at 102° C. and all of the water when strongly ignited, forming in presence of oxygen the stable magnesium pyronrsenate, Mg₂As₂O₁, in which form arsenie is determined.

Procedure. The solution containing the arsenie, in the form of arsenate, and having a volume not exceeding 100 cc. per 0.1 gram arsenic present, is treated with 5 cc. of concentrated hydrochloric acid, added, with constant stirring, drop by drop. Ten cc. of magnesia mixture are added (Reagent = 55 grams MgCl₂+70 grams NH₄Cl₄+650 cc. H₂O and made up to 1000 cc. with NH₄OH, sp.gr. 0.96), for each 0.1 gram of arsenic present. Ammonia solution (sp.gr. 0.96) is added from a burette, with stirring, until the nixture is nentralized (a red color imparted to the solution in presence of phenolphthalein indicator), and

¹ Average of three results. J. F. Virgili, Z. anal. Chem., 44, 504 (1905).

then ammonia added in excess equal to one-third the volume of the neutralized solution. The precipitate is allowed to settle at least twelve hours and is then filtered into a weighed Gooch crucible and washed with 2.5% ammonia until free from chloride. After draining as completely as possible by suction the



F10. 3.—Scott's Hydrogen Sulphide Generator.

Fig. 3 shows a convenient form of a generator for obtaining hydrogen sulphide gas under pressure. The apparatus is the writer's modification of the Banks' generator sold by E and A. and is designed for large quantities of hydrogen sulphide gas. The cylinder A A is constricted, as shown, to support perforated lead disk G, upon which rests the iron sulphide. The loven end of the chamber is closed to eatch small particles of FcS that may be carried through the perforations of the disk. Small upentups admit the acid to A'. The level of the acid is below the disk G, so that the acid only romes in contact with the sulphide when pressure is applied by means of the rubbor hulb. E, the stopcock S' being open and S' closed. The mercury gauge C is adjusted to blow out at a given pressure, to prevent accident, the bulb D preventing the mercury from being blown out of the apparatus. A small opening in D silows the escape of the gas. When the apparatus is in operation, II is connected to an empty heavy-walled bottle, which in turn is attached with glass tube connection to the pressure flask in which the precipitation of the sulphide in A. The entire system will now be under the pressure indicated by the gauge C. The pressure is released by opening the stopcock S's and the flask containing the precipitate then disconnected. The reservoir is designed to hold shout two liters of acid, and the explander containing the sulphide is of sufficient capacity to hold over one pound of FeS, so that the apparatus will deliver a large quantity of hydrogen sulphide.

precipitate is dried at 100° and then heated to a dull red heat (400 to 500° C.), preferably in an electric oven, until free of ammonia. The temperature is then raised to a bright red heat (800 to 900° C.) for about ten minutes, the crucible then cooled in a desiccator and the residue weighed as Mg₂As₂O₇.

Factors, $Mg_2As_2O_7\times0.4827 = As$, or $\times 0.6373 = As_2O_3$, or $\times 0.7403 = As_2O_4$, or $\times 0.7925 = As_3S_3$.

Notes. In place of an electric furnace the Gooch crucible may oe placed in a larger non-perforated crucible, the bottom of the Gooch being 2-3 mm. above the bottom of the outer crucible. The product may now be heated in presence of a current of oxygen passed through a perforation in the covering lid of the Gooch, or




Fig. 4. -Urbasch's Hydrogen Sulphide Generator.

The apparatus designed by Urbasch (Chem. Zeit. (1910) 34, 1010. The Anniyst (1910) 35, 558), shown in Fig. 2, enables a constant supply of gas and its saturated aqueous solution to be obtained. The bottle IV is charged with hydrochloric acid, and iron sulphide is placed in III. The hydrogen sulphide is passed through the water in H until a saturated solution is obtained. Water is placed at land II. If gas is required the taps A and B are opened and Its drawn ofform A. Bydrogen sulphide water is obtained by opening the pinch cock C of the burete, the hydrogen sulphide water from the vessel II. The container is made of dark-colored glass to protect the hydrogen sulphide water from light. Water may be drawn into II, when required by opening the piach cock leading to the bottle I.

in place of the oxygen, a thin layer of powdered NH₄NO₄ may be placed on the arsenate residue and the heat gradually applied until the outer crucible attains a light red glow.

VOLUMETRIC METHODS FOR THE DETERMINATION OF ARSENIC

Oxidation of the Arsenous Acid with Standard Iodine 1

This procedure is applicable for the determination of arsenie in acids, after reduction of arsenie to its arsenous form, for valuation of arsenic in the trioxide, for determination of arsenic isolated by distillation as arsenous chloride, for arsenic in arsenies and reduced arsenates in insecticides, etc. The method depends upon the reaction— $As_2O_3+2H_2O+2I_2=As_2O_6+4HI$. The liberated hydriodic acid is neutralized by sodium bicarbonate. The trace of excess iodine is detected by means of starch, a blue color being produced.

Procedure. If the solution is acid, it is neutralized by sodium or potassium hydroxide or carbonate (phenolphthalein indicator) then made slightly acid. If the solution is alkaline, it is made slightly acid. Two to 3 grams of sodium bicarbonate are added together with starch indicator and the solution titrated with tenth normal iodine solution, the iodine being added cautiously from a burette until a permanent blue color develops.

One ee. N/10 iodine = 0.00375 gram As, or 0.004948 gram As₂O₃. As₂O₃×1.1616 = As₂O₅. As×1.3201 = As₂O₃ or ×1.5336 = As₂O₅. As₂O₃×0.7575 = As.

Potassium Iodate Method for Determining Arsenic

The method is specially applieable to determining arsenic in insecticides. The reaction is represented as follows:

$$As_2O_3 + K1O_3 + 211CI = As_2O_5 + ICI + KCI + H_2O$$
.

Procedure. In determining total arsenie the sample is placed in a distilling bulb, connected to a condenser, strong hydrochloric acid added together with cuprous chloride, and arsenious chloride distilled over into an Erlenmeyer flask according to the standard procedure outlined on page 38. If arsenie is high, an aliquot portion of the distillate is taken and the titration made with standard iodate solution as stated later.

¹ Geo. S. Jamison, J. I. E. C. 10, 290-292, 1918.

For determining arsenious oxide in Paris Green or other arsenite 0.15 to 0.4 grams of the sample may be weighed directly into a glass-stoppered bottle (500 cc.) and the titration made.

Iodate Titration. 30 cc. of hydrochloric acid sp.gr. 1.19, 20 cc. of water and 6 cc. of chloroform are added to the solid arsenite. If the arsenic is in solution, sufficient HCl should be present to have the acidity between 11 and 20 per cent HCl. (If this falls below H % HCl thydrolysis of the iodine monochloride will take place. If over 20% HCl the reaction proceeds very slowly.) Potassium iodate solution is now added, rapidly at first, shaking the contents of the bottle. When the iodine that has been liberated during the first part of the titration has largely disappeared from the solution, the stopper of the bottle is inserted and the contents thoroughly shaken. The titration is now conducted cautiously, shaking thoroughly with each addition of the reagent. The titration is complete when after shaking and allowing to stand 5 minutes no color is observed in the chloroform.

Reagent. Contains 3.244 g. of K1O₃ (dried at 140° C.) per 1000 cc.--1 ec. = 0.003 g. As₂O₃.

Volumetric Determination of Arsenic by Precipitation as Silver Arsenate

Bennett's modification of Pcarce's method, combining Volhard's, depends upon precipitation of arsenic, from a solution neutralized with acetic, by addition of neutral silver nitrate solution; the silver arsenate is dissolved in nitric acid, and the silver titrated with standard thiocyanate.

Procedure. 0.5 gram, or less, of the finely powdered substance is fused with 3 to 5 grams of a mixture of sodium carbonate and potassium nitrate (1:1) about one-third being used on top of the charge. The cooled mass is extracted with boiling water and filtered. The filtrate, containing the alkali arsenate, is strongly acidified with acetic acid, boiled to expel the carbon dioxide, then cooled and treated with sufficient sodium hydroxide solution to give an alkaline reaction to phenolphthalcin indicator. The purple red color is now discharged from the solution by addition of acetic acid. A slight excess of neutral silver nitrate is vigorously stirred in and the precipitate allowed to settle in the dark. The supernatant liquid is poured off through a filter and the precipitate washed by decantation with cold distilled water, then thrown on the filter and washed free of silver nitrate solution. The funnel is filled with water and 20 ee. of strong nitrie acid added. The dissolved silver arsenate is caught in the original beaker in which the precipitation was made, the residue on the filter washed thoroughly with cold water and the filtrate and washings made up to 100 ee. The silver is now titrated by addition of standard animonium or potassium thioeyanate, until a faint red color is evident, using ferric ammonium alum indicator, according to the procedure described for determination of silver. (See Chlorine and Silver Chapters.)

One cc. N/10 thiocyanate = 0.010788 gram Ag. Factor. Ag $\times 0.2316$ = As.

Note. The silver arsenate salt is nearly six times the weight of arsenic, so that very small amounts of arsenic may be determined by the procedure, hence it is not necessary to use over 0.5 gram of the material. For traces of arsenic the Gutzeit method, following, should be used.

DETERMINATION OF SMALL AMOUNTS OF ARSENIC ... Modified Gutzeit Method

The following procedure furnishes a rapid and accurate method for determination of exceedingly small amounts of arsenic ranging from 0.001 milligram to 0.5 milligram As₂O₅. It is more sensitive and less tedious than the Marsh test. The details, given below with slight modifications, have been earefully worked out in the laboratories of the General Chemical Company and have proved exceedingly valuable in estimating small amounts of arsenic in acids, bases, sults, soluble arsenic in lead arsenate and zine arsenite and other insecticides, traces of arsenic in food products, baking powders, canned goods, etc.

The method depends upon the evolution of arsine by the action of hydrogen on arsenic compounds under the eatalytic action of zine, the reaction taking place either in alkaline or acid solutions. The evolved arsine reacts with mercuric chloride, forming a colored compound. From the length and intensity of the color stain the amount of arsenic is estimated by comparison with standard stains.

Although the acidity of the sample and the amount of zinc shot should be kept within certain limits, the results are not effected by slight variation as was formerly thought. The physical characteristics of the zinc used rather than the surface exposed to acid action appears to have an effect on the evolution of arsine. The best results are obtained with zinc having a finely crystalline structure.

Iron present in the solution tends to prevent evolution of stibine, but has no apparent effect of arsine generation.

Stannons chloride is essential to the complete evolution of arsine, hence this reagent is added to the solution in which arsenie is determined.

Antimony present in the solution in amounts less than 0.0001 gram, does not interfere with the determination of arsenic. If a greater amount of antimony is present a separation of arsenic should be made by distillation. The following modification of the method given on page 38 is recommended. In place of the generator for HCl shown in Fig. 1, air saturated with HCl, by passing it through a gas wash bottle containing concentrated hydrochloric acid, is drawn through the boiling solution containing the sample in a saturated HCl solution, reduction of arsenic to arsenions chloride having been effected with cuprous chloride as prescribed. The air sweeps the arsine into the water in the receiving flasks (Fig. 1). It is advisable to have two flasks connected in series in place of one as shown. Gentle suction is applied at the receiving end of the train. The apparatus may be made in fairly compact form.

Note. The above method was carefully investigated by R. M. Palmer and F. J. Seibert and found to be extremely accurate.

• Special Reagents. Standard Arsenic Solution. One gram of resublimed arsenous acid, As₂O₃, is dissolved in 25 cc. of 20% sodium hydroxide solution (arsenic-free) and neutralized with dilute sulphuric acid. This is diluted with fresh distilled water, to which 10 cc. of 95% H₂SO₄ has been added, to a volume of 1000 cc. Ten cc. of this solution is again diluted to a liter with distilled water containing acid. Finally 100 cc. of the latter solution is diluted to a liter with distilled water containing acid. One cc. of the final solution contains 0.001 milligram As₂O₃.

Standard Stains. Two sets of stains are made, one for the small apparatus for determining amounts of As₂O₃ ranging from 0.001 to 0.02 milligram, and a second set for the larger-sized apparatus for determining 0.02 to 0.5 milligram As₂O₃. Stains made by As₂O₃ in the following amounts are convenient for the standard sets; e.g., small apparatus, 0.001, 0.002, 0.004, 0.006, 0.01, 0.15, 0.02 milligram As₂O₃. Large apparatus, 0.02, 0.05, 0.1, 0.2, 0.3, 0.4, 0.5 milligram As₂O₃.

In making the stain the requisite amount of standard reagent, As₇D₃ solution, is placed in the Gutzeit bottle with the amounts of reagents prescribed for the regular tests and the run made exactly as prescribed in the regular procedure.

Preservation of the Stains. The strips of sensitized paper with the arsenie stain are dipped in molten paraffine (free from water), and mounted on a sheet of white paper, folded back to form a cylinder. The tube is placed in a glass test-tube containing phosphorus pentoxide, which is then closed on a stopper. It is important to keep the stained strip dry, otherwise the stain soon fades, hence the paper on which the strips are mounted and the glass test-tube, etc., must be perfectly dry. It is advisable to keep the standard in a hydrometer case, while not in use, as light will gradually fade the color.

Sensitized Mercuric Chloride (or Bromide) Paper. 20×20 in. Swedish Filter Paper No. 0 is cut into four equal squares. For use in the large Gutzeit apparatus the paper is dipped into a 3.25% solution of mercuric chloride (mercuric bromide may be used in place of the chloride) or if it is to be used in the small Gutzeit apparatus it is dipped into a 0.35% mercuric chloride solution. (The weaker the solution, the longer and less intense will be the stain.) The paper should be of uniform thickness, otherwise there will be an irregularity in length of

¹ The accuracy of the method is within 10% of the truth.

Evolution of arsine by the electrolytic method, in place of the method outlined, proved to be unreliable. The evolution of arsine is effected by the slightest variation in conditions so it is extremely difficult to obtain concordant results.

In the Marsh test arsine is passed through a glass tube constricted to capillarity. By application of heat the arsine is decomposed and metallic arsenic deposited. The tube is heated just before the capillary constriction so that arsenic deposits in the drawn out tube. Comparison is made with standards, the length of the stain being governed by the amount of arsenic in the evolved gas. Slight variations in the size of the capillary tube and rate of evolution make a notable variation in length of stain.

stain for the same amounts of arsenic. (The thicker the paper the shorter the stain. The paper is hung up and dried in the air, free from gas fumes, H_2S being particularly undesirable.) When dry, half an ineli of the outer edge is trimmed off (since this is apt to contain more of the reagent), and the paper cut into strips. The paper with more concentrated reagent is cut into strips 13 cm. by 5 mm. and that with 0.5% mercuric chloride into strips 7 cm. by 4 mm. The paper is preserved in bottles with tight-fitting




Fig. 5 .- Purification of Hydrochloric Acid.

stoppers. Standards should be made with each batch of paper. Paper with a white deposit of llgCl₂ should not be used.

Ferric Ammonium Alum. Eighty-four grams of the alum with 10 cc. of mixed acid is dissolved and made up to a liter. Ten cc. of this solution contains approximately 0.5 gram Fe₄O₃.

Lead Acetate. One per cent solution with sufficient acetic acid to clear the solution.

Zinc. Arsenic-free zinc shot, 3 to 6-in, mesh. The zinc is treated with C. P. hydrochlorie acid, until the surface of the zinc becomes clean and dull. It is

hen washed, and kept, in a easserole, covered with distilled water, a clock-glass recping out the dust.

Mixed Acid. One volume of arsenic-free H₂SO₄ is diluted with four volumes of pure water and to this are added 10 grams of NaCl per each 100 cc. of solution.

Stannous Chloride. Eighty grams of stannous chloride dissolved in 100 ee. of water containing 5 ee. arsenic-free hydrochloric acid (1.2 sp.gr.).

Arsenic-free Hydrochtoric Acid. The conunercial acid is treated with potassium chlorate to oxidize the arsenic to its higher form and the acid distilled. The distilling apparatus may be arranged so that a constant distillation takes place, acid from a large container dropping slowly into a retort containing potassium chlorate, fresh hydrochloric acid being supplied as rapidly as the acid distills. See Fig. 5 on page 48.

Lead Acetate Test Paper for Removal of H_2S . Large sheets of qualitative filter paper are soaked in a dilute solution of lead acetate and dried. The paper is cut into strips 7×5 cm.

Blanks should be run on all reagents used for this work. The reagents are arsenic-free if no stain is produced on mercuric chloride paper after forty-five minutes' test.

Special Apparatus. The illustration, Fig. 6 (page 52), shows the Gutzeit apparatus connected up, ready for the test. The dimensions on the left-hand side are for the small apparatus and those on the right for the large form. Rubber stoppers connect the tubes to the bottle. The apparatus consists of a wide-mouth 2-oz. or 8-oz. bottle according to whether the small or brige apparatus is desired, a glass tube (see Fig. 6) containing dry lead acctate paper and moist glass wool for removal of traces of hydrogen sulphide and a small-bore tube containing the strip of mercaric chloride paper.

Preparation of the Sample

The initial treatment of the sample is of vital importance to the Gutzeit Method for determining traces of arsenic. The following procedures cover the more important materials or substances in which the chemist will be called upon to determine minute amounts of arsenic.

Traces of Arsenic in Acids. The acid placed in the Catzeit apparatus should be equivalent to 4.2 grams of sulphuric acid or 3.1 grams of hydrochlorie acid and should contain 0.05 to 0.1 gram Fe₂O₃ equivalent. If large samples are required for obtaining the test it is necessary either to expel a portion of the acid in order to obtain the above acidity or to make standard stains under similar conditions of acidity. It must be remembered that arsenous chloride is readily volatile, whereas the arsenie chloride is not, hence it is necessary to oxidize arsenic before attempting to expel acids. If nitric acid or bromine or chlorine (chlorate) be added for this purpose, it must be expelled before attempting the Gutzeit test. Nitric acid may be expelled by adding sulphuric acid and taking to SO, fumes. Free chlorine, bromine, or iodine will volutilize on warming the solution. Chlorine in a chlorate is expelled by taking the sample to near dryness in presence of free acid. Sulphurous acid or hydrogen sulphide, if present, should be expelled by boiling the solution, then making faintly pink with KMnO, and destroying the excess with a drop or so of oxalic acid. SO₂ is reduced by zine and hydrogen to H₂S, which forms black HgS with

mercuric ehloride, hence removal of SO_2 and H_2S are necessary before running the test.

Sulphuric Acid. With amounts of arsenic exceeding 0.00005% As₂O₃, 5 to 10 grams of acid, according to its strength, are taken for analysis and diluted to 15 or 20 cc. If II₂S or SO₂ are present, expel by boiling for fifteen or twenty minutes. Prolonged fuming of strong acid should be avoided by previously diluting the acid with sufficient water. In mixed acid containing nitric acid the sample is taken to SO₃ fumes to expel nitric acid. The procedure given later for the regular determination is now followed.

For estimating very minute amounts of arsenic, 0.000005 to 0.00005% As₂O₃, it is necessary to take a 25- to 50-gram sample for analysis. The acid is treated as directed above for removal of H₂S or SO₂ or nitric acid and diluted in the Gutzeit apparatus to at least 130 cc., using the large apparatus. Upon the addition of iron and stannous chloride as directed in the procedure described on page 52 for large Gutzeit test. The stains are compared with standard stains produced by known amounts of arsenic added to 50-gram portions of arsenic-free sulphuric acid of strength equal to that of the sample. The stains are longer and less intense than those produced by less acid.

Hydrochloric Acid. Twenty cc. is taken for analysis (sp.gr. being known); the sample should contain an acid equivalent of about 3.1 grams of hydrochloric acid. Chlorine is expelled by bubbling air through the acid before taking a sample. The procedure is given for further treatment of the sample following the section on preparation of the sample.

Nitric Acid. One hundred ec. of the acid (sp.gr. being known) is evaporated with 5 ec. of concentrated sulphuric acid to SO₃ fumes, to expel nitric acid. Arsenic is determined in the residue by the standard procedure.

Iron Ores, Pyrites, Burnt Pyrites, Cinders, etc. One gram of the finely ground ore is oxidized by treating with 5 cc. of a mixture of 2 parts liquid bromine and 3 parts of earloon tetrachloride. After fifteen minutes, 10 cc. of concentrated nitric acid are added and the mixture taken to dryness. Five cc. of concentrated sulphuric acid (95%) are added and the mixture taken to SO₃ finnes to expel the nitric acid. The cooled sample is taken np with 50 cc. of water and digested until all of the iron sulphate has dissolved; it is now washed into a 100-cc. flask, made to volume, and arsenic determined in an aliquot portion in the usual way, given later. Insoluble FeA03, briquettes, etc., is best dissolved by fusion with potassium bisulphate, KHSO4. The fused mass is dissolved in warm dilute hydrochloric acid, and then washed into the Gutzeit bottle.

Alumina Ores. Bauxite. One gram of bauxite is treated with one part of concentrated nitric acid and 6 parts of concentrated hydrochloric acid, and taken to dryness on the water buth. The residue is taken up with an equivalent of 4.7 grams of hydrochloric acid or 6.3 grams of sulphuric acid in a volume of 25 cc. and the mix heated until the material has dissolved. The sample is diluted to exactly 100 cc. and arsenic determined on an aliquot portion.

Phosphates, Phosphoric Acid. Arsenic, in phosphorie acid, combined or free, cannot be determined in the usual way, as P₂C₂ has a retarding effect upon the evolution of arsine, so that the results are invariably low, and small amounts of arsenic escaping detection. Arsenic, however, may be volatilized from phosphates and phosphoric acid, as arsenous chloride, AsCl₂, in a current of

hydrogen chloride by heating to boiling. One gram or more of the phosphate is placed in a small distilling flask, connected directly to a 6-in. coil condenser dipping into the Gutzeit bottle, containing 20 to 30 ec. of cold distilled water. A second bottle connected in series may be attached for safeguarding loss (this sedom occurs). Fifty ec. of concentrated hydrochloric acid are added to the sample and 5 grams of enprous chloride. Arsenic is distilled into the Gutzeit bottle by heating the solution to boiling and passing a current of air through strong hydrochloric acid into the distilling flask by applying suction at the receiving end of the system. All of the arsenic will be found in the first 10 or 15 ec. of the distillate. Arsenic may now be evolved after addition of iron, stannous chloride and zinc, as directed in the procedure.

Salts, Sodium Chloride, Magnesium Sulphate, etc. One-gram samples are taken and dissolved in a little water and an equivalent of 6.3 grams of sulphuric acid added. The solution of iron and stammous chloride having been added, the run is made with 5 ce. of zine shot, placed in the Gutzeit bottle.

Baking Powder, Other than Phosphate Baking Powder. A 10-gram sample is heated with 10 cc. hydrochloric acid, 10 cc. of ferric ammonium alum and 30 cc. of distilled water, until the starch hydrolyzes. 0.5 cc. of stannous chloride is added to the hot solution and the mixture washed into the Gutzeit apparatus. The required amount of zinc is added and the arsenic determined as usual.

Phosphate Baking Powders. Ten grams of the material mixed to a paste with about 50 cc. of hydrochloric acid are transferred to a small distilling flask with a few ec. of HCl. A tube, connected to a bottle of strong hydrochloric acid, passes into the mixture in the flask through a ground glass stopper. The flask is attached to a tube, which dips into water in a Gutzeit bottle. Two grams of cuprons chloride are added, the apparatus made tight and the flask immersed in boiling hot water. By aspirating air through the system into the Gutzeit bottle, which is water cooled, arsenic distills into the bottle and may be determined by the procedure outlined.

Arsenic in Organic Matter, Canned Goods, Meat, etc. The finely chopped, well-mixed sample is placed in a large flask and enough water added to produce a fluid mass. An equal quantity of concentrated hydrochloric acid and I to 2 grams of potassium chlorate are added. The flask is shaken to mix the material and it is then placed on the steam bath. Upon becoming hot, nascent chlorine is evolved and vigorously attacks the organic matter. Half-grain portions of potassium chlorate are added at five-minute intervals, shaking the flask frequently. When the organic material has decomposed and the solution becomes a pale yellow color, the mass is diluted with water and filtered. Arsenic will be found in the filtrate. A white, amorphous substance generally remains on the filter, when cadaver is being examined. The filtrate is diluted to a given volume and an aliquot portion taken for analysis. This is evaporated to near dryness to expel excess of acid and decompose chlorates. An equivalent of 4.7 grams of hydrochloric acid is added (three times this amount for the large apparatus), the volume of the solution made to about 30 cc., 10 cc. of ferrie ammonium alum and 0.5 ec. of stannous chloride added, and the solution poured into the Gutzeit apparatus for the test as given below.

ARSENIC


Procedure for Making the Test

For amounts of arsenic varying from 0.001 milligram to 0.02 milligram As₂O₃, small apparatus is used. The volume of the solution should be 50 ee. It ruld contain an equivalent of 4.2 to 6.3 grams sulphuric acid and should have

about 0.1 gram equivalent of Fe₂O₄ reduced by 0.5 cc. of stannons chloride solution. Arsine is generated by adding one 5-cc. crucible of arsenie-free zine shot, \(\frac{1}{3}\) to \(\frac{1}{6}\)-inch mesh. Temperature 75 to 80° F.

For amounts ranging from 0.02 to 0.5 milligram As₂O₃, the large apparatus is used. The volume of the solution should be about 200 cc. and should contain an equivalent of 18.5 grams of sulphuric acid and should have 0.1 gram equivalent of Fe₂O₃, reduced by 0.5 ec. stannous chloride solution. Arsine is generated by adding one 12-ec. crucible of zinc shot (\{\}\ to \{\}\ -inch mesh.) The temperature should be 105° F. The sample taken should be of such size that a stain is obtained equivalent to that given by 0.1 to 0.5 milligram As₂O₃.

Lead acetate paper is placed in the lower portion of tube B; the upper portion of B contains glass wool moistened with lead acetate solution; the tube A contains the test strip of mercuric chloride paper. See Fig. 6. Immediately upon adding the required amount of zine to the solution in the bottles, the connected tubes are put in position, as shown in the illustration, and the bottle gently shaken and allowed to stand for one hour for the small apparatus, forty minutes for the large. The test paper is removed, dipped in molten paraffine and compared with the standard stains. See Plate I.



⁷10. 6.—Gutzeit Apparatus for Arsenic Determination.

Estimation of Per cent.

The milligram As_2O_3 stain $\times 100$ Weight of sample taken = % As_2O_3 .

¹ It is advisable to use smaller samples when the arsenic content is over 0.3 millium As₂O₃, as the longer stains are moreliable.

Ferrous iron prevents polarization between zine and the acid and hence aids in the plution of arsine.

In the analysis of baking powders, bauxite, sodium or similar salts, the distillation of thod is recommended. See pages 50 and 51, "Phosphates," and "Phosphate baking wder."

Hydrochloric acid is used in place of sulphuric acid in cases where complete solun by the latter acid cannot be effected.

Standards and samples should be run under similar conditions, temperature, dity, amount of zinc, volume of solution, etc. In place of zinc shot, zinc rods, cubes discs may be used for generating arsine and hydrogen.

-3-			

*METHOD FOR ANALYSIS OF COMMERCIAL "ARSENIC," ARSENOUS OXIDE, As2O3

The following constituents may be commonly present as impurities, SiO₃, Sb₂O₃, Fe₂O₃, NiO, CoO, CaO, SO₃, Cu, Pb, and Zn.

Determination of Moisture

Two 10-gram samples are dried to constant weight in the oven at 100° C-Loss in weight - meisture.

Sulphuric Acid, H₂SO₄

The samples from the moisture determination are dissolved in concentrated hydrochloric acid, heating to boiling if necessary, and the samples diluted to 300 to 400 cc. Barium chloride solution is added in slight excess to the hot solution, the precipitate, BaSO₄, allowed to settle and filtered and the sulphate dried and ignited as usual.

 $BaSO_4 \times 0.343 = SO_4$

Determination of Arsenic as As₂O₃

Duplicate 5-gram samples are dissolved in 20 grams potassium carbonate in 60 cc. of hot water, by boiling until solution is effected. The samples are made up to 1 liter and aliquots of 100 cc. (=0.5 gram) taken for analysis. The solution is made faintly acid with hydrochloric acid, testing the solution with litmus paper or by adding methyl orange directly to the solution. An excess of bicarbonate is added and the arsenic titrated with tenth-normal iodine according to the standard procedure for arsenic. One cc. N/10 I=.004948 gram As_2O_4 .

Residue upon Sublimation of As₂O₃. SiO₂, Pb, Cu, Fe₂O₃, NiO, CoO. Zn

Two 5-gram samples are weighed into tared porcelain crucibles and heated gently on sand baths with the sand banked carefully around the crucible so as to heat the entire receptacle. After the greater part of the arsenous oxide has volatilized, the crucible is ignited directly in the flame to a dull red heat, until fumes are no longer given off. The residue is weighed as total non-sub-limable residue.

Silica

The residues are transferred to beakers and treated with aqua regia, taken to dryness, and the silica dehydrated at 110° C. for an hour or more. The residue is taken up with hot dilute hydrochloric acid, boiled, and the silica filtered off, ignited, and weighed.

Lead and Copper

The filtrate from the silica is "gassed" with H₂S and the precipitate filtered off. The filtrate is put aside for determination of iron, etc. The precipitate is dissolved in hot dilute nitric acid, 2 to 3 cc. of concentrated sulphuric acid added,

the solution taken to SO₁ fumes, the ecoled concentrate diluted to 20 or 30 cc., and the lead sulphate filtered off, ignited, and weighed as PbSO₄.

The filtrate from the lead sulphate containing the copper is treated with aluminum powder and the copper thrown out of solution; the excess of aluminum is dissolved with a few ec. of hydrochloric acid. The filtrate should be tested for copper with H₂S and the precipitate added to the copper thrown out by the aluminum. The copper on the filter is dissolved in hot dilute nitric acid, the extract evaporated to 2 or 3 cc., the acid neutralized with ammonia and then made acid with acetic, potassium iodide added and the liberated iodine titrated with standard thiosulphate solution according to the regular scheme for copper.

Iron, Nickel, Cobalt, and Zinc

The filtrate from the H₂S Group is boiled to expel the H₂S and the iron oxidized by addition of nitric acid and boiling. The iron (and alumina) is precipitated with ammonium hydroxide and the precipitate filtered off and washed several times with hot water. If alumina is suspected (light-colored precipitate) it may be determined by the difference method—ignition of the precipitate, weighing, and finally subtracting the iron found by titration with standard stannons chloride solution. The iron is dissolved in hydrochloric acid and titrated hot with stannous chloride solution.

The filtrate from the iron is boiled and a 1% alcoholic solution of dimethylglyoxime added to precipitate the nickel. The salt is filtered on a tared Gooch, the precipitate dried at 100° C., and weighed. The weight of the salt × 0.2032 = Ni.

The filtrate from the nickel is boiled until all the alcohol has been driven off and the cobalt precipitated by addition of sodium hydroxide in excess filtered, ignited, and weighed as CoO.

The filtrate is made acid with hydrochloric acid, and then alkaline with ammonium hydroxide and colorless sodium sulphide solution added to precipitate the zinc. The n.ixture is boiled five to ten minutes, the precipitated ZnS allowed to settle, filtered off, and washed once or twice and then dissolved in hydrochloric acid and the zinc determined by titration directly with potassium ferrocyanide, or by converting to the carbonate by addition of potassium carbonate, filtered and washed free of alkali, the precipitate dissolved in a known amount of standard acid, and the excess acid titrated with standard caustic (methyl orange indicator) according to the procedure given for zine. H₂SO₄×0.06665 = Zn.

Antimony and Calcium Oxides

Two 15-gram samples are treated with 300 cc. of concentrated hydrochloric acid, boiled down to 50 cc. to expel the arsenic as AsCl₁, an equal amount of concentrated hydrochloric acid is added, and the last traces of arsenic precipitated by H₂S passed into the hot concentrated hydrochloric acid solution. The arsenous sulphide, As₂S₁, is filtered off. Antimony is precipitated by diluting the solution with an equal volume of water, the solution having been concentrated by boiling down to about 50 cc. The Sb₂S₃ is filtered off, washed several times with hot water, dissolved by washing through the filter with concentrated hydrochloric acid, and antimony determined in the strong hydrochloric acid solution by the potassium bromate method—addition of methyl orange indicator

and titration with standard potassium bromate added to the hot solution to the

disappearance of the pink color of the indicator.

The filtrate from the antimony is concentrated, made slightly alkaline with ammonium hydroxide, and gased with hydrogen sulphide to remove iron, nickel, cobalt, zine, chromium, and last traces of lead, etc. The filtrate is then concentrated and made acid with crystals of oxalic acid, boiled and methyl orange added and then ammonia drop by drop slowly until the indicator changes to an orange color. An excess of ammonium oxalate is now added and the beaker placed on the steam bath until the calcium oxalate has settled. The lime is now determined by filtering off the precipitate and washing, drying and igniting to CaO, or by titration with standard permanganate, according to the regular procedure for calcium.

Arsenic in Iron and Steel. Ten grams of sample are placed in a distillation flask and dissolved in dilute HNO₃, the solution evaporated to dryness and heated to expel oxides of nitrogen, 100 cc. of HCl and 20 grams of CuCl are added and the arsenious acid distilled and determined by the iodine method.

Arsenic in Copper. Since arsenic impairs the electrical conductivity of copper, its determination is required. One gram of the sample is placed in a distillation flask with 10 cc. FeCl₃ and 100 cc. HCl and 5 grams KCl and the arsenious acid distilled and determined by titration with iodine.

BARIUM

Ba, at.wt. 137.37; sp.gr. 3.78; m.p. 850° C.; volatile at 950° C.; oxides, BaO, BaO₂.

DETECTION

Barium is precipitated as the carbonate together with strontium and calcium, by addition of ammonium hydroxide and anunonium carbonate to the filtrate of the ammonium sulphide group. It is separated from strontium and calcium by precipitation as yellow barium chromate, BaCrO₄, from a slightly acetic acid solution.

Saturated solutions of calcium or strontium sulphates precipitate white barium sulphate, BaSO₄, from its chloride or nitrate or acetate solution, barium sulphate being the least soluble of the alkaline carth sulphates.

Soluble chromates precipitate yellow barium chromate from its neutral or slightly acetic acid solution, insoluble in water, moderately soluble in chromic acid, soluble in hydrochloric or nitric acid.

Fluosilicic acid, H₂SiF₄, precipitates white, erystalline barium Iluosilicate, BaSiF₄, sparingly soluble in acctic acid, insoluble in alcohol. (The Iluosilicates of calcium and strontium are soluble.)

Flame. Barium compounds color the flame yellowish green, which appears blue through green glass.

Spectrum. Three characteristic green bands (α, β, γ) .

Barium sulphate is precipitated by addition of a soluble sulphate to a solution of a barium salt. The compound is extremely insoluble in water and in dilute acids (soluble in hot concentrated sulphuric acid). The sulphate is readily distinguished from lead sulphate by the fact that the latter is soluble in ammonium salts, whereas barium sulphate is practically insoluble.

ESTIMATION

The determination of barium is required in the valuation of its ores, bariteheavy spar, BaSO₄; witherite, BaCO₅; baryto calcite, BaCO₅CaCO₅. It is determined in certain white mixed paints and colored pigments, Venetian, Hamburg or Dutch whites, chrome paints, etc. In analysis of Paris green, baryta insecticides, putty, asphalt, dressings and pavement surfacings. It may be found as an adulterant in foods, wood preservatives, filler in rubber, rope, fabrics. It is determined in salts of barium. The nitrate is used in pyrotechny, in mixtures for green fire.

Chapter contributed by Wilfred W. Scott.

BARIUM 57

Preparation and Solution of the Sample

Compounds of barium, with the exception of the sulphate, BaSO₄, are soluble in hydrochloric and nutric acids. The sulphate is soluble in hot concentrated sulphuric acid, but is reprecipitated upon dilution of the solution. The sulphate is best fused with sodium carbonate, which transposes the compound to barium carbonate; sodium sulphate may now be leached out with water and the residue, BaCO₄, then dissolved in hydrochloric acid.

Solution of Ores. Sulphates. 0.5 to 1 gram of the finely divided ore is fused with 3 to 5 grams of sodium and potassium carbonate mix, 2:1, or sodium earbonate alone, in a platinum dish. (Prolonged fusion is not necessary.) The melt is cooled and then extracted with hot water to dissolve out the alkali sulphates. Barium carbonate, together with the other insoluble carbonates, may now be dissolved by hot dilute hydrochloric acid. From this solution barium may be precipitated by addition of sulphuric acid. If it is desired to separate barium along with strontium, calcium, and magnesium, the members of the preceding groups are removed by H₂S in acid and in ammoniacal solution, as directed under "Separations."

Sulphides. The ore is oxidized, as directed for pyrites under the subject of sulphur. After the removal of the soluble sulphates, the residue, containing silica, barium, and small amounts of insoluble oxides, is fused and dissolved according to the procedure for sulphates.

Carbonates. In absence of sulphates the material may be dissolved with hydrochloric acid, taken to dryness to dehydrate silica and after heating for an hour in the steam oven (110°±) the residue is extracted with dilute hydrochloric acid and filtered. The filtrate is examined for barium according to one of the procedures given later.

Salts Soluble in Water. Nitrates, chlorides, acetates, etc., are dissolved with water slightly acidulated with hydrochloric acid.

Material Containing Organic Matter. The substance is roasted to destroy organic matter before treatment with acids or by fusion with the alkali carbonates.

The Insoluble Residue remaining from the acid treatment of an ore may contain barium sulphate in addition to silica, etc. The filter containing this residue is burned and the ash weighed. Silica is now volatilized by addition of hydrofluoric acid with a few drops of sulphuric acid, and evaporation to dryness. If an insoluble substance still remains after taking up the remaining residue with dilute hydrochloric acid, barium sulphate is indicated. This is treated according to the method given for sulphates.

Note. The insoluble substance remaining is frequently ignited and weighed as barium sulphate without fusion with the carbonate.

SEPARATIONS

The Alkaline Earths

Preliminary Considerations. In the determination of barium, ealcium, and strontium, the following causes may lead to loss of the elements sought:

- a. Presence of Phosphates. Phosphoric acid, free or combined, has a decided influence upon the determination of the members of this group. Combined as phosphate it will cause the complete precipitation of barium, calcium, and strontium, along with iron, alumina, etc., upon making the solution alkaline for removal of the ammonium sulphide group. It is a common practice to hold up the iron+alumina by means of tartaric, citric, or other organic acids before making ammoniacal for precipitation of this group as oxalates, or again the basic acetate method is used for precipitation of iron and alumina; calcium, barium, and strontium going into solution. These procedures may be satisfactory for the analysis of phosphate rock and similar products, but do not cope with the difficulty when large amounts of phosphates are present. In samples containing free phosphoric acid, barium, ealcium, and strontium, present in small amounts, may remain in solution in presence of sulphates or oxalates. Appreciable amounts of ealcium, 1% or more, may escape detection by the usual method of precipitation by ammonium oxalate added to the alkaline solution, on account of this interference, so that the removal of phosphoric acid before precipitation of this group is frequently necessary. This may be accomplished by addition of potassium carbonate in sufficient excess to combine completely with the phosphoric acid and form carbonates with the bases. The material taken to dryness is fused with additional potassium carbonate in an iron erucible, and the fusion leached with hot water-sodium phosphate dissolves and the earbonates of the heavy metals remain insoluble.
- b. Another source of loss is the presence of sulphates, either in the original material or by intentional or accidental addition, in the latter case due to the oxidation of hydrogen sulphide, which has been passed into the solution during the removal of elements of the hydrogen sulphide and ammonium sulphide groups, barium and strontium sulphate being precipitated along with these members. A potassium carbonate fusion will form K₂SO₄, which may be leached out with water.
- c. Loss may be caused by occlusion of barium, calcium, strontium, and magnesium by the gelatinous precipitates Fe(OH), Al(OH), etc. A double precipitation of these compounds should be made if considerable amounts are present.
- d. A large excess of ammonium salts, which accumulate during the preliminary separations, will prevent precipitation of the alkaline earths. This can be avoided by using the necessary care required for accurate work, the addition of reagents by means of burettes or according to definite measurements in graduates, etc. Careless addition of large amounts of ammonium hydroxido and hydrochloric acid should be guarded against. In ease large amounts of ammonium chloride are present, time is frequently saved by a repetition of the separations. Ammonium chloride may be expelled by heating the material, taken to dryness in a large platinum dish, the ammonium salts being volatilized.
- e. Carbon dioxide absorbed by ammonium hydroxide from the air will precipitate the alkaline earths with the ammonium sulphide group.




Plate II.

• Direct Precipitation on Original Sample. For the determination of barium, calcium, and strontium, it is advisable to take a fresh sample, rather than one that has been previously employed for the estimation of the hydrogen sulphide and ammonium sulphide groups, as is evident from the statements made above. The alkaline earths are isolated by being converted to the insoluble sulphates and separations effected as given later under Sulphate Method.

Preliminary Tests. Much time may be saved by making a preliminary test for barium, strontium, and calcium by means of the spectroscope and

avoiding unnecessary separations.

By means of the spectroscope with the use of the ordinary Bunsen flame exceedingly minute amounts of calcium, strontium and barium may be detected per cc. The test is very much more delicate by the arc spectra method. The liquid containing the substance is connected to the positive pole and an iridium needle is connected by means of an adjustable resistance of 300 to 500 ohms to the negative pole. An E.M.F. of 100 to 200 volts and 1 ampere current are required. By the arc it is possible to detect 0.002 milligram of calcium, 0.003 milligram of strontium, 0.006 milligram of barium, 0.1 milligram of magnesium per cc. In these concentrations, calcium shows one brilliant line (423 $\mu\mu$), a bright line (616 $\mu\mu$), and a faint line between them; strontium two bright lines (422 and 461 $\mu\mu$) and two fairly bright lines; barium two brilliant lines (455 and 493 $\mu\mu$), two other bright lines, and a fairly bright one; and magnesium a brilliant band composed of three lines (516.8 to 518.4 $\mu\mu$), as well as a fairly bright line further towards the violet end of the spectrum

The flame test may be of value in absence of sodium; barium giving a green

flame, strontium a brilliant scarlet, and calcium an orange red.

Separation of the Alkaline Earths from Magnesium and the Alkalies. Two general procedures will cover conditions commonly met with in analytical work:

A. Oxalate Method. Applicable in presence of comparatively large portions of calcium. The acid solution containing not over 1 gram of the mixed oxides is brought to a volume of 350 ec. and for every 0.1 gram of magnesium present about 1 gram of ammonium chloride is added, unless already present. Sufficient oxalic acid is added to completely precipitate the barium, calcium, and strontium.² (11₂C₂O₄·211₂O = 126.04, 13a = 137.37, Ca = 40.07, Sr = 87.63.) The solution is slowly neutralized by addition, drop by drop, of dilute ammonium hydroxide (1:10), methyl orange being used as indicator. About ½ gram of oxalic acid is now added in excess, the solution again made alkaline with ammonium hydroxide, and allowed to settle for at least two hours. The precipitate is filtered off and washed with water containing 1% ammonium oxalate, faintly alkaline with ammonia.

The precipitate contains all the calcium and practically all of the barium and strontium. If Mg is present in amounts of 10 to 15 times that of the alkaline earths a double precipitation is necessary, to remove it completely from this group. The oxalates are dissolved in hydrochloric acid and reprecipi-

tated with ammonium oxalate in alkaline solution.

The filtrate contains magnesium and the alkalies. Traces of barium and strontium may be present. If the sample contains a comparatively large proportion of barium and strontium, the filtrate is evaporated to dryness, the ammonium salts expelled by gentle ignition of the residue, and the Ba and

¹E. H. Riesenfeld and G. Pfützer, Ber., 1913, 46, 3140-3144; Analyst, 1913, 38, 584.

² Calcium and strontium will slowly precipitate in the oxalic acid solution. Baoxalate will precipitate upon making the solution alkaline.

Sr recovered as sulphates according to the method described below. Magnesium is precipitated as magnesium ammonium phosphate from the filtrate.

1 The oxalates of barium, calcium, and strontium are ignited to oxides, in which form they may be readily converted to chlorides by dissolving in hydrochloric

acid, or to nitrates by nitric acid.

B. Sulphate Method. Applicable in presence of comparatively large proportions of barium, strontium, or magnesium. The solution containing the alkaline earths, magnesium and the alkalies is evaporated to dryness and about 5 cc. concentrated sulphuric acid added, followed by 50 cc. of 95% alcohol. The sulphates of barium, calcium, and strontium, are allowed to settle, and then filtered onto an S. and S. No. 589 ashless filter paper and washed with alcohol until free of magnesium sulphate. In presence of large amounts of magnesium as in case of analyses of Epsom salts and other magnesium salts it will be necessary to extract the precipitate by adding a small amount of water, then sufficient 95% alcohol to make the solution contain 50% alcohol and filter from the residue. Magnesium is determined in the filtrate.

The residue containing barium, calcium, and strontium as sulphate is fused with 10 parts of potassium carbonate or sodium acid carbonate until the fusion becomes a clear protein mass, a deep platinum crucible being used for the fusion. A platinum wire is inserted and the mass allowed to solidify. The fusion may be removed by again heating until it begins to melt around the surface next to the crucible, when it may be lifted out on the wire. The mass is extracted with hot water and filtered, Na₂SO₄ going into the solution and the carbonates of barium, strontium, and calcium remaining insoluble. The carbonates should dissolve completely in hydrochloric acid or nitric acid, otherwise the decomposition has not been complete, and a second fusion of this insoluble residue will be necessary.

Separation of the Alkaline Earths from One Another. This separation may be effected by either of the following processes:

 Barium is separated in acetic acid solution as a chromate from strontium and calcium; strontium is separated as a nitrate ² from calcium in ether-alcohol or anyl alcohol.

2. The three nitrates are treated with ether-alcohol in which barium and strontium nitrates are insoluble and calcium dissolves; the barium is now separated from strontium by ammonium chromate.

Procedures. 1. (a) Separation of Barium from Strontium (and from Calcium). In presence of an excess of ammonium chromate, barium is precipitated from solutions, slightly acid with acetic acid, as barium chromate (appreciably soluble in free acetic acid), whereas strontium and calcium remain in solution.

The mixed oxides or carbonates are dissolved in the least amount of dilute hydrochloric acid and the excess of acid expelled by evaporation to near dryness. The residue is taken up in about 300 cc. of water and 5-6 drops of acetic acid (sp.gr. 1.065) together with sufficient ammonium acctate (30% solution) to neutralize any free mineral acid present. The solution is heated and an excess of ammonium chromate (10% neutral sol.) added (10 cc. usually sufficient).

¹Solubility of BaSO₄=0.17 milligram, CaSO₄=179 milligram, SrSO₄=11.4 milligrams per 100 cc. sol. cold.

² Method of Stromayer and Rose. H. Rose, Pogg. Ann., 110, 292, (1860).

³ The solution is prepared by adding NH₄OH to a solution of (NH₄)₂Cr₂O₇ until yellow. The solution should be left acid rather than alkaline.

The precipitate of barium chromate is allowed to settle for an hour and filtered off on a small filter and washed with water containing ammonium chromate until free of soluble strontium and calcium (test—addition of NH₄OH and $(NH_4)_2CO_2$ produces no cloudiness), and then with water until practically free of ammonium chromate (e.g., only slight reddish brown color with silver nitrate solution).

To separate any oeeluded precipitate of strontium or ealcium the filter paper is pierced and the precipitate rinsed into a beaker with warm dilute nitrie acid (sp.gr. 1.20) (2 cc. usually are sufficient). The solution is diluted to about 200 cc. and boiled. About 5 cc. of ammonium acetate, or enough to neutralize the free HNO₁, are added to the hot solution and then sufficient ammonium chromate to neutralize the free acetic acid, 10 cc. usually sufficient. The washing, as above indicated, is repeated. Barium is completely precipitated and may be determined either as a chromate or a sulphate or by a volumetric procedure. Strontium and calcium are in the filtrates and may be separated as follows:

(b) Separation of Strontium from Calcium. The method depends upon the insolubility of strontium nitrate and the solubility of calcium nitrate in a mixture of ether-alcohol, 1:1.

Solubility of $Sr(NO_3)_2=1$ part $Sr(NO_3)_2$ in 60,000 parts of the mixture. Cu easily soluble.

If the solution is a filtrate from barium, I ec. of nitric acid is added and the solution heated and made alkaline with ammonium hydroxide followed immediately with ammonium carbonate, the carbonates of strontium (together with some SrCrO₄) and calcium will precipitate. The precipitate is dissolved in hydrochloric acid and reprecipitated from a hot solution with ammonium hydroxide and ammonium carbonate. The precipitate, SrCO3 and CaCO3, is washed once with hot water and is then dissolved in the least amount of nitric acid, washed into a small casserole, evaporated to dryness and heated for an hour at 140 to 160° C, in an oven, or at 110° C, over night. The dry mass is pulverized and mixed with 10 cc. of ether-alcohol (absolute alcohol, one part, ether-anhydrons, one part). Several extractions are thus made, the extracts being decanted off into a flask. The residue is again dried in an oven at 140 to 160° C., then pulverized and washed into the flask with the ether-alcohol mixture and digested for several hours with frequent shaking of the flask. The residue is washed onto a filter moistened with ether-alcohol mixture. Strontium nitrate, Sr(NO₂)₂, remains insoluble, and may be dissolved in water and determined gravimetrically as a sulphate, oxide, or carbonate or volumetrically. Calcium is in the filtrate and may be determined gravimetrically as an oxide or volumetrically.

Instead of using a mixture of ether-alcohol, anyl alcohol may be used (hood), the mixture being kept at boiling temperature to dehydrate the alcohol to prevent solution of strontium $(b,p,=130^{\circ})$.

2. Separation of Barium and Strontium from Calcium.¹ The procedure depends upon the insolubility of barium nitrate, (BaNO₂)₂, and strontium nitrate, Sr(NO₂)₂, in a mixture of anhydrous ether and absolute alcohol or anhydrous amyl alcohol, whereas Ca(NO₂)₂ dissolves.

The mixed oxides or carbonates are dissolved in nitrie acid and taken to dryness in a beaker or Erlenmeyer flask, and heated for an hour or more in an ¹ See Fresenius, Z. anal. Chem., 29, 413-430 (1890).

BARIUM 62

oven at 140 to 160° C. Upon cooling, the mixture is treated with ten times its weight of ether-alcohol mixture and digested, cold, in the covered beaker or corked flask for about two hours with frequent stirring. An equal volume of ether is now added and the digestion continued for several hours longer. The residue is washed by decentation with ether and alcohol mixture until calcium is removed (test-no residue on platinum foil with drop of filtrate evaporated to dryness).

Separation of Barium from Strontium. The dry mixed chlorides are dissolved in the least possible amount of water (0.2 ec., or more if necessary) the solution warmed, then cooled. More water is added if crystals appear. (The solution should be saturated.) A mixture of 4:1 of HCl (33%) and ether is added dropwise with stirring. Sufficient reagent is added to precipitate BaCl₂ and dissolve SrCl₂. The mixture is decanted on an asbestos filter and washed with the HCl-ether reagent. The BaCl2 is dried at 150° C. and weighed. (Method of Gooch and Soderman.)

Barium and strontium may be separated by precipitation of barium as a chromate, the nitrate residue being dissolved in water and barium precipitated according to directions given under Procedure No. 1.

Amyl alcohol may be used in place of ether-alcohol by digesting the nitrates in a boiling solution (130° C.), calcium going into solution and barium and strontium remaining insoluble as nitrates.

Separation of the Alkaline Earths from Molybdenum. The substance is fused with sodium carbonate and the fusion extracted with water and filtered. Molybdenum passes into the filtrate and the alkaline earths remain in the residue.

Separation of Phosphoric Acid from the Alkaline Earths. Ammonium carbonate is added to the hydrochloric acid solution until a slight permanent turbidity is obtained, and the solution just cleared with a few drops of HCl. Ferrie chloride is now added drop by drop until the solution above the yellowish white precipitate becomes brownish in color. The solution is diluted to about 400 cc. and brought to boiling and then filtered and the residue washed with water containing ammonium acetate. The filtrate contains the alkaline earths, free from phosphoric acid.

BARIUM 63

GRAVIMETRIC METHODS FOR THE DETERMINATION OF BARIUM

For reasons given under "Preliminary Considerations," it is advisable to take a special sample for the determination of barium that has not undergone treatment with hydrogen sulphide or ammonium hydroxide, since these may cause the loss of barium as stated.

Barium in Insoluble Residue. In the complete analysis of ores the residue remaining insoluble in acids is composed largely of silica, together with difficultly soluble substances, among which is barium sulphate. This residue is best fused in a platinum dish with sodium carbonate or a mixture of sodium and potassium carbonates (long fusion is not necessary). The cooled mass is digested with hot water to remove the soluble sodium compounds, silicate being included. Barium, together with the heavy metals, remains insoluble as carbonate and may be filtered off. The residue is now treated with dilute ammonia water to remove the adhering sulphates (testing the filtrate with hydrochloric acid and barium chloride solution; the washing being complete when no white precipitate of barium sulphate forms). The carbonates are washed off the filter into a 500-cc. beaker, the clinging carbonate being dissolved by pouring a few ce. of dilute, 1:1, hydrochloric acid on the paper placed in the funnel. This extract is added to the precipitate in the braker and the latter covered to prevent loss by spattering. Additional hydrochlorie acid is cautiously added so that the precipitate completely dissolves and the solution contains about 10 cc. of free hydrochloric acid (sp.gr. 1.2). Barium is precipitated from this solution best as a sulphate according to directions given later.

Silicates. One grant of the finely pulverized sample is treated with 10 cc. of dilute sulphuric acid, 1:4, and 5 cc. of strong hydrofluoric acid. The mixture, evaporated to small bulk on the steam bath, is taken to SO₃ fumes on the hot plate. Additional sulphuric acid and hydrofluoric acid are used if required. By this treatment the silica is expelled and barium, together with other insoluble sulphates, will remain upon the filter when the residue is treated with water and filtered. Lead sulphate, if present, may be removed by washing the residue with a solution of ammonium acetate. Barium sulphate may be purified by fusion with potassium carbonate as above directed or by dissolving in hot concentrated sulphuric acid, and precipitating again as BaSO₄ by dilution.

Ores may be decomposed by either of the above methods or a combination of the two. Sulphide ores require roasting to oxidize the sulphide to sulphate.

Barium Sulphate is decomposed by fusion with sodium and potassium earbonates. The fusion is leached with water to remove the soluble sulphate and the residue, BaCO₃, is dissolved in HCl. Barium is determined in this solution.

63a BARIUM

Determination of Barium as a Chromate

A preliminary spectroscopic test has indicated whether a separation from calcium and strontium is necessary. If these are present, barium is separated along with strontium from calcium as the nitrate in presence of alcohol-ether inixture, according to directions given under "Separations." Barium is now precipitated as the chromate, BaCrO₄, from a neutral or slightly acetic acid solution, strontium remaining in solution.

Precipitation of Barium Chromate. If barium is present in the form of nitrate, together with strontium, the mixed nitrates are evaporated to dryness and then taken up with water. About 10 cc. ammonium acetate (300 grams NH₄C₄H₅O₄ neutralized with NH₄OH+H₄O to make up to 1000 cc.) added and the solution heated to boiling. Five cc. of 20% ammonium bichromate are added drop by drop with constant stirring and the precipitate allowed to settle until cold. The solution is decanted off from the precipitate through a filter and washed by decantation with dilute (0.5%) solution of ammonium acetate, until the excess chromate is removed, as indicated by the filtrate passing through uncolored. If much strontium was originally present, a double precipitation is necessary, otherwise the precipitate may be filtered directly into a Gooch erucible and dried, (120° C.) to constant weight.

Purification from Strontium. The precipitate is dissolved from the filter by running through dilute (1:5) warm nitric acid, poured upon the chromate, eatching the solution in the beaker in which the precipitation was made; the least amount of acid necessary to accomplish this being used and the filter washed with a little warm water. Ammonium hydroxide is now added to the solution, cautiously, until a slight permanent precipitate forms and then 10 cc. of ammonium acetate solution added with constant stirring and the mixture heated to boiling. The precipitate is allowed to settle until the solution is cold and then filtered and washed by decantation as before, a Gooch erucible being used to eateh the precipitate.

Ignition. The precipitate is washed with dilute alcohol once, then dried at 110° C. The Gooch containing the BaCrO₄ is gently heated in a larger crucible (allowing an encirching air space around the Gooch) until the color of the chromate becomes uniform.

$BaCrO_4 \times 0.6051 = BaO$. $BaCrO_4 \times 0.5420 = Ba$.

Notes. The use of sodium hydrate or acetate in place of the animonium hydroxide and acetate is sometimes recommended, owing to the slight solubility of BaCrO₄ in ammonium salts, as seen by the following table, approximate figures being given:

100,000 parts of cold water dissolves	0.38	parts Ba	CrO ₄
100,000 parts of hot water dissolves	4.35	parts Ba	CrO_4
100,000 of 0.5% solution of NH ₄ Cl dissolves	4.35	parts Ba	CrO₄
100,000 of 0.5% solution of NH ₄ NO ₃ dissolves		parts Ba	
100,000 of 0.75% solution of NH ₄ C ₂ H ₃ O ₂ dissolves	-2.00	parts Ba	
100,000 of 1.5% solution of NH ₄ C ₂ H ₃ O ₂ dissolves	4.12	parts Ba	
100,000 of 1% acetic acid dissolves	20.73	parts Ba	CrO ₄

63b BARIUM

Although the solvent action of annuonium salts is practically negligible under conditions of analysis given above, the solvent action of free acetic acid is of importance. so that it is necessary to neutralize or eliminate free mineral acids before addition of the acctate salt.

The edges of the BaCrO4 precipitate upon drying may appear green, owing to the action of alcohol; upon ignition, however, the yellow chromate is obtained.

color orange yellow, when hot, fades to a light canary yellow upon cooling.

BaCrO₄, mol.wt., 253.47; sp.gr., 4.498¹⁵°; 100 cc. H₂O sol, cold will dissolve 0.00038¹⁵° gram, bot dissolves 0.0043 gram; soluble in HCl, HNO₄, yellow rbombic plates.

Determination of Barium as Barium Carbonate. The solution free from previous groups and from calcium and strontium is made ammoniacal; after addition of ammonium chloride if not already present for the purpose of preventing precipitation of magnesium. Ammonium carbonate is now added in slight excess and the precipitated BaCO₃ allowed to settle on the water bath or in a warm place for an hour or preferably longer. The precipitate is filtered and washed with dilute NH₄OH, dried and ignited and weighed as BaCO₃. The method proposed by Fresenius, is considered by some to be more accurate than the sulphate method.

 $BaCO_3 \times 0.686 = Ba$.

Determination of Barium by Precipitation as Sulphate, BaSO₄

This method depends upon the insolubility of barium sulphate in water and in very dilute hydrochloric acid or sulphuric acid, one gram of the salt requiring about 344,000 cc. of hot water to effect solution.

Reaction, $BaCl_2+H_2SO_4=BaSO_4+2HCl$.

BaSO₄, mol.wt., 233,44; sp.gr., 4.47 and 4.33; m.p., 1580° (amorphous decomposes); H₂O dissolves 0.000172° gram and 0.0003³⁴° per 100 cc. 3% HCl dissolves 0.0036 gram. Soluble in conc. H₂SO₄. White, rhombic and amorphous forms.

Procedure. The slightly hydrochloric acid solution of barium chloride, prepared according to directions given, is heated to boiling (volume about 200–300 cc.) and a slight excess of dilute hot sulphuric acid added. The precipitate is settled on the water bath and the clear solution then decanted through a weighed Gooch crucible or through an ashless filter paper (S. and S. 590 quality). The precipitate is transferred to the Gooch (or paper), and washed twice with very dilute sulphuric acid solution (0.5% H₂SO₄), and finally with hot water until free of acid. The precipitate is dried and ignited, at first gently and then over a good flame to a cherry red heat, for half an hour. The residue is weighed as barium sulphate, BaSO₄.

 $BaSO_4 \times 0.5881 = Ba$, or $\times 0.6569 = BaO$, or $\times 0.8155 = BaCO_b$.

Notes. The determination of bariam is the reciprocal of the determination of sulphur or sulphuric acid. Precantions and directions given for the sulphur precipitation apply here also, with the exception that dilute sulphuric acid is used as the precipitating reagent in place of burium charite.

the precipitating reagent in place of barium chloride.

The author found that precipitation of barium sulphate in a large volume of cold solution containing 10 cc. of concentrated hydrochloric acid per 1600 cc. of solution, by adding a slight excess of cold dilute sulphuric acid in a fine stream, exactly in the manner that barium chloride solution is added in the precipitation of sulphur, and allowing the precipitate to settle, at room temperature, for several hours (preferably over night), gives a precipitate that is pure and does not pass through the Gooch asbestos mat. We refer to the chapter on Sulphur for directions for filtering washing, and ignition of the residue.

The addition of hydruchloric acid causes rapid settling of the barium sulphate. F. A. Gooch has shown that the precipitation should be conducted at temperatures over 75° C., preferably at 90° C. Of Methods in Chemical Analysis," 1912, page 168.

VOLUMETRIC METHODS FOR THE DETERMINATION OF BARIUM

Titration of the Barium Salt with Dichromate

This method is of value for an approximation of the amount of barium present in a solution that may also contain calcium, strontium, and magnesium or the alkalies. It depends upon the reaction

$$2BaCl_2+K_2Cr_2O_7+H_2O=2BaCrO_4+2KCl+2HCl$$
.

 $\rm N/10~K_2Cr_2O_7$ (precipitation purposes) contains 7.355 grams pure salt per liter.

Procedure. The solution containing the barium is treated with ammonia until it just smells of it. (If an excess of ammonia is present the solution is made faintly acid with acetic acid.) It is then heated to about 70° C. and the standard dichromate added, with stirring until all the barium is precipitated and the clear supernatant solution is a faint yellow color from the slight excess of the reagent. For accurate work it is advisable to titrate the precipitate formed by one of the methods given below. One ce. $K_2Cr_2O_7 = 0.00687$ gram Ba. (Note reaction given above.)

Note. An excess of potassium dichromate may be added, the precipitate filtered off, washed and the excess of dichromate determined as stated below.

Reduction of the Chromate with Ferrous Salt and Titration with Permanganate

Ferrons sulphate reacts with barium chromate as follows:

$$2BaCrO_4 + 6FeSO_6 + 8H_2SO_4 = 3Fe_2(SO_4)_3 + Cr_2(SO_4)_3 + 2BaSO_4 + 8H_2O_5$$

An excess of ferrous salt solution is added and the excess determined by titration with $N/10 \text{ KMnO}_4$ solution. Fe = $\frac{1}{2}Ba$.

Reagents. N/10 solution of KMnO₄. N/10 FeSO₄ (27.81 grams per liter) or FeSO₄ (NH₄)₂SO₄ (39.226 grams per liter). One oc. =0.004579 Ba.

Procedure. The well-washed precipitate of barium chromate is dissolved in an excess of standard N/10 ferrous ammonium sulphate solution containing free sulphuric acid. The excess ferrous salt is titrated with standard N/10 potassium permanganate solution.

(Cc. N/10 ferrous solution minus cc. permanganate titration) multiplied by 0.004579 gives grams barium in the solution. Iron factor to barium is 0.8187.

Potassium Iodide Method

The procedure depends upon the reactions:

- 1. $2BaCrO_4+6K1+16HCl=2BaCl_2+2CrCl_3+6KCl+8H_2O+6I$.
- 2. $3I_2 + 6Na_2S_2O_3 = 6NaI + 3Na_2S_4O_6$.

Procedure. The precipitate, BaCrO₄, is dissolved in 50 to 100 cc. of dilute hydrochloric acid and about 2 grams of solid potassium iodide salt added and allowed to react about ten minutes. The liberated iodine is now titrated

66 BARIUM

with N/10 thiosulphate. Near the end of the titration starch solution is added and followed by N/10 thiosulphate until the color disappears.

One cc. N/10 Na₂S₂O₄ = 0.004579 gram Ba.

Titration of Barium Carbonate with Standard Acid

To the well-washed barium carbonate, BaCO₂, an excess N/10 H₂SO₄ is added and the excess acid determined.

One cc. N/10 neid = 0.00687 gram Ba.

ANALYSIS OF BARYTES AND WITHERITE

Barytes or heavy spar is a variety of native barium sulphate, and witherite a native barium carbonate. These minerals are typical examples of barium-bearing ores. The analysis may involve the determination of barium and calcium sulphates or carbonates, magnesia, iron and aluminum oxides and moisture. Traces of lead, copper, and zinc may be present, as well as sulphide, sulphur and fluorine in fluorspar. The following is an approximate composition of a high-grade sample:

$$BaSO_4 = 96\%, \ CaCO_2 = 1.5\%, \ MgCO_3 = 0.3\%, \ SiO_2 = 0.5\%, \ Al_2O_3 = 0.5\%, \\ Fe_4O_4 = 0.2\%, \ H_4O = 0.5\%.$$

For complete analysis treat as directed under preparation of the sample.

Procedure for Commercial Valuation of the Ore

Total BaO as Barium Sulphate

One gram of the finely pulverized sample is weighed into a platinum crucible (35 cc. capacity), mixed with 8 grams of sodium carbonate, fused for twenty minutes over a Bansen burner and twenty minutes over a Méker burner or blast lamp. The fusion is leached out with 200 cc. hot water in a 250 cc. beaker, the barium carbonate filtered off, washed thoroughly with hot dilute sodium carbonate solution (2 grams per liter) until no test for sulphate is obtained. The barium carbonate is dissolved from the paper with hot dilute hydrochloric acid, catching solution in a 600 cc. beaker and the paper thoroughly washed. The solution is neutralized with ammonium hydroxide, made barium precipitated with hydrochloric acid (1-1.5 cc.), heated to boiling and the barium precipitated with hot ammonium sulphate solution (30 grams per liter). After standing on a steam plate for four hours, the barium sulphate is filtered off on a weighed platimm gooch crucible, ignited for 35 minutes and weighed.

The filtrate containing the SO_4 and washings from the barium carbonate is acidified with hydrochloric acid, 1-1.5 cc. excess heated to boiling, the sulphates precipitated with hot 10% barium chloride solution and proceeding as above.

¹ Standard Method of New Jersey Zinc Company.

Silica

One gram of the finely pulverized sample is weighed into a platinum crucible and fused with sodium carbonate as under Total BaO as Barium Sulphate. The melt is detached from the crucible, placed together with the crucible and cover in a 150 cc. platinum dish and covered with hot water. Leaching is carried on until disintegration of the fusion is complete. The residue, composed of mixed carbonates, silicates, etc., is filtered off, catching filtrate in a 400 cc. beaker, and washed thoroughly with hot water containing sodium carbonate. The residue on the paper is dissolved with hot dilute hydrochloric acid, catching in a separate 400 cc. beaker, and the paper thoroughly washed. This paper containing a portion of the silica is placed in a platinum crucible and retained.

The first filtrate, from the barium carbonate, is acidified and evaporated to dryness to dehydrate the silica. The second solution, containing the barium in solution as chloride is also evaporated to dryness. After dehydrating, the residues in both beakers are taken up with hydrochloric acid and filtered. They may be filtered through the same paper, washing the paper thoroughly before passing the second solution. Following the passage of the second solution, the paper is thoroughly washed, added to the original paper in the erucible, ignited and weighed. The contents of the crucible are treated with hydrofluoric and sulphuric acids, evaporated to dryness, ignited and weighed. The difference in weight is amount of silica present.

Iron and Alumina

The two filtrates from the silica determination are nearly neutralized with ammonium hydroxide (acidity 1 cc. hydrochloric acid), and combined. Ammonium sulphate solution is added to assure complete precipitation of all the barium, the beaker placed on a steam plate for two hours. The barium sulphate is then filtered off. The iron and alumina in the filtrate are precipitated with ammonium hydroxide, the precipitate filtered off, washed, ignited in a platinum crucible and weighed.

Lime

The filtrate from the precipitated iron and alumina is acidified slightly with hydrochloric acid, boiled down to a volume of less than 100 cc. and filtered if necessary. The solution is now made ammoniacal, heated to boiling, and 10 cc. of ammonium oxalate solution added. After standing for two hours in a warm place the precipitate of calcium oxalate is filtered off, washed with hot water, ignited and weighed.

Magnesia

The filtrate from the lime determination is boiled down to about 200 cc., slightly acidified, and 15 cc. of microcosmic salts (Saturated Solution) added. Ammonium hydroxide is added with 40 cc. in excess and the precipitate allowed to settle over night. The precipitate is then filtered off, dissolved with hydrochloric acid (1 part concentrated acid to four parts of water), diluted to 100 cc., 10 cc. of microcosmic salt solution added, followed by ammonium hydroxide with 40 cc. excess and allowed to stand over night. The precipitate of magnesium ammonium phosphate is filtered off, washed, carefully ignited and weighed.


Carbon Dioxide

The carbon dioxide is determined according to method given for carbonates under chapter on Carbon, page 111. It is necessary to use a large sample, i.e., 5-10 grams, and for samples containing a small amount of carbonates a Geissler absorption bulb is preferable to the heavy Fleming bulb.

Fluorine

One gram of sample is placed in a lead bomb with 12 cc. of sulphuric acid, the bomb closed with glass plate in place and heated in an oil bath for 45 minutes at 165° C. The etc. ing on the glass plate is compared with etching using known amounts of fluorine as CaF₂ and the same kind of glass.

The glass plate is kept cool by circulating cold water. The type of bomb and its connections are shown in figure 6a.



Loss on Ignition

One gram of the sample is weighed out into a platinum crucible dried at 110° C. for two hours and weighed. This moisture is to be used for calculating all results to a dry basis. The crucible is heated gently at first and then placed in a muffle furnace or over a blast lamp and ignited until it ceases to lose weight on reheating. This loss is calculated to a basis of one gram of dry material.

Blanc Fixe

This sulphate of barium is generally marketed as paste and less commonly in the form. Both pulp and dry forms should contain not less than 97.5% BaSO₄ on the dry basis. The pulp (paste) should not contain over 30% H₂O. Blane Fixe is used in

photography, in coating paper and in paint.

Qualitative Tests. Suitability for photographic purposes. Spread a sample on a glass plate and apply a drop of 10% AgNO, solution. Set aside in a dark closet. No dark brown or black stain should be evident in five minutes.

Alumina and Iron. Heat a small portion with HNO₃, dilute and filter. Test the filtrate with NH₄OH. A gelatinous colorless precipitate = Al(OH)₃, a red precipitate = Fe(OH)₃ and possibly Al(OH)₃ with the iron.

Lead. Extract a small portion with ammonium acetate and test the extract with

K₂Cr₂O₇. A yellow precipitate indicates PbCrO₄, showing the presence of PbSO₄. Silica. Test about 0.5 g. with 10 cc. conc. H₂SO₄, complete solution shows the absence of SiO2.

Organic Matter. Coloration of the acid in the silica test indicates the presence of

organie matter.

Carbonates. Addition of acid will cause effervescence in presence of carbonate. Phosphates. Extract a small portion with HNO, and test the extract with am-

pronium molybdate for phosphate.

Quantitative Analysis. The qualitative tests will indicate the presence of impurities. These can now be determined by the standard procedures. The following brief

outline may be found useful as a guide for the method of examination.

Moisture. Determine loss on 2-gram sample dried at 105° C. for two hours Loss on Ignition. Ignite residue from above. Loss is due to escape of CO₂ and

to organic matter and combined water.

Iron and Alumina. Digest a 5-gram sample with 150 cc. HCl (1:3). Evaporate extract to dryness, take up with 100 cc. dilute HCl and filter to remove SiO₂. Precipitate iron and alumina in filtrate in usual manner and determine. If P2O6 is present it will be present with the precipitate. If present it will be necessary to add a known quantity of iron as FeCl₃ to carry down all the P₂O₅. This iron and the P₂O₅, determined on a separate sample, must be deducted, to obtain the iron and alumina in the sample.

Phosphate. Extract a 2-grain sample with water by decantation. Digest the residue with a 10% solution of HNO₃ and filter. Precipitate P₂O₅ in the filtrate with ammonium molybdate in the usual manner. The yellow precipitate is dissolved in NH₄OH and P₂O_b precipitated with magnesia mixture and determined by the standard procedure.

> $Mg_2P_2O_7\times0.6379=P_2O_\delta$ $Mg_2P_2O_7 \times 2.7038 = Ba_3(PO_4)_2$

Lead Sulphate. This may be determined in the residue from the iron and alumina determination by extraction with ammonium acctate and precipitation with dichromate reagent by usual procedure. PbCrO₄ \times 0.9383 = PbSO₄.

For Other Ingredients consult chapter on Paint Analysis, page 1188.

BERYLLIUM (GLUCINUM)

Gl, at.wt. 9.1; sp.gr. $1.85^{20^{\circ}}$; m.p. > 960° C.; oxide, GlO.

DETECTION

In the usual course of analysis glucinum will be precipitated by ammonia along with iron and aluminum hydroxides. Silica having been removed by evaporation to dryness of the acid solution of the substance, extraction of the residue with dilute hydrochloric acid and subsequent filtration; the members of the hydrogen sulphide group are precipitated from slightly acid solution by hydrogen sulphide. The filtrate is concentrated to about 30 cc., and about 2 grams of sodium peroxide are added to the cooled liquid, which is now heated to boiling and filtered. Fe(OH), remains insoluble, if iron is present, while aluminum and glueinum dissolve. The filtrate is acidified with nitric acid, and ammonia then added in excess. If a precipitate forms, alumina or glucinum or both are indicated. Glucimum hydroxide and aluminum hydroxide cannot be distinguished by appearance; the solubility of the former in sodium bicarbonate solution makes it possible to separate the two. The precipitate is dissolved in acid and the solution made almost neutral with ammonia. Solid sodium bicarbonate is added in sufficient amount to make the solution contain 10% of the reagent and the mixture heated to boiling, then filtered. Alumina hydroxide remains on the filter paper and glucimum passes into the filtrate, in which it may be detected by diluting to ten volumes with water and boiling, whereupon glueinum hydroxide precipitates.

Ghieinum hydroxide, Gl(OH)₂, is precipitated from neutral or acid solution by ammonin, insoluble in excess (distinction from Al(OH)₃). It is precipitated by sodium and potassium hydroxides, soluble in excess (separation from iron); if this solution is boiled Gl(OH)₂ is reprecipitated, Al(OH)₃ remains in solution. Gl(OH)₂ is soluble in an excess of ammonium carbonate, Al (OH)₃ is insoluble.

ESTIMATION

Glucinum occurs in the minerals beryl, cuclase, davalite, chrysoberyl, helvite, leucophane, phencaite.

The oxide, GlO, is soluble in strong sulphuric acid. It is decomposed by fusion with potassium fluoride. The freshly precipitated hydroxide, Gl(OH)₂, is easily soluble in dilute acids, in alkalies and alkali carbonates and bicarbonates.

The methods of preparation and solution of the sample are the same as those described for the estimation of aluminum. For details of these procedures the analyst is referred to the chapter on this element.

Chapter contributed by W. W. Scott.

SEPARATIONS

Removal of Silica and Members of the Hydrogen Sulphide Group. See procedure given under "Detection."

Separation of Glucinum from Iron and Manganese. The acid solution is nearly neutralized with annuonia and then poured with constant stirring into an excess of a cold mixture of annuonium sulphide and carbonate. Iron and manganese are precipitated, whereas glucinum passes into the filtrate. (Zirconium and yttrium will be found with glucinum, if they are present in the material examined.)

Separation from Zirconium and Yttrium. The filtrate obtained from the separation of iron and manganese is boiled for an hour, the precipitate is filtered and washed, then dissolved in dilute hydrochloric acid. To this solution is added an excess of sodium hydroxide, zirconium and yttrium are precipitated, whereas glucimum remains in solution. After filtering, glucinum may be precipitated by boiling the diluted filtrate.

Separation from Aluminum, Chromium and Iron. The elements precipitated as hydroxides are ignited to oxides and fused with sodium carbonate for an hour or more. Upon leaching with water, aluminum and chromium dissolve, while iron and glucinum remain insoluble. The oxides of glucinum and iron may be separated by fusion with sodium acid sulphate, extracting with water and precipitating the iron with an excess of sodium hydroxide, glucinum remaining in solution.

Separation of Glucinum from Aluminum. The hydroxides of alumina and glucinum are precipitated with ammonia and the precipitate treated with an excess of ammonium carbonate. Gl(OII)₂ dissolves, whereas Al(OH)₄ remains insoluble. See Detection, also Gravimetric Method for Determination of Glucinum.

Barium carbonate is precipitated from ammoniacal solution by addition of ammonium carbonate in slight excess and allowed to settle at least an hour (preferably longer). The carbonate is filtered and washed with dilute NH₄OH, dried and gently ignited to constant weight and weighed as BaCO₃. It is advisable to add a little ammonium carbonate powder to the BaCO₃ with the final ignition.

Notes. The mineral beryl contains approximately 14 per cent of beryllium oxide, BeO, and is the principal source of beryllium. Beryllium is used in alloys. The aluminum alloy has considerable tensile strength, is hard and light (sp.gr. 2.5 with 90% Al and 10% Be). Beryllium added to alloys of calcium and aluminum makes a tougher and more malleable product. (85% Al, 10% Be, 5% Cu, sp.gr. 2.8 with tensile strength equal to that of bronze.) Alloys of beryllium and copper are valuable for making scientific instruments on account of their electrical properties. Beryllium oxide is used in incandescent mantles. It acts as an accelerator for catalyzers. N.B. Ind. Eng. Chem., 16, 74 (Jan., 1924). Article on catalyzers by W. W. Scott.

GRAVIMETRIC DETERMINATION OF BERYLLIUM

The procedure recommended by Parsons and Barnes depends upon the solubility of glucinum hydroxide in a 10% sodium bicarbonate solution, in the separation of this element from iron and aluminum hydroxide precipitate, with which it is commonly thrown out from solution. (Uranium, if present, also dissolves.)

Procedure. Siliea and the members of the hydrogen sulphide group having been removed by the usual methods (See Detection), hydrogen sulphide is expelled by boiling, nitric acid is added in sufficient amount to oxidize iron (the hydrochloric acid solution turns yellow) and animonium hydroxide added in slight excess. The precipitated hydroxides are allowed to coagulate by heating to boiling and, after settling a few minutes, filtered and washed with a 2% solution of animonium acetate containing free animonia.

Separation from Iron and Aluminum Hydroxide. The precipitate is dissolved in hydrochloric acid, the solution oxidized with nitric acid or hydrogen peroxide (C.P.), if necessary, and the free acid then neutralized with ammonia. To the cold solution are added 10 grams of sodium bicarbonate for each 100 cc. of liquid. The mixture is hented to boiling and boiled for one minute, then cooled and filtered. The residue is washed with hot 10% solution of sodium bicarbonate. Iron and aluminum hydroxides remain on the filter and glucinum passes into the filtrate.

To recover occluded glucinum from the hydroxides of iron and alumina, the precipitate is dissolved in a few drops of hydrochloric acid, and the precipitation repeated. It is advisable to repeat this treatment a third time, adding the filtrates to the first portion containing the glucinum.

Precipitation of Glucinum. The combined filtrates from the alumina and iron hydroxides are acidified with strong hydrochloric acid, the beakers covered to prevent loss by spurting and the carbon dioxide completely removed by boiling. (CO₂ remaining in solution would form ammonium carbonate, on subsequent treatment with ammonia, which would dissolve glucinum.) A slight excess of mumonia is now added, the mixture again boiled and the precipitated glucinum hydroxide allowed to settle, then filtered and washed with a 2% solution of ammonium accente containing free ammonia, until the chlorides are removed. After ignition the residue is weighed as glucinum oxide, GlO.

C. L. Parsons and S. K. Barnes, Jour. Am. Chem. Soc., 28, 1589, 1906.
 Prolonged boiling would cause the loss of too much CO₂, so that Al(OII)₃ would be apt to pass into solution. The evolution of CO₂ may be mistaken for boiling.

Other Methods for Determining Beryllium (or Glucinum)

Gibson's Method.1 Decomposition of beryl is heated with ammonium hydrogen fluoride. Much of the silica is volatilized as ammonium fluosilieate and the aluminum and beryllium are converted to fluorides, then to sulphates. Beryllium is now separated from aluminum by extraction with ammonium earbonate and precipitated from the extract by boiling.

Pollok's Method.² The beryl is fused with caustic soda, and the fusion is dissolved in HCl. The hydroxides are now precipitated with NH₄OH and filtered and washed. The precipitate is dissolved in HCl and aluminum preeipitated by saturation with HCl gas. (See notes below.) (AlCl₃.4H₂) precipitated. Animonium carbonate is now used to separate the beryllium by methods described.

Notes.3 Be(OH)2 resembles Al(OH)3 in being soluble in an excess of fixed alkali, but differs from it by the fact that Be(OII)₂ reprecipitates on boiling the solution, while aluminum remains in solution.

A saturated solution of sodium carbonate dissolves Be(OII), but not Al(II), or Fe(OH)3.

If ether is added to a solution or BeCl₂ and AlCl₃ and then HCl gas passed in, aluminum chloride is precipitated, while beryllium remains in solution.

Fusion of the oxides of aluminum and beryllium with Na₂CO₃ produces a water soluble aluminate of sodium, while beryllium remains insoluble. Fusion with $\rm Na_2SIF_6$ produces soluble $\rm Na_2BeF_4$ and insoluble $\rm Na_2AlF_6$.

- Jour, Chem. Soc., 63, 909 (1893).
 Trans. Roy. Dublin Soc., 8, 139 (1904).
 Chemistry of the Rarer Elements by B. Smith Hopkins. The Analysis of Minerals and Ores of the Rarer Elements by W. R. Schoeller and A. R. Powell.

BISMUTH

Bi, at.wt. 209.0; sp.gr. 9.7474; m.p. 271°; b.p. 1420° C.; oxides, Bl₂O₃, Bl₂O₄,

DETECTION

Bismuth is precipitated from its solution, containing free acid, by H₂S gas, as a brown sulphide, Bi₂S₂. The compound is insoluble in ammonium sulphide (separation from arsenic, antinony, and tin), but dissolves in hot dilute nitric acid (separation from mercury). The mitrate, treated with sulphuric acid and taken to SO₄ fumes, is converted to the sulphate and dissolves upon dilution with water (lead remains insoluble as PbSO₄). Bismuth is precipitated from this solution by addition of ammonium bydroxide, white Bi(OH)₃ being formed (copper and cadmium dissolve). If this hydroxide is dissolved with hydrochloric acid and then diluted with a large volume of water, the white, basic salt of bismuth oxychloride, BiOCl, is precipitated. The compound dissolves if sufficient hydrochloric acid is present. It is insoluble in tartaric acid (distinction from antimony).

Reducing Agents. Formaldehyde in alkaline solution, hypophosphorous acid, potassimi or sodium stamite, reduce bismuth compounds to the metallic state. For example, a hot solution of sodium stamite poured onto the white precipitate of Bi(Oll), on the filter will give a black stain. The test is very delicate and enables the detection of small amounts of the compound.

 $3K_{2}SnO_{2} + 2BiCl_{3} + 6KOII = 2Bi + 3K_{2}SnO_{3} + 6KCl + 3H_{2}O$

Blowplpe Test. A compound of bismuth heated on charcoal with a powdered mixture of carbon, potassium iodide and sulphur, will give a scarlet incrustation on the charcoal.

ESTIMATION

The determination of bismuth is required in complete analysis of ores of cobalt, nickel, copper, silver, lead, and tin, in which it is generally found in small quantities. In evaluation of bismuthite, bismuth other, etc. In the analysis of the minerals wolfram, molybdenite. It is determined in the residues from the refining of lead (the principal source of bismuth in the United States). In the analysis of alloys—antifriction metals, electric fuses, solders, stereotype metals, certain amalgams used for silvering mirrors (with or without lead or tin), and in bismuth compounds.

Preparation and Solution of the Sample

In dissolving the substance, the following facts must be kept in mind: nitric acid is the best solvent of the metal. Although it is soluble in hot sulphuric acid, it is only very slightly soluble in the cold acid. The metal is practically insoluble in hydrochloric acid, but readily dissolves in nitrohydrochloric acid.

Chapter contributed by W. W. Scott and J. J. Mulligan.

The hydroxides, oxides, and most of the bismuth salts are readily soluble in hydrochloric, nitric, and sulphurie acids.

Ores or Cinders. One gram of the finely pulverized ore or einder (or larger amounts where the bismuth content is very low) is treated in a 400-ec, beaker with 5 cc. of bromine solution (Br+KBr+H₂O), followed by the cautious addition of about 15 cc. of HNO₃ (sp.gr. 1.42). When the violent action has ceased, which is apt to occur in sulphide ores, the mixture is taken to dryness on the steam bath, 10 cc. of strong HCl and 20 cc. of concentrated H₂SO₄ and the covered sample heated until SO₃ fumes are freely evolved. The cooled solution is diluted with 50 cc. of water and gently heated until only a white or light gray residue remains. The solution is filtered and the residue washed with dilute H₂SO₄ (1:10), to remove any adhering bismuth. Silica, the greater part of the lead (also BaSO₄) remain in the residue, whereas the bismuth, together with iron, alumina, copper, antimony, etc., are in the solution. Details of further treatment of the solution to effect a separation of bismuth are given under "Separations" and the procedures for determination of bismuth.

Alloys, Bearing Metal, etc. One gram of the borings, placed in a small beaker, is dissolved by adding 20 ec. of concentrated HCl and 5 ce. of strong HNO₃. The alloy will usually dissolve in the cold, unless considerable lead is present, in which case prolonged heating on the steam bath may be necessary. (A yellow or greenish-yellow color at this stage indicates the presence of copper.) Lead may now be removed either as a sulphate by taking to SO₃ fumes with H₂SO₄ or by precipitating as a chloride, in the presence of alcohol, according to directions given under Separations. The bismuth is determined in the filtrate from lead according to one of the procedures given under the quantitative methods.

Lead Bullion, Refined Lead. Ten to twenty-five grams of the lead, hammered or rolled out into thin sheets and cut into small pieces, are taken for analysis. The sample is dissolved by a mixture of 250 cc. of water and 40 cc. of strong nitric acid, in a large covered beaker, by warming gently, preferably on the steam bath. When the lead has dissolved, the beaker is removed from the heat and dilute ammonia (1:2) added to the warm solution, very cautiously and finally drop by drop until the free acid is neutralized and the liquid remains faintly opalescent, but with no visible precipitate. Now 1 cc. of dilute HCl (1:3) is added. The solution will clear for an instant and then a crystalline precipitate of bismuth oxychloride will form, if any considerable amount of bismuth is present. The beaker is now placed on the steam bath for an hour, during which time the bismuth oxychloride will separate out, together with a small amount of lead and with antimony if present in appreciable amounts. The further isolation and purification of bismuth is given under "Separations." In brief-antimony is removed by dissolving the precipitate in a small amount of hot dilute HCl (1:3), precipitating bismuth, traces of lead, and the antimony by H₂S, dissolving out the antimony sulphide with warm ammonium sulphide, dissolving the Bi₂S₂ and PbS in HNO₂ and reprecipitation of the bismuth according to the procedure given above. Bismuth is now determined as the oxychloride. Further details of this method are given under the gravimetric procedures for bismuth.

¹ Bromine solution is made by dissolving in water 75 grams of KBr, to which are added 50 grams of liquid bromine and the mixture diluted to 500 ec. with water.

SEPARATIONS

The following procedures are given in the order that would be followed in the complete analysis of an ore, in which all the constituents are sought. This general scheme, however, is not required for the majority of bismuth-bearing samples commonly met with in the commercial laboratory, direct precipitations of bismuth frequently being possible.

Separation of Bismuth from Members of Subsequent Groups, Fe, Cr, Al, Mn, Co, Ni, Zn, Mg, the Aikaline Earths and Alkalies, together with Rare Elements of these Groups. The solution should contain 5 to 7 ec. of concentrated hydrochloric acid (sp.gr. 1.19) for every 100 ec. of the sample. The elements of the hydrogen sulphide group are precipitated by saturating the solution with H₂S (Hg, Pb, Bi, Ch, Cd, As, Sb, Sn, Mo, Se, Te, Au, Pt). The members of subsequent groups remain in solution and pass into the filtrate.

Separation of Bismuth from Arsenic, Antimony, Tin, Molybdenum, Tellurium, Selenium. In presence of mercury, the soluble members of the hydrogen sulphide group are separated from the insoluble sulphides by digesting the precipitate above obtained with anmonium sulphide; in absence of mercury, however, which is generally the case, digestion of the sulphides with sodium hydroxide and sodium sulphide solution is preferred, the general procedure being followed. Mercury, lead, bismuth, copper, and cadmium remain in the residue, whereas the other members of the group dissolve.

Separation of Bismuth from Mercury. The insoluble sulphides, remaining from the above treatment with ammonium sulphide after being washed free of the soluble members of this group, are placed in a porcelain dish and boiled with dilute nitric acid (sp.gr. 1.2 to 1.3). The solution thus obtained is filtered, upon dilution, from the insoluble sulphide of mercury. A little of the lead may remain as PbSO₄, the solution may contain lead, bismuth, capper, and cadmium.

Separation of Bismuth from Lead. This is the most important procedure in the determination of bismuth as the separation is almost invariably necessary, as these elements commonly occur together.

Precipitating Lead as PbSO₄. This procedure is generally used in the process of a complete analysis of an ore containing lead and hismuth. The nitrie acid solution of the sulphides, obtained upon removal of the soluble group and mercury by hoiling the insoluble sulphides with dilute nitrie acid, is treated with about 10 ec. of strong sulphuric acid, and taken to SO₃ fumes by heating. The cooled sulphate solution is diluted with water and the insoluble lead sulphate filtered off and washed with dilute sulphuric acid solution (1:20). Bismuth passes into solution, together with copper and cadmium, if also present in the original sample.

Precipitation of Lead as PbCl₂. This separation is used in the complete analysis of pig lead.

Separation of Bismuth from Copper and Cadmium. This separation is accomplished by precipitating bismuth as the oxychloride with hydrochloric acid, or as the carbonate by adding an excess of ammonium carbonate to the solution nearly neutralized by ammonia, or as the hydroxide by adding an excess of ammonia. Details of these procedures are given under the gravimetric methods for determining bismuth.

GRAVIMETRIC METHODS FOR THE DETERMINATION OF BISMUTH

Determining Bismuth by Precipitation and Weighing as the Basic Chloride, BiOCl

The determination depends upon the formation of the insoluble oxychloride, BiOCl, when a hydrochloric acid solution of bismuth is sufficiently diluted with water, the following reaction taking place, $BiCl_1+H_2O=BiOCl+2HCl$.

The procedure is recommended for the determination of bismuth in refined lead, bearing metal, and bismuth alloys. Copper, cadmium, and lead do not interfere; appreciable amounts of antimony and tin, however, should be removed by H₂S precipitation and subsequent treatment with Na₂S, and the residual sulphides dissolved in hot dilute nitric acid, according to directions given under "Separations."

Properties of BiOCl. Mol.wt., 259.46; sp.gr., 7.717^{15°}; m.p., red heat; insol. in H₂O and in H₂C₄H₄O₆, soluble in acids. Appearance is white, quadratic crystalline form.

Procedure. The solution of bismuth, freed from appreciable amounts of tin and antimony, is warmed gently and treated with sufficient ammonia to neutralize the greater part of the free acid. At this stage a precipitate is formed by the addition, which dissolves with difficulty; the last portion of the dilute ammonia (1:2) is added drop by drop, the solution is diluted to about 300 ce., and the remainder of the free acid neutralized with dilute ammonia added cautiously until a faint opalescence appears, but not enough to form an appreciable precipitate. One to 3 cc. of dilute hydrochlorie acid (1 part HCl sp.gr. 1.19 to 3 parts H₂O) are now added, the mixture stirred and the bismuth oxychloride allowed to settle for an hour or so on the steam bath, then filtered hot by decanting off the clear solution through a weighed Gooch erucible. The precipitate is washed by decantation twice with hot water and finally washed into the Gooch, then dried at 100° C. and weighed as BiOCl.

$BiOCl \times 0.8017 = Bi$.

Note. Three ce. of dilute hydrochloric acid (or 1 cc. conc. HCl, sp.gr. 1.19) are sufficient to completely precipitate 1 gram of bismuth from solution.

Determination of Bismuth as the Oxide, Bi₂O₃

Preliminary Considerations. The determination of bismuth as the oxide requires the absence of hydrochloric acid or sulphuric acid from the solution of the element, since either of these acids invariably contaminates the final product. In presence of these acids, which is frequently the case, determination of bismuth by precipitation as Bi₂S₃ or by reduction to the metal and so weighing is generally recommended; a brief outline of the methods is given later; a solution of bismuth free from hydrochloric acid and practically free of sulphuric acid may be obtained by precipitating Bi₂S₃, together with CuS, CdS, and PbS, the amount of sulphuric acid formed by the reaction being negligible. Bismuth should be in a nitric acid solution, free from antimony and tin.

Two general conditions will be considered: 1. Solutions containing lead. Copper and cadminm may also be present. 2. Solutions free from lead. Copper and cadmium may be present.

1. Separation from Lead, Copper, and Cadmium, by Precipitation as Basic Nitrate. Either the sulphuric or hydrochloric acid methods may be employed for effecting the separation of lead by precipitation. Furthermore advantage may be taken of the fact that bismuth mitrate is changed by the action of water into an insoluble basic salt, while lead, copper and cadmium do not undergo such a transformation.

Procedure. The bismuth nitrate solution is evaporated to syrupy consistency and hot water added with constant stirring with a glass rod. The solution is again evaporated to dryness, and the hot-water treatment repeated. Four such evaporations are generally sufficient to convert the bismuth nitrate completely into the basic salt; when this stage is reached the addition of water will fail to produce a turbidity. The solution is finally evaporated to dryness and, when free from nitric acid, is extracted with cold ammonium nitrate solution (1.NH₄NO₂: 500 H₂O) to dissolve out the lead and other impurities. After allowing to stand some time with frequent stirring, the solution is filtered and the residue washed with ammonium nitrate solution, then dried.

Ignition to Bismuth Oxide. As much of the precipitate as possible is transferred to a weighed porcelain crucible, the filter is burned and the ash added to the main precipitate. This is now gently ignited over a Bunsen burner. Too high heating will cause the oxide to fuse and attack the glaze of the crucible.

Properties. Bi(OH)₂NO₃ mol.wt., 301.03; sp.gr., 1.928.5°; decomp., 260°; insol. in H₂O; sol. in acids; hexagonal plates.

Bi₂O₄ = mol. wt., 464.0; sp.gr., 8.8 to 9.0; m.p., 820 to 860°; insoluble in cold water and in alkalies, but soluble in acids; yellow tetragonal crystals.

Bi₂O₄×0.8965 = Bi.

- 2. Precipitation of Bismuth as the Subcarbonate or Hydroxide, Lead being Absent. Either of these procedures effects a separation of bismuth from copper and cadmium.
- A. Procedure. Precipitation of the Subcarbonate. The solution is diluted to about 300 ec. and dilute ammonia added cautiously until a faint turbidity is obtained and then an excess of ammonium carbonate. The solution
 - ¹ J. Löwe, Jour. prak. Chem., (1), 74, 344, 1858.

is heated to boiling, the precipitate filtered off, washed with hot water, dried and ignited according to directions given in the bismuth subnitrate method. The residue is weighted as Bi₂O₃.

B. Procedure. Isolation of Bismuth by Precipitation as the Hydroxide.¹ The solution is taken to dryness and the residue treated with 5 cc. of nitric acid (1:4) and 25 cc. of water added. The resulting solution is poured, with constant stirring, into 25 cc. of concentrated anunonia and 50 cc. of 4% hydrogen peroxide. Upon settling of the bismuth hydroxide, the clear solution is filtered off and the residue is treated with more anunonia and peroxide. It is then filtered onto a filter paper, washed with hot, dilute ammonium hydroxide, (1:8), followed by hot water and washed free of any adhering copper or cadmium (no residue when a drop is evaporated on platinum foil). Re-solution in hot dilute nitrie acid and reprecipitation may sometimes be necessary to obtain the pure product. The hydroxide may be dried, ignited and weighed as Bi₂O₃ according to directions already given on page 74.

Properties. Bi₂O₃·CO₂·H₂O, mol.wt., 526.02; sp.gr., 6.86; decomp. by heat; insoluble in water, soluble in acids, insoluble in Na₂CO₃; white precipitate.

Bi(OH)₃, mol.wt., 259.02; loses 1½ H₂O at 150°; insol. in cold water and in alkalies; soluble in acids; white precipitate.

Determination of Bismuth as the Sulphide, Bi₂S₃

The procedure is applicable to the determination of bismuth in a hydrochloric or sulphuric acid solution, freed from other members of this group.

Procedure. Bisnruth sulphide is precipitated by passing H₂S into the slightly acid solution, preferably under pressure. When the precipitation is complete, the bismuth sulphide, Bi₂S₃, is filtered off into a weighed Gooch crucible, the precipitate washed with H2S water, then with alcohol to remove the water, followed by carbon disulphide to dissolve out the precipitated sulphur, then alcohol to remove the disulphide, and finally with ether. After drying for fifteen to twenty minutes, the residue is weighed as Bi₂S₃. This weight multiplied by 0.8122 = Bi.




Fig. 7.—Purification of Carbon Disulph. Ge.

Note. The carbon disulphide used should be freshly distilled. This may be accomplished by placing the carbon disulphide in a small flask (A, Fig. 7) connected by means of a glass tube (C) to a second flask (B), cork stoppers being used. The vessels are immersed in beakers of water, the container with the reagent being placed in hot water (60-80°C.) and the empty flask in cold water. The reagent quickly distills into the empty flask in pure form.

Properties of Bismuth Sulphide. BirS₃, mol.wt., 512.21; sp.gr., 7-7.81; decomposed by heat, solubility = 0.000018g. per 100 ce. cold H_2O ; soluble in nitric acid: brown rhombic crystals.

¹ P. Jannasch, Zelt. anorg. Chem., 8, 302, 1895.

Determination of Bismuth as the Metal

Reduction with Potassium Cyanide. Bismuth precipitated as the earbonate and ignited to the oxide according to the procedure given, is fused in a weighed porcelain crucible with 5 times its weight of potassium cyanide over a low flame. The cooled melt is extracted with water, pouring the extracts through a filter that has been dried and weighed with the crucible. Bismuth is left undissolved as metallic bismuth. After washing with water, alcohol, and ether, the filter, with the metal and loosened pieces of porcelain glaze, is dried at 100° C. together with the crucible. These are then weighed and the increased weight taken as the amount of bismuth present in the sample.

Electrolytic Deposition of Bismuth

With samples containing less than 0.03 gram bismuth, the metal may be satisfactorily deposited by electrolysis of its sulphuric acid solution, lead having been removed previously by sulphuric acid by the standard procedure. The solution contains about 6 cc. of strong sulphuric acid per 100 ce. This is electrolyzed with a current of 0.6 to 0.7 ampere and about 2.7 to 3 volts.

VOLUMETRIC DETERMINATION OF BISMUTH

Determination of Bismuth by Precipitation as Oxalate and Titration by Potassium Permanganate 2

Normal bismuth oxalate, produced by addition of oxalic acid to a nitric acid solution of the element, boiled with successive portions of water, is transformed to the basic oxalate. This may be titrated with potassium permanganate in presence of sulphuric acid.

Procedure. Preparation of the Sample. One gram of the finely ground sample is treated with 5 to 10 cc. of concentrated nitric acid and digested on the steam bath and finally evaporated to dryness, the residue is taken up with 5 cc. of nitrie acid (sp.gr. 1.42) +25 cc. of water, and diluted to 100 cc.

Precipitation of the Oxalate. About 5 grams of ammonium oxalate or oxalie acid are added and the liquid boiled for about five minutes, the preeipitate allowed to settle and the supernatuut solution filtered off. The precipitate is boiled twice with 50-cc. portions of water and the washings poured through the same filter. If the filtrate still passes through acid, the washing is continued until the acid is removed and the washing passing through the filter is neutral. The bulk of the basic oxalate precipitate is placed in a beaker and that remaining on the filter paper is dissolved by adding 2 to 5 cc. of hydroehloric acid, 1:1, the solution being added to the bulk of the precipitate.

¹ Method by H. Rose, Pogg. Ann., 110, p. 425. Vanino and Treubert (Ber., 31 (1898), 1303), reduce bismuth by adding formal-dehyde to its slightly acid solution and then making strongly alkaline with 10% NaOH solution and warming.

² The method is rapid and is sufficiently accurate for commercial work. Warwick and Kyle (C. N., 75, 3). Muir and Robbs, J. C. S., 41, 1.

This is now warmed until it goes into solution and the liquid is diluted to 250 c. with hot water. Dilute ammonia is now added until the free acid is eutralized; the resulting precipitate is taken up with dilute sulphuric acid, 1:4, dded in slight excess. The resulting solution, warmed to 70°, is titrated with tandard potassium permanganate.

One ec. KMnO₄ N/10 = 0.0104 gram Bi.

NOTE. Lead, copper, arsenic, iron, zinc, and tellurium do not interfere. Hy-rochloric acid should not be used to dissolve the sample, as it interferes with the xalate precipitation.

Cinchonine Potassium Iodide, Colorimetric Method 1

This method is applicable for the determination of small amounts of bisnuth, 0.00003 to 0.00015 gram, in ores and alloys. The procedure depends ipon the fact that bismuth nitrate produces a crimson or orange color when its solution is added to a solution of cinchonine potassium iodide, the intensity of the color depending upon the amount of bismuth in the resulting product.

Special Reagents. Cinchonine Potassium Iodide Solution. Ten grams of inchonine are dissolved by treating with the least amount of nitrie acid that is necessary to form a viscous mass and taking up with about 100 ee. of water. The acid is added a drop at a time, as an excess must be avoided. Twenty grams of potassium iodide are dissolved separately and cinchonine solution added. The resulting nuxture is diluted with water to 1000 ce. After allowing the reagent to stand forty-eight hours, any precipitate formed is liltered off and the clear product is ready for use. The reagent preserved in a glass-stoppered bottle keeps indefinitely. It should be filtered free of suspended matter before use.

Standard Bismuth Solution. One gram of metallic bismuth is dissolved in the least amount of dilute nitric acid (1:1) that is necessary to keep it in solution and diluted to 1000 cc., in a graduated flask. One hundred cc. of this solution is diluted to 1000 cc. One cc. of this diluted solution contains 0.0001 gram bismuth.

Procedure. Isolation of Bismuth. The solution is freed from lead by H₂SO₄, and from arsenic, antimony, and tin by precipitation of the sulphides and extraction with Na₂S solution. The residual sulphides are dissolved in hot dilute nitric acid, according to the standard methods of procedure. The free nitric acid is nearly neutralized by the cautious addition of dilute ammonia, the last portion being added drop by drop, until a faint cloudiness is evident, and then 10 to 15 ec. of 10% ammonium carbonate are added with constant stirring. The mixture is digested for about three hours on the steam bath, the clear solution decanted through a small filter, the residue washed by decantation once or twice with hot water containing ammonium carbonate and then on the filter twice with pure hot water.

Colorimetric Comparison

The residue of bismuth basic carbonate is dissolved in the least amount of dilute nitrie acid necessary to effect solution and the filter washed free of bismuth with a little water containing a few drops of nitrie acid. The solution is made up to a definite volume, 50 cc. or 100 cc. according to the bulk of

¹Method of W. C. Ferguson.

precipitate dissolved. Two small beakers placed side by side may be used for the color comparison, a sheet of white paper or tile being placed under the beakers. Two 50-cc. Nessler tubes, however, are preferred. Three ee. of einchonine solution are added to each container. From a burette the bismuth nitrate sample is run into one of these containers in just sufficient quantity to color the reagent a crimson or orange tint. The exact volume required to do this is noted and the equivalent amount of sample used calculated. (If no color is produced bismuth is absent.) The reagent in the adjacent beaker or Nessler tube is diluted to 5 to 7 cc., and into this is run, from a burette, the standard bismuth nitrate solution until the color exactly matches the sample. From the cc. of the standard required the amount of bismuth in the sample can readily be calculated.

Reaction. $3KI + (_{19}II_{22}N_2OKI + Bi(NO_3)_3 = (_{19}II_{22}N_2OKIBiI_3 + 3KNO_3,$

Precautions. The sensitiveness of the method is lost if the depth of color is too great. It is necessary, then, to add the sample to the cinchonine reagent in such quantity only as will produce a light crimson or orange color.

Solutions in the comparison tubes or beakers must not be overdiluted, since the bismuth salt formed by the reaction of the cinchonine reagent is soluble in water with the disappearance of color in too dilute solutions.

Comparison must be expeditiously made, as a precipitate is apt to form upon

standing, and iodine will sometimes separate.

The order of addition must be observed; e.g., the bismuth solution is added to the einchonine reagent, never the reverse.

Colorimetric Determination of Bismuth. Bismuth Iodide Method 1

Bismuth iodide gives an intense yellow, orange, or red color to its solution. The color is not destroyed by SO₂, as is that of free iodine. The intensity of the color varies as follows:

1 part of bismuth in 10,000 parts of water produces an orange-colored solution. 1 part of bismuth in 40,000 parts of water produces a light orange color.

I part of bismuth in 100,000 parts of water produces a faint yellow color.

Reagents. Standard Bismuth Solution. One gram of bismuth is dissolved in 3 cc. of strong nitric acid and with 2.8 cc. of water and made up to 100 cc. with glycerine. Glycerine is added to keep the BiI₂ in solution. Glycerine is not necessary for amounts of bismuth below 0.0075 gram per cc.

Potassium Iodide Solution. Five grams of potassium iodide dissolved in 5 cc. of water is diluted to 100 cc. with glycerine.

Procedure. The sample is dissolved with just sufficient nitric acid and water necessary to cause solution, 10 cc. of glycerine and 10 cc. of potassium iodide solution added and the sample diluted to 50 cc. Comparison is now made with 10 cc. of the standard bisauth solution to which has been added 10 cc. of potassium iodide and 30 cc. of water. It is advisable to have the standard stronger in bismuth than the sample and to draw out the standard from the comparison cylinder until the two colors match.

¹T. C. Thresh, Pharm. Jour., 641, 1880.

Bismuth Determination in Lead Bullion¹

Ten to twenty-five grams of the lead, hammered or rolled out and cut into small pieces, are taken for analysis. The sample is dissolved in a mixture of 200 ec. water and 50 ec. strong nitrie acid, in a large covered beaker, and warmed gently on water or steam bath. When lead has dissolved, the beaker is removed and placed on cool surface and enough sulphuric acid (1-1) added to precipitate lead.

The lead sulphate is allowed to settle and the elear supernatant liquid is deeanted into another beaker and held. To the residue of lead sulphate 10-20 ce, concentrated sulphuric acid is added and brought down to strong fumes on hot plate. After strong fuming, the portion containing lead sulphate is diluted with water. To the first clear decanted portion, 10 cc. sulphuric acid is added and this also evaporated down to fumes of sulphuric acid. Both portions are removed from hot plate and when cool add 50 ee, water and 3 to 5 grams of tartarie acid to each. Heat to dissolve tartaric acid and filter over asbestos pad, the clear portion first, and then follow with the one containing bulk of lead sulphate. The bulk of lead sulphate is washed by deeantation three or four times with warm water before transferring to asbestos pad. When bismuth is higher than .30% in the bullion, the sulphate residue may be retreated with sulphuric acid, fumed and washed. The clear solution is allowed to stand for one honr and refiltered to ensure removal of all lead sulphate. The filtrate is then warmed and hydrogen sulphide gas passed filtered on a paper and washed with cold H_2S water. The sulphides are washed from filter back to precipitating beaker. The sulphides of Sb, Sn, Te, etc., are leached out with a $10\%~K_2S$ solution, which has been saturated with hydrogen sulphide, and allowed to stand in warm place and filtered over the original sulphide paper. After washing with warm water containing a few drops of K₂S solution, the precipitate is dissolved in nitric acid and a few drops of bronine to ensure solution of all sulphur. It is all important to remove Sb, Sn and Te from sulphide precipitate before going any further by repeating hydrogen sulphide precipitation.

The nitric acid solution of Bi, Cu, etc. is made faintly alkaline with ammonia and 1 gram ammonium carbonate added and the solution boiled for five to ten minutes when the bismuth is precipitated as basic salt. To ensure solution of the copper, a few drops of free ammonia are added with stirring before filtering. The bismuth precipitate is filtered on a tared gooch, washed with water, dried and ignited to Bi₂O₃ over Bunsen flame.

$$Bi_2O_3 \times .8966 = Bi$$
.

If the bismuth precipitate is dark after precipitation with ammonia and ammonium carbonate, it may be due to tellurium. If so, the filtered precipitate is dried, ignited and fused with caustic potash and sulphur to put the tellurium in a soluble form and thus remove tellurium from insoluble bismuth sulphide; or redissolving in acid and reprecipitating as sulphides and washing the sulphides with K_2S solution as before mentioned.

This method is applicable to refined lead when larger portions are taken.

¹ J. J. Mulligan.

Bismuth in Alloys1

The alloy is dissolved in nitric acid, as little hydrochloric as possible, and 10 cc. sulphuric, and run down to strong SO₃ fumes and proceed as for ores.

Where bismuth is present with considerable tin, the cementation of the bismuth with pure iron wire to free it from tin and then treat residue same as for ores and mattes, seems to be the best means for obtaining a bismuth precipitation free of tin for coatrol analyses.

In the presence of considerable copper, the bismuth can be precipitated as basic carbonate, filtered and the impure basic precipitate treated with nitric acid and evaporated to fumes of sulphuric, the procedure is then the

same as for ores and matte.

Determination of Bismuth in Ores, Mattes¹

A qualitative test for lead and insoluble bismuth compounds on all products to be analyzed for bismuth is an important step with the removal of lead as sulphate as soon as perfect solution of the sample is insured.

For products containing from ½% to 25% bismuth, one gram portions are

taken; for 50% or higher ½ gram portions are weighed up.

The weighed portion is transferred to a 250 ee. beaker and 25 ec. H₂O and 10 cc. concentrated aitrie acid added, and where sulphur is present a few drops of bromine are added cautiously after acid has been allowed to act for a sufficient time. After all sulphur has gone in solution, boil down to dryness on water bath or hot plate, 2 cc. of nitrie acid and 1 cc. hydrochloric acid are added, then 10 ec. of sulphuric acid cautiously added, and the covered sample taken down on hot plate to strong fumes of SO₃. The cooled solution is diluted with 50 ec. water and 2 to 3 grains tartarie acid are added and the mixture brought to a boil. The residue containing insoluble lead sulphate, silica and other insolubles are filtered and washed with 2% solution of sulphuric acid to free residue of soluble bismuth.

The filtrate contains Bi, Cu, Sb, As, Te and a small amount of Pb may be in the solution. After standing for one-half hour or more, the solution is refiltered to remove any lead that may have gone through on first filtration.

The clear solution containing bismuth is saturated with hydrogen sulphide gas for one-half hour.

Filter sulphides on filter paper and wash with H₂S water. If much iron is present the sulphides are redissolved in nitrie and sulphurie, taken to fumes, and the sulphide precipitation repeated.

The sulphides are leached with a 10% solution of K₂S saturated with H₂S gas to remove As, Sb, Sn, Te and Sc. The remaining sulphides containing Cu, Cd, Bi are dissolved in nitric neid and a little bromine water, bromine boiled off and solution made slightly alkaline with ammonia water and 1 gram of ammonium carbonate added. The solution is boiled for five to ten minutes and 1 cc. of ammonia is added and the basic carbonate filtered on a tared Gooch, ignited and weighed as Bi₂O₃.

 $Bi_2O_3 \times .8966 = Bi$.

J. J. Mulligan.

B, at.wt. 10.82; {amorp. sp.gr. 2.45; m.p. 2200°; b.p. sublimes. cryst. sp.gr. 2.55; m.p. 2500°; b.p. 3500° C; oxide, B₁O₁

DETECTION

Flame Test. Boric acid is displaced from its salts by nearly all acids, including even carbonic acid. Upon ignition, however, it in turn drives out other acids which are volatile at lower temperatures. A powdered borate, previously calcined, is moistened with sulphuric acid and a portion placed on the loop of a platinum wire is heated to expel the sulphuric acid, then moistened with glycerine and placed in the colorless flame; a green color will be imparted to the flame. Copper salts should be removed with H₂S and barium as BaSO₄ if present, as these also color the flame green.

The flame test may be conveniently made by treating the powdered sample in a test-tube with sulphuric acid and alcohol (preferably methyl alcohol). A cork carrying a glass tube is inserted and the test-tube gently warmed. The escaping gas will burn with a green flame.

The test may be made by igniting the mixture of powder, alcohol, and sulphuric acid in an open porcelain dish. The green color will be seen in presence of a borate. The test is not as delicate as the one with the test-tube.

Borax Bead. Na₂B₄O₇·10H₂O fused in a platinum loop, swells to several times its original volume as the water of crystallization is being driven out, then contracts to a clear molten bead. If the bead is dipped into a weak solution of cobalt and plunged into the flame, until it again becomes molten, the bead upon cooling will be colored blue.

Turmeric Test. A few drops of acetic acid are added together with 2 or 3 drops of an alcoholic turmeric solution to an alcoholic extract of the sample, placed in a porcelain dish. The solution is diluted with water and then evaporated to dryness on the water bath. 1/1000 milligram of boric acid will produce a distinct color, 2/100 milligram will give a strong reddish-brown colored residue, which becomes bluish-black when treated with a drop of sodium hydroxide solution.

ESTIMATION

The determination of boron is required in the valuation of borax, Na₁B₄O₇·10H₂O; boracite, 4MgB₄O₇·2MgOMgCl₂; borocalcite, CaB₄O₇·6H₂O; hydroboracite; boronatrocalcite, etc., the element being reported generally as the oxide, B₂O₂. The determination is required for obtaining the true value of commercial boric acid, in the analysis of fluxes and certain pigments. It is determined as a food-preservative in milk, meat, canned goods, etc. The element is determined in certain alloys of nickel, cobalt, zinc, chromium, tungsten, molybdenum and in the analysis of steel.

¹ Silicates should be mixed with potassium fluoride and potassium acid sulphate, KHSO₄, then held in the flame.

Chapter contributed by Wilfred W. Scott.

Preparation and Solution of the Sample

It will be recalled that crystalline boron is scarcely attacked by acids or alkaline solutions; the amorphous form, however, is soluble in concentrated nitric and sulphurie acids. Both forms fused with potassium lydroxide are converted to potassium metaborate. Boric acid is more readily soluble in pure water than in bydrochloric, nitrie, sulphurie, or acetic acids, but still more soluble in tartaric acid (Herz, Chem. Zentr., 1903, 1, 312). It is soluble in alcohol and volatile oils. Borax is insoluble in alcohol. With acids it becomes transposed to boric acid and the sodium salt of the acid.

Boric Oxide in Silicates, Enamel, etc. About 0.5 gram of the finely ground material is fused with five times its weight of sodium carbonate, the melt extracted with water and the extracts, containing the sodium salt of boric acid, evaporated to small volume. The greater part of the excess sodium carbonate is neutralized with hydrochloric acid and finally made acid with acetic acid (litnus paper test=red). Boric oxide is now determined by the distillation process according to the procedure given later in the chapter.

Boronatrocalcite, Borocalcite, Boracite, Calcium Borate. Ten grams of the powdered material is placed in a flask with a reflux condenser and about 50 cc. of normal hydrochloric acid added and the mixture boiled for half an hour. The contents of the flask, together with the washings, including those of the reflux condenser (CO₂-free water being used), are filtered into a 500-cc. flask and made to volume with CO₂-free water. Fifty cc. of this solution is titrated with half-normal sodium hydroxide, using paramitrophenol indicator. When a yellow color appears the hydrochloric acid has been neutralized. A second 50-cc. portion is now taken for analysis and the free hydrochloric acid neutralized with sodium hydroxide, using the amount of caustic required in the trial analysis (this time without an indicator). Boric acid is now determined by titration according to the procedure on p. 86.

Borax, Boric Acid. Ten grams of the material are dissolved in about 300 cc. of water (free from CO₂) and made to 500 cc. in a graduated flask, with pure water. One hundred-cc. portions are taken for analysis and the solution titrated, in prescuce of mannitol or glycerol, according to directions given under the volumetric procedures.

Boric Acid in Mineral Water. Water containing more than 0.1 grain borie acid per liter, about 200 cc. are evaporated to small volume, the precipitated salts are litered off and washed. Boric acid passes into the filtrate and may be determined by the distillation method of Gooch given on p. 84.

With water containing traces of borie acid, 5 liters or more are evaporated to about one-tenth the original volume the precipitate filtered off and washed with hot water. The filtrete is evaporated down to a moist residue. If the residue is small, it is aciditied with acetic acid and the borie acid determined by distillation, as stated on p. 84. If considerable residue is present, hydrochlorie acid is added to acid reaction, and then the mixture digested with absolute alcohol in a corked flask for ten to lifteen hours, with occasional shaking. The solution is filtered, the residue washed with 95% alcohol, the filtrate diluted with water, 10 ec. of 10% sodium hydroxide solution added and the alcohol distilled off. A second alcoholic

extraction is generally recommended. The final alkaline solution is taken to dryness and gently ignited. The residue is extracted with water, made acid with acetic acid and B2O3 determined by distillation.

Carbonates. The material is treated with sufficient acid (M. O. indicator) to liberate all the CO2 and react with the combined alkali of boric and earbonic acid; it is boiled in a flask with reflux condenser to expel CO₂, ten to fifteen minutes, the solution exactly neutralized with sodium hydroxide, (M. O.), and the liberated borie acid titrated in presence of glycerol and phenolphthalein as usual.

Boric Acid in Milk, Butter, Meat and Other Foods

Milk. One hundred ec. of milk is treated with 1 to 2 grams of sodium hydroxide, and evaporated to dryness in a platinum dish. The residue is thoroughly charred 2 by gently heating; at this stage care must be exercised or loss of boric acid will result; 20 cc. of water are added, the sample heated and hydrochloric acid added drop by drop until all but the earbon has dissolved. The mixture is washed into a 100-cc. flask with as little water as possible, 0.5 gram calcium chloride added, then a few drops of phenolphthalein indicator, then a 10% sodium hydroxide solution until a slight permanent pink color is obtained and finally 25 cc. of lime water. (All P2Os is precipitated as calcium phosphate.) The liquid is made to 100 cc., mixed thoroughly, and then filtered through a dry filter. To 50 cc. of the filtrate, equivalent to 50 cc. of the milk taken, normal sulphuric acid is added until the pink color disappears, then methyl orange indicator is added, followed by more of the standard acid until the yellow color changes to a faint pink. Carbon dioxide is expelled and the liberated boric acid titrated in presence of glycerine, according to the procedure given for evaluation of borax and boric acid, under "Volumetric Determination of Boron."

Butter.3 Twenty-five grams of butter are weighed out in a beaker and 25 ce. of a sugar sulphuric acid mixture added. (Mix=6 grams sugar of milk, 4 cc. normal sulphuric acid per 100 cc. of solution.) The beaker is placed in the oven (100° C.) until the fat is melted and the mixture is thoroughly stirred. When the aqueous solution has settled, 20 cc. are pipetted out, phenolphthalein added, the solution brought to boiling and balf-normal sodium hydroxide added until a faint pink color is obtained. Ten ec. of neutral glycerine are added and the titration carried on until a permanent pink color appears. The difference between the two titrations multiplied by the factor for equivalent boric acid gives the weight of boric acid in the portion taken.

The determination is not affected by the phosphoric or butyric acid or by the sugar of milk in the butter.

Meat. Ten grams of the chopped meat are mixed in a mortar with 40 to 80 grains of anhydrous sodium sulphate, and dried in the water oven. The mass is powdered, then placed in a flask and 100 ce. of methyl alcohol added and allowed to stand for about twelve hours. The alcohol is distilled into a flask and saved. Fifty cc. more of alcohol are added to the residue and this again distilled into the first distillate. The distillates are made up to 150 cc., a

¹ R. T. Thomson, Glasgow City Anal. Soc. Repts., 1895, p. 3.

⁴ C. Fresenius and G. Popp, Chem. Centr., 1897, 2, 69.

²The milk residuc thoroughly charred will give a colorless solution upon extraction. ³H. Droop Richmond and J. B. P. Harrison, Analyst, 27, 197.

50-cc. portion diluted with 50 cc. of water and 50 cc. of neutral glycerine added with phenolphthalein indicator, and the boric acid titrated with twentieth-normal sodium hydroxide.

One ec. N/20 NaOH = 0.0031 gram borie aeid, HaBOa.

Boric acid in canned goods, sauces, cereals, etc., may be determined by evaporation of the substance with sodium hydroxide and incineration as in case of milk. The sodium hydroxide is neutralized and boric acid titrated as usual.

GRAVIMETRIC DETERMINATION OF BORON

The solubility of boron compounds prevents complete precipitation by any of the known reagents, hence most of the gravinetric methods are indirect.

Distillation as Methyl Borate and Fixation by Lime 1

This excellent method, originally worked out by F. A. Gooch, and later modified by Gooch and Jones, depends upon the fact that the borates of alkaline earths and alkalies give up their boron in the form of the volatile methyl borate (b.p., 65° C.), when they are distilled with absolute methyl alcohol (acctone-free). The methyl borate passed over lime in presence of water is completely




Fig. 8.-Distillation of Methyl Borate.

saponified, the liberated borie acid combining with the lime to form calcium borate, which may be dried, ignited, and weighed. The increase of the weight of the lime represents the B₂O₃ in the sample.

$$2B(OCH_3)_3+CaO+6H_2O$$

= $6CH_3OH+Ca(BO_2)_2+3H_2O$.

Procedure. About 1 gram of pure calcium oxide is ignited to constant weight over a blast lamp and then transferred to the dry, Erlenmeyer receiving flask (Fig. 8). The crucible in which the lime was heated and weighed is set aside in a desiceator for later use.

0.2 gram or less of the alkali borates, obtained in solution by a procedure given under "Preparation of the Sample," is treated with a few drops of litmus (or laemoid), solution and the free alkali neutralized with dilute HCl solution added drop by drop. A drop of dilute sodium hydroxide solution is added and

then a few drops of acetic acid. The slightly acid solution is transferred to the

¹ Proc. Am. Acad. of Arts and Sciences, 22, 167-176 (1886). Anal. Chem., Treadwell-Hall, Vol. 2.

² See note on p. 75.

pipette-shaped retort R, Fig. 8, by means of the attached funnel F, washing out the beaker and funnel with three 2- to 3-cc. portions of water. The stopeoek of the funnel is closed, the apparatus is connected up as shown in the illustration, the paraffine bath, heated to not over 140° C., placed in position and the liquid in the retort distilled into the receiver containing the known amount of line. When all the liquid has distilled over, the paraffine bath is lowered, the retort allowed to eool for a few minutes, 10 cc. of methyl alcohol (acetonefree) added to the residue in R and the contents again distilled by replacing the paraffine bath. The process is repeated three times with methyl alcohol. The contents of the retort (which are now alkaline), are made distinctly acid by addition of acetic acid, and three more distillations made with 100-cc. portions of methyl alcohol, as before. The paraffine bath is now removed, the receiving flask is stoppered, the contents thoroughly mixed by shaking, and set aside for an hour or more for complete saponification of the methyl borate. The contents are now poured into a large platinum dish and evaporated on the water bath at a temperature below the boiling-point of the alcohol. (Loss of borie acid will occur if the alcohol boils.) The adhering lime in the receiving flask is dissolved by wetting its entire surface with a few drops of dilute nitric acid (the flask being inclined and revolved to flow the acid over its sides). The contents are transferred to the dish with a little water and the evaporation repeated. No loss of boric acid will take place at this stage, the alcohol having been removed during the first evaporation. The residue is gently heated to destroy any ealcium acetate that may have formed, the cooled borate and lime are taken up with a little water and transferred to the crucible in which the lime was heated and weighed. The material clinging to the dish is dissolved with a little nitric acid (or acetic acid), and washed into the crueible. The contents of the crucible are evaporated to dryness on the water bath, then heated very gently over a flame (the crucible being covered) and finally more strongly. The heating is continued until a constant weight is obtained. The increase of weight of the lime represents the amount of B_iO_i in the sample.

Notes. Gooch and Jones worked out a procedure which utilizes sodium tungstate as a retainer of the methyl borate, in place of the lime. This substance is definite in weight, not hydroscopic, soluble in water, and recoverable in its original weight after evaporation and ignition. "Methods in Chem. Anal.," p. 204, 1st Ed. By F. A. Gooch, John Wiley & Sons, Publishers.

By F. A. Gooch, John Wiley & Sons, Publishers.
The receiving flask has a cork stopper with a hole to accommodate the tube of

the condenser and a slit to permit the escape of air from the flask. Gooch recommends cooling of the receiving flask.

VOLUMETRIC DETERMINATION OF BORON

Titration of Boric Acid in Presence of Mannitol or Glycerol Evaluation of Borax

The method takes advantage of the fact that boric acid reacts neutral to methyl orange (or paranitrophenol), but is acid to phenolphthalein, and may be quantitatively titrated in the presence of mannitol or of glycerol, which prevent the hydrolization of sodium borate. If insufficient mannitol or glycerol are present the color change takes place too soon, the color fading upon adding more of these substances. The end-point is reached when the further addition of these reagents produces no fading of the color. In the procedure, the alkali is neutralized in presence of methyl orange (or paranitrophenol), and the liberated boric acid is now titrated.

Reactions. Na₂B₄t)₇+2HCl+5H₂O = 2NaCl+4H₂BO₂ H₃BO₃+NaOH = NaBO₂+2H₂O.

Procedure. One hundred cc. of the solution containing the borax, prepared according to directions under "Preparation and Solution of the Sample," equivalent to 2 grams of the substance, is taken for analysis.

A. Titration of Combined or Free Alkali. Methyl orange indicator is added and the solution is titrated with normal or half-normal sulphuric acid until the yellow color is replaced by an orange red. (With paranitrophenol the solution becomes colorless.) From this titration the combined alkali, together with any free alkali, is calculated. If free alkali is known to be absent (see note), the amount of borax may be calculated.

One cc. N. $H_2SO_4 = 0.031$ gram Na_2O_7 , or =0.1911 gram $Na_2B_4O_7 \cdot 10H_2O_7$ or =0.101 gram $Na_2B_4O_7$.

B. Titration of Boric Acid. The liberated boric acid may now be titrated with eaustic. This may be accomplished either on the above portion or on a fresh 100-cc. portion (free from methyl orange indicator), to which the amount of acid, required to neutralize the alkali, has been added. Fifty ec. of neutral glycerol or 1 gram of mannitol are added, followed by phenolphthalein indicator. Normal or half-normal sodium hydroxide is added from a burette until a change of color takes place. If methyl orange is present, the color, first becoming yellow, changes to an orange red. In absence of methyl orange the characteristic lavender or purplish pink of alkali phenolphthalein is obtained. More glycerol or mannitol is now added and if the color fades the titration is continued until the addition of these reagents no longer produces this fading of the end-point, From this titration boric acid is calculated and the equivalent borax determined.

One ec. N. NaOII =0.062 gram H_2BO_3 , equivalent to 0.0505 $Na_2B_4O_7$, or 0.0955 $Na_2B_4O_7$ ·10 H_2O .

Factors. Na₂O to Na₂B₄O₇ = 3.2581, reciprocal = 0.3069. Na₂O to Na₂B₄O₇ · 10H₂O = 6.1638, recip. = 0.1622. Na₂O to Na₂CO₂ · 10H₂O = 4.6155, recip. = 0.2167. Na₂O to Na₂CO₃ · 10H₂O = 4.6155, recip. = 0.2167.

Notes. In borax (free from excess B₂O₂ or Na₂O), the acid titration is half the subsequent alkali titration (factor, acid to borax =0.1911, alkali to borax =0.0955).

If the acid titration exceeds this proportion, alkali other than that combined with borie acid is indicated; if the alkali titration is greater than twice the acid titration, free borie acid is indicated.

The glycerol should be made neutral with N/10 NaOH before use, in case it con-

tains free fatty acids.

Mannitol is a solid and has some advantages over glycerol;' it gives a sharper end-point, is less apt to contain free acids and does not appreciably alter the bulk of the solution to which it is added. (L. C. Jones, C. N., 80, 65, 1899).

N.B. Paper on use of mannitol and glycerol in determining boric acid, by R.

T. Thonson, J. S. C. 1., 12, 432.

Example. By actual test 2 grams $Na_2B_4O_7 \cdot 10H_2O$ required 10.66 ce. N. $H_2SO_4 = 10.66 \times 0.1911 = 2.037$ gram $Na_2B_4O_7 \cdot 10H_2O$. The liberated H_2BO_2 required 21.39 cc. of N. $NaO(11 = 21.39 \times 0.0955 = 2.043$ gram $Na_2B_4O_7 \cdot 10H_2O$. The borax had lost a small amount of water of erystallization, hence the high results when calculated to N82B4O7 · 10H2O.

EVALUATION OF BORIC ACID

One hundred cc. of the solution, prepared as directed under "Preparation of the Sample," equivalent to 2 grams of the original material, is treated with 50 cc. of glycerol or 1 gram of mannitol, and the acid titrated with standard caustic, in presence of phenolphthalein indicator according to the procedure given in B, under "Evaluation of Borax."

One ce. normal acid contains 0.062 gram H₃BO₃, hence the ce. of caustie

required multiplied by 0.062 = grams boric acid.

Examples. Two grams HaBOs by actual test required 32.1 ec. N. NaOII $=32.1\times.062 = 1.99$ grams H_3BO_3 .

Detection of Minute Amounts of Boron.

Robin's Test for Boron. To a few drops of the aqueous solution under examination (slightly acidified with HCl) are added two drops of a tineture of miniosa flowers, and the mixture evaporated to dryness on the water bath. The residue is treated with dilute ammonla water, whereupon in presence of boric acid, a rose pink to blood red color develops, according to the amount present. L. Robin claims that as little as 0.0001 milligram may be detected in presence of nitrates, chlorides, iodides, or calcium sulphate. Organic acids and sodium phosphate interfere. The reagent is prepared by extracting the mimosa flowers with ethyl alcohol. The extract is protected from the light.

Distillation Method as Modified by Chapin

Reagents'

1. Paranithrophenol.—One gram dissolved in 75 cc. of neutral ethyl alcohol and made up to 100 ec. with water.

2. Phenolphthalcin.—One gram dissolved in 100 cc. of ethyl alcohol and made up to 200 cc. with water.

3. Hydrochloric Acid, 0.1 Normal.—The water should be boiled to remove carbonic aeid.

4. Hydrochloric Acid, 1.1 Strength.-A dropping bulb should be filled with this acid

when it is needed in accurate small amounts.

5. Sodium Hydroxide, 0.5 and 0.1 Normal.—These should be standardized as follows: Fuse pure borie acid in a platinum dish. While still warm break the melt up and place the fragments quickly in a weighing tube. Dissolve 1.75 grams in 250 ee. of hot,

¹ Bulletin 700, "The Analysis of Silicate and Carbonate Rocks," by W. F. Hillebrand. Department of the Interior, U. S. Geological Surveys. Am. Jour. Sci., 4th Ser., Vol. 14, 1903, p. 195.

recently boiled water, cool, and dilute the solution to 500 ec. This solution is 01. normal—that is, in presence of mannite or glycerol 1 cm. is neutralized to the phenol-phthalein end point by 1 ce. of 0.1 normal sodium hydroxide.

In standardizing the sodium hydroxide against this solution both indicators should be used, so that the end may be the same as that seen in actual titration. Follow exactly the directions given under b, below, for the final titraction, only assuming that the boric acid solution is exactly neutral to paramitrophenol-that is, free from mineral acid. When sodium hydroxide is standardized in this way the small amount of carbonate present does no harm.

6. Mannite.—This is preferable to glycerol, for it requires no special preparation, does not materially increase the bulk of the solution to be titrated, and gives an equally

sharp end point.

7. Methyl Alcohol.—This should be distilled over lime after it has been heated for some hours in contact with the lime under a reflux condenser. The more nearly anhydrous the alcohol is the better.

8. Calcium Chloride.—This should be granular, anhydrous, and free from boron.

Apparatus

The main set up of the apparatus required is shown in Fig. 8a.




Fig. Sa.—Distilling Apparatus for Boron

A. Flask of 500 cc. capacity for methyl alcohol, having a U tube containing a little mercury as a safety trap, and a capillary "boiling tube" 3 mm. in bore, the bore closed at 1 cm. from the lower end.

B. Flask of 250 cc. capacity, supported in a casserole of water but not touching the bottom. The outlet tube of B should be not less than 12 cm. in vertical height and of rather wide bore. The end inside the flask should be jagged to allow condensed liquid to drop back instead of jumping up the tube.

C. Glass condenser, 40 cc. long, of tubing 3 cm. wide.
D. Receiving flask of 250 cc. capacity. Two or three of these flasks should be at hand, with necks of same size, so that the receiver can be changed without interrupting the distillation. The small U tube attached contains a little water to prevent the escape of any uncondensed methyl borate.

E. (Not shown.) A second glass condenser like C, connected on the one side to a flask exactly like B, which, however, has a stopper with only one hole and rests completely within a large bath. The flask carries also a "boiling tube." On the other side is n receiver like D, but without the U trap. This apparatus is used

for distilling off the alcohol after the preliminary titration,

F. (Not shown.) Filter pump. At the end of the side tube is an elbow tube connected to a rubber stopper with two holes and of a size to fit the flask mentioned in connection with E. The second hole of the stopper is closed by a glass plug, which can be withdrawn to break the vacuum. Midway between pump and stopper is a small safety bottle, to prevent the tap water from sucking back the flash

Procedure

Chapin used not more than half a gram of mineral powder for even very small amounts of boron, and not less unless the percentage exceeded 10. When the percentage is high it is best to so limit the weight of the sample that the of B_2O_3 shall not exceed 0.1 gram. If a flux is used it should be weighed to within a milligram of two; then the amount of acid required to take up the melt can be measured out at once and there is no danger of using too great an excess.

If the mineral is soluble in hydrochloric acid, transfer 1 gram of it to the flask B, without letting any adhere to the neck, and treat with not more than 5 cc. of 1:1 hydrochloric acid. Heat gently on a water bath until solution is complete.

If the mineral is not soluble, add to it exactly six times its weight of sodium carbonate or of an equimolecular mixture of sodium and potassium carbonates, mix, and fuse in the usual manner. Without removing from the crucible, decompose the melt with 1: I hydrochloric acid in calculated amount added by degrees. While this is being done the crucible should rest in a casserole, and the lid should be kept in place as much as possible. Toward the end it may be necessary to heat a little, but care should be taken not to boil, for boric acid would be lost with the steam. Pour the solution into the flask B and rinse the crucible with a very little water.

Then add pure anhydrous calcium chloride, using about 1 gram for each cubic centimeter of solution and running it through a paper funnel to keep the neck of the flask clean. Twirl the flask a little to allow the chloride to take up the water, connect it with the rest of the apparatus, raise the casserole beneath it until the flask rests in the water but does not touch the bottom, and then begin the distillation of the alcohol from the flask A, taking care that the open end of the capillary "boiling tube" is free from alcohol and that the U tube attached to the receiver is trapped with water.

The decomposition flask, B, is not heated until about 25 cc. of alcohol has condensed in it. After that the water bath is heated by a small flame and the flask thus kept hot enough to prevent further condensation of alcohol. The distillation should not be so rapid as to permit escape of methyl borate from the system.

When a distillate of about 100 cc. has collected the receiver is exchanged for a fresh one and the collection of a second distillate is proceeded with. The contents of the trap tube are added to the first receiver, and a preliminary titration is made as follows: Add a few drops of paranitrophenol solution and run in the standard sodium hydroxide until the indicator shows that the free mineral acid is neutralized. Next, add 1 cc. of the phenolphthalein solution and continue the titration until the color of that indicator begins to appear. The end point will not be sharp, but the amount of alkali used between the two end points indicates approximately the amount of boric acid in the distillate. If the mineral is likely to contain more than 3 or 4% of B_2O_2 use the 0.5 normal solution, the object being to keep the distillate as free from the water as possible and thus facilitate the dehydration later on.

After completing the titration add to the distillate twice as much alkali as was used between the two end points, transfer the distillate to the second

distilling apparatus, and boil off the alcohol. The addition of the indicated amount of alkali prevents loss of boron by converting unstable NaBO₂ to stable Na₂BO₂.

In the meantime the second distillate of 100 cc. will have collected. Unless the alcohol contained water or insufficient calcium chloride was used, this second distillate will contain the remainder of the boron. Therefore, before removing the receiver stop the distillation. Treat the second distillate exactly like the first and then add it to the first.

If the amount of alkali used for titrating the second distillate is less than 0.1 cc. of the 0.1 normal solution the distillation may be regarded as complete.

When the liquid from the alcohol is being distilled no longer boils in the steam bath, remove it to a easserole, rinsing the flask once or twice with water, and heat over a direct flame, rotating the casserole while doing so, until the little remaining alcohol has been boiled out. The residue should now be small—about 25 cc. if 0.1 normal alkali was used and much less if 0.5. If the volume is less than 25 cc. make up to that extent.

Return the solution to the flask and add drop by drop with constant twirling 1:1 hydrochloric acid from a dropping bulb, until the color of both indicators is discharged, taking care not to add a drop too much. Now put in the "boiling tube," heat the flask in the steam bath for a minute or two, then attach to the filter pump and boil under reduced pressure until the liquid is nearly cold and only an occasional bubble appears.

All carbon dioxide being thus removed, break the vacuum, cool if necessary under the tap, and proceed to the final titration.

First neutralize the excess of hydrochloric acid by running in carefully 0.5 normal sodium hydroxide until the yellow of paranitrophenol just appears. Bring back to acid reaction with 0.1 normal hydrochloric acid and then to the appearance of a faint yellow with 0.1 normal alkali. The solution is now exactly neutral as the indicators itself shows this color in a neutral solution. Make sure that the end point is reached exactly. One drop of 0.1 normal acid should discharge the color entirely.

Now add I gram of mannite, read the burette, and continue titrating to the end point of phenolphthalein. Add another gram of mannite, and if this causes a disappearance of the end color add more alkali until it reappears.

The number of cubic continueters of alkali used multiplied by its equivalent in terms of B₂O₃ gives the amount of the latter contained in the solution. If the solution of alkali is exactly 0.1 normal this equivalent is 0.0035.

The changes of color that take place during the titration need mention. When the mannite (or glycerol) is added to the solution the yellow color due to the paranitrophenol disappears at once. This is due to the fact that the combination of these reagents with the boric acid forms an acid of sufficient strength to affect the indicators, although boric acid alone does not. As the titration proceeds the color reappears and grows stronger, becoming very intense just before the phenolphthalein end point appears. The latter will be noticed as a faint brownish tinge, and then another drop of the 0.1 normal alkali changes it to an intense brownish red, which is the real end point.

Notes

E. T. Allen and E. G. Ziez¹ tested the Chapin method very fully in its application to the determination of boron in glasses and regard it as far superior to other methods, even though it is subject to a slight but very uniform correction of 1 milligram or less, to be determined by a blank run. The correction seems to be due always in part to a boron content of the reagents used and in part to a titration error. The fact that such correction is unavoidable makes the method of uncertain value for determining the very small amounts of boron that rocks may be presumed to earry, but the constancy of results is so great that a consistent excess found over what the blank affords is strong evidence that boron is actually present.

Allen and Ziez found the method to be affected appreciably by relatively large amounts of arsenious acid but not by arsenic acid. The effect of the former can be eliminated by converting it to arsenic acid by oxidizing with hydrogen peroxide after making the solution distinctly alkaline with sodium hydroxide.

Allen and Ziez also found that relatively large amounts of fluorides effect the accuracy of the method but do not seriously impair its usefulness for ordinary work.

¹ "Analysis of Silicate and Carbonate Rocks," by W. T. Hillehrand, Bull. 700, U. S. Geol. Survey, 1919.

BROMINE

Br, at.wt. 79.92; sp.gr. 3.1883°; m.p. -7.3°; b.p. 58.7° C.; acids, HBr, HBrO, HBrO;

DETECTION

Silver Nitrate solution precipitates silver bromide, AgBr, light yellow, from solutions containing the bromine anion. The precipitate is insoluble in dilute nitrie acid, but dissolves with difficulty in ammonium hydroxide and is practically insoluble in ammonium carbonate solution (distinction from AgCl).

Carbon Disulphide or Carbon Tetrachloride shaken with free bromine solution, or with a bromide to which a little chlorine water has been added, (a large excess of chlorine must be avoided, as this forms BrCl compound), will absorb the bromine and become a reddish-yellow color, or if much bromine is present, a brown to brownish-black. In the latter case a smaller sample should be taken to distinguish it from iodine.

Bromates are first reduced by a suitable reducing agent such as cold oxalic acid, sodium nitrite, hydrochloric acid, etc., and the liberated bromine tested as directed above. Siteer nitrate added to bromates in solution precipitates AgBrO₁, which is decomposed by hydrochloric acid to bromine gas.

Barium Chloride precipitates Ba(BrO₂)₂, which is reduced readily to bromine as directed above.

Magenta Test for Bromine. The test reagent is made by adding 10 ee. of 0.1% solution of magenta to 100 ec. of 5% solution of sulphurous acid and allowing to stand until colorless. This is the stock solution. Twenty-five ec. of this reagent is mixed with 25 cc. of glacial acetic acid and 1 ee. of sulphuric acid. Five ec. of this is used in the test.

Test. Five ce, of the magenta reagent is mixed with 1 ee, of the solution tested. Chlorine produces a yellow color. Bromine gives a reddish-violet eoloration. The colored compound in each case may be taken up with ehloroform or earbon tetrachloride and a colorimetric comparison made with a standard.

In halogen mixes, iodine is first eliminated by heating with an iron per salt. Bromine is now liberated by adding sulphuric acid and potassium chromate. A glass rod with a pendant drop of sodium hydroxide is held in the vapor to absorb bromine, and the drop then tested with the magenta reagent. After iodine and bromine are eliminated, chlorine may be tested by heating the substance with potassium permanganate, which liberates this halogen.

¹G. Deniges and L. Chelle. Ann. Chim. anal., 1913, 18, 11-15; The Analyst, 1913, 119.

Chapter contributed by Wilfred W. Scott.

ESTIMATION

Bromine never occurs free in nature. It is found chiefly combined with the alkalics and the alkaline earths, hence occurs in many saline springs and is a by-product of the salt industry. It is found in silician zine ores, Chili saltpeter, in sea water (probably as MgBr₂), in marine plants. Traces occur in coal, hence in gas liquors.

The substance is used in metallurgy, the arts, and medicine. It is a valuable oxidizing agent for the laboratory.

Preparation and Solution of the Sample

The following facts regarding solubility should be remembered: The element bromine is very soluble in alcohol, ether, chloroform, carbon disulphide, carbon tetrachloride, concentrated hydrochloric acid and in potassium bromide solution. One hundred ce. of water at 0° C. is saturated with 4.17 grams of bromine, and at 50° C. with 3.49 grams. The presence of a number of salts increases its solubility in water, c.g., BaCl₂, SrCl₂, etc.

Note. The element is a dark, brownish-red, volatile liquid, giving off a dark reddish vapor with suffocating odor, irritating the mucous membrane (antidote dil. NII4OII, ether), very corrosive. Acts violently on hydrogen, sulphur, phosphorus, arsenic, antimony, tin, the heavy metals, and on potassium, but has no action on sodium, even at 200° C. Bleaches indigo, litmus, and most organic coloring matter. It is a strong oxidizing agent. Bromine displaces iodine from its salts, but is displaced by chlorine from its combinations.

Bromides are soluble in water, with the exception of silver, mercury, lead, and cuprous bromides.

Bromates are soluble in water with the exception of barium and silver bromates and some basic bromates.

Decomposition of Organic Matter for Determination of Bromine. The substance is decomposed with nitrie acid in presence of silver nitrate in a bomb combustion tube by the Carius method described in the chapter on Chlorine, under "Preparation and Solution of the Sample" The residue, containing the halides, is dissolved in warm ammonia water, and filtered, as stated. The filtrate and washings are acidified with nitric acid, heated to boiling and the silver bromide settled in the dark, then filtered through a weighted Gooch crucible, the washed precipitate dried at 130° C. and weighted as AgBr.

In presence of two or three halogens the lime method is recommended, as given in the ehapter on ehlorine, page 146.

Salts of Bromine. The ready solubility of bromides and bromates has been mentioned. A water extract is generally sufficient. Insoluble salts are decomposed by acidifying with dilute sulphuric acid and adding metallic zinc. The filtrate contains the halogens.

SEPARATIONS

Separation of Bromine from the Heavy Metals. Bromides of the heavy metals are transposed by boiling with sodium carbonate, the metals being precipitated as carbonates and sodium bromide remaining in solution.

Separation of Bromine from Silver (AgBr) and from Cyanides (AgCN). The silver salts are heated to fusion. The mass is now treated with an excess of zine and sulphuric acid, the metallic silver and the paracyanogen filtered off and the bromine determined in the filtrate.

Separation of Bromine from Chlorine or from Iodine. Details of the procedure for determining the halogens in presence of one another is given in the chapter on Chlorine, page 154. Free bromine is liberated when the solu-

tion of its salt is treated with chlorine.

Separation of Bromine from Iodine.¹ The neutral solution containing the bromide and iodide is diluted to about 700 ee. and 2 to 3 ee. of dilute sulphuric acid, 1:1, added, together with about 10 ce. of 10% sodium nitrite, NaNO2, solution. (Nitrous acid gas may be passed through the solution in place of adding sodium nitrite, if desired.)² The solution containing the halides is boiled until colorless and about twenty minutes longer, keeping the volume of solution above 600 ec. 0.5 gram KI may be decomposed and the iodine expelled from the bromide in half an hour. The bromine is precipitated from the residue remaining in the flask by addition of an excess of silver nitrate and determined as silver bromide.

The procedure for determining iodine is given in the chapter on this subject.

GRAVIMETRIC METHODS

Precipitation as Silver Bromide

The general directions for determination of hydrochloric acid and chlorides apply for determining hydrobromic acid and bromides.

I. Hydrobromic Acid and Bromides of the Alkalies and Alkaline Earths.

Broadure. The bromide in cold solution is made slightly acid with uitrice.

Procedure. The bromide in cold solution is made slightly acid with nitric acid and then silver nitrate added slowly with constant stirring until a slight excess is present. The mixture is now heated to boiling and the precipitate settled in the dark, then filtered through a weighed Gooch crucible, and washed with water containing a little nitric acid and finally with pure water to remove the nitric acid. After ignition the silver bromide is cooled and weighed as AgBr.

 $AgBr \times 0.4256 = Br$, or $\times 0.6337 = KBr$.

II. Heavy Metals Present.

If heavy metals are present it is not always possible to precipitate silver bromide directly. The heavy metals may be removed by precipitation with ammonia, sodium hydroxide or carbonate and the bromide then determined in the filtrate as usual.

¹ F. A. Gooch and J. R. Eusign, Am. Jour. Sci., (3), xl, 145.

² Nitrous acid gas is generated by dropping dilute H₂SO₄, by means of a separatory funnel onto sodium nitrite in a flask.

VOLUMETRIC METHODS

Free hydrobromic acid may be titrated with standard alkali exactly as is described for the determination of hydrochloric acid in the chapter on Acids. One ce. normal caustic solution is equivalent to 0.08093 gram HBr.

Determination of Free Bromine. Potassium Iodide Method

The method depends upon the reaction KI+Br=KBr+I.

Procedure. A measured amount of the sample is added to an excess of potassium iodide, in a glass-stoppered bottle, holding the point of the delivering burette just above the potassium iodide solution. The stoppered bottle is then well shaken, and the liberated iodine titrated with standard thiosulphate solution.

One cc. of N/10 thiosulphate, Na₂S₂O₃ = 0.007992 gram Br.

Determination of Bromine in Soluble Bromides. Liberation of Bromine by Addition of Free Chlorine

When eldorine is added to a colorless solution of a soluble bromide, bromine is liherated, coloring the solution yellow. At boiling temperature the bromine is volatilized, the liquid becoming again colorless. When the bromide is completely decomposed and bromine expelled, further addition of chlorine produces no color reaction. KBr+Cl=KCl+Br.

Procedure. The solution containing the bromide is heated to boiling and standard chlorine water added from a burette (protected from the light by being covered with black paper), the tip of the burette being held just above the surface of the hot bromide solution to prevent loss of chlorine. The reagent is added in small portions until finally no yellow coloration is produced. From the value per cc. of the chlorine reagent the bromine content is readily calculated.

Standard Chlorine Water. The reagent is made by diluting 100 ce. of water saturated with chlorine to 500 cc. This solution is standardized against a known amount of pure potassium bromide (dried at 170° C.), the same amount of bromide being taken as is supposed to be present in the solution examined. The value per cc. of the reagent is thus established.

Silver-Thiocyanate-Ferric Alum Method. (Volhard)

The procedure is the same as that used for the determination of chlorine. The bromide solution is treated with an excess of tenth-normal silver nitrate solution, and the excess of this reagent determined by titration with ammonium thioeyanate, using ferric alum indicator. One cc. of the thiocyanate should be equivalent to 1 cc. of silver nitrate solution. The formation of the red ferric thiocyanate indicates the completed reaction. (Consult the procedure in the chapter on Chlorine, page 149.)

One cc. of $N/10 \text{ AgNO}_{2} = 0.007992 \text{ gram Br.}$

Determination of Traces of Bromine

By means of the magenta reagent, described under "Detection." small amounts of bromine may be determined colorimetrically.

To 5 ec. of the solution is added 0.2 ce. of strong hydroehlorie acid, 1 ec. of concentrated sulphuric acid, 1 cc. of the stock magenta reagent and 0.2 cc. of a 10% solution of potassium chromate, shaking the mixture with addition of each reagent, and without cooling, 1 cc. of chloroform is added. Comparison is made with a standard sample containing a known amount of bromide.1

Note. A solution containing 0.001 gram bromine per liter has a violet to reddishviolet color.

Determination of Bromates by Reduction with Arsenous Acid and Titration of the Excess 2

Bromie acid may be reduced by arsenous acid in accordance with the reaction 3H₄AsO₄+HBrO₄=3H₄AsO₄+HBr. In the process a considerable excess of arsenous acid is added, the excess titrated with iodine and the bromate calculated.

Procedure. The sample of bromate, dissolved in water, is treated with a eonsiderable excess of N/10 arsenous oxide (dissolved in alkali hydrogen carbonate) reagent, the solution then acidified with 3 cc. to 7 cc. of dilute sulphuric acid (1:1) and diluted to a volume not exceeding 200 cc. After boiling for ten minutes, the free acid is neutralized with alkali hydrogen earbonate (NaIICO₃ or KHCO₃) and the excess of arsenite titrated with N/10 iodine.

Let x ce, equal the difference between the two titrations with N/10 iodine (i.e. of total arsenite minus excess arsenite) and w equal the weight of bromate desired, then

$$w = \left(\frac{x \text{ cc.} \times \text{niol. wt. } \text{RBrO}_3}{6 \times 10 \times 1000}\right) \text{milligrams.}$$

ANALYSIS OF CRUDE POTASSIUM BROMIDE AND COMMERCIAL BROMINE

Determination of Chlorine, Combined or Free

This is the principal impurity present and its estimation is concerned here. Andrews' modification of Bugarszk's method is as follows:

¹G. Denigés and L. Chelle, Ann. Chem. anal., 1913, 18-15; Analyst, 1913, p. 119. By means of the magenta reagent it is possible to detect bromine in the ash of plants, beet root, spinach, etc. The organic substance may be decomposed by heating in a combustion tube. Filter paper moistened with the reagent and held in the fumes of the organic substances gives the characteristic test if bromine is present.

Method of F. A. Gooch and J. C. Blake, Am. Jour. Sci., 14, Oct., 1902. Procedure communicated to the Editor by Prof. Gooch.

Jour. Am. Chem. Soc., 1907, 29, 275-283; Zeits. anorg. Chem., 1895, 10, 387.

. Procedure.	The	following	amount	of	sample	and	rcagents	should	he
taken.									

Approx. per cent Impurity if KCl Present is	Amount Substance to	Iodate Solution 1/5 N.	2N. HNOs Required,
	be Taken, Gram.	Required: cc.	cc.
Over 5	0.6	36	20
1.5 to 5	1.8	96	26
0.2 to 1.5	3.6	186	35

The mixture is gently heated to boiling in a long-necked Kjeldahl flask, inclined at an angle of 30°, potassium iodate solution added, then nitric acid and sufficient water to make the volume about 250 cc. The boiling is continued until bromine is expelled (test steam with 2% KI solution rendered faintly acid with hydrochloric acid). The mixture is boiled down to not below 90 cc. Now 1 to 1.5 cc. of 25% phosphorus acid are added and the mixture boiled for five minutes after all the iodine has been expelled. The colorless liquid is cooled, mixed with a slight excess of 1/20 or 1/50 normal silver nitrate solution (according to the proportion of chloride), the excess of silver nitrate then determined by titration with standard thiocyanate with ferric nitrate as indicator. (See procedure for silver-thiocyanate-ferric alum method of Volhard for determination of chlorine, page 149.)

Determination of Chlorine in Crude Bromine

Three grams of bromine (or more if less than 0.5% chlorine is present) in 50 ce. of 4% potassium iodide solution in a glass-stoppered flask (cooled in ice during hot weather) are shaken and then transferred to a Kjeldahl flask. Sixty ec. of 1/5 N. KIO₄ solution and 24 cc. 2N. HNO₄ introduced, the solution diluted to 250 cc. and chlorine determined as directed above.

Ail commercial bromine contains chlorine. The U.S. Bureau of Standards determines the specific gravity of the two.

Determination of Bromine in Mineral Waters in Presence of lodine. Separation from Iodine

The method of Baughman and Skinner (U. S. Bureau of Chemistry) is as follows:

The neutral or slightly acid sample, which should contain not more than 0.1 g. bromine, or 10 g. total salts, is introduced into the distillation flask and adjusted to a volume of approximately 75 cc. One and a half to 2 grams of ferric sulphate are added, the liberated iodine distilled with steam into 100 cc. of potassium iodide solution (10 g. KI per 100 cc.). The potassium iodide solution may be titrated with sodium thiosulphate solution, to determine the iodine. The bromine is determined in the liquid remaining in the distillation flask.


Determination of Bromide in Mineral Waters and Brines¹

Bromine occurs combined as bromide in natural and artificial brines, associated frequently with small amounts of iodide. Bromine may be obtained in the mother liquor or "bittern," a by-product in the manufacture of common salt. The following procedure for evaluation of these brines for their bromine content was developed by W. F. Baughman and W. W. Skinner, U. S. Bureau of Chemistry.

1 J. Ind. Eng. Chem., 11, 954-959 (Oct., 1919).

Apparatus. Three tall form, 250 cc. glass stoppered Dreschsel gas washing bottles or cylinders are joined together in series, the first two are joined by welding together the outlet tube of the first and the intake tube of the second, and the second and third by rubber tubing, bringing the ends of the glass tubing in contact with each other. The drawing Fig. 8b shows the details of the apparatus.

Procedure. "Evaporate the sample of water or brine, which should not be acid (if necessary add a small amount of sodium carbonate), to dryness or nearly so. Charge the reaction cylinder by introducing first glass beads to a



depth of about 1 in., then as much of the sample as can be scraped in, and finally enough glass beads to fill the cylinder half full. Make a solution of sodium sulphite and sodium carbonate of such a concentration that 25 cc. will contain 1 g. of sulphite and 0.2 g. of carbonate. Add 20 cc. of this solution to the first absorption cylinder, 5 cc. to the second, and dilute each to approximately 200 ec. Connect the three cylinders and draw througha slow current of air. Add 15 g. of chromic anhydride dissolved in 10 to 12 cc. of water to the reaction cylinder, followed by washings from the evaporat-

ing dish which contained the sample, sufficient to bring the total volume added to about 25 ec. Aspirate until the contents of the reaction cylinder are in solution and thoroughly mixed, then discontinue, close the julet tube with a small piece of rubber tubing and a clamp, and reduce the pressure in the apparatus slightly by sucking out some air in order to guard against any possible escape of bromine at the ground glass stopper. Allow to stand overnight, then aspirate with a rather strong current of air (about \{\frac{1}{2}\) to \{\frac{3}{2}\} l. per min.) for three hours, adding four 2 cc. portions of 3 per cent hydrogen peroxide at thirty minute intervals. Stop the aspiration and evaporate the contents of the two absorption cylinders nearly to dryness. Clean out the reaction cylinder and freshly charge with glass beads and 15 g. chromic anhydride. Into the first absorption cylinder, put 10 g. potassium iodide, dissolved in 200 cc. of water, and into the second 3 or 4 g. in a like amount of water. Connect the apparatus, draw through a slow current of air, and transfer the contents of the evaporating dish to the reaction cylinder by means of a small funnel, using 25 cc. of water. Aspirate with a rather strong current of air until all the bromine is evolved (about 1 hour) and titrate the potassium iodide solution with thiosulphate."

Chromie acid in concentrated solution liberates bromine from bromides quantitatively at room temperature.

Iodides should be removed if present in appreciable amount.

CADMIUM

Cd. at.wt. 112.41 sp.gr. 8.642; m.p. 320.9°; b.p. 778° C.; oxide CdO.

DETECTION

Cadmium is detected in the wet way by precipitation as the yellow sulphide w hydrogen sulphide from an acid solution. It is distinguished from arsenic, intimony and tin (stannic) by the insolubility of its sulphide in ammonium hydroxide or colorless ammonium sulphide; from tin (stannous) by its insolubility in yellow ammonium sulphide; and from mereury by its solubility m hot nitric acid. The separation of cadmium may be made from lead since radmium sulphate is soluble in dilute sulphuric acid while lead sulphate is not; rom bismuth since ammonium hydroxide precipitates bismuth hydroxide but iolds cadinium in solution, and from copper by passing hydrogen sulphide into he solution containing potassium eyanide which prevents the precipitation of sopper sulphide but not cadmium sulphide.

The detection of cadmium may be made in the dry way through the tube test. This test is earried out in the following manner. A piece of hard glass tubing of about 5 mm. bore is sealed at one end. From 200-400 milligrams of the fine dried ore is mixed with a reducing agent as dry powdered chareoal and introduced into the tube. The tube is heated just above the mixture of . ore and reducing agent and drawn out to a capillary of about 1 mm. diameter. The end of the tube containing the mixture is now heated in the blast lamp and the cadmium together with zine, arsenic, antimony, etc., is volatilized and condensed in the capillary in the form of separated rings. The eadmium ring is detected from the others by introducing a little powdered sulphur into the tube and heating so that the sulphur vapor passes over the rings. The cadmium is converted to sulphide and appears red while hot and yellow while cold. Very small amounts of eadmium may be detected in this way and it is possible with experience to estimate, from the appearance of the ring, either metallic or sulphide the amount of cadmium present. See Fig. 8c page 102.

Cadmium. Brilliant Spectrum of Green and Blue Lines.

Blowpipe Tests. Heated on chargoal in the reducing flame, eadmium gives a brown incrustation which is volatile.

ESTIMATION

Cadmium occurs in small quantities in practically all zinc ores and is found in most spelters and commercial zine materials as sheet zine, zinc oxide, etc. In ores it occurs usually as the sulphide; the rare mineral greenoekite being The metal cadmium is largely obtained as a by-product from zine smelting. It is used in certain alloys, as trial plates for silver coinage and more recently in substitutes for tin base-bearing metals. Precipitated yellow eadmium sulphide is used as a paint pigment.

¹ All metals present in the ore must be in the oxidized state. Sulphide ores must be carefully roasted before using in this test. In the case of metallic substances, however, no reducing agent is necessary.

Chapter contributed by L. S. Holstein and L. A. Wilson.

Cadmium is determined, after separation from other elements, by weighing as the sulphide or as the metal following electrolysis. As it usually occurs in small quantities in the presence of large quantities of zine, several precipitations with hydrogen sulphide are necessary and the methods must be followed in close detail to obtain accurate results. The determination of cadmium is necessary in case of spelters sold under specified rejection limits, in ores purchased and to be smelted for such spelter, and in other zinciferous material where cadmium is deleterious to the finished product. The methods to be used for the determination of cadmium in spelter is given under the chapter on zine.

Preparation of Sample

Samples of metals, as spelter, cadminm metal, brass, etc., should be in the form of drillings, sawings or pourings, taken in a proper manner to be representative of the lot and of sufficient fineness to preclude against a non-representative sample being weighed for analysis. The samples of orc or fine material should be ground to pass a 100-mesh screen. Metallies, if also present, are kept separate from the fine material which passes through the screen, and in weighing out the sample, proportional amounts of each are taken.

SEPARATIONS

Removal of Silica. Evaporate with hydrochloric acid or sulphuric acid, and filter off the dehydrated silica, using suction.

Removal of Lead. Evaporate to fumes with sulphuric acid, cool, take up with water, warm until all soluble salts are dissolved and allow to stand until all lead sulphate settles. By using sulphuric acid to dehydrate the siliea, lead and silica may be separated together.

Separation from Ammonium Sulphide Group, Except Zn, Alkaline Earths, and Alkalies. The solution from lead and silies separation containing 12 cc. sulphuric acid (1:1) per 100 cc. of solution is saturated cold with hydrogen sulphide, passing a steady stream for 20-30 minutes, and after the first 5 minutes adding a drop of ammonium hydroxide until zinc sulphide precipitates in quantity. It is necessary to add ammonium hydroxide to bring down zinc in order to assure the complete precipitation of cadmium. The precipitate of sulphides is filtered off and washed with cold water.

Removal of Arsenic, Antimony and Tin. The precipitate on the filter is washed with ammonium hydroxide or colorless ammonium sulphide, dissolving out the arsenic, antimony and tin (stannic). If tin in the stannous condition is found to be present, yellow ammonium sulphide must be used. Arsenious sulphide is practically insoluble in the hydrochloric acid used in dissolving the cadmium sulphide. Antimonious sulphide is also only slightly soluble, so that these sulphides remain behind in carrying out the analysis.

The sulphides of tin, however, are soluble in the hydrochloric acid and must be removed before the liual precipitation of cadmium sulphide.

• Removal of Bismuth, Copper and Mercury. Bismuth is not removed in the course of analysis as its sulphide is soluble in hydrochloric acid and hence it must be removed by precipitating with ammonium hydroxide before the final precipitation of cadmium is made. Copper sulphide is, however, practically insoluble in the hydrochloric acid used and remains behind when dissolving the first precipitations of cadmium sulphide, so that the use of potassium syanide need schom be resorted to mercuric sulphide is practically insoluble in cold hydrochloric acid (1:2) and is left behind in carrying out the analysis.

Separation from Zinc. Cadmium is separated from the accompanying zine by successive precipitations with hydrogen sulphide, each time bringing down less zinc, until finally only cadmium is precipitated. In the presence of a large quantity of zinc it is not possible to precipitate all cadmium with the acidity required to prevent the precipitation of any zinc sulphide.

GRAVIMETRIC METHODS

Determination as Cadmium Sulphide

Procedure for Ores

A 10 gram sample of the finely pulverized ore is weighed out into a 400 cc. beaker, moistened with water and 50 cc. of aqua regia carefully added. When violent action has stopped, the beaker is placed on a warm plate to complete decomposition. The cover glass and sides of beaker are washed down with water, 25 cc. of sulphuric acid (1:1) added and evaporation carried to fumes. Water (100 cc.) is added, boiled until all soluble salts are dissolved, and the residue filtered off, and washed, using suction.

A steady stream of hydrogen sulphide is passed through the filtrate, which should have a volume of approximately 300 cc. for 30-10 minutes. After all iron in solution has been reduced, annaonium hydroxide is added 1 ec. at a time until a heavy precipitation of zinc sulphide bas taken place.2 The precipitate is allowed to settle, the clear solution decanted and finally the bulk of the precipitate transferred to a 15 cc. paper, and washed with cold water. The sulphides on the paper are dissolved with hydrochloric acid (1:2) catching the solution in a clean beaker. Any precipitate adhering to the sides of the original beaker is also dissolved off and poured into the filter. After all zine sulphide has been dissolved, the paper is washed three more times with the hydrochloric acid.3 To the solution 15 cc. of sulphuric acid is added and evaporation carried just to fumes. Water is added (200 cc.) and hydrogen sulphide passed through as before. Ammonium bydroxide should be added one drop at a time, only to start the precipitation of cadmium sulphide. This precipitate is filtered off, redissolved as previously and a third precipitation made.4 Before making the final precipitation, the solution should be allowed

¹ In the case of oxidized ores, hydrochloric acid alone may be used, although it is well to use a little nitric acid also.

² The solution should always be sufficiently acid so that no iron etc. precipitates.

³ This strength of acid will leave on the paper as an insoluble residue all the As, Cu, and Hg, most of the Sb, and some of the Bi and Sn. The second precipitation of CdS should free the Cd of the rest of the Sb, but not the Bi or Sn.


⁴ It is necessary to make three or even four precipitations of cadmium sulphide in order to free it completely of zinc.

to stand, and any lead sulphate filtered off. The final precipitate of cadmium sulphide is filtered on a weighed Gooch crucible.

The cadmium sulphide on the Gooch crucible need only be washed once or twice, if at all, as it usually receives sufficient washing in the transfer to the crucible, and in the scrubbing and washing out of the beaker. After drying at 110° C. for 1 hour, the crucible is cooled, weighed and the cadmium calculated from the difference in weights.

$$CdS \times .778 = Cd.$$

It is seldom that bismuth and tim will be encountered in making a determination for cadmium so that the procedure for removing these elements need rarely be used. Cadmium sulphide precipitated from sulphuric acid is bright



Tube Test.
Fig. Sc.

yellow to orange. If the precipitate is brown in eolor, bismuth and tin should be looked for and removed.

Determination as Sulphate

The final precipitate of cadmium sulphide is dissolved with hydrochloric acid, and evaporated to dryness in a weighed platinum crucible or dish. A slight excess of dilute sulphuric acid is poured over the residue and evaporated over a steam bath or warm plate. The excess of sulphuric acid is driven off by heating in an air bath, or in a muffle heated below a dull red heat. For

an air bath, the crucible or dish may be placed in a larger vessel, and this outer vessel heated to redness. $CdSO_4 \times 0.5392 = Cd$.

Electrolytic Determination of Cadmium

The final precipitate of CdS is dissolved and the cadmium determined electrolytically as given under cadmium in spelter, Chapter on Zinc, or if the amount of cadmium is large the electrolytic determination is best carried out with a potassium cyanide electrolyte. The hydrochloric acid solution of cadmium, after separation of interfering elements is taken to fumes with sulphuric acid, a drop of phenolphthalem added for indicator, and a pure solution of sodium hydroxide added until a permanent red color is obtained. A strong solution of potassium cyanide is added drop by drop until the cadmium hydroxide just dissolves, avoiding any excess. The solution is diluted to 100 cc. with water, electrolyzed cold using a gauze electrode with a current

of 0.5-0.7 ampere and voltage of 4.8-5.0. At the end of 5-6 hours the current is increased to 1-1.2 amperes and electrolysis continued for an hour more. The electrode is removed from the solution the instant the current is broken and immediately washed with water, followed by alcohol and ether. After drying at 100° C., the electrode is cooled and weighed. Prolonged heating of the deposit should be avoided.

Rapid deposition can be effected by means of the rotating anode (600 revolutions per minute). The solution of cadmium sulphate containing 3 cc. of H₂SO₄ (I: 10) per 150 ce. The solution, heated to boiling, is electrolyzed with a current of N.D.100 =5 amperes, E.M.F. =8-9 volts. Fifteen minutes is sufficient for the deposition of .5 gram of cadmium.

Notes. Before washing and discontinuing the current, it is advisable to add a little water to raise the level of the liquid and continue the electrolysis to ascertain

whether the deposition is complete.

Traces of cadmium may be estimated in the above solution by saturating this with H2S and comparing the yellow-colored colloidal cadmium sulphide solution with a known quantity of cadmium and the same amounts of potassium hydroxide and evanide as in the solution tested.

VOLUMETRIC DETERMINATION OF CADMIUM

Titration of Cadmium Sulphide with Iodine.²

The titration of eadmium sulphide with standard iodine in a hydrochloric acid solution is the same as the procedure given for determination of sulphur by the evolution method, the following reaction taking place:

$$CdS+2HCl+I_2=CdCl_2+2HI+S.$$

Procedure. Cadmium having been isolated as the sulphide according to the standard procedures given, the precipitate is washed and allowed to drain on the filter. The filter, together with the sulphide, is placed in a beaker or an Erlenmeyer flask, water added, and the whole shaken to break up the precipitate. A moderate quantity of hydrochloric acid is added and the solution titrated with standard N/5 or N/10 iodine solution. Towards the end a little starch solution is added and the titration continued until the excess of iodine colors the solution blue. If preferred, an excess of iodine solution may be added and the excess determined by a back-titration with standard thiosulphate solution.

One cc. N/10 iodine =0.00562 gram cadmium.

¹ Electro-Analysis, E. F. Smith. P. Blakiston's Son & Co. Pub.

² P. von Berg (Z. a. C., 26, 23) transfers the precipitate and filter to a stoppered flask, expels the air with CO₂ and by boiling and then titrates in an hydrochloric acid solution. Experiments by the author have shown this caution to be unnecessary.

CALCIUM

Ca. at.wt. 40.07; sp.gr. 1.544629; m.p. 810°1 C.; oxide, CaO

DETECTION

In the usual course of qualitative and quantitative analysis calcium passes into the filtrates from the elements precipitated by hydrogen sulphide in acid and alkaline solutions (Ag, Hg', Hg", Pb, Cu, Cd, As, Sb, Sn, Fe, Cr, Al, Mn, Ni. Co. Zn. etc.), and is precipitated from an ammoniacal solution by ammonium earbonate as calcium carbonate, along with the carbonates of harium and strontium. The separation of calcium from barium and strontium is considered under Separations. The oxalate of calcium is the least soluble of the alkaline-earth group.² All, however, are soluble in mineral acids. Calcium oxalate may be precipitated from weak acetic acid solution by ammonium

Flame Test. The flame of a Bunseu burner is colored vellowish red when a platinum wire containing calcium salt moistened with emeentrated hydrochlorie acid is held in the flame.

Spectrum. An intense orange and green line with a less distinct violet line. Note chart of the spectra of the alkaline earths. Plate II.

See chapter on Barium under Separations—Preliminary Tests, page 58.

ESTIMATION

The determination of calcium is required in complete analyses of ores. It is of special importance in the analysis of mortar, cement, bleaching powder. plaster of Paris, certain paint pigments such as phosphorescent paint, CaS. The determination is required in the analysis of water.

Calcium occurs in the following substances: as earbonate in limestone, marble, chalk, Iceland spar, shells, coral, pearl. Together with magnesium it is found in dolumite. It occurs as sulphate in anhydrite, gypsum, alabaster, selenite; as silicate in the mineral wollastonite, CaSiOs; as phosphate in phosphorite, Cn₄(PO₄)₂, also in bones and in apatite, 3Ca₂(PO₄)₂·CaF₂; as fluoride in fluorspar, CaF₄. As oxalate it occurs in plant cells. It is found in nearly all mineral springs, artesian wells, and river waters, principally as bicarbonate of calcium, CaHCOs.

Preparation and Solution of the Sample

The oxide, hydroxide, and salts of calcium are soluble in acids with the exception of gypsum and certain silicates which require fusion with sodium carbonate or bicarbonate followed by an hydrochloric acid extraction,

\$ \$2 (2d Ed.) U. S. Bureau of Standards. \$ \$2 ability: CaC_tO_t \cdot H_tO = 0.000554 gram per 100 cc. H_tO. BaC_tO_t \cdot H_tO = 0.0093 gram. \$ SrC_tO_t \cdot H_tO = 0.0051 gram. \$ MgC_tO_t2H_tO = 0.07 gram. \$ Van Nostrand's Chem. Annual—Olsen.

Chapter contributed by Wilfred W. Scott.

Solution of Limestones, Dolomites, Magnesites, Cements, Lime, etc. One gram of the powdered material is digested in a 250-cc. beaker with 20 ec. of water, 5 ee. of concentrated hydrochloric acid, and 2 or 3 drops of nitric acid (sp.gr. 1.42). The beaker is covered to prevent loss by effervescence. When the violent action has subsided, the sample is placed on a hot plate and boiled for a few minutes. The wateh-glass is rinsed into the beaker and the solution filtered. The residue is washed, dried and ignited in a platinum crucible, and then fused with a little sodium carbonate or bicarbonate. The cooled fusion is dissolved in hot dilute hydrochloric acid, the liquid added to the main solution and calcium determined by precipitation as calcium oxalate, after removal of silica, iron, alumina, etc.

Solution of Gypsum, Plaster of Paris, and Sulphates of Lime, etc. The treatment of the sample is similar to the one given above with the exception that it is advisable to add a larger amount of strong hydrochlorie acid, e.g., about 20 to 25 ec. If barium sulphate is present it is indicated by the elouding of the solution, upon acidifying the water extract of the carbonate fusion.

Silicates. Solution of silicates is best obtained by direct fusion of 1 gram of the powdered material with 4 to 5 grams of sodium earbonate, in a platinum erucible. The cooled melt is now covered with water and dissolved with hydrochloric acid according to the standard procedure for carbonate fusions. The hydrochloric acid solutions are taken to dryness and the silica dehydrated in an oven at 110° C. for an hour and then the residue is extracted with diffute hydrochloric acid and filtered. The filtrate contains iron, alumina, magnesium, lime, etc.

Chlorides, Nitrates, and Other Water-soluble Salts. These are dissolved in water slightly acidified with hydrochloric acid.

Sulphides, Pyrites Ore, etc. The ore should be oxidized with bromine or by roasting, previous to the acid treatment.

SEPARATIONS

Removal of Silica. The solution obtained by one of the above procedures is evaporated to dryness and the silica dehydrated at 110° C. for an hour. The residue is now extracted with dilute hydrochloric aeid. Silica remains insoluble and may be filtered off. The solution contain lime, together with iron, alumina, magnesia, etc., as chlorides.

Removal of Iron and Alumina. The filtrate from the silica residue is treated with a few drops of nitric acid and boiled to oxidize the iron. Ammonia is now added cautiously until the solution just smells of it (a large excess over that required to neutralize the acid and combine with iron and alumina, will tend to dissolve Al(OH)₃). The precipitated hydroxides are allowed to settle and then filtered hot through a rapid filter and washed with hot water. Calcium, together with magnesium, is in solution and passes into the filtrate.

Removal of Copper, Nickel, Cobalt, Manganese, Zinc, and Elements Precipitated as Sulphides in Acid and Alkaline Solutions. This separation is required seldom in lime-bearing ores. In analysis of pyrites and catain other ores, containing members of the hydrogen sulphide and ammonium sulphide groups, the removal of these impurities is necessary.

The solution from the residue of silica is made slightly ammoniacal and H₂S passed into the solution to saturation (or ammonium sulphide may be

added). The precipitated sulphides are filtered off from the solution heated to boiling. The filtrate containing the calcium is boiled down to 50 to 75 cc. and the precipitated sulphur removed by filtration. Calcium is determined in the filtrate by precipitation with ammonium oxalate or oxalic acid according to directions given later.

Separation of Calcium from Magnesium and the Alkalies. In the presence of considerable amounts of calcium and comparatively small quantities of magnesium the oxalate method of precipitating ealeium, in presence of aminonium chloride, is generally sufficient for precipitating ealeium free from magnesium and the alkalies. In analysis of dolomite, MgCO₂ CaCO₃, and of samples containing comparatively large amounts of magnesium, a double precipitation of calcium is generally necessary for removal of occluded magnesium.

Separation of Calcium from Barium and from Strontium. The alkaline earths are converted to nitrates, all moisture expelled by heat, and calcium nitrate extracted from the insoluble nitrates of barium and strontium by a mixture of anhydrous ether and absolute alcohol, in equal parts, or by boiling the dry nitrates in amyl alcohol $(b.p., 137.8^{\circ} \text{ C.})$. Details of the procedure are given under Separations of the Alkaline Earths in the chapter on Barium, page 59.

Determination of Lime in Presence of Phosphates, Iron, and Alumina. Should phosphorie acid be present in the solution, calcium will be precipitated as a phosphate upon making the solution neutral or slightly alkaline with ammonia, and will remain with iron and alumina precipitates.

Precipitation of Calcium Oxalate in Presence of Iron and Alumina. The solution containing the phosphates freed from silica is oxidized by boiling with nitric acid as usual. Annuonia water is added to the cooled solution until a slight precipitate forms, and then citric acid is added in sufficient quantity to just dissolve the precipitate. If this does not readily occur, additional ammonia is added, followed by citric acid until the solution clears, then about 15 ce. of citric acid in excess. The solution is diluted to 200 ce. and heated to boiling. Calcium oxalate is now precipitated by addition of ammonium oxalate. Iron and alumina remain in solution.

Citric acid is made by dissolving 70 grams of the acid, H₂C₆H₆O₇·H₂O, in a liter of water.

Wagner's Solution. In place of citric acid, the following solution may be used. Twenty-five grams of citric acid and 1 gram of salicylic acid are dissolved in water and made to 1000 cc. Twenty-five to 50 cc. of this reagent is effective in preventing precipitation of iron and alumina.

Decomposition of Material. Though carbonates are easily dissolved in hydrochloric acid, sulphates and fluorides of calcium require fusion with sodium and potassium carbonate to effect decomposition. In case calcium fluoride is being decomposed, the addition of an equal weight or more of silica is necessary, and sodium or potassium hydroxide may be substituted for potassium carbonate. The fusion is leached with water to remove the mineral acids, and the residue, containing all of the calcium, is dissolved in hydrochloric acid. Calcium is now determined in the hydrochloric acid solution. If phasphate is present in the sample, it is not completely removed by the water leaching as sodium phosphate, as this reacts in the solution with calcium arbonate causing a partial conversion to calcium phosphate, which remains in the residue. In this case it is advisable to precipitate calcium oxalate from a slightly acetic acid solution, in which calcium phosphate, will not precipitate, as it would if the solution was made ammoniacal.

GRAVIMETRIC DETERMINATION OF CALCIUM

Precipitation of Calcium Oxalate and Ignition to Calcium Oxide

Calcium oxalate is precipitated from feebly ammoniacal solutions or from solutions acidified with acctic, oxalic, citric, or salicylic acids, by means of ammonium oxalate. The presence of ammonium chloride hinders precipitation of magnesium and does not interfere with that of calcium. If, however, much magnesium (or sodium) is present it will contaminate the calcium precipitate so that a second precipitation is necessary to obtain a pure product. The compound formed from hot solutions is erystalline or granular and filters readily, whereas the flocculent precipitate formed in cold solutions does not. Calcium oxalate, CaC₂O₄·H₂O, decomposes at red heat to CaO, in which form it is weighed.

Procedure. If the calcium determined is in the filtrate from previous groups, hydrogen sulphide is expelled by boiling and the precipitated sulphur filtered off, the solution having been concentrated to about 200 cc. The filtrate should contain sufficient ammonium chloride to hold magnesium in solution in presence of ammonium oxalate (i.e, about 10 grams NII,Cl per 0.0015 gram MgO per 100 cc. of solution.) If not already present, the chloride is added in sufficient amount, and the solution diluted to about 400 cc.

Precipitation. The solution is heated to boiling and 10 ec. of acetic acid added to the neutral mixture. Fifteen ec. or more of a saturated solution of oxalic acid is added and after five minutes a slight excess of ammonia. The solution is allowed to cool an hour or so, the clear solution decanted through a 10-cm. filter and the precipitate washed three times by decantation and finally

on the filter with dilute ammonia (1:10), or 1% ammonium oxalate.

To remove clinging impurities (Na or Mg) the precipitate is dissolved in dilute nitric acid (1:4) and the filtrate collected in the beaker in which the first precipitation was made. The solution is heated to boiling after addition of a few drops of oxalic acid and sufficient ammonium hydroxide to make the solution slightly alkaline. The precipitated oxalate is allowed to settle, filtered and washed as in the first precipitation, the oxalate adhering to the sides of the beaker being carefully "copped" out. The oxalate is ignited wet in a weighed crucible, the heat being low at first, until the filter has charred and then to the full heat of the Méker blast lamp. Fifteen minutes of blasting should be sufficient to obtain constant weight. If the precipitate is large a second ignition is advisable to insure the complete decomposition of the oxalate and carbonate to oxide.

The crucible is cooled in a desiccator and weighed as soon as possible. Factors. $CaO \times 0.7146 = Ca$, or $\times 1.7847 = CaCO_1$, or $\times 2.8908 = Ca(HOO_1)_2$, or $\times 2.428 = CaSO_4$.

¹ Calcium oxalate dried at 100 = CaC₂O₄·H₂O. Heated to 200° C. = CaC₂O₄. At 500° C, the oxalate begins to decompose, free carbon is liberated, and calcium carbonate begins to form. At bright red heat carbon burns off and the carbonate is completely decomposed to the oxide and CO₂.

Calcium Phosphate. Fusion of the phosphate with sodium carbonate and silica does not effectively accomplish removal of P_2O_6 by leaching with water if calcium is present (also Ba and Sr) since the phosphate of calcium forms an insoluble phosphate, the reaction of calcium carbonate to phosphate and phosphate to carbonate being reversible. Under these conditions it is preferable to precipitate aluminum in a faintly acid solution by addition of sodium thiosulphate.

VOLUMETRIC DETERMINATION OF CALCIUM

Titration of the Oxalate with Permanganate

This procedure may be applied successfully in a great variety of instances on account of the readiness with which calcium oxalate may be separated. In the presence of iron, alumina, manganese, magnesia, etc., it is advisable to make a reprecipitation of calcium exalate to free it from adhering contaminations.

The following reaction takes place when potassium permanganate is added to calcium oxalate in acid solution:

 $5CaC_2O_4 + 2KMnO_4 + 8H_2SO_4 = 5CaSO_4 + K_2SO_4 + 2MnSO_4 + 10CO_2 + 8H_2O_4$

Procedure. Calcium oxalate, obtained pure, by precipitation and washing according to directions given under the gravinetric determination of calcium. is washed into a flask through a perforation made in the filter paper, the filter is treated with a little warm, dilute sulphuric acid and the adhering oxalate dissolved and washed into the flask. About 25 cc. of dilute sulphuric acid, 1:1, is added and the solution diluted to 250 to 300 cc.

When the precipitate has dissolved, the solution warmed to 60 or 70° C. is titrated with standard potassium permanganate, added cautiously from a burette with constant agitation, until a faint permanent pink color is obtained.

One cc. N/10 KMnO₄ = 0.0020 gram Ca, or $\times 0.0028$ = CaO.

Factors. $Ca \times 1.3993 = CaO$ or $\times 2.4974 = CaCO_1$ or $\times 3.3975 = CaSO_4$ or $\times 2.581 = \text{Ca}_4(\text{PO}_4)_3$.

Norges. Precipitation from Acetic Acid Solution. This is recommended if the material contained phosphates. The solution should contain about I cc. free glacial acetic neid per two hundred cc. of solution. In presence of phosphate, iron and aluminum cannot be removed by addition of annuous as calcium would also precipitate as phosphate. Citric acid may also be used to prevent precipitation of iron.

Procedure. To a volume of about 75 cc. of solution containing 0.1 to 0.15 g. Ca add 10 ce. acetic acid (glacial), beat to boiling and add slowly 10 ce. of a saturated solution of ammonium oxalate. Now add a slight excess of ammonia mid make slightly acid with acetic acid (about 0.5 ce. per 100 ce. solution). If phosphate is present this last acidification is necessary, likewise in presence of aluminum.

Available Lime

This is the usual method followed in cyanide mills for determining the per cent which will dissolve of the line added to the mill solution, and therefore the amount to add to maintain the desired protective alkalimity.

Procedure. One gram of the finely ground sample is placed in a glass stoppered bottle which has been previously marked to hold 500 ce. Thirty grams of sugar and about 300 ce. of water are added and the bottle shaken vigorously. The solution is diluted to 500 cc. and shaken at ten minute intervals for 11 to 2 hours. Then the insoluble material is allowed to settle, part of the solution filtered through a coarse filter paper, 50 ee. of the litrate drawn out with a pipette into an Erlenneyer flask, two drops of phenolphthalein indicator added, and the solution titrated with N/10 oxalic acid solution till the pink color disappears. The lime is reported as per cent available CaO.

1 ec. N/10 Oxalic Acid = .0028 grams CaO.

Standard N/10 Oxalic Acid Solution. Dissolve 6.303 grams $\rm H_2C_4O_4.2H_2O$ in distilled water and dilute to 1000 cc. The solution ordinarily need not be standardized as the weight of the oxalic neid is constant.

To standardize take 30 cc. of the solution, add 100 cc. of water and 5 cc. of conc. H₂SO₄, heat to 70° and titrate to a permanent pink with N/10 KMnO₄.

Rapid Iodine Method for Calcium Oxide in Presence of Calcium Carbonate

The method worked out by John C. Bailar, Great Western Sugar Company, is based on the fact that a solution of iodine reacts with calcium hydroxide, but does not react with calcium earbonate. The method is used in the evaluation of lime.

Reagents. Iodine Solution. A standard solution is made by dissolving 90 grams of potassium iodide and 45.27 grams of iodine in the least quantity of water necessary to effect solution, and diluting with water to one liter. 1 cc. is equivalent to 0.01 g. CaO.

Thiosulphate Solution. The reagent is made by dissolving 44.27 grams of thiosulphate of sodium in water and diluting to one liter. Two ec. of this solution is equivalent to one ec. of the iodine solution.

Standardization. A definite weight of 0.5 to 1.0 gram of pure arsenous oxide (As_2O_3) is dissolved in 10% sodium hydroxide solution and the resulting product acidified with hydrochlorie or sulphuric acid. This solution is now neutralized with sodium bicarbonate and 4 to 5 grams added in excess. Starch indicator is now added and the arsenite titrated with the standard iodine solution. Since one gram of As_2O_3 is equivalent to 0.5656 gram of CaO, the weight of the arsenic taken multiplied by 0.5656, divided by the ce. of iodine required, gives the equivalent time per ec. of the standard iodine reagent. Use this factor in the iodine titrations of lime.

The thiosulphate may be standardized against a definite volume of the iodine reagent and its equivalent value established in terms of the standard iodine solution. See Notes below.

Procedure. The sample of lime (one gram is recommended) is slacked by adding boiling water (5 to 10 minutes is ample to accomplish this). An excess of iodine is added (see Notes) and the mixture stirred occasionally until the lime is all in solution. Insoluble silica is generally present but can easily be distinguished from the milky appearing lime. When the solution of the lime is complete (1 to 10 minutes will accomplish this), the excess of iodine is titrated with the standard thiosulphate. The excess thus determined is subtracted from the total iodine added and the equivalent CaO, to the combined iodine, calculated from the CaO factor of iodine.

Notes. Any substance which liberates iodine quantitatively from a solution of potassium iodide can be used for the standardization of sodium thiosulphate. Ansong such substances are potassium permangunate, potassium diebromate, potassium iodate, potassium bi-iodate, metallic copper oxidized to a cupric salt, etc. In using any of the above reagents first acidify the solution of an excess of potassium iodide with hydrochloric acid (strongly acid if dichromate is used, end point in this case is green in place of colorless) and then add the permanganate or dichromate or other reagent desired and titrate the liberated iodine in presence of starch indicator.

Lime Equivalents.	1 g. KMnO ₄	0.8870 g. CaO
	1 g. K ₂ Cr ₂ O ₇	0.5718 g. CaO
	1 g. KIO ₃	0.7860 g. CaO
	1 g. KIO ₃ HIO ₃	0.8602 g. CaO
	1 g. Cu	0.4410 g. CaO

An excess of 5 cc. of iodine is recommended in the lime determination. To the same amount of water used in the analysis add 5 cc. of the iodine and use this as a standard for color comparison in running in the necessary excess of iodine in the sample.

STANDARD METHODS OF TESTING GYPSUM AND GYPSUM PRODUCTS

ADOPTED BY A. S. T. M. IN AMENDED FORM, 1923

Free Water. Not less than 1 lb. of the entire sample as received shall be weighed, spread out in a thin layer in suitable vessel, placed in a drying oven, and dried at 45° C. for 2 hours. It shall then be cooled in an atmosphere free from moisture, and weighed again. The loss of weight corresponds to the free water, and shall be calculated to percentage of sample as received.

Preparation of Sample. Dry sample as in Section 1, and reduce about 10 g, until it all passes a 100-mesh sieve, using extreme eare not to unduly expose the material to the action of moisture or to overheating. The sample shall be kept in an air-tight container until ready for use.

Combined Water. Place 1 g. of the sample in a covered crucible and dry at 215 to 230° C, to constant weight. Calculate the loss of weight to percentage of sample as received and report as combined water.

Carbon Dioxide. Place the residue obtained after drying, as described above, in a suitable flask and dissolve it in dilute HCl (not stronger than 1:4) in such a way that the gas evolved, after being freed from H₂O vapor by calcium chloride or sulfuric acid, can be collected in either soda line or caustic potash and weighted. The solution should be boiled for one minute, and a current of CO₂-free air kept passing through the apparatus for 30 minutes. The increase of weight of the soda lime or caustic potash corresponds to the weight of carbon dioxide, which is to be calculated to percentage of sample as received.

Silica and Insoluble. Place 0.5 g. of the sample prepared as described above in a percelain casserole. Add about 25 ec. of 1:5 HCl, and evaporate to apparent dryness on a hot plate. Cool and add enough concentrated HCl to wet thoroughly. Add about 10 ec. of water, boil, filter, and wash. Put the filtrate back in the same casserole. Evaporate it to dryness and heat to about 120° C. for one hour. Cool. Add enough concentrated HCl to wet thoroughly. Add about 25 ec. of water, boil, filter, and wash. Transfer the two papers containing the two precipitates to the same crucible, ignite, and weigh. Calculate this weight to percentage of sample as received.

Iron and Alumina. To the filtrate obtained above, add a few drops of HNO₃ and boil to insure oxidation of the iron. Add 2 g. of NH₄Cl previously dissolved in water. Make alkaline with NH₄OH. Digest hot for a few minutes until the precipitate coagulates. Filter, wash, ignite the precipitate and weigh as Fe₂O₃+Al₂O₃. Calculate this weight to percentage of sample as received. This precipitate may be further treated to separate the two oxides, but this is generally unnecessary.

Lime. (a) To the filtrate obtained above, add 5 g. of (NII₄)₂C₂O₄ dissolved in water. Digest hot for ½ hour, making sure that the solution is always alkaline with NI₄OH. Filter, wash and ignite in a platinum crucible over a strong blast to constant weight. Calculate this weight to percentage of sample as received.

(b) Alternative Method. To the filtrate obtained from the iron and alumina precipitates, add 5 g. of (NH₄)₂C₂O₄ dissolved in water. Digest hot for ½ hour, making sure that the solution is always alkaline with NH4OH. Filter and wash. Transfer the precipitate to a beaker, and wash the filter paper with hot dilute H2SO4, catching the washings in the same beaker. Heat gently to complete solution, adding more H2SO4 if necessary. While still warm titrate with a solution of KMnO4 containing 5.6339 g. per liter, until the pink color is permanent. The number of cubic centimeters of KMnO4 used gives directly the percentage of lime in the dried sample. Recalculate to percentage of sample as received.

Magnesia. To the filtrate obtained from calcium precipitate, add enough water to give a total volume of about 600 cc. Cool. Add 10 cc. of NH4OH and 5 g. NaNII4HPO4 dissolved in water. Stir until precipitate begins to form. Let stand over night. Filter, wash with a 2.5 per cent by weight solution of NII4NO2. Ignite and weigh. Multiply this weight by 40/111 to find the weight of MgU. Then calculate to percentage of sample as received.

Sulfur Trioxide. Dissolve 0.5 g. of the sample prepared as described in Section 3 in 50 cc. of 1:5 HCl. Boil. Add 100 cc. of boiling water, and continue boiling for 5 minutes. Filter immediately and wash thoroughly with hot water. Boil, and while boiling, add slowly 20 ec. of a boiling 10 per cent solution of BaCl₂. Digest hot for one hour, or until precipitate settles. Filter and wash. Dry earefully. Ignite over Bunsen burner at lowest heat possible until filter paper is burned off. Ignite at bright red heat for 15 minutes, and weigh. Multiply this weight by 80/233 to determine the weight of SO₃. Then calculate to percentage of sample as received.

Sodium Chloride. Dissolve in boiling water a 1-g. sample (prepared as described in Section 3), put on the filter and wash with 250 cc. of boiling water, then titrate the filtrate. Add two or three drops of potassium ehromate solution and titrate with an N/20 solution of silver nitrate. Each cubic centimeter of silver nitrate solution = 0.002923 g, of sodium chloride. Calculate to percentage of sample tested.

Calculation of Results. By the methods given above, the results are obtained and reported in the following form: PER CENT.

		1 1111 () 1311111
Free water		
Combined water		
Silica and insoluble, SiO2		
Iron and alumina, R ₂ O ₃		
Lime, CaO	 	
Magnesia, MgO		
Sulfur Trioxide, SO ₁		
Carbon Dioxide, CO ₂		
Sodium Chloride, NaCl	. 	
		100.00
		$100.00 \pm$

Note

Since it is frequently advisable to recalculate these results, that they may be more

calightening, the following method is submitted for consideration:

(a) Multiply percentage of MgO by 84/40 to find percentage of MgCO₂.
(b) Multiply the percentage of MgO by 44/40 to find the percentage of CO₂ as MgCÓ₂.

(c) Deduct CO₂ as MgCO₃ from the CO₂ determined.
 (d) Multiply the CO₂ remaining by 100/44 to find percentage of CaCO₃.

(e) Add together the percentage of SiO2, R2O3, MgCO3, and CaCO3, and report in

the aggregate.

(f) Multiply the percentage of CaCO₃ by 56/100 to find the percentage of CaO as CaCO₃.

(g) From the total percentage of CaO deduct the percentage of CaO as CaCO:

The remainder may be called "available CaO."

(h) The "available CaO" should bear to the SO₂ a ratio of 7 to 10. Determine

which (if either) is in excess. (i) If the Ca() is in excess, multiply the SO₂ by 7/10, and subtract the result from the "available Ca()." The remainder is reported as "excess Ca()."

(j) If the SO₂ is in excess, multiply the "available CaO" by 10/7 and subtract the result from the SO₃. The remainder is reported as "excess SO₃."
 (k) Add together the "available CaO" and the SO₃, and subtract the "excess CaO" or "excess SO₃." The remainder is CaSO₄.

(t) If the CaSO₄ is present as CaSO₄ ½H₂O, the percentage of CaSO₄ should bear to the percentage of combined water a ratio of 136 to 9. Determine which (if either)

is in excess (m) If the CaSO₄ is in excess, some of it is present in the anhydrous form. Multiply the percentage of combined water by 136/9 to find the percentage of CaSO₄ as CaSO₄ 4H₄O. The difference between the total CaSO₄ and the percentage of CaSO₄ as CaSO4 III2O is the CaSO4 in the anhydrous form.

(a) If the water is in excess, some of the CaSO₄ is present as gypsum. Let x = percentage of CaSO₄· $\frac{1}{2}$ H₂O, and y = percentage of CaSO₄· $\frac{1}{2}$ H₂O. Then x + y = percentage of CaSO₄ (as found in k) + percentage of water.

$$\frac{9x}{145} + \frac{36y}{172}$$
 = percentage of combined water.

Solve these equations for x and y. Report x as percentage of "calcined gypsum," $CaSO_4$ $4H_2O$. Report y as percentage of gypsum, $CaSO_4$ $2\Pi_2O$.

Having nade these calculations, the result may be reported as follows:

	1	PER CENT.
Typsnin, CaSO ₄ + 2H ₂ O		
Calcined gypsmu, CaSO ₄ + \H2O		
Anhydrite, CaSO4	٠.	
EXCOSS CITY		
Excess Ca() or Excess SO ₃ Sodium chloride, NaCl	• •	•
Sodium chloride, NaCl		•
Other ingredients		•
		100.00 +

¢

The presence of the different forms of CaSO₄ may be corroborated by a microscopic examination.

Other Gravimetric Methods

Calcium may be converted to carbonate, sulphate, fluoride, tungstate and so weighed The oxide, obtained by ignition of the oxalate may be converted to sulphate by moistening with a few drops of H₂SO₄, then adding an excess of NH₄OH and igniting to expel excess of sulphate and NH₃.

Calcium sulphate may be precipitated by adding an excess of H_2SO_4 and then 95% alcohol (two to four times the total volume of the solution). The precipitate is washed

With alcohol and then ignited to constant weight. (Fresenius.)

Calcium tungstate by Saint Sernin's method is precipitated by adding ammonia until the solution is alkaline and then an excess of 20% solution of sodium tungstate. The precipitate is best filtered into a weighted Goods crucible and washed with ammonia (1:10 sol.) then dried at 100° C. and weighed as CaWO.

CARBON

C, 1 at.wt. 12.0; sp.gr. amorp. 1.75-2.10; cryst.: graphite, 2.25; diamond, 3.47-3.5585; m.p. sublimes at 3500° C.; oxides, CO and CO;

DETECTION

Element. Carbon is recognized by its appearance and by its inertness towards general reagents. It is seen in the charring of organic matter when heated or when acted upon by hot concentrated sulphuric acid.

Upon combustion with oxygen or by oxidation with chromic and sulphuric acids, carbon dioxide is formed. The gas passed into lime water forms a white precipitate, CaCO₂. Penfield fuses the substance with precipitated and washed PbCrO₄ in a hard glass tube closed at one end. The CO₂ is tested at the mouth of the tube.²

Carbon Dioxide. Carbonates. CO₂ in Gas. A white precipitate with lime water, baryta water, ammoniacal solutions of calcium, or barium chlorides, or lead acetate (basic), carbonates of the metals are formed.

Carbonates. Action of mineral acids cause effervescence, CO_2 being evolved. The gas is odorless (distinction from SO_2 , H_2S , and N_2O_3) and is colorless (distinction from N_2O_3). The gas absorbed in the reagents above mentioned produces a white precipitate. The test is best made by placing the powdered material in a large test-tube with a stopper carrying a funnel and delivery tube as shown in the illustration, Fig. 9. For small amounts of combined

phosphoric acid should be used to liberate the gas, which is conducted into the reagent used for the test.

Distinction between Soluble Carbonates and Bicarbonates. The solution of the former is alkaline to phenolphthalein indicator (pink). Bicarbonate solutions remain colorless with this indicator. Normal earbonates precipitate magnesium carbonate when added to magnesium sulphate solution; bicarbonates cause no precipitation.

CO2, warming of the test-tube may be necessary. Sulphuric or

precipitation.

Free Carbonic Acid in Water in Presence of Bicarbonates.

O.5 ee. of rosolie acid (1 part acid in 500 parts of 80% Carbonate.

alcohol), produces a red color with bicarbonates in absence of free CO2, and a colorless or faintly yellow solution when free CO3 is present.

Carbon Monoxide. The gas burns with a pale blue flame and is not absorbed by potassium hydroxide or lime water (distinction from CO₂). It is oxidized to CO₂ and so detected. With hot, concentrated potassium hydroxide, potassium formate is produced.

M'2 CO3

The gas is detected in the blood by means of the absorption spectrum.

Van Nostrand's Chemical Annual, Olsen.
Chapter contributed by Wilfred W. Scott.

ESTIMATION

The element occurs free in nature in the crystalline forms, diamond and graphite, and in the amorphous form, charcoal, coke, etc. It occurs in iron, steel, and in certain alloys. Its estimation in these metals is generally required. Carbon is determined in the analysis of organic compounds in which it is invariably combined and may also be present as free carbon (asphaltum).

Combined as a carbonate it occurs in a large number of substances, among which are found calcite, marble, limestone, dolomite, magnesite, strontianite, witherite, spatic iron ore. It occurs as the dioxide in the air, in water (H₂O·CO₂) and in flue gas. Carbon dioxide is the active constituent of baking powders (NaHCO₂).

Preparation of the Sample

Iron, Steel, and Alloys. The subject is discussed in the chapter on Iron and Steel, Volume II.

Organic Matter. It is advisable to fuse this in a nickel or iron crucible with sodium peroxide. The carbonate thus formed may be determined as usual. The organic substance may be oxidized directly in the combustion furnace.

Carbonates. Limestone, Dolomite, Cement, Alkali Carbonates and Bicarbonates. The powdered material is decomposed by addition of an acid as directed in the methods given later.

Separation of Carbon from Other Substances

The element is generally determined as carbon dioxide, in which form it is liberated from most of the combinations in which it occurs, free from other substances by ignition in a current of oxygen, or by oxidation with chromic acid as directed later.

Separation of Carbon in Iron and Steel. Cupric Potassium Chloride Method. 0.5 to 2 grams of the drillings are treated with 100 to 200 cc. of cupric potassium chloride solution and 10 cc. of hydrochloric acid (1.19). This mixture dissolves the iron according to the reaction

The solution should be stirred frequently to hasten the solution of the iron. It is advisable to keep the temperature of the solution at about 50° C. When the iron and copper have dissolved the carbon is filtered off into a perforated platinum boat or crucible, as directed under the methods. It is now oxidized to CO₂ and so determined.

Note. The cupric potassium chloride solution is prepared by dissolving 150 parts of potassium chloride and 170 parts of crystallized cupric chloride in water and crystallizing out the double salt. Three hundred grams of this salt are dissolved in 1000 cc. The solution may be used several times by chlorinating the dirty brown filtrate from the carbonaceous residue. The cuprous chloride formed during the solution of the steel is converted again to cupric chloride, and the chlorinated double salt is even more energetic in its solvent action than the freshly made reagent. (Blair.)

GRAVIMETRIC METHODS FOR DETERMINATION OF CARBON 1

The determination of carbon by combustion with oxygen is made in two general classes of substances: A. Steel, iron and in certain alloys. B. Organic compounds. Carbon in steel and alloys is considered in two forms: carbide or combined carbon, and graphitic carbon. In organic substances carbon occurs principally combined with hydrogen, oxygen, and nitrogen. For the present we will consider procedures for the determination of carbon in steel and alloys.

The most accurate procedure for determination of carbon in steel, alloys, and in other materials containing the substance combined or free is by combustion with oxygen in a furnace heated by gas or electricity; the carbon dioxide formed being absorbed in caustic, and weighed.

Apparatus. Combustion Furnace. Although the gas furnace has been used more commonly on account of gas being more available than electricity, the extension of generating electric plants makes it possible to use electric furnaces, and these are gradually displacing those heated by gas, as they are more compact, easily manipulated and comparatively simple in structure.

A simple electric furnace may be made by wrapping a silica tube with a thin covering of asbestos paper, which has been moistened with water. On drying the paper will cling to the tube. A spiral coil of nichrome wire (Driver and Harris) is wound around this core. On a 2-foot length of tube two 45-foot lengths of No. 18 wire, connected in parallel, will heat the tube to bright redness, attaching the terminals to an ordinary light socket. The coils should be covered with \(\frac{1}{2}\)-in, coating of alundum cement. For appearance' sake as well as for protection, the tube is placed in a large cylinder of sheet iron, packed around with asbestos, and is held in position by circular asbestos boards placed at the ends of the large cylinder. The cylinder is mounted on a stand.

Absorption Apparatus. A large number of forms are for sale. The Coissler and Liebig bulbs have been popular (Figs. 11 and 12), but are now being displaced by forms that have less surface exposed, that are more easily cleaned and less fragile, such as Gerhardt's, Vanier's and Fleming's apparatus (Figs. 13, 14 and 16). The Vanier and the Fleming absorption apparatus are especially to be

passing at a rapid rate, and their simplicity of form.

¹ The Wet Method. Oxidation of carbon in iron and steel is accomplished by means of boiling chromie-sulphuric acids, containing copper sulphate (35 cc. chromic acid made by dissolving 720 grams of chromic acid with 700 cc. of water, 150 cc. of 20% copper sulphate and 200 cc. of strong sulphuric acid); the evolved carbon dioxide is absorbed in soda lime. The method is of value in cases where a combustion furnace is not available. The procedure, however, requires considerably more time and manipulation and can not compare with the standard combustion methods described.

recommended, on account of their capacity, compactness, efficiency, in handling gases



Fig. 10.—Hutchinson-Weirich Combustion Bulb for the Rapid Absorption of CO₂ in Carbon Determinations in Iron and Steel.

Procedure for Determining Carbon by Combustion. 1

The greatest value of this rapid method is realized when it is used to follow a bath of steel in the open-hearth furnace preliminary to tapping. It abolishes








Fig. 11.—Geissler Bulb.

Fro. 12.—Liebig Bulb.

Fig. 13.—Gerhardt Bulb.

completely the unreliable and dangerous color carbon. By this method absolutely accurate results can be reported to the open hearth ten minutes after the drillings are received.

In principle this method is not new; in manipulation it is new. Hereto-



Fig. 14.—Vanier Bottle.

fore chemists have been laboring under the impression that the flow of gas during a combustion must not exceed a certain snail-like pace. This false impression has been injected into the minds of chemists by a few who were supposed to have investigated the matter. The truth is that the faster oxygen is fed to burning steel the more complete the combustion will be. The rate of current is limited by the efficiency of the apparatus used to absorb the evolved earbon dioxide.

The Apparatus Described. The combustion train is shown complete in Fig. 15. The oxygen is delivered to the train through a regulating and reducing valve such as is used for welding. The regulating valve is not essential, yet any chemist who uses one will appreciate its convenience, especially in this method. Its convenience will be explained later. K is a mercury pressure gauge. It serves as a guide during the combustion and is an essential piece of apparatus. The graduated column is 6 ins. high and is

divided into eighths. P is a washing bottle containing caustic potash solution. Filled to the mark indicated with 50% solution it will serve for at least 1000 combustions. It is used solely to indicate the flow of gas, not to purify it. If the chemist desires he may omit this from the train. T is a calcium chloride jar. It is filled to the mark indicated with finely divided calcium chloride, about pea size, retaining all the dust. A layer of asbestos is formed over the chloride and the remaining space filled with soda lime. The glass tubing leading from the jar is loosely packed for a distance of several inches with asbestos. This prevents any soda lime dust being carried into the combustion tube. G is a mercury valve like that used in Johnson's train. It is used solely to maintain an atmosphere of

¹ By Wm. R. Fleming, Metallurgist, Andrews Steel Company, Newport, Ky. Iron Age, Jan. 1, 1924.

pure oxygen in the purifying train, a condition essential to accurate results. It is not used to prevent earbon dioxide backing into the purifying train, of which there is not the remotest possibility.

The combustion tube is the ordinary fused silica tube glazed on the inside only. The tube is 30 ins. long with inside diameter of from 7 to 1 in. One tube of 30 ins. will serve twice as long as one of 24 ins. It is loosely packed with asbestos for a distance of 6 ins. at the exit end. and 3 ins. is allowed to project from the furnace. For about the first 100 combustions, the combustion boat is pushed close against the asbestos. The portion of the tube immediately above this will become coated with iron oxide. The asbestos is then moved up so that it covers this portion of the tube and a fresh area exposed to the spraying oxide. In this manner one tube can be made to serve 600 combustions or even more. Both platinum and nickel cylinders have been used inside the tube to protect it from the spraying oxide, but it is doubtful whether this practice pays. These cylinders are not used in this laboratory because it is believed that they delay incipient combustion for at least thirty seconds.

The Furnace and Combustion Tube. The furnace used is one of the ordinary resistance type. It is constantly maintained at a temperature of 1000° C. This temperature is verified daily by the use of a pyrometer. Many claim to be expert at judging temperatures, but none are expert enough to be without a pyrometer. The two-way stop following the combustion tube will be found very convenient when it is not desirable to pass the current through the jars Z and O.

Z is filled with 20-mesh zinc. Once filled it will serve for several thousand combustions. As a matter of fact it is included in this train as a filter. If nickel boats and aliminimm are used the chemist may omit this zinc jar from the train, for with all ordinary grades of steel it serves no purpose.

O is the phosphoric anhydride jar. A little asbestos is placed in the lower part just above the lower stopper. The remaining space in the jar is completely filled with phosphoric anhydride. The upper stopper is packed tightly enough to prevent any powder being swept into the weighing apparatus. As the anhydride liquefies it passes down into the lower stopper, where it can

Fro. 15.—Fleming's Apparatus for Determination of Carbon by Combustion

be removed conveniently without disturbing the anhydride above it. Likewise

the anhydride can be replenished by removing only the upper stopper. The jar need not be washed oftener than once in 500 combustions. When filled with anhydride, fresh reagent need not be added for at least 150 combustions. After each combustion the jar should be given a few sharp taps with the hand to prevent canals being formed.

Details of the Absorption Apparatus. The absorption apparatus, shown




Fig. 16.—Fleming Absorption Apparatus.

in detail in Fig. 16, has been modified slightly at the suggestion of Henry G. Martin, of the Railway Steel Spring Company, Chicago Heights, Ill. This apparatus is no more efficient than the old style, but it is much more convenient and less tromblesome. In the old-style tube the anhydride would liquefy after several days and require replenishing. To overcome this, Mr. Martin suggested using separate chambers for the anhydride and soda line, so that communication could be broken when the tube was standing idle. The tube shown, Fig. 16, is Fleming's modification of Mr. Martin's suggestion. When properly filled this tube will serve for at least 70 combustions when operating on 1.5 grams of sample containing 1.03% carbon.

The unhydride in the upper chamber serves for at least 300 combustions. Soda lime, placed in the lower tube in alternate layers (\frac{1}{2}\) in.) of the different meshes, has proven a very convenient and desirable reagent. The 12-mesh soda lime for nitrogen can also be used with excellent results. If this is employed, part of it should be ground to about 60-mesh and

alternate layers of fine and coarse used.

It is exceedingly important that the tube be loaded with alternate layers of coarse and fine reagent, for, if the 12-mesh reagent is transferred directly from the bottle to the absorption tube, the latter will fail to be effective for more than 30 combustions and in some cases less. The reason for this is evident. The lower stopper is packed loosely with asbestos, also the lower portion of the soda lime chamber just above the stopper. Beginning with a layer of 12-mesh soda lime, the entire chamber is filled with alternate layers of fine and coarse reagent. The small diameter of the anhydride chamber is packed with asbestos and the remaining space filled with phosphoric anhydride. Finally, the upper stopper is packed with asbestos. The anhydride chamber, filled as indicated, will not require refilling for at least 300 combustions. It is not necessary to turn the chamber to break communication while the tubes are idle, for the packing of the small diameter with asbestos prevents the absorption of moisture from the soda lime. The tubes must be used in pairs, so that one serves as a ture in weighing the other. A pair of tubes assures the operator of at least 140 combustions. A glass or rubber tubing about 12 ins. long serves as a guard for the absorption tube. It connects the bottle, P_1 , which is used to indicate flow of gas.

The use of elay boats has been abandoned in favor of nickel boats filled with alundum. These are greatly superior to elay boats in every conceivable way. The alundum is labeled as being free from carbon, but this is not true. In fact, some of it contains considerable carbon. It should always be burned in oxygen at 1000° before using. The boats are formed out of 22-gauge pure sheet nickel. One boat will serve for about 100 to 150 combustions, some more, some less.

Details of the Analysis. The furnace being at 1000° , the two freshly prepared absorption tubes are placed in the train and oxygen run through at the rate of 300 ee. per minute for fifteen minutes. This insures the displacement of all air from the purifying train as well as the absorption tubes. Remove one absorption tube from the train and turn on the oxygen until the mercury stands at about 2 ins. The rate of current is then measured by inverting a graduated cylinder filled with water. Several trials will establish a rate of about 325 ec. per minute. Note the reading of the column of mercury at this rate and subsequently, when using the same absorption tube, maintain this same pressure in the train and the rate of flow will be 325 ec., the rate during all combustions. Shut off the oxygen and, when it comes to a slow bubbling through P_1 , close the upper stopper of the absorption tube. Disconnect it from the train, but do not close the lower stopper for about five seconds after disconnection. Weigh against its mate as a tare. It is now ready for the first combustions.

Weigh 1.5 grams of drillings, preferably thin, curly drillings from a twist drill, and spread out in the nickel boat which is half filled with alundum. Place the absorption tube in the train and place its mate beside it. With the oxygen flowing about 100 cc. per minute, the drillings are pushed into the combustion tube. The current is immediately run up to the desired pressure, which gives 325 cc. per minute. The regulator will do the rest. It will feed the oxygen automatically to the burning steel. As a rule the drillings are entirely burned one and one-half minutes after insertion. Continue the flow of oxygen for three and one-half minutes more (five minutes, total time) and disconnect as before the absorption tube. Weigh immediately. The result will be accurate and reliable. Whether determining carbon in a standard steel, where the greatest accuracy is required, or in a bath test, the time required is always five minutes.

The weight of the boat, plus refractory lining, should be kept as low as possible, so as not to introduce too much cold material into the combustion tube. The boats used in this laboratory are $\frac{1}{2}$ in. wide, $\frac{1}{2}$ in. deep and 3 ins. long. Sheet nickel varies in percentage of carbon. As a rule, a nickel boat must be ignited in oxygen at 1000° for one to two hours.

There seems to be a difference of opinion concerning the physical condition of the steel after burning, some chemists believing that inaccurate results are obtained if the drillings have fused during combustion. Others maintain that complete fusion of the drillings is essential to accurate result. If drillings which happen to be a little thick are used, low results are obtained unless these are perfectly fused.

Graphitic Carbon

In Iron and Steel. The sample of 1 gram of pig iron or 10 grams of steel is treated with 15 ee. of nitrie acid (sp.gr. 1.2), per gram of sample taken. When all the iron has dissolved, the graphite is allowed to settle and the supernatant liquid decanted onto an ignited asbestos filter, using either a perforated boat, Fig. 17, or a filtering tube. The residue is transferred to the filter, and washed thoroughly with hot water. It is treated with hot eaustic solution (sp.gr., 1.1), washed thoroughly again with hot water, then with a little dilute hydrochloric acid, and finally with hot water. The carbon is now burned by one of the procedures given—the oxidation in the combustion

furnace being recommended. The CO₂ is absorbed in caustic and estimated according to the standard procedure given for carbon.



Fig. 17.—Boat and Holder for Carbon Determination.

 $CO_2 \times 0.2727$ = graphitic carbon.


The perforated boat, shown in the cut, fits snugly into the receptacle below. Sufficient asbestos is poured into the boat to form a film over the bottom. A seal is made around the boat with additional asbestos, the apparatus having been inserted in a rubber stopper in the neck of a suction flask and suction applied.

The apparatus is recommended by Blair for combustion of graphitic carbon or of total carbon liberated from iron or steel by the cupric potassium chloride method. The boat may be placed directly in the combustion tube and the carbon oxidized as usual.

The Shimer Combustion Apparatus 1

The apparatus, designed for the rapid determination of iron and steel, is in general applicable to the same class of chemical operations as is the com-

bustion tube of platinum, silica, or porcelain. It offers the advantage of neatness, reduction in the number of parts to be handled, diminished consumption of gas, and increased ease of manipulation. The simplified form, shown in the cut, Fig. 18, enables the use of the standard form of platinum crucible, A, with its inner wall ground to fit a tapered nickel, water-jacketed stopper, B. The rubber jacket of the original type is eliminated and a detachable nickel reinforcing ring, C, at the top of the erucible serves the double purpose of completing the security of the seal and as a support for the apparatus.



Water is circulated through the stopper through Fig. 18.—Shimer Combustion the tubes c and d. The current of oxygen passes Apparatus, Simplified Form.

through a into the crucible, oxidizing the material within the crucible, which is heated to red heat with a burner placed below it. The carbon dioxide formed passes through b to the absorption train. The remainder of the apparatus for the determination is the same as is used with the combustion tube. An asbestos shield protects the upper portion of the outfit, the crucible fitting snugly in a hole in the asbestos board.

Combined Carbon

Indirect Method. The excess of carbon remaining when the graphitic carbon is subtracted from total earbon (in iron and steel), is calculated as combined carbon. This difference method is generally accepted as being the most accurate for estimation of combined earbon.

¹ Courtesy of Baker Platinum Works.

Stetser and Norton Combustion Train for Carbon **Determinations**




Fig. 18a.—Stetser and Norton Combustion Train for Carbon Determinations.

- Assirator Bottle, 8 licers capacity, graduation interval 250 ml., with one hole rubber stopper.

 Bottle, narrow mouth, of green glass, 2 gallons capacity, with two hole rubber stopper
 Glass Tubing, 6 mm. outside diameter, for connections.

 Glass Tube, 3 mm. bore.

 Glass Stopcock, 2 mm. bore; used to prevent the gas from flowing through the train when turned on at the resultator.
- C
- on at the regulator.

 Bottle, wide mouth, 8 oz. capacity, with two hole rubber stopper; to be used empty as a safety.

 Ditto; to be filled one-third full with concentrated Sulphuric Acid.

 Ditto; to be filled with Ascarite.

 Combustion Tube, of Silica, glassed, 30 inches long by ¾ inch diameter.

 Combustion Tube Firmsce.

 Rheosatt, for controlling the temperature.

 Vanier Zinc Drying Tube; to be filled with 30 mesh Zinc.

 Vanier Sulphuric Acid Bolb; to be filled with Sulphuric Acid.

 Stetzer and Norton Modification of the Midvale Absorption Bulb.

Combustion Method

The train illustrated in Fig. 18a was described by J. B. Stetser and R. H. Norton in "Combustion Train for Carbon Determinations," The Iron Age, Vol. 102, No. 8. The special features of this outfit are rapidity with which combustions can be made, simplicity of the absorption bulb, and the use of Ascarite, a special sodium hydrate asbestos absorbent mixture according to the formula of Mr. J. B. Stetser. It is a dryer as well as an absorber.

The absorption bulb is a modification of the Midvale Absorption Bulb designed by Mr. H. L. Fevert, of the Midvale Steel Company, and with one

filling can be used for at least 400 determinations using one-half factor weight with carbon 0.50%. The bulb measures 45 mm. in diameter at its widest portion at the bottom, and 120 mm. high over all. It is provided with a eapillary tube and rubber stopper at top, or with ground glass stopper.

The usual procedure is to allow three or four minutes for combustion. Results are often reported in six minutes after the sample enters the laboratory: this includes time for drilling, weighing sample, running test, weighing bulb

and reporting result.

The oxygen is delivered from a high pressure cylinder through the gas pressure regulator, and the authors also recommend that bottles as shown in the illustration be used to measure the amount of gas consumed and to supply rapidly the extra quantity of oxygen required during the burning of the drillings, in addition to equalizing the pressure.

Method of Operation.—The train is set up free from leaks, and the stop-coeks are opened with the exception of the one on the Sulphuric Acid Bulb K. This is opened sufficient to allow gas to flow at the rate of 200 to 250 ml. per

minute when the Absorption Bulb is attached.

The stopcock C is then closed, the remaining stopcocks being left as adjusted. The train is now ready for operation. Bottle B is filled with water. The gas regulator is opened, allowing oxygen to displace the water in bottle B, which water is driven into bottle A. When bottle A is filled, the regulator is closed and the train is ready for combustion. The exit end of the combustion tube, the usual glazed silica tube being recommended, is packed with some asbestos burned in a current of oxygen prior to using.

A sample of one-half factor weight properly prepared and weighed is placed in the alundum boat, RR Alundum protection being used, and then inserted in the furnace. The stopcock C is opened, and if the furnace is at 1800° C. or over, and the sample of drillings fine and uncovered, it should begin to burn in 20 seconds. The burning should take 40 to 60 seconds additional, consuming 500 ml. of oxygen. An additional 500 ml. of oxygen is turned on to wash out all CO₂, and the bulb is then ready to be weighed.

If the sample is covered by a lid or RR Alundum, or if the drillings are coarse, or the furnace is below 1800° C., the combustion may be delayed as much as two minutes. The actual burning will, as before, take from 40 to 60 seconds. In any event, 500 ml. of gas must be passed through the apparatus after the steel has ceased burning. The point at which the burning of the sample begins may be determined by the increased rate at which gas passes through the liquid in bottle E, due to the rapid absorption of oxygen by the burning steel. A similar decrease marks the end of the burning period.

Standardization of the Stetser and Norton Absorption Bulb.—A freshly filled bulb should be run on the train for an hour and then weighed. When the bulb has reached a constant weight, the train is checked by running a government standard

A bulb once filled and standardized will last for several weeks and is sufficient for from three to four hundred determinations. On account of the difference in color between the used and unused portions of the absorbent, it is possible to determine the moment a bulb can be discarded.

Notes. In chromium, tungsten and titanium steels a temperature of 1500° C. is necessary to oxidize the carbon by direct combustion for thirty minutes. (J. R. Cain and H. E. Cleaves, J. Wash. Acad. Sci., 194, 4, 393–397.)

DETERMINATION OF CARBON IN ORGANIC SUBSTANCES

Combustion of Organic Substances Free of Nitrogen, Halogens, Sulphur, and the Metals

The following modification of the procedure described for determination of carbon in iron and steel is applicable to the determination of carbon in organic substances free from the substances mentioned above.

Apparatus. This is practically the same as that shown in Fig. 19, with the exceptions that copper plugs may be used to advantage in place of the platinum plugs. In the absorption end of the train a calcium chloride tube is preferred. The calcium chloride should have been saturated with dry CO₁ gas, the excess of which has been removed by a current of pure air. This tube




Fig. 19.—Diagrammatic Sketch of Combustion Tube.

is weighed as well as the potash bulb, the calcium chloride retaining the water formed by the combustion of the hydrogen of the organic substance, which is thus determined.

The organic substance, if a solid, is introduced into the combustion boat directly; if it is a liquid, it is held in a bulb blown in a capillary tube. One end of the tube is scaled and a bulb blown. When cool, the tube is weighed, and the material then introduced by first warming the bulb and then inserting the open end of the tube into the liquid to be examined. By cooling the bulb, liquid is drawn into the tube. The end is wiped off, and the liquid expelled from the capillary by gently heating this portion. The end is now sealed if the liquid is volatile, otherwise it is left open, and the tube is weighed. The increased weight is due to the organic substance. The tip of the capillary is now broken, if sealing was necessary, by means of a file. The tube containing the sample is placed in the boat, the open end of the capillary pointing toward the open end of the combustion tube. After connecting up the apparatus, the copper oxide end of the tube is heated to redness and oxygen slowly passed through the tube at such a rate that the bubbles in the potash bulb can be readily counted. The entire tube is now heated and remaining operation is the same as has been described for iron and steel combustion.

The gain of weight of the calcium chloride tube is due to water formed by the combustion of hydrogen of the compound, that of the potash bulb to the carbon.

 $H_2O \times 0.1121 = H$, $CO_2 \times 0.2727 = C$.

Carbon in Sails. One to 3 grams of 60-mesh sample is treated with a solution of 3.3 grams $\text{CrO}_3 + 10$ ec. H_2O and 50 ec. conc. H_2SO_4 (1.84). The evolved CO_2 is absorbed in standard caustic and titrated with acid, phenolphthalein and methyl orange being used as indicators. (J. Ind. Eng. Chem., 1914, 6, 843-846.)

NOTE. The oxygen gas should be free from hydrogen. A preheater, placed before the purifying tubes of the train, causes the combustion of the hydrogen and the absorption of the water formed before the gas enters the combustion tube.

Determination of Carbon and Hydrogen in Nitrogenous Substances

A modification of the first procedure described for determinations of carbon and hydrogen in organic substances must be made, since from substances containing nitrogen, nitroso and nitro compounds, oxides of nitrogen are formed which would be absorbed in the calcium chloride and potash bulbs, giving high results for hydrogen and carbon. To overcome this difficulty, a copper spiral, that has been reduced (See note below) is placed in the front end of the combustion tube (to the right in Fig. 19) to reduce the oxides of nitrogen to nitrogen.

Note. Reduction of copper spiral may be accomplished as follows: The copper spiral is prepared by rolling together a piece of copper gauze about 10 centimeters wide, making it as large as will conveniently pass into the combustion tube. The spiral is heated till it glows by holding it in a large gas flame, and while still hot it is dropped into a test-tube containing 1 or 2 cc. of methyl alcohol or ether. This quickly boils away, igniting at the end of the tube. The copper is completely reduced to bright metallic copper. The spiral is taken out with a pair of crueible tongs and dried by quickly passing it through a flame a few times, and while it is still warm it is introduced into the front of the combustion tube.

The substance is introduced into the tube and the connections made. The copper oxide spiral, that was pushed after the boat, is heated, and then the reduced spiral (right end of tube). The oxide near the boat, and finally the entire tube is heated to a red heat. When the bubbles cease to show in the potash bulb, the stopcock is opened to the oxygen-purifying train and a slow flow of oxygen turned on, the gas allowed to pass through the tube until it can be detected with a glowing splinter at the exit of the absorption end of the apparatus.

If the substance is difficult to burn, it is mixed with freshly ignited (cold) sopper oxide, which assists combustion.

The remainder of the operation is the same as has been described.

Organic Substances Containing Halogens

The procedure is the same as that described for nitrogenous substances with the exception that a silver spiral is used in place of the reduced copper spiral. The heating of this spiral should be between 180 and 200° C. (not over 200°).

Organic Substances Containing Sulphur

These are best ignited with sodium peroxide and the carbonate formed is determined by the procedure given for carbon dioxide in carbonates.

The Wet Combustion Process for Determination of Carbon

The method depends upon the oxidation of earbon to carbon dioxide when the powdered material is digested with a mixture of concentrated sulphuric acid and chromic acid, or potassium dichromate, or permanganate. The procedure is applicable to oxidation of free carbon, earbon combined in organic substances and in certain instances to carbon combined with metals, where the substance may be decomposed by the action of the acids.¹ It is of value in determination of carbonates in presence of sulphides, sulphites, thiosulphates and nitrites, which would vitiate results were they not oxidized to more stable forms, from passing into the potash bulb with the earbon dioxide.

Apparatus. The apparatus is identical with that used for determining carbon dioxide in carbonates, Fig. 20, with the exception that in place of the acid bulb nearest the decomposition flask two bulbs are placed. The first of these contains a strong solution of chromic and sulphuric acids, the second is filled with glass beads moistened with chromic acid solution. Following this is the drying bulb containing concentrated sulphuric acid and finally the

absorption apparatus, as shown in the illustration.

Procedure. 0.2 to 1 gram of the powdered material, fine drillings, free carbon, or organic substance is placed in the decomposition flask. If the material is apt to pack it is advisable to mix with it pure ignited sea-sand to prevent this. Five to 10 grams of granular potassium dichromate are added and the apparatus swept free of carbon dioxide by passing purified air through it before attaching the absorption apparatus. The potash bulb is now weighed, using a counterbalance bulb and following the precautions given in the drycombustion method. The bulb is attached to the train.

Oxidation. Concentrated sulphuric acid placed in the acid funnel, attached to the decomposition flask, is allowed to flow down on the sample until the funnel is almost empty; the stop-cock is then closed. A flame is placed under the flask, when the vigorous action has ceased, and the material gently heated until the reaction is complete and the organic matter or carbon completely oxidized.

The apparatus is now swept free of residual CO₂ by applying suction, the gas being completely absorbed by the potash, or the soda lime reagent.

The increase of weight of the absorption bulb is due to carbon dioxide.

$$CO_2 \times 0.2727 = C.$$

Note. The following additional purifiers are frequently advisable: (a) an absorption bulb containing silver sulphate to absorb chlorine and vapors from sulphur compounds; (b) a capillary tube of silica or platinum heated to a dull redness to oxidize any hydrocarbons, carbon monoxide, etc., that may be evolved and imperfectly oxidized by the chromic acid.

DETERMINATION OF CARBON DIOXIDE IN CARBONATES

The method is applicable for determination of carbon dioxide in limestone, dolomite, magnesite, strontianite, witherite, spatic iron ore, carbonates of sodium, and potassium, bicarbonates in baking powder, carbon in materials readily oxidized to CO₂ chronic sulphuric acid mixture. The procedure depends upon the evolution of carbon dioxide by a less volatile acid, or the oxidation of carbon. The CO₂ is absorbed in caustic and weighed.

Apparatus. The illustration shows the apparatus found suitable for this determination. It is Knorr's apparatus slightly modified. The absorption bulb or bottle should be one that will effectively absorb carbon dioxide entering

¹ Not applicable for determining carbon in ferro-silicon, ferro-chrome or tungsten steel.

at a rapid rate. The Vanier or the Fleming forms is satisfactory for this purpose.

Procedure. A sample weighing 0.5 to 2 grams, according to the carbon dioxide content, is placed in the dry decomposition flask (C). The flask is closed by inserting the funnel tube (B) fitted with the soda lime tube (A), and connected by means of a condenser to the train for removing impurities from carbon dioxide, leading to the absorption bulb, as shown in Fig. 20.




Fig. 20.—Apparatus for Determining Carbon Dioxide.

The apparatus is swept out with a current of dry, purified air before attaching the weighed absorption bottle. This is accomplished by applying gentle suction at the end of the purifying train. The absorption apparatus is now attached (Fleming absorption apparatus is shown in the illustration). The tube (B) is nearly filled with dilute sulphuric acid (1:3), the stop-cock (B') being closed. The soda lime tube is now inserted into place as shown in the cut. The acid in (B) is now allowed to run slowly down on the sample at a rate that evolves

gas not too rapidly to be absorbed; 1 to 2 cc. of acid being retained in (B) to act as a seal, the stop-cock (B') being then closed.

When the violent action has ceased, the solution in (C) is heated to boiling and boiled for about three minutes. If the sample is baking powder, or contains organic matter, the decomposition flask is protected from excessive heat by placing a casserole of hot water under it. This prevents charring of the starch or organic matter, which would be apt to occur if the direct flame was used. Gentle suction is now applied to the absorption end of the apparatus and the stop-cock (B') opened, allowing the remainder of the acid to flow into the flask (C) and admitting a current of air, purified by passing through the soda lime in The suction should be gentle at first, and then the speed of the flow increased to the full capacity of the absorption bottle. A fairly rapid current is preferred to the old-time procedure of bubbling the gas through the apparatus at a snail-like pace, but discretion should be used in avoiding a too rapid flow.

In the analysis of baking powders, where foaming is and to occur, the decomposition flask should be of sufficient capacity to prevent foaming over. A small flask is generally to be preferred for obvious reasons. By gently heating to boiling during the passage of the air, steam assists in expelling any residual CO, in the flask. When the passage of air is rapid, this boiling should be dis-

The increase of weight of the absorption bottle is due to the earbon dioxide of the sample. This procedure gives total CO2.

Determination of Carbon Dioxide by Measuring the Gas

Fairly accurate results may be obtained by measuring the gas evolved. A large cylindrical tube having a capacity of about 1100 ec. is used. The tube is graduated from 1000 cc. to 0 at the upper portion of the cylinder; a space of about 100 cc. remains at the upper portion. A tube extending from a little above the 0 graduation to the bottom of the cylinder carries out the water as the gas is admitted.

To make the run, the eylinder is filled to the mark 0 with saturated salt solution.1 It is now connected to a condenser.2 Twenty-five cc. of saturated salt solution are admitted to the decomposition flask, and the generated gas measured by the water displacement in the tube described. Calculations are made after reduction to standard conditions. 5.1 ee. CO2 at 0° C. and 760 mm, weigh 0.01 gram.

Residual Carbon Dioxide

This is the CO2 remaining after baking powder has been treated with water and the evolved CO2 expelled by warming.

The procedure recommended by the U. S. Department of Agriculture is as follows:

¹ H. W. Brubacker, Jour. Ind. Eng. Chem., 1915, 7, 432. ² The nitrometer may be used in place of the cylinder and atmospheric conditions obtained as usual. Formula for reduction to 760 millimeters and 0° C.:

$$V' = V \frac{(P-w)}{760(1+.00367t)}.$$

^{*}Bureau of Chem. Bulletin No. 107.

Weigh 2 grams of baking powder into a flask suitable for the subsequent determination of earbonic acid, add 20 ec. of cold water, and allow to stand twenty minutes. Place the flask in a metal drying cell surrounded by boiling water and heat, with occasional shaking, for twenty minutes.

To complete the reaction and drive off the last traces of gas from the semisolid mass, heat quickly to boiling and boil for one minute. Aspirate until the air in the flask is thoroughly changed, and determine the residual earbon dioxide

by absorption, as described under total carbonic acid.


The process described, based on the methods of McGill and Catlin, imitate, as far as practicable, the conditions encountered in baking, but in such a manner that concordant results may be readily obtained on the same sample, and comparable results on different samples.

Available Carbon Dioxide

The residual is subtracted from the total, and the difference taken as available CO₂.

Determination of Carbon Dioxide by Loss of Weight

An approximate estimation of the carbon dioxide in carbonates—baking powders, bicarbonate of soda, limestone, etc., may be obtained by the loss of weight of the material when treated with a known weight of acid.








Fig. 22.-Mohr's Alkalimeter.

Various forms of apparatus are used for this determination. The Schroetter and Mohr types are shown, Figs. 21 and 22.

About 0.5 to 1.0 gram of sample is taken and placed in the bottom of the flask, dilute hydrochloric and strong sulphuric acids then placed in the bulbs as indicated in the illustrations. The apparatus is weighed as it is thus charged. The hydrochloric acid is now allowed to flow down on the carbonate and the stopper closed. The evolved gas passes through the strong sulphuric acid, which absorbs the moisture. After the vigorous action has subsided the apparameters are the strong sulphuric acid,

ratus is placed over a low flame and the solution heated to boiling and boiled very gently for about three minutes. CO_1 -free air is aspirated through the solution to expel the last traces of CO_1 , by applying gentle suction at a and opening b, the air being purified by passing through soda lime. The apparatus is again weighed and the loss of weight taken as the CO_1 of the material.

Available CO, in baking powder may be determined by substituting water


in place of hydrochloric acid.

Determination of CO₂ in Carbonates — Hydrometer Method of Barker¹

No mechanical balance or scale is required by the following procedure.

The method depends upon the principle of the hydrometer, following the law that when an object is immersed in a liquid it is buoyed up by a force equal to the weight of the liquid displaced by the object. The earbon dioxide set free from the sample decreases the weight; and the rise of the graduation scale tube above the water records the percentage of carbonates from which the gas was released. The procedure is suitable for determining the comparative strengths of baking powders, for rapid tests of the quality of limestone and for estimation of earbon dioxide of earbonates in general.

Procedure. To analyze a sample for earbonates measure out 40 ee. of hydrochloric acid (sp.gr. 1.15), using a small graduate; pour this into the acid reservoir through the opening A. With graduated stem disconnected hang a 10 grain weight at B. The hydrometer should then float in a cylinder of water and be immersed to some point at C. Remove the 10 gram weight and introduce pulverized limestone, or other substance that is being tested, until the instrument is immersed to exactly the same point that it occupied with the suspended weight. The reservoir will now contain 10 grams of sample. Connect up the graduated stem and add water, a drop at a time, through the funnel-shaped top, until immersed to the zero point. Raise the hydrometer out of the water and open the stopcock D until the acid drops slowly into the reaction chamber, decomposing the earbonate. As the reaction proceeds the instrument rises slowly and at the conclusion the point on stem at the surface of the water gives the per



F10. 22a.—Barker's Hydrometer.

J. F. Barker, Jour. Ind. Eng. Chem., IX, 8, 786-787 (1917).

cent of calcium carbonate equivalent to the carbon dioxide in the sample. This figure is the calcium carbonate equivalent so often mentioned in connection with limestone analyses.

A Fahrenheit thermometer accompanies each instrument and is hung inside the floating cylinder. Its reading is taken before and after each determination to allow for any error due to change in temperature. To the figure for calcium earbonate equivalent add 0.5 for each degree rise, or subtract 0.5 for each degree fall in temperature between the two readings. This temperature change need seldom amount to more than a fraction of a degree.

Notes. The limestone may be weighed to an accuracy of 0.02 gram. The weight of CO₂ remaining in the apparatus tends to offset the loss due to moisture escaping with the gas, but the difference, together with any other sources of error has been accounted for in the graduation of the reading stem.

Determination of Percarbonates

Percarbonates are decomposed by dilute sulphuric acid according to the reaction $K_2C_7O_4+2iI_2SO_4=2KHSO_4+2CO_2+H_2O_3$. Procedure. Two tenths of a gram of the sait is added to about 300 ec. of cold dilute

Procedure. Two tenths of a gram of the sait is added to about 300 ec. of cold dilute sulphuric acid (1:30). The liberated hydrogen peroxide is titrated with potassium permanganate.

1 cc. N/10 KMnO₄=0.00991 g. $K_2C_2O_6$.

VOLUMETRIC METHODS FOR THE DETERMINATION OF CARBON

Total Carbon. Absorption of Carbon Dioxide in Barium Hydroxide

The carbon dioxide evolved by oxidation of the material by dry combustion with oxygen or by oxidation with chromic sulphuric acid mixture is absorbed in barium hydroxide, free from carbonate, and the precipitated barium carbonate titrated with standard hydrochloric acid.

Procedure. The essential difference in this method from those already described under the gravimetric methods is in the fact that a perfectly clear saturated solution of barium hydroxide is used for absorption of the carbon dioxide in place of eaustic potash. Considerable care must be exercised to prevent contaminating the reagent with carbonate. The solution is drawn by suction through a siphon, dipping below the surface of the reagent, into the absorption tube, which should be of such construction that the inaterial may readily be poured out. Details of the procedure are given in the chapter on Iron and Steel, Volume II, under carbon determination. The precipitate barium carbonate is filtered off and washed by a special procedure, and then titrated with standard hydrochloric acid.

1 cc. 0.1 N HCl=0.0006 g.

Determination of Carbon by Measurement of the Volume of Carbon Dioxide Evolved by Oxidation of Carbon, or by the Decomposition of Carbonates with Acid.

Description of the Scheibler and Dietrich Process and that of Lunge and Marchlewski are given in Mellor's work on "Inorganic Analysis," pp. 555-559, 1st Ed. A modification of Wiborg's method is described in Blair, "Chemical Analysis of Iron," pp. 146-149, 7th Ed.

Determination of Carbon Dioxide in a Gas Mixture.

See Gas Analysis.

Direct Colorimetric Method for Determination of Combined Carbon

The procedure is of value to the steel laboratory where a large number of daily determinations of combined carbon are required. By this method over a hundred determinations a day may be made by an experienced manipulator. The method depends upon the color produced by combined carbon dissolved in nitric acid, the depth of color increasing with the combined carbon content of the material. Comparison is made with a standard sample of iron or steel, which is of the same kind and in the same physical condition as the material tested. That is to say, a Bessemer steel should be compared with a Bessemer standard, open hearth with open hearth, crucible steel with crucible steel, the standards containing approximately the same amounts of carbon, and as nearly as possible the same chemical composition. The samples should be taken from the original bar which has not been reheated, hammered, or rolled. Copper,






Fig. 23. Fig. 24.

Hot Water Racks for Test Tubes. Color Carbon Determination.

cobalt, and chromium will interfere with the test; the other elements have very little effect.

Procedure. One standard sample of 0.2 gram and the same amount of sample drillings are taken for analysis. The weighings are conveniently made in brass or aluminum pans, boat-shaped to enable the drillings to be dumped into test-tubes. A counterpoise, weighing the same as the boat, is placed on the opposite pan, together with the 0.2 gram weight. A magnetized knife will assist in removing the excess of material. The weighed sample is brushed into a test-tube 6 ins. long (150 mm.) § in. (16 mm.) in diameter. (Each test-tube has a label near the open end to distinguish the sample.) A rack or a 600-cc. beaker may be employed for holding the test-tubes during the weighing. After the batch is ready the tubes are transferred to a perforated rack (Figs. 23 or 24) and this then stood in the water bath filled with cold water.

The proper amount of nitric acid (sp.gr. 1.2; e.g., 1 eonc. $HNO_a:1\ H_2O)_a$ from a burette, is now added to each test-tube.

3 ec. HNO, for 0.3% C.

6 cc. HNO, for 0.8 to 1% C.

4 ec. HNO₁ for 0.3 to 0.5%.

7 cc. HNO, for over 1% C. steel.

5 cc. HNO, for 0.5 to 0.8% C.

1 Blair, "The Chemical Analysis of Iron."

The depth of color produced by the acid will give an idea of the amount required. One cc. of acid is added at a time until the depth of color is correct. This requires experience gained from observation of the color produced by standard samples. The acid is added slowly to the coarse drillings. Insufficient acid gives a darker tinted solution than it properly should be. The nitric acid should be free from chlorine and hydrochloric acid, since these produce a yellow color. (Cl and FeCl₂ are yellow.)

A glass bulb or a small funnel is placed in each test-tube and the water in the bath then heated to boiling and boiled until all the carbonaceous matter has dissolved, the tubes being shaken from time to time to prevent formation of a film of oxide. Low-carbon steels require about twenty minutes, whereas steels of over 1% carbon require about forty-five minutes. (Blair.) As soon as the bubbles cease and the brownish flocculent matter disappears, the rack is removed from the bath and placed in a casserole of cold water. (Prolonged heating and strong light each causes fading of the color due to combined carbon.)




Fig. 25.—Carbon Tubes.

Fig. 26.—Color Comparator or Camera.

Color Comparison. This is made in graduated, clear, colorless, glass cylinders called carbon tubes. The form shown in Fig. 25 was found by the writer 1 to be the most satisfactory type for a steel-works laboratory where rapidity of manipulation was essential. The bend at the upper portion of the tube facilitates mixing of the solution upon dilution with water, the tube being tilted back and forth until the solution is homogeneous, the bend preventing the liquid from spilling. The dilution should be at least twice that of the amount of nitric acid used, as this amount of water is necessary to destroy the color due to ferric nitrate.

The standard is poured into the carbon tube and the rinsings from the test-tube added. The solution is diluted to a convenient multiple in cc. of the carbon content. For example, 0.45% carbon sample may be diluted to 9 cc., then each cc. will represent 0.05% carbon. The sample is placed in a second tube of exactly the same diameter, wall thickness, and form. If the solution of the sample is darker than the standard, water is added little by little,

followed by mixing, until the shade matches the standard. If the standard, on the other hand, is darker than the sample, a greater dilution of the standard is necessary, the cc. again representing a multiple of the earbon content. For example dilution of the .45% carbon sample to 15 cc. makes each cc. to represent 0.03 carbon. (It is frequently advisable to take a standard of lower carbon content in place of greater dilution of the standard.)

Example. Suppose in the first ease the dilution of the sample was 15 ee. in order to match the standard, then $15 \times 0.05 = 0.75\%$ carbon. Six cc. dilution

case $2 = 6 \times 0.03 = 0.18\%$ carbon.

The color comparison can be best made in a "camera," a long box with one end closed by a ground-glass screen, Fig. 26. Parallel to the screen and near it, two holes through the top of the box admit the test-tubes. The inner walls of the camera are blackened to prevent reflection of light. If a camera is not available, the tubes may be held side by side and compared against a sheet of white paper held as a background.

CARBON DETERMINATION IN STEEL

Beneker's Modification of Eggertz's Method for Determining Carbon in Steel

By this procedure interference of the color due to iron is eliminated.

.2 g. of the sample and standard (which does not need to be very similar in earbon content to the sample) are weighed into two test tubes, treated with .7 ce. — 10 cc. of nitric acid of the usual dilution, say 3 parts water to 2 parts acid, and warmed until dissolved and perfectly clear. When cold, ½ cc. of 85% phosphoric acid is added to each tube, transferred to the comparison tubes and read. When this method is used on low carbon steel the bleaching action is very pronounced, because in that case the iron color bleached out represents the major part of the original color. Dilution of standard or sample introduces no error, because of the absence of the interfering iron color.

ANALYSIS OF GRAPHITE

Determination of Carbon

The procedure for determining earbon in graphite is the same as that described for determination of earbon in difficultly combustible organic substances.

The material is broken down in a steel mortar and powdered in an agate mortar. About 0.2 gram is taken for the determination and mixed with copper oxide to assist the combustion, then placed in the boat and the combustion of the carbon carried on according to the standard method in the combustion tube.

 $CO_1 \times 0.2727 = C$.

CYANOGEN

DETECTION

Traces of Hydrocyanic Acid. To the solution to be tested are added two drops of 10% NaOH and the mixture is evaporated to near dryness. After cooling, a drop of 2% ferrous sulphate is added and the sample allowed to stand in the cold for about fifteen minutes. Now 2-3 drops of strong HCl are added and the solution warmed gently, then cooled. The solution is a blue green if HCN was present in the original sample. 0.000002 g. HCN may be detected.

Note. Test for Cyanide. This depends upon the solvent action of HCN upon freshly precipitated HgO in presence of KOH. The filtrate is tested for mercury in an acid solution by addition of HsS. (Hood.)

VOLUMETRIC DETERMINATION OF HYDROCYANIC ACID¹

The method depends upon the decolorization of the blue ammoniacal solutions of cupric salts by a soluble cyanide, the reduction to cuprous condition being available for an accurate quantitative estimation of the eyanide.

Standard Copper Sulphate. Twenty-five grams of copper sulphate, CuSO₄·5H₂O are dissolved in a 1000-cc. flask with 500 cc. of distilled water and ammonium hydroxide added until the precipitate that first forms dissolves and a deep blue solution is obtained. Water is now added to make the volume exactly 1000 cc. The cupric solution is standardized by running a portion into a solution containing 0.5 gram pure potassium cyanide, KCN, per 100 cc. of water and 5 cc. of ammonium hydroxide until a faint blue color is evident. Chlorides do not interfere.

Procedure. 0.5 gram of the soluble cyanide is dissolved in 100 cc. of water and 5 cc. strong amnionium hydroxide added. The standard cupric sulphate solution is now added until the blue color is obtained. The cc. required multiplied by the factor of the copper salt in terms of the salt sought gives the weight of that salt in the sample.

Liebig's Method for Determination of Hydrocyanic Acid. Soluble Cyanides ²

Silver nitrate reacts with an alkali cyanide in neutral or alkaline solution as follows: AgNO₂+2KCN =Ag(CN)₂K+KNO₂. The potassium silver eyanide is soluble, hence the precipitate that first forms immediately dissolves on stirring as long as the cyanide is present in excess or in sufficient quantity to react according to the equation. A drop of the silver salt in excess will produce a permanent turbidity, owing to the following reaction:

Ag(CN), K-AgNO, = 2AgCN+KNO, the insoluble AgCN being formed.

¹ J. McDowell, C. N., 1904, p. 221. ² Ann. d. Chem. und Pharm., 77, p. 102. Procedure. The alkali eyanide contained in a beaker placed over a sheet of black glazed paper, is treated with 4 to 5 cc. of 10% KOH solution and diluted to 100 cc. The liquid is now titrated with standard silver nitrate, with constant stirring, until a faint permanent turbidity is obtained.

One ec. $N/10 \text{ AgNO}_1 = 0.013022 \text{ gram KCN}$.

Determination of Cyanide by Volhard's Method

The method involves Vollhard's method for determining halogens, the procedure depending upon the fact that the silver salts of eyanides are insoluble in dilute cold nitric acid solutions.

The neutral cyanide solution is treated with an excess of silver nitrate reagent, and slightly acidified with nitrie acid and diluted to a definite volume in a measuring flask. A portion of the solution is now filtered through a dry filter, and a convenient aliquot portion of this is titrated with standard thiocyanate solution, using ferric alum as indicator (see page 149) to determine the silver nitrate present. From this titrate the excess silver nitrate reagent added and that combined with the cyanide ascertained.

1 cc. $N/10 \text{ AgNO}_3 = 0.006511 \text{ g. KCN or } 0.002601 \text{ g. CN.}$

Determination of Cyanide and Thiocyanate in Presence of One Another

The cyanide is determined preferably by Liebig's method, page 131 and the cc. of AgNO₃ required recorded. To the alkaline or neutral solution is added an excess of standard AgNO₃ and the solution acidified with HNO₃, then made to definite volume and a portion filtered. The silver nitrate in a convenient amount of the filtrate, an aliquot portion of the whole, is determined by titrating with standard thiocyanate solution, using ferric alum indicator (page 149). From this titration the excess of AgNO₃ added is determined, and the amount of reagent required for the thiocyanate is known.

1 cc. $N/10 \text{ AgNO}_3 = 0.006511 \text{ g. KCN}$ or 0.002601 g. CN or 0.005808 g. CNS.

In place of the above method the following may be used: One portion of the solution is treated with nitrie acid and the thiocyanic acid oxidized to sulphate. By adding Ba(NO₃)₂ solution BaSO₄ is precipitated and the equivalent thiocyanic acid calculated, also the equivalent N/10 AgNO₃ that would be required to precipitate this. In another portion an excess of N/10 AgNO₃ is added and the thiocyanate and cyanide precipitated. The excess of the silver nitrate may now be determined by Vollard's method described above and the amount required by CN and CNS thus ascertained. The amount of reagent required for CNS is subtracted from this total and that required by CN thus obtained. The factors are given above.

For determination of cyanide in presence of the halogens see the chapter on chlorine, page 154.

COMPLEX COMPOUNDS—FERRO AND FERRI CYANIDES

Hydroferrocyanic Acid

On gram of the hydroferrocyanide in 100 cc. of water acidified with 10 cc of sulphuric acid is titrated in a casserole with standard potassium permanganate to a permanent pink color. The end-point is poor, so that it is advisable to standardize the permanganate against pure potassium ferrocyanide.

Reaction: $2H_4Fe(CN)_6+O=H_2O+2H_2Fe(CN)_6$


One ec. N KMnO₄=0.3683 gram K₄Fc(CN)₆

Hydroferricyanic Acid

Ten grams of hydroferricyanide are dissolved in water, the solution made alkaline with KOH and heated to boiling and an excess of ferrous sulphate solution added. The yellowish brown ferrid hydroxide turns black with excess of ferrous salt. The solution is diluted to exactly 500 ec. and 50 ec. of a filtered portion titrated with potassium permangate.

One cc. N KMnO₄=.3292 gram K₃Fc(CN)₆.

The illustration below shows a convenient form of cabinet for electrolytic determinations. The eabinet can be obtained from the Denver Fire Clay Co., Denver, or from Braun Corporation, Los Angeles. The anode may be rotated or left stationary as desired.



F10. 26a'. Electrolytic Analysis Cabinet.

In the determination of copper in alloys, 0.5 g. alloy is dissolved in 10 ec. HNO₁ in a 250 ce. beaker, the solution diluted to 100 ee. is treated with 5 ee. $\rm H_2SO_4$ and electrolyzed at $\rm 1\frac{1}{2}$ –2 amperes. Do not use greater current. 0.2 g. Cu deposits readily in 1 hour with the rotating anode. Turn switch, after washing the deposit with water and alcohol, to "Off" position, otherwise the current will be broken through remaining units. Each unit has its own switch.

In determining copper in ores, iron is removed by precipitation with $NH_4OH.(30\%$ Fe carries down 0.3% Cu on 0.5 g. sample), lead is removed as sulphate and the filtrate electrolyzed for copper.

Copper is removed from the electrode by means of HNO₃.

Fig. 26a' by courtesy of the Denver Fire Clay Company.

CERIUM AND THE OTHER RARE-EARTH METALS

Atomic num- ber	Name	Sym- bol	Atomic weight	Colour of sesquioxide	Absorption spectrum	Solubility of double sodium sulphates
57 58 59 60 61 62	Lanthanum Cerium Praseo- dymium Neodymium Samarium	La Ce Pr Nd	139.0 140.25 140.9 144.3 	White White Greenish- yellow Lilac	None None Strong Strong	Cerium group: Double sodium sul- phates insoluble in saturated sodium sulphate solution.
63 64 65	Europium Gadolinium Terbium	Eu Gd Tb	152.0 157.3 159.2	Pale pink White White	Faint In the Ultra- violet	Terbium group: Double sodium sulphates sparingly soluble in saturated sodium sulphate solution.
39 66 67 68 69 70	Yttrium Dysprosium Holmium Erbium Thulium Ytterbium Lutecium	Y Dy Ho Er Tm Yb Lu	88.7 162.5 163.5 167.7 168.5 173.5 175.0	White White Pale yellow Itose White White	None Strong Strong Strong Moderate None	Yttrium group: Double sodum sulphates readily soluble in saturated sodium sulphate solution.

All the metals in the above list have now been characterised with certainty as elements. The results of X-ray analyses of the elements indicate that another rare-earth metal, and only one, of atomic number 61, still remains to be discovered. Element 72 or celtium, discovered by Urbain in 1911, is not a rare-earth element but an analogue of zirconium; it appears that Coster and Hevesy's hafnium (1923) is identical with celtium. When a mixture of prascodymium and neodymium is referred to, the old term didymium (symbol Di) is often used for the sake of brevity.

Only a few of the rare-earth metals have so far been prepared in the pure state, but an alloy of the cerium metals, prepared from the oxides which form a hy-product in the extraction of thoria from monazite, is used under the name of Mischmetall as a reducing agent for preparing a number of metals from their oxides. Cerium (and, to a very limited extent, didymium) nitrate is used in the gas-mantle industry. Cerium or Mischmetall forms the basis of the pyrophoric alloys for cigarette and gas lighters. Cerium glass (Crookes'

W. R. Schoeller, Ph.D., and A. R. Powell. Metallurgical chemists, London, England. glass) containing ceria and various other oxides, whilst transparent to light rays, intercepts the ultra-violet and a large proportion of the heat rays. A small quantity of yttria is consumed in the manufacture of filaments for Nernst lamps. To a limited extent, cerium compounds are employed in medicine; they have been proposed for use as catalysts, in dyeing, tanning and photography.

TABLE OF THE MORE IMPORTANT RARE-EARTHS MINERALS

Name	Composition	Solvent	
Cadolinita	Phosphate of the yttria earths.	H ₂ SO ₄ H ₂ SO ₄ HCl or H ₂ SO ₄	
Cerite	Hydrated silicate of ceria earths, lime and ferrous oxide.	HCl or H ₂ SO ₄	
Euxenite/Polycrase	vttria) containing uranium.	NaHSO ₄ or HF	
Samarskite	. Columbate of the yttria earths, lime and ferrous oxide, containing uranium.	NaHSO4 or HF	
Yttrotantalite	. Tantalate of yttria, lime and ferrous oxide.	NaHSO ₄ or HF	

The only mineral of considerable commercial importance is monazite; this is due, not to its content of rare earths, but of thoria, monazite forming the raw material for the gas-mantle industry. Ceria and the other earths of the cerium sub-group are obtained in large quantities as by-products in the extraction of thoria from monazite. Yttria is extracted from gadolinite.

QUALITATIVE ANALYSIS

Detection of the Rare Earths in the Systematic Procedure for Qualitative Analysis. The rare earths are precipitated as hydroxides by ammonia and are therefore found, together with alumina, ferrie hydroxide, etc., in the precipitate obtained in the ordinary course of analysis. The precipitate is dissolved in hydrochloric acid and the solution evaporated to dryness or carefully neutralised with ammonia. In the former ease the residue is dissolved in 150 ee. of dilute hydrochlorie acid (30 ec. of strong acid per litre) and the solution, warmed to 60° C., treated with 30 ce. of saturated oxalic acid solution. A white crystalline precipitate, obtained either at once or, in the ease of small quantities, after standing over night in a warm place, consists of the oxalates of some or all of the following oxides: the rare earths, thoria, and scandia. The washed oxalate precipitate is brought into solution by digestion with fuming nitric acid of sp. gr. 1.5 and subsequent evaporation to dryness; the residue of nitrates is converted into chlorides by the usual evaporation to dryness with hydrochloric acid. The chlorides are dissolved in water and the solution boiled with sodium thiosulphate: thoria and seandia are precipitated. The filtered solution is treated with excess of ammonia: a white floeeulent precipitate, which discolors on exposure to air if cerium is present, indicates the presence of the rare carths.

For further characterisation the precipitate is collected, washed with hot

water, dissolved in hydroehlorie acid, and the solution saturated with solid sodium sulphate: if a white crystalline precipitate forms, the cerium group is present. The filtrate is again treated with ammonia when the earths of the yttrium group are precipitated as hydroxides. The metals of the terbium group are found in both fractions.

The double sulphate precipitate of the cerium metals may be treated as follows: it is converted into hydroxides by digestion with caustie soda and the washed precipitate is dissolved in dilute nitric acid. The solution is boiled with potassium bromate and lump marble by which procedure the cerous nitrate is oxidised to cerie salt which is then hydrolysed with precipitation of a yellow basic salt whilst the nitrates of the other rare earths remain unchanged. The cerium precipitate is filtered off and dissolved in strong nitric acid; the solution, on addition of citric acid, ammonia, and hydrogen peroxide, gives a yellow to brown coloration characteristic of cerium. The filtrate from the cerium precipitate is treated with ammonia, the precipitate dissolved in nitric acid and the liquid evaporated to dryness: the dry residue is heated to 450° C, for half a minute, the cooled mass extracted with water and the liquid filtered. The more basic lanthanum is chiefly in the filtrate, the less basic didymium in the residue. Lanthanum is characterised by addition of a few drops of acetic acid, iodine solution in potassium iodide, and ammonia, drop by drop until the brown color of the iodine nearly disappears; a blue color, appearing on gentle warming, indicates lanthanum. The residue of basic didymium nitrate is ignited: the brown color of the resulting oxides, due to a higher oxide of praseodymium, proves that metal to be present; it is invariably associated with neodymium.

The precipitate of hydroxides of the yttria group, obtained above, may be dissolved in nitrie acid and the solution tested for its absorption spectrum (erbia, etc.). Yttria is by far the most common earth of this group.

Detection of Cerium. If it is desired to prove the presence of cerium only, the procedure is the same as that outlined above up to the point where the ammonia precipitate of rare-earth hydroxides has been obtained in the filtrate from the thoria-scandia precipitation by thiosulphate. The ammonia precipitate is collected, washed, and dissolved in nitric acid with a little hydrogen peroxide, if necessary. The solution is taken to dryness and the residue dissolved in water. Cerium is detected in this solution in the presence of the other rare earths by colour reactions based on oxidation to the ceric state:

- 1. Boiling with lead peroxide and nitric acid causes the appearance of a deep yellow color.
- 2. The solution is treated with tartarie acid, made ammoniacal, and boiled with a few cc. of hydrogen peroxide: a dark brown coloration develops.
- 3. Ammonium acetate and hydrogen peroxide produce a yellow precipitate or colour.
- 4. In the presence of large quantities of the other rare earths a precipitate rich in cerium may be obtained by addition of hydrogen peroxide to the solution, followed by ammonia added drop by drop until a slight permanent precipitate forms: cerium will be concentrated in the precipitate, the colour of which will be orange to reddish-brown.

QUANTITATIVE ANALYSIS

Decomposition of Minerals. Concentrated sulphuric acid is the most generally applicable solvent; it can be used for practically all rare-earth minerals except those containing tantalic, columbic and titanic acids, which are best decomposed by fusion with sodium bisulphate (pyrosulphate). When the mass resulting from the decomposition by sulphuric acid is dissolved in water, it should be borne in mind that the sulphates of the rare-earth metals, whilst soluble in cold water, yield sparingly soluble compounds at higher temperatures; care should therefore be taken in keeping the temperature of the solution below 20° C. The use of icc-cold water is recommended as this counteracts the rise in temperature resulting from the hydration of the strong acid; alternatively the cold pasty mass is simply stirred into a large excess of cold water. Again, the double sulphates of the cerium group and potassium arc more insoluble than the corresponding sodium salts; sodium bisulphate is therefore to be preferred to the potassium salt as a flux. If the sodium bisulphate melt begins to solidify before decomposition is complete, it is allowed to cool somewhat and treated with 1 cc. of strong sulphuric acid; on renewed heating the bisulphate is regenerated. In the case of decomposition by hydrofluoric acid, the rare carths are obtained as a residue of insoluble fluorides which must be converted into sulphates by evaporation with strong sulphuric acid. Cerite and gadolinite are silicates decomposable by hydrochloric or sulphuric acid.

SEPARATIONS

1. Separation of the Rare Earths (and Thoria) from Other Metals. The oxalate precipitation outlined under "Qualitative Analysis" is also a quantitative method for separating the rare earths from base metals of the ammonia precipitate. The chloride solution of the ammonia precipitate, if acid, is evaporated to dryness and the residue dissolved in 0.3N hydrochoric acid so that the concentration of the oxides present is less than 1 gram per 60 cc. The solution is warmed and precipitated with a saturated solution of oxalic acid so that the final solution contains 3 grams of free acid per 100 cc. The oxalate precipitate, which is flocculent at first, soon becomes crystalline; it is allowed to stand over night in a warm place, filtered off, and washed with a 1% solution of oxalic acid. If the base metals are present in fairly large quantity, it is best to repeat the precipitation: the oxalates are digested with caustic soda, the hydroxides filtered off, washed and dissolved in nitric acid; the solution is evaporated to dryness and the residue treated as before. The solubility of the oxalates of the rare earths in water is of the order of 0.4 to 1 milligram of anhydrous oxalate per litre. They are more soluble in dilute mineral acids, but the solubility is reduced by the presence of free oxalic acid.

Another method of separating the rare earths and thoria from base metals of the ammonia group consists in precipitating them as fluorides from a weakly acid chloride solution. This method is less reliable and convenient than the oxalate precipitation.

2. Separation of the Rare Earths from Thoria. The oxalate precipitate obtained as just described is digested with fuming nitric acid and the solution evaporated to dryness. The mass is moistened with water and dried again; it is then dissolved in 100 cc. of water, 10 grams of ammonium nitrate are

added, the solution is heated to 60° C., and the thorium precipitated by addition of 20 cc. of hydrogen peroxide. The gelatinous precipitate is collected, washed with 2% ammonium nitrate solution, and dissolved in nitrie acid. The solution is evaporated to dryness and the precipitation of the thorium repeated as before. The combined filtrates, which contain the rare earths, are treated with ammonia and the washed precipitate is redissolved in nitric acid; the solution is then ready for the separation of cerium from the other earths by one of the following methods.

3. Separation of Cerium from the Rare Earth Metals. The methods for the quantitative separation of ceria from the other earths are based on the fact that cerium alone can be oxidised to the quadrivalent ceric state, and

ceric hydroxide being a weak base, its salts are easily hydrolysed.

(a) James and Pratt's method (Jour. Amer. Chem. Soc., 1911, 33, 1326) consists in boiling the neutral nitrate solution with potassium bromate. As soon as bromine vapours begin to be evolved two or three small lumps of marble are added to the solution which is boiled for some hours, water being added from time to time to replace that lost by evaporation. When a qualitative test by hydrogen peroxide in a small part of the filtered solution shows only a trace of cerium, the boiling is interrupted and the marble removed and washed. The precipitate is left to settle, filtered off, and washed with a 5% solution of ammonium nitrate. For very accurate work the precipitate is dissolved in nitric acid with the help of a little hydrogen peroxide, the solution evaporated to dryness and the whole process repeated. The combined filtrates containing the rare earths and a trace of cerium are boiled with more bromate and marble until the peroxide test for cerium is negative. The small precipitate so obtained requires purification by reprecipitation.

(b) In Brinton and James' method (Jour. Amer. Chem. Soc., 1919, 41, 1080) the cerium is oxidised by means of potassium bromate and the metal in its quadrivalent state precipitated as iodate. The cold solution of the rareearth nitrates (50 cc.) containing not more than 0.15 gram of ceria is treated with 25 cc. of strong nitric acid and 0.5 gram of potassium bromate. This is followed by 10 to 15 times the quantity of potassium iodate (in the form of a solution containing 100 grams of iodate and 333 cc. of strong nitric acid per litre) required to precipitate ceric iodate Ce(IO4)4, added slowly with constant stirring. The bulky flocculent precipitate is left to settle in the cold and filtered off; the beaker and precipitate are washed once with a solution containing 8 grams of potassium iodate and 50 cc. of strong nitric acid per litre and the precipitate is rinsed back into the beaker, thoroughly stirred up with 50 cc. of the washing solution, and again filtered on the same paper. The precipitate is once more returned to the beaker with hot water and dissolved by boiling with not more than the necessary amount of strong nitric acid (20 to 25 cc.). The solution is again treated with potassium bromate (0.25gram) and the same amount of potassium iodate as for the first precipitation. The precipitate is left to settle completely, filtered off on the paper previously used, returned to the beaker and stirred up with 50 cc. of washing solution, and finally washed several times on the filter with the same solution. Filter and precipitate are then boiled in the original beaker with 5 to 8 grams of oxalic acid and 50 cc. of water until iodine vapours cease to be evolved. After standing for several hours the cerous oxalate is collected, washed with cold water, ignited strongly in a platinum crucible and weighed as CeO₂.

ESTIMATION OF CERIUM

1. Gravimetric. In technical practice cerium is almost invariably estimated volumetrically as this procedure obviates its separation from the other rare earths. The only compound obtained in gravimetric work is the dioxide, CeO2, which is formed when cerium salts of the volatile acids are strongly ignited. Thus in the preceding paragraph ceric iodate was converted into cerous oxalate which was ignited to dioxide. The routine process consists in obtaining the cerium in a nitrie acid solution. For this purpose, eeric hydroxide as obtained in the bromate-marble separation from the other rare earths is dissolved in nitric acid and hydrogen peroxide and the solution is evaporated to dryness. The residue is dissolved in water and a few drops of nitrie acid, and an excess of oxalic acid is added to the hot solution which is allowed to stand on the water bath until the precipitate becomes erystalline. The cerous oxalate is filtered off noxt day, washed with slightly acidulated water and ignited gradually at first, then more strongly over a blast burner. The residue is weighed as CeO₂. Factors: CeO₂ to Ce=0.8142; CeO₂ to Ce₂O₃ =0.9536. The oxalate for the purpose of gravimetric estimation should be precipitated in a solution free from hydrochloric acid and alkali metals or high results will be obtained.

2. Volumetric. The volumetric estimation of cerium is both quick and accurate and is therefore applied in commercial and industrial practice. The other rare earths need not be eliminated. Of the several processes published only Metzger's bismuthate method (Jour. Amer. Chem. Soc., 1909, 31, 523) will be described here as it is easily carried out and reliable in the presence of thoria, zirconia and the rare earths.

Cerium and the rare earths are first separated from the base metals by precipitation as oxalates (see under "Separation from other Metals"); the precipitate is ignited to oxides and these are converted into sulphates by heating with 20 cc. of strong sulphuric acid. The cooled mass is poured into 100 cc. of ice-cold water and the solution treated with 2 grams of ammonium sulphate and 1 gram of sodium bismuthate, boiled for 5 minutes, cooled and a filtered through a Gooch crucible on asbestos which has previously been washed with an acidified solution of potassium permanganate followed by water. The crucible is washed with about 100 cc. of 2% sulphuric acid, a small excess of ferrous sulphate solution is added to the filtrate and this excess is measured by N/20 permanganate. According to the equation

$$2\text{Ce}(SO_4)_2 + 2\text{Fe}SO_4 = \text{Ce}_2(SO_4)_2 + \text{Fe}_2(SO_4)_2$$

140.25 parts of cerium are equivalent to 55.84 parts of iron; hence the iron factor of the permanganate multiplied by 2.5116 gives the cerium factor.

ESTIMATION OF THE OTHER RARE EARTHS

1. Estimation of the Sum of the Rare Earths Other than Ceria. This is preceded by the separation of ceria by one of the methods described. If the bromate-marble method has been used, the solution is acidified with 5 cc. of nitric acid per 100 cc. In the case of the iodate-bromate method the combined filtrates are diluted somewhat and precipitated with caustic soda. The precipitate is filtered off, well washed, and dissolved in nitric acid. The solution is evaporated to dryness and the residue taken up in water containing 5 cc. of nitric acid per 100 cc.

Either solution is treated whilst hot with an excess of saturated oxalic acid solution. After standing over night the precipitate is collected and washed with acidulated water. For accurate work reprecipitation is recommended. The precipitate is rinsed off the paper and evaporated twice to dryness with fuming nitric acid. The residue is dissolved in 5% nitric acid and the oxalate precipitation repeated as before. The washed precipitate is dried and ignited strongly, first in the air then in hydrogen, cooled, and weighed as sesquioxides. If the reduction is omitted, a colored residue and high result will be obtained caused by higher oxides of praceodymium and terbium. The rare earths should be weighed without delay in covered crucibles as they absorb carbon dioxide and water like lime.

2. Estimation of the Cerium and Yttrium Groups. The weighed sesquioxides obtained in the preceding paragraph are converted into sulphates by heating with strong sulphuric acid and the mass is heated to 450° C. to expel the excess of acid. After fumes cease to be evolved, the mass is allowed to cool and dissolved in icc-cold water to give a nearly saturated solution. An equal bulk of water is added followed by powdered sodium sulphate until the solution is saturated with the salt. The precipitated double sulphates of sodium and the eerium metals are filtered off next day and washed with a saturated solution of sodium sulphate; they are digested with hot caustic soda, the hydroxides filtered off, dissolved in hydrochloric acid and the solution evaporated to dryness. The residue is dissolved in the minimum of water, an equal bulk of water added and the precipitation with sodium sulphate is repeated. The combined filtrates are treated with ammonia, the precipitate is dissolved in nitrie acid and the yttria earths precipitated by addition of oxalic acid. The precipitate after ignition is weighed as "oxides of the yttrium group." The double sulphate precipitate is once more converted into hydroxides, which are dissolved in nitric acid and converted into oxalates as before. The precipitate is ignited in air, then in hydrogen and weighed as "oxides of the cerium group."

The above separation is more or less approximate. The mixture of eerium group oxides contains all the lanthana, praseodymia, neodymia and nearly all the samaria as well as the greater part of the terbia group and a minute quantity of the yttria earths; the remainder of the terbium group is not precipitated by sodium sulphate and remains with the yttria group. The separate estimation of the terbium group is neither feasible by ordinary analytical methods nor of any practical importance.

3. Estimation of the Individual Earths. The separation of a mixture of the rare earths into its individual constituents is not a practical proposition. It can be accomplished by fractional crystallisation but the process requires large quantities of material and the fractionations must be repeated many hundreds of times. As a general rule the solubility of the salts of the rare earths increases with their atomic weight, whereas the basicity of the oxides decreases.

TECHNICAL METHODS

1. Estimation of Cerium in Minerals. This is effected in the following manner by means of the methods described in this chapter: The ore is decomposed by heating with sulphuric acid and the sulphates are dissolved in ice-cold water. The solution is precipitated with oxalic acid, the oxalate precipitate strongly ignited and the oxides again converted into sulphates. These are brought into solution as before and the cerium is estimated volumetrically by the bismuthate method.

2. Colorimetric Estimation of Ceria in Thoria, Thorium Nitrate, etc. (Benz, Z. angew. Chem., 1902, 16, 300.) The oxide is fused with sodium bisulphate, the melt leached with cold water and the sulphates converted into nitrates by precipitation with ammonia, filtration and solution in nitric acid. The liquid is evaporated to dryness, the residue dissolved in water, the solution filtered to remove filter fibres and the filtrate heated with a known excess of citric acid and hydrogen peroxide. The solution is neutralised with ammonia and an aliquot part transferred to a colorimeter tube. The standard is made by mixing cerium nitrate solution (1 cc. = 0.0005 gram of ceria) with the same quantities of pure thorium nitrate, citric acid, hydrogen peroxide and ammonia as are contained in the test. Equality of tints is produced by withdrawal of a suitable amount of liquid from the solution showing the deeper colour.

Cerium in thorium nitrate is detected by heating a solution of 5 grams of the salt with ammonia and hydrogen peroxide. A yellow colour developing in the precipitate proves the presence of cerium. The quantitative estimation is carried out colorimetrically as described above.

3. Detection and Estimation of Didymium in Cerium Salts. (Dede, Chem. Zeit., 1923, 47, 82.) When the light from mercury vapour is made to pass through crystals or solutions of didymium salts, the absorption band covers the two yellow lines of mercury, and the solution or crystals appear blue. The reaction is sensitive: thus crystals of cerium nitrate, in which the didymium band can hardly be detected in a 20 mm. layer of 5 per cent. solution, appear distinctly blue in mercury vapour light. In dilute solutions the absorption of the mercury lines is proportional to the concentration of the didymium, which can therefore be estimated colorimetrically without a spectral photometer.

INDIUM, SCANDIUM, THALLIUM

INDIUM

At. wt. Symbol: In.

Occurrence. Indium is a rare element found in many deposits of zine blende, in some tungsten ores, in most tin ores and, sometimes, in pyrites, siderite and galena. It is often found concentrated as an indium-gullium

alloy of low melting point in the residues from zinc retorts.

Detection. For the detection of indium in an orc, e.g., in zine blende, the mineral is dissolved in hydrochloric acid with the addition, if necessary, of a little nitric acid, the excess of which is expelled by boiling with hydrochloric Digestion of the filtered solution with metallic zine precipitates all the indium together with lead, copper, eadminm, etc. The precipitate is dissolved in nitric acid and the solution evaporated with sulphuric acid to fumes. The cold residue is extracted with water and the lead sulphate, etc., filtered off. The filtrate is treated with an excess of ammonia, boiled and filtered. The precipitate is dissolved in the minimum of hydrochloric acid, the solution neutralised with ammonia, an excess of sodium bisulphite added and boiling continued for some time. A white microcrystalline precipitate indicates As a confirmatory test the precipitate is dissolved in a few drops of hydrochloric acid and a platinum wire is dipped into the solution and held in the Bunsen flame. A bright blue colour showing two characteristic bright blue lines (λ 4511.55 and λ 4101.95) when yiewed through the spectroscope confirms the presence of indium.

Indium oxide is a yellow powder soluble in acids and readily reduced on charcoal to metallic globules with a yellow incrustation. Indium salts give a yellow precipitate with hydrogen sulphide in neutral, alkaline or acetic acid solutions and a white gelatinous precipitate with ammonia insoluble in excess but soluble in cold caustic alkali and re-precipitated on boiling.

Quantitative Analysis. For the quantitative determination of indium in zinc blende and retort residues as much as 100 grams may have to be taken. The procedure follows the same lines as that described above with the usual precautions to render the separations quantitative. As the bisulphite precipitate obtained contains a little iron, it is dissolved in hydrochloric acid and the solution treated with sodium acetate and a little α -nitroso- β -nuphthol dissolved in 50% acetic acid. The precipitate is filtered off, washed with cold water and the indium recovered from the filtrate by boiling with a very slight excess of ammonia. The indium hydroxide is collected, washed well with 5% ammonium nitrate solution, ignited wet at a temperature below 800° and the residue weighed as In₂O₃. Factor to indium: 0.8271.

Chapter by W. R. Schoeller, Ph.D., and A. R. Powell, metallurgical chemists, London, England.

SCANDIUM

At. wt. Symbol: Sc.

Occurrence. Scandium is very widely distributed in minute quantities in almost all rocks but it is found in appreciable quantity only in very few minerals. Mica, cassiterite and wolframite from some localities, cuxenite and keilhauite contain a few tenths per cent. of scandia; wikite contains a little more than 1% and thortveitite, the only mineral in which scandium is an essential constituent, over 30%.

Detection. For the detection of scandia in a mineral the solution obtained as described later is treated as usual for the separation of the ammonia group. The precipitate is dissolved in hydrochloric acid, the solution neutralised and boiled with sodium thiosulphate and the precipitate of basic scandium thiosulphate redissolved in hydrochloric acid. After filtering off the sulphur, seandium (and thorium) oxalates are precipitated by addition of oxalic acid. The precipitate is collected, washed and digested with fuming nitric acid. The solution is evaporated to dryness, the residue dissolved in a little water, the solution poured into a 20% solution of ammonium tartrate and the mixture boiled with ammonia; the gradual separation of a crystalline precipitate indicates the presence of scandium.

In the examination of mixtures of the rare earths, which often contain scandia, the mixed oxides obtained from the oxalates by ignition (see Rare Earth chapter) are dissolved in hydrochloric acid and the solution is boiled with sodium silicofluoride; a heavy gelatinous precipitate of scandium fluoride is obtained, free from all but traces of rare earths.

Minute quantities of scandia are readily detected in minerals by examination of the spark spectrum. The scandium must first be concentrated together with any rare earths by precipitation with oxalie acid. The precipitate is ignited to oxides and these are dissolved in hydrochloric acid; the filtrate from the oxalates should be examined also for scandia. The most intense lines of this element lie between 3500 and 3700 Å.; they are 3572.72, 3613.98, 3630.90, 3642.96.

Quantitative Analysis. Minerals containing rare earths are decomposed by treatment with hydrochloric or sulphuric acids or by fusion with sodium pyrosulphate (see Rare Earth chapter). Euxenite, and similar minerals containing titanium, tantalum and columbium, may be decomposed by moistening the finely ground sample with a little water, adding 40% hydrofluoric acid, and, after the violent action has subsided, evaporating to dryness on the water-bath. The residue is extracted with boiling water and the insoluble material, which contains all the scandium, is filtered off, using a rubber funnel, and dissolved by heating with strong sulphuric acid. Wolfram, which sometimes contains scandia, is decomposed by digesting the slimed mineral with aqua regia until the residue is a pale yellow colour.

The solution obtained by any of the above methods is saturated with hydrogen sulphide to remove heavy metals and the filtrate is boiled to expel excess of the gas and oxidised with nitric acid. The hot solution is treated with a slight excess of ammonia, the precipitate collected, well washed with 2% ammonium nitrate solution and dissolved in the minimum of 1:1 nitric

acid, and the solution (50 to 60 ce.) treated hot with 20 ee. of a saturated solution of oxalie acid added slowly with vigorous stirring. After standing over night the precipitate is filtered off, washed with a dilute solution of oxalie acid, rinsed back into the original beaker and digested with furning nitrie acid until completely dissolved. The nitrates are converted into chlorides by two evaporations with hydroehlorie acid to dryness. The residue is dissolved in 200 cc. of hot water and the solution boiled with 10 grams of sodium thiosulphate for one hour. The precipitate is filtered off, washed with hot water and digested with hydrochloric acid. The insoluble residue of sulphur is removed by filtration and well washed with hot water. The filtrate is evaporated to dryness, the residue dissolved in water and the thiosulphate precipitation repeated using 5 grams of this salt in a bulk of 150 cc. The second precipitate is treated as before and the filtered solution neutralised with ammonia. One drop of 1:1 hydrochloric acid is added and the solution (50 ee.) is allowed to drop slowly into 50 cc. of a boiling 20% solution of ammonium tartrate. Boiling is continued, with the addition of a few ee. of ammonia from time to time, for 40 minutes. After standing until cold, the solution is filtered; the precipitate is washed with cold 5% ammonium tartrate solution and ignited wet in a platinum crucible. The residue is weighed as seandia.

In the case of wolfram, the solution obtained by digesting the mineral with aqua regia is boiled with 5 grams of sodium silicofluoride for 1 hour. The precipitate of scandium fluoride is collected, washed with hot water and heated in a platinum dish with strong sulphuric acid until copious fumes are evolved. After cooling, the residue is dissolved in water and the scandium is precipitated as scandium ammonium tartrate as described above.

THALLIUM

At. wt.

Symbol: Tl.

Occurrence. Thallium occurs in quantity only in a few rare minerals such as crookesite, (Cu, Tl, Ag)₂Se, and lorandite, TlAsS₂. It occurs in small quantities however associated with the alkali metals, zine, iron and lead, and is usually recovered from the flue dust from burning iron pyrites.

Detection. Thallium forms two series of salts. The reactions of thallous salts recall those of lead: thus thallous chloride is a white crystalline sparingly soluble compound and thallous iodide is a yellow crystalline compound almost insoluble in water. Thallous sulphide is produced as a brown precipitate by addition of sodium sulphide to an alkaline or acetic acid solution of a thallous salt. Thallous sulphate and hydroxide are both soluble like the corresponding potassium salts whilst the chloroplatinate and cobaltinitrite are insoluble yellow and red compounds respectively. Thallous chromate like lead chromate is insoluble in water and dilute acetic acid.

Thallie salts are obtained by oxidising thallous salts with chlorine, permanganate and similar oxidising agents; they are all readily hydrolysed yielding brown basic salts and give a brown gelatinous precipitate with ammonia, resembling ferric hydroxide.

In the usual course of qualitative analysis thallium passes into the zinenickel group, being precipitated with aminonium sulphide in ammoniacal solution. The most satisfactory procedure is to evaporate the solution to be tested with sulphuric acid to remove the lead and then saturate the filtrate with hydrogen sulphide. After filtration the excess of the precipitant is removed by boiling and the solution oxidised with nitric acid. Iron, aluminum, the zine-nickel group and the alkaline earths are removed by boiling with sodium earbonate and the filtrate is treated with ammonium sulphide. If a brown precipitate is formed, it is dissolved in a little dilute sulphuric acid and the solution, after boiling, is treated with potassium iodide. A yellow crystalline precipitate proves the presence of thallium. A little of this substance held in the loop of a platinum wire in the Bunsen flame gives a characteristic c green flame which, viewed through the spectroscope, shows a broad green line at \(\lambda 5350.7. \) For the isolation of minute quantities of thallium from a solution free from heavy metals a mixture of potassium iodide and antimony trichloride is added, when a characteristic orange-red micro-crystalline precipitate of 3TlI · 2SbI is formed.

Separation from Other Metals and Gravimetric Determination. Practically all materials containing thallium yield the metal to treatment with hydrochloric or nitric acids or to aqua regia. The solution obtained in all eases is evaporated with strong sulphuric acid until copious fumes are evolved; after cooling, the residue is dissolved in water and the solution filtered for the removal of lead sulphate. If the amount of thallium present in the original material is very small, a large amount should be taken for the analysis; after removal of the nitric acid used in dissolving the substance the solution is boiled with several strips of zine until effervescence ceases and basic salts begin to be precipitated. A few ec. of hydrochloric acid are added and the solution is filtered whilst a feeble evolution of hydrogen is maintained from the zinc. The precipitate is washed, digested with hot 20% sulphuric acid and the solution containing the thallium filtered.

The sulphate solution obtained by either of the above methods is neutralised with sodium carbonate, 5 grams of potassium eyanide and a further 2 grams of sodium carbonate are added and the mixture warmed on the water-bath. The precipitate is filtered off and washed with a 1% solution of sodium carbonate. To the filtrate, which contains all the thallium, are added a few cc. of colourless ammonium sulphide: the precipitated thallous sulphide is collected on a filter, washed with a very dilute solution of ammonium sulphide and dissolved in the minimum of hot 10% sulphuric acid. After boiling to expel hydrogen sulphide, the solution is neutralised with sodium carbonate, diluted to 100 ec. and treated at 80° C. with a 10% solution of potassium iodide drop by drop until no further precipitate forms. One gram of the solid salt is added in excess and the assay set aside over night. The precipitate is collected in a tared Gooch crueible, washed first with the minimum quantity of a cold 1% solution of potassium iodide, then with 82% alcohol until the washings cease to react for iodide, dried at 110° C. and weighed as TII. Factor to thallium: 0.6165.

Volumetric Method. The sulphide obtained as described above is dissolved in 4 cc. of hydrochloric acid and a little water. The solution is boiled to expel hydrogen sulphide, cooled, diluted to 60 cc. and titrated with N/10 potassium permanganate standardised against pure thallous chloride. (Hawky,

Jour. Amer. Chem. Soc., 1907, 29, 300.)

Electrolytic Method. Thallous sulphide is dissolved in nitric acid and the filtered solution is evaporated to dryness on the water-bath. The residue is dissolved in 100 cc. of water and transferred to a platinum dish with roughened surface to act as anode. Ten ec. of absolute alcohol or acetone are added and the solution is electrolysed for 6 to 8 hours at 60° C. with a disc of iridoplatinum, rotating at 300 revolutions per minute, as cathode. A current of 0.5 amp. at 2.5–3 volts is used. The thallie oxide deposited on the anode is washed with distilled water, dried at 160°, and weighed. Factor to thallium: 0.8947.

Uses. The chief use of thallium appears to be in the manufacture of artificial stones and optical glass of very high refracting power. In the analysis of these products the thallium is rendered soluble by fusion with sodium earbonate followed by solution of the melt in water and evaporation with sulphuric acid. The resulting mass is dissolved in water, the solution filtered from insoluble matter and the thallium determined in the filtrate as described above.

CHLORINE

Cl₂, at.wt. 35.46; D. (air), 2.491; ni.p. -101.5°; b.p. -33.6° C.; oxides, Cl₂O, Cl₂O, Cl₂O₇.

DETECTION

Free Chlorine. The yellow gas is recognized by its characteristic odor. It liberates iodine from iodidos; it bleaches litmus, indigo, and many organic coloring substances.

Chlorides. Silver Nitrate Test. In absence of bromides and iodides, which also form insoluble silver salts, silver nitrate precipitates from solutions containing chlorides white, curdy, silver chloride, AgCl (opalescent with traces), soluble in NH,OH (AgBr slowly soluble, AgI difficultly soluble), also soluble in concentrated ammonium carbonate (AgBr is very slightly soluble; AgI is insoluble). Silver chlorido turns dark upon exposure to light.

Free Hydrochloric Acid. Manganese Dioxide, Potassium Permanganate, and certain oxidizing agents liberate free chloring gas when added to solutions containing free hydrochloric acid. The gas passed into potassium iodide liberates free iodine, which produces a blue solution with starch.

Concentrated Sulphuric Acid added to chlorides and heated liberates HCl gas, which produces a white fume in presence of ammonium hydroxide.

Detection in Presence of Cyanate, Cyanide, Thiocyanate. An excess of silver nitrate is added to the solution, the precipitate filtered off and boiled with concentrated nitrie acid to exidize the cyanogen compounds and the white precipitate, silver chloride, subjected to the tests under chlorides to confirm the compound.

Detection in Presence of Bromide and Iodide. About 10 cc. of the solution is neutralized in a casserole with acetic acid, adding about 1 to 2 cc. in excess, and then diluting to about 6 volumes with water. About half a gram of potassium persulphate, K2S2O3, is added and the solution heated. Iodine is liberated and may be detected by shaking the solution with carbon disulphide, which is colored blue by this element. Iodinc is expelled by boiling, the potassium persulphate being repeatedly added until the solution is colorless. Bromino is liberated by adding 2 or 3 ec. of dilute sulphuric acid and additional persulphate. A yellowish-red color is produced by this element. Carbon disulphide absorbs bromine, becoming colored yellowish red. Bromine is expelled with additional persulphate and by boiling. The volume of the solution should be kept to about 60 cc., distilled water being added to replace that which is expelled by boiling. When bromine is driven out of the solution, the silver nitrate test for chlorides is made. A white, curdy precipitate, soluble in ammonium hydroxide and reprecipitated upon acidifying with nitric acid, is produced, if chlorides are present.

Chapter contributed by Wilfred W. Scott.

If Chlorates are Present. The halogens are precipitated with silver nitrate, the precipitate dissolved with zine and sulphurie acid and the solution treated as directed in the preceding paragraph.

Test for Hypochlorite. Potassium hypochlorite, KClO, shaken with mereury forms the yellowish-red compound Hg₂OCl₂, which does not form with the

other potassium salts of chlorine, i.e., KCl, KClO2, KClO2, KClO4.

Hypoehlorites decolorize indigo, but do not decolorize potassium permanganate solutions. If arsenious acid is present, indigo is not decolorized until all of the arsenious acid has been oxidized to the arsenic form.

Tests for Chlorite. Potassium permanganate solution is decolorized by

chlorites. (The solution should be dilute.)

A solution of indigo is decolorized, even in presence of arsenious acid (distinction from hypochlorites).

Detection of Chlorate. The dry salt heated with concentrated sulphurie acid detonates and evolves yellow fumes.

Chlorates liberate chlorine from hydrochloric acid.

Perchlorate. The solution is boiled with hydrochloric acid to decompose hypochlorites, chlorites and chlorates. Chlorides are removed by precipitation with silver nitrate, the filtrate evaporated to dryness, the residue fused with sodium carbonate to decompose the perchlorate to form the chloride, which may now be tested as usual.

ESTIMATION

The determination of chlorine is required in a large number of substances. It occurs combined as a chloride mainly with sodium, potassium and magnesium. Rock salt, NaCl, sylvine, KCl, carnallite, KCl·MgCl₂·6H₂O, matlockite, PbCl₂·PbO; horn silver, AgCl, atacamite, CuCl₂·3Cu(OH)₂, are forms in which it is found in nature. Chlorine is determined in the evaluation of blenching powder. It is estimated in the analysis of water.

Preparation and Solution of the Sample

In dissolving the sample the following facts should be borne in mind: Although chlorides are nearly all soluble in water, silver chloride is practically insoluble (100 cc. dissolves 0.000152 gram at 20° C.); mercurous chloride is nearly as insoluble as silver chloride (0.00031 gram); lead chloride requires heat to bring it into solution (in cold water only 0.673 gram soluble per 100 cc. of water). Chlorides of antimony, tin, and bismuth require free acid to keep them in solution. Hydrochloric acid increases the solubility of silver, mercury, lead, antimony, bismuth, copper (Cu'), gold and platinum, but decreases the solubility of eadmium, copper (Cu''), nickel, cobalt, manganese, barium, calcium, strontium, magnesium, thorium, sodium, potassium and ammonium chlorides.

Chlorine gas is most readily dissolved in water at 10° C. (1 vol. H₂O dissolves 3.095 vols. Cl). Boiling completely removes chlorine from water.

Hypochlorites, chlorites, ehlorates, and perchlorates are soluble in water.

The chlorine may be present either combined or free. In the combined state it may be present as free hydrochloric acid or as a water-soluble or insoluble salt.

14 Prescott and Johnson, Qual. Chem. Anal. D. Van Nostrand Co.

Water-soluble Chlorides. Chlorides of the alkali or alkaline earth groups may be treated directly with silver nitrate upon making slightly acid with nitric acid, the chlorine being determined either gravimetrically or volumetrically according to one of the procedures given later. It is convenient to work with samples containing 0.01 grain to 1 gram of Cl. The sample is dissolved in about 150 cc. of water, made acid with nitric acid with about 5 to 10 cc. in excess of the point of neutralization, should the sample be alkaline. Then the chlorine combined as chloride is determined as directed later.

If the water solution contains a chloride of a heavy metal which forms basic salts (e.g., stannic, ferric, etc., solutions), or which may tend to reduce the silver solution, it is necessary to remove these by precipitation with ammonium hydroxide, or by sodium hydroxide, or potassium carbonate solution. The salt is dissolved in water and acidified with HNO3, adding about 10 cc. in excess, for about 150 cc. of solution. (This excess HNO, should be sufficient to oxidize substances which would tend to reduce the silver reagent; e.g., FeSO., Animonia solution (free from chloride) is added in sufficient quantity to precipitate the heavy metals iron, manganese, aluminum, etc. The mixture is filtered and the residue washed several times with distilled water. Chlorine is determined in the filtrate by acidifying with HNO, as directed above.

Water-insoluble Chlorides. The chloride may frequently be decomposed by boiling with sodium carbonate solution. Many of the minerals, however, require fusion with sodium carbonate to prepare them for solution; e.g., apatite,

sodalite, etc. Silver chloride may also be decomposed by fusion.

Silver Chloride. The sample is mixed with about three times its weight of Na₄CO₄ and fused in a porcelain crucible until the mass has sintered together. The soluble chloride, NaCl, is leached out with water, leaving the water-insoluble carbonate of silver, which may be filtered off. The filtrate is acidified with HNO, and chlorine determined as usual.

Chlorine in Rocks. The finely ground material is fused with about five times its weight of potassium carbonate. The melt is extracted with hot water, cooled and the solution acidified with nitric acid (methyl orange indicator), and the solution allowed to stand several hours (preferably over night). If silicic acid precipitates, the solution is treated with annuonia and boiled, filtered and the filter washed with hot water. The cooled filtrate is acidified with nitric acid and chlorine determined as usual. If silicic acid does not separate, the addition of ammonia may be omitted and chlorine determined in the solution.

Free Chlorine. Free chlorine may be determined volumetrically according to the procedure given under this section. If it is desired to determine this gravimetrically, a definite amount of the chlorine water is transferred by means of a pipette to a flask containing ammonia solution and the mixture heated to boiling. The cooled solution is acidified with nitric acid and the chloride precipitated with silver nitrate according to the standard procedure given

on page 151.

Note. Free chlorine cannot be precipitated directly, as the following reaction takes place: 6Cl+6AgNO₁+3H₁O=5AgCl+AgClO₂+6HNO₂.

Reaction of chlorine with ammonia: 2Cl+2NH₄OH=NH₄Cl+NH₄OCl+H₄O.

When the solution is boiled, NH₄OCl breaks down, e.g., 3NH₄OCl+2NH₂=3NH₄Cl $+N_1+3H_2O.$

Chlorine in Ores and Cinders. One hundred grams of the finely ground ore or cinder are placed in a 500-cc. flask, containing 300 cc. of strong sulphuric acid (Cl-free). The flask is shaken to mix the sample with the acid and then connected with an absorption apparatus, containing distilled water or dilute caustic solution. The sample is gradually heated, the distillation flask resting upon a sand bath. After two hours, which is sufficient to expel all the chlorine as hydrochloric acid, the contents of the absorption tubes are filtered, if free sulphur is present (sulphide ores), nitric acid added and the filtrate brought to boiling to oxidize any SO₂ that may be present. Chlorine is precipitated according to the standard procedure on page 148.

During the run the distilling flask should be shaken occasionally to prevent caking. Suction applied at the absorption end of the apparatus and a current of air swept through the system aids in carrying over the HCl into the water

or NaOH.

Determination of Halogens in Organic Compounds. Method of Carius 1

Organic compounds may be decomposed by heating with strong nitric acid at high temperatures under pressure. If this heating is conducted in the presence of silver nitrate, the halogen hydride, formed by the action of nitric acid on the organic compound, is converted to the silver halide. This is weighed, or the excess AgNO₃ titrated (p. 149). Arsenic, phosphorus, and sulphur are oxidized to arsenic, phosphorie, and sulphuric acids, the metals present being converted to nitrates.

Procedure. About 0.5 to 1 gram of powdered silver nitrate is introduced, by means of a glazed paper funnel, into a heavy-walled, bomb-glass tube, which is sealed at one end and is 50 cm. long, 2 cm. in diameter and about 2 mm. thickness of wall. About 30 cc. of strong nitric acid (96%), free from chlorine, are introduced by means of a long-stemmed funnel, to avoid wetting the upper portion of the tubing. About 0.1 gram of the organic substance, contained in a small bore, thin wall, glass tube closed at one end (4-5 cm. long), is introduced into the bomb tube, inclined to one side. The small tube should flont in the nitric acid, as it is important that the material should not come in contact with nitric acid until the bomb has been sealed, as loss of halogen is apt to occur with open tubes. The upper end of the bomb is softened in the blast-lamp flame, drawn out to a thickwalled capillary tube and fused.

When cold, the bomb is wrapped in asbestos paper, shoved into an iron tube of a bomb furnace and the heat turned on. The heating is so regulated that the temperature is raised to 200 °C. in three hours. If a higher temperature is necessary, the heating should be such as to cause a rise of 50°C. in three hours. Substances of the aromatic series require eight to ten hours heating at 250 to 300°C., while aliphatic substances may be decomposed at 200°C. in about four hours. Cocasionally it is necessary to relieve the pressure in a tube after heating to 200°C., before taking to a higher temperature, by softening the tip of the cooled bomb in a flame, allowing the accumulated gas to blow out, resealing and again heating to the desired temperature. Evidence of crystals or drops of oil in the glass tube indicate incomplete decomposition. When the bomb is cooled, it is removed by

¹ Ann. d. Chem. u. Pharm. (1865), 186, p. 129.

² Treadwell and Hall, Anal, Chem., J. Wiley & Son. P. C. R. Kingscott and R. S. G. Knight, Methods of Quant. Org. Anal. Longmans, Green & Co. (1914), Clowes and Coleman, Quant. Chem. Anal., P. Blakiston's Son & Co., 1900.

taking out the iron sheath from the furnace and inclining it so that the glass capillary tip slides partly out of the tube. (The eyes should be protected by goggles.) The point of the capillary is held in the flame until the tip softens and the gas pressure is released by blowing through a passage in the softened glass. When the gas has escaped, a scratch with a file is made below the capillary and the tip broken off by touching the scratch with a hot glass rod. The contents of the bomb are poured out into a beaker, the tube washed out with water and the combined solution made to about 300 cc. This is heated to boiling and then allowed to cool. The halide precipitate is filtered through a Gooch crucible, then dried and weighed. or by titrating the excess AgNO, by Volhard's method, the halide may be estimated.

If pieces of glass should be present, the precipitates, AgCl or AgBr, are dissolved, in ammonium hydroxide, filtered and reprecipitated by acidifying with nitric acid. AgI may be dissolved by means of dilute sulphuric acid and zinc. The excess zinc is removed, the glass washed free of iodine, dried and weighed and its weight subtracted from the original impure AgI, giving the weight of the pure silver iodide.

Lime Method for Determination of Halogens in Organic Matter

A layer of lime (free from chloride), about 6 cm. long, is introduced into a difficultly fusible glass tube, closed at one end (35 cm. long and with 1 cm. bore), followed by 0.5 gram of the substance, and 6 cm. more of the lime. The substance is thoroughly mixed by means of a copper wire with a spiral end. The tube is nearly filled with lime, and in a horizontal position, gently tapped to cause the lime to settle and form a channel above the layer. The tube is placed in a small carbon combustion furnace. The heat is turned on, so that the front end of the tube is heated to dull redness and then the end containing the substance. When the organic matter has been decomposed, the tube is cooled and the contents transferred to a beaker and the lime dissolved in dilute nitric acid (Cl-free). The carbon is filtered off and the halogen determined as usual in the filtrate.

Should a sulphate be present in the mixture, organic matter will reduce it to a sulphide, so that AgS will be precipitated along with the halides. To prevent this, hydrogen peroxide is added to the solution which should be slightly alkaline. The mixture is boiled to remove the excess of H_2O_2 and is then acidified with nitric acid, the solution filtered and the halide determined in the filtrate.

With substances rich in nitrogen, some soluble cyanide is apt to form. The silver precipitate containing the halides and the cyanide is heated to fusion. The residue is now treated with zine and sulphuric acid, the metallic silver and the paracyanogen filtered off and the halides determined in the filtrate,

Sodium Peroxide Method

Organic compounds may be decomposed by sodium peroxide in an open crucible without recourse to a scaled tube, as is required by the Carius method. The following is the procedure outlined by Pringsheim.

About 0.2 gram of substance in a small steel crucible is treated with a calculated quantity of sodium peroxide.2 The crucible should be only two-thirds of its height full; this is put in a large porcclain crucible, in which a little cold water is carefully placed, so that the steel crucible stands out 1 to 2 cm. This latter crucible is covered with its own cover, in which is a hole through which an iron wire heated to redness can be introduced with the object of starting the combustion. As soon as the combustion is completed the whole is plunged into the water in the larger crucible. The porcelain crucible is covered with a watch-glass and heated gently until the whole mass is dissolved. This point is recognized when no more bubbles are given off and when there are no more particles of carbon which have escaped combustion. The steel crucible is then removed and washed carefully; the solution is filtered and treated with an excess of sulphurous acid (to neutralize the alkaline liquid, and to reduce the oxidized products: bromic, iodic acids, etc.). The solution is acidulated with nitric acid, then made to a volume of about 500 cc., and the halogens precipitated with silver nitrate and the precipitate washed, dried and weighed as usual.

Chlorine and Chlorides in Gas. The gas is bubbled through dilute sodium hydroxide contained in one or more cylinders, gas wash bottle type, measuring the gas by means of a dry meter, placed after the cylinders. The meters are protected from moist gas by passing this through sulphurie acid and an asbestos filter, loosely packed. Aliquot portions of the sodium hydroxide are now examined for chlorine by acidifying with nitric acid and adding silver nitrate. If only traces are present the turbidity of the solution is compared with standards made up with known amounts of sodium chloride dissolved in water. The comparisons may be made conveniently in Nessler tubes. To different quantities of the standard made up to a convenient volume, silver nitrate reagent is added and the solution diluted to 50 or 100 cc. The unknown, placed in a Nessler tube, is treated with nitric acid and silver nitrate and matched with the standards, after dilution to the same volume adopted for the standards.

¹ C. N., 1905, 91, 2372, 215.

² Charge of sodium peroxide is judged as follows:

Per cent C and O in material.	Amount of sugar to add.	Amount of NasOs required.
Over 75 30 to 75 25 to 50 Below 25	0 0 1 the wt. of sub. An equal weight	18 times wt. of sub. 16 times wt. of sub. 16 times wt. of sub. 16 times wt. of sub.

SEPARATIONS 1

Separation of Chlorine and the Halides from the Heavy Metals. Halides of the heavy metals are transposed by beiling their selutions with sodium earbonate, the heavy metals being precipitated as carbonates and the halides going into solution as sodium salts.

Separation of Halides from Silver and from Silver Cyanide. The silver salt is treated with an excess of zinc and sulphuric acid, the metallic silver and the paracyanogen filtered off, and the halides determined in the filtrate.

Separation of the Halides from One Another. Separation of Chlorine from Iodine. The method depends upon the fact that nitrous acid sets iedine free from dilute solutions containing a mixture of halogen salts, bromides and chlorides being unaffected.

The solution of the chloride and the iodide in an Erlenmeyer flask is diluted to 400 ee. and 10 cc. of dilute sulphuric acid, 1:1, are added. The gas from 2 grams of sodium nitrite is passed into the solution at the rate of about five bubbles per second. (Pure sodium or potassium nitrite may be added directly to the solution in the flask.) The liberated iodine is now completely expelled by boiling until the evolving steam no longer reacts upon litmus paper. Should a determination of iodine be desired the evolved gas is absorbed in a hydrogen perexide sodium hydroxide solution according to the procedure described under iodine.

The contents of the flask are treated with silver nitrate and the precipitated

silver chlorido determined as usual.

Separation of Chlorine and Bromine from Iodine. The precedure is similar to the separation of chlorine from iodine with the exception that a more dilute solution is necessary to prevent the volatilization of bromine with the iodine.

The neutral solution containing the halogens is diluted to about 700 cc. and about 2 to 3 cc. of dilute sulphuric acid, 1:1, are added and a sufficient amount of pure sodium nitrite introduced or nitrous acid gas passed into the solution as directed above. The solution is boiled until colorless and until the evolved steam no longer acts upon litmus paper. About twenty minutes' boiling after the color of iodine has disappeared from the flask will completely eliminate iodine; in this case, however, water should be added to the flask to replace that evaporated before the solution has been reduced to a volume of less than 600 cc.

For determination of bromine in the residue remaining in the flask, see the chapter on this subject, page 93 and page 154.

¹ Attention is called to "Methods in Chemical Analysis," by F. A. Gooch for useful information on the separation of the halogens.

Nitrous acid is generated by addition of dilute H₂SO₄ to NaNO₃, the acid being added drop by drop through a thistle tube with glass stop-cock.

GRAVIMETRIC Silver Chloride Method

The procedure is based on the insolubility of silver chloride in dilute nitric acid solution, the following reaction taking place, M representing a monatomic element:

 $M.Cl + AgNO_3 = M.NO_3 + AgCl$

From the equation it is evident that 35.45 grams of chlorine require 169.9 grams of silver nitrate. In practice it is best to add about 20% excess of the silver salt.

Equivalents: 1 gram Cl, 4.79 grams AgNO₃, 3.043 grams Ag.

Reagents. Silver Nitrate Solution. Make up a solution containing 4.8 grams AgNO₃ per 100 ec. of distilled water, or dissolve 3.05 grams of silver foil in 10 ec. of dilute nitric acid (1:1.6) and make up to 100 ec. 1 ec. of this reagent will precipitate 0.01 gram of chlorine, or 0.0404+ gram AgCl.

Dilute Nitric Acid. One vol. HNO₃ to 1.6 vols. H₂O (dist.). Procedure. Soluble Chlorides. Preparation of the Solution.

1. Weigh 0.4 to 0.5 gram of the salt on a watch glass or in a weighing bottle and transfer to a beaker or an Erlenmeyer flask.

2. Dissolve in 100 cc. of water and ndd 2 cc. of dilute nitric acid.

3. Precipitation. Calculate roughly the cc. of the silver nitrate reagent that are required to precipitate the chlorine in the sample. If it is an unknown, consider the chlorine in the material to be about 50%. Run the determination in duplicate. The first will be a guide to the amount of silver nitrate solution required.

4. Add the silver nitrate from a burette, drop by drop, to approximately the quantity calculated to be necessary, stirring the solution during the addition. Allow the precipitate to settle and add a few more drops of the reagent, and continue the addition as long as a precipitate forms with the reagent.

Now add about 20% in excess.

5. Heat to boiling, covering the beaker with a watch glass.

6. If the solution is still cloudy, stir vigorously. If the solution is in an Erlenmeyer flask, the mixture may be shaken. This will cause the finely divided silver salt to coagulate so that the solution will settle out clear. Avoid exposing the precipitate to strong light, as this will cause the exposed surface to decompose into the subchloride Ag₂Cl and liberate chlorine.

7. Filtration. Two processes are commonly practiced.

Filter Paper Method. Decant the clear solution into a filter. Test the filtrate to be sure all chlorine has been precipitated by adding a drop or so of silver nitrate solution. Wash the precipitate in the beaker twice by decantation and then transfer to the filter and wash until free of chlorides. The wash water should contain 1 cc. of nitric acid per 100 cc. of distilled water.

8. Dry the filter with its contents at 105° C. either in the funnel in which the operation was conducted or on a watch glass. It is advisable to protect

the sample from dust by placing a large filter over the material.

9. Remove as much of the precipitate as possible from the filter, placing

the silver chloride on a 4-inch square of glazed paper.

10. Ignite the filter allowing the ash to drop into a weighed porcelain erucible. Add a drop of nitric acid and a drop of hydrochloric acid to react

with any reduced silver. Place the silver salt (on the glazed paper) in the crucible and gently ignite until the chloride begins to melt. If the AgCl appears dark, moisten with HCl and again apply heat to expel the free acid.

11. Cool in a desiceator.

12. Weigh as silver chloride. (wt. crucible + AgCl) - wt. crucible = wt. AgCl. The compound contains 24.74% of chlorine.

$AgCl \times 0.2474 = Cl.$

13. Calculate the per cent chlorine from the weight of sample taken.

Gooch Crucible Method. 8ª. Prepare a Gooch crucible filter with a moderately thick asbestos mat and wash thoroughly with distilled water containing 1 cc. nitric acid per 100 cc. of water.

9°. Dry the crucible with mat in an oven at 100° C., then heat gently

over a free blue flame. Cool in desiccator and weigh.

- 10°. Wash the silver chloride, first by decantation, then transfer to the Gooch crucible, which has been placed in position on a suction flask. (Consult directions for the preparation of a Gooch and the method of filtration under "Laboratory Apparatus and Manipulation" in the introductory chapter.) Gentle suction is applied and the precipitate is washed free of chloride by repeated additions of the wash water containing the nitric acid.
- 11°. Place the crucible in an oven for 15 minutes or more and dry at 105° C. Now place over a free blue flame and heat until the silver begins to melt. Cool in a desiceator.
- 12°. Weigh. The weight in excess of that due to the crucible is due to silver chloride.
- 13a. Calculate percent chlorine as stated under the "filter paper method," 12 and 13.

Nore. The silver chloride may be removed from the crucible by adding a piece of zinc and dilute sulphuric acid to the residue. AgCl is soluble in ammonia.

VOLUMETRIC METHODS

Determination of Chlorine in Acid Solution, Silver Thiocyanate Ferric Alum Method

The method, devised by Volhard, is applicable to titration of chlorine in acid solutions, a condition frequently occurring in analysis, where the Silver-Chromate Method of Mohr cannot be used. The method is based on the fact that when solutions of silver and an alkali thiocyanate are mixed in presence of a ferric salt, the thiocyanate has a selective action towards silver, combining with this to form thiocyanate of silver, any excess of that required by the silver reacting with the ferric salt to form the reddish-brown ferric thiocyanate, which color serves as an indication of the completion of the reaction. An excess of silver nitrate is added to the nitric acid solution containing the chloride, AgCl filtered off, and the excess of silver titrated with the thiocyanate in presence of the ferric salt.

Copper (up to 70%), arsenic, antimony, cadmium, bismuth, lead, iron, zine, manganese, cobalt, and nickel, do not interfere, unless the proportion of the latter

metals is such as to interfere by intensity of the color of their ions.

Preparation of Special Reagents. N/10 Ammonium or Potassium Thiocyanate Solution. About 8 grams of ammonium or 10 grams of potassium salt are dissolved in water and diluted to one liter. The solution is adjusted by titration against the N/10 silver nitrate solution. It is advisable to have 1 ee. of the thiocyanate equivalent to 1 cc. of the silver nitrate solution. Owing to the deliquescence of the thiocyanates the exact amount for an N/10 solution cannot be weighed.

N/10 Silver Nitrate. This solution contains 10.788 grams Ag or 16.989 grams AgNO₃ per liter. The silver nitrate salt, dried at 120° C., or pure metallic silver may be taken, the required weight of the latter being dissolved in nitric acid and made to volume, or 17.1 grams of the salt dissolved in distilled water and made to 1000 cc. The solution is adjusted to exact decinormal strength by standardizing against an N/10 sodium ebloride solution, containing 5.846 grams

of pure NaCl per liter.

Ferric Indicator. Saturated solution of ferrie anomonium alum. Should this not be available, FeSO₄ may be oxidized with nitric acid, and the solution evaporated with an excess of H₂SO₄ to expel the nitrous fumes. A 10% solution is desired. Five cc. of either of these reagents are taken for each titration.

Pure Nitric Acid. This should be free from the lower oxides of nitrogen. Pure nitric acid is diluted to contain about 50% HNO,, and boiled until perfectly colorless. The reagent should be kept in the dark. Dilute nitric acid does not interfere with the method.

Procedure. To the solution, containing 0.003 to 0.35 gram chlorine, in combination as a chloride, is added sufficient of the pure HNO, to make the solution acid and about 5 cc. in excess. To the solution, diluted to about 150 cc., is added an excess of standard silver nitrate reagent. The precipitated AgCi

¹ Liebig's Ann. d. Chem., 190, 1; Sutton, "Volumetric Analysis," 10 Ed. Z. Anorg. Chem., 63, 330, 1909.

is filtered off and washed free of silver nitrate. The filtrate and washings are combined and titrated with standard thiocyanate.

The filtrate from the precipitated chloride is treated with 5 cc. of the ferric solution, and the excess silver determined by addition of the thiocyanate until a permanent reddish-brown color is produced. Each addition of the reagent will produce a temporary reddish-brown color, which immediately fades as long as silver uncombined as thiocyanate remains. The trace of excess produces ferric thiocyanate, the reddish-brown color of this compound being best seen against a white background. From this titration the amount of silver nitrate used by the chloride is ascertained.

One cc. $N/10 \text{ AgNO}_3 = 0.00355 \text{ gram Cl or } 0.00585 \text{ gram NaCl.}$

Volumetric Determination of Chlorine in a Neutral Solution, Silver Chromate Method

The method, worked out by Fr. Mohr, is applicable for determination of chlorine in water or in neutral solutions containing small amounts of chlorine; the element should be present combined as a soluble chloride. Advantage is taken of the fact that silver combines with chlorine in presence of a chromate, Ag₁CrO₄ being decomposed as follows: Ag₂CrO₄+2NaCl=2AgCl+Na₂CrO₄. When all the chlorine has gone into combination as AgCl, an excess of K₂CrO₄ immediately forms the red Ag₂CrO₄, which shows the reaction of AgNO₃ with the chloride to be complete.

Reagents. Tenth Normal Silver Nitrate Solution. Theoretically 16,989 grams AgNO, per liter are required. In practice 17.1 grams of the salt are dissolved per 1000 cc. and the solution adjusted against an N/10 NaCl solution containing 5.846 grams NaCl per liter.

Potassium Chromate. Saturated solution.

Procedure. To the neutral solution are added 2 or 3 drops of the potassium chromate solution. A glass cell i (or a 50-cc. beaker) is filled to about 1 cm. in depth with water tinted to the same color as the solution being titrated. The cell is placed on a clear glass plate half covering the easserole containing the sample. The standard silver solution is now added to the chloride solution from a burette until a faint blood-red tinge is produced, the red change being easily detected by looking through the blank, colored cell.

One cc. N/10 $K_1CrO_4 = 0.003546$ gram Cl.

Notes. Chlorides having an acid reaction (AlCl₁) are treated with an excess of neutral solution of sodium acetate and then titrated with silver nitrate.

Elements whose ions form colored solution with chlorine are precipitated from the solution by sodium hydroxide or potassium carbonate, and the filtrate, faintly saidified with acetic acid, is titrated as usual.

'1 Time is saved by filtering, through a dry filter paper, only a portion of the mixture made to a definite volume, and titrating an aliquot portion. The first 10-15 cc. of the filtrate are rejected.

² Upon addition of the ferric solution no color should develop. If a reddish or yellowish color results, more nitric acid is required to destroy this. The amount of nitric acid does not affect results when within reasonable limits.

Depré, Analyst, 5, 123; also, Systematic Handbook of "Volumetric Analysis," F. A. Sutton.

Free hydrochloric acid is neutralized with ammonium hydroxide and titrated. It is advisable to titrate the sample under the same conditions as those observed The solution should be kept to small bulk and low temduring standardization.

perature for accuracy on account of the solubility of the silver chromate.

Free chlorine should be converted to a chloride before titration. This may be accomplished, as stated under preparation of the sample, by boiling with ammonium hydroxide. Free chlorine may be determined by sweeping the gas, by means of a current of air, into a solution containing potassium iodide, the liberated iodine titrated by N/10 thiosulphate, Na₂S₂O₃, and the equivalent chlorine estimated.

Volumetric Determination of Free Chlorine

The determination depends upon the reaction Cl+KI = KCl+I. liberated by the chlorine is titrated with Na2S2O1 and the equivalent Cl calculated.

Procedure. A measured amount of the chlorine water is added to a solution of potassium iodide in a glass-stoppered bottle by means of a pipette, the delivery tip of which is just above the surface of the iodide solution. The bottle is then closed and the contents vigorously shaken. The liberated iodine is titrated with tenth-normal sodium thiosulphate (2Na₂S₂O₂+I₂=2NaI+Na₂S₄O₂). When the yellow color of the iodine has become faint, a little starch solution is added and the titration completed to the fading out of the blue color.

One cc. N/10 Na₂S₂O₃ = 0.003546 gram Cl.

Determination of Hypochlorous Acid in the Presence of Chlorine

The determination depends upon the reactions:

$$2KI + HOCl = KCl + KOII + I_2$$
 and $2KI + Cl_2 = 2KCl + I_2$.

The alkali liberated by hypochlorous acid and the total iodine are determined and the calculations made for each of the constituents.

Procedure. A measured volume of N/10 HCl is added to a potassium iodide solution. To this the sample containing the hypochlorous acid and chlorine are added. The liberated iodine is titrated with N/10 Na₂S₂O₄. (The addition of starch is omitted.) The colorless solution is treated with methyl orange indicator and the excess of hydrochloric acid is titrated with N/10 NaOH. The potassium hydroxide, produced by the action of the hypochlorous acid upon the iodide, requires half as much acid for neutralization as the volumes of thiosulphate required by the iodine set free by the hypochlorous acid.

Calculation. The cc. back titration with NaOH are subtracted from the total ee. of HCI taken =cc. HCl required by NaOH liberated by HOCl =A. Then 2A cc. =cc. Na₂S₂O₄ required by the I liberated by HOCl. Cc. $A \times 0.005247$ =gram HOCl. The total Na₂S₂O₂ titration minus 2A cc. (due to the iodine liberated by HOCl) =ec. Na₂S₂O₄ that are required by the iodine liberated by chlorine. The ce. thus required multiplied by 0.003546 = grams chlorine in the sample taken.

¹ Six parts AgCrO₄, dissolve in 100,000 parts H₂O at 15.5°.—W. G. Young, Analyst, 18, 125.

Gravimetric Determination of Chloric Acid, HClO₃, or Chlorates, by Reduction to Chloride and Precipitation as Silver Chloride

Reduction of the Chlorate. Among the methods of reduction of chlorates the following deserve special mention: 1. Reduction with Sulphurous Acid.¹ 2. Ferrous sulphate. 3. Zinc.

1. About 0.2 to 0.5 grain of the salt is dissolved in 100 cc. of distilled water and either SO₂ gas passed into the solution or sulphurous acid in solution added in excess. The solution is now boiled to expel SO₂ and the chloride precipitated

as AgCl in presence of free nitrie acid.

2. The sample in 100 cc. of distilled water is treated with 50 cc. of crystallized ferrous sulphate (10% solution), heated to boiling, with constant stirring, and then boiled for fifteen minutes. Nitric acid is added to the cooled solution, until the deposited basic ferric salt is dissolved. The chloride is now precipitated as AgCl, as usual.

3. The dilute chlorate solution is treated with acctic acid until it reacts distinctly acid. An excess of powdered zine is now added and the solution boiled for an hour. Nitrie acid is added to the cooled solution in sufficient quantity to dissolve the zine remaining. The solution is filtered, if necessary,

and the chloride precipitated as usual.

Factors. AgCl \times 0.855 = KClO₃, or \times 0.2474 = Cl.

NOTE. In absence of cyanides, carbonates and acids decomposed and volatilized by hydrochloric acid, or oxides, hydroxides and substances other than chlorates that may be decomposed or acted upon by this acid, evaporation of the salt with HCl and ignition of the residue, or addition of an excess of annuonium chloride, ² and subsequent heating will give a residue of chloride, which may be determined as usual and the equivalent chlorate calculated. Method by L. Blangey.

The methods may be used in determining chlorates in presence of perchlorates, only the former being reduced to chlorides. Outline of the procedure is given later.

Gravimetric Determination of Perchloric Acid by Reduction to Chloride

A perchlorate ignited with about four times its weight of ammonium chloride in a platinum dish may be decomposed to chloride. A second treatment is usually necessary to change the salt completely. Platinum appears to act as a

ecatalyser, so must be added in solution if a porcelain crucible is used.

Procedure. About 0.2 to 0.5 gram of potassium perchlorate is intimately mixed with about 2 grams of ammonium chloride in a platinum crucible, the latter then covered with a watch-glass and the charge ignited gently for one and a half to two hours, the temperature being below the fusing-point of the residual chloride (otherwise the platinum would be attacked). A second addition of ammonium chloride is made and the mix again heated as before. The resulting chloride may now be determined as usual.

Factors. AgCl \times 0.9667 = KClO₄, \times 0.2474 = Cl.

¹ Blattner and Brassuer, Chem. Zeit. Rep., 1900, 24, 793.

² Perchlorates are decomposed by ignition with NH₄Cl in presence of platinum.

Determination of Chlorates and Perchlorates in Presence of One Another

(1) A portion of the sample is treated with about twelve times its weight of ammonium chloride in a platinum dish (or in a porcelain dish with the addition of 1 ee. of hydroplatinic acid), and the mixture heated according to the procedure given for perchloric acid (page 152). The resulting chloride is determined as usual. This is the total chlorine in the sample.

(2) In a second portion the chlorate is reduced by means of SO₂ or FeSO₄, according to directions given for determination of chloric acid, and chlorine determined. The chlorine of this portion is subtracted from the total chlorine, the difference multiplied by 3.9075 = KClO₄. The chlorine of the second portion multiplied by 3.4563 = KClO₃, or AgCl in (2) subtracted from AgCl of (1) and the difference multiplied by 0.9667 = KClO₄. AgCl of (2) multiplied by 0.855 =

= KClO₃.

Determination of Hydrochloric, Chloric, and Perchloric Acids in the Presence of One Another

(I) Total Chlorine. If the determination is made in the valuation of niter a 5-gram sample is fused with about three times its weight of alkali earbonate ¹ or ealeium hydroxide, ² in a platinum dish, whereby all the chlorine compounds are converted to chlorides. If the compounds are present as alkali salts, fusion with ammonium chloride in a platinum dish may be made and the total chlorides determined after dissolving the residue in nitric acid.

(2) Chloride and Chlorate. If the estimation is being made in niter, 5 grams of the salt are treated with 10 grams of zinc dust (Cl-free) in presence of 150 ec. of 1% acetic acid. The solution is boiled for half an hour, filtered, and the chloride determined. In a mixture of alkali salts of hydrochloric, chloric, and perchloric acids, reduction may be accomplished by passing in SO, gas or by adding ferrous sulphate and boiling according to directions given for the determination of chlorate. The chloride now present in the residue is due to the reduced chlorate and to the original chloride of the sample.

(3) The chloride of the sample is determined by acidifying the salt with

nitric acid (cold) and precipitating as AgCl.

Perchlorate. The ehloride and ehlorate in terms of ehlorine are subtracted from total chlorine of (1) and multiplied by the factor for the salt desired.

Chlorate. The chlorine of (3) is subtracted from chlorine of (2) and multiplied by the factor for the compound desired.

Chloride. The AgCl of (3) is multiplied by the appropriate factor.

Factors. AgCl \times 0.2474 = Cl, or \times 0.2544 = HCl, or \times 0.4078 = NaCl, or \times 0.5202 = KCl.

 $AgCl \times 0.855 = KClO_4$, or $\times 0.9667 = KClO_4$.

Cl $\times 3.4563$ = KClO₁, or $\times 3.9075$ = KClO₄, or $\times 2.1027$ = KCl, or $\times 3.0028$ = NaClO₄, or $\times 3.4535$ = NaClO₄, or $\times 1.6486$ = NaCl.

¹ Mennick, Chem. Zeit. Rep., 1898, 22, 117.

Blattner and Brasseur, Chem. Zeit. Rep., 1900, 24, 793.

Determination of Chlorine, Bromine, and Iodine in the Presence of Each Other

The procedure is Bekk's modification of Baubigny's method.1

Procedure. The halogens are precipitated with an excess of silver nitrate. filtered onto asbestos or glass wool, washed, dried, and weighed as total halogens as silver salts. A second portion is precipitated and the moist, washed silver salts (0.3 to 0.4 gram) are treated with a solution of 2 grams of potassium dichromate in 30 cc. of concentrated sulphuric acid at 95° C., and digested for thirty minutes. By this procedure the iodine is oxidized to hydriodic acid (HIO₁) and chlorine together with bromine is liberated in form of the free halogen. Toward the end of the reaction a stream of air is led through the solution to remove any chlorine and bromine. This is now diluted to 300 to 400 ec., filtered, and the hydriodic acid reduced by adding, drop by drop, with constant stirring, a concentrated solution of sodium sulphite, Na₂SO₂, until a faint odor of SO₂ remains after standing ten minutes. (Under certain conditions an excess may result in a partial reduction of the silver iodide.) The precipitated silver salt is filtered, washed with hot, dilute nitric acid, dried and weighed as AgI. The filtrate containing the silver, formerly with the chlorine and bromine, is treated with potassium iodide in sufficient amount completely to precipitate the silver as AgI. This is filtered, washed and weighed. From the three weights the chlorine, bromine and iodine can be easily calculated.

NOTE. Bekk claims an accuracy within less than 0.15%.

Determination of Free Hydrochloric Acid

In absence of other free acids, hydrochloric acid may be accurately determined by titration with standard alkali. Details for the volumetric analysis of muriatic acid in presence of commonly occurring impurities are given in Volume II in the chapter on Acids.

1 cc. N/1 NaOII = 0.03647 g. HCl.

Determination of Chloride and Cyanide in Presence of One Another

The cyanide is determined by Liebig's method described on page 131. To the neutral solution is added sufficient N/10 silver nitrate to combine with all of the cyanide and chloride present and an excess. The solution is acidified with nitric acid and diluted to a definite volume and a portion filtered through a dry filter. A portion of the filtrate, an aliquot of the whole is titrated with standard thiocyanate solution (page 149) using ferric alum indicator and the excess of the AgNO₃ added thus ascertained. From this the amount combined with the CN and Cl is known. The equivalent required by the cyanide is deducted, the difference being due to the chloride present in the solution.

1 cc. N/10 AgNO₃=0.005203 g. CN, or 0.013022 g. KCN, or 0.003546 g. Cl or 0.005846 g. NaCl, or 0.007456 g. KCl.

Determination of Chloride, Cyanide and Thiocyanate in Presence of One Another

The eyanide is determined by the method of Liebig described on page 131, and the equivalent AgNO₂ required recorded = A.

¹ Julius Bekk, Chem. Ztg., 39, 405-6 (1915). C. A., 9, 2042, (1915).

An excess of N/10 AgNO₃ over that required by CN, CNS and Cl is added and the solution acidified with nitric acid. After making to a definite volume, the solution is filtered through a dry filter, the residue being saved. A portion of the filtrate, an aliquot of the whole solution, is titrated with standard thiocyanate solution using ferrie alum indicator (see page 149), the excess of AgNO₃ is calculated. The amount combining with CN, CNS and Cl is now known = B.

The silver salts on the filter paper are washed with water and transferred by means of strong hydrochloric acid to a flask and boiled for an hour. The cyanide and thiocyanate are decomposed and dissolve, while the silver chloride remains unchanged. The sulphuric acid formed by oxidation of the thiocyanate is precipitated by barium nitrate (as BaSO₄). Without removing the precipitate: AgCl and BaSO₄ the silver nitrate in this solution is determined by Volhard's method (page 149) and the AgNO₃ required by thiocyanic acid and cyanide thus ascertained = C.

By deducting the AgNO₃ of (A) from (C) the silver nitrate required by

thiocyanic acid is determined.

Deducting the AgNO₃ required by CN and CNS (C) from the total AgNO₃ required by CN, CNS and Cl is (B) the amount required by chlorine is obtained. We now have the silver nitrate equivalent of Cl, CN, CNS.

 $N/10 \text{ AgNO}_3 = 0.005203 \text{ g. CN}$, or 0.005808 g. CNS or 0.003546 g. Cl.

Note. In the analysis of compounds containing hypochlorites and chlorides, the conversion of hypochlorites to chlorides by heating with hydrogen peroxide is a great convenience.

For instances in the analysis of bleach liquors, washes, etc., the (OCl) and Cl may be very easily and quickly determined by titrating an aliquot with As₁O₃ and then a similar aliquot with AgNO₃ after converting all the OCl to Cl by warming with H.O.

EVALUATION OF BLEACHING POWDER, CHLORIDE OF LIME, FOR AVAILABLE CHLORINE

When chloride of lime is treated with water, it is resolved into calcium hypochlorite, Ca(OCl), and calcium chloride, CaCl₂. The calcium hypochlorite constitutes the bleaching agent. The technical analysis is confined to the determination of available chlorine, which is expressed as percentage by weight of the bleaching powder.

Procedure. Ten grams of the sample arc washed into a mortar and ground with water, the residue allowed to settle and the supernatant liquor poured into a liter flask. The residue is repeatedly ground and extracted with water until the whole of the chloride is transferred to the flask. The combined extracts are made up to 1000 cc.

To 50-cc. portions (0.5 gram) of the solution, 3 to 4 grams of solid potassium iodide and 100 cc. of water are added and the solution acidified with acetic acid. Iodine equivalent to the available chlorine is liberated. This is titrated with N/10 arsenious acid.

One cc. N/10 arsenious acid = 0.003546 gram Cl. This multiplied by 200 = %Cl.

In France the strength is given in Gay-Lussac degrees, e.g., liters of gas evolved by 2 kilograms of bleaching powder, 0° C. and 760 mm. 100° = 31.78% Cl.

CHROMIUM

Cr, at.wt. 52.0; sp.gr. 6.92; m.p. 1520°; b.p. 2200° C; oxides, CrO₂; Cr₂O₃, CrO₃.

DETECTION

Chromium is precipitated by hydrogen sulphide and anunonium hydroxide as bluish-green, Cr(OH)₃, along with the hydroxides of iron and aluminum (members of previous groups having been removed). The chromic compound is oxidized to chromate by action of chlorine, bromine, sodium peroxide, or hydrogen peroxide added to the substance containing an excess of caustic alkali. The chromate dissolves and is thus separated from iron, which remains insoluble as Fe(OH)₃. The alkali chromates color the solution yellow.

Barium acetate or chloride added to a neutral or slightly acetic acid solution of a chromate precipitates yellow barium chromate, BaCrO₄. Addition of ammonium acetate to neutralize any free inorganic acid aids the reaction.

Lead acetate produces a yellow precipitate with chromates, in neutral or acetic acid solutions.

Mercurous nitrate or silver nitrate gives red precipitates with chromates.

Hydrogen peroxide added to a chromate and heated with an acid, such as sulphurie, nitrie, or hydrochloric, will form a greenish-blue colored solution. Chromates are reduced by hydrogen peroxide in acid solution, the action being reversed in alkaline solution.

Reducing agents, hydrogen sulphide, sulphurous acid, ferrous salts, alcohol form green chromic salts when added to chromates in acid solution.

Ether shaken with a chromate to which nitric acid and hydrogen peroxide are added, is colored a transient blue. Oxygen is given off as the color fades.

$$HCrO_4+3HNO_3 = Cr(NO_3)_8+2H_2O+O_2$$
.

Diphenyl carbazide test. To 5 cc. of the solution containing chromium as chromate, 2 drops of hydrochlorie or acetic acid are added, and 1 drop of an acetic acid solution of diphenyl carbazide (0.2 gram CO $(NH\cdot NH\cdot C_0H_0)_2$ is dissolved in 5 cc. glacial acetic acid and diluted to 20 cc. with ethyl alcohol). A violet pink color is produced in presence of a chromate. Less than 0.0000001 gram chromium may be detected.

Chromic salts are bluish green; chromic acid is red; chromates, yellow; bichromates, red; chrome alum, violet.

The powdered mineral, containing elironium, when fused with sodium carbonate and nitrate, produces a yellow colored mass.

ESTIMATION

Among the substances in which chromium is determined are the following: Chrome iron or chromite, Cr₂O₃·FeOMgO; croeoisite, PbCrO₄: slags; chromic oxide, chrome green, in pigments; chromates and dichromates; chrome steel and ferro-chrome.

Chapter contributed by Wilfred W. Scott.

Preparation and Solution of the Sample

Although powdered metallic chromium is soluble in dilute hydroehloric or sulphuric acid, it is only slightly soluble in dilute or concentrated nitric acid. It is practically insoluble in aqua regia and in concentrated sulphuric acid. Chrome iron ore is difficult to dissolve. It is important to have the material in finely powdered form to effect a rapid and complete solution of the sample. An agate mortar may be used to advantage in the final pulverizing of the substance.

General Procedures for Decomposition of Refractory Materials Containing Chromium. The following fluxes may be used:

- A. Fusion with KHSO, and extraction with hot dilute HCl. The residue fused with Na₂CO₂ and KClO₂, 3:1, or fusion with soda line and KClO₂, 3:1.
 - B. Fusion with NaHSO, and NaF, 2:1.
- C. Fusion with magnesia or lime and sodium or potassium carbonates, 4:1.
- E. Fusion with Na₂O₂, or NaOH and KNO₁, or NaOH and Na₂O₂. Niekel, iron, copper, or silver crucibles should be used for E. Platinum may be used for A, B, or C.

Special Procedures. Materials High in Silica. The finely ground sample, 1 to 5 grams, is placed in a platinum dish and mixed with 2 to 5 ec. concentrated sulphuric acid (1.84), and 10 to 50 cc. of strong hydrofluoric acid added. The solution is evaporated to small volume on the steam bath and to SO, fumes on the hot plate. Sodium carbonate is added in sufficient amount to react with the free acid, and then an excess of 5 to 10 grams added and the mixture heated to fusion and kept in molten condition for half an hour. From time to time a crystal of potassium nitrate is added to the center of the molten mass until 1 to 2 grams are added. (Caution. Platinum is attacked by KNO₃, hence avoid adding a large amount at any one time.) Chromium and aluminum go into solution in the flux, but iron is thrown out as Fe(OH). The cooled fusion is extracted with hot water and filtered from the iron residue. Chromium is in solution together with aluminum. If much iron is present it should be disdissolved in a little hydrochloric acid and the solution poured into boiling 10% solution of potassium hydroxide, the cooled solution + Fe(OH), precipitate is treated with hydrogen peroxide or sodium peroxide to oxidize any chromium that may have been occluded by the iron in the first precipitate. The mixture is again filtered and the combined filtrates examined for chromium.

Sodium Peroxide Fusion. Chrome Iron Ores. One to two grams of finely pulverized ore are placed in a nickel or iron crucible of 50 to 75 cc. capacity and mixed with 5 to 10 grams of yellow sodium peroxide. (Fresh peroxide is best). The mass is gently heated over a Bunsen burner until it melts. The fusion is kept at a low red heat for about fifteen minutes. About 5 grams more of the Na₂O₃ are added and the fusion heated for about ten minutes more. The cooled fusion is dissolved in a casserole with 100 cc. to 150 cc. of peroxide being added to this solution if it appears purple. The excess of peroxide is decomposed by boiling the solution, and to the caustic solution free from peroxide is added 10 to 15 grams of ammonium earbonate or a sufficient quantity of the salt to neutralize four-fifths of the sodium hydroxide present in the solution, as the strong caustie would otherwise dissolve the filter. The solution is now filtered. The insoluble matter is treated on the filter with dilute sulphuric

acid, 1:4. If a portion remains insoluble, it is an indication of incomplete decomposition of the ore, and this residue is again fused with peroxide and treated as above. The combined filtrates contain the chromium.

Since chromates are reduced in presence of free acid and peroxide, the latter

should be expelled before making the solution acid.1

If the chromate is to be precipitated as BaCrO₄ or PbCrO₄, the solution should be acidified with hydrochloric acid. If the reduced solution is to be titrated with potassium permanganate, it is best to use sulphuric acid in neutralizing the caustie solution. Further directions will be given under the method chosen.

Method for Solution of Iron and Steel. See methods at close of chapter.

SEPARATIONS

Chromium, Iron, and Aluminum. If ehromium has been fused with sodium peroxide or earbonate containing a little potassium nitrate, and the fusion extracted with boiling water, most of the chromium goes into solution as a chromate, together with alumina, but some of the chromium is occluded by Fe(OH). If the amount of the iron precipitate is appreciable, and warrants the recovery of occluded ehromium, it is dissolved in hydrochloric acid and the iron reprecipitated by pouring into a solution of strong sodium hydroxide. Before filtering off the iron hydroxide, a little H₂O₂ is added to oxidize the Cr₂O₃, if accidentally present, and the solution boiled and filtered. The combined filtrates will contain all of the chronium and aluminum.

If chromium is present as a chromic salt, instead of a chromate, it is oxidized to the higher form, by adding peroxide (H2O2 or Na2O2) to the alkaline solution. Bromine added to this solution or chlorine gas passed in will accomplish complete oxidation. It must be remembered that in acid solutions hydrogen peroxide, sodium peroxide, or mitrites will eause reduction of chromates to chromic salts (exception, see method for solution of steel), so that these should be boiled out of the alkaline solution before making decidedly acid with hydrochloric or sulphuric acids. Since these are difficult, if not impossible, to completely expel from an alkaline solution, after boiling the strongly alkaline solution, dilute sulphurie acid is added until the solution acquires a permanent brown color (nearly acid), acid potassium sulphate, KHSO4, is added, and the boiling continued.3 This will decompose the bromates and expel bromine, etc., but will not eause the reduction of the chromate, as would a strong acid solution.

Separation of Chromium from Aluminum. This separation is necessary if chromium is to be precipitated as Cr(OII)₁. The sodium chromate and aluminate solutions are made slightly acid with nitric acid and then faintly alkaline with ammonium hydroxide, Al(OH), is precipitated and chromium remains in solution as a chromate.

¹ See Separations.

Br may be added and then NaOH to oxidize Cr and precipitate Fe(OH)1.

Chromic oxide and most of its compounds, except chrome iron stone, may be decomposed by cone. HNO₂+KClO₃ (added in small portions). M. Gröger, Zeitsch. anorg. Chem., 81, 233-242, 1913.

³ KHSO₄ will not eause reduction of chromates. A. Kurtenacker, Zeitsch. anal. Chem., **52**, 401-407, 1913. The Analyst, **38**, 449, page 387.

GRAVIMETRIC METHODS FOR THE DETERMINATION OF CHROMIUM

Precipitation of Chromic Hydroxide and Ignition to Cr2O31

Chromium present as a chromic salt in solution, free from iron and aluminum or elements precipitated as hydroxides, is thrown out of solution by NH₄OH as Cr(OH)₁, the precipitate ignited to the oxide, Cr₂O₃, and so weighed. The presence of hydrochloric acid or sulphuric acid does not interfere.

Reduction. If the chromium is already present as the chromic salt, free from iron and alumina, it may be precipitated directly as the hydroxide by addition of ammonia; otherwise, if present as the chromate, as is the ease when a separation from iron and alumina has been necessary, and in cases where the ehronium has been brought into solution by fusion with an oxidizing reagent, reduction is necessary. This is accomplished by passing SO₂ or H₂S into the slightly acid solution of the chromate, or by adding alcohol to the hydrochloric acid solution and boiling until the solution appears a deep grass green. Twenty ec. of alcohol for every 0.1 grain of Cr has been found to be ample for this reduction. The SO₂ or H₂S should be expelled from solution by boiling, in case either has been used for reduction of the chromate.

Precipitation. Ammonium hydroxide or ammonium sulphide are added in slight excess and the solution boiled for about ten minutes. The solution should be slightly alkaline (litmus), otherwise a few drops of ammonia should be added, but not a large excess; the solution will then settle out clear. A cloudy solution results from prolonged boiling when the solution has become acid; on the other hand, a large excess of ammonia will prevent complete precipitation of chromium and the filtrate will be colored pink or violet. The chromic hydroxide is filtered off on S and S 589 filter paper. Since the precipitate is apt to be gelatinous it is advisable to wash two or three times by decantation and several times on the paper. The well-drained precipitate and filter is ignited wet in a porcelain or platinum crucible, first over a low flame until the paper has been charred, then over a strong gas flame for about thirty minutes, and finally a blast heat for five minutes. The green residue is weighed as Cr_2O_3 .

 $Cr_2O_3 \times 0.6846 = Cr.$

 2 Cr₂O₃, mol.wt., 152; sp.gr., 5.04; m.p., 2059°; insol. in H₂O, slightly sol. in acids, dark green hexagonal.

¹ It is advisable to take such a weight of sample that the ignited Cr₂O₂ does not exceed 0.5 gram in weight.

Determination of Chromium as Barium Chromate

Chromium, present as a chromate, is precipitated from a neutral or faintly acetic acid solution of an alkali chromate by addition of barium acetate or chloride. The BaCrO4 is gently ignited and weighed. The solution should be

free from sulphuric acid or sulphates.

Procedure. The alkali chromate solution is neutralized with nitric acid or ammonia as the caso may require, precautions for avoiding reduction having been observed as indicated under Preparation and Solution of the Sample. 10 cc. of 1 N. BaCl₂ or Bu(C₂Il₃O₂)₂ (approx. 10% sol.) are added to the boiling solution for each 0.1 gram of chromium present. The reagent should be added in a fine stream or drop by drop to prevent occlusion of the reagent by the precipitate. The precipitated chromate is allowed to settle on the steam bath for two or three hours and then filtered into a weighed Gooch crucible and washed with 10% alcohol solution. The precipitate is dried for an hour in the oven, then placed in an asbestos ring suspended in a large crucible with cover and thus heated over a low flame, gradually increasing the heat until the outer crucible becomes a dull red. The cover is removed and the heating continued for five minutes, or until the precipitate appears a uniform yellow throughout. High heating should be avoided. The cooled residue is weighed as BaCrO₄.

> $BaCrO_4 \times 0.2055 = Cr$ $BaCrO_4 \times 0.3002 = Cr_2O_3$ $BaCrO_4 \times 0.7666 = K_2CrO_4$ $BaCrO_4 \times 0.5807 = K_2Cr_2O_2$

NOTES. If the precipitate on the sides of the crucible appears green, it is ignited

until the green color disappears.

If sulphates are present, BaSO4 will be precipitated, hence this method could not be used. In this case either reduction to the chromic sult and precipitation of chromium as Cr(O11), or a volumetric procedure should be followed.

Oxidize chromium with an excess of hydrogen peroxide in alkalinc solution, reduce Oxidize enrollment with an excess of hydrogen peroxide in alkanne solution, require in acid solution with ferrous sulphate and titrate with permanganate. Decomposition of hydrogen peroxide is accelerated by heat and by presence of sodium sulphate or ferric salts. Salts of nickel cobalt, or manganese, decompose H₂O₂ energetically and lower results are obtained. F. Bourin and A. Senechal. Compt. 1end., 157, 1528-31.

Mercurous Nitrate Method. To the chromate solution (containing 0.2-0.5 g. Ccr) heated to boiling is added 2 grains of Na₂CO₂ and then a saturated solution of pure mercurous nitrate in 1/10 sol. conc. HNO₃ (free from nitrous oxides), added in slight

excess. The mixture is boiled until the brown precipitate changes to the orange crystalline form. The precipitate is filtered and washed with hot water, then ignited three hours over a Meeker burner until the weight is constant.

1 If the filtrate appears yellow, chromate is indicated, the solution should be reduced and the chromium precipitated as $Cr(OH)_3$. If the filtrate is pink, it should be boiled until it appears green and $Cr(OH)_3$ precipitates. These precipitates should be included in the above calculation for chromium.

BaCrO₄, mol.wl., 253.47; sp.gr., 4.498; solubility per 100 cc. H₂O, 0.00038¹⁰ and 0.0043 hot. Soluble in HCl and in HNO₁; yellow rhombic plates.

VOLUMETRIC METHODS FOR THE DETERMINATION OF CHROMIUM

Potassium Iodide Method for Determination of Chromium

Chromium present as a chromate is reduced in acid solution by addition of potassium iodide and the liberated iodine titrated by standard sodium thiosulphate. The method depends upon the following reactions:

(a)
$$2CrO_1+6KI = Cr_2O_1+3K_2O+6I$$
.

(b)
$$I_2 + 2Na_2S_2O_4 = 2NaI + Na_2S_4O_6$$
.

The presence of large quantities of Ca, Ba, Sr, Mg, Zn, Cd, Al, Ni, Co, H₂SO₄, HCl, does not interfere.1

Procedure. The alkali chromate solution containing not over 0.17 gram Cr 2 and free from Fe₂O₃, is made nearly acid with H₂SO₄, boiled with 20 ee. of 30% potassium acid sulphate to decompose bromates or expcl Br, Cl, or H2O2' as the ease may require, more KHSO4 being added if necessary. If the solution is not acid it is made so with sulphuric acid and 5 cc. of the acid per 100 cc. of solution is added in excess.3 About 2 grams of solid potassium iodide are added and, after five minutes, the liberated iodine is titrated with N/10 Na₂S₂O₃ solution. When the green color of the reduced chromate begins to predominate over the free iodine color (brownish red) a little starch solution is added and the titration with the thiosulphate continued until the blue color of the starch compound is just destroyed, care being taken not to confuse the green color of the reduced chromium with the blue of the starch.

One ce. of N/10 Na₂S₂O₃ 4 =0.001733 grain Cr.

Determination of Chromium by Reduction of the Chromate with Ferrous Salts

The procedure may be used for the determination of chromium in presence of ferric iron and alumina. Hydrochloric or sulphuric acids do not interfere. If hydrochloric acid is present in solution, the K2Cr2O7 back titration should be made. In presence of H2SO4 either KMnO4 or K2Cr2O7 titrations may be made. The method depends upon the reduction of soluble chromates by ferrous salts, the excess being determined by titration.

Reactions. a. $2\text{CrO}_3 + 6\text{FeO} + xs\text{FeO} = \text{Cr}_2\text{O}_3 + 3\text{Fe}_2\text{O}_3 + xs\text{FeO}$.

b. xsFeO is oxidized by standard oxidizing reagent to Fe₂O₄.

Sodium peroxide is generally used for oxidation of chromium. The solution is now neutralized with acid, the iodide added and 10 ce. of strong HCl. The liberated iodine is immediately titrated.

² If desired, stronger solution of titration reagents may be used, and consequently a larger sample taken. A normal sol. of Na₈S₂O₃ may be used to advantage with 1 gram samples of chronium salts or hydrates, where Cr exceeds 10%.

Sutton recommends for every 0.5 gram K₂Cr₂O₇ present to add .5 gram KI and 1.8 gram H₂SO₄ per 100 cc. of solution. If more K₂Cr₂O₇ is present, increase the KI and H₂SO₄, but not the water.

4 If desired, a normal solution of thiosulphate may be used with one gram sample when the chromium present exceeds 10 per cent.

Procedure: Reduction. The sample, containing not over 0.17 gram chromium present as a chromate, is boiled to expel oxidizing reagents according to the method described under the potassium iodide procedure for chromium. The solution is made acid, if not already so, and about 5 cc. conc. H₂SO₄ per 100 cc. of solution, added in excess. Tenth normal ferrous ammonium sulphate solution containing free sulphuric acid is added until the solution changes from yellow through olive green to deep grass green. For every 0.1 gram of chromium about 65 to 70 cc. of N/10 ferrous salt solution should be added. After five minutes, the excess of this reducing reagent is titrated either with permanganate or with dichronate as directed below.

Potassium Permanganate Titration. To be used in presence of free sulphuric

acid, free hydrochloric acid being absent.

Tenth-normal potassium permanganate solution is run into the reduced chromate until the green color gives place to a violet tinge. At the end-point the solution appears to darken slightly. A little practice enables one to get this with accuracy. A slight excess of permanganate gives the solution a pinkish color, readily distinguishable in the green. Addition of 3 to 4 cc. syrupy phosphoric acid gives a sharper end-point. The color should hold one minute. Potassium Dichromate Titration. N/10 $K_2Cr_2O_7^{-1}$ is run into the solution

until a drop of the sample placed on a white glazed surface with a drop of potas-

sium ferricyanide reagent no longer gives a blue color.

Calculation. From the total ferrous ammonium sulphate added, subtract the cc. of back titration (the reagents being exactly N/10), the difference gives the cc. of ferrous salt required for chromium reduction. If reagents are not N/10, multiply cc. titrations by factor converting to N/10.

Cc. ferrous animonium sulphate $\times 0.001733 = Cr$.

 $Cr_2O_1+3O=Cr_2O_6$. : $Cr=1\frac{1}{2}O$ or =3H; hence $\frac{1}{3}$ mol. wt. Cr per liter =N sol.

Determination of Small Amounts of Chromium²

Advantage may be taken of the color produced by chromates in solution in determining small amounts, the depth of color depending upon the amount of chromate in solution. The method possesses the usual disadvantage of colorimetric procedures in that there is always room for doubt as to whether the element sought is entirely responsible for the color of the solution.

Procedure. The solution containing the sample is nearly neutralized with sodium carbonate, the reagent being added until a slight cloudiness results. The solution is now cleared with a few drops of sulphuric acid, and then sufficient excess of a strong solution of sodium thiosulphate added to precipitate aluminum, chromium, manganese, etc. The precipitate is filtered off, dissolved in the least amount of dilute nitric acid, then filtered from the precipitated sulphur and diluted to 300 to 400 cc. Chromium is now oxidized by adding 10 ec. of 0.2% silver nitrate solution, about 10 grams each of ammonium nitrate and persulphate. After boiling for about twenty minutes, sufficient hydrochloric acid is added to decompose any permanganate present and to precip-

¹If desired, a larger sample may be taken and N/5 or N solutions used in titration. It is advisable to titrate chromium salts, e.g., over 1.0% Cr, with normal solutions, so that one gram sample may be taken for analysis.

M. Dittrich, Zeitsch. anorg. Chem., 80, 171-174, 1913.

itate the silver, and a few cc. added in excess. The solution is again boiled for about ten minutes and then filtered. The filtrate is treated with a little sodium phosphate to repress the color of traces-of iron that may be present and made to a definite volume.

The solution may now be compared with a standard solution containing the same amounts of acids, manganese, alumina, etc., as are present in the sample, tenth normal potassium, dichromate being run into this standard solution until its color matches that of the sample. The burette reading is taken and the chromium calculated.

One ec. of N/10 $K_2Cr_2O_7 = 0.00173$ gram Cr.

Notes. Prolonged boiling after addition of hydrochloric acid to the solution of the chromate will cause its reduction. A green tint usually indicates that the chromate has been reduced.

The test may be carried on in the presence of sulphuric, hydrochloric, phosphoric, hydrofluoric, and nitric acids. Alumina, manganese, and small amounts of iron do not interfere.

Organic matter should be destroyed by either calcining the sample or by oxidation by taking to fumes with sulphuric acid. The presence of this prevents precipitation of chromium.

Colorimetric Estimation of Small Amounts of Chromium with Diphenyl Carbazide

Diphenyl carbazide, CO(NH·NH·C₆H₅)₂, gives a violet color with chromic salts or chromates in acid solution, the intensity of the color being proportional to the concentration of the chromate. Less than 0.0001 milligram of chromium may be detected by this reagent. The following procedure may be used for determining traces of the element:

I to 2 grams of the substance, which has been brought into solution with water or acid, is treated with an excess of sodium peroxide to oxidize chromium, and the solution filtered. The filtrate, concentrated to 75–80 cc. is acidified with hydrochloric, so that there is present about 5 cc. of free concentrated acid (sp. gr. 1.19) per 100 cc. of Solution. The Solution transferred to a Nessler tube, is treated with 1 cc. of the reagent, and the color compared with standards containing the same reagents as the sample examined. A colorimeter may be used and comparison made with a standard according to details given for the colorimetric comparison of traces of lead or titanium.

Preparation of Diphenyl Carbazide Reagent. One tenth of a grain of the compound is dissolved in 10 cc. of glacial acctic acid and diluted to 100 cc. with ethyl alcohol.

Diphenyl carbazide may be made by heating a mixture of 15 grams of urea with 50 grams of phenyl hydrazine four hours, finishing at 155° C. The solid product is crystallized three times with alcohol. A light straw-colored product is obtained. A white product is obtained if the urea is cut down to 5 grams, the yield, however, is only 25 per cent of that obtained by the first method and the compound possesses no advantages.

Determination of Chromium in a Soluble Chromate

To a concentrated solution of potassium iodide is added a known amount of the soluble chromate dissolved in a little water. The liberated iodine is now titrated with standard thiosulphate reagent.

 $N/10 \text{ Na}_2S_2O_3 = 0.001733 \text{ g. Cr.}$

Determination of Chromium in Chromite

About 0.2 g. of the powdered cre is fused with ten times its weight of Na₂O₂ in a porcelain crucible, placed inside a larger crucible. The melt is dissolved in water and the Fe(OH)₂ filtered off. The filtrate is evaporated to dryness, the residue taken up with as little water as possible and about two grams of KI added. The solution is now diluted to about 300 ee. and the liberated iodine titrated with standard thiosulphate.

 $N/10 \text{ Na}_2S_2O_3 = 0.001733 \text{ g. Cr.}$

Rapid Method for Determination of Chromium in Steel¹

Three grams of steel are dissolved in 100 ee. sulphurie acid 1 to 4. If it does not dissolve rapidly a crystal of $(NII_4)_2(SO_4)_2$ will hasten it. After solution add cone. $IINO_2$ until iron is oxidized. Boil for one minute, add 10 ee. 5% AgNO₅, remove from flame and add crystals of Am. Persulphate until all the chromium is oxidized as shown by the manganese being converted to Permanganate. Boil until persulphate is broken up and then add 5% sod. chloride until permanganate is destroyed as shown by the disappearance of the red color. An excess of salt sol, should be avoided. Cool thoroughly and titrate with ferous sulphate, determining the excess with permanganate. These solutions are standardized on a known sample of chrome steel.

Two determinations run simultaneously will cheek within .02%.

¹ Method by A. I. Appelbaum, the chemist analyst, J. T. Baker Chem. Co.

DICHROMATE-DIPHENYLAMINE METHOD FOR DETERMIN-ING CHROMIUM IN IRON ORES AND ALLOYS

The method takes advantage of Knop's reaction with diphenylamine (Journal of the American Chemical Society, Fcb., 1924) in titration of iron with potassium dichromate, here chromate is titrated with a solution of iron. The procedure is applicable to the determination of chromium in ores, ferrochrome, chrome steels and soluble chromates.

Reagents

Potassium Diehromate. 0.1 N solution.

Ferrous Ammonium Sulphate or Ferrous Sulphate. 0.1 N solution.

Phosphoric-Sulphuric Acid. 150 cc. sulphuric acid (d. 1.84) and 150 cc. phosphoric acid (d. 1.70) diluted to 1000 cc. with water.

Diphenylamine Indicator. 1 g. of the reagent dissolved in 100 ce. of sulphurie acid (d. 1.84). Use 4 drops (0.2 cc.). Deduct 0.1 ce. blank.

Sodium Peroxide. Fresh powder.

Procedure


The amount of the sample should be such as contains between 0.002 to 0.08 g. chromium. The finely powdered material is fused with ten times its weight of sodium peroxide in a niekel or iron crucible. (It appears unnecessary to heat to molten condition, provided the mass sinters.) After heating at dull red heat for ten minutes, the crueible is cooled and then upset in a 400 cc. beaker containing about 100 ec. of water. (The beaker should be immediately covered as the reaction is violent.) The crucible is washed out and removed, and the solution boiled to expel the peroxide. The solution is cooled and dilute sulphuric acid added until the alkali is neutralized and the solution is slightly acid. (Iron hydroxide dissolves, but manganese dioxide remains in suspension.1) If manganese is present, it is removed by filtration. To the filtrate 15 ee. of phosphorie-sulphuric acid mixture is now added and, from a burette, a measured excess of standard ferrous ammonium sulphate. (With an excess of ferrous salt the solution turns green.) Four drops (0.2 ee.) of diphenylamine indicator are now added and the excess of ferrous salt titrated with standard potassium dichromate. The green color changes to a blue green and then to an intense blue or violet color. (If the end-point is overrun, titrate back with ferrous sulphate to a green color and repeat the dichromate titration. Convert the reagents to exact equivalents, i.e., terms of 0.1 N solution.) The difference between the cc. of ferrous solution and the diehromate reagent multiplied by the chromium equivalent represents the chromium in the sample. 1 ec. 0.N solution is equivalent to 0.00173 g. chromium.

Notes. 1. If it is desired to filter off the iron and manganese precipitates, it will be necessary to filter through asbestos or to neutralize the caustic with ammonium carbonate (1.5 times as much as peroxide used in fusion), boil and filter through paper. The ferric hydroxide occludes chromium, hence solution of the iron with acid and reprecipitation is necessary to recover chromium.

2. If the iron precipitate has been dissolved and much manganese is present, the precipitate may be filtered off. Manganese dioxide does not occlude an appreciable amount of chromium.

3. Chrome steels may be dissolved with acid followed by treatment with permanganate to oxidize the iron.

5. It is evident that neither ferric salt nor dichromate alone produce the blue color, but an excess of dichromate in presence of ferric iron. If much chromium is present, the end point may be overrun owing to the depth of color, the excess of dichromate causing a greenish blue color to reappear. Back titration with ferrous sulfate will restore the blue or violet color, and an excess will change the color to blue green.



By courtesy of Arthur H. Thomas Company, Philadelphia, Pa.

Fig. 26a.-Colorimeter.

DIRECTIONS FOR THE USE OF A DUBOSCQ TYPE OF COLORIMETER

The mirror is turned so that the two halves of the field appear to be equally illuminated with the cups clean and empty. The solutions are then poured into the cups. The cup containing the standard solution is then lowered to a definite thickness of the standard solution between the bottom of the cup and the end of the plunger. With this movement the half of the field corresponding to the standard solution is seen to darken, while the other half remains luminous and colorless. If the cup containing the unknown solution is now moved in its turn, the two halves of the field are brought to the same intensity, after which the height at which the two liquid columns display this equal absorptive power is read by means of this scale. The proportion of coloring matter in two solutions is inversely proportional to the heights of the two columns necessary to obtain the same intensity of illumination, thus if the standard tube is at a 10 mm, and the solution under examination is the same intensity of color at 20 mm, the latter is just one-half the concentration of the standard. This is usually expressed by the formula:

Color of test solution
Color of standard solution
Height of solution to be tested

If, therefore, the scale reading is 20 mm. for the standard, and 15 mm. for the solution to be tested, the formula reads: $\S = 1.33$. If, for example, the standard solution contains 4 ml. of coloring matter in 100 ml., the solution under test will be found to contain 4 x 1.33 = 5.32 ml. in 100 ml.

DETERMINATION OF CHROMIUM IN STEEL— CHLORATE METHOD

The following method is recommended for routine by the A.S.T.M.

Reagents

Nitrie Acid. 1000 cc. HNO3 (d. 1.42) and 1200 cc. water.

Potassium-Ferricyanide Indicator. 0.1 g. salt per 50 ec. water. Prepare fresh each day the indicator is used.

Potassium Dichromatc. 5 grams of salt per liter. Adjust to 0.1 N.

Potassium Permanganate. 2 grams of salt per liter, standardized against sodium oxalate. The solution adjusted so that 1 cc. is equal to 0.001 g. chromium (1 cc. = .1% per 1 g. sample). 1 g. Na₂C₂O₄ = 0.2584 g. Cr; hence 0.001 g. Cr=0.00387 g. Na₂C₂O₄ and 0.1548 g. Na₂C₂O₄ should require 40 cc. titration.

Ferrous Sulphate. 25 grams of ferrous ammonium sulphate dissolved in 900 cc. water and 100 cc. (1:1) H₂SO₄ added.

Procedure

A sample of 1 gram of steel in a 300 cc. Erlenmeyer flask is dissolved in 30 cc. of the nitric acid and the solution evaporated rapidly to about 15 cc. 50 cc. of strong HNO₃ (d. 1.42) are added and 1 g. of sodium or potassium chlorate. The solution is boiled down to about half the volume. Either of the following procedures are recommended.

1. The solution is diluted with 100 cc. of water, the manganese filtered off and washed with hot water. The filtrate containing the chromium is cooled, diluted to 600 cc., an excess of the ferrous sulphate solution added and the excess titrated with potassium dichromate reagent, using the spot test with potassium-ferricyanide indicator, the spot no longer showing a blue color of ferrous iron.

Note. In place of the outside indicator, the editor, W. W. Scott, recommends the use of the internal indicator, diphenylamine (0.2 cc. of a solution 1. g. salt per 100 cc. strong H₂SO₄). See method, page 164a.

2. 10 cc. of hydrochloric acid (1:1) are added and the solution boiled until the manganese dissolves. The cooled solution is diluted to 300 cc. An excess of ferrous sulphate is added and the excess titrated with standard potassium permanganate solution to a faint pink color.

Notes. The ferrous ammonium sulphate should be compared with the dichromate or permanganate reagents the day it is used and the ratio of the reagents established. Oxidation may be effected of the manganese with potassium permanganate added to a boiling solution of the steel dissolved in sulphuric acid (in volume of about 150 cc.), a large excess of the permanganate being avoided, as it is claimed that MnO₂ carries down Cr. The A.S.T.M. method now recommends either of two methods: (a) precipitation of iron as hydroxide with ammonia, filtering off a portion and determining Cr in the filtrate, or method 2 above. The editor finds that the Fe(OH)₄ is largely responsible for holding up chromium, and advises against this procedure (a).

COBALT

Co, at.wt. 58.97; sp.gr. 8.7918; m.p. 1478°; b.p. unknown; Oxides, Co₁O₄, Co₂O₅, CoO, CoO₂.

DETECTION

After the removal of the elements precipitated by hydrogen sulphide from acid solution, a little nitric acid is added to the solution to oxidize to the ferric state any ferrous salts which may be present, and ammonia is added until its odor is distinctly perceptible, to precipitate iron, aluminum and chromium. This precipitate is removed by filtration and hydrogen sulphide passed through the ammoniacal solution to precipitate cobalt, nickel, manganese and zinc. After collecting this precipitate it is washed thoroughly with cold hydrochloric acid of approximately 1.035 specific gravity, to remove manganese and zinc. A small quantity of the residue is finsed with borax in the loop of a platinum wire. A blue color in the cold bead indicates cobalt. This test is masked in the presence of largo quantities of nickel. In this case the residue is dissolved in hydrochloric acid to which a few drops of nitric acid have been added and the solution evaporated to dryness. The residue is redissolved in water, acidified with hydrochloric acid and the cobalt precipitated with a hot solution of nitroso-beta-naphthol in 50% acetic acid. A brick red precipitate indicates cobalt.

Potassium sulphocyanate, KCNS, produces a red color with cobalt. If to this neutral or faintly acid solution are added twice its volume of alcohol and four times its volume of ether and the solution shaken the ether layer is colored blue by cobalt. If iron is present a solution of sodium thio-sulphate, Na₂S₂O₃, is added until the red color disappears, the solution filtered and then treated with the alcohol-ether mixture.

Potassium Nitrite, KNO₂, added to a neutral or slightly acid solution containing acetic acid, will precipitate cobalt as a yellow complex nitrite having the formula K₂Co(NO₂)₄.

A solution of dicyandiamidine sulphate and sodium hydroxide added to a cobalt solution to which ammonia has been added until the odor is distinctly discernible, and containing from 10 to 20 ec. of 10% sugar solution, will change the color of the solution to red or reddish violet. If large quantities of nickel are present the color will be yellow or reddish yellow, after which the nickel will separate out in brilliant crystals, leaving the cobalt in solution, coloring it as described above.

A concentrated solution of ammonium sulphocyanate added to a cobaltous solution colors it blue. On dilution this becomes pink. Amyl alcohol or a mixture of amyl alcohol and ether 1:1, added to this and shaken, extracts this blue compound. Iron sulphocyanate, Fc(CNS), likewise colors the ether-

¹ If a relatively large amount of iron is present, the basic acetate method of separation is necessary, as iron occludes cobalt.

Chapter contributed by W. L. Savell.

alcohol extract red, which may mask the cobalt blue. By addition of sodium carbonate solution ferric hydroxide precipitates, while the cobalt color will remain after this treatment.

ESTIMATION

Cobalt is usually estimated as metal; either reduced by hydrogen from the ignited oxide or reduced by electrolysis from an ammoniacal solution of its salts. Sometimes, however, it is estimated as oxide; usually as Co₂O₄. The reduction of the oxide by hydrogen may be carried out in conjunction with any process giving an oxide, hydroxide, carbonate, nitrate, chloride or an organic compound, as a final product.

The reduction of the metal, in solution, by electrolysis, must be accomplished in a strongly ammoniacal solution free from copper and nickel, as these metals are deposited with the cobalt on the cathode. When desirable the copper and nickel may be estimated after the electrolysis by dissolving the deposit from the cathode and proceeding in the usual manner.

Preparation and Solution of the Sample

General Procedure for Ores. The orcs containing cobalt vary so widely in their chemical nature that it is difficult to lay down a method for treating all ores. However, as the principal ores contain the cobalt as a sulphide or arsenide the same general methods may be used in the majority of cases. In all cases it is necessary to prepare the sample for treatment by grinding finely. Usually either of the above ores may be brought into solution by heating with strong nitric acid or a mixture of nitric and hydrochloric acids, except silver-bearing ores, which may usually be dissolved in a mixture of nitric and sulphuric acids.

While it is desirable to use no more acid than is necessary to bring the sample into solution, an excess will not interfere, as it may be driven off by evaporation and in the event of determining the cobalt electrolytically it is essential that the solution be free from nitric acid, so that this evaporation becomes part of the procedure.

In the case of especially refractory ores or oxides of cobalt or nickel, a fusion with potassium bisulphate will usually be found sufficient as a preliminary treatment to enable it to be brought into solution. Under certain conditions, however, it has been found necessary to fuse the ore with sodium peroxide in a silver crucible, dissolving the cobalt oxide formed in hydrochloric acid. In somewhat less refractory ores of a silicious nature a preliminary fusion with a mixture of sodium carbonate and potassium carbonate with subsequent solution in hydrochloric acid or sulphuric acid, if the ore is a silver-bearing one, will be found satisfactory.

Cobalt Oxides. Cobalt oxide, gray or black, may be fused with potassium bisulphate, and the melt leached with water; or they may be treated with sulphuric acid, in which they dissolve slowly; or with hydrochloric acid, in which they dissolve more rapidly.

Metallic Cobalt, Nickel and Cobalt Alloys. Metallic cobalt dissolves readily in nitric acid, as do nickel and the ordinary cobalt alloys. There are some alloys of cobalt, however, which require fusion with sodium peroxide before they become amenable to further treatment. Among these are certain cobalt-chromium alloys.

SEPARATIONS

Separation of the Ammonium Sulphide Group Containing Cobalt from the Hydrogen Sulphide Group—Mercury, Lead, Bismuth, Copper, Cadmium Arsenic, Antimony, Tin, Gold, Molyhdenum, etc.

Hydrogen sulphide passed into a hydrochloric acid solution containing from 5 to 7 cc. of concentrated hydrochloric acid per 100 cc. of solution, precipitates only the members of that group and silver, whereas the members of the subsequent groups remain in solution. If the solution is too acid, lead and cadmium are not completely precipitated.

Separation of the Ammonium Sulphide Group from the Alkaline Earths and Alkalies. Ammonium sulphide, free from earbonate, added to a neutral solution containing the above elements in the presence of ammonium chloride, precipitates only the members of this group; the alkaline earths metals, magnesium and the alkalies remain in solution. A second precipitation should be made if large quantities of the alkaline earths or alkalies are present.

Separation of Cobalt and Nickel from Manganese. The solution of the chlorides or sulphates of cobalt or nickel is treated with an excess of sodium carbonate and then made strongly acid with acetic acid. About 5 grams of sodium acetate for each gram of cobalt or nickel present is now added, the solution diluted to 200 cc. and heated to about 80° C. and saturated with hydrogen sulphide. Cobalt and nickel are precipitated as sulphides and the manganese remains in solution. The filtrate is concentrated, and colorless ammonium sulphide added when the cobalt and nickel that may have passed in solution from the hydrogen sulphide treatment, will be precipitated. The treatment should be repeated with the second filtrate to ensure complete precipitation of the cobalt and nickel.

Separation of Cobalt from Nickel. Among a number of methods for effecting this separation the following give good results:

A. Nickel is removed from the solution by precipitation with dimethylglyoxime. The details of the procedure may be found in the gravimetric methods for the determination of nickel. Cobalt remains in solution.

B. Cobalt is precipitated by nitroso-beta-naphthol, leaving nickel in solution. Details of the procedure are given under gravimetric methods for determination of cobalt.

C. Cobalt is precipitated as potassium cobalti-nitrite, niekel remaining in solution. Details of the procedure are given under gravimetric methods for the determination of cobalt.

Separation of Cobalt from Zinc. Zinc is precipitated from weak acetic or formie acid solution by hydrogen sulphide as zinc sulphide. Cobalt, nickel and manganese remain in solution. The details of the procedure are given under the methods of determination of zinc.

GRAVIMETRIC METHODS FOR THE DETERMINATION OF COBALT

Precipitation of Cobalt by Potassium Nitrite

Cobalt may be precipitated from a solution made slightly acid with an excess of acetic acid by adding a hot solution of potassium nitrite. The cobalt is precipitated as potassium cobalti-nitrite, K₃Co(NO₂)₆, very completely, after standing for a period of six hours in a warm place. This method has the advantage of making possible the separation of cobalt from nickel and iron, although it has the one disadvantage, for commercial purposes, of requiring a long time to complete the determination.

After bringing the material into solution and separating the Procedure. silica and members of the first and second groups in the usual manner, the solution is boiled to eliminate hydrogen sulphide. Oxidize the iron present with a little hydrogen peroxide and evaporate the solution to a syrup. Take up in a little water and neutralize with a practically saturated solution of sodium earbonate. Render slightly acid with acetic acid and add an excess of 1:1 acetic acid. Heat to almost boiling and add solution of 50% potassium nitrite containing 100 cc. of glacial acetic acid per liter, also heated to nearly boiling. This solution should be added slowly to the solution of the sample which should be agitated, preferably by rotating gently while the addition is being made. The sides of the beaker should be washed down with a 1% solution of potassium nitrite containing 1 cc. of glacial acetic acid per liter. Allow to stand for at least six hours and if possible overnight. Filter through thick Swedish filter paper without previous wetting. As this precipitate shows a very decided tendency to ercep, considerable carc is required to keep it well down in the apex of the filter-paper cone. Wash about ten times with the warm nitrite solution mentioned above. Transfer to a beaker by removing the filter paper from the funnel and opening it into the beaker with the outside of the paper against the glass. This leaves it in a convenient position for washing. The bulk of the precipitate is washed off with 10 cc. of 1:1 sulphuric acid, heated to about 80° C. This should leave only a slight film of precipitate on the paper. Keep the solution in the beaker at about 80° C. to assist in dissolving the precipitate and wash the paper with the hot sulphuric acid solution five times, using about 10 ee. each time. Gradually withdraw the filter paper from the top of the beaker during the washing operation. Give the paper a final wash with hot water and squeeze the last drops from it into the beaker. Evaporate and allow to fume strongly for ten minutes. Set the beaker in a cooling trough and add water until the volume is about doubled. Neutralize and make slightly ammoniacal and then add an excess of 50 ec. of strong ammonia and electrolyze as described under Electrolysis in Reduction of Cobalt by Electrolysis, page 170.

Precipitation of Cobalt by Nitroso-beta-Naphthol 1

Nitroso-beta-naphthol, C₁₀H₄(NOH), added to a hydrochloric acid solution of cobalt, precipitates cobalti-nitroso-beta-naphthol, Co(C₁₀H₄O(NO))₁; niekel, if present, remains, in solution. The method is especially suitable for the determination of small amounts of cobalt in the presence of comparatively large

¹ Burgess, Z. Angew., 1896, 596.

170 COBALT

amounts of nickel. The cobalt precipitate is voluminous, so that the sample taken for the determination should not contain over 0.1 gram of cobalt. The reagent will also precipitate copper and iron completely from solution, and silver, bismuth, chromium and tiu partially; but mercury, lead, cadmium, arsenic, antimony, aluminum, manganese, nickel, glucinum, calcium and magnesium remain in solution.

Procedure. To the solution containing the cobalt is added a freshly prepared hot solution of nitroso-beta-naphthol, in 50% acetic acid, as long as a precipitate is produced. After allowing it to settle, more of the reagent is added to insure complete precipitation of the cobalt. The compound is allowed to settle for two of three hours, the clear solution decanted through a filter and the precipitate washed by decantation with cold water, then with warm 12% hydrochloric acid solution to remove the nickel, and finally with hot water until free of acid.

The brick-red precipitate is dried, then ignited in a weighed platinum erucible (Rose erucible), first over a low flame and finally at a white heat, the erucible being covered by a platinum cover (Rose erucible type) with a platinum tube, through which is passed a slow current of oxygen. The residue is weighed as Co₃O₄. The oxide may be reduced in a current of hydrogen and weighed as metallic cobalt. Ignited in the presence of CO₂ the oxide CoO is formed.

Edler finds it unnecessary to ignite the cobalt in a current of oxygen. Ignition in air is best.

Precipitation of Cobalt by Electrolysis 1

Metallic cobalt is readily deposited from an ammoniacal solution of the sulphate, but in the presence of copper and nickel these are also completely precipitated on the cathode; so, in ease it is desired to determine the cobalt alone it is necessary to separate these metals from the solution before electrolysis or to determine them separately after electrolysis in a solution of the metallic deposit. In practice the copper is usually separated before electrolysis and the nickel, if determined separately, is estimated afterward by one of the methods given under Nickel, the cathode deposit being dissolved for this purpose.

Procedure. After preparation and solution of the sample the usual separations with hydrogen sulphide in acid solution are made if necessary. In most cases it is necessary to pass hydrogen sulphide through the warmed solution for at least one hour to insure the complete precipitation of arsenic. Filter and boil to expel hydrogen sulphide. Add 5 cc. hydrogen peroxide to insure oxidation of iron compounds to ferric state and add anunonium hydroxide until slightly alkaline to litinus. Filter off ferric hydroxide and wash with water containing a small quantity of animonium hydroxide. Redissolve and reprecipitate this ferric hydroxide in the above manner, using a little hydrogen peroxide in each instance, until the last traces of cobalt have been removed from it, keeping the filtrates, which should be as small as possible, to add to the main filtrate. If much iron is present this is best removed as the basic acetate.

Electrolysis. If the treatment of the iron precipitate has made a large volume of solution this may be reduced by evaporation, after which 50 ec. of strong ammonia are added and the solution electrolyzed, using direct current of 2 volts and 0.5 ampere per square decimeter. The electrodes should be platinum, the anode a spiral wire and the eathode either a hollow cylinder or a cylindrical gauze. By agitating the solution, raising the voltage and the cur-

Low, "Technical Methods of Analysis."

rent density, the rate of deposition may be increased. In a properly agitated solution the deposition may be completed in forty-five minutes.

The current should not be cut off until the solution is tested to determine if the electrolysis is complete. This is done by mixing a drop or two of the solution from the end of a stirring rod with a few drops of ammonium sulphide. If the electrolysis is complete the mixture will remain colorless, but if some cobalt still remains in the solution the mixture will be darkened. After the electrolysis is complete the cathode is earefully removed from the solution and dipped into a beaker of clean water, after which it is washed with alcohol, preferably ethyl alcohol.

If a large number of electrolytic determinations are to be made, it is convenient to have a wide-mouthed bottle with a well-ground-in glass stopper or a cork stopper for holding the alcohol for the preliminary washing. The mouth should be large enough to receive the cathode without pouring out the alcohol. The cathode may be lowered into the alcohol in this bottle, which should only be partly filled, and then rinsed again by pouring fresh alcohol over it and allowing it to drain into the wide-month bottle. This allows a great many eathodes to be washed with a comparatively small quantity of alcohol. Directly after the final washing with alcohol the cathode is passed through the flame of a Bunsen burner and the alcohol ignited. After this is entirely burned off the cathode is placed in a desiccator to cool and when cool is weighed. The increase in weight of the cathode is the weight of cobalt in the sample if the solution had been free from nickel before electrolysis. If the nickel remained in the solution the increase in weight of the cathode represents the cobalt and nickel in the sample. If it is desired to determine the cobalt and nickel together the increase in weight of the cathode is divided by the weight of the sample and multiplied by 100 to obtain the percentage. If it is desired to obtain the percentage of cobalt separately, the plate is dissolved from the cathode in a few ce. of nitrie acid and the nickel determined in the resulting solution by precipitation with dimethyl-glyoxime as described in the chapter on Nickel, after which the cobalt is found by difference.

Cobalt in Cobalt Oxide 1

One gram of finely ground cobalt oxide is either fused with 10 grams of potassium bisulphate or heated with 20% sulphuric acid until dissolved. If the fusion method is used the melt is extracted with water and acidified with sulphuric acid. Arsenic and copper are precipitated by passing hydrogen sulphide through the warmed solution, which should be diluted to about 200 cc. for about one hour. These are removed by filtration and the cobalt determinated by one of the above methods. The following procedure is one of the most satisfactory:

Procedure. If it is desired to determine the nickel separately, as is usually the ease, this is first precipitated with dimethylglyoxime as described in the chapter on Nickel, after boiling the solution to expel hydrogen sulphide. It is then evaporated to firmes of sulphur trioxide and taken up with twice its volume of water. The free acid is neutralized with ammonium hydroxide and an excess of 50 ec. of strong ammonium hydroxide added. The solution is made up to 250 cc. and electrolyzed as under Precipitation of Cobalt by Electrolysis.

¹R. W. Landrum, Proc. Am. Ceramic Soc., 12, 1910.

Cobalt in Metallic Cobalt and Ferro-cobalt

Cobalt is usually determined in metallic cobalt and ferro-cobalt by electrolysis, after separation of the elements precipitated by hydrogen sulphide in acid solution and elimination of iron, if present in large quantities. In case it is desired to estimate nickel separately it is precipitated by dimethylglyoxime as described in the chapter on Nickel, before electrolysis, taking the solution down to sulphur trioxide funes, diluting with water and adding aminonium hydroxide in excess and electrolyzing. In ease the solution is electrolyzed before separating the nickel the determination of this element may be made in the solution of the electrolytic deposit dissolved in acid, the cobalt then found by difference.

Procedure. Dissolve 1 gram of well-mixed drillings in the least possible quantity of nitric acid and add 20 cc. of 1:1 sulphuric acid. Evaporate to fumes of sulphur trioxide and allow to fume strongly for ten minutes. This insures the complete elimination of nitrates, which would interfere subsequently with the electrolysis. Cool and dilute carefully with 20 cc. of water. Heat the solution to nearly boiling and pass in hydrogen sulphide for one hour to precipitate copper and arsenic. Filter and boil the solution to expel the last traces of hydrogen sulphide. Add 2 cc. of hydrogen peroxide to oxidize ferrous compounds to ferric state, and add amnionium hydroxide until slightly alkaline to litmus paper and heat to boiling. Filter off the ferric hydroxide and wash with water containing a small quantity of ammonium hydroxide. Redissolve the precipitate in a little 1:1 sulphuric acid, adding a little hydrogen peroxide to keep the iron in the ferric state, and reprecipitate in the same manner as that described above. In presence of comparatively large amounts of iron the basic acetate separation of iron is necessary, as Fc(OH), occludes cobalt and nickel. The filtrates from these precipitations are added to the main one.

In determining the cobalt in metallic cobalt it is not necessary to filter off the iron precipitate, if this is small, as it has been found by W. L. Rigg, of Deloro, Ontario, that this precipitate does not interfere with the accuracy of the determination. The iron content may be up to 5% without interfering seriously with the electrolysis.

The solution is made annuoniacal with 50 ec. of strong ammonium hydroxide and electrolyzed as described above.

Cobalt in Metallic Nickel

The cobalt in metallic nickel may be determined by precipitation with potassium nitrite from a solution of the sample containing an excess of acetic acid. The precipitate is filtered off and dissolved in hot sulphuric acid solution, after which the solution is evaporated to fumes of sulphur trioxide and carefully diluted. The excess of acid is neutralized and made strongly ammoniacal with ammonium hydroxide. The solution is then electrolyzed as previously described.

Procedure. Dissolve 5 grams of thoroughly mixed drillings in a minimum quantity of nitric acid. Evaporate to a syrup. Care must be exercised at this point to prevent evaporating too far and decomposing the nitrates. Dissolve in 50 cc. of water. Neutralize with a practically saturated solution of sodium carbonate. For this purpose a dropping bottle is very convenient. Render slightly acid with acetic acid and add an excess of 10 cc. of 1:1 acetic acid. Heat

to almost boiling and add 10 cc. of a 50% solution of potassium nitrite to which has been added 10 cc. of glacial acetic acid per 100 cc. of solution. This solution must also be nearly boiling and should be added while gently rotating the nickel solution. Wash down the sides of the beaker with a 1% solution of potassium nitrite containing 1 ec. glacial acetic acid per liter. Allow to stand for at least six hours and preferably overnight. Filter through a thick, 9-cm. filter paper without previous wetting. Considerable care is required to keep the precipitate well down in the apex of the filter paper cone, as it creeps very badly. Wash about ten times with the warm nitrite solution mentioned above. Lift gently from the funnel and open the filter paper into a beaker. Lay the paper against the side of the beaker with the outside against the glass. This leaves the paper adhering to the side of the beaker in a most convenient position for washing. Wash down as much of the precipitate as possible with about 10 ee. of 1:1 sulpluric acid solution, heated to about 80° C. This should leave only a slight film of precipitate on the paper. Keep the solution at about 80° C. and wash the paper five times with the warm sulphuric acid solution, using about 10 cc. each time, gradually withdrawing the paper from the top of the beaker. Give a final wash with hot water and squeeze the last drops from the filter paper into the beaker. Evaporate and allow to fume strongly for ten minutes. Add water in a cooling trough until the volume is about doubled. Neutralize with ammonium hydroxide and add an excess of 50 cc. of strong ammonium hydroxide and electrolyze as described in Precipitation of Cobalt by Electrolysis.

Cobalt in Ores and Enamels 1

The determination of cobalt in ores and enamels is usually made by a slight variation of the above methods. The silica is separated in the usual manner by taking down to dryness with hydrochloric acid and the warmed solution is treated with hydrogen sulphide to precipitate sulphides insoluble in acid solution. Aluminum, chromium and iron are precipitated by adding ammonium hydroxide to the oxidized solution. In the enamel industry it has been the practice to follow R. W. Landrum's method, in which the cobalt, manganese and nickel are precipitated together as sulphides and filtered off. The manganese is dissolved from this precipitate with cold hydrogen sulphide water acidified with one-fifth its volume of hydrochloric acid (sp.gr. 1.11). The residue of cobalt sulphide is burned in a porcelain crucible, dissolved in aqua regia and evaporated with hydrochloric acid. The platinum and copper, if they are present, are thrown down by passing hydrogen sulphide through the solution. The filtrate is made ammoniacal and the cobalt is precipitated with hydrogen sulphide. This is filtered off and washed with water containing a small quantity of ammonium sulphide. The precipitate is either ignited and weighed as oxide or reduced in hydrogen to metallic cobalt, taking care to cool it thoroughly in an atmosphere of hydrogen before allowing it to come into contact with the atmosphere of the room, as finely divided cobalt is decidedly pyrophoric and oxidizes readily, particularly if reduced at a low temperature.

Instead of igniting the sulphide precipitate it may be dissolved in hot 1:1 sulphuric acid solution with the aid of a little nitric acid and treated as described under Precipitation of Cobalt by Electrolysis.

¹ R. W. Landrum, Trans. Am. Cer. Soc., 12, 1910.

Cobalt in Steel

This determination is a modification of the nitroso-beta-naphthol method already described, as worked out in the laboratory of the Firth Stirling Steel Company, McKeesport, Pa. The procedure as described by Mr. Giles, Chief Chemist, is as follows.

Two grams of the sample are weighted into a 500-ce. Erlenmeyer flask and dissolved in 50 cc. of concentrated hydrochloric acid. When the sample is completely decomposed 10 ce, of concentrated nitric acid are added to oxidize the iron, tungsten, etc. The solution is evaporated to 10 ec.; 50 cc. of water are added; the contents of the flask are then transferred to a 500-cc. volumetric flask and cooled to room temperature. A fresh solution of zine oxide is added in slight excess, the contents of the flask diluted to the mark, well mixed, transferred back to the original Erlenmeyer flask and allowed to settle. Filter 250 cc. (equivalent to 1 gram of the sample) through a dry filter paper, transfer it to a 500-ce. flask, then add 6 ec. of concentrated hydrochloric acid.

The solution, which should now be between 300 and 350 cc. in volume, is heated to boiling and 10 cc. of freshly prepared solution of nitroso-beta-naphthol (1 gram of salt to 10 ee. glacial acetic acid) are added for each 0.025 gram of cobalt present. Continue to heat for two minutes, remove from plate, shake well, and set aside until the bright red precipitate settles, which will only take a few minutes. Filter the hot solution and wash the flask out with hot 1:1 hydrochloric acid and then wash the flask out with hot acid of the same strength. Wash the paper alternately with hot (1:1) hydrochloric acid and hot water until it has been washed five times with the acid, then wash ten times with hot water. The precipitate is transferred to a quartz or porcelain erucible, heated gently to expel the carbonaccous matter, then at a high temperature until ignition is complete. After cooling the crucible is weighed and the weight of the residue (Co₂O₄) is multiplied by 0.734 to obtain the percentage of cobalt present. If desired the Co₂O₄ may be reduced in hydrogen and weighed as metal.

Sulphide Pyrophosphate Method (Dufty). Cobalt is precipitated as sulphide and this is converted to ammonium cobalt phosphate. The preeipitate is filtered and washed, then ignited and the cobalt weighed as pyrophosphate. Traces of cobalt passing into the filtrate are recovered by precipitation as sulphide, this is filtered off, ignited to oxide and added to results

obtained. (Oxide is Co₅O₄.)

COBALT 175

Volumetric Methods for the Determination of Cobalt

Perborate Method. Nickel and cobalt are oxidized to trivalent oxide or hydroxides by various oxidizing agents but neither the cobalt and nickel salts of the trivalent metals are stable. Both the trivalent hydroxides liberate iodine when treated with acids and potassium iodide and form the nickelous or cobaltous salts, e.g.,

$$C_0(OH)_2 + KI + 3HCI = C_0(CI_2 + I + KCI + 3H_2O)$$
.

Cobalt is more readily oxidized than nickel and when oxidized, forms the more stable compounds. Cobaltic hydroxide may be formed by treating the sulphate with potassium hydroxide and hydrogen peroxide while nickel is not affected even on boiling with these reagents. This procedure, however, has not been satisfactory as a method of analysis on account of the difficulty of removing the excess hydrogen peroxide which persists in the precipitate even after boiling and prolonged washing.

After some rather extended tests, W. D. Engle and R. G. Gustavson have found that the differential oxidation may be very satisfactorily accomplished by means of sodium perborate in the presence of potassium hydroxide and the excess of this oxidizing agent readily decomposes on boiling. Advantage is then taken of the reaction stated above and the iodine liberated is titrated with a standard sodium thiosulphate solution.

Procedure. The ore, metal or other material may be dissolved with acids or brought into solution by any of the usual methods and the metals of the Cu and Fe groups including manganese removed in the usual way. The solution so obtained may contain niekel, cobalt, zinc and the metals of the alkaline and alkaline earth groups, but must be free from any substances capable of liberating iodine from an acid solution of potassium iodide. In some cases, it is desirable to precipitate Fe by means of zinc oxide or zinc hydroxide emulsion, making up the mixture so obtained containing the emulsion to a certain volume and after allowing the precipitate to settle, filtering aliquot portions and treating as described. This solution with a volume of about 100 cc. is made acidified with dilute H2SO4 using about 5 cc.'s excess (1:5) and then adding one or two grams of dry sodium perborate. Sodium hydroxide is added to a strong alkaline reaction. The mixture is boiled for ten minutes to decompose the excess of perborate. This solution is then cooled to room temperature and after one gram of potassium iodide is added, acidified with dilute H2SO4 the potassium iodide slowly reduces the cobaltic hydroxide liberating iodine. Any attempt to hasten the determination at this point will cause low results as cobaltic hydroxide itself is not readily soluble and must be reduced to the cobaltus form before going into solution. This reduction consequently takes place very slowly and care must be exercised to make certain that all the precipitate has been entirely dissolved before the titration is attempted.

176 COBALT

After the complete solution of the precipitate, the liberated iodine is titrated with standard solution of sodium thiosulphate, using starch paste as an indicator in the usual manner.

As it is somewhat difficult to obtain cobalt compounds of known cobalt content, the sodium thiosulphate solution may be standardized by means of potassium bichromate in the usual manner and the factor for cobalt calculated from this determination.

Since one $K_2Cr_2O_7 = 6I = 6Co$, then the potassium bichromate factor of the solution multiplied by 1.2027 gives its cobalt factor.

General Procedure for Determining Nickel and Cobalt in Ores—Method of Schoeller and Powell 1

1. The ore is free from copper, manganese, lime, and magnesia; presence of arsenie immaterial. Dissolve in nitric or hydrochloric acid or both, but convert metals into nitrates; take almost to dryness, avoiding separation of basic salts. Add tartaric acid (10 times the weight of trivalent metals) dissolved in a minimum of water. Add 50 cc. of strong ammonia whilst cooling, and 3 to 5 gms. of solid potassium iodide according to the quantity of nickel or cobalt present. Allow to stand, stoppered, with occasional shaking, for fifteen minutes, or longer if eobalt predominates. Filter on loose paper, wash with ammoniacal iodide solution (4 per cent of potassium iodide dissolved in 4 vol. strong ammonia: 1 vol. water). Dissolve precipitate in dilute hydrochloric acid, filter off gangue, precipitate cobalt as phosphate, titrate nickel in filtrate.

2. The ore contains copper, otherwise the same as 1. Proceed as above to the point where the iodide precipitate is dissolved in dilute hydrochloric acid. Decolorize the liquid with sulphurous acid, heat just to boiling, allow to cool, filter off insoluble gangue and cuprous iodide, apply phosphate separation.

3. General procedure for complex ores free from manganese. Dissolve in a suitable acid, precipitate heavy metals with hydrogen sulphide. To the filtrate add ammonium chloride and a slight excess of ammonia; saturate with hydrogen sulphide, taking care to precipitate the whole of the nickel. Dissolve the precipitate in aqua regia, evaporate almost to dryness, etc., as under 1.

4. The ore contains manganese. (a) Subordinate amounts. Apply one of the precoding methods; titrate cobalt ammonium phosphate with N/5 acid (not hydrochloric), or dissolve the weighed cobalt pyrophosphate in sulphuric acid. Determine the manganese colorimetrically with persulphate and silver nitrate in an aliquot portion of the cobalt solution, obtaining cobalt by difference.

(b) Moderate to large amounts. Dissolve the mixed iodide precipitate in dilute acid, and precipitate nickel and cobalt sulphides from an acetic solution. Or neutralize the acid solution and precipitate cobalt and nickel as xanthates. Either precipitate is dissolved in aqua regia and the two nictals separated as before.

(c) With nickel ores free from cobalt, manganese does not interfere in the cyanide titration in the presence of citrate.

¹ By W. R. Schoeller and A. R. Powell, The Analyst, Aug., 1919.

Cu, at.wt. 63.57; sp.gr. 8.89²⁰; m.p. 1083 (in air 1065); b.p. 2310; oxides Cu₂O and Cu₂O.

DETECTION

Copper is precipitated in an acid solution by H₂S gas, along with the other members of the hydrogen sulphide group. The insolubility of its sulphide in sodium sulphide is a means of separating copper from arsenic, antimony, and tin. The sulphide dissolves in nitric acid (separation from mercury) along with lead, bismuth, and cadmium. Lead is precipitated as PbSO₄ by sulphuric acid and bismuth as the hydroxide, Bi(OH)₃, upon adding ammonium hydroxide. Copper passes into the filtrate, coloring this solution blue,

Cu(OH)2.2NH4OH · (NH4)2SO4.

Flame Test. Substances containing copper (sulphides oxidized by roasting), when moistened with hydrochloric acid and heated on a platinum wire in the flame, give a blue color in the reducing flame and a green tinge to the oxidizing flame.

Wet Tests. Nitric acid dissolves the metal or the oxides (sulphides should be roasted), forming a green or bluish-green solution. Ammonium hydroxide added to this solution will precipitate a pale blue compound, which dissolves in excess with the formation of a blue solution. (Nickel also gives a blue color.)

Hydrogen sulphide passed into a copper solution which is free of SO₂ or an oxidizing agent, but somewhat acid with a mineral acid, precipitates at once brownish black CuS or Cu₂S (distinction from nickel, cobalt and zinc), which is difficulty soluble in strong, hot HCl (distinction from antimony), insoluble in fixed alkaline polysulphides (distinction from gold and platinum), soluble in alkaline eyanides (distinction from lead, bismuth, cadmium, mercury and silver), soluble in nitric acid (distinction from sulphide of mercury), with production of a bluish solution (distinction from all other metals except silver).

Potassium ferrocyanide precipitates from an acid or neutral solution of a cupric salt reddish-brown cupric ferrocyanide, which can be confused only with similarly colored precipitates from inolybdenum or uranium solutions.

Cupric salts in halogen acid solution are reduced to colorless cuprous compounds by metallic copper, stannous chloride and sulphurous acid; and in alkaline solution are reduced by grape sugar, arsenious or sulphurous acids.

ESTIMATION

The estimation of copper is required in the following substances: In orest

¹Ores, copper pyrites, chalcopyrite, Cu₂S·Fe₂S₃; copper glance chalcocite, Cu₂S (gray to bluish-black); malachite, CuCO₂·CuOH·H₂O (green); azurite, 2CuCO₂·-CuOH₂O (blue); cuprite, red copper, Cu₂O; malaconite, CuO (black); dioptase, CuOSiO₂H₂O (green vitreous); atacamite, CuCl₂3Cu(OH)₃; bornite, Cu₂FeS₃; brochantite, 4CuO·SO₂·3H₂O; corellite, CuS; crysocolla, CuO·SiO₂·2H₂O; tetrahedrite, 4Cu₂S·Sb₂S₃; termantite, 4Cu₂S·As₂S₃; olirenite, 4CuO·As₂O₃·H₂O.

Chapter contributed by W. W. Scott and W. G. Derby.

of copper, in which it occurs as native copper or combined as sulphide, oxide, carbonate, chloride, silicate and basic sulphate. In furnace slags, mattes, concentrates, blister copper, bottoms. The determination of copper is required in the analysis of alloys containing copper, brass, bronze, etc. It is occasionally looked for as an undesirable impurity in food products. It is determined in salts of copper, in insecticides, germicides, etc.

Preparation and Solution of the Sample

Hydrochloric and sulphuric acids are effective in dissolving metallic copper only in presence of an oxidizing agent; nitric acid is the most active solvent. The oxides of copper may be dissolved in hydrochloric or sulphuric acid, but nitric acid is commonly used. Some refractory furnace products are with most certainty decomposed by treatment with hydrofluoric and fuming sulphuric acid followed by a bisulphate fusion.

Ores. If the ore consists practically of a single mineral, the fineness of the sample need not exceed 80 mesh. If the ore is a mixture of minerals, lean and

rich in copper, the laboratory sample should pass a 120-mesh sieve.

Metallic particles or masses are separated at some stage in the process of sampling and made into a separate sample. If the metallic portion is a small percentage of the total sample and consists of particles, the copper value of which is known to vary by a few percent, no attempt is made to refine the sample of such, but a large portion, 10-100 grams, is taken for analysis and the copper determined in an aliquot part of the solution. If the metallic masses are a large percentage of the sample, large of size, or consisting of particles differing widely in copper content, a weighed amount of I to 50 lbs, is melted in a graphite crucible, with addition of suitable fluxes, such as powdered silica or lime, if necessary. Separate samples are made of the weighed products of the fusion and the copper content of the material before melting calculated from their analyses. amount of sample taken for assay depends upon the richness of the ore, homogeneity of the material and the commercial importance of the determination. As a rule in the assay for purchase and sale, a I gram test portion is taken of finely pulverized samples containing over 20% copper, 2 to 3 grams of 30% ores and 5 grams of ores containing less than 10% copper.

Sulphide Ores and Matte. One to five grams of the sample are dissolved by adding 10-20 ee. dilute nitric acid (1.2 sp.gr.), or 10 ee. strong nitric acid saturated with potassium chlorate, and allowing the mixture to stand in a warm place for about 15 minutes before applying heat. Decomposition is completed by evaporating to small volume in a casserole and continuing to dryness after addition of 10 cc. hydrochloric acid, or by adding 5-10 cc. 50% sulphuric acid, to the assay in a flask or tall beaker and heating to fumes. Continuing the first procedure, the residue is taken up by warming with 20 ec. 10% H₂SO₄, diluting, boiling and filtering the residue of silica, lead sulphate and silver chloride from the copper solution. Continuing the second procedure, the mass of anhydrous salts are dissolved with water, silver dissolved by just sufficient NaCl solution if the determination is to be by the electrolytic method, and the solution filtered; after it has reached room temperature when the per cent of silver present is high.

Oxidized Ores with the exclusion of details relating to the oxidation of sulphur are brought into solution by the same method of treatment as sulphide ores.

Notes. The sulphur that appears upon adding acid to the ore, with proper precautions, should be yellow. If it is dark and opaque, the solution has been overheated, and some of the ore has been occluded. It is advisable in this case to remove the globule of sulphur and oxidize it separately with bromine and nitric acid, then boil out the bromine and add the solution to the rest of the sample.

Sulphide ores may be treated according to the procedure reconnended for iron pyrites in the chapter on Sulphur, the ore being decomposed with a mixture of bromine and carbon tetrachloride, 2:3, followed by nitrie acid and then sulphuric acid.

Treatment of Matte Slag. Only by quick quenching of the molten slag is decomposition of the sample by acids made possible, without preliminary treatment with hydrofluoric acid. As a rule lime slags are readily decomposed by mixed acids. Extremely acid, and high iron slags are apt to be refractory and are decomposed with most certainty by treatment with hydrofluoric acid followed by fusion with potassium bisulphate.

The following scheme of attack, which also can be applied to silicious ores,

with skilful manipulation gives very satisfactory results:

One gram of the 100 mesh fine slag is placed in a 250 cc. beaker of Jena glass, moistened with water, mixed with 3 cc. of sulphuric acid (sp.gr. 1.54), and then, while the particles of the slag are in suspension through rotary movement of the beaker, 15 cc. hydrochloric acid are added. The silica is gelatinized in 2 or 3 minutes by heating the beaker over a free flame. One cc. nitric acid followed by a few drops of hydrofluoric acid are added, and the heating continued in a hood until the material is nearly dry, and then to strong sulphuric acid fumes on a hot plate. When cool, 4 cc. of sulphuric acid are added.

The remainder of the procedure depends upon the method that is to be followed in the determination of copper. If the electrolytic method is preferred, 3 cc. of nitric acid are add:d; the mass heated until solution is effected, the liquid diluted to 175 cc. with cold, distilled water, and copper plated out in 20-35 minutes, using a rotating anode and $2\frac{1}{2}$ amperes current.

If the iodide method is to be followed, without addition of other acid than sulphuric, the mass is again heated to fumes. When cooled, 25-30 cc. water and 5 cc. hydrochloric acid are added and the liquid boiled until clear. After addition of 40 cc. saturated solution of sodium acctate, 4½% solution of sodium fluoride is added until the color of ferric acctate is discharged, and then an excess of 10 cc. When cold, titration is commenced, using a thiosulphate solution with a copper equivalent of 0.0005 g. per cc.

The following quick method has been systematically and satisfactorily checked for a long period by a hydrofluoric acid-bisulphate fusion method, by which copper, precipitated as a sulphide, is ignited, the oxide dissolved in nitric acid and

copper determined by electrolysis.

Three grams of the 100 mesh fine sample are placed in an 800 cc. resistance beaker. The slag is spread over the bottom of the beaker, and while in motion 5 cc. of sulphuric acid are added rapidly to prevent the slag gathering into a mass. After addition of 40 cc. hydrochloric acid, the beaker is heated over a bare flame for about 3 minutes until the silica has gelatinized. To the hot

¹ White, Chemist Analyst, July, 1912.

solution nitric acid is added, drop by drop, until the liquid becomes dark brown. To the liquid, while in a state of agitation, 1-2 cc. hydrofluoric acid are added and the mixture boiled until the solution is complete. The liquid is diluted to 400 cc. and saturated with hydrogen sulphide and the precipitate filtered and washed as usual. The copper sulphide is ignited in a silica crucible; the residue, if washing of the precipitate has been thorough, can be brushed into a 250 cc. beaker and dissolved with a few cc. of nitric acid. After boiling gently to expel nitrogen gases, the free acid is neutralized with ammonia, and the solution then acidified with a slight excess of acetic acid. The cold solution is titrated by the iodide method, using a thiosulphate solution having a copper equivalent of about 0.0005 g. per 1 cc.

Metals. A casting of a copper alloy and even of refined copper is not homogeneous, and the zones of segregation of the constituents of the alloy (usually roughly parallel to the cooling surfaces) are the more sharply defined as the conditions which favor diffusion of the eutectic prevail, therefore, unless the casting be quite thin and quickly cooled, a satisfactorily representative sample of it cannot be obtained from a single drill hole. A single easting may be sampled by complete cross-sectional cuts by a suitable saw or by a series of drill holes located in such a manner as to amount substantially to one or more cross-sectional cuts. Steel is usually present as a contaminant of the drill or saw shavings from refined copper and the tougher alloys and should be removed by a magnet. Crude copper, such as blister or black copper, is sampled by drilling one hole in each piece of a definite fraction of the total pieces of the average lot. The position of the hole in successive pieces is changed to conform with a pattern or "templet" which will cover a quarter, or half, or the complete top surface of the average piece, the "templet" is divided into squares, preferably about 1 inch on a side, and in the centre of each square the 1-inch hole is drilled. The drillings are ground to pass a 20-mesh screen and the sample then withdrawn by means of a riffic sampler.

Sampling by splashing a molten stream with a wooden paddle and by slowly pouring the metal into water are methods frequently practiced. The size of the particles, the degree of homogeneity and the limit of accuracy of result required are factors which determine whether one or more grams of the sample should be taken for analysis.

Iron Ores and Iron Ore Briquettes. A 5-gram sample of the finely divided material is fused in a large platinum dish with 40 grams of pure potassium bisulphate. If the ore is high in sulphur, it should be roasted by heating to redness in a silica or porcelain crueible before placing in the platinum dish and mixing with the bisulphate.

The cooled fusion is broken up into small pieces and placed in an 800-cc. beaker with clock-glass cover. Three hundred cc. of hot water and 25 cc. of strong hydrochloric acid are added and the fusion is boiled until it passes into solution. If an appreciable residue remains, the solution is filtered, the residue fused with additional bisulphate, then dissolved in hot dilute acid and the filtrate added to the first solution. Silica and barium sulphate remain in the residue.

The solution is now reduced and copper precipitated according to directions given under "Separation of Copper by Precipitation in Metallic Form by a more Positive Element," aluminum powder being preferably used.

The precipitated copper is filtered free from iron and other commonly occurring impurities, then dissolved by pouring on the precipitated metal 30 cc. of hot dilute nitric acid, 1:1, followed by 10 cc. of bromine water and then 10 cc. of hot water. The filter paper is removed, ignited and the ash added to the copper solution. The whole solution is now evaporated to small volume and determined, preferably, by the "Potassium Iodide" method as described under the volumetric procedures.

Steel, Cast Iron, and Alloy Steels. From 3 to 5 grams of steel, depending upon the amount of copper present, are dissolved in a mixture of 60 cc. of water and 7 cc. of sulphuric acid (sp.gr. 1.84) in a 250-cc. beaker. After all action has ceased, a strip of sheet aluminum, 1½ ins. square, bent so that it will stand upright in the beaker, is placed in the solution.

After boiling the solution for twenty to twenty-five minutes, which is sufficient to precipitate all of the copper in the sample, the beaker is removed from the heat and the cover and the sides washed down with cold water. The tiquid is decanted through an 11-cm. filter, the precipitate washed three times with water, then placed with the filter in a 100-cc. beaker, and 8 cc. of concentrated nitric acid and 15 cc. of water are poured over the aluminum and the solution heated to boiling. This hot solution is poured over the precipitate and filter in the 100-cc. beaker, and boiled until the paper becomes a fine pulp, only a few minutes being required. The solution is filtered, the residue washed several times with hot water and copper determined in the filtrate by the electrolytic or iodide methods.

SEPARATIONS

Separation of Copper as Cuprous Thiocyanate. Isolation of copper from solutions containing iron, nickel, cobalt, zinc, cadmium, arsenic, antimony and tin may be accomplished by this method. When much arsenic is present, precipitation should be from a solution in which hydrochloric is the only free strong acid. Unless previously removed from the solution, lead, mercury, tellurium and the precious metals will contaminate the precipitate. Selenium may be a contaminant when present in considerable quantity, sometimes when the only free acid is sulphuric, always when hydrochloric acid is present.

Cuprous thiocyanate, besides being the medium of separation of copper from interfering elements preliminary to its determination by the standard electrolytic, iodide or cyanide methods, is the basis of a number of other more or less useful gravimetric and volumetric methods of determining copper. The details of the procedure of procuring the precipitate vary to some extent with its object.

When the intention is to secure in the precipitate substantially all the copper from the solution, the procedure in the main is as follows: To the cold, concentrated and very slightly acid copper solution which must be free of any oxidizing agent, sulphur dioxide, gaseous or in solution, or a solution of an alkaline bisulphite or metabisulphite is added somewhat in excess of the quantity theoretically required to reduce all the copper and ferric iron present, or until saturation of the liquid with SO₂.

¹ W. B. Price, Jour. Ind. Eng. Chem., Vol. 6, No. 2, p. 170.

Cool the liquid if hot through the formation of H_2SO_3 , and add then with constant stirring a solution of alkali thiocyanate of about normal strength until precipitation ccases. Reaction is $2CuSO_4 + 2KCNS + H_2SO_3 = 2Cu-CNS + 2II_2SO_4 + K_2SO_4$. It is common practice to continue introduction of SO_2 throughout precipitation. Let the precipitate stand until it is white and the liquid above it is clear. The presence of $FeSO_4$ accelerates conversion of cupric to cuprous thiocyanate when sulphuric is the only free acid. Filter with the aid of reduced pressure through doubled filter papers of tight texture. Wash with cold water until a washing is obtained which gives no or very slight indication of thiocyanate when tsted with a ferric salt.

The precipitate is inclined to float and creep with the capillary film of fluid, so precautious must be taken in its manipulation to avoid loss of copper on account of this characteristic.

The collected precipitate may now be treated in several ways which will produce a solution fit for the determination of copper by one of the standard methods. (a) Transfer the filter and precipitate to a porcelain or silica crucible which is very much larger than the volume of the wet precipitate, dry slowly in an oven or muffle and finally incinerate. Some operators made the final washing with 20% alcohol to facilitate drying or with a weak solution of an alkali nitrate to aid incineration. Dissolve the residue in the erucible with hot, strong nitric acid. (b) The point of the filter is punctured and the precipitate washed with as little water as possible into a flask or tall beaker. The filter is finally cleansed of adherent precipitate by washing with dilute nitric acid. The filter is dried, incinerated and dissolved separately or added to the main precipitate before its decomposition. Add 15 cc. strong nitric acid for each gram or fraction of a gram of copper present and let the covered beaker or funnel-closed flask stand in a warm place until the precipitate is dissolved, then boil until solution is free of the nitrogen gases. It is the practice of some to add now 10-15 cc. sulphuric acid and evaporate to fumes. Because evolution of gas during dissolution of the precipitate is profuse, care must be taken to expel the gas slowly to prevent boiling over.

The method as described is rather tedious in its operation and therefore is commonly carried out with modifications which may include: Employing a mixture of the precipitating and reducing agents (for instance, 25 grams alkali thiocyanate with an equal or larger amount of alkali bisulphite in a liter solution); quickening settlement of the precipitate by letting the assay stand in a warm place or even bringing the fluid to boiling; filtering through asbestos, alundum or porous stoneware; washing with hot water. Some of these modifications yield a certain amount of copper to the filtrate because of the appreciable solubility of cuprous thiocyanate in warm or hot water. Consistent with the value of the determination, the amount so dissolved is disregarded, accounted for by an empirical correction, or recovered by expelling SO₂ and concentrating filtrate and washings by boiling, precipitating with H₂S and determining copper, usually by a colorimetric method.

COPPER 182a

Separation of Copper by Precipitation in Metallic Form by a More Positive Element. Metallic aluminum or zine is more commonly used in this procedure. A strip of pure aluminum or zine, placed in the neutral or slightly acid solution, causes the complete deposition of copper. To obtain quick precipitation, a sheet of aluminum, 2.5 by 14 cm., is bent to form a triangle, placed in a covered 150 cc. beaker containing the copper solution, which should be not much over 75 cc. in volume and should hold about 10% free H₂SO₄. Boil 7-10 minutes. (Low, "Technical Methods of Analysis.") The copper is removed mechanically from the displacing metal and dissolved in nitric acid and then estimated, or the aluminum may be dissolved with the copper.

A method of precipitation by means of powdered aluminum is recommended especially for separation of copper from large amounts of iron, iron ores and iron ore briquettes. The solution of the bisulphate fusion of the iron ore is heated until bubbles appear over the bottom of the containing beaker. Aluminum powder is now added in small portions at a time, in sufficient quantity to reduce the iron, the solution becoming colorless. The solution is now licated until the aluminum completely dissolves. Metallic copper is precipitated. It is advisable to add 25 ce. of water saturated with H₂S gas to precipitate traces of copper in solution. The solution is filtered while hot through a close thick filter, and washed six times, keeping the residue covered with water to prevent oxidation by air. The copper is now dissolved in hot dilute nitric acid, evaporated to small volume and determined by the procedure preferred. The potassium iodide method gives excellent results.

Separation of Copper from Members of the Ammonium Sulphide and Subsequent Groups by Precipitation as Copper Sulphide in Acid Solution. The solution containing free hydrochloric or sulphuric acid is saturated with H₂S gas, the precipitated copper sulphide (together with the members of the group), is filtered and washed, first with water containing H₂S and finally with a little pure water. The residue is dissolved in nitric acid and the resulting solution

examined for copper.

Removal of Silver. This element is precipitated as the insoluble chloride, AgCl, by addition of hydrochloric acid, and may be removed by filtration, copper

passing into the filtrate.

Removal of Bismuth. Upon adding ammonium hydroxide to a solution containing copper and bismuth the latter is precipitated as Bi(OH), and may be removed by filtration. Copper passes into the filtrate as the double ammonium salt. Ammonium carbonate or potassium cyanide may be used instead of animonium hydroxide.

Removal of Lead. Lead is precipitated by sulphuric acid as PbSO, and

may be removed by filtration, copper passing into the filtrate.

Removal of Mercury. The sulphide of mercury remains undissolved when the precipitated sulphides are treated with dilute nitric acid, copper sulphide

dissolving readily.

Removal of Selenium and Tellurium. Selenium can be eliminated from a copper solution by evaporating several times to dryness with hydrochloric acid. Saturation with SO₂ of a slightly acid sulphate of copper solution which contains about twice as much silver as selenium and boiling then to expel most of the gas, will precipitate selenium and tellurium free of copper, also nearly all the silver. Precipitation of the remainder of the silver as AgCl helps to retain the fine precipitate on the filter.

182b COPPER

Removal of Arsenic, Antimony, Tin, Selenium and Tellurium. Copper in minor quantity may be separated from these elements by passage of H₂S into the solution made slightly alkaline with sodium hydrate; after addition of about a gram of tartarie acid if iron is present. Copper sulphide remains insoluble also when the mixed sulphides precipitated from an acid solution are treated with a hot mixture of sodium sulphide and hydrate. These elements in minor quantity, whose presence in the electrolyte for copper determination is an objectionable impurity, are removed very satisfactorily by adding enough ferric iron to the solution to make the total iron present about twenty times that of the combined impurity, making ammoniacal and filtering after settling. Some copper is retained in the precipitate. Moderate amounts of arsenic may be climinated as arsenious fluoride by the method employed to expel silica from an assay. Oxidizing agents must not be present.

In an alloy tin and antimony may be precipitated as oxides by evaporation of the solution of the alloy with strong nitric acid. A slight amount of copper may remain insoluble.

Separation from Cadmlum. The sulphides in a solution of dilute sulphurie acid, 1:4, are boiled and H₂S gas passed in for twenty minutes, the solution being kept at boiling temperature. Cadmium sulphide dissolves while copper sulphide remains unaffected. The solution is filtered hot, the air above the filter being displaced by CO₂ to prevent oxidation. Traces of eadmium are removed by repeating the operation. (Method by A. W. Hofmann.)

GRAVIMETRIC METHODS Methods of Isolating Copper

Separation of Copper as Cuprous Thiocyanate. Isolation of copper from solutions containing iron, nickel, cobalt, zinc, cadmium, arsenic, antimony and tin may be accomplished by this method. When much arsenic is present, precipitation should be from a solution in which hydrochloric is the only free strong acid. Unless previously removed from the solution, lead, mercury, tellurium and the precious metals will contaminate the precipitate. Sclenium may be a contaminant when present in considerable quantity, sometimes when the only free acid is sulphuric, always when hydrochloric acid is present.

Cuprous thioeyanate, besides being the medium of separation of copper from interfering elements preliminary to its determination by the standard electrolytic, iodide or eyanide methods, is the basis of a number of other more or less useful gravimetric and volumetric methods of determining copper. The details of the procedure of procuring the precipitate vary to some extent with its object. Low grade copper ores may be conveniently determined by this method.¹

Procedure. To the cold, concentrated and very slightly acid copper solution (which must be free of any oxidizing agent) sulphur dioxide, gaseous or in solution, or a solution of an alkaline bisulphite or metabisulphite is added somewhat in excess of the quantity theoretically required to reduce all the copper and ferric iron present.

The liquid is cooled if hot, and then, with constant stirring, a solution of alkali thiocyanate of about normal strength is added until precipitation ceases. Reaction: $2\text{CuSO}_4 + 2\text{KCNS} + \text{H}_2\text{SO}_3 + \text{H}_2\text{O} = 2\text{CuCNS} + 2\text{H}_2\text{SO}_4 + \text{K}_2\text{SO}_4$. It is common practice to continue introduction of SO_2 throughout precipitation. The precipitate is allowed to stand until it is white and the liquid above it is clear. The presence of FeSO₄ accelerates conversion of cupric to cuprous thiocyanate when sulphuric is the only free acid. The precipitate is filtered off with the aid of reduced pressure through doubled filter papers of tight texture and washed with cold water until a washing is obtained which gives but very slight indication of thiocyanate when tested with a ferric salt.

The precipitate is inclined to float and creep with the capillary film of fluid, so precautions must be taken in its manipulation to avoid loss of copper on account of this characteristic.

The collected precipitate may now be treated in several ways which will produce a solution fit for the determination of copper by one of the standard methods. (a) The filter and precipitate are transferred to a porcelain or silica crucible which is very much larger than the volume of the wet precipitate, dried slowly in an oven or muffle and finally incinerated. Some operators made the final washing with 20% alcohol to facilitate drying or with a weak solution of an alkali nitrate to aid incineration. The residue is dissolved in the crucible with hot, strong nitric acid. (b) The point of the filter is punctured and the precipitate washed with as little water as possible into a flask or tall beaker. The filter is finally cleansed of adherent precipitate by washing with dilute nitric acid. The filter is dried, incinerated and dissolved separately

¹ With high grade ores or copper bullion a trace of copper (usually less than 0.0005 g. Cu) will pass into the filtrate when the copper precipitated amounts to 0.5 gram Cu. The loss with low grade copper ores is negligible.

or added to the main precipitate before its decomposition. 15 ec. strong nitric acid is added for each gram or fraction of a gram of copper present and the covered beaker or funnel-closed flask allowed to stand in a warm place until the precipitate is dissolved, then boil until solution is free of the nitrogen gases. It is the practice of some to add now 10-15 ec. of sulphuric acid and evaporate to fumes. Because evolution of gas during dissolution of the precipitate is profuse, eare must be taken to expel the gas slowly to prevent boiling over.

Separation of Copper by Precipitation in Metallic Form by a More Positive Element. Metallic aluminum or zine is more commonly used in this procedure. A strip of pure aluminum or zine, placed in the neutral or slightly acid solution, causos the complete deposition of copper. To obtain quick precipitation, a sheet of aluminum, 2.5 by 14 cm., is bent to raise the metal from the bottom of the beaker, placed in a covered 150 cc. beaker containing the copper solution, which should be not much over 75 cc. in volume and should hold about 10% of free H_2SO_4 . Boil 7-10 minutes. The copper is removed mechanically rom the displacing metal and dissolved in nitric acid and then estimated.

A method of precipitation by means of powdered aluminum is recommended specially for separation of copper from large amounts of iron, iron ores and ron ore briquettes. The solution of the bisulphate fusion of the iron ore is neated until bubbles appear over the bottom of the containing beaker. Aluminum powder is now added in small portions at a time, in sufficient quantity to reduce the iron, the solution becoming colorless. The solution is now neated until the aluminum completely dissolves. Metallic copper is precipitated. It is advisable to add 25 ec. of water saturated with H₂S gas to precipitate traces of copper in solution. The solution is filtered while hot through close thick filter, and washed six times, keeping the residue covered with water to prevent exidation by air. The copper is now dissolved in hot dilute nitric acid, evaporated to small volume and determined by the procedure preferred. The potassium iodide method gives excellent results.

Occasionally the aluminum lies inert in the solution. If this occurs, two or three drops of hydrochloric acid (do not use much) will start a vigorous action and cause a rapid precipitation of metallic copper.

Deposition of Metallic Copper by Electrolysis

The electrolytic method of determining copper is the most accurate of the gravimetric methods. This deposition may conveniently be made from acid solutions containing free nitric or sulphuric acid) or from an ammoniacal solution.




Fig. 27.—Terminal Case Showing Battery of Electrodes for Electrolytic Deposition of Copper.

The end sought by this method is to plate out all, except a trace, of the copper in the form of an evenly distributed, firmly adherent, very finely crystal-line deposit, which is free from a weighable amount of impurity.

In ores, mattes, alloys (from which lead has been removed as the sulphate by taking the solution to fumes with sulphuric acid) deposition by electrolysis, from a solution containing free sulphuric acid, is convenient. On the other hand, deposition from a nitric acid solution is advantageous under conditions where this reagent has been used as a solvent and evaporation with sulphuric acid is unnecessary. This is the case in the analysis of certain alloys and the determination of copper from which impurities have been largely removed. A chloride in an acid solution gives rise to a spongy deposit of copper, and endangers a solvent action on the anode and deposition of platinum on the cathode.

Conditions other than the presence of precipitable impurities, which affect the character of the deposit are—quantity and concentration of copper, size and shape of electrodes, current density, uniformity of distribution of current to the cathode, volume, temperature and rate of circulation of the electrolyte, and concentration of oxidizing agents such as nitric acid and ferric salts. Inasmuch as the change of one condition limits or makes possible or necessary a modification of others, a large number of practicable combinations of conditions are possible. For discussion of these conditions reference is made to articles by Blasdale and Cruess, Jour. Am. Chem. Soc. Oct. 1910, 1264; and by Richards and Bisbee, Jour. Am. Chem. Soc., May, 1904, 530.

By the feature of rate of deposition, electrolytic methods may be classified as "slow" or "rapid." The slow methods, with 12 to 24 hour periods of electrolysis, are practiced when extreme accuracy is required, or when the distribution of laboratory labor and time allowed for completion of the assays permit their economical employment. The electrolyte is a solution of sulphate salts of the metals present, ammonium sulphate or nitrate, and a quantity of free nitric acid, which varies with the amount of copper and ferric salts present, and the current density employed. The oxidizing effect of nitric acid is intensified by the presence of ferric ions.¹ Electrolysis is carried out at room temperature, at current densities varying from ND/100, 0.15 to 0.5 amperes; and deposition on plain, corrugated, slit or perforated platinum cylinders from 0.75 to 2 in. diameter having 50 to 200 cm. depositing surface. A perforated cylinder permits freedom of circulation between the two surfaces of the electrode, the most even distribution of current density, and produces the most uniform coating of the foil. On account of the effect on the character of the deposit by oxygen lodging in regions of the cathode where the current density and circulation is least, the anode should be of such a form that all the gas liberated will be in the zone of maximum circulation. To procure uniform behavior under given conditions the size and shape of the electrolytic beaker should be such as to present the smallest practicable volume of electrolyte between the outer surface of the cylinder and the inside of the beaker. An unclosed seam or rivetted joint in a negative electrode will hold tenaciously salts which require extreme care to remove. It is probable that such recesses retain traces of the electrolyte underneath the coating of copper.

Rapid methods have a tendency to procure high results, resolution and mechanical loss through misting having been prevented. Deposition is hastened by increasing the rate of circulation and the current density. Circulation is

¹ Larison, Eng. and Min. Jour. 84, 442. Fairlic and Boone, Elect and Met. Ind. 6, 58.)


promoted by the use of the gauze cathode, by rotating either cathode, or by placing the vessel, containing the solution and electrodes, in a field of electromagnetic force. Quick deposition of a quality satisfactory for some classes of work is brought about by increase of current density upon an electrolyte heated to 50° to 80° C. In all the quick methods, the progress of electrolysis should be watched, and the cathode removed as soon as completion of deposition is detected by the evolution of gas about its surface. The completion of action is ascertained with greater certainty by addition of water to the electrolyte and observing whether the newly exposed surface of the cathode remains bright. When the electrolyte is hot or has a high acid content, detachment of the cathode should be preceded by removal of the electrolyte and simultaneously washing the cathode without interruption of the current. A syphon may be employed, water being added as the liquid drains from the beaker until the acid is removed.

RAPID METHODS

Rapid Deposition of Copper-Solenoid Method of Heath 4

The solenoid is made by winding 500 turns of No. 13 B and S gauge magnet wire upon a copper cylinder $2\frac{3}{4}$ in. in diameter, $3\frac{1}{4}$ in. high, $\frac{3}{32}$ in. thickness of

The eylinder is brazed water tight at the bottom to a $5\frac{1}{2}$ in. disc of 3 in. soft steel. In this disc is a 1-in. hole for the insertion of a rubber plug, through which glass tubes may be inserted for inlet and outlet of air or water to cool the electrolytic beaker. A steel disc of the same size as the bottom and with an opening to fit is brazed to the top of the eylinder. The solenoid thus made is suitable for a 300 cc. lipless beaker 47 in. high and 21 in. The solenoid diameter. coil may be in series in the electrolytic line or excited separately.



The negative electrode is of gauze 40 meshes per linear Inch, with a depositing surface of 100 cm. and is slit to permit quick removal from the electrolyte.

² Eng. and Min. Jour., 89, 89, 1910. ³ Frary, Jour. Am. Chem. Soc., Nov., 1907, 1592. Heath, Jour. Ind. Eng. Chem., Feb., 1911, 74.

¹ Stoddard, Jour. Am. Chem. Soc., 1909, 385. Price and Humphreys, Jour. Soc. Chem. Ind., 1910, 307.

⁴ Heath, Jour. Ind. Eng. Chem., Feb., 1911, 76.

Procedure. Five grams of the thoroughly cleaned copper sample are dissolved in the covered electrolytic beaker on a steam plate with 40 cc. of stock acid solution composed of 7 parts (1.42 sp.gr.) nitric acid, 10 parts sulphuric acid (1.84 sp.gr.) and 25 parts by volume of water. The temperature during the solution is kept just below the boiling point, 50 cc. of the stock solution is used for copper containing 0.03 to 0.1 per cent of arsenie, 60 cc. for material containing 0.11 to 0.5 per cent arsenie. The electrolyte is diluted to 120 ee. A current of 4.5 amperes is used for the electrolysis and the same amount employed to excite the solenoid. During the deposition a double pair of watch glasses cover tightly the beaker until the color of the electrolyte fades out, when they are rinsed and removed. Twenty minutes later and thereafter at 5 minute intervals, a test for completion of deposition is made by withdrawal of I cc. onto a porcelain tile and treating with a few drops of freshly prepared hydrogen sulphide water. This test will detect the presence of 0.000005 g. copper or more remaining in the solution. The determination is complete in two and a half hours. Extromely accurate results are obtained when the electrolyte is kept very cold by circulation of water about it and when the cathode is withdrawn within 5 minutes after completion of deposition.

In the assay of casting copper, in ease the deposit is evidently impure, the cathode may be stripped by treatment with 50 ee. of the stock solvent and then replated under the conditions described.

Notes. The advantage of the solenoid over any mechanical device for the rotation of electrodes is due to the prevention of loss by spraying from the anode, as the beaker can be covered with a double pair of watch glasses.

Results range from 0.003 to 0.01 per cent higher than the author's slow method of assay of refined copper, and is due to platinum from the anode, which is corroded by the influence of heat, nascent nitrous acid and high current.

Deposition from Nitric Acid Solution. The solution should not contain over 2-3 cc. of free concentrated nitric acid. If more than this is present, the solution is evaporated to expel most of the acid, the remainder neutralized with ammonia and the requisite amount of nitric acid added. The solution is diluted to 100 cc., warmed to 50° or 60° C. and electrolyzed with a current of 1 ampere and 2-2.5 volts. Two hours are sufficient to deposit 0.3 gram copper. Since the hot acid acts vigorously on copper, it is necessary to wash out the acid from the beaker before breaking the current. (See method for copper in alloys, page 207.)

Deposition from an Ammoniacal Solution. Ammonium hydroxide is added to the solution containing copper until the precipitate, first formed, dissolves. Twenty to twenty-five cc. of ammonium hydroxide (sp.gr. 0.96) are required for 0.5 grain copper or 30-35 cc. for 1 grain. Three to four grams of ammonium nitrate are added and the solution electrolyzed with a current of ND/100=2 amperes. The electrodes are washed, without breaking the current, until the ammonia and nitrate are removed.

Lead, bismuth, mercury, cadminin, zine and nickel should be absent from the ammoniaeal solution. Arsenic is-not deposited. Unless a very pure platinum anode is used, platinum may contaminate the deposit appreciably. Jena or other brand of zine borate resistance glass should not be used for the electrolytic beaker.

SLOW METHODS

Electrolytic Determination of Copper in Blister Copper

The sample should be no coarser than 20 mesh. Because fine particles are comparatively poor in copper, extreme care must be taken in drawing the portion for analysis to preserve the ratio of the coarse to fine. Some analysts, to avoid sampling error, sieve the coarse from the 40 or 60 mesh fine and either make a separate analysis of each weighed product, or weigh into a single test the due proportion of each. Others draw a large portion, by means of a riffle (Fig. 29) or similar sampling device and from its solution in a volumetric flask, pipette an aliquot part equivalent to one or more grams.

By the small portion method insoluble matter must be removed by filtration. When the sample contains an insignificant quantity of insoluble matter, the prac-

tice is to deposit the silver with the copper and make a correction for its presence in accordance with the result of the silver assay of the sample.

By the large portion method, insoluble matter and silver, as silver chloride, is removed from the electrolyte by sedimentation in the volumetric flask.

Procedure. Small Portion Method. The coarse and fine portions are quartered down to convenient amounts and from these a 5-gram composite weighed, which contains the coarse and fine portions in ratio of their percentage weights. The sample is placed in a 350-cc. tall-form beaker, without lip and with flaring rim. Fifty ec. of chlorine-free, stock acid solution (15 parts nitrie and 5 parts sulphuric acids) are added, the beaker covered with a funnel (stem up), which just fits in the rim, and the mixture heated gently at first and finally to boiling. When the sample has dissolved, 5 cc. saturated solution of am-




Fig. 29.—Riffle Sampler.

monium nitrate are added and the sample diluted to 200 cc. with water. When the electrolyte has cooled to room temperature the electrodes are introduced, the beaker covered with split watch glasses and electrolysis started with a current of .05 ampere and continued until the appearance of the foil indicates that the silver has deposited. The current is then raised to ND/100 = .75 ampere and this continued for twenty to twenty-two hours, or until the appearance of gas about the negative electrode indicates that deposition of the copper is practically complete. For the unexperienced a simple method is to add a little water to the electrolyte without breaking the current and after 15 minutes to observe whether any deposition or copper takes place on the freshly exposed surface. The watch glasses and electrode stems should be rinsed when the electrolysis has continued 15–16 hours.

Procedure. Large Portion Method.¹ The sample is quartered by a riffle sampler (see Fig. 29) to an amount very close to 80 grams. This quantity is weighed and transferred by a paper chute into a 2000 cc. flask, which has been calibrated by the method of repeated delivery at constant temperature, of a 50 cc. overflow, dividing pipette (see Fig. 30). The liquid employed in calibrating is a copper solution of the same composition as that for which the flask is to be used. A cold mixture of 80 cc. sulphuric acid (sp.gr. 1.82) and 200 cc. nitric acid (1.42) with 500 cc. of water is added. A standard solution of sodium chloride is added in sufficient quantity to precipitate the silver, care being taken to add less than 20% excess. A bulbed condenser tube is placed in the neck before putting the flusk on a hot plate.

The solution is gradually heated to boiling and when the solution is nearly complete, boiled gently for one hour. This generally completely dissolves the copper present. Residues of lead, tin, silver, or silica if present in appreciable amounts are separated at this point by filtration.

When the solution in the flask has cooled for half an hour, water is added to a little above the 2000-cc. mark, giving the flask a rotary motion, during the addition, to mix the solution. The flask is placed in a large tank, Fig. 30,




Fig. 30.—Constant Temperature Bath and Dividing Pipette.

containing water and allowed to remain until it becomes of the same temperature as the water and very close to that of the room. The solution is then made exactly to the mark and allowed to settle, after thorough mixing, by placing the flask again in the water tank.

W. C. Ferguson, Jour. Ind. and Eng. Chem., May, 1910.

Electrolysis. Portions equivalent to 2 grams of sample are measured out



by means of a dividing pipette, with water-jacket through which the tank-water flows. The solution is run into glasses, hydrometer-jar in shape, with coneave bottoms, height of glass, 6½ ins., diameter 2½ ins., Fig. 31. Each portion is treated with 5 ee. of a saturated solution of ammonium nitrate and diluted to 125 ce. with water. (NH₄NO₂ or (NH₄)₂SO₄ delays deposition of As and Sb until electrolyte is freed from Cu.) The electrolyte, at this stage, contains about 3.7 ee. of nitric acid.

The copper is deposited by electrolysis, using a current of .33 ampere per 100 sq.em., which is kept constant until deposition is complete, about twenty hours. It is advisable to begin the electrolysis in the evening, 5 p.m. The following morning, the inside of the jar, the rods of the electrodes, and the split

watch-glasses which cover the jar are rinsed with a spray of water into the glass and the run continued for two or three hours. Each electrode is quickly detached from the binding posts, the cathode plunged into cold water, then successively into three jars of 95% alcohol, shaken free of adherent drops and dried by revolving rapidly over a Bunsen flame for a few seconds after ignition of the film of alcohol.

The weighing of foil plus the deposit is made with as little delay as possible.

Determination of the Copper Remaining in the Electrolytes. Since the exhausted electrolyte seldom contains over 0.01% copper, this residual copper can be closely estimated by observation of the depth of the sulphide precipitate. Should circumstances be such that the quantity be more than can be estimated by the appearance of the sulphide precipitate and a determination without rerun is necessary, the precipitate is filtered, incinerated, dissolved with a little hot HNO₃, made ammoniacal and after settling, filtered through asbestos. The color of the solution is compared with a standard solution treated with the same amount of reagents as the sample, care being taken that similar conditions prevail when making comparison.

Notes and Precautions

Character of the Deposits. The ideal deposit is of a salmon-pink color, silky in texture and luster, smooth and tightly adherent. A slightly spongy and coarsely crystalline deposit, although good in color and perfectly adherent, will invariably give high results. A loosely adherent deposit caused by either too rapid a deposition at the commencement or too low a current density at some period of the electrolysis, at the commencement or too low a current density at some period of the electrolysis, at the commencement of particles. A darkly shaded deposit indicates the presengult because of detachment of particles. A darkly shaded deposit indicates the presenges of impurity in greater or less extent. If it is impossible to complete the electrolence of impurity in greater or less extent. If it is impossible to complete the electrolence of impurities such as yes without this appearance the electrolyte should be purified. Impurities such as yes without this appearance the electrolyte should be purified. Impurities such as electrolyte and the provided years are deposited in disappearance the electrolyte should be purified.

ysis without this appearance the electrolyte should be purified. Impurities such as arsenic, antimony, bismuth, selenium and tellurium may occur in the blister copper. A dark colored, but perfectly adherent deposit is dissolved very slowly from the foil, in a covered electrolytic jar, by gently heating for several hours with about 60-70 cc. of a solution containing 2 cc. sulphuric and 5 cc. nitric acids. When the solution is complete the temperature is raised to expel dissolved gases. Five cc. saturated ammonium nitrate solution is added and the electrolyte diluted to 125 cc. When ammonium nitrate solution is added and the electrolyte diluted to 125 cc. When cooled to room temperature, electrolysis is carried out under the same conditions as that of the first deposit and on the same foil, if arsenic or antimony is the interfering that of the first deposit and on the same foil, if arsenic or antimony is the interfering that of the first deposit and on the same foil if selenium or tellurium has been the contaminating element. The undeposited copper is determined colorimetrically in the mixture of the first and final electrolytes and added to the weight of the copper deposited.

nnai electrolytes and added to the weight of the copper approximation of the sample contains a large percentage of arsenic or antimony, a portion representing 2 grams is drawn from a pipette into a Kjeldahl flask, 10 cc. of sulphuric acid added,

and the liquid evaporated to fumes to expel nitrie acid. From this solution cuprous thiocyanate is precipitated according to the method described on page 153. The funnel containing the filter is placed in a 500 cc. flask with long neck, the filter is punctured and the precipitate washed into the flusk with the least quantity of water possible, the adherent precipitate is dissolved from the filter with warm dilute nitric acid, added cautiously to avoid violent evolution of gases from the dissolving precipitate in the flask. The washed filter is incinerated and the solution of its ash by nitric acid added to the electrolyte after completion of electrolysis. When solution of the precipitate is complete, the liquid is boiled to small volume, neutralized, and 5 cc. ammonium nitrate solution and 3 cc. excess free nitric acid added. The liquid is transfered to an electrolytic jar and electrolysis carried out in the manner already described.

The amounts of bismuth, arsenic, antimony, selenium or tellurium usually found in blister copper may be separated together with iron present by addition of ammonia to a pipetted portion. The filtered precipitate is purified of copper by solution with nitrie acid and reprecipitation. The combined filtrates are neutralized, 31 ec. of free nitric acid added and the solution electrolyzed under the conditions already described. The nitric acid solution of the incinerated filter, carrying the iron, etc., is added to the electrolyte, after electrolysis is complete, for determination as undeposited copper, The undeposited copper is determined colorimetrically by one of the procedures outlined

on pages 165, 166 or 167.

The deposited copper is never absolutely pure. The total impurities seldom exceed 0.03%. Ag from 0.000 to 0.18%; As from 0.000 to 0.003%; Sb from 0.000 to 0.004%; Se and Te from 0.001 to 0.027%; Bi from 0.000 to 0.0003%. Periodical complete analyses may be made and corrections applied to the analysis when exceedingly accurate percentages are required.

Too low a current density or excessive oxidizing power of the electrolyte may produes high results, due to the exidation of the deposited copper. Too high a current density or a deficiency of oxidizing power in the electrolyte, by eausing a deposition

of impurities, will give high results.

The electrodes used by the Nichols Copper Co. are straight platinum wires for the positive ends and cylinders 13 in. long, 1 in. in diameter of 0.004 in. iridoplatinum foil, 111 sq. in. depositing surface, for the cathodes.

A uniform current is essential.

The nitrie acid used should be free of iodic acid.

The presence of oxide of nitrogen gases, or a chloride in an acid solution, will cause a coarsely crystalline or brittle deposit, under conditions which in their absence would produce a good plating. The deposit moreover may contain platinum from the an de if the electrolyte contains a chloride salt.

Silver may be deposited with the copper and correction made for its presence from the result of a separate assay. Copper deposits in poor form, unless the silver be first plated out at a very low current density, about 0.03 Amp. ND 100.

Solid matter, unless removed, will contaminate the deposit mechanically.

Arsenie, antimony, sclenium or tellurium have an influence on the physical character of the deposit which may affect the copper result beyond the sum of such impurities deposited.

Whether impurities are deposited or not, appreciably high results are obtained by continuing electrolysis for some time after the electrolyte has become impoverished of copper.

Overheating of the copper deposit, in the process of ignition of the alcohol clinging to the cathode, will cause oxidation of the copper. As much as possible of the alcohol must be shaken off before passing the electrode rapidly through the flame. It is advisable to weigh the copper shortly after deposition, as prolonged contact with air is undesirable, if extreme accuracy is desired.

The copper deposits may be removed by plunging the electrode, for a few moments, in hot nitric acid. After washing with water, the foil is ignited to a cherry red in a direct colorless flame. The ignition removes any grease which would be objectionable, that may contaminate the platinum. Alcohol frequently contains oily matter which will cling to the electrode in spite of the rapid ignition for drying the deposit.

VOLUMETRIC METHODS FOR THE DETERMINATION OF COPPER

Potassium Iodide Method

The procedure depends upon the fact that cupric salts when treated with potassium iodide liberate iodine, the cuprous iodide formed being insoluble in dilute acetic acid.

Reactions. $2\text{CuSO}_4 + 4\text{KI} = \text{Cu}_2\text{I}_2 + 2\text{K}_2\text{SO}_4 + \text{I}_2$, or $2\text{Cu}(\text{C}_2\text{H}_3\text{O}_2)_2 + 4\text{KI} = \text{Cu}_2\text{I}_2 \downarrow + 4\text{KC}_2\text{H}_3\text{O}_2 + \text{I}_2$.

The liberated iodine is titrated with standard thiosulphate.

 $2Na_2S_2O_3 + I_2 = Na_2S_4O_6 + 2NaI$

The method is extremely accurate. Only a few elements interfere, such as selenium, trivalent arsenie, antimony and iron. Lead, mercury and silver increase the consumption of potassium iodide, but otherwise interfere only because of the color of their iodides. No free iodine is consumed by these.

N/10 solution contains 24.82 grams Na₂S₂O₃.5H₂O per liter. According to the reaction above, 1 cc. of this will be equivalent to 0.006357 g. Cu.

If a solution is desired so that 1 cc. = 0.001 g. Cu, dissolve 3.92 grams of the Na₂S₂O_{3.5}H₂O crystals per liter (248.2÷63.57). If a 0.5 gram sample is to be taken, it is convenient to have the reagent of such strength that 1 cc. is equivalent to 0.005 g. Cu so that 1 cc. is equivalent to 1% Cu. $3.92 \times 5 = 19.6$ grams of thiosulphate crystals are required. The addition of 2-4 grams NaOH per liter is claimed to preserve the solutions.

Standardization. Copper Method. If either a N/10 reagent or the one containing 19.6 grams of the salt are being standardized, weigh 0.2-0.25 gram of pure copper (electrolytic) (not over 0.1 gram should be taken for the weakest solution) Dissolve the copper in about 5 cc. of nitric acid (in a flask or a covered beaker), boil to expel brown fumes, dilute to about 50 cc., add ammonia in slight excess (10-12 cc. is generally sufficient), boil until the odor of ammonia is faint and add 5 cc. glacial acetic acid, or sufficient to make the solution acid (test with litmus) and again boil for about one minute. Cool and add to the cold solution 6 cc. of a 50% potassium iodide solution or about 3-4 grams of the solid, and titrate with the standard thiosulphate reagent. The iodine that is liberated (see reaction above) colors the solution brownish; on addition of the thiosulphate the color fades; when the brown color has become faint, add starch solution and complete the titration adding the thiosulphate until the blue color (lilae at end) fades out with an added drop of the reagent.

Divide the weight of copper taken by the cc. of reagent required and the result is the weight of copper represented by one cc. of the reagent. An exactly N/10 solution is equivalent to 0.006357 g. Cu.

Standardization with Permanganate. The reagent may be standardized against N/10 potassium permanganate or a permanganate solution whose iron equivalent is known. To about 40 cc. of the N/10 permanganate solution add 6 cc. of the potassium iodide (50%) reagent and titrate the liberated iodine in presence of acetic acid exactly as is described above. 1 cc. of N/10 permanganate should equal 1 cc. of the N/10 thiosulphate. Establish its normality by converting the permanganate to exact cc. in normality equivalent and

193a COPPER

dividing the cc. by the cc. of thiosulphate required. If preferred, multiply the iron equivalent by $\frac{63.57}{55.84} = 1.139$ to get the copper equivalent.

Procedure for Copper in Ores

Solution of the Sample. Weigh 0.5 gram of the powdered ore (if a N/10 thiosulphate reagent is to be used, the factor weight 0.636 gram of ore is convenient so that 1 ec. of the reagent is equivalent to 1% Cu). Dissolve in 10 cc. hydrochloric acid and 5 cc. nitric, heating gently to effect solution, adding more of the acids if necessary. Add 10 cc. of sulphuric acid and evaporate to fumes. Heat until any free sulphur that precipitates disappears. Allow to cool. Dilute with 30-40 cc. of water, heat to boiling and keep hot until ferric sulphate has dissolved (copper will all be in solution). Filter into a small bcaker and wash the residue at least six times with hot water, using small portions at a time. The volume of the filtrate need not exceed 75-100 cc. This contains all of the copper.

Precipitation of Metallic Copper. Place in the beaker containing the copper solution a piece of heavy sheet aluminum (1.5 inches square) or a bent strip of aluminum bent in form of a triangle, or add 1-2 grams of pure granulated aluminum. If a sheet is used, bend the corners at right angles so it will not lie flat in the beaker. (The sheet may be used repeatedly as it is not attacked to any great extent by the nitric acid subsequently used). Heat the solution to boiling (beaker covered) and keep at this temperature for about 10 minutes. All of the copper will precipitate an equivalent amount of aluminum dissolving. If the action is sluggish, add 2 or 3 drops of hydrochloric acid. Wash down the cover and sides of the beaker with hydrogen sulphido water. (This precipitates any trace of copper in the solution and prevents oxidation of the copper.)

Isolation of Copper. Decant the solution through a filter and rinse the metallic copper into the filter with a jet of the hydrogen sulphide water, leaving the aluminum as clean as possible in the beaker. Save this. Wash the precipitate 6 times with hydrogen sulphide wash water, allowing to drain, but following up immediately with more solution, until the washing is complete. (Copper will oxidize if allowed to stand exposed to the air. Hence the washing should be completed as soon as possible.)

Solution of the Copper. Punch a hole in the filter and wash the copper into a beaker with a jet of water, using as little as possible. (If much copper is present, open the filter on a watch glass and wash the precipitate into a beaker. Again fold the filter and place in the funnel over the beaker.) Pour 5 cs. of strong nitric acid over the aluminum which still contains a little of the copper. When all of this has dissolved, pour the nitric acid solution over the filter, catching the acid in the beaker containing the bulk of the copper. (Removing the beaker, place the one containing the foil under the filter.) Cover the beaker containing the copper and boil until the metal is in solution and again place under the filter funnel. Wad the filter paper loosely in the funnel. Pour over this filter 5-10 cc. of bromine water, catching the solution in the beaker containing the copper; this should impart a yellow color to the copper solution. Wash the filter 6 times with water, pouring the water first into the beaker with the aluminum and from this over the wadded filter.

COPPER 193b

Concentration. Boil the combined solution down to about 25 cc. The bromine will be expelled. Add a small excess of ammonia; the free acid is neutralized and the solution smells of ammonia. Again boil to expel the excess of ammonia. The solution should still smell faintly of NH₃. Add glacial acetic acid until slightly acid (litmus test); 5 cc. should be sufficient. Cool thoroughly.

Potassium Iodide Treatment and Titration with Thiosulphate. To the cold solution add 5-6 cc. of 50% solution of potassium iodide and titrate the liberated iodine with standard thiosulphate until the brown color has become faint, add starch and complete the titration.

1 cc. $N/10 \text{ Na}_2S_2O_3 = 0.00636 \text{ g. Cu.}$

Note. Since a yellow color may be due to other causes than to free iodine, it is advisable to make a preliminary titration by adding the starch indicator before starting titration with thiosulphate. In a check run the starch is added upon neutralizing the greater part of the free iodine. This precaution prevents overrunning the endpoint, which one is apt to do when depending upon a color change of iodine brown to yellowish brown due to a trace of free iodine.

Short Iodide Method for Copper

The method takes advantage of the repression of ionization of iron by addition of potassium fluoride to a neutral or acetic acid solution containing the ferric salt. Ag, As, Bi, Cd, Co, Fe, Hg, Mn, Mo, Ni, Pb, Sn, U, Zn do not interfere. Cr forms an insoluble sulphate, which holds Cu, hence avoid using H_2SO_4 . V interferes.

Procedure

Decomposition. 0.5 to 1.0 gram of the material is decomposed by 10-15 cc. hydrochloric acid and 5 cc. nitric acid and warming. When the action has ceased, 5 cc. of sulphuric acid are added and the solution taken to strong funcs. (In presence of chromiam the sulphuric acid is omitted, the solution being taken to near dryness, 10 cc. more HCl is added and the evaporation repeated to expel HNO₃.) 30 cc. water are now added to the cooled solution and the solution boiled to dissolve any salt that has crystallized out. 5 cc. bromine water are added to oxidize any arsenic or antimony that may be present and the excess expelled by boiling.

Ammonium hydroxide is now added until the solution shows an alkaline reaction, the odor of ammonia being evident in the solution. The mixture is now acidified with glacial acetic acid (5-10 cc. should make the solution decidedly acid). Two grams (approximately 2 cc.) of solid potassium fluoride are now added to precipitate iron, additional fluoride may be necessary if the supernatant solution is colored by iron. The solution is boiled for a minute or so and then cooled under the tap.

To the cold solution 5 cc. of a 50% solution (or its equivalent of 2 g. of KI)

of potassium iodide are added, together with 5 cc. of starch solution.

The liberated iodine is now titrated with 0.1 N thiosulphate, to the point where one drop destroys the blue color. It is advisable to add 1-2 cc. more of potassium iodide, and if a blue color results, to add more of the thiosulphate until the color is destroyed.

1 cc. 0.1 N $Na_2S_2O_3 = 0.00636$ g. Cu.

Nore. The additional iodide is occasionally necessary owing to its consumption by Co, Ni, U, Mo, Pb, etc.

Potassium Cyanide Method

This procedure is largely employed on account of its simplicity, although it does not possess the degree of accuracy of the Iodide Method. The procedure depends upon the decoloration of an ammoniacal copper solution by potassium cyanide.

The operations of the standardization of potassium cyanide and of making the assay should be as near alike as possible. If iron is present in the assay it should be added to the standard copper solution titrated, in order to become accustomed to the end-point in its presence.

Silver, nickel, cobalt, cadmium, and zinc interfere and should be removed if present in appreciable quantities. Precipitation of metallic copper by aluminum powder, as directed under Separations, is recommended as a procedure for iron ores and briquettes. In presence of smaller amounts of iron, the titration may be made in presence of iron suspended in the solution. It is not advisable to filter off this precipitate, as it invariably occludes copper. With practice, the shade of color the iron precipitate assumes at the end of the reaction serves as an indicator, so that the operator is assisted rather than retarded by its presence.

 $2Cu(NH_1)_4SO_4 \cdot H_2O + 7KCN =$

 $K_1NH_4Cu_2(CN)_6+NH_4CNO+2K_2SO_4+6NH_4+H_1O$.

Standard Potassium Cyanide Solution. Thirty-five grams of the salt are dissolved in water, then diluted to 1000 cc.

Standardization. 0.5 gram of pure copper is dissolved in a flask by warming with 10 cc. of dilute nitric acid (sp.gr. 1.2), the nitrous fumes expelled by boiling, the solution neutralized, diluted and titrated as directed under Procedure. If iron is present in the samples titrated, it is advisable to add iron to the standard copper solution as directed above.

$$\frac{0.5}{\text{cc. KCN solution}}$$
 =wt. Cu per cc. of standard KCN.

Procedure. The solution containing the copper is neutralized with sodium carbonate or hydroxide, the reagent being added until a slight precipitate forms. One cc. of ammonium hydroxide is now added and the solution titrated with standard potassium cyanide solution. The blue color changes to a pale pink; finally a colorless solution is obtained. In presence of iron, when the copper is in excess of the eyanide, the iron precipitate possesses a purplish-brown color, but, as this excess lessens, the color becomes lighter until it is finally an orange brown, the solution appearing nearly colorless. The reagent should be added from a burette drop by drop as the end-point is approached.

Cc. KCN x factor per cc. = weight Cu in assay.

¹ Sutton, "Volumetric Analysis." Davies, C. N., 58, 131, J. J. and C. Beringer, C. N., 49, 3. Dr. Steinbeck, Z. a. C., 8, 1; C. N., 19, 181.

VOLUMETRIC METHODS BASED UPON THE PRECIPITA-TION COPPER AS CUPROUS THIOCYANATE

Iodide Method1

A thioeyanate salt is oxidized by a series of reactions which when completed has this form: $4\text{CuCNS} + 7\text{KIO}_3 + 14\text{HCl} = 4\text{CuSO}_4 + 7\text{KCl} + 7\text{ICl} + 4\text{HCN}$ Other cyanate than copper, lead and antimony must be absent +5H₂O. from the precipitate of cuprous thiocyanate. This precipitate together with the filter paper is placed in a 250 cc. glass stoppered bottle and 5 ee. ehloroform, 20 cc. water and 30 cc. concentrated hydrochloric acid added.

A certain amount of standard potassium iodate solution (11.784 grams KIO₃ per liter, 1 cc. = 2 milligrams copper) is added from a burette. When the bottle is thoroughly shaken, a violet color appears in the stratum of chloroform which may increase in depth of tint and then fade with each addition of iodate solution. Disappearance of color determines the end point. The KIO, solution is very stable. The same layer of eliloroform can be used for successive determinations by decanting only the liquor carrying the paper pulp. The immediate coloring of the eliloroform on addition of a precipitate to the bottle is due to the reaction with residual ICI and has no harmful effect on the determination.

Permanganate Method²

Although this method is based upon these reactions: CuCNS+NaOII = CuOH + NaCNSand $5HCNS + 6KMnO_4 + 4H_2SO_4 = 3K_2SO_4 + 6MnSO_4$ +5HCN+4H₂O, solution of the copper salt by the method of manipulation and possibly incompletion of oxidation makes necessary the use of an empirical Theoretically the iron value multiplied by 0.1897 gives the copper value of permanganate. By this method the Fe to Cu factor may be from 0.192 to 0.2. The thiocyanate precipitate is decomposed on the filter with boiling 8% NaOH. The filter is washed with hot water. After making the filtrate acid with dilute H₂SO₄, titration of the solution to permanent tint is made with standard KMnO₄ solution having a strength of 1 ce. equivalent to about I nigni, eopper.

¹ Jamieson, Levy and Wells, Jo. Am. Chem. Soc., May, 1908, p. 760. Price and Meade, "Technical Analysis of Brass," Sec. Ed., p. 84.

² Low, "Technical Methods of Analysis." Chapter on Copper has table of empirical

factors, compiled by G. A. Guess.

Demorest's Method 1

Precipitation of cuprous thioeyanate is from a nearly boiling 75-100 cc. solution containing ammonium sulphate about 3 grams ammonium tartrate and 1 cc. free sulphuric acid. 5% solution of sodium sulphite is first added then slowly, with stirring 5% solution of potassium thioeyanate. The coagulated precipitate is collected from the hot liquid in an asbestos lined Gooch crucible and washed thoroughly. The precipitate is decomposed in the crucible by pouring on it hot, 10% NaOH. The residue of CuOH in the crucible is washed well with hot water.

The alkaline filtrate is warmed to 50° C. and a few cc. of standard permanganate solution introduced. At 10 or 5 cc. intervals during the titration, a drop of the green solution is placed on a parafined white plate together with a drop of strong hydrochloric acid. When the red color of this test drop becomes faint on addition of a drop of a 10% solution of FeCl₃, 30 cc. of 50% H₂SO₄ are added and the flask shaken until all the MnO₂ is dissolved. The characteristic end point will appear on addition of very little more permanganate. This method has the merit of not requiring an empirical factor, the copper value of the permanganate being 0.1897 times that of the iron.

Volhard's Method

The copper is precipitated with a standard solution of alkali thiocyanate. After filtering and washing the precipitate free of reagent, the excess is titrated with standard silver uitrate solution.

Garrigue's Method

The precipitate of cuprous thiocyanate is collected in a Gooch crucible, decomposed in a casserole with an excess of hot, standard NaOH. The cuprous hydrate formed is filtered, washed and the excess alkali titrated with standard HCl. The reactions are: CuCNS+NaOH=CuOH+NaCNS and NaOH+HCl=NaCl+H₂O.

¹ Jo. Ind. and Eng. Chem., Mar., 1913, p. 215.

COLORIMETRIC DETERMINATION OF SMALL AMOUNTS

OF COPPER

Potassium Ethyl Xanthate Method

The method is based upon the fact that potassium ethyl xanthate produces a yellow-colored compound with copper. The reagent added to a solution containing traces of copper will produce a yellow color varying in intensity in direct proportion to the amount of copper present. Larger amounts of copper with the reagent produce a bright yellow precipitate of copper xanthate. Small quantities of iron, lead, nickel, cobalt, zinc, or manganese do not interfere. The procedure is especially valuable for determination of the purity of salts crystallized in copper pans.

Special Solutions. Stock Solution of Copper Sulphate. 3.9283 grams CuSO₄·5H₂O are dissolved in water and made up to a volume of 1000 cc. One cc. is equivalent to 0.001 gram Cu.

Standard Copper Sulphate. Ten cc. of the stock solution are diluted to 1000 cc, with distilled water. One cc. = 0.00001 gram Cu.

Potassium Ethyl Xanthate Solution. One gram of the salt is dissolved in 1000 cc. of water. The solution is kept in an amber-colored glass-stoppered bottle.

Procedure. Five grams of the substance are dissolved in 90 cc. of water (see note) and the solution poured into 100-cc. Nessler tube; 10 cc. of the potassium xanthate reagent are added and the solution mixed by means of a glass plunger. To a similar tube containing 50 or 60 cc. of water are added 10 cc. of the xanthate reagent and then gradually drop by drop the standard copper solution from a 10-cc. burette (graduated in $\frac{1}{10}$ cc.) until the colors in both tubes match.

If a = grams of the substance taken for analysis, b = number of cc. standard copper solution required to match the sample; then $b \times 0.00001 \times 100 \div a = \%$ Cu.

Notes. The amount of the substance to be taken varies according to its copper content. The greater the copper contamination of the salt, the less sample required. The solution should be neutral or only very slightly acid.

In place of the Nessler tubes the special colorimetric apparatus described under Titanium and under Lead may be used. A very weak copper standard will be required for the comparison tube.

If the substance is insoluble in water the copper is rendered soluble by treatment with nitric acid. Hydrochloric acid is added and the nitric expelled by evaporation. The substance is taken up with water and the insoluble residue filtered off.

Starch and organic matter are destroyed by addition of 10 cc. 10% sodium hydroxide+10 cc. of saturated sodium nitrate solution, then evaporating to dryness and igniting. Hydrochloric acid is now added to expel the nitric acid as directed above.

In dealing with a flotation concentrate containing oil, the sample should be taken to fumes with nitric acid, otherwise the color is apt to be green instead of blue.—C. Y. Pfoutz.

Ferrocyanide Method for Determination of Small Amounts of Copper

By this colorimetric method it is possible to detect one part of eopper in 2.500,000 parts of water. The procedure depends upon the purplish to chocolatebrown color produced by potassium ferrocyanide and copper in dilute solutions. The procedure is applicable to the determination of copper in water and may be used in presence of a number of elements that occur in slags. Iron also produces a colored compound with ferrocyanide (1 part Fe detected in 13 million parts H₂O), so this element must be removed from the solution before testing for copper.

Solutions. Standard Copper Solution. 0.393 gram CuSO4.5H2O per liter.

1 cc. = 0.0001 gram Cu.

Ammonium Nitrate. 100 grams of the salt per liter.

Potassium Ferrocyanide. Four grams of the salt per 100 ce. of solution.

Procedure. A volume of 5 to 20 drops of potassium ferrocyanide, according to the amount of copper present in the solution, is placed in a tall, clear, glass cylinder or Nessler tube of 150 ce. capacity, 5 cc. of ammonium nitrate solution added and then the whole or an aliquot portion of the neutral 1 solution of the assay. The mixture is diluted to 150 ce. The same amount of ferrocyanide and ammonium nitrate solutions are poured into the comparison cylinder, placed side by side with the one containing the sample, on a white tile or sheet of white paper. The standard copper solution is now run from a burette into the comparison cylinder, stirring during the addition, until the color matches that of the assay. The number of ce. required multiplied by 0.0001 gives the weight of copper in the sample contained in the adjacent cylinder.

 $\frac{\text{Amount of Cu} \times 100}{\text{Wt. of sample compared}} = \% \text{ Cu in the sample.}$

Notes. The solution must be neutral, as the copper compound is soluble in ammonium hydroxide and is decomposed by the fixed alkalies. If the solution contains free alkalies, it is made slightly acid and then the acid neutralized with ammonia, added in slight excess. This is boiled to expel the excess of ammonia, and then tested according to the directions under "Procedure." Solutious containing free acids are neutralized with ammonia.

Iron may be removed by precipitation with ammonia. As this hydroxide occludes copper, the precipitate should be dissolved and reprecipitated to recover the occluded

Determination of copper in water is accomplished by evaporating a quantity of water to drvness, taking up the residue with a little water containing 1 ee. nitrie acid, the residue having been ignited to destroy organic matter, precipitating iron with ammonia, as directed above, and determining copper in the filtrate.

The colorimeter used in determination of traces of lead and for the colorimetric

determination of titanium may be employed in place of the Nessler tubes.

Ammonia Method for Determining Small Amounts of Copper

In the absence of organic matter, nickel and elements giving a precipitate with ammonia, copper to an upper limit of 10 milligrams can be determined by comparison of the depth of the blue tint of its ammonium solution with a tem-

porary or permanent standard copper solution of equal volume. Because copper in ammoniacal solution combines with the cellulose of filter paper, clarification of such a solution should be through asbestos. Permanent standard solution of copper sulphate, free of nitrate, if kept cool and away from the direct sunlight, lasts for a long time.

Hydrogen Sulphide Method

In the absence of elements precipitated by hydrogen sulphide, copper to the limit of about 1 milligram, in a solution not too strongly acid with sulphuric or hydrochloric acid, may be determined by comparison of its sulphide with that of a known quantity of copper in equal volume and similarly treated. The liquid should be cold and the passage of the hydrogen sulphide stopped before the compound coagulates.

Note. Fither the ammonia or the hydrogen sulphide method is applicable to the determination of the copper not deposited in the operation of the electrolytic method.

DETERMINATION OF IMPURITIES IN BLISTER AND REFINED COPPER

In the complete analysis of copper the following impurities Introduction. are generally estimated: silver, gold, lead, bismuth, arsenic, antimony, selenium, tellurium, iron, zinc, cobalt, nickel, oxygen, sulphur, and less commonly, tin and phosphorus. In high grades of blister and in refined copper the percentage of these impurities is very low, the blister copper usually averaging over 99.0% copper with silver and the refined copper over 99.93% of the metal. The principal impurity in the refined element is oxygen, which may be present to the extent of .02 to .15%, the remaining impurities being in the third decimal place. From this it is readily seen that largo samples are required for the accurate determination of these constituents. The amount of sample taken in blister copper depends upon the grade of copper analyzed. The impurities in this vary from tenths of a per cent to thousandths, as the metal from one locality may contain quite appreciable amounts of a constituent, which may be present only in extremely small quantities or not at all in copper from a different section. In usual practice it is customary to take from 10 to 50 grams of blister and 50 to 500 grams of refined copper for analysis, depending upon the purity of the material. If a larger sample than 50 grams is taken, it is necessary to divide the material into several lots, and, after removal of the bulk of copper and isolation of the impurities, to combine the filtrates or residues containing the constituents sought.

In the procedures the smallest amount of sample, 10 grams, is taken as the basis of calculation for amounts of reagents used. For larger samples, in the initial treatment for removal of eopper, proportionately larger amounts of the reagents are required, i.e., multiples of from 2 to 5 times the amount stated. A 50-gram sample is the largest amount of material handled in one lot.

Scrupulous care must be exercised throughout the analysis to prevent con-

tamination of the sample or reagents, and to avoid loss of constituents. The reagents used should be free from the substance sought or from interfering substances. It is the practice to carry blank tests of the reagents through under conditions similar to a regular analysis for iron, lead, zinc, arsenic antimony and sulphur.

It is found best to determine the impurities in several portions, i.e., gold and silver by assay; bismuth and iron in one portion; lead, zine, cobalt, and nickel in a second; arsenic, antimony, selenium, and tellurium in a third; and separate portions for sulphur, oxygen, phosphorus and tin, when these are occasionally required.

Determination of Bismuth and Iron

Separation of Copper. Amount of Sample. Blister copper 10 to 25 grams, refined copper 100 to 500 grams. The drillings are dissolved in a large beaker in 40 cc. of nitric acid per 10-gram sample and the free acid expelled by boiling. The solution should not become basic during the evaporation. Water is added to make the volume 130 cc. per 10 grams or proportionately more for larger samples. Animonia is now added in sufficient excess to hold the copper in solution and 5 cc. of saturated ammonium carbonate solution and the sample diluted to 200 cc. (25 cc. (NH₄)₂CO₃ per 50 grams, and dilution to 1000 cc.). The beaker is placed on the steam bath for several hours, preferably over night. The solution is filtered hot (to avoid crystallization of the copper salt), the first 100 cc. being refiltered, and the residuo washed with hot water containing a little ammonia. By this procedure the copper passes into the filtrate and bismuth and iron remain in the residuo on the filter.

Separation of Iron and Bismuth. The precipitate is dissolved in warm, dilute hydrochloric acid (1:3), ammonia added to the solution in sufficient amount to almost neutralize the acid and the solution then saturated with hydrogen sulphide. After settling some time, the precipitate containing bismuth sulphide is filtered off, iron passing into the solution.

Determination of Iron. Hydrogen sulphide is expelled by boiling the filtrate, and iron oxidized by addition of hydrogen peroxide, or potassium chlorate (nitric acid should not be used). The solution is evaporated to dryness and iron then determined in the residue by the stannous chloride method,

details of which may be found in the chapter on Iron, page 257.

Determination of Bismuth. The sulphides remaining on the filter are dissolved in nitric acid, the solution evaporated with sulphuric acid to SO₁ fumes to expel nitric acid, the concentrate diluted with water, and lead filtered off. Bismuth is precipitated in the filtrate by addition of annuonia in slight excess, followed by 10 ec. of a saturated solution of annuonium carbonate, and boiling. The precipitate is settled for several hours or over night if preferred, and then separated by filtration. This is now dissolved in the least amount of nitric acid, added to the filter drop by drop from a burette and bismuth determined in the solution by the cinchonine iodide method, given in detail in the chapter on Bismuth, page 77.

NOTES. An excess of nitric acid, or the presence of cadmium, lead, silver, or

hydrochloric acid interferes with the colorimetric procedure.

In analysis of refined copper several 50-gram portions are taken for analysis, ten such portions on a 500-gram sample; the filtrates, obtained upon dissolving the residue freed from copper, are combined and bismuth and iron determined on this combined solution.

Determination of Lead, Zinc, Nickel, and Cobalt

Removal of Copper. Ten to 25 grams of blister copper, and 100 to 250 grams of refined copper in 25-gram portions are taken for analysis. The metal is dissolved in nitric acid (40 cc. per 10 grams) and the solution boiled until a faint green precipitate begins to appear on the surface of the solution. The free acid being expelled, the solution is made faintly acid by adding I to 2 cc. of nitrie acid, the solution diluted 300 to 700 ec., according to the amount of copper taken, and then electrolyzed with a current of 1.5 to 2 amperes for thirty-six hours, with a spiral anode and a cathode with about 160 cm. depositing surface. The solution should remain slightly acid throughout the electrolysis, otherwise cobalt, nickel, and zinc may be precipitated as hydroxides from a neutral solution. When the copper is nearly removed, the electrodes are disconnected, and removed.

The solution is concentrated by boiling, a few crystals of oxalic acid added, and the anode (which may be coated with PbO₂) immersed in the hot solution for a few minutes, then rinsed off into the solution.

Separation of Lead. The solution is evaporated to small volume, about 40 ec. of dilute sulphuric acid (1:1) are added and the mixture evaporated to SO; funcs. The cooled concentrate is diluted with 100 cc. of water and again evaporated to fumes. About 300 ec. of water added and when the soluble salts have dissolved, the solution is filtered and the residue, PbSO; washed. The filtrate contains Zn, Ni, Co, etc.

Determination of Lead. The residue, PbSO₄, is dissolved by successive treatments with ammonium acetate and hot water, the lead precipitated from the solution, made slightly acid with acetic acid, by adding a slight excess of potassium chromate and the element determined as lead chromate according to the standard procedure for lead. See page 274 in the chapter on Lead.

Removal of the Hydrogen Sulphide Group. The filtrate from the lead sulphate is saturated with H₂S and filtered. The filtrate contains zinc, cobalt, and nickel. To recover any occluded zinc, the precipitate is dissolved in nitric acid, taken to funnes with sulphuric acid, diluted to about 200 cc., and again treated with H₂S. The filtrate from this precipitate is combined with the first portion. The precipitate is rejected.

Removal of Iron. This, if present, will be found in the filtrate. The Removal of Iron. This, if present, will be found in the filtrate. The H₂S is expelled by boiling and the solution concentrated to 400 cc. after adding 5 cc. of H₂O₂ to oxidize the iron. Five grams of anomonium sulphate are added, the solution made strongly animoniacal, and filtered. Iron is precipitated as Fe(OH)₂ and is thus removed. If much iron is present, a double precipitation is advisable to recover any occluded zinc, nickel, or cobalt, and the filtrates

Determination of Zinc. The filtrate from iron is concentrated to 400 cc., then made neutral to litinus by cautious addition of dilute sulphuric acid, drop by drop, and then faintly acid with 3 drops in excess. Zinc is now precipitated as the sulphide by saturating the solution with H₂S and allowing to stand over night. The sulphide is filtered off. The filtrate contains cobalt and nickel.

Zine sulphide is dissolved in hot dilute HCl (1:2) and a few crystals of KClO₂. The solution is evaporated to dryness, the residue taken up water containing a few drops of HCl and the extract filtered. (To remove any SiO₂ dis-

solved from the beakers.) Zinc carbonate is now precipitated (in a beaker of glass, which does not contain zinc) from the filtrate by addition of sodium carbonate, and ignited to the oxide ZnO.

$ZnO \times 0.8034 = Zn$

Determination of Nickel and Cobalt. The filtrate from the zine sulphide is examined for niekel and cobalt. About 0.5 cc. of sulphurie acid is added. H₂S is expelled by boiling, and 2 ee. of H₂O₂ added. The solution is concentrated to about 400 ec. (this should be free from nitric acid), treated with about 25 cc. of ammonium hydroxide, and electrolyzed over night with a current of 0.5 amperes. Nickel and cobalt, if present, are deposited on the cathode as metals and so determined. For greater details, consult the chapter on Nickel under the method by electrolysis.

Determination of Arsenic, Antimony, Selenium, and Tellurium

Separation of Copper. Ten to 50 grams of blister copper and 100 to 500 grams of refined copper are required for the determination. (For 500-grams sample, 5 lots of 100 grams are taken.) The drillings are dissolved in nitrie acid (40 ee. per 10 grams) and the solution boiled until a light-green precipitate appears on the surface. The liquor is diluted to 500 cc., and 5 cc. of ferrie nitrate containing 3% of iron are added. A basic acetate precipitate is now made, weak sodium hydroxide being added to neutralize the free acid, but not in sufficient amount to produce a permanent precipitate. If the end-point is overrun, nitric acid is added drop by drop until the solution clears. The solution is diluted to about 800 cc., 20 cc. of a saturated solution of sodium acetate added, the liquor brought to boiling and filtered hot through a large creased filter paper, the first portion of the filtrate being poured back on the filter. The residue is washed twice with hot water to remove the copper. Five ce. additional iron are added to the filtrate and a second basic acetate precipitation made, a separate filter being used. The precipitates are dissolved in the least amount of nitric acid necessary and the solutions combined. The liquor is concentrated to 150 ec., a pinch of potassium chlorate added, and the coneentration continued until the volume has been reduced to about 30 cc. An equal volume of strong hydrochloric acid is added and a second pinch of chlorate and the evaporation repeated to eliminate all traces of nitric acid.

The evaporation is best conducted in a casserole, resting in the circular opening of an asbestos board, in order that the sides of the vessel may be protected from the flame.

Separation and Determination of Arsenic. The solution is transferred to a distillation flask, arsenic reduced with ferrous chloride, and distilled according to the standard procedure for this element, p. 37.1 In this distillate arsenic is determined volumetrically.2 (See chapter on subject.) Antimony, selenium and tellurium remain in the flask.

Separation and Determination of Antimony. Twenty-five ce. of a saturated solution of zine ehloride are added to the liquor remaining in the distilling

¹The concentration should not be carried below 30 cc.

² Arsenic may be precipitated by H₂S, the sulphide dissolved in NH₄OH, the filtrate taken to dryness, HNO₂ added and the evaporation repeated. Arsenic now is determined by precipitation with AgNO₂ and titration of the silver with KCNS in presence of a ferric salt. Ag×0.2316=As.

flask after the elimination of arsenic. The antimony is now distilled, strong hydrochloric acid being introduced in the distilling flask drop by drop by means of a separatory funnel, to replace the solution distilled, the volume in the flask being kept as low as possible, avoiding crystallization. When the antimony has been completely eliminated, the contents of the distilling flask is poured out while still hot, and, together with the rinsings of the flask, placed aside for the subsequent determination of selenium and tellurium.

The distillate is neutralized with ammonia, then made slightly acid with HCl and antimony precipitated with H₂S. Most of the selenium and tellurium remain in the flask. Some of the selenium, however, distills with the antimony, hence this must be recovered from the antimony sulphide precipitate and at

the same time this must be purified.

The precipitate is dissolved in dilute HCl (1:2), containing a little bromine to oxidize the sulphur. The solution is filtered free from sulphur and the filter washed with a little dilute HCl. The filtrate should contain one-third its volume of strong HCl. Selenium is now precipitated by passing in SO₂ gas to saturation and bringing the solution to boiling. The precipitate is allowed to settle several hours and then filtered through a tared Gooch erucible. (To this is added the selenium and tellurium later obtained from the residue of the flask.) The filtrate contains antimony.

After boiling out the SO₂, the filtrate is first neutralized with ammonia, then mado slightly acid with hydrochloric acid and antimony precipitated as the sulphide by saturating the solution with H_2S , allowing the precipitate to settle, resaturating with H_2S and again allowing to settle. The filtered, washed precipitate is dissolved with sodium sulphide, and 10 ec. of 25% potassium cyanide (poison) added to the filtrate, together with 2 cc. of 25% sodium hydroxide.

The solution is now electrolyzed hot (90° C.) for an hour with a current of 0.5 ampere and antimony deposited as the metal on the cathode. This is quickly removed and washed by dipping it successively into a beaker of cold water, three of hot water and one of 95% alcohol. The foil is dried at 100° C., and then weighed, on cooling, as usual. Antimony is now removed by immersing the cathode in boiling nitric acid containing tartaric acid, and washing as before. The loss of weight of the foil is taken as antimony.

Note. It is advisable to test the electrolyte for antimony by acidifying the solution with oxalic acid (Hood). A reddish coloration indicates the incomplete removal of the element.

Determination of Selenium and Tellurium. The solution from the distillation flask is nearly neutralized with animonia and saturated with H₂S. The precipitate is filtered off and dissolved in equal parts of nitric acid (sp.gr. 1.42) potassium bromide bromine solution (20 cc. Br added to a saturated solution of KBr and diluted to 200 cc.). The liquor is diluted to 400 cc., 5 cc. of ferric nitrate (3% Fe") solution added, and sufficient ammonia to make the solution decidedly alkaline. The precipitate contains, besides the iron, all of the selenium and tellurium, whereas any copper that may have been present is removed. The precipitate, washed, is dissolved in hydrochloric acid, the free acid nearly neutralized and H₂S passed in to saturation. The precipitate is filtered off, washed, and dissolved in the nitric acid potassium bromide and bromine mixture stated above. The solution is filtered and then sufficient hydrochloric acid added to make the solution contain about one-third its volume of strong HCl. Selenium and tellurium are precipitated from this solution by pass-

ing in SO₂ to saturation, and boiling for a minute or so. The precipitate is now filtered into the crucible containing the selenium obtained in the purification of the antimony precipitate. After washing with hot water and once with 95% alcohol, the residue is dried at 100° C, for an hour and weighed as selenium and tellurium. Solution should stand three hours at least, or overnight, before filtering.

Note. The precipitate of sclenium and tellurium may contain gold, which should be determined by assay.

Determination of Oxygen

This determination is required only in refined copper. The method depends upon the reduction with hydrogen of cuprous oxide heated to redness; the water formed by the reaction being the measure of the oxygen.

Apparatus. The combustion-furnace is the same as that used for the determination of carbon. As it is necessary that the hydrogen be absolutely free from oxygen and moisture, the gas is passed through a preheater consisting of a platinum or silica tube of small bore heated to redness by a flame or an electrical device. The gas is then passed through a tube containing calcium chloride and finally through a P₂O₅ bulb containing the anhydride. In this purified form it enters the combustion-tube. The product of combustion, water, is absorbed in a tared bulb by P₂O₅, to which is attached a tube of calcium chloride.

Procedure. The sample, which has been drilled with considerable care to avoid overheating, is dried under partial vacuum in a desiccator after warming to below 70° C. for a few minutes.

One hundred grains are taken for analysis and placed in the combustion tube, the drillings being held in a large boat. Purified hydrogen is rapidly passed through the tube for half an hour to sweep out the air, the tube being cold. The tared P₂O₄ bulb and the calcium chloride tube are now attached. The heat is turned on to bring the sample to cherry red heat, 900° C., and the current of hydrogen passed slowly over the sample for several hours.

The increase of weight of the $P_2()_b$ bulb = $H_2()_c$

 $H_2O \times 0.8881 = O$. $O \times 4.9687 = CuO$.

Determination of Sulphur

This determination is rarely required in refined copper.

Twenty grams of blister, unrefined or cement copper, placed in a casserole, are treated cold with 50 cc. bromine-potassium bromide mixture (see under Determination of Sclenium and Tellurium). After standing at least ten minutes, 100 cc. of strong nitric acid are added. After another ten minutes the casserole is placed on the steam bath and the solution evaporated to small volume. This is taken up with 25 cc. of strong hydrochloric acid and evaporated to a pasty mass. The treatment is repeated to ensure the decomposition of nitrates and to expel nitric acid. It is now taken up with 5 cc. of hydrochloric acid, diluted with water and sulphuric acid precipitated as BaSO₄, according to the standard procedure for sulphur.

 $BaSO_4 \times 0.1374 = S$

Determination of Phosphorus

This determination is seldom required, and then only in low-grade copper and copper scrap containing phosphor bronze. The sample, dissolved in nitric acid, is treated with ferrie nitrate and the basic acetate precipitation made as has been described for the determination of arsenic, etc. The precipitate is dissolved in HCl, this solution then made strongly ammoniacal, and saturated with H2S, and filtered. The filtrate containing the arsenie and phosphorie acid is acidified, arsenie sulphide and sulphur filtered off, and phosphoric acid determined in the filtrate by precipitation with magnesia mixture as usual. See chapter on Phosphorus.

 $Mg_2P_2O_7 \times .2787 = P$.

DETERMINATION OF COPPER IN REFINED COPPER

In determining the quality of copper for electrical purposes each hundredth of a percent above 99.90 has its significance. The methods employed are the electrolytic and the hydrogen reduction methods. Silver present is rated as copper.

Electrolytic Method. The sample, consisting of unground drillings, should be untarnished, free of grease or oil, and cleaned of particles of iron by use of a good magnet.

Procedure. A eatch weight of about 5 grams is taken, each piece being examined for dust, particles from the drill and surface oxidation before it is

placed on the balance pan. Solution is effected in a special 400 cc. beaker which has hipped sides to support a series of watch glasses, the lower hip at the 125 ec. mark, the upper at 350 ce.

(Fig. 32.)

The drillings are treated with 50 ec. of a stock solution (10.5 ports nitrie acid and 4.5 parts of sulphuric). The watch-glass traps are put in place to retain the copper which is always entrained in the nitrogen peroxide fumes. Except that the current is maintained at .75 ampere throughout the period of electrolysis, the conditions are the same as have been described for



F10. 32.

the determination of copper by the "Small Portion Method."

Hydrogen Reduction Method. This method is applicable to the determination of copper in grades of refined copper which are characterized by a metallic impurity content which is constant and less than 0.01 per cent. The apparatus consists of a combustion furnace, preferably electrolytically heated, the temperature of which can be kept constant at about 950° C.; a silica tube of 1-in. bore, one end of which is connected with a large Peligot tube containing concentrated sulphuric acid, the other end is connected by a rubber plug and flexible tube with a source of purified hydrogen; porcelain combustion boats 95 mm. long, 18 mm. wide and 10 mm. deep.

Procedure. A catch weight of about 25.1 grams of drillings is placed in the combustion boat, and the boat inserted in the silica tube. After passing hydrogen for half an hour through the cold tube, the temperature is raised to 950° C. and so maintained for two hours. If the furnace is of a type, which will permit the removal of the tube without disconnecting the train,2 the tube is taken from the

¹ Ferguson, Jour. Ind. and Eng. Chem., May, 1910. * Electric Heating Apparatus Co., New York.

furnace without interruption of the stream of hydrogen and cooled by a jet of cold air. When cold, the mass of copper, the particles of which are cemented, is taken from the boat and weighed.

Note. If the sample is allowed to become molten, the boat and tube will be coated

with a film of copper.

A convenient and efficient type of combustion furnace, hinged design, is shown in Fig. 326. This furnace may be purchased from the Electric Heating Apparatus Company, New York City.



Fig. 32a.—Combustion Furnace, Hinged Design, Type 70—Shown with one "Spare"
Unit. Height to center, 91".

By courtesy of the Electric Resting Apparatus Company, New York City.

CHLORINE IN CEMENT COPPER AND COPPER ORES

If the material contains very little silver the following method is applicable in laboratories equipped with apparatus for furnace assaying.

Ten grams of the finely ground sample placed in an 800 ec. beaker are treated with 600 ec. water, 100 ec. nitric acid (free from iodic acid) and the mixture brought to boiling by gentle heating. After filtration and thorough washing, the insoluble residue is treated repeatedly with additional water and acid, of the above proportion, until a test of the filtrate with silver nitrate indicates complete extraction of the soluble chloride. The combined filtrates are treated with a slight excess of silver nitrate and chloride of silver precipitated and determined in the usual way.

On a separate 10 gram sample an assay of silver is made and the equivalent weight of chloride calculated. This equivalent is added to the weight of silver chloride obtained in the extract. The percent of chlorine is calculated from this result by the formula.

Weight of AgCl
$$\times$$
.2474 \times 100 = gram chlorine.

DETERMINATION OF COPPER IN BLUE VITROL

This is best determined on a 2 gram sample of the finely powdered dry salt or a catch weight of approximately 2 grams if the salt is moist. Copper is deposited electrolytically, the electrolyte being diluted to 130 ec. and containing 4 ec. of nitric acid and 5 ec. saturated solution of ammonium nitrate. A current of .18 amperes and an electrode of 11½ sq. in. depositing surface are used. If the salt contains insoluble matter consisting wholly of basic salts, complete solution is brought about by gently boiling after adding 4 ec. nitric acid and 25 ec. of hot water to the salt. If the insoluble matter shows a tendency to remain in suspension, the presence of arsenic or antimony is indicated. In this case the impurities are precipitated along with ferric hydroxide as has been previously described under the notes on the electrolytic determination of copper in blister copper.

DETERMINATION OF COPPER AND LEAD IN BRASS 1

One gram of the alloy is dissolved in 8 ec. nitrie acid and the nitrous fumes are boiled off; if tin is present, 40 cc. of boiling water are added, the metastannic acid allowed to settle on the hot plate for fifteen minutes and filtered off. (Method for tin is accurate only for wrought brass; high iron or antimony interfere).

The filtrate from the tin is electrolyzed for copper and lead. If the lead is less than 0.75 per cent, an ordinary sandblasted, spiral anode is used; if the amount of lead is 0.75 to 5 per cent a sandblasted gauze cylinder is necessary. For amounts of lead over 5 per cent either a smaller sample is taken or the greater part of the lead is precipitated as lead sulphate and the small amount of lead passing into the filtrate is recovered by electrolysis, using \(\frac{1}{4}\) ampere current per solution, after adding 3 cc. of nitric acid. For lead under 0.5 per cent; 5 cc. of 1:1 sulphuric acid are stirred in, after the current has been passing for at least ten minutes. If the lead is high the sulphuric acid is added after the electrolysis has continued for at least an hour. Under these conditions no lead sulphate deposits from the solution and as long as the current passes, the sulphuric acid present does not attack the PbO₂ deposited. After the sulphuric acid is added the current is raised to \(\frac{1}{2}\) ampere per solution and the electrolysis continued overnight.

The lead peroxide is dried at 250°C. for half an hour. The factor 86.43 gives the equivalent per cent lead. (Factor determined from the average of a large number of tests made on pure lead. The factor is best obtained under the conditions of the laboratory where the determinations are made, as it varies slightly with change of conditions.)

The copper on the cathode is washed, dried and weighed according to the usual standard procedure.

¹ Method of The National Brass and Copper Tube Company, communication by R. T. Roberts.

METHODS OF DETERMINING THE COMBINATIONS OF COPPER IN ORES AND FURNACE PRODUCTS

Sulphurous Acid Method¹

The method is based on results which show that cuprite, melaconite, malaconite, chrysocolla, and metallic copper, when finely pulverized, are readily and completely soluble in sulphurous acid. Copper sulphides, chalcoeite and chaleopyrite, are not attacked, no matter how finely pulverized or how long the period of contact. Metallic iron in quantities ordinarily found in pulverized mineral, even up to 3%, dissolves and affects the determination not at all, provided there is a strong excess of H2SO3. The essential conditions of the method are: (a) Fine pulverization of the sample in order completely to liberate the particles of copper minerals from the gangue; (b) The powdered sample must be kept in suspension during the period of lixiviation. Most ores give recovery in a half hour's contact and refractory ores yield in less than two hours.

In general, a solution containing 3% SO₂ should be used, but a much weaker one, as low as 0.75%, will suffice in the ease of some ores.

Note. For the manufacture of sulphurous acid, an absorption tower of 1 in. dia. and 4 ft. long glass tubing filled with broken hard-burned fire elay is set at an angle of 75° between two 3 to 5 gal. bottles, one about 5 ft. above the other. The tube is open at the top and scaled at the bottom with a plug of scaling wax, through which two small glass tubes extend. The upper bottle contains cold distilled water which is siphoned into the upper end of the absorption tower, the flow being regulated by a stopcock. A 6 to 50 lb. cylinder of sulphur dioxide is connected to one of the glass tubes extending into the absorption tower. On opening the valve of the cylinder the issuing SO_2 is gasified and passes to the tower where it is absorbed by water from the upper bottle, converted into SO₂ solution of the desired strength and caught in the lower bottle. A gas generator may be employed instead of cylinder of SO₂. A 3% solution of SO₃ may be produced by this apparatus at the rate of 3 liters per hour.

The procedure is as follows: Place 2 grams of pulp of 100 to 150 mesh fineness in a bottle, add 100 ec. 3% solution of SO2, seal the bottle and agitate by rolling ½ to 3 hours. Filter, wash the residue with SO2 solution and add the washings to the filtrate which contain in solution all oxides, carbonates and silicates of copper and all the metallic copper. To this solution and 5 to 10 ce. nitric acid, evaporate to 20 cc., dilute with distilled water and determine copper by the electrolytic or other method suitable to the quantity.

The residue from the filtration contains the unaltered and undissolved sulphides, the copper in which is determined by the method suitable to the grade of ore.

The Silver Sulphate-Sulphuric Method²

The method as described is especially adapted to the determination of metallic copper, cuprous oxide and eupric oxide in the raw material used for the manufacture of marine paints, but can with obvious modifications be applied

Van Barneveld and Leaver, Met. and Chem. Eng., Feb. 15, 1918, pp. 204-206. Eng. and Min. Jour., March 23, 1918, pp. 553-4.

Communicated by E. F. Fitzpatrick, chemist, Nichols Copper Co.

to the differentiation of sulphide and metallic from oxidized copper in ores. Particles of iron from the grinding plates do not interfere. The sample should be no coarser than 150 mesh.

According to the importance of close valuation of any constituent, 2, 5, or 10 grams of the sample are placed in an 800 cc. beaker together with 300 cc. of a neutral, saturated solution of silver sulphate. Boil gently for 10 minutes, decant the solution on to a 15 cm. thick filter paper of close texture and wash the residue in the beaker by decantation. These operations are repeated with addition each time of more silver sulphate, until a NH40H test of a filtrate shows no copper. When extraction of all metallic or sulphide copper has been accomplished, the entire residue is transferred to the filter and washed with hot water until an HCl test of the washing shows the presence of no silver. After evaporation to convenient volume and precipitation of silver from the hot liquid by dilute HCl (cautiously added to ensure no excess in case determination is to be by the electrolytic method), removal of the precipitate by filtration only after the liquid has become cold, copper is determined in the whole or an aliquot part by the electrolytic or iodide method.

The residue is washed (with care not to break the paper) into a beaker or flask and boiled for 5 minutes with 200 cc. of 10% H₂SO₄ to bring into solution all the copper combined as CuO and half that combined as Cu₂O. Decant the solution upon the filter used for the silver sulphate leach to decompose particles of oxides which may be retained upon the paper. Wash thoroughly with

cold water.

The copper on the filter, precipitated by the reaction $Cu_2O + H_2SO_4 = Cu + CuSO_4$, is dissolved with dilute nitric acid (about $12\% + HNO_2$), solution filtered and freed from silver by the same method and with the same precautions as were employed on the filtrate from the treatment with $10\% + H_2SO_4$. According to the amount of sample taken or the evident quantity of copper in solution, copper is determined, by any method suitable to the quantity, in the whole or an aliquot part. This copper in terms of per cent content in the sample multiplied by two gives the copper combined as cuprous oxide, and multiplied by 1.1258 gives per cent Cu_2O .

From the per cent of copper in the sample dissolved by 10% H₂SO₄ and determined by any method suitable to the quantity, is subtracted that precipitated by the same operation to obtain by difference copper combined as

cupric oxide. This multiplied by 1.2518 gives the per cent CuO.

Phosphoric Acid-Ammonium Chloride Method¹

This method depends upon the solubility of carbonates and silicates and insolubility of sulphides of copper in 15% phosphoric acid; also upon the solubility of metallic copper in a solution of ammonium chloride. Metallic iron does not interfere.

¹ Cremer, Met. and Chem. Eng., June 15, 1918, p. 645.

One gram of the fine sample is placed in a 500 ee. flat bottom flask, covered with 20 ee. of 15% H₃PO₄ and an equal amount of a 20% NH₄Cl solution and boiled gently for 10 minutes. Because H₃PO₄ gives to the solution a yellow tint which interferes with a sharp end point in the determination of copper by the cyanide method, a pinch of burned lime is added to the solution after it has cooled somewhat. The flask is thoroughly shaken, 25 cc. strong ammonia added and the solution boiled again for some time. The ammoniacal copper solution is filtered from the residue, allowed to cool and titrated by the cyanide method. The method as described is adapted to ores containing up to 3% of oxidized copper.

Caustic Soda-Sodium Tartrate Method¹

This method is based on the permanence of sulphides, the rapid yielding to solution of cupric oxide and the decomposition of cuprous oxide ores on treatment with a mixture of caustic soda and sodium tartrate; also upon the solubility of the more refractory form of oxide of copper by a mixture of ammonium hydrate and sulphate. The method is subject to some error because washing with the ammonia solution dissolves some copper from the chalcocite, and because of the difficulty of washing out all of the dissolved copper from the gelatinized spongy mass on the filter when chrysocolla is a constituent of the sample. These errors tend to balance each other when chalcocite and chrysocolla are both present and the resultant error in assays of ores containing less than 5% copper is not serious.

The procedure is to add 20 ee. of a solution of sodium hydrate and tartrate to 2 grams of pulp and boil gently for 5 to 10 minutes with occasional shaking of the beaker. While hot add 25 ee. 20% solution of ammonium sulphate, heat for 10 minutes, filter, wash several times with a hot mixture of ammonium hydrate and sulphate and finish the washing with hot water. Neutralize the filtrate with dilute $\rm H_2SO_4$, add $\rm 2\frac{1}{2}$ ee. concentrated HNO₃ and determine copper by the electrolytic method.

Note. The caustic soda-sodium hydrate stock solution consists of 100 grams sodium hydrate and 50 of sodium tartrate dissolved in 1000 cc. distilled water. The ammonium hydroxide and sulphate washing solution is a mixture of 100 cc. ammonium hydrate, 100 grams ammonium sulphate and 1000 cc. distilled water.

¹ Hunt and Thurston, Col. School of Mines Meg., Sept., 1917, pp. 157-8.

Sulphuric Acid-Mercury Method¹

This method depends upon the dissolution of oxide copper by dilute sulphuric acid and amalgamation of metallic copper, native and that resulting from the decomposition of cuprous oxide, thus separating intact sulphide copper.

According to the copper content, 1 to 3 grams of the sample are heated at 80° to 90° C. for 30 to 45 minutes in a 150 cc. casserole with 50 cc. of 4% II₂SO₄, care being taken to avoid boiling. Cool then to room temperature and add 4 to 5 cc. clean mercury. Rub the mercury about the casserole with the finger or other object for 3 or 5 minutes until it is certain that all the particles of ore have come in contact with the mercury. Pour the supernaturt solution, containing the sulphide minerals suspended in it into a beaker, taking care to retain the mercury in a single globule in the casserole. Wash the last traces of the ore into the beaker by means of a fine stream of water. The solution is now filtered and the copper determined by any suitable method.

The copper in the residue represents the sulphide, while that in the filtrate represents the so-called "oxide" or sulphuric acid soluble copper.

Copper in Brass-Short Iodide Method

Determination of copper in brass may be accomplished by the short iodide method given on page 256. The tin should remain in the solution since the tin oxide carries down a small amount of copper, which would be lost if the tin were removed by filtration as is prescribed for wrought brass using the electrolytic method. The sample brought into solution by dilute nitric acid (1:1), the factor weight 0.6357 requires about 10 cc. 11NO₃, and 5 cc. strong sulphuric acid are added and the sample evaporated to strong fumes. Any copper that may have been occluded by tin passes into solution upon dilution with water, lead will remain as a white precipitate, but does not interfere and should be left in the solution. Addition of bromine water is generally necessary, and in any case will do no harm, the bromine being subsequently removed by boiling the solution.

Copper in Babbitt Metal and Alloys High in Tin-Short Iodide Method

High tin alloys may be decomposed, generally, by strong sulphuric acid. This prevents formation of tin oxide obtained by the nitric acid method. If much copper is present, dilute nitric acid decomposition must be used, since copper is more readily attacked by nitric acid. (Copper is attacked by strong sulphuric acid, but is insoluble in dilute sulphuric acid or hydrochloric acid.) Tin oxide occludes copper, as has been stated under the iodide method for brass, treatment with sulphuric acid, as prescribed, frees any occluded copper. Since tin and lead do not interfere in the method, their removal is not necessary nor advisable.

¹ Maier, Eng. and Min. Jour., Feb. 23, 1819, pp. 372-3.

The editor (W. W. Scott) has taken the liberty to revise portions of this chapter.


FLUORINE

F', at.wt. 19; D (air) 1.3115°, sp.gr. (-187°) 1.14; m.p. -223; b.p. -187° C; acids. HF, H2SIF4.

DETECTION

Fluorine is the most active element known, and is by far the most active of the halogens, displacing chlorine, bromine, and iodine from their combinations.

Etching Test. The procedure depends upon the corrosive action of hydrofluoric acid on glass, the acid being liberated from fluorides by means of hot



concentrated sulphuric acid. This test is applicable to fluorides that are decomposed by sulphurie acid. The reactions taking place may be represented as follows:

- I. $CaF_2+H_2SO_4=CaSO_4+2HF$.
- II. $SiO_2+4HF=2H_2O+SiF_4$.

The test may be carried out in the apparatus shown in the illustration, Fig. 33. A clear, polished glass plate 2 ins. square, free from scratches, is warmed and molten wax allowed to flow over one side of the plate, the excess of wax being drained off. A small mark is made through the wax, exposing the surface of the plate, care being exercised not to scratch the glass. If the test is to be quantitative, the marks should be of uniform length and width. The powdered material is placed in a large platinum erucible (B) (a lead crucible will do); sufficient concentrated sulphurie acid is added to cover the sample. The plate (D) with the wax side down is placed over the Fig. 33.—Etching Test for Fluorine, crucible and pressed firmly down. To prevent the wax from melting, a condenser (C), with

flowing water, cools the plate. An Erlenmeyer flask (C) is an effective and simple form of condenser, though a metallic cylinder is a petter conductor of heat. A little water placed on the plate makes better contact with the condenser. As a further protection a wide collar of asbestos board (E) may be placed as shown in the figure. In quantitative work, where a carcful regulation of heat is necessary, the crucible is placed in a easserole with concentrated sulphuric acid or in a sand bath, containing a thermometer to register the temperature. The run is best conducted at a temperature of 200° C. (not over 210°-H,SO, fumes).

Chapter contributed by Wilfred W. Scott.

After an hour the wax is removed with hot water and the plate wiped clean, and examined by reflected light for etching. A test is positive when the mark can be seen from both sides of the glass. Breathing over the etched surface intensifies the mark.

Treatment of Fluo-Silicates not Attacked by Sulphuric Acld. The powdered material is mixed with about eight times its weight of sodium carbonate and fused in a platinum erueible. The cooled melt is extracted with water. Calcium fluoride is thrown out from the filtrate, according to directions under Preparation and Solution of the Sample. The fluoride may now be tested as directed in the etching test or as follows by the hanging drop test.

The Hanging Drop Test. The test depends upon the reaction 3SiF₄+3H₂O =2H₂SiF₆+H₂SiO₃.

If the material contains carbonates, it is calcined to expel carbon dioxide. Half a gram of the powdered dry material is mixed with 0.1 gram dried pre-

cipitated silica and placed in a test-tube, Fig. 34, about 5 cm. long by 1 cm. in diameter. A one-hole rubber stopper fits in the tube. A short glass tube, closed at the upper end, passes through the stopper extending about 3 mm. below. Two or three drops of water are placed in this small tube by means of a pipette, nearly filling it. Two ce. of concentrated sulphuric acid are added to the sample in the test-tube and this immediately closed by inserting the stopper carrying the hanging drop tube, exercising care to avoid dislodging the drop of water. The test-tube is placed in a beaker of boiling water and kept there for thirty minutes. If an appreciable quantity of fluorine is present a heavy gelatinous ring of silicie acid will be found at the end of the hanging drop tube in the stopper.

It is important to have material, test-tube, and rubber stopper dry, so that the deposition may occur as stated.

F10. 34.

F10. 34.
Hanging Drop Test
for Fluorine.

NOTE. Dr. Olsen³ makes the test by heating the sample in a small Erlenmeyer flask, with concentrated sulphuric acid. A watch-crystal with a drop of water suspended on its curved

A watch-crystal with a grop of water suspended on its curved of the curved surface is placed over the mouth of the flask. A spot etch is obtained in presence of fluorine.

Black Filter Paper Test. According to Browning, small amounts of fluorine



Fig. 35.

may be detected by the converse method for detection of silicates and fluosilicates (See silicon). The fluoride is placed with a suitable amount of silica, in a small lead cup, 1 cm. in diameter and depth (Fig. 35); a few drops of concentrated sulphuric are added; the cup is covered by a flat piece of lead with a small hole in the center; upon the cover is placed a piece of moistened black filter paper and upon this a small pad of moistened filter paper. The cup

is heated on the steam bath for ten or fifteen minutes. A white deposit will

¹C. D. Howard; Jour. Am. Chem. Soc., 1906, 28, 1238-1239. C. N., 1906, 36, 420.

Communicated to the author by J. C. Olsen.
P. E. Browning, Am. Jour. Sci. (4), 32, 249. "Methods in Chemical Analysis," by F. A. Gooch.

be found on the under side of the black filter paper, over the opening in the eover, if fluorine is present in an appreciable amount. (0.001 gram CaF, or above, and 0.005 gram Na AlF, will give the test.)

ESTIMATION

The determination of fluorine in the evaluation of minerals used for the production of hydrofluoric acid is of technical importance. The demand for elimination of the use of fluorides for preservatives of food makes its estimation in small amounts of importance.

Fluorine occurs only combined. It is found abundantly combined with lime in the mineral fluorspar, CaF2. It occurs as cryolite, Na3AlF6; apatite. 3Ca₄(PO₄)₂CaF₂. It is found in mineral springs, ashes of plants, in bones, and in the teeth (Cal'z). It occurs sparingly, with aluminum and silicon, in topaz, and with cerium and yttrium in fluocerite, yttrocerite, also in wavellite, wagnerite, etc.

Preparation and Solution of the Sample

Fluorides of the alkalies, and of silver and mereury, are readily soluble; copper, lead, zine, and iron fluorides are sparingly soluble; the alkaline earth fluorides dissolve in 100 cc. H_2O as follows: $BaF_1 = 0.163$ gram, $SrF_2 = 0.012$ gram, CaF₂ = 0.0016 gram.

Fluosilicates of potassium, sodium, and barium are slightly soluble in water and practically insoluble if sufficient alcohol is added.

Organic Substances.1 These are best decomposed by the lime method, the details of which are given in the chapter on chlorine under the section for the preparation and solution of the sample, p. 146. For fluorides in organic matter it is advisable to decompose the substance in a seamless nickel tube, 40 mm. long by 4-5 mm. bore. The end of the tube is sealed with silver solder. The lime used should be soluble in acetic acid. The tube is heated to yellow heat for two hours. The lime is then extracted with acetic acid and fluorine determined as calcium fluoride.

Silicious Ores and Slags. 0.5 to 1.0 gram of material is fused in a crueible with ten times its weight of sodium and potassium carbonates (1:1) and poured into an iron mould. If a porcelain erucible has been used, this is broken up and added to the cooled fusion. The mass is digested with about 200 cc. of hot water for an hour, the mass having been broken up into small lumps, (Kneeland recommends using an agate-ware easserole as diminishing the liability of subsequent bumping) * then boiled briskly for ten minutes longer and filtered, the solution being caught in a large beaker. The residue is washed with hot water, followed by a hot solution of ammonium carbonate and the insoluble material rejected. The silica is removed with ammonium earbonate, followed by the zine oxide treatment of the second filtrate, as described under the section of Separations. In presence of appreciable amounts of fluorides, the gravimetric precipitation of fluorine as calcium fluoride is recommended

of Ore Analysis."

¹ H. Meyer and A. Hub, Monatsch. für Chem., 1910, 31, 933-938. C. N., 1910, \$5, 489. E. Kneeland, Eng. and Min. Jour., 80, 1212. A. H. Low, "Technical Methods

The product is best decomposed by fusion with sodium Calcium Fluoride. and potassium earbonates, after mixing the fluoride with 2.5 times as much silicie acid, followed by ten times its weight of carbonates. Most of the silicic acid and all the fluorine will be changed to soluble alkali salts, while the calcium will be left as insoluble calcium carbonate. The mixture must be heated gradually to prevent the contents of the crucible from running over by the rapid evobution of carbon dioxide. The thin liquid fusion soon thickens to a pasty mass. The reaction is complete when there is no further evolution of carbon chioxide. The fused mass is now extracted with hot water as indicated above, and the soluble fluoride filtered from the calcium earbonate residue. Silicic acid is removed from the filtrate by addition of ammonium carbonate. Traces of silicie acid are removed from the filtrate taken to near dryness, after neutralizing the alkali with dilute hydrochloric acid (phenolphthalcin indicator), by the zinc oxide cmulsion method given under Separations. Fluorine is precipitated as calcium fluoride, according to the procedure given later on page 216.

Soluble Fluorides. See page 223b, 226.

Hydrofluorie Acid. See page 216. Also Vol. II Acids.

Valuation of Fluorspar. Perehloric Acid Method. One gram of fluorspar is treated with 15 ee. perehloric acid and 15 ee. of water in a suitable distillation flask and heated in an oil bath until the residue is almost dry. The distillation is continued with 10 ee. and finally 5 ec. portions of perehloric acid and equal amounts of water. Hydrofluoric acid may be determined as lead chlorofluoride in the distillate and water soluble residue analyzed for metals. If a residue analysis is desired treat first with H F evaporate and follow with perehloric acid. The residue is soluble in water or dilute HCl.

SEPARATIONS

Removal of Silicie Acid from Fluorides. This separation is frequently required, especially in samples where the sodium and potassium carbonate fusion has been required for decomposition of fluosilicates, or calcium fluoride mixed with silicie acid. (See Preparation and Solution of the Sample.)

To the alkaline solution about 5 to 10 grams of ammonium carbonate are added, the solution boiled for five minutes and allowed to stand in the cold for two or three hours. (Treadwell and Hall recommend heating to 40° C., and allowing to stand over night.) The precipitate is filtered off and washed with ammonium carbonate solution. The fluoride passes into the filtrate, while

practically all of the silicia acid remains on the filter.

Small amounts of silica in the filtrate are removed by evaporating the solution to near dryness on the water bath, then neutralizing the carbonate with dilute hydrochloric acid (phenolphthalein indicator) added to the residue taken up with a little water. Upon boiling the pink color is restored, the solution then cooled and acid again added to discharge the color; this is repeated until finally the addition of 1-2 ec. of 2 N. HCl is sufficient to discharge the color. Four to 5 cc. of ammoniacal zine oxide solution (moist ZnO dissolved in NH₄OH—Low recommends 20 cc. of an emulsion of ZnO in NH₄OH) is added and the mixture boiled until amnonia has been completely expelled. The precipitate of zine silicate and oxide is filtered and washed with water. The fluoride is determined in the filtrate by precipitation with calcium chloride as directed later.

Separation of Hydrofluoric and Phosphoric Acids. The method of Rose modified by Treadwell and Koell, takes advantage of the fact that silver phosphate is insoluble in water, whereas silver fluoride is soluble. The alkaline solution of the salts of the acids (solution of the sodium carbonate fusions) is carefully neutralized with nitric acid and transferred to a 300-ec. calibrated flask. A slight excess of silver nitrate solution is added, and the mixture made to volume and thoroughly shaken. After settling, the solution is filtered through a dry filter, the first 10 to 15 cc. being rejected; 225 cc. of this filtrate is again transferred to a 300-ec. calibrated flask, the excess of silver precipitated by adding sodium chloride solution, and after diluting to the mark and shaking, the precipitate is again allowed to settle; 200 cc. of this solution is taken for analysis, after filtering as previously directed. This sample represents 50% of the original sample taken. Fluorine is now determined by one of the procedures outlined

Separation of Hydrofluoric and Hydrochloric Acids. The solution containing hydrofluorie and hydrochloric acids, in a platinum dish, is treated with nitric acid and silver nitrate. The chloride is precipitated as the silver salt, whereas the fluorine remains in solution and may be filtered off through a glass funnel coated with paraffine or wax, or a hard rubber funnel. In presence of phosphoric acid, silver nitrate added to the solution will precipitate the phosphate as well as the chloride, whereas the fluoride remains in solution. The phosphate may be dissolved out from the chloride by means of dilute nitric acid.

Separation of Hydrofluoric and Boric Acids. An excess of calcium chloride is added to the boiling alkali salt solutions of the two acids. The precipitate is filtered off and washed with hot water. The residue, consisting of calcium fluoride, borate and carbonate, is gently ignited and then treated with dilute acetic acid, taken to dryness, and the residue taken up with acetic acid and water. Calcium acetate and borate are dissolved, whereas the fluoride remains insoluble and may be filtered off and determined.

GRAVIMETRIC METHODS FOR THE DETERMINATION OF FLUORINE

Precipitation as Calcium Fluoride

The method utilizes the insolubility of calcium fluoride in dilute acetic acid in its separation from calcium carbonate, the presence of which facilitates filtration of the slimy fluoride. The reaction for precipitation is as follows:

Procedure. Solution of the sample and the removal of silica having been accomplished according to procedures given under Preparation and Solution of the Sample, and Separations, the solution is neutralized, if acid, by the addition of sodium carbonate in slight excess; if basic, by addition of hydrochloric acid in excess, followed by sodium carbonate. To this solution, faintly basic, 1 cc. of twice normal sodium carbonate reagent is added, followed by sufficient

¹Z. anal. Chem., 48, 469, 1904. "Analytical Chemistry," Vol. 2, by Treadwell and Hall. John Wiley and Sons.

calcium chloride solution to precipitate completely the fluoride and the excess of carbonate, i.e., until no more precipitate forms, and then 2-3 cc. in excess. After the precipitate has settled, it is filtered and washed with hot water. (The filtrate should be tested for fluoride and carbonate with additional calcium chloride.) The precipitate of calcium fluoride and carbonate is dried and transferred to a platinum dish, the ash of the filter, burned separately, is added and the material ignited. After cooling, an excess of dilute acctic acid is added, and the mixture evaporated to dryness on the water bath. The lime is converted to calcium acctate, while the fluoride remains unaffected. The residue is taken up with a little water, filtered and washed with small portions of hot water, by which procedure calcium acetate is removed, while calcium fluoride remains on the filter. The residue is dried, separated from the filter and ignited. This, together with the ash of the filter, is weighed as calcium fluoride, CaF₂.

To confirm the result, the residue is treated with a slight excess of sulphuric acid and taken to fumes in a platinum dish. The adhering acid is removed as usual by heating with ammonium carbonate, and the ignited residue weighed as calcium sulphate. One gram of calcium fluoride should yield 1.7436 grams of calcium sulphate.²

 $CaO \times 1.3924 = CaF_2$, or $\times 0.677 = F$.

Factors. $CaF_2 \times 0.4867 = F$, or $\times 0.5126 = HF$, or $\times 1.0757 = NaF$. $CaSO_4 \times 0.5735 = CaF_2$.

Precipitation of Fluorine as Lead Chlorofluoride

The method, worked out by Starck, takes advantage of the double halide formed by action of lead ehloride upon a soluble fluoride. The compound, PbFCl, is about fourteen times the weight of the fluorine it contains. Unfortunately, the compound is quite appreciably soluble in water, so that a loss occurs if pure water is used for washing the precipitate. The method is limited to the determination of soluble fluorides.

The sample, made neutral, is treated with a large excess of a cold saturated solution (200 cc. PhCl₂ per 0.1 gram NaF in 50 cc. solution) of lead chloride, the precipitate, settled over night, is filtered off in a weighed Gooch crucible, washed several times with a saturated solution of lead chlorofluoride, and finally two or three times with ice-cold water. The compound is dried two hours at 140–150° C., and weighed as PbFCl.

¹The results are slightly low, owing to the solubility of calcium fluoride: 100 cc. H₂O dissolves 0.0016 gram CaF₂: 100 cc. 1.5 N. HC₂H₂O₂ dissolves 0.011 gram. Low recommends disintegration of the fluoride with sulphuric acid, diluting the mixture with water, boiling with ammonium chloride, and then with ammonium hydroxide and hydrogen peroxide. Calcium oxalate is now precipitated from the filtrate and CaO determined by titration with standard permanganate according to the usual procedure for determination of line.

*Z. anorg. Chem., 70, 173 (1911); Chem. Abs., 5, 2049 (1911).

*One hundred grams H₂O at 18° C. dissolves 0.0325 gram PbFCl and 0.1081 gram at 100° C.

VOLUMETRIC METHODS FOR THE DETERMINATION OF FLUORINE

Volumetric Determination of Fluorine—Formation of Silicon Tetrafluoride and Absorption of the Evolved Gas in Water. Offerman's Method ¹


Silicon tetrafluoride is formed by the action of sulphuric acid upon a fluoride in presence of silica, the evolved gas is received in water and the resulting compound titrated with standard potassium hydroxide. The following reactions take place:

A. $3SiF_4+2H_2O=2H_2SiF_6+SiO_2$.

. B. $H_2SiF_6+6KOH=6KF+SiO_2+4H_2O$.

The method is suitable for determining fluorine in fluorspar in evaluation of this mineral.

Procedure. The powdered sample, containing the equivalent of 0.1-0.2 gram calcium fluoride, is mixed with about ten times its weight of pulverized quartz (previously ignited and kept in a desiccator), placed in the decomposition flask F, shown in Fig. 36, and about 1 gram of anhydrous copper sulphate



F10. 36.

added, followed by 25 cc. of concentrated sulphuric acid. The stopcock E is closed and the air bath heated gradually till in one-half hour the temperature has risen to 220°. The cock E is now opened and air slowly forced through the apparatus (by means of water pump) at the rate of about three bubbles per second, the temperature being kept at 220°, and the flask containing the sample occasionally shaken. When the bubbles of silicon tetrafluoride have disappeared from F, the flame is removed, but the air current continued for half an hour longer. The solution in the receiving flask is now titrated with 0.1 N. KOH.

Notes. The apparatus shown in the cut is the form recommended by Adolph, and the details of procedure are essentially his. This method is preferred to that of Penfield, in which an alcoholic solution of potassium chloride is used to absorb the tetrafluoride, and the liberated hydrochloric acid titrated with the standard alkali in presence of cochineal indicator.

The results obtained by this method are generally low, but the procedure is useful for rapid valuation of fluorspar.

¹Z. angew. Chem., **3**, 615 (1890). Wm. H. Adolph, Jour. Am. Chem. Soc., **37**, 11, 2500 (1915).

² Am. Chem. Jour., **1**, 27 (1879).

The run having been made as directed, the solution in tube "K" is poured into a beaker, an excess of standard potassium hydroxide added and the excess alkali titrated with standard sulphuric acid, to the boiling solution. Norris prefers the use of litmus indicator to phenolphthalcin, claiming that the end point is sharper.

It is found advisable to use mercury in the tube "K" as a trap, thus preventing the stoppage of the delivery tube by crystallization. The gas rendily passes up through the mercury and is absorbed in the supernatant solution.

In place of using N/10 solutions the potassium hydroxide may be made of such strength that 1 cc. will equal 1% fluorine with 0.5 g. sample taken and the acid made to a corresponding strength.

The following suggestions for the method are made by W. V. Norris,

Colorado School of Mines.

It is especially necessary that all apparatus be dry, as the least amount of moisture will make the results run low. For this reason it is better to use phosphoric anhydride in washing bottle "B" instead of sulphuric acid.

The sulphuric acid used should be previously treated as follows:-Heat 500 cc. of acid to white fumes, cool, warm gently but not to fumes, then again cool in a desiceator until ready for use. This will produce an acid that will be an efficient dehydrator and will give off no free sulphur trioxide.

It is advisable to use a large excess of silica in the generator apparatus, preferably

ten times the weight of the sample taken.

The copper sulphate must be anhydrous, and can best be obtained by heating very thin layers of the pure blue crystals in an oven for about five hours at 215° C.


Adhere strictly to the directions of keeping the temperature in the flask at 220° C.,

as that temperature will give the maximum recovery.

The bottles "A," "B," "C" and "D" are for the purpose of thoroughly drying the air. "G" contains strong sulphuric acid, prepared as suggested above. "H" is filled with glass beads, to remove sulphuric acid spray; "I" and "J" are empty tubes which should be thoroughly dry. The gas is completely absorbed in tube "K."

Colorimetric Determination of Fluorine—Method of Steiger¹ and Merwin²

The method is based on the bleaching action of fluorine upon the yellow color produced by oxidizing a solution of titanium with hydrogen peroxide. A known amount of titanium in solution is mixed with definite volume of the solution containing the fluorine and the tint compared with a standard solution containing an equivalent amount of titanium. The extent of bleaching enables the computation of the fluorine present. The method is applicable to determination of fluorine in amounts ranging from 0.00005 to 0.01 gram. Merwin has shown that large amounts of alkali sulphates have a bleaching action similar to fluorine. Addition of free acid, or rise of temperature, intensifies the color lost by bleaching. Aluminum sulphate has no marked effect on standard solutions, or on solutions bleached by alkali sulphates, but it restores the color to a considerable degree to solutions bleached by fluorine. Ferric sulphate has a similar effect. Phosphoric acid bleaches a standard solution. Silica has little




F10. 37.

effect. According to Merwin an accuracy of 0.002 grain may be expected, an error which is half that of the most reliable gravimetric method.

Reagents. Standard Titanium Solution. An intimate mixture of 1 gram of TiO₂ and 3 grams of anunonium persulphate is heated until the vigorous action has ecased, and the ammonium sulphate is expelled. The residue is treated with 20 ec. of strong sulphuric acid, heated to funning and, when cold, poured into about 800 cc. of cold water. When the suspended salt has dissolved, 57.5 ec. of strong sulphuric acid are added, and the solution made up to 1000 cc. (50 ec. or more of the solution should be analyzed for TiO₂). One cc. will contain 0.001 gram TiO₂.

Standard Fivorine Solution. 2.21 grams of sodium fluoride, which has been purified by recrystallizing, washing, and igniting strongly, is dissolved in 1000 cc. of water. One cc. will contain 0.001 gram fluorine.

G. Steiger, Jour. Am. Chem. Soc., 30, 219, 1908.
 H. E. Merwin, Am. Jour. Sci. (4), 28, 119, 1909. Chem. Abs., 3, 2919 (1909).
 J. W. Millor, "A Treatise on Quantitative Inorganic Analysis." Chas. Griffin & Co.






Fig. 38.

Hydrogen Peroxide. Ordinary strength.

Standard Colored Solution. The solution used in determining fluorine in materials fused with alkali earbonates contains 10 cc. of the titanium solution, 4 cc. of hydrogen peroxide, and 4 cc. of concentrated sulphuric acid.

Apparatus. Nessler Tubes 6 cm. long, 2.7 ec. in diameter are recommended by the authors. Colorimeters may be used in place of Nessler tubes. A very suitable type for this purpose is shown on page 283, Fig. 43.

Procedure. Two grams of the powdered sample are fused with 8 grams of mixed sodium and potassium carbonates, the fusion taken up with hot water, and when leached, 3 to 4 grams of ammonium earbonate added. The mix is warmed for a few minutes and then heated on the water bath till the ammonium carbonate is decomposed and the bulk of liquid is small. Silica, ferric oxide, and alumina oxide are thrown down and are removed by filtration. The filtrate, which should not exceed 75 cc., is treated with 4 cc. of hydrogen peroxide, and then 10 ce. of standard titanium solution cautiously added (H2O2 prevents precipitation of TiO2 by the alkali carbonates), followed by 4 cc. of strong sulpharic acid to neutralize the alkali carbonates. The solution, neutral or slightly acid. acquires a light orange tint. A little sodium carbonate is added in just sufficient amount to discharge the color, and then a drop or so of acid to again restore it. The amount of excess acid now required depends upon the amount of fluorine present in the solution. For amounts of fluorine less than 0.0025 gram (0.125% of sample), 3 cc. of acid are added. For amounts of 0.0025 to 0.012 gram fluorine, 12 ec. of acid are added. The solution is diluted to 100 cc.

Comparison. The test solution is now compared with the standard solu-

tion containing 10 ce. titanium reagent, and the same amount of acid and hydrogen peroxide as in the test sample, in a volume of 100 ec. If Nessler tubes are used, these are held over a white surface illuminated with diffused light. In the absence of a bleaching substance, such as fluorine, the two solutions will have the same tint, but in presence of fluorine the bleaching effect will cause the test solution to appear paler than the standard. The depths of the liquids are adjusted so that the tubes will have the same intensity of color when moved from right to left or reversed. Should the left eye perceive a darker shade, the tube on the left will appear uniformly darker whether it be the test sample or the standard. The comparative depths of the liquids in the tubes are measured and the ratio obtained by dividing the depth of the fluorine solution by the depth of the standard and multiplying by 100. Reference may be made to the

plotted curve shown in Fig. 38. The ratio $\frac{\text{Depth of F Sol.}}{\text{Depth of Standard}} \times 100 = \text{the}$

abseissa, while the ordinate represents the amount of fluorine in the 2-gram sample.

Example. Suppose the test solution = 3.6 ec. and the standard = 4.5 cc., the ratio then=80, from the curve it is evident that the fluorine=0.00095 gram or 0.0475%, since a 2-gram sample was taken.

Notes. 1. The destruction of ammonium earbonate is necessary because ammonium sulphate bleaches the final solution and should be absent.

Changes of temperature of 50° C. intensify the color 5 to 15%.

 Increasing the acidity tends to restore the bleached color.
 The same ratios are obtained by dividing the final volume of the standard by the volume of the test in cases in which a colorimeter is used which requires the standard to be diluted.

According to Merwin, however, the bleaching effect of alkali sulphates, which are present, will make the ratio much higher than it would be if they were absent. (The sulphates alone give a ratio of 125.) This ratio should be determined on two 8-gram portions of the alkali carbonate mixture used in the fusion and the correction made accordingly. If this ratio is represented by m and r is the ratio of the two solutions, then (r-m) + 23,000 = g. F for amounts of fluorine not exceeding .0025 g. (3 et. H_2SO_4 , 22^{o} C., 4 et. H_4O_4 , .01 g. TiO₂). If the fluorine amounts to .0025 g. (3 et. H_2SO_4) is added and the formula required is (r-m-3)+6300 = g. F (m blank should be determined and should not much exceed 108). In absence of sulphates the following formulas are given-

(a) (r-100)+70,000=g. F, with .5 cc. H_4SO_4 , limits of F=.00005 to .001 g. (b) (r-100)+22,000=g. F, with 3.5 cc. H_2SO_4 , limits of F=.001 to .004 g.

Example (a) if r = 142, then $(142-100) \div 70,000 = .0006$ g. F.

THE VOLUMETRIC DETERMINATION OF FLUORINE 1

Two procedures are suggested—a rapid method depending upon the estimation of fluorine from the percentage of calcium present with fluorine, the calcium combined with commonly occurring substances being extracted by glacial acetic acid; and a procedure that depends upon separation of fluorine from its combination by converting it to soluble alkali salt and reprecipitating it from solution by addition of a known amount of calcium salt, the excess of the calcium being converted to oxalate and so determined, the amount combined with fluorine being thus estimated and the equivalent fluorine calculated.

Reagents

Calcium Acetate (0.25 N solution). 12.51 grams of pure ealeium carbonate are dissolved in 500 cc. of water and 75 cc. glacial acetic acid (large beaker necessary) and the acetate formed is placed in a graduated flask and diluted to 1000 cc. The solution is standardized by precipitation of the ealeium oxalate in an aliquot portion (40 cc.) and titration with standard potassium permanganate. Exact normality is recorded.

1 ec. 0.25 N solution=0.005 gram ca.cium.

Potassium Permanganate (0.25 N solution). 7.91 grams of pure crystals (KMnO₄) per liter are standardized against 0.67 gram of pure sodium oxalate equivalent to 40 cc. 0.25 N solution. Exact normality is recorded.

Sodium Oxalate (0.25 N solution containing 16.75 grams of the salt per liter). Solution is best effected in hot water. (Solubility, 3.22 grams per 100 ee. at 15° C.)

Preliminary Procedure

(a) Minerals Containing Phosphates or Sulfates. One gram of the finely powdered mineral, ore, or calcium fluoride salt is extracted with 50 ce. of dilute acctic acid (1 part glacial, 10 parts water) by gently warming for 15 to 20 minutes with stirring. The residue, transferred to a small, ashless filter, is washed with about 50 cc. of water making the total extract 100 cc. (Save for calcium determination, if desired.) The filter and residue are dried rapidly by spreading out on a watch glass. The fluoride is carefully transferred onto a sheet of glazed paper, the filter ignited, and the ash added to the fluoride. The residue is fused as directed under Fusion.

NOTE. For exact work an allowance has to be made for the solubility of the calcium fluoride. The following solubilities were found, 0.5-gram samples of material being taken and treated with 100 cc. of acetic acid of the strength stated:

Acid 1 part	H ₂ O	CaF ₂	CaCO ₃	Ca ₄ PO ₄	CaSO ₄
	2 parts	0.0103	Very soluble	0.240	0.084
	10 parts	0.0144	Very soluble	0.276	0.170
1 part	10 parts	0.0144	tery norman		

(b) Phosphates and Sulfates Absent. No acetic acid extraction is necessary.

(c) Sulfides Present. Sulfur as sulfide occurs generally combined with iron, copper, cobalt, etc. No special procedure is necessary here, as the sulfide is oxidized later.

¹ By Wilfred W. Scott. Reprinted from Industrial and Engineering Chemistry, Vol. 16, No. 7, page 703. July, 1924.

Fusion. Five grams of sodium carbonate and 10 grams of potassium hydroxide, placed in a 50 to 60-cc. silver or iron crucible, are brought to quiet fusion, and allowed to cool until a crust forms over the melt. Half a gram of the fluoride sample is intimately mixed with 0.5 to 1 gram of powdered silica prepared as outlined above (powdered sand free of fluorine will do), and placed in the crucible over the fusion. The crucible is covered and heat applied to bring the contents of the crucible to molten temperature. (High heat is not necessary.) Complete decomposition is effected in half to three-quarters of an hour. The crucible should be agitated frequently during fusion to mix the contents.

Note. Calcium fluoride is not so easily decomposed as many existing methods indicate. Hydrochloric acid apparently dissolves the mineral, but on dilution calcium fluoride precipitates. Sulfuric acid and potassium acid sulfate fusion is far from satisfactory; platinum is required and a loss due to bumping is liable to occur. Complete decomposition by acid treatment is frequently doubtful. The alkali fusion appears to be the best method for decomposing the fluoride.

If the mass is in molten condition, it may be poured in the lid of the erueible; if too viscous to pour, it is spread over the inner surface of the erueible by rotating the erueible over the flame. The material is now disintegrated and removed from the crucible and lid by action of about 200 cc. of hot water in a 500-ec. beaker. Ten cubic centimeters of hydrogen peroxide are added and the solution is boiled for about 5 minutes.

Nore. Fusions made in silver disintegrate more readily than those made in iron. Calcium carbonate tends to adhere to the walls of the crucible.

Boiling the solution expels the excess of peroxide, which interferes in the oxalate precipitation of calcium, if left in solution. Sulfides, iron, and other oxidizable materials are oxidized by the peroxide.

The solution containing the excess of sodium carbonate, potassium hydroxide, alkali fluoride, and the greater portion of the silica is filtered off; the residue, containing calcium carbonate (or phosphate if present in the fused material), silver, iron, some silica (10 to 15% of total), etc., is washed with hot water (10 times) and the washings are combined with the first filtrate. The residue is used for Procedure A, the filtrate for Procedure B.

Note. Should phosphates be present in the material, the greater portion will remain in the residue, and a small amount will pass into the filtrate as sodium salt.

 $Ca_2(PO_4)_2+3Na_2CO_3 \rightleftharpoons 3CaCO_3+2Na_3PO_4$

Procedure A-Determination of Calcium and Equivalent Fluorine

The residue washed into a benker is dissolved in hydroehloric acid (200 ee. of water, 20 ec. HCl). If any gritty material remains, it is advisable to fuse this with about 2 grams of sodium earbonate and 3 to 5 grams of potassium hydroxide, repeating the extraction with water; the residue is dissolved in hydroehloric acid and added to A and the water extract to B. The free acid is neutralized with ammonia, the solution heated and filtered, and the residue washed. Calcium passes into solution, iron (and silver) remains on the filter. (The crucible should be rinsed out with dilute hydrochloric acid, as calcium earbonate may adhere to the walls of the vessel.)

Note. A small amount of calcium is liable to be occluded by the hydroxide of iron. If this is present in appreciable amount, it is necessary to dissolve this in hydrochlorie acid, reprecipitate with ammonia, and filter, adding the filtrate to the main portion containing calcium.

Calcium is now precipitated from the filtrate by adding 0.25 N sodium oxalate. About 60 cc. are necessary for 0.5 gram of calcium fluoride (fluorspar). After heating to crystallize the oxalate, the calcium is filtered off, washed with water (6 times), dissolved in water containing sulfuric acid (200 cc. H₂O+10 cc. H₂SO₄), and titrated hot with 0.25 N potassium permanganate.

1 cc. $0.25 \text{ N KMnO}_4 = 0.005 \text{ gram Ca}$ and 0.00474 gram F.

Note. If the mineral was extracted with dilute acetic acid (1:10) to remove calcium phosphate, carbonate, or sulfate, an allowance should be made for the solubility of calcium fluoride of approximately 0.014 gram CaF, per 100 ee. extract at 18° C

If total calcium is desired, the calcium in the extract should be determined and

added to the calcium of the fluoridc.

Procedure B-Determination of Fluorine. Calcium Acetate Method

The alkaline filtrate (water extract of the fusion) contains the fluorine, sodium and potassium salts, and silicic acid.

The filtrate is heated to near boiling and sufficient 0.25 N calcium acctate reagent is added to precipitate all the fluorine and about 5 to 10 cc. excess (60 cc. per 0.5 gram CaF2). Glacial acetic acid is now added until faintly acid (if the solution is alkaline, litmus paper test) and then an excess of 1 cc. per 100 cc. of solution. The heating is continued for about 5 minutes.

Note. Upon addition of the calcium acetate, calcium carbonate also precipitates with calcium fluoride. When the solution becomes acid, the carbonate dissolves. If the acidity is correct, the precipitate settles readily and is easily filtered. Should it be finely divided and remain in suspension, the addition of sufficient potassium or sodium hydroxide to give an alkaline reaction will coagulate and settle the precipitate.

The solution and precipitate are transferred to a 500-ce. (or larger) graduated volumetric flask and, after cooling (18° C.), made to volume, then transferred to a large beaker and the precipitate allowed to settle for a few minutes. An aliquot portion of the clear solution is decanted through a filter, the first 5 to 10 cc. being rejected (several filters may be used to hasten filtration, if slow). A measured volume of the filtrate is now taken for the determination of excess calcium.

Precipitation and Titration of Calcium. Sufficient 0.25 N sodium oxalate solution is added to precipitate the calcium. It is safe to use as much oxalate as the aliquot requires in case no calcium was removed by fluorine-i.c., if one-half the total solution represents the aliquot, then 30 cc. of oxalate are The author prefers to precipitate the calcium from a weak acctic acid solution (about 0.5 cc. free glacial acetic acid per 100 cc.). This is the acidity of the solution obtained on adding calcium acetate and acetic acid, as directed, no alkali being added, as suggested, for settling stubborn calcium fluoride precipitates.

The calcium oxalate is coagulated by heating, then filtered, washed, and titrated with 0.25 N potassium permanganate in a hot solution containing sulfuric acid. The oxalate is best dissolved from the filter by hot water

containing sulfuric acid.

1 cc. 0.25 N potassium permanganate = 0.005 gram calcium.

Calculation. If A = cc. 0.25 N calcium acetate,

B = cc. 0.25 N potassium permanganate,

X = factor for converting the aliquot portion of solution taken in the calcium determination to total solution.

Then A cc. -XB cc. = cc. 0.25 N calcium acetate required by fluorine. The difference multiplied by 0.005=calcium combined with fluorine, or multiplied by 0.006 = equivalent fluorine (Ca $\times 1.2 = \text{F}$). (See Discussion.)

Counection. Owing to the slight solubility of calcium fluoride and possibly to the formation of a complex compound, calcium fluoride with a fluosilicate, a corrective factor seems to be necessary, the ratio of calcium to fluorine being 40:48, rather than the ratio represented in the formula CaF_2 .

Procedure C—Determination in Alkali Fluorides

Decomposition. 0.5 to 1 gram of the alkali fluoride is dissolved in about 100 cc. of hot water.

Precipitation. The fluorine is precipitated by adding, from a buret, a known amount of 0.25 N calcium acctate in sufficient amount to precipitate all the fluorine, and then 5 to 10 cc. in excess. If the solution has not become acid by addition of the reagent, make it so by adding acetic acid. The solution and precipitate are transferred to a 250-cc. graduated flask, and after cooling are made to volume and well mixed. An aliquot portion is now filtered through a fine-mesh filter (rejecting the first 5 to 6 cc.). A measured portion (half the original total is recommended) is heated to boiling, and calcium is precipitated by adding an excess of sodium oxalate. The solution is neutralized with ammonia and the calcium oxalate filtered off, washed, and titrated with 0.25 N potassium permanganate, according to the standard procedure. (See Precipitation and Titration of Calcium.)

Calculations of Fluorine.

If A = total cc. of 0.25 N calcium acctate,

B=cc. of 0.25 N potassium permanganate required by the calcium in half the total volume.

Then A-2B= per cent fluorine per half gram sample or $A-2B\times0.005$ $\times 0.948 = \text{gram fluorine}$.

It appears that the compound formed by addition of calcium acetate to the soluble fluoride is Cal²; it is thus possible to use the conversion factor 0.948 for converting the calcium, combined with fluoride, to its equivalent fluoride.

The method does not distinguish fluorine combined as a fluosilicate from fluorine

combined as a fluoride.

The best method for decomposing fluorspar or calcium fluoride was found to be by fusion with sodium and potassium carbonates, sodium carbonate and potassium hydroxide, or sodium or potassium carbonate and sodium hydroxide. The presence of

silica is necessary.

CaF₂ is precipitated by adding the calcium acetate reagent to the alkaline solution of the fluoride. The calcium carbonate, which also forms, redissolves as soon as the solution becomes acid. A large amount of acid is to be avoided, as this liberates silicic acid, which prevents the settling of the fluoride. When the solution is first acidified and the calcium fluoride is then precipitated, the compound settles badly and is difficult to filter. Should the fluoride be difficult to settle, it is preferable to make the solution alkaline by addition of sodium or potassium hydroxide, rather than to add an insoluble substance to carry down the floculent material. The alkali treatment coagulates the fluoride (probably dissolving silicic acid) and causes rapid settling.

VALUATION OF FLUORSPAR

The following procedure, worked out by Dr. Bidtel, meets the commercial requirements for the valuation of fluorspar. The determinations usually required are calcium fluoride, silica, and calcium carbonate; in some particular cases lead, iron, zinc, and sulphur.

Procedure. Calcium Carbonate. One gram of the finely powdered sample is placed in a small Erlenmeyer flask, 10 cc. of 10% acetic acid are added, a short-stemmed funnel inserted in the neck of the flask as a splash trap, and the mixture heated for an hour on a water bath, agitating from time to time. The calcium carbonate is decomposed and may be dissolved out as the soluble acetate, whereas the fluoride and silica are practically unaffected. The solution is filtered through a 7-cm. ashless filter, the residue washed with warm water four times, and the filter burned off in a weighed platinum crucible at as low a temperature as possible. The loss of weight minus 0.0015 gram (the amount of calcium fluoride soluble in acetic acid under the conditions named) is reported as calcium carbonate.

Silica. The residue in the platinum crucible is mixed with about 1 gram of yellow mercuric oxide, in form of emulsion in water (to oxidize any sulphide that may be present); any hard lumps that may have formed are broken up, the mixture evaporated to dryness and heated to dull redness, then cooled and weighed. About 2 cc. of hydrofluoric acid are added and the mixture evaporated to dryness. This is repeated twice to ensure complete expulsion of silica (as SiF₄). A few drops of hydrofluoric acid are then added, together with some macerated filter paper, and a few drops of ammonium hydroxide to precipitate the iron. The solution is evaporated to dryness, heated to dull redness, cooled and weighed. The loss of weight is reported as silica.

Calcium Fluoride. The residue is treated with 2 cc. of hydrofluoric acid and 10 drops of nitric acid (to decompose the oxides), the crucible covered and placed on a moderately warm water bath for thirty minutes, the lid then removed and the sample taken to dryness. The evaporation with hydrofluoric acid is repeated to ensure the transposition of the nitrates to fluorides, and if the residue is still colored, hydrofluoric acid again added and the mixture taken to dryness a third time; then a few drops of hydrofluoric acid are added and 10 cc. of ammonium acetate solution (the acetate solution is made by neutralizing 400 cc. of 80% acetic acid with strong ammonia, adding 20 grams of citric acid and making the mixture up to 1000 cc. with strong ammonium hydroxide). The mixture is digested for thirty minutes on a boiling water bath, then filtered and washed with hot water containing a small amount of ammonium acetate, and finally with pure hot water. (Several washings by decantation are advisable.) The residue is ignited in the same crucible and weighed as calcium fluoride. An addition of 0.0022 gram should be made to compensate for loss of CaF.

Pure calcium fluoride is white. To test the purity of the residue, 2 cc. of sulphuric acid are added and the material taken to fumes to decompose the fluoride; 1 cc. of additional sulphuric acid is added and the excess of acid expelled by heating. The residue is weighed as calcium sulphate. This is now fused with sodium carbonate, and the fusion treated with hydrochloric acid in excess. If barium is present the solution will be cloudy (=BaSO₄.)

¹ Dr. E. Bidtel, Jour. Ind. Eng. Chem., Vol. 4, No. 3, March, 1912.

ANALYSIS OF SODIUM FLUORIDE

Preparation of the Sample and Insoluble Residue. Ten grams of the sample arc dissolved in 250 cc. of water in a beaker, and boiled for five minutes, then filtered into a liter flask through an ashless filter; the residue is washed with several portions of water and ignited. This is weighed as insoluble residue. The filtrate and washings are made to 1000 cc. with distilled water.

Sodium Fluoride. Fifty cc. of the solution equivalent to 0.5 gram of sample are diluted to 200 cc. in a beaker, 0.5 gram sodium carbonate is added and the mixture boiled. An excess of calcium chloride solution is now added slowly and boiled for about five minutes. A small amount of paper pulp is added to prevent the precipitate from running through the filter, the precipitate allowed to settle and then filtered, using a 9-cm. S. & S. 590, or B. & A. grade A, filter paper. The fluoride is washed twice by decantation, and four or five times on the filter with small portions of hot water. The final washings should be practically free of chlorine.

The residue is ignited in a platinum dish, then treated with 25 cc. of acetic acid, and taken to dryness. This treatment is repeated and the residue taken up with a little hot water and filtered. The calcium fluoride is washed free of calcium acctate with small portions of water, remembering that CaF₂ is slightly soluble in water. The ignited residue is weighed as CaF₂.

$$CaF_{2} \times 1.0757 = NaF.$$

Sodium Sulphate. To the filtrate from calcium fluoride is added 10 cc. hydrochloric acid and then a hot solution of barium chloride. The BaSO₄ is allowed to settle, filtered, washed, dried, ignited, and weighed as usual.

$$BaSO_4 \times 0.6086 = Na_2SO_4$$

Sodium Carbonate. Sodium carbonate is determined on a 5-gram sample by the usual method for carbon dioxide as described in the chapter on Carbon.

Approximate results may be obtained by adding a small excess of normal sulphuric acid to 5 grams of the fluoride in a platinum dish, boiling off the carbon dioxide, and titrating the excess of acid with normal caustic, using phenolphthalein indicator.

One cc. N. $H_2SO_4 = 0.053$ gram Na_2CO_3 .

 $H_2SO_4 \times 1.0816 = Na_2CO_3$.

Sodium Chloride. Fifty cc. of the sample is titrated with N/10 AgNO₃ solution.

Silica. This is probably present as sodium fluoride and silicate. One gram of the sample is dissolved in the least amount of water and a small excess of hydrofluoric acid added to convert the silicate to silico-fluoride, then an equal volume of alcohol. After allowing to stand for an hour, the precipitate is filtered, washed with 50% alcohol until free of acid and the filter and fluoride are placed in a beaker with 100 cc. of water, boiled and titrated with N/10 NaOH.

One cc. N/10NaOH = 0.0015 gram SiO₂ or 0.0047 gram Na₂SiF₄.

Volatile Matter and Moisture. One-gram sample is heated to dull redness to constant weight. Loss of weight is due to moisture and volatile products.

Determination of Traces of Fluorine

An approximate estimation of traces of fluorine may be made by utilizing the method outlined for detection of this element. By varying the amounts of substance tested, an etch is obtained that is comparable with one of a set of standard etches, obtained with known amounts of fluorine in form of

calcium fluoride, added to the same class of material examined.

The conditions in obtaining the standard etches and those of the tests should be the same. This applies to the temperature of the paraffine bath, duration of the run, size of mark exposing the surface of the test-plate, and the general mode of procedure.

One gram of sample is placed in a lead bomb with 12 cc. of sulphuric acid, the bomb closed with glass plate in place and heated in an oil bath for 45 minutes at 165° C. The etching on the glass plate is compared with etching using known amounts of fluorine as CaF₂ and the same kind of glass.

The glass plate is kept cool by circulating cold water. The type of bomb Burned
Joint

Olass Plate

I" Hose
Coupling
Parts
Gasket

Immerse to this
Bupth in Oil
Bath

and its connections are shown in Figure 38a. Fig. 38a.

Note. The importance of regulating the temperature may be seen by the results obtained by Woodman and Talbot. With a temperature of 79-80° C., one part of fluorine may be detected in 25 to 100 thousand parts of material; by raising the temperature to 136° C., the delicacy of the procedure is increased to one part of fluorine in 1 to 5 million parts. The limit of delicacy is apparently reached at 213-218° C. (i.e.,

1 part F per 25 million).

A mctal condenser, such as is recommended for nicreury determinations, may be
A mctal condenser, such as is recommended for nicreury determinations, may be
and the oil or paraffine bath substituted by an electric heater automatically

controlled.

Crisco is claimed to be better than paraffine, as this does not give off any unpleasant fumes when heated.

Au, at.wt. 197.2; sp.gr. 19.33; m.p. 1063; b.p. 2530°C; oxides, Au,O, Au,O,

DETECTION

Because of the limited application and tediousness of wet methods, the detection of a small quantity (2 parts per million or less) of gold in a mineral or base metal is most positively carried out by furnace methods of assaying. Wet methods of detection of traces of gold can be applied only to solutions free of colored salts and elements precipitated by the reagents employed. As a rule, in the treatment of an unknown substance, advantage is taken of the solubility of most metals and their compounds, and insolubility of gold by one of the mineral acids.

Detection of Gold in Alloys. In metals or alloys which produce colorless solutions with dilute nitric acid, gold, in the absence of other insoluble matter, exhibits itself as a black or brownish residue which settles readily, and from which the liquid can be separated by eareful decantation. If unassociated with metals of the platinum group, this residue will become yellowish brown on heating with strong nitrie acid.

In copper, nickel and such alloys, which leave a residue of sulphur, carbon or silicious matter on treatment with dilute nitrie acid, the solution is filtered through double ashless filters and the filter and residue incinerated in a porcelain crucible. The residue, which may require pulverizing, is digested for a few minutes with aqua regia, and the dilute, filtered solution evaporated to dryness by heating below 200° F. Just as soon as dry, the mass is moistened with the least quantity of hydrochloric acid and the purple of Cassius test applied to its water solution in a small volume. This test is made by adding a solution of stannous chloride, containing stannic chloride. In strongly acid and concentrated gold solutions a precipitate of brown metallic gold is obtained. If the solution is but slightly acid and dilute, a reddish purple color is produced by colloidal gold and the stannic acid. The tint fades on standing. Addition of ammonia produces a red coloration.

This test applied to 1 part of gold in 600,000 of solution will impart a perceptible shade; to double this quantity, a mauve color. When gold is present in somewhat greater proportion a floceulent precipitate will form.

Test for Gold in Minerals. From minerals, in which the metal exists in unalloyed, or uncombined state, gold may be extracted by iodine in potassium iodide solution, or by ehlorine or bromine water. All minerals containing sulphides should be roasted. In natural or roasted state the sample should be ve y finely pulverized, and usually yields the gold best if first digested with nitric acid and washed free of soluble salts. The sample in a flask is covered with bromine water, the flask closed with a plug and shaken frequently during a period of three

Chapter contributed by W. G. Derby.

or four hours. The purple of Cassius test is applied to the extract, removed by decantation after on entration.

If it is evident that base metals are present in the bromine water extract in quantity sufficient to mask the purple of Cassius test, hydrogen peroxide is added to the concentrated liquid, slightly alkaline with sodium or potassium hydroxide or carbonate.1 After boiling the solution until hydrogen peroxide is removed, precipitated hydroxides or earbonates are dissolved by hydrochloric acid. Gold in exceedingly small quantity exhibits itself as a light-brown residue on a fine filter. This indication should be confirmed by a purple of Cassius test on the aqua regia solution of the residue; the test carried out in the same manner as on the residue from a solution of a metal.

Benzidine Acetate Tests. Maletesta and Nola: make use of benzidine acetate (1 gram benziding dissolved in 10 cc. acetic acid and 50 cc. water) as a reagent in the detection of gold and platinum in quite dilute solutions. Gold gives a blue coloration which gradually changes to violet. The coloration is green in the presence of free acetic acid, changing to blue with addition of benzidine in excess. Platinum gives a blue flocculent precipitate, the formation of which is promoted by heating. Free mineral acids have no influence on the gold and retard the platinum reaction only in the cold. Since ferric salts give a blue coloration, stable only in excess of benziding, their absence must be assured before application of the test for the precious metals. The limit of sensitiveness of the test is 35 parts for gold and 125 parts for platinum per 10,000,000.

Phenylhydrazine Acetate Test. E. Pozzi Escot adds phenylhydrazine acetate to a very dilute gold solution which contains an excess of an organic acid (formic or citric). A violet coloration, permanent for several hours, is imparted. The depth of color is proportional to the quantity when the gold is present in less

amount than one part in 500,000.

ESTIMATION

Solubility

Gold in massive form is practically insoluble in pure nitric, sulphuric or hydrochloric acids, but in the presence of oxidizing agents, is attacked appreciably by sulphuric, and actively by hydrochloric acid. Gold is found in minute quantity in the nitric acid solution of its alloys and in such as contain selenium, the amount may be a large part of the total present.

Gold is attacked energetically by aqua regia. Large amounts of gold are dissolved with requirement of least attention when the proportion of hydrochlorie

acid is several times that of the aqua regia formula, (3HCl: IHNO1).

Gold is dissolved by solutions of chlorine or bromine, by alkaline thiosulphates: in the presence of free oxygen by iodine in potassium iodide solution, by soluble cyanides, by fused potassium or sodium hydroxide; by fused potassium or sodium nitrate or sulphide. In a finely divided state, it is dissolved by a solution of potassium or sodium hydroxide.

Gold alloys quickly with molten lead. When in the form of bright, untarnished

particles it alloys readily with mercury.

Vanino and Seeman, Berichte, 32, 1968; Rossier, Zeit. Anal. Chem., 49, 733.

* Bull. Chim. Farm, 52, 461; Chem. Abs., April 20, 1397, 1914.

* Am. Chim. Anal. Appl., 1907, 12, 90; J.S.C.I., June 15, 1907, 645.

* Dewey, J.A.C.S., March, 1910, 318; E. Keller, Bull. Am. Inst. Min. Eng., 67, 681. 20

GRAVIMETRIC METHODS

Gold is always weighed in metallic state, and is determined most accurately in the form of the mass obtained by dilute nitric acid treatment of the silver alloy resulting from the operation of cupellation in the method of assaying by furnace processes. On account of tediousness in making complete separation from associated metals, and of uncertainty in collection of the product in a form suitable for accurate weighing, direct precipitation methods are never used for the valuation of gold-bearing material, but may be applied to the estimation of gold in plating baths, the Wohlwill parting electrolyte and solutions of similar type.

Precipitation of Gold. From such solutions of auric chloride, slightly acid with hydrochloric, freed of oxidizing agents by evaporation and displacement with hydrochloric acid, and containing but little of the salts of the alkalis or alkali earths, gold is separated from other than occluded platinum and palladium by precipitation with oxalic acid, ferrous sulphate, or hydrazine hydrochloride. The reactions are hastened by heat. When salts of the alkalis or earths are present, equally good separation and more complete precipitation can be obtained by addition of excess of sodium peroxide, boiling vigorously for a few minutes and then acidifying with hydrochloric acid. The precipitated metal is collected on an ashless filter paper, and after drying, weighed.

Gold precipitated from a very weak solution is in such fine form that it is not

wholly retained by the finest paper.

Wet Gold Assay of Minerals

A wet gold assay, suitable for prospector's use, is carried out by covering one assay ton (29.17 grams), of the finely pulverized natural or roasted orc, in a porcelain mortar, with 50 cc. of a solution of 2 parts of iodine and 4 parts potassium iodide in 100 cc. of water. Sulphide ores should be roasted and digested with nitric acid before treatment with the iodine solution. Similar treatment is advantageously applied to all ores. The ore is ground in contact with the iodine solution and additions of the halogen are made whenever the liquid becomes colorless. The solution is then allowed to stand at least an hour. To the filtrate and washings from the pulp, in a glass-stoppered bottle or flask, are added 5 grams of gold free mercury. The liquid is shaken vigorously with the mercury until clear. The mercury is then transferred to a small porcelain casserole, washed with clean water and dissolved by warming carefully with 10 cc. nitric acid. The gold mass is washed free of nitrate of mercury by decantation, dried and annealed by heating in a casserole over a Bunsen flame, and the metal weighed. Each milligram represents an ounce per ton. Results obtained by this method of assaying are usually more than 50 per cent of the actual gold content.

Electrolytic Method. The gold content of a cyanide plating bath containing no potassium ferrocyanide may be estimated by electrolysis.²

Procedure. A measured quantity, 25 to 50 cc. in a tared platinum dish, is diluted to 1 cm. of the rim of the dish and using a carbon or platinum anode, elec-

* Electro Deposition of Metals, Langbein.

De Luce, Min. Sci. Press, 100, 895; Hawson, Min. Sci. Press, 100, 936; Davis, Mines and Minerals, Oct., 1910, Feb., 1911; Austen, Inst. of Min. and Met., May 31, 1911.

trolyzed for about three hours at a current density $ND_{100} = 0.067$ amp. (0.0043 per square inch). Completion of deposition is recognized by the lack of any deposit within fifteen minutes, on a platinum strip suspended on the rim of the dish. The dish plus gold deposit is washed, rinsed with alcohol, dried at 212° and when cold weighed.

The following is a summary of the conditions of deposition of gold in compact form as described by Classen '3 grams potassium cyanidc were added to a gold chloride solution containing 0.0545 grams of gold in 120 cc. This solution heated to about 55° C. when electrolyzed at a current density of $ND_{100} = 0.38$ amp. (0.024 amp. per square inch) with a potential difference of 2.7–4.0 volts, deposited its gold content in one and a half hours. Time required for deposition is tripled if the electrolyte is at room temperature.

Miller² deposited 0.1236 gram of gold in two and a quarter hours from 125 cc. of electrolyte at 50° C. containing I grain potassium eyanide by a current of ND₁₀₀= 0.03 amp. (0.002 amp. per square inch) and 2.5 volts.

Perkin and Preble use an electrolyte containing ammonium thiocyanate in place of

potassium or sodium cyanide.

Gold is removed from the platinum electrode by warming with a solution of chromic anhydride in a saturated salt solution,4 or with a solution of potassium cyanide containing some oxidizing agent as hydrogen peroxide, sodium peroxide or alkali persulphate.

VOLUMETRIC METHODS

These methods are applicable to the determination of the strength of ehloride of gold solutions used in photography, electro gilding, and as electrolyte in the Wohlwill parting process.

Preparation of the Sample. Nitric acid or nitrates in the solutions should be removed by repeated evaporations to syrup with addition of hydrochloric acid saturated with chlorine. Free chlorine or bromine should be removed by addition of ammonia to formation of permanent precipitate, then making the solution very slightly acid with hydrochloric acid and heating until the precipitate of fulminating gold dissolves. The gold solution should contain but little free hydrochloric acid, an excessive amount of which may be removed by ammonia.

Permanganate Method

Weak gold solutions should be concentrated whenever possible. The permanganate method, which is not applicable when the sample contains organic matter, depends upon the titration, after complete precipitation of gold, of the unoxidized portion of a measured quantity of an added reagent of a known gold precipitating value. The reagent may be ammonium or potassium oxalate, ferrous sulphate or ferrous ammonium sulphate in solutions varying from 5 to 25 milligrams gold precipitating value and is titrated with a permanganate solution of approximately equal oxidizing strength. One part of gold requires for precipitation 1.08 of ammonium oxalate, 1.40 of potassium oxalate, 4.22 of ferrous sulphate, 5.96

¹ Classen, "Quantitative Chemical Analysis by Electricity," Classen-Boltwood.

² J.A.C.S., Oct., 1904, 1255.

³ Elec. Chem. and Mct. Ind., 3, 490.

⁴ Classen-Boltwood, "Quantitative Chemical Analysis by Electricity."

⁵ Rose, "Met. of Gold," 5th Ed., 469.

⁶ Bull. Chim. Farmac., 1894, XXX, III, 35; Oestr. Zeit. f. Berg. und Hut., 182, 1880; Sutton, "Volumetric Analysis," 10th Ed.; E. A. Smith, "Sampling and Assaying of Precious Metals"; Min. Eng. World, 37, 853.

parts ferrous ammonium sulphate, each in crystalline form. The most satisfactory precipitations are made with the iron salts. The standard solution of either should contain about 0.1 per cent of sulphurie acid. One part of gold, in solution as auric ehloride, has an oxidizing value equivalent to 0.4808 part of potassium permanganate.

The precipitating value of 0.2548 gram of dry Sorenson's sodium oxalate is 250 milligrams of gold, and by titrating a solution of this amount of oxalate in 250 ee. of water, aciduated with a few drops of sulphuric acid, the oxidizing value of the

permanganate solution is obtained in terms of gold.

The value of the precipitating reagent and relative oxidizing value of the permanganate solution can be checked very accurately by adding a measured quantity of the reagent to an excess of gold chloride, filtering, washing thoroughly, incinerating and weighing the precipitate obtained in a tared porcelain crucible.

Procedure. In earrying out the determination of a gold solution, a measured or weighed portion is freed of oxidizing agents, a measured amount of the standard precipitating reagent added in slight excess of the amount required to decolorize the solution, and digestion on a steam bath or hot plate continued until the gold settles out, leaving a clear liquid. A few drops of sulphuric acid may be then added and, without filtering, titration performed. The gold value of the quantity of reagent added, minus that found of the excess of reagent, is the gold content of the amount of the sample taken.

Iodide Method

Small quantities of gold are determined by Gooeh and Morley's iodide method.¹ A measured or weighed portion of the gold solution is treated, as has been described for removal of oxidizing agents, with an excess of free hydrochloric acid. Potassium iodide solution is run into the cold liquid until the gold precipitated as aurous iodide is completely dissolved. Starch solution is then added, and the amount of N/1000 thiosulphate required to decolorize the liquid noted. From this amount is deducted the amount of N/1000 iodine required to just produce a perceptible rose tint in the liquid.

The reactions involved are AuCl₁+3Kl = Aul+I₂+3KCl and I₂+2Na₂S₂O₂ =

2NaI+Na2StO.

The gold value of the N/1000 solution of sodium thiosulphate should be determined by performance of the operations of the method on a known quantity of gold, similar in amount and contained in a volume of solution approximately equal to that of the analysis.

Lenher's Method. By Lenher's method of determining gold in solutions free of oxidising agents, sulphurous acid of a reducing strength of 2-5 milligrams gold per co. is used as the reagent. The sulphurous acid requires frequent standardizing by means of standard iodine or potassium iodide to which a definite amount of standard permanganate has been added or by a gold solution of known strength. Using starch as indicator, the iodine liberated by addition of potassium iodide can be titrated by sulphurous acid. Bromine liberated by potassium bromide according to the equation, AuCl₁+2KBr=AuCl+2KCl+Br₂, can be titrated by sulphurous acid. Excess of magnesium or sodium chloride gives to auric chloride a yellow color which by sulphurous acid can be titrated to the colorless or aurous state. These alkaline salts do not interfere in the potassium bromide or iodide reactions.

¹ Amer. Jour. Sci., Oct., 1899, 261; Min. and Eng. World, 37, 853; Vol. Am., 7utton, 10th Ed.; "Assaying of Precious Metal," E. A. Smith.

² Jour. Am. Chem. Soc., June, 1913, 735.

COLORIMETRIC METHODS

Practical application of these methods is made in the estimation of gold in the liquors produced in the treatment of ores by the cyanide process.

Prister's Method

By Prister's method ¹ a slight excess of copper solution is added to a 100 to 200-cc. portion of a cyanide solution in which the cyanide has been decomposed by boiling several minutes after acidifying with hydrochloric acid. Assurance of the presence of an excess of copper is made by spot test with a solution of potassium ferrocyanide.

The copper solution is made by boiling for ten minutes in contact with copper shavings, a solution of 1 part blue vitriol and 2 parts salt in 10 parts of water, and adding a little acetic acid on cooling. A few drops of a 1 to 2 % sodium sulphide solution are added, the liquid boiled for five minutes, the precipitate allowed to settle, and liquid separated by decantation on to a filter. The precipitate in the beaker and on the filter is dissolved with 2½ to 3 cc. of a 3 to 5% solution of potassium cyanide to which a few drops of potassium hydrate solution has been added.

Gold is precipitated from this cyanide solution (which may be turbid), by addition of 1 to 2 g ams of zine dust and warming to 100° F, for half an hour. Liquid is separated by decantation through a filter. The residue on the filter and in the beaker is first treated with hydrochloric acid to dissolve zinc, then with 10 cc. aqua regia, the reagent being passed several times through the filter. Stannous chloride solution is then added to the liquid diluted to 20 cc. Comparison of the coloration produced is made with that from a standard solution of gold treated in the same manner.

Cassel's Method. By Cassel's method ² 0.5 gram potassium bromate is mixed with 10 to 50 cc. of the cyanide solution and concentrated sulphuric acid added gradually with constant agitation until reaction commences. When the reaction stops, saturated solution of stannous chloride is added dropwise until the liquid is just colorless. The tint produced is compared with that from a standard gold solution treated in the same manner.

Moir's Method. By Moir's method a measured quantity of the cyanide solution is oxidized by addition of 1 to 2 grams of sodium peroxide and boiling. If sufficient sodium peroxide is present, the brown spot produced by addition of a few drops of lead acetate will immediately dissolve. The lead-aluminum couple formed by addition of aluminum powder precipitates gold which is filtered off. To the aqua regia solution of the precipitate a solution of stannous chloride is added drop by drop until the liquid is dissolved. The purple of Cassius tint developed is compared with permanent standards composed of mixtures of solutions of copper sulphate and cobalt nitrate which have been adjusted to shades corresponding to those produced hy known amounts of gold treated according to the method described.

Bettel 4 filters suspended matter from the cyanide solution, adds a measured quan-

Bettel 4 filters suspended matter from the cyanide solution, adds a measured quantity of a strong solution of potassium cyanide which contains some cuprous cyanide and precipitates gold by the copper zinc couple produced by addition of a measured quantity of zinc fume. The remainder of the method is the same as Prister's.

⁴ Min. World, 33, 102 and 35, 987.

¹ Proc. Chem. Met. and Min. Soc. of So. Af., IV, 235, 1904.

² Eng. and Min. Journal, Oct. 31, 1903. ³ Proc. Chem. Met. and Min. Soc. of So. Af., Sept., 1913.

Dowsett's 1 factory test of barren cyanide solutions is capable of detecting variation in gold value of 1 cent per ton in solutions varying from one cent to about 15 cents per ton. To 500 ec. of the sample in a bottle with slight shoulder are added 10-15 cc. saturated sodium cyanide solution, 2 or 3 drops saturated lead nitrate solution and 1-2 grams 200-mesh fine zine dust. The stoppered bottle is shaken violently until the precipitate settles rapidly. Inverting the bottle allows the precipitate to settle into a casserole. Clear liquid is removed by decantation. Zine is dissolved by hydrochloric acid added drop by drop until reaction ceases. A few drops excess hydrochloric acid and 3-5 drops dilute nitrie acid (sp.gr. 1.18) are added and the liquid concentrated to 1-2 ee. The solution is transferred to a \(\frac{1}{2} \)-in. diameter test-tube, about 1 cc. of stannous ehloride reagent added and grade of cyanide solution estimated by the tint obtained after one or two minutes standing. 1/1000 oz. gold per ton of original cyanide solution gives a very slight coloration; 15/10000 a slight yellow; 1/500 a slight pinkish yellow; 3/1000 a strong pink; 1/250 the purple of Cassius. Too much nitrie acid hinders the production and the presence of mercury causes modification of the eolor. No more lead nitrate should be used than is sufficient to produce a rapidly settling precipitate. The stannous chloride reagent is a water solution containing about 121% crystals and 10% concentrated hydrochloric acid.

PREPARATION OF PROOF GOLD

Commercial gold may contain arsenic, antimony, selenium, tellurium, copper, lead, mercury, silver, zinc, palladium, platinum and other metals of the platinum group. The method of making pure gold depends to a certain extent upon the character and quantity of impurities.² The method described assumes the raw material to be of extreme impurity. The metal is treated in 10-g am portions.

When the metal contains silver its solution is effected most quickly by rolling extremely thin and annealing before treatment with acids.

The strips, in a covered No. 6 casserole on a steam bath, are dissolved with a mixture of 5 cc. nitric and 50 cc. hydrochloric acid. If but little silver is present the quantity of hydrochloric acid may be decreased to 25 cc. The solution is evaporated to dryness and the casserole gently heated over a l'unsen flame until all the gold is reduced to metal.

Digestion with animonia will dissolve most of the silver and copper. After decanting the animoniacal solution and washing with water, the gold is digested with hot nitrie acid. If the solution is wine colored the digestion is continued for several hours, and reheated with fresh portions of acid until the absence of color indicates removal of palladium. The gold is now dissolved with 5 cc. of nitrie and 15 to 20 cc. hydrochloric acids, evaporated to dryness, residue moistened with the least quantity of hydrochloric acid, dissolved with about 800 ee. water and liquid transferred to a 1000 cc. beaker. After the faint cloud of silver chloride settles to the bottom of the beaker, the clear liquid only is siphoned to another beaker, and allowed to stand another period of several days if it appears at all cloudy. The clear liquid is now siphoned into a 1000-cc. flask and sulphur dioxide gas passed until the gold is practically all precipitated. The gold is allowed to

¹ Trans. I.M.M., 1912-13, 190; Met. and Chem. Eng., July, 1914.

² Eng. and Min. Jour., 68, 785, 1899; "Metallurgy of Gold," Rose, 5th Ed.; Min. and Sci. Press, Nov. 14, 1903; "Manual of Fire Assaying," Fulton; "Assaying of Precious Metals," Smith.

settle, digested with hot nitric acid for a few minutes, washed by decantation several times, redissolved with aqua regia, solution transferred to a casserole, and nitric acid expelled by repeated evaporation to syrup with addition of hydrochloric acid. The product of the second evaporation is moistened with the least quantity of hydrochloric acid, dissolved with water and solution transferred to a 1000-cc. beaker or Erlenmeyer flask. To the liquid of about 500-cc. volume is added 11 grams of ammonium oxalate crystals. The beaker is permitted to remain on a steam bath until reaction is complete. The spongy mass of gold is now washed with hot water by decantation until free of salts.

The gold is dried, melted in a clay erucible which has previously been thinly glazed with borax glass and poured out into a mold of charcoal, graphite and clay

or iron polished with graphite.

The ingot, which will have a volume of half a cubic centimeter, is cleaned by paring with a knife and rolled or hammered into a thin sheet. The rolls or hammer should be clean, bright and free of grease.

The gold, cut into convenient strips, is digested for several hours with hydrochloric acid and finally washed thoroughly with distilled water.

The dried gold thus prepared may be considered 1000 fine.

FURNACE METHODS OF ASSAY FOR GOLD

Details of assay for gold and silver by furnace methods will be found following the chapter on silver.

I, at.wt. 126.93; sp.gr. 4.948^{17°}; m.p. 113.5°; b.p. 184.4° C; acids, HI, HIO, HIO, HIO,

DETECTION

The element may be recognized by its physical properties. It is a grayish black, crystalline solid, with metallic luster, brownish-red in thin layers. It vaporizes at ordinary temperatures with characteristic odor. Upon gently heating the element the vapor is evident, appearing a deep blue when unmixed with other gases, and violet when mixed with air. It colors the skin brown. Chemically it hehaves very similarly to chlorine and bromine.

Free iodine colors water yellow to black, carbon disulphide violet, ether or chloroform a reddish color, cold starch solution blue.

Tannin interferes with the usual tests for iodine, unless ferric chloride is

Iodide. The dry powder, heated with concentrated sulphuric acid, evolves violet fumes of iodine. Iodine is liberated from iodides by solutions of As⁵, Sb⁵, Bi⁵, Cu", Fe"', Cr⁵, H₂Fe(CN)₄, HNO₂, Cl, Br, H₂O₂, ozone.

Insoluble iodides may be transposed by treatment with H2S, the filtered

solution being tested for the halogen.

Iodate. The acidulated solution is reduced by cold solution of SO_2 , or $K_4Fe(CN)_4$, (acidulated with dilute H_2SO_4), or by Cu_2Cl_2 , H_2AsO_4 , $FeSO_4$, etc. An iodate in nitric acid may be detected by diluting the acid with water, adding starch solution, then hydrogen sulphide water, drop by drop, a blue zone forming in presence of the substance.

ESTIMATION

The element is found free in some mineral waters; combined as iodides and iodates in sea water; in ashes of sea plants; small quantities in a number of minerals, especially in Chili saltpeter as sodium iodate, hence in the mother liquor from the Chilian niter works from which iodine is principally produced. Sea-weed ash (drift kelp, Laminaria digitata and L. stenophylla) is an important source of iodine.

Free iodine, potassium iodide, iodoform, are the principal commercial products.

Preparation and Solution of the Sample

In dissolving the substance it will be recalled that free iodine is soluble in alcohol, ether, chloroform, glycerole, benzole, carbon disulphide, solutions of soluble iodides. One hundred cc. of water at 11° C. is saturated with 0.0182 gram iodine, at 55° with 0.092 gram.

Chapter contributed by Wilfred W. Scott.

Iodides of silver, copper (cuprous), mercury (mercurous), and lead are insoluble, also TII, PdI₂. Iodides of other metals are soluble; those of bismuth, tin, and antimony, require a little acid to hold them in solution.

Iodates of silver, barium, lead, mercury, bismuth, tin, iron, chromium require more than 500 parts of water at 15° C. to hold them in solution. Iodates of copper, aluminum, cobalt, niekel, manganese, zine, calcium, strontium, magnesium, sodium, and potassium are more soluble. One hundred cc. of cold water dissolves 0.00385 gram AgIO₄ and 0.000035 gram AgI at ordinary temperatures.

Free Iodine (Commercial Crystals). Iodine is best brought into solution in a strong solution of potassium iodide according to the procedure described for standardization of sodium thiosulphate under Volumetric Methods. The iodine is now best determined volumetrically by titration with standard thiosulphate or arsenic.

Iodine or Iodides in Water. The sample of water is evaporated to about one-fourth its volume and then made strongly alkaline with sodium carbonate. The precipitated calcium and magnesium carbonates are filtered off and washed. The filtrate containing the halogens is evaporated until the salts begin to crystallize out. The list concentrated solution is poured into three volumes of absolute alcohol and the resulting solution again filtered. The residue is washed four or five times with 95% alcohol. All of the bromine and iodino pass into tho solution, whereas a large part of chlorine as sodium chloride remains insoluble and is filtered off. About half a cc. of 50% potassium hydroxide is added and a greater part of the alcohol distilled off with a current of air. The residue is concentrated to crystallization and again poured into three times its volume of absolute alcohol and filtered as above directed. This time only one or two drops of potassium solution is added and the procedure repeated several times. The final filtrate is freed from alcohol by evaporation, the solution taken to dryness and gently ignited, then taken up with a little water and filtered. Iodine is determined in the filtrate, preferably by the volumetric procedure III, decomposition with nitrous acid, described under Volumetric Methods, p. 242.

Organic Substances. If only an iodide is present, the Carius method is followed; in presence of other halogens, the "lime method" is preferred. Details of these methods are given in the chapter on Chlorine under Preparation and Solution of the Sample, p. 145.

Silver iodide cannot be separated from the glass of the combustion-tube by solution with ammonium hydroxide as is the chloride or bromide of silver. The compound, together with the glass, is collected upon a filter paper, and washed with dilute nitric acid, followed by alcohol; then dried at 100° C. After removing most of the iodide and the glass, the filter is ignited in a weighed porcelain crucible, the main bulk of the material then added, the substance fused and weighed as AgI+glass. The mass is then covered with dilute sulphuric acid and a piece of pure zine added. After several hours (preferably over night) the excess zinc is carefully removed and the iodine solution decanted from the glass and metallic silver, and the residue washed by decantation. The silver is now dissolved in hot dilute nitric acid, then filtered from the residue of glass through a small filter. The glass and filter are ignited and weighed. The difference between the two weighings is due to silver iodide.

Minerals. Phosphates. The substance is decomposed by digestion with 1:1 sulphuric acid in a flask through which a current of air passes to sweep out

the iodine vapor into a solution of potassium hydroxide, the sample being boiled until all the iodine vapors have been driven into the caustic. Iodates are converted to iodides by reduction with sulphurous acid.

With the iodine content below 0.02%, a 50 to 100-gram sample should be taken.

SEPARATIONS

Separation of Iodine from the Heavy Metals. The heavy metals are precipitated as earbonates by boiling with solutions of alkali earbonates, the soluble alkali iodide being formed.

Iodine is liberated from combination by nitrous acid.

Silver iodide may be decomposed by warming with inctallie zinc and sulphuric acid.

Separation of Iodine from Bromine or from Chlorine. Details of separation and estimation of the halides in presence of one another are given in the chapter on Chlorine. Advantage is taken of the action of nitrous acid on dilute solutions, free iodinc being liberated, while bromides and chlorides are

not acted upon.

The solution containing the halogens is place in a large, round-bottom flask and diluted to about 700 ce. Through a two-holed stopper a glass tube passes to the bottom of the flask; through this tube steam is conducted to assist the volatilization of iodinc. A second short tube connected to the absorption apparatus conducts the evolved vapor from the flask into a 5% caustic soda solution containing an equal volume of hydrogen peroxide (about 50 ce. of each). The absorption system may be made by connecting two Erlenmeyer flasks in series, the inlet tubes dipping below the solutions in the flasks. It is advisable to cool the receivers with ice.

Two to 3 ec. of dilute sulphurie acid (1:1) and 25 cc. of 10% sodium nitrite solution are added to the liquid containing the halogens, the apparatus is immediately connected, and the contents of the large flask heated to boiling, conducting steam into it at the same time. The iodine vapor is gradually driven over into the cooled receiving flasks.

When the solution in the large flask has become colorless it is boiled for half an hour longer. The steam is now shut off, the flask disconnected from the receiving flasks and the heat turned off. The contents of the receiving flasks are combined with the washing from the connecting tubes and the solution heated to boiling to expel, completely, hydrogen peroxide. The cooled liquid is acidified with a little sulphuric acid and the solution decolorized with a few drops of sulphurous acid. Iodine is now precepitated as silver iodide by adding an excess of silver nitrate and a little nitric acid and boiling the mixture to coagulate the precipitate. AgI is determined as directed on page 239.

Chlorine and bromine remain in the large flask in combined form and may be determined in this solution if desired.

Separation of Iodine from Chlorine and Bromine by Precipitation as Palladous Iodide. The solution containing the halogens is acidified with hydrochloric acid, and palladous chloride solution added to the complete precipitation of the iodide. The compound is allowed to settle in a warm place for twenty-four hours or more and then filtered and washed free of the other halogens. It may now be dried and weighed as palladous iodide, PdI₂, or ignited in a current of hydrogen, then weighed as metallic palladium and the equivalent iodine calculated. See Gravimetric methods.

GRAVIMETRIC METHODS

Precipitation as Silver Iodide

The procedure is practically the same as that described for determining chlorine.

Silver nitrate solution is added to the iodide solution, slightly acidified with nitrie acid. The precipitate is filtered into a weighted Gooch crucible, then washed dried, gently ignited, and weighted as silver iodide.

$$AgI \times 0.5406 = I \text{ or } \times 0.7071 = KI.$$

Note. If filter paper is used in place of a Gooch crucible, the precipitate is removed and the filter ignited separately. A few drops of nitric and hydrochloric acid are added, the acids expelled by heat and the residue weighed as AgCl. This, multiplied by 1.638 = Agl. The result is added to the weight of the silver iodide, which is ignited and weighed separately.

Determination of Iodine as Palladous Iodide

This method is applicable for the direct determination of iodine in iodides in presence of other halogens.

The method of isolation of iodine as the palladous salt has been given under Separations. The salt dried at 100° C. is weighed as PdI₂.

$$Pdl_2 \times 0.704 = I$$
.

PdI, ignited in a current of hydrogen is changed to metallic palladium.

 $Pd \times 2.379 = I$.

VOLUMETRIC METHODS

Determination of Hydriodic Acid—Soluble Iodides

Free hydriodic acid cannot be determined by the usual alkalimetric methods for acids. The procedures for its estimation, free or combined as a soluble salt, depends upon the liberation of iodine and its titration with standard sodium thiosulphate, in neutral or slightly acid solution; or by means of standard arsenious acid, in presence of an excess of sodium bicarbonate in a neutral solution. The following equations represent the reactions that take place:

I. Thiosulphate. $2Na_2S_2O_3+I_2=2NaI+Na_2S_4O_6$.

II. Arsenite. $Na_3AsO_4+I_2+H_2O=Na_3AsO_4+2HI$.

The free acid formed in the second reaction is neutralized and the reversible reaction thus prevented:

$$HI + NaHCO_2 = NaI + H_2O + CO_2$$
.

The presence of a free alkali is not permissible, as the hydroxyl ion would react with iodine to form iodide, hypoiodite and finally iodate, hence sodium or potassium carbonates cannot be used. Alkali bicarbonates, however, do not react with iodine.

Standard Solutions. Tenth Normal Sodium Thiosulphate. From the reaction above it is evident that 1 gram molecule of thiosulphate is equivalent to 1 atom iodine = 1 atom hydrogen, hence a tenth normal solution is equal to one-tenth the molecular weight of the salt per liter, e.g., 24.82 grams Na₁8₂O₂·5H₂O; generally a slight excess is taken—25 grams of the crystallized salt. It is advisable to make up 5 to 10 liters of the solution, taking 125 to 250 grams sodium thiosulphate crystals and making up to volume with distilled water, boiled free of carbon dioxide. The solution is allowed to stand a week to ten days, and then standardized against pure, resublimed iodine.

About 0.5 gram of the purified iodine is placed in a weighing bottle containing a known amount of saturated potassium iodide solution (2 to 3 grams of KI free from KIO₂ dissolved in about $\frac{1}{2}$ cc. of H₂O), the increased weight of the bottle, due to the iodine, being noted. The bottle and iodine are placed in a beaker containing about 200 cc. of 1% potassium iodide solution (1 gram KI per 200 cc.), the stopper removed with a glass fork and the iodine titrated with the thiosulphate to be standardized.

Calculation. The weight of the iodine taken, divided by the cc. thiosulphate required, gives the value of 1 cc. of the reagent; this result divided by 0.012692 gives the normality factor.

Note. The thiosulphate solution may be standardized against iodine, which has been liberated from potassium iodide in presence of hydrochloric acid by a known amount of standard potassium bi-iodate, a salt which may be obtained exceedingly pure.

KIO₄·HIO₅+10KI+11HCl=11KCl+6H₂O+6I₂.

A tenth normal solution contains 3.2496 grams of the pure salt per liter. (One cc. of this will liberate 0.012692 gram of iodine from potassium iodide.) The purity of the salt should be established by standardizing against thiosulphate, which has been

freshly tested against pure resublinied iodinc.

About 5 grains of potassium iodide (free from iodate) are dissolved in the least amount of water that is necessary to effect solution, and 10 cc. of dilute hydrochloric acid (1:2) are added, and then 50 cc. of the standard bi-iodate solution. The solution is diluted to about 250 cc. and the liberated iodine titrated with the thiosulphate reagent; 50 cc. will be required if the reagents are exactly tenth normal.

Tenth Normal Arsenite. From the second reaction above it is evident that As₁O₁ is equivalent to 2I₂, e.g., to 4H, hence \(\frac{1}{2}\) the gram molecular weight of arsenious oxide per liter will give a normal solution: 198÷4=49.5.

4.95 grams of pure arsenious oxide is dissolved in a little 20% sodium hydroxide solution, the excess of the alkali is neutralized with dilute sulphuric acid, using phenolphthalein indicator, the solution being just decolorized. Five hundred cc. of distilled water containing about 25 grams of sodium bicarbonate are added. If a pink color develops, this is destroyed with a few drops of weak sulphuric acid. The solution is now made to volume, 1000 cc. The

IODINE 241.

reagent is standardized against a measured amount of pure iodine. The oxide may be dissolved directly in sodium bicarbonate solution.

NOTE. Commercial arsenious oxide is purified by dissolving in hot hydrochloric acid, filtering the hot saturated solution, cooling, decanting off the mother liquor, washing the deposited oxide with water, drying and finally subliming.

Starch Solution. Five grams of soluble starch are dissolved in cold water, the solution poured into 2 liters of hot water and boiled for a few minutes. The reagent is kept in a glass-stoppered bottle.

The addition of a few cc. of 5% NaOH, then heating to boiling and filtering

will preserve the starch.

Decomposition of the lodide by Ferric Salts

The method takes advantage of the following reaction:

$$Fe_2(SO_4)_4 + 2KI = K_2SO_4 + I_2 + 2FeSO_4$$

The procedure enables a separation from bromides, as these are not acted upon by ferric salts.

Procedure. To the iodide in a distillation flask is added an excess of ferrie ammonium alum, the solution acidified with sulphuric acid, then heated to boiling, and the iodine distilled into a solution of potassium iodide. The free iodine in the distillate is titrated with standard thiosulphate, or by arsenious acid in presence of an excess of sodium bicarbonate.

The reagent is added from a burette until the titrated solution becomes a pale yellow color. About 5 cc. of starch solution are now added and the titration continued until the blue color of the starch fades and the solution becames colorless.

One cc. of tenth normal reagent =0.012692 gram iodine, equivalent to 0.012793 gram HI, or 0.016602 gram Kl.

Decomposition with Potassium Iodate 1

The reaction with potassium iodate is as follows:

$$5KI + KIO_3 + 6HCl = 6KCl + 3H_2O + 3I_2$$
.

It is evident that & of the titration for iodine would be equal to the iodine of the iodide, hence 1 cc. of tenth normal thiosulphate is equivalent to 0.012692 \times = 0.01058 gram iodine due to the iodide. The procedure is as follows:

Procedure. A known amount of tenth normal potassium iodate is added to the iodide solution, in sufficient amount to liberate all of the iodine, combined as iodide, and several ee. in excess. Hydrochloric acid and a piece of calcite are added. The mixture is boiled until all of the liberated iodine has been expelled. To the cooled solution 2 or 3 grams of potassium iodide are added and the liberated iodine, corresponding to the excess of iodate in the solution, is titrated with standard thiosulphate. If I cc. of thiosulphate is equal to 1 cc. of the iodate, then the total ce. of the iodate used, minus the cc. thio-

¹ H. Dietz and B. M. Margosches, Chem. Ztg., 2, 1191, 1904. Treadwell and Hall, "Analytical Chemistry," Vol. 2.

sulphate required in the titration gives a difference due to the volume of iodate required to react with the iodide of the sample.

One cc. of N/10 KIO₂ = 0.01058 gram I in KI.

Note. Tenth normal potassium iodate contains 3.5675 grams KIO₄ per 1000 cc.

Decomposition of the Iodide with Nitrous Acid (Fresenius)

Nitrous acid reacts with an iodide as follows:


$$2HNO_2 + 2HI = 2NO + 2II_2O + I_2$$

Since neither hydrochloric nor hydrobromic acids are attacked by nitrous acid, the method is applicable to determining iodine in presence of chlorine and

bromine; hence is useful for determining small amounts of iodine in mineral waters containing comparatively large amounts of the other halogens.

Nitrous Acid. The reagent is prepared by passing the gas into strong sulphurie acid until saturated.

Procedure. The neutral or slightly alkaline solution of the iodide is placed in a glass-stoppered separatory funnel, Fig. 39, and slightly acidified with dilute sulphurie acid. A little freshly distilled colorless earbon disulphide (or chloroform) is added, then 10 drops of nitrous acid reagent. The mixture is well shaken, the disulphide allowed to settle, drawn off from the supernatant solution and saved for analysis. The liquor in the funnel is again extracted with a fresh portion of disulphide and if it becomes discolored it is drawn off and added to the first extract. If the extracted aqueous solution appears yellow, it must be again treated with additional earbon disulphide until all the iodine has been removed (e.g., until additional CS2 is no longer colored when shaken with the solution). The combined extracts are washed with three



reddish-violet carbon disulphide becomes colorless. The sodium thiosulphate used is standardized against a known amount of pure potassium iodide treated in the manner described above.

One ee. N/20 Na₂S₂O₃ = .00635 gram I, 1 cc. N/50 Na₂S₂O₃ = .002538 gram I.



Fro. 39.

Liberation of Iodine by Means of Hydrogen Peroxide and Phosphoric Acid ¹

Principle. Iodine is liberated from an iodide by addition of hydrogen peroxide to the solution acidified with phosphoric acid, the iodine distilled into

potassium iodide and titrated with thiosulpliate.

Procedure. Fifty ec. of the iodide solution are mixed with 5 ec. of pure phosphorie acid and 10 to 20 ec. hydrogen peroxide added, the mixture being placed in a round-bottomed flask, connected with a short condenser, delivering into two absorption vessels containing a 10% solution of potassium iodide. A current of air is drawn through the apparatus, and the contents of the flask gradually heated to boiling. The iodine is absorbed in the potassium iodide solution and titrated as usual with standard sodium thiosulphate. Twenty minutes' heating is generally sufficient.

One ee. $Na_2S_2O_3 = 0.012692$ gram I, or 0.016602 gram KI.

Note. Iodine in urine may be determined by evaporating to 1/10 its volume. After adding an excess of sodium hydroxide, the mixture is taken to dryness and gently ignited. The ash may be used for the iodine determination.

Oxidation of Combined Iodine with Chlorine. (Mohr's Modification of Dupré's Method)²

When a solution of potassium iodide is treated with successive amounts of chlorine water, iodine is liberated, which reacts with an excess of chlorine with formation of chloride of iodine (ICl) and with greater excess the pentachloride (ICl₂) which is changed in presence of water to iodic acid (HIO₂),

Procedure. The weighed iodide compound is brought into a stoppered flask, and chlorine water delivered from a large burette until all yellow color has disappeared. A drop of the inixture brought in contact with a drop of starch solution should produce no blue color. Sodium bicarbonate is now added until the mixture is slightly alkaline, followed by an excess of potassium iodide and 4 to 5 ce. of starch reagent. Standard thiosulphate is now added until the blue color is removed. The excess of chlorine water is thus ascertained. From the value of the chlorine reagent the iodine of the sample may readily be calculated.

The chlorine water is standardized by running 25 to 50 ec. of the reagent into potassium iodide solution (see procedure for bromides, p. 95), and titrating the liberated iodine with standard sodium thiosulphate. The value of the reagent in terms of thiosulphate are thus ascertained and from this the value per ec. in terms of iodine.

OTHER METHODS

Volhard's Method for Determining Iodides

This procedure is very similar to those for determining chlorine or bromine, with the exception that silver iodide formed will occlude both the iodide solu-

¹E. Winterstein and E. Herzfeld, Zeit. Physiol. Chem., **63**, 49-51, 1909. Chem. Zentralbl., (1), 473-474, 1910.

² Sutton, "Volumetric Analysis," 10th Ed.

tion and silver nitrate unless the additions of the silver salt are made in small

portions with vigorous shaking.

Standard silver nitrate is added to the solution in a glass-stoppered flask, shaking vigorously with each addition. As long as the solution appears milky the precipitation is incomplete. When the silver iodide is eoagulated and the supernatant liquid appears colorless, ferric alum solution is added, and the excess of silver nitrate titrated with potassium sulphocyanate until the characteristic reddish end-point is obtained.

The iodine is ealculated from the amount of silver nitrate required. E.g., total AgNO₁ added, minus excess determined by KCNS=ec. AgNO₁ required by the iodine.

Note. The ferric salt oxidizes hydriodic acid with separation of iodine, whereas the silver iodide is not acted upon, hence the indicator is added after all the iodide has combined with silver.

Determination of Iodates

The procedure is the reciprocal of the one for determination of iodide by means of an iodate:

Reaction. $KIO_3+5KI+6HCl=6KCl+3H_2O+3I_2$.

Procedure. The solution containing the iodate is allowed to run into an excess of potassium iodide solution containing hydrochloric acid. The liberated iodine is titrated with sodium thiosulphate as usual.

One cc. N/10 Na₄S₂O₃ = 0.002932 gram HIO₃, or 0.003567 gram KIO₃.

Determination of Periodates

The procedure is the same as that described for iodates, the reaction in this ease, however, being as follows:

$$KIO_4 + 7KI + 8HCl = 8KCl + 4H_1O + 4I_2$$

From the equation it is evident that 1 gram molecule of the iodate is equivalent to 8 atoms of iodine =8 atoms of hydrogen, hence $\frac{1}{6}$ the molecular weight per liter of solution would equal a normal solution. Therefore, 1 ee. of a tenth normal solution would contain 0.019193÷8 =0.002399 gram HIO₄.

One ec. N/10 Na₂S₂O₁ = 0.002399 gram HIO₄, or = 0.002849 gram HIO₄·2H₂O, or = 0.002875 gram KIO₄.

, Determination of Iodates and Periodates in a Mixture of the Two

The procedure depends upon the fact that an iodate does not react with potassium iodide in neutral or slightly alkaline solutions, whereas a periodate undergoes the following reactions:

$$KIO_4+2KI+H_4O=2KOH+KIO_4+I_4$$

Procedure. The sample, dissolved in water, is divided into two equal portions.

A. To one portion a drop of phenolphthalein indicator is added and the

solution made just faintly alkaline by addition of alkali to acid solutions or hydrochloric acid to alkaline solution, as the case may require. Ten cc. of cold saturated solution of sodium bicarbonate are added and an excess of potassium iodide. The liberated iodine is titrated with tenth normal arsenious acid.¹ (Na₂S₁O₂ will not do in this case, as the solution is alkaline.)

One ce. N/10 As₂O₄ = 0.0115 gram KIO₄.

B. To the other portion potassium iodide is added in excess and the solution made distinctly acid. The liberated iodine is titrated with standard sodium thiosulphate. (As₂O₂ will not do.)

Calculation. In the acid solution, B, both iodates and periodates are titrated, whereas in the alkaline solution, A, only the periodates are affected. From the reactions for periodates it is evident that 1 ee. Na₂S₂O₃ = 4 cc. As₂O₃ for the periodate titration, hence

Cc. $Na_2S_2O_4 - ec. As_2O_4 \times 4 = ec.$ thiosulphate due to KIO₄.

The difference, multiplied by 0.003567 = grains KIO, in the sample.

Determination of Iodine in Mineral Waters and Brines

The following procedure is given by W. F. Baughman and W. W. Skinner. Take such a quantity of the brine or water as will contain not more than 0.1 g. iodine as iodide or more than 10 g. total salts. Adjust the volume to 100 ec. to 150 cc. and boil it with a sufficient amount of sodium hydroxide and sodium carbonate to precipitate the ealcium and magnesium. Filter off the precipitate and wash with hot water. Introduce the filtrate into an Erlenmeyer flask, adjust the volume to about 100 cc., neutralize with dilute sulphuric acid, and add 1 ce. of a solution of sodium hydroxide (4 g. per 100 ec.). Heat to boiling, add an excess of potassium permanganate, continue the heating until the precipitate begins to coagulate, and then allow to cool. Add sufficient alcohol to cause the permanganate color to disappear and allow the precipitate to settle on the steam bath. Filter and wash with hot water. After cooling, add one or two grams of potassium iodide, acidify with hydrochloric acid, and titrate with standard thiosulphate. The number of cc. required, divided by 6, represents the number of ec. required by the iodine in the sample.

¹In alkaline solutions the arsenious acid titration must be made, whereas in acid solutions potassium thiosulphate is used.

²Bureau of Chemistry, Dept. Agriculture, Washington, D. C. Ref. Jour. Ind. Eng. Chem., Vol. 11, No. 6, page 563 (June, 1919).

Fe, at.wt. 55.84; sp.gr. 7.85-7.88; m.p. pure 1530°,1 wrought 1600°,2 white pig 1075°,1 gray pig 1275°,1 steel 1375°;1 b.p. 2450°1 C.; oxides FeO. Fe₁O₁, Fe₂O₄.

DETECTION

Ferric Iron. The yellow to red color in rocks, minerals, and soils is generally due to the presence of iron.

Hydrochloric acid solutions of iron as ferrie ehloride are colored yellow.

Potassium or ammonium sulphocyanate produces a red color with solutions containing ferric iron. Nitric acid and chloric acid also produce a red color with potassium or ammonium sulphocyanate. This color, however, is destroyed by heat, which is not the ease with the iron compound. The red color of ferrie iron with the cyanate is destroyed by mercuric chloride and by phosphates, borates, eertain organic acids, and their salts, e.g., aeetic, oxalie, tartaric, eitrie, racemie, malic, succinic, etc.

Potassium ferrocyanide, K.Fe(CN), produces a deep blue color with ferric salts.

Salicylic acid added to the solution of a ferric salt containing no free mineral acid gives a violet color. Useful for detecting iron in alum and similar products.

Ferrous Iron. Potasslum Ferricyanide, K.Fe(CN), gives a blue color with solutions of ferrous salts.

Distinction between Ferrous and Ferric Salts.

KCNS gives red eolor with Fe" and no color with Fe".

K,Fe(CN), gives a blue color with Fe" and a brown or green with Fe".

NH.OH, NaOH or KOH precipitates red, Fe(OH), with Fe" and white,

Fe(OH), with Fe" turning green in presence of air due to oxidation.3

Sodium peroxide produces a reddish-brown precipitate of Fe(OH), with either ferrous or ferrie salt solutions, the former being oxidized to the higher valence by the peroxide. Chromium and aluminum remain in solution, if present in the sample.

ESTIMATION

Iron is so widely diffused in nature that its determination is necessary in practically all complete analyses of ores, rocks, minerals, etc. It is especially important in the evaluation of iron ores for the manufacture of iron and steel. Among the ores of iron the following are more common:

Oxides. Red hematite, Fe₂O₁; brown hematite, 2Fe₂O₁·3H₂O; black magnetite or magnetic iron ore, Fe₂O₄. Ferrie oxide with varying amounts of water

¹Circular 35 (2d Ed.) U. S. Bureau of Standards.

²D. Van Nostrand's Chemical Annual.—Olsen.

³The green salt is a hydrate of Fe₂O₄. The white precipitate can be obtained in absence of air or by using H₂SO₂ to take up oxygen in solution.

Chapter contributed by Wilfred W. Scott.

forms the substances known as hematite, gothite, limonite, yellow ochre, bog iron ore.

Sulphide. Iron pyrites or "fool's gold," FeS, pyrrhotite, FeS.

Carbonates. Spatic iron ore, FeCO₂; combined with clay in elay ironstone with bituminous material as "black band."

Iron is determined in the einders and in iron ore briquettes from burned iron pyrites, by-products of sulphuric acid.

It is found as an impurity in a large number of commercial salts and in the mineral acids.

Preparation and Solution of the Sample

The material should be carefully sampled and quartered down according to the general procedure for sampling. Ores should be ground to pass an 80-mesh sieve. In analysis of metals, both the coarse and fine drillings are taken.

The following facts regarding solubility should be remembered: The element is soluble in hydrochloric acid and in dilute sulphuric acid, forming ferrous salts with liberation of hydrogen. It is insoluble in concentrated, cold sulphuric acid, but is attacked by the hot acid, forming ferric sulphute with liberation of SO₂. Moderately dilute, hot nitric acid forms ferric nitrate and nitrous oxide; the cold acid gives ferrous nitrate and ammonium nitrate or nitrous oxide of hydrogen. Cold, concentrated nitric acid forms "passive iron," which remains insoluble in the acid. The oxides of iron are readily soluble in hydrochloric acid, if not too strongly ignited, but upon strong ignition the higher oxides dissolve with extreme difficulty. They are readily soluble, however, by fusion with acid potassium sulphate followed by an acid extraction. Silicates are best disselved by hot hydrochloric acid containing a few drops of hydrofluoric acid or by fusion with sodium and potassium carbonates, followed by hot hydrochloric acid.

Soluble Iron Salts. Water solutions are acidified with HCl or H₂SO₄, so as to contain about 3% of free acid.

Ores. The samples should be pulverized to pass an 80- to 100-mesh sieve.

Sulphides, Ores Containing Organic Matter. One- to 5-gram samples should be roasted in a porcelain crucible over a Bunsen flame for about half an hour, until oxidized. The oxide is now dissolved as directed in the following procedure.

Oxides, Including Red and Brown Hematites, Magnetic Iron Ore, Spatose Iron Ore, Roasted Pyrites, and Iron Ore Briquettes. One to 5 grains of the ore, placed in a 400-cc. beaker, is dissolved by adding twenty times its weight of strong hydrochloric acid with a few drops of $5\frac{C}{C}$ stannous chloride solution. Addition of 4 or 5 drops of HF is advantageous if small amounts of siliea are present. The solution is covered with a watch-glass and heated to 80 or 90° C. until solution is complete. Addition of more stannous chloride may be necessary, as this greatly assists solution. An excess sufficient to completely decolorize the solution necessitates reoxidation with hydrogen peroxide, hence should be avoided. If a colored residue remains, it should be filtered off, ignited and fused with a mixture of Na₂CO₄ and K₂CO₄ in a platinum crucible. The fusion dissolved in dilute HCl is added to the main filtrate.

Note. The ore placed in a porcelain boat in a red-hot combustion tube may be reduced with hydrogen (taking precaution first to sweep out oxygen with CO₂) and after cooling in an atmosphere of hydrogen the reduced iron may be dissolved in acid and titrated.

Iron Silicates. One to 5 grams of the material, placed in a deep platinum crucible, is treated with ten times its weight of 60% HF and 3 to 4 drops of cone. H_2SO_4 . The mixture is ovaporated to near dryness on the steam bath and taken up with dilute sulphuric acid or hydrochloric acid. The latter acid is the best solvent for iron.

Fusion with Potassium Bisulphate. The sample is mixed with ten times its weight of the powdered bisulphate and 2-3 cc. of concentrated sulphuric acid added. A porcelain or silica dish will do for this fusion. The fusion should be made over a moderate flame and cooled as soon as the molten liquid becomes clear. Complete expulsion of SO₁ should be avoided. It may be necessary to cool and add more cone, sulphuric acid to effect solution. Iron and alumina completely dissolve, but silica remains undissolved. The melt is best cooled by pouring it on a large platinum lid.

Fusion with Carbonates of Sodium and Potassium. The residues insoluble in hydrochloric acid are fused with 5 parts by weight of the fusion mixture (Na₂CO₃+K₂CO₂) in a platinum crucible. The Méker blast will be necessary. When the effervescence has ceased and the melt has become clear, the crucible is removed from the flame, a platinum wire inserted and the melt cooled. Upon gently reheating, the fuse may be readily removed by the wire in a convenient form for solution in dilute hydrochloric acid.

The bisulphate fusion is recommended for fusion of residues high in iron and alumina. It is an excellent solvent for ignited oxides of these elements. The carbonate fusions are adapted to residues containing silica.

SEPARATIONS

General Procedure. In the usual course of analysis silica is removed by evaporating the acid solution to dryness, taking up with water and filtering. Mercury, lead, bismuth, copper, cadmium, arsenie, antimony, tin, molybdenum and other elements precipitated from an acid solution as sulphides are removed as such by filtration and iron, after oxidation to the ferric state, is precipitated as Fe(OH)₂. In the majority of cases it may now be determined by titration.

Ether Method for Removing Iron from a Solution. Ferric chloride dissolved in HCl (sp.gr. 1.1) is more soluble in ether than in this acid. Advantage is taken of this fact when it is desired to remove a greater portion of the iron in determining copper, nickel, cobalt, chromium, vanadium and sulphur (as H₂SO₄) in steel. The hydrochloric acid solution of iron, etc., is evaporated to a syrupy consistency and then taken up with HCl (sp.gr. 1.1) and transferred by means of more of the acid to a separatory funnel. The cold acid solution is now extracted several times by shaking with ether, each time allowing the ether carrying the iron to separate before drawing off the lower layer for reextraction. Three extractions are generally sufficient for removing the iron.

Since alkali salts cause trouble by crystallizing and clogging the borings of the stopcock, the use of alkalies should be avoided when this method of separation is used. The iron may be extracted from the ether by shaking this with water and drawing off the lower water layer. Since heat is generated by the mixing of ether and the ferric chloride-hydrochloric acid solution, cooling the mixture under the tap during inixing may be necessary. This heating is reduced by using a mixture of ether and hydrochloric acid. Strong hydrochloric acid (sp. gr. 1.19) is saturated with ether, an excess of ether separating out as an upper layer. 100 cc. of the acid will absorb 150 cc. ether. (Dilute hydrochloric acid (sp. gr. 1.1) absorbs only 30 cc. ether.)

GRAVIMETRIC METHODS FOR THE DETERMINATION OF IRON

The gravimetric determination of iron may be made from solutions practically free from other metals. A number of elements such as phosphorus, arsenic, molybdenum, tungsten, and vanadium, in neutral or slightly alkaline solutions, form fairly stable compounds with iron, whereas others, such as lead, copper, nickel, cobalt, sodium, and potassium may be occluded in the ferric hydrate precipitate and are removed only with considerable difficulty. Aluminum, chromium, and several of the rare carths are precipitated with iron, if present. These facts taken into consideration, the volumetric methods are generally preferred as being more rapid and trustworthy.

Determination of Iron as Fe₂O₃

Iron is precipitated as the hydroxide and ignited to the oxide, Fe₂O₂, in which form it is weighed.

Reactions. $FeCl_i+3NH_4OH = Fe(OH)_i+3NH_4Cl_i$ $2Fe(OH)_i+heat = Fe_iO_i+3H_2O_i$

Procedure. One-gram sample or a larger amount of material if the iron content is low, is brought into solution with hydrochloric acid, aqua regia, or by fusion with potassium carbonate or potassium acid sulphate, as the case may require. Silica is filtered off and the acid solution treated with H₂S if members of that group are present. The filtrate is boiled to expel H₂S and the iron oxidized to ferric condition by boiling with 5 cc. concentrated nitric acid.

Absence of Aluminum and Chromium. About 1 gram of ammonium chloride salt or its equivalent in solution is added, the volume made to about 200 cc. and ammonium hydroxide added in slight excess to precipitate Fe(OH). The solution is boiled for about five minutes, then filtered through an ashless filter.

If Aluminum and Chromium are Present. In place of animonium hydroxide powdered sodium peroxide is added in small portions until the precipitate first formed clears, the solution being cold and nearly neutral. It is diluted to about 300 ee. and boiled ten to fifteen minutes to precipitate the iron. Aluminum and chromium are in solution. (Mn will precipitate with Fe, if present.) The precipitate is filtered onto a rapid filter and washed with hot water.

Second Precipitation. In either case dissolve the precipitate with the least amount of hot dilute hydrochloric acid and wash the paper free of iron. Add a few ec. of 10% ammonium chloride solution and reprecipitate the hydroxide of iron by adding an excess of ammonium hydroxide, the volume of the solution being about 200 cc. Washing the precipitate by decantation is advisable. Three such washings, 100-cc. portions, followed by two or three on the filter paper, will remove all impurities.

Ignition. The precipitate is ignited wet over a low flame, gradually increasing the heat. Blasting is not recommended, as the magnetic oxide of iron, Fe₁O₄, will form with high heating. The oxide heated gently appears a reddish-brown. Higher heat gives the black oxide, Fe₁O₄. Twenty minutes' ignition, at red heat, is sufficient.

The crucible, cooled in a desiccator, is weighed and Fe₂O₂ obtained.

Factors. $Fe_2O_1 \times 0.6994 = Fe$. $Fe_2O_1 \times 0.8998 = FeO$.

Precipitation of Iron with "Cupferron," Amino nitrosophenylhydroxylamine 1

By this procedure iron may be precipitated directly in acid solution in presence of a number of elements. Mercury, lead, bismuth, tin, and silver may be partially precipitated. Copper precipitates with iron, but may be easily removed by dissolving it out with amutonia. The method is especially adapted for separation of iron from aluminum, nickel, cobalt, chronium, cadmium, and zinc.

Procedure. The solution containing the iron is made up to 100 cc. and 20 cc. of concentrated hydrochloric acid added. To this cool solution (room temperature) Baudisch's reagent, cupferron, is slowly added with constant stirring, until no further precipitation of iron takes place, and crystals of the reagent appear. The iron precipitate is a reddish-brown. Copper gives a grayish-white flocculent compound. An excess of the reagent equal to one-fifth of the volume of the solution is now added, the precipitate allowed to settle for about fifteen minutes, then poured into a filter paper and washed, first with 2N. HCl, followed by water, then with ammonia and finally with water. The drained precipitate is slowly ignited in a porcelain or platinum crucible and the residue weighed as Fe_2O_2

$Fe_2O_1 \times 0.6994 = Fe$.

Notes. Baudisch's reagent, amino nitrosophenyl-hydroxylamine (cupferron), is made by dissolving 6 grams of the salt in water and diluting to 100 cc. The reagent keeps for a week if protected from the light. It decomposes in the light, forming nitrobenzine. Turbid solutions should be filtered.

The precipitates of copper or iron are but slowly attacked by twice normal hydrochloric acid in the cold, but decomposed by hot acid, hence the solution and reagent

should be cold.

Cold, dilute potassium carbonate solution, or ammonium hydroxide, have no action on the iron precipitate; the copper compound dissolves readily in ammonia. Alkaline hydroxide causes rapid decomposition.

The precipitation is best made in comparatively strong acid solutions (HCl, H2SO4,

or acetic acid).

¹ O. Baudisch, Chem. Ztg., 33, 1298, 1905. Ibid., 35, 913, 1911. O. Baudisch and V. L. King, Jour. Ind. Eng. Chem., 3, 627, 1911.

VOLUMETRIC DETERMINATION OF IRON IN ORES AND METALLURGICAL PRODUCTS

General Considerations. Two general procedures are commonly employed in the determination of iron.

A. Oxidation of ferrous to ferric condition by standard oxidizing agents.

B. Reduction of ferric iron to ferrous condition.

The sample is dissolved as directed under Preparation and Solution of the Sample.

Determination of Iron by Oxidation Methods

Some modification of either the dichromate or permanganate methods is commonly employed in the determination of iron by oxidation. To accomplish this quantitatively, the iron must be reduced to its ferrous condition. This may be accomplished in the following ways:

1. Reduction by Hydrogen Sulphide. During the course of a complete analysis of an ore, H₂S is passed into the acid solution to precipitate the members of that group (Hg, Ph, Bi, Cu, Cd, As, Sh, Sn, Pt, Au, Se, etc.). The filtrate contains iron in the reduced condition suitable for titration with either dichromate or permanganate, the excess of H₂S having been boiled off. If the expulsion of H₂S is conducted in an Erlenmeyer flask there is little chance for reoxidation of the iron during the boiling. Reduction by H₂S is very effective and is frequently advisable. This is the case when titanium is present, since this is not reduced by H₂S, but by methods given below. Arsenic, antimony, copper, and platinum, which, if present would interfere, are removed by this treatment.

Reaction. $2 \text{FeCl}_1 + \text{H}_2 \text{S} = 2 \text{FeCl}_2 + 2 \text{HCl} + \text{S}$.

2. Reduction with Stannous Chloride. SnCl₂ solution acts readily in a hydrochloric acid solution of the ore; the reduction of the iron is easily noted by the disappearance of the yellow color. The excess of the reagent is oxidized to SnCl₄ by addition of HgCl₂.

Reactions. 1. $2 \text{FeCl}_2 + \text{SnCl}_2 = 2 \text{FeCl}_2 + \text{SnCl}_4$.

2. Excess SnCl₂+2HgCl₂=SnCl₄+2HgCl precipitated.

An excess of SnCl₂ is advisable, but a large excess is to be avoided, as a secondary reaction would take place, as follows: 2SnCl₂+2HgCl₂=2SnCl₄+2Hg. This reaction is indicated by the darkening of the solution upon the addition of HgCl₂. Precipitation of metallic mercury would vitiate results. The solution should be cooled before addition of mercuric chloride. About 15-20 cc. of saturated mercuric chloride, HgCl₂, solution should be sufficient.

3. Reduction by a Metal such as Test Lead, Zinc, Magnesium, Cadmium, or Aluminum, in Presence of Either Hydrochloric Acid or Sulphuric Acid. The former acid is preferred with the dichromate titration, and the latter with the permanganate. Two methods of metallic reduction are in common use—reduction by means of test lead, and reduction with amalgamated zinc by means of the Jones reductor.

(a) Reduction with Test Lead. By this method copper is precipitated from solution and small amounts of arsenic and antimony expelled. Sufficient test lead is added to the acid ferric solution to completely cover the bottom of the beaker. The solution is covered and boiled vigorously until the yellow color has completely disappeared, and the solution is colorless. The reduced iron solution, cooled, is decanted into a 600-cc. beaker, the remaining iron washed out from the lead mat by several decantations with water; two or three 50-cc. portions of water should be sufficient; the washings are added to the first portion. If the solution becomes slightly colored, a few drops of stannous chloride, SnCl₂, solution are added, followed by 10 cc. mercuric chloride, HgCl₂, solution. The sample is now ready for titration.

(b) Reduction with Zinc, Using the Jones Reductor. The acid solution of iron, preferably sulphuric acid, is passed through a column of amalgamated zinc. The hydrogen evolved in presence of the zinc reduces the ferric iron to ferrous condition. The procedure is described in detail under the Permanganate Method for Determination of Iron, page 254. Titanium if present will also be reduced.

4. Reduction with Sulphurous Acld, Sodium Sulphite or Metablsulphite. SO: gas is passed into a neutral solution of iron, since iron is not reduced readily in an acid solution by this method. The excess SO: is expelled by acidifying the solution and boiling.

5. Reduction with potasslum lodlde, the liberated iodine being expelled by heat.

In the solution of the ore with stannous chloride and hydrochloric acid, if an excess of the former has been accidentally added, it will be necessary to oxidize the iron before reduction. This may be accomplished by addition of hydrogen peroxide until the yellow color of ferric chloride appears (or by addition of $KMnO_4$ solution), the excess H_2O_2 may be removed by boiling. The iron may now be reduced by one of the above methods.

¹ Amalgamated zinc is best prepared by dissolving 5 grams of mercury in 25 cc. of concentrated nitric acid with an equal volume of water, 250 cc. of water are added and the solution poured into 500 grams of shot zinc, 20-mesh. When thoroughly amalgamated the solution is poured off, and the zinc dried.

Volumetric Determination of Iron by Oxidation with Potassium Dichromate

Principle. This method depends upon the quantitative oxidation of ferrous salts in cold acid solution (HCl or II₂SO₄) to ferric condition by potassium dichromate, the following reaction taking place:

$$6FeCl_2+K_2Cr_2O_7+14HCl=6FeCl_4+2CrCl_2+2KCl+7H_7O.$$

Potassium ferricyanide is used as an outside indicator. This reagent produces a blue compound with ferrous salts and a yellowish-brown with ferric. The chromic salt formed by the reaction with iron colors the solution green.

Reagents Required. Standard Potassium Dichromate. When oxygen reacts with ferrous salts, the following reaction takes place:

$$6FeCl_2+6HCl+3O=6FeCl_1+3H_2O$$
.

Comparing this reaction with that of dichromate, it is evident that a normal solution of dichromate contains one-sixth of the molecular weight of K₂Cr₃O₇ per liter, namely, 49.033 grams. For general use it is convenient to have two strengths of this solution, N/5 for ores high in iron and N/10 for products containing smaller amounts.

Standardization. For N/5 solution 9.807 grams of the recrystallized dehydrated salt are dissolved and made up to one liter; N/10 potassium dichromate contains 4.903 grams of the pure salt per liter. It is advisable to allow the solution to stand a few hours before standardization. The Sibley iron ore furnished by the U. S. Bureau of Standards, Washington, D. C., is recommended as the ultimate standard. Other ores uniform in iron may be standardized against the Sibley ore and used as standards. For accurate work it is desirable to use a chamber burette with graduations from 75 to 90 cc. in tenths and from 90 to 100 in twentieths of a cc. A titration of 90 to 100 cc. of the dichromate would require 0.9 to 1.1 gram of iron for a fifth normal solution and half this amount for a tenth normal solution of dichromate. The ore is best dissolved in strong HCl, adding a few drops of stannous chloride solution and heating just below boiling. In case of an ore or iron ore briquette, containing silica in an appreciable amount, a carbonate fusion of the residue may be necessary. Reduction and titration of the ore is done exactly as prescribed later.

The equivalent iron in the ore divided by the cc. titration required for complete oxidation gives the value in terms of grams per cc., e.g., 1.4 gram of ore containing 69.2% Fe required a titration of 95 cc. K₂Cr₂O₇ solution, then,

1 ec. =
$$\frac{(69.2 \times 1.4)}{100} \div 95 = 0.0102$$
 gram Fe.

Stannous Chloride. Sixty grams of the crystallized salt dissolved in 600 cc. of strong HCl and made up to one liter. The solution should be kept well stoppered.

Mercuric Chloride. Saturated solution of HgCl₂ (60 to 100 grams per liter). Potassium Ferricyanide, K₂Fe(CN)₈. The salt should be free of ferrocyanide,

as this produces a blue color with ferrie salts, which would destroy the endpoint. It is advisable to wash off the salt before using. A crystal the size of a pinhead dissolved in 50 cc. of water is sufficient for a series of determinations. The solution should be made up fresh for each set of determinations.

Apparatus. Chamber burette. This should read from 75 to 90 ce. in tenths and from 90 to 100 cc. in twentieths of a cc.

Test Plate. The usual porcelain test-plate with depressions may be replaced by a very simple and efficient test-sheet made by dipping a white sheet of paper in paraffin. The indicator does not eling to this surface, the drops assuming a spherical form, which renders the detection of the end-point more delicate.

Procedure. Iron Ores. The amount of sample taken should be such that the actual iron present would weigh between 0.9 to 1.1 grain. This weight can be estimated by dividing 95 by the approximate percentage of iron present. e.g., for 50% Fe ore take \$6 = 1.9 gram; 95% iron material would require 1 gram, whereas 20% Fe ore would require 4.75 grams.

For samples containing less than 20% Fe it is advisable to use N/10 K₂Cr₂O₇ solution.

The sample should be finely ground (80-mesh).

Solution. The hydrochloric acid method for solution of the oxidized ore with subsequent carbonate fusion of the residue is recommended as being suitable for iron ores, briquettes, and materials high in iron.

Reduction. H₂S reduction is recommended in ores containing arsenie or titanium. SuCl₂ in very slight excess, followed by mercuric chloride, HgCl₂, gives excellent results in absence of other reducible salts of elements, Cu, As, etc.

Test Lead. The easy manipulation and efficiency of this method of reduction makes it applicable for a large variety of conditions. The acid solution preferably, HCl, is diluted to about 150 to 200 cc., containing 15 to 20 cc. concentrated hydrochloric acid (sp.gr. 1.19). Sufficient test lead is added to cover the bottom of a No. 4 beaker. The solution covered is boiled vigorously until it becomes colorless. Copper, if present, is precipitated as metallic copper, and small amounts of arsenie and antimony eliminated from the solution during the reduction of the iron. The ecoled solution is poured into a 600-ee, beaker and the mat of lead remaining in the No. 4 beaker washed free of iron, two or three 50-cc. washings being sufficient. The main solution and washings are combined for titration. If the solution is slightly colored, due to reoxidation of iron, a few drops of stannous chloride solution are added to reduce it, followed by an excess of HgCl₂ solution, 20 to 25 ec., and allowed to stand five minutes.

The standard potassium dichromate is run into the solution to within 5 to 10 cc. of the end-point, this having been ascertained on a portion of the sample. The dichromate is run in slowly near the end-reaction, and finally drop by drop until a drop of the solution mixed with a drop of potassium ferrieyanide solution produces no blue color during thirty seconds. A paraffined surface is excellent for this test.

Co. $K_2Cr_2O_7$ inultiplied by value per ec. = Fe present in sample. $\% = \frac{\text{Fe} \times 100}{\text{wt. taken}}$

Norms. If SnCl₂ solution has been used for reduction of the iron, it is necessary to add the HgCl, rapidly to a cold solution, as slow addition to a warm solution is apt to precipitate metallic mercury.

In case an excess of dichromate has been added in the titration, as often occurs,

back titration may be made with ferrous ammonium sulphate (NH4), SO4. FeSO4. 6H2O.

N/10 solution of this reagent may be prepared by dissolving 9.81 grams of the clear crystals in about 100 cc. of water, adding 5 cc. of concentrated H₂SO₄ and making to 250 cc. The solution should be standardized against the dichromate solution to get the equivalent values, by running the dichromate directly into the ferrous solution.

The ferricyanide indicator should be made up fresh each time it is required.

Large amounts of manganese in the iron solution titrated cause a brown coloration, which masks the end-point. Nickel and cobalt, present in large amounts are objectionable for the same reason. This interference may be overcone by using very dilute acid solutions of ferricyanide indicator, so that the insoluble ferricyanide of these metals will not form.

Dichromate Method for Iron with Diphenylamine Indicator

The disadvantage of the dichromate method in requiring an outside indicator (potassium ferricyanide on a spot plate) is overcome by the procedure outlined by J. Knop (The Journal of the American Chemical Society, 46, 263 (Feb., 1924)) in which diphenylamine is used as an internal indicator, the end point being a violet blue or blue-black.

Reagents

0.1 N Potassium Dichromate solution.

Sulphuric-Phosphoric Acid Mixture. 150 cc. sulphuric acid (d. 1.84), 150 cc. phosphoric acid (d. 1.7), diluted to 1000 cc., 15 cc. used.

Diphenylamine solution. 1 g. diphenylamine dissolved in 100 cc. of strong sulphuric acid. 3 drops used as indicator. (A color change to brown does not impair the efficiency of the indicator.)

Procedure for Ores

Hulf to 1 gram of the ore is digested with 20 ec. of strong hydrochloric acid at 70-80° C., the solution diluted with an equal volume of water and filtered. The insoluble residue is fused with sodium carbonate in a platinum crucible, the melt dissolved in dilute hydrochloric acid, the iron precipitated with ammonium hydroxide and filtered off. The ferric hydroxide on the filter is dissolved with a few cc. of dilute HCl and the solution added to the main solution containing the iron.

The iron is now reduced by addition of stannous chloride solution (60 g. SnCl₂ in 600 cc. HCl and 400 cc. H₂O) added cautiously until the color of iron is no longer evident (other reducible elements must be absent, i.e., Cn, As, etc.), the excess of stannous chloride is overcome with mercuric chloride solution (saturated solution) as usual.

15 cc. of sulphuric-phosphoric acid mixture are added and 3 drops of diphenylamine indicator, the solution is diluted to 150-200 cc. and titrated with 0.1 N potassium dichromate solution.

Near the end the green color of the solution deepens to a blue-green or in presence of a large amount of iron to a grayish blue. The dichromate is now added dropwise until the color changes to an intense violet blue.

1 cc. 0.1 N $K_2Cr_2O_7 = 0.0056$ g. Fe.

Notes. The method has the advantage of having no fading end point as is obtained in the permanganate titrations in presence of mercurous chloride. The method permits back titration with standard ferrous solution. Organic substances do not interfere as they do in permanganate titrations. Zinc, aluminum, manganese, nickel, cobalt and chromium do not interfere. Copper present in quantities less than 1 mg. does not interfere, in larger quantities it lowers results as it assists oxidation of fron by air. Trivalent arsenic raises results as it is oxidized by dichromate to pentavalent form.

¹ The residue may be fused with KHSO₄ in glass in place of Pt.

Potassium Permanganate Method for Determination of Iron

Introduction. The method depends upon the quantitative oxidation of ferrous salts to the ferric condition when potassium permanganate is added to their cold solution, the following reaction taking place:

$$10 \text{FeSO}_4 + 2 \text{KMnO}_4 + 8 \text{H}_2 \text{SO}_4 = 5 \text{Fe}_2 (\text{SO}_4)_2 + \text{K}_2 \text{SO}_4 + 2 \text{MnSO}_4 + 8 \text{H}_2 \text{O}_5$$

Hydrochloric acid in presence of iron salts has a secondary reaction upon the permanganate, e.g.,

$$2KMnO_4+16HCl=2KCl+2MnCl_2+8H_2O+10Cl$$
.

This reaction may be prevented by addition of large amounts of zinc or manganous sulphates together with an excess of phospnoric acid or by large dilution. See note on page 257. The solution is diluted and reduced with zinc and titrated as directed.

The reduction of ferric sulphate is best accomplished by passing the solution through a column of amalgamated zinc in the Jones reductor. In presence of titanium, reduction is accomplished by H₂S in a hydrochloric acid solution of the iron.

Since potassium permanganate enters into reaction with acid solutions of antimony, tin, platinum, copper and mercury, when present in their lower state of oxidation, (also with manganese in neutral solutions) and with SO₂, H₂S, N₂O, ferrocyanides and with most soluble organic bodies, these must be absent from the iron solution titrated.

Potassium permanganate produces an intense pink color in solution, so that it acts as its own indicator.

Solutions Required. Standard Permanganate Solutions. As in case of potassium dichromate, it is convenient to have two standard solutions, N/5 and N/10.

From the reaction given above it is evident that 2 KMnO₄ are equivalent to 5 oxygens, e.g., 2KMnO₄=K₂O+2MnO+5O, hence a normal solution would contain one-fifth of the molecular weight of KMnO₄=31.6 grams of the pure salt.

Since commercial potassium permanganate is scldom pure, it is necessary to determine its exact value by standardization. This is commonly accomplished by any of the following methods:

- (a) By a standard electrolytic iron solution.
- (b) By ferrous salt solution, e.g., (NH₄)₂SO₄·FeSO₄·6H₂O.
- (c) By oxalic acid or an oxalate.

Reaction. $2KMnO_4+5Na_2C_2O_4+8H_2SO_4$ = $K_2SO_4+2MnSO_4+5Na_2SO_4+10CO_2+8H_2O_3$

Standardization of KMnO₄ against sodium oxalate is recommended as the most accurate procedure.

To standardize 0.2 g. of pure sodium oxalate, equivalent to $0.2 \pm .0067 = 29.9$ cc. 0.1 N solution (or if preferred 0.67 g. ≈ 100 cc. 0.1 N solution), is dissolved in 100 cc. hot water and 5-10 cc. H_2SO_4 (1.84) and titrated with the permanganate solution until a faint pink color, that persists, is obtained. The oxalate equivalent in cc. divided by cc. KMnO₄ required=normality of KMnO₄, in terms of N/10 solution.

Procedure for the Determination of Iron by the Jones Reductor

Preparation of Sample. Such an amount of the sample is taken that the iron content is between two- and three-tenths of a gram (0.2 to 0.3 gram). If hydrochloric acid has been required to effect solution, or hydrochloric acid and nitric acid (25 cc.: 1 cc.), as in case of iron and steel, 4 to 5 cc. conc. sulphuric are added, and the solution evaporated to small bulk on the steam bath and to SO₁ fumes to remove hydrochloric acid. The iron is taken up with about 50 cc. dilute sulphuric acid, 1:4, heating if necessary, and filtering if an insoluble residue remains.

Preparation of the Reductor. Cleaning out the apparatus. Scc Fig. 40. The stop-cock of the reductor is closed, a heavy-walled flask or bottle is put into




Fig. 40.—Jones Reductor.

position at the bottom, and 50 cc. of dilute sulphuric acid poured into the funnel. The cock is opened and the acid allowed to flow slowly through the zinc in the tube, applying a gentle suction. Before the acid has drained out of the funnel, 50 cc. of water are added, followed by 50 cc. more of dilute sulphuric acid and 50 cc. of water in turn. The stop-cock is turned off before the water has drained completely from the finnel so that the zinc is always covered by a solution of acid or water.

Determination of the Blank. Fifty cc. of dilute sulphuric acid, 1:4, are passed through the reductor, followed by 250 cc. of distilled water, according to the directions given above. The acid solution in the flask is then titrated with N/10 KMmO₄ solution. If more than 3 or 4 drops of the permanganate are required, the operation must be repeated until the blank titration does not exceed this amount. The final blank obtained

should be deducted from the regular determinations for iron. The end-point of the titration is a faint pink, persisting for one minute.

Reduction and Titration of the Iron Solution. The sample is diluted to 200 cc., and, when cold, is run into the funnel, the stop-cock opened and the solution drawn slowly through the column of zine into the flask, about four minutes being required for 200 cc. of solution. Before the funnel has completely drained, rinsings of the vessel which contained the sample are added; two 50-cc. portions are sufficient, followed by about 50 cc. of water. The stop-cock is closed before the solutions have completely drained from the funnel.

Thration. The flask is removed and tenth normal solution of permanganate added until a faint pink color, persisting one minute, is obtained. The blank is deducted from the cc. reading of the burette.

One cc. N/10 KMnO₄=.005584 gram Fe; or .007984 gram Fe₂O₂.

NOTE. Diphenylamine indicator may be used as in case of dichromate titrations of iron. See page 255. Titrations may be made in presence of considerable HCl by this means.

257a IRON

OPTIONAL PERMANGANATE METHOD FOR IRON IN ORES

1. Solution of the Sample. 0.5 gram of ore. 8-oz. flask. With oxidized ores add 10-15 ec. of HCl and warm gently until the iron oxide is dissolved; then if sulphides are also present add 5 cc. of HNO₃ to decompose them also. With straight sulphides use 10 ee. of HCl and 5 cc. of HNO₃. When decomposition is complete add 5 cc. of H₂SO₄ and boil over a free flame nearly to dryness.

Refractory Ores. Certain silicates, oxides of iron, furnace slags, etc., do not decompose with acid treatment. Decomposition may be accomplished by fusion methods followed by solution of the fused mass with water and hydroehloric acid. Fusions with Na₂CO₃ and K₂CO₃ are made in a nickel or platinum erucible and arc recommended for materials high in siliea. Fusions with an acid flux, K₂SO₄ (+5 cc. H₂SO₄ d. 1.84) or KHSO₄ are recommended for oxides. These latter fusions are conveniently carried out in pyrex flasks held by a heavy wire clamp. About 10-15 grams of the solid flux is added to the ore in the flask and the fusion completed by heating until the mix becomes transparent. Oxides which do not readily decompose may be brought into solution, frequently, by adding a little piece of filter paper to the molten mass in the flask. The earbon thus furnished reduces the oxides, effecting decomposition. If decomposition is incomplete, the water and acid extraction is made, the soluble constituents deeanted off and the residue again fused with more KHSO₄ and filter paper. It may be necessary to follow KHSO₄ fusion by the Na₂CO₃ fusion, on the insoluble residue remaining from the acid extraction of the KHSO4 mass.

- 2. Reduction. After cooling, add 30 ec. water, 10 ec. HCl and 6 grams of 20 mesh granulated zine. Not necessary to get salts into solution. Now add 3 ec. of a 4% copper sulphate solution. Allow to stand until the action has become feeble.
- 3. Add 50 cc. of eold water and then 10 cc. of strong H₂SO₄ and allow to stand until the zine is nearly all dissolved.
- 4. Filtration from Insoluble Gangue and Excess Zinc. Prepare a filter by placing a rather thick wad of absorbent cotton in a funnel and wetting it into place. Place a battery jar, or a liter beaker containing about an inch of cold water, under the funnel. Have the beaker marked at the 700 ec. point.
- 5. When the zine in the flask has nearly all dissolved, filter the liquid through the absorbent cotton and wash out the flask at least 10 times with cold water, pouring through the filter. Use the wash bottle reversed to save time, and use enough water for each wash to completely cover the absorbent cotton. Allow to drain between washes. Continue the washing until the filtrate reaches the 700 ce. mark on the beaker.
- 6. Titration of the Sample. Titrate at once with standard permanganate to a very faint pink tinge and take reading.
- 7. A blank should previously be run on the zinc to determine any correction (usually due to a little iron) necessary. Deduct this correction from the above reading.
 - 8. Multiply the cc. of permanganate used by the factor for iron.
- 9. Standardization of Permanganate. See procedure on the following page.

IRON 257b

Diphenylamine Indicator in Permanganate Titrations of Iron. As in case of titrations of iron with potassium diehromate, diphenylamine may be used in potassium permanganate titrations. The advantage of the indicator is in the fact that titrations may be made in presence of considerable hydrochloric acid and in the presence of tin and mercury salts without a fading endpoint, obtained, when permanganate is used alone. The blue color is more intense than the pink of potassium permanganate.

Procedure

Decomposition and Reduction of Sample. The procedure given on page 315 applies also to this method.

Titration. About 15 cc. of phosphoric-sulphuric acid mixture are added and the solution is diluted to about 100 cc. 0.2 cc. (4 drops) of diphenylaminc indicator are added and the titration now made with the standard potassium permanganate solution. The color becomes green, deepening to a blue-green or grayish blue. The reagent is now added "dropwise" until an intense violet blue or dark blue color is obtained.

1 cc. 0.1 N KMnO₄ 0.005584 g. Fe.

Notes. If 0.5584 gram of sample is taken then 1 cc. of 0.1 N potassium permanganate is equivalent to one per cent of iron.

The phosphoric-sulphuric acid mixture prevents the yellow color of iron from producing a green with the blue end-point. A larger amount of indicator than is recommended should not be used, as this necessitates a blank being deducted for the action of the oxidizing agent on the indicator.

Standardization of Potassium Permanganate-Oxalate Method. Weigh 0.2 to 0.3 gram of pure sodium oxalate, place in a beaker and add 200 cc. of water and about 5 cc. strong sulphuric acid. Heat to boiling and titrate with the potassium permanganate solution. The reaction starts slowly, but with the progress of the titration the action becomes vigorous. Towards the end of the reaction the pink color fades less rapidly and finally a permanent pink color is obtained with one drop of the reagent.

Calculation of Normality. Since 67 grams of sodium oxalate per 1000 cc. of solution is a normal solution the cc. equivalent of the amount taken is obtained by dividing by 0.067. This value divided by the titration of the oxalate with the reagent being standardized will give the normality of the reagent.

Example. Suppose 0.268 gram of sodium oxalate required a titration of 50 cc. of the permanganate solution. Since 67 g. is equivalent to 1000 cc. N solution of sodium oxalate, then 0.268 is equivalent to

 0.268×1000 divided by 67 = 4 cc. N sol. 4 divided by 50 = 0.08 N.

¹ Wilfred W. Scott, Jour. Am. Chem. Soc., 46, 1396, (June, 1924).

Determination of Ferric Iron by Titration with Titanous Salt Solution

Method of Knecht and Hibbert¹ (modified by Thornton and Chapman²)

Introduction. The iron solution, which may contain hydrochloric acid. sulphuric acid or hydrofluoric acid (provided boric acid be added in considerable

excess) - but not nitric acid, is titrated while cold (15-20° C.) with a standard solution of titanous sulphate,* using ammonium thiocyanate as indicator, until the red color of the ferric thiocyanate just dis-

Any substance that might reduce the ferric iron or oxidize the titanous salt should, of course, bc absent. Many forms of organic matter, however, do not interfere. Copper is quantitatively precipitated as cuprous thiocyanate, and certain other metals of the hydrogen sulphide group arc not without Platinum salts, chromic effect. acid (not chromic salts) and vanadic acid exert an oxidizing action on the titanium compound.

Reagents. Titanous Sulphate Solution (1/10 Normal). The titanium solution is prepared by mixing 100 cc. of a 20% solution of titanous sulphate with 80 cc. of sulphuric acid (1:1) and making up the volume to 1 liter with cold

water.

Ammonium Thiyanate Solution. One hundred grams of the crystals are dissolved in water, filtered and the clear solution diluted to 1 liter.




Fig. 40a.—Apparatus for Storing and Using Titanous Salt.

Ferric Ammonium Sulphate Solution.4 Forty eight grams of ferric alum crystals are dissolved in water, the solution acidified with 50 cc. of concentrated sulphuric acid and after filtration the volume made up to 1 liter.

¹ E. Knecht and E. Hibbert, "New Reduction Methods in Volumetric Analysis." 1918, pp. 12, 49, 51 and 53.

Wm. M. Thornton, Jr. and J. E. Chapman, J. Am. Chem. Soc., 43, 91 (1921).

² Knecht and Hibbert employ titanous chloride, which for most purposes is equally efficient. Either salt, in the form of a 20% solution, may be obtained from The La Motte Chemical Products Co., 13 W. Saratoga St., Baltimore, Md.

The ferric alum solution will serve for a "back titer" in any analysis, and it will

enable the operator to quickly detect any change in the oxygen consuming capacity of

the titanous salt solution.

Apparatus. The titanous sulphate solution, prepared as described above, is charged into the storage bottle S, Fig. 40a, the volume being so regulated as to fill the container to its neck. The stopcock F is then turned so that the liquid rises in the burette B and on up until hydrostatic equilibrium has been reached. With the hydrogen supply turned on from the Kipp generator K, the burette is allowed to empty itself by properly manipulating the cock F, and a current of pure hydrogen is maintained through the npparatus till it is reasonably certain that all air from within the system has been displaced. On being refilled the burette will be ready for service.

Standardization. One and five tenths grams of ferrous ammonium sulphate (C. P. crystals) are weighed with exactness into a 500 cc. Erlenmeyer flask and dissolved in about 150 cc. of water. Ten cc. of sulphuric acid (1:1) are added and the solution titrated at once with potassium permanganate, which has previously been standardized against Bureau of Standards sodium oxalate. until the end-point is just reached. After boiling for 10 minutes, the liquid is eooled at the tap to about 15° C. and titrated carefully with titunous sulphate in the presence of 10 cc. of the ammonium thiocyanate solution to complete loss of color. Another 1.5 gram portion of the same ferrous ammonium sulphate is titrated with titanous sulphate—omitting, however, the preliminary oxidation with permanganate. If the second small titer be deducted from the first titer, the difference will give the iron value of the titanium solution against sodium exalate; while the main titer (uncorrected) will serve as a basis on which to calculate the standard against ferrous ammonium sulphate. With specimens of ferrous ammonium sulphate of good quality, the results will be found to be in close agreement; but in case there is any considerable diserepancy, preference should be given to the sodium oxalate value.

Procedure. Ferric Iron. The solution, which may conveniently contain any amount of iron up to 0.28 gram and whose initial volume should not at the most exceed 500 cc., is titrated with titanous sulphate—using the same quantities of reagents and otherwise as prescribed above.

Total Iron. To determine the entire amount of iron present, notwith-standing its state of oxidation, the whole must be gotten into the ferric condition. This may be accomplished in one of three ways: (1) the solution is treated with hydrogen peroxide in ammoniacal solution and boiled to decompose the excess of the peroxide and finally acidified with hydrochloric acid; (2) the sulphuric acid solution is titrated with potassium permanganate (the exact strength of which need not be known) as detailed under standardization; (3) the solution is oxidized with potassium chlorate and hydrochloric acid acid the excess chlorate removed by evaporation. The second incthod is generally to be preferred. Large amounts of hydrochloric acid may be removed by evaporation on the water bath with sulphuric acid in excess; but with small concentrations of said acid the evil effect upon permanganate may be offset by adding a sufficient quantity of the Zimmermann-Reinhardt preventive reagent. 67 g. MnSO₄·4H₂O + 500 cc. H₂O + 138 cc. H₂PO₄ (sp. gr. 1.7) + 130 cc. H₂SO₄ (sp. gr. 1.82). Mixture diluted to 1000 cc.

Stannous Chloride Method for Determination of Ferric Iron

The procedure is based upon the reduction of the yellow ferric chloride to the colorless ferrous salt by stannous chloride, the following reaction taking place:

2FeCl₂+SuCl₂=2FeCl₂+SnCl₄.

The method is of value in estimating the quantity of ferrie iron in presence of ferrous, where the two forms are to be determined. In order to obtain the

total iron the ferrous is oxidized by adding a few crystals of potassium chlorate and taking to dryness to expel chlorine, and then titrated with stannous chloride.

The accuracy of the method depends upon the uniformity of conditions of temperature, concentration, etc., of making the run with the sample and of standardizing the stannous chloride. The solution should be free from other oxidizing agents, or from salts that give colored solutions.

The amount of iron in terms of ferrie oxide that can be estimated by this procedure ranges from 0.002 gram to 0.05 gram.

Reagents. Stannous Chloride Solution. The reagent is prepared by dissolving 2 grams of stannous chloride erystals in hot concentrated hydrochlorie acid and making up to 1 liter. The solution should be kept in a dark bottle to which the titrating burette is attached in such a way that the liquid may be siphoned out into this, as shown in the illustration, Fig. 41. The air entering the bottle passes through phosphorous or pyro-




Fig. 41.—Apparatus for Stannous Chloride Titration of Iron.

gallie acid to remove the oxygen. In this way, protected from the air, the reagent will keep nearly constant for several weeks. It is advisable, however, to restandardize the solution about every ten to fifteen days. One ee. will be equivalent to about 0.001 grain Fe.

Standard Iron Solution. 8.6322 grams of ferrie ammonia alum is dissolved in dilute hydrochloric acid and made up to one liter. The iron is determined in 100-ee. portions by the dichromate method. One ec. will contain about 0.001 gram Fe.

Procedure. To the sample in a easserole is added 25 ee. of concentrated hydrochloric acid and an equal volume of water. The resulting solution is heated to boiling and quickly titrated with the stannous chloride reagent, until the yellow color fades out and the solution becomes colorless.

Note. The titration should be done quickly, as the iron will reoxidize on standing and the solution again become yellow. The true end-point is the first change to a colorless solution.

COLORIMETRIC METHODS FOR THE DETERMINATION OF SMALL AMOUNTS OF IRON

Iron Traces. Sulphocyanate (Thiocyanate) Method¹

Introduction. By this method I part of iron may be detected in 50 million parts of water. The presence of free mineral acid increases the sensitiveness of the method, so that it is especially applicable to the determination of small amounts of iron in mineral acids. It is available in presence of many of the ordinary metals and in presence of organic matter. Silver, copper, cobalt, mercuric chloride, however, interfere.

Nitric acid gives a color with sulphocyanates that may be mistaken for iron.

This method, like the stannous chloride method, determines only the ferric iron. It is based on the fact that ferric iron and an alkali sulphocyanate, ammonium or potassium sulphocyanates, in an acid solution gives a red color, the intensity of which is proportional to the quantity of iron present. The color is due to the formation of the compound, Fe(CNS), 9KCNS-4H₂O.

Reagents Required. Standard Iron Solution. A ferric solution, the iron content of which has been determined, is diluted and divided so as to obtain 0.0004 gram Fe. This is made up to 2 liters with water containing 200 ee. of iron-free, C.P. 11₂SO₄. One hundred ee. of this solution, together with 10 ee. of normal ammonium sulphocyanate solution, is used as a standard. One hundred ee. contains 0.00002 gram Fe.

Normal sulphocyanate contains 76.1 grams of NHCNS per liter.

Procedure. The weighed sample, 1 to 10 grams, or more if necessary, is dissolved in dilute H₂SO₄ and oxidized by adding dilute permanganate, KMnO₄, solution drop by drop until a faint pink color is obtained. The sample is diluted to exactly 100 cc. and is poured into a burette graduated to $\frac{1}{10}$ cc. Two colorless glass cylinders of the 100-cc., Nessler type are used for comparison of standard and sample. Into one cylinder is poured 100 cc. of the standard solution, made as directed above. Into the second cylinder containing 10 cc. of sulphuric acid with 10 cc. ammonium sulphocyanate, NH₄CNS, diluted to 60 or 70 cc., the sample is run from the burette until the depth of the color thus produced on dilution to 100 cc. exactly matches the standard. From the number of cc. used the weight of the sample is calculated. One hundred cc. of the standard contains 0.00002 gram Fc.

Dividing the weight of iron in the standard by the weight of sample used and multiplying by 100 gives the per cent of iron in the sample.

Notes. If other metals are present, that form two series of salts, they must be in the higher state of oxidation, or the color is destroyed. (Sutton.) Oxalic acid, if present, destroys the color. Oxidation with KMnO₄ or KClO₂ with subsequent removal of Cl₂ prevents this interference. (Lunge, C. N., 73, 250.)

Chlorides of the alkaline earths retard or prevent the sulphocyanate reaction.

(Weber, C. N., 47, 165.)

The colorimeter used for the determination of minute quantities of lead would serve admirably for the determination of traces of iron by the sulphocyanate method.

Acids, hydrochloric or sulphuric (diluted), may be added directly to the ammonium sulphocyanate solution.

¹ Thomson, J. C. S., 493, 1885, and C. N., 51, 259. Kruss and Moraht, C. N., 64, 255. Davies, C. N., 8, 163.

Salicylic Acid Method for Determining Small Amounts of Iron

Salicylic acid produces an amethyst color with neutral solutions of ferric salts, the depth of the color being proportional to the concentration of the ferric iron in the solution. The reaction is useful in determining small amounts of iron in neutral salts, such as sodium, ammonium, or potassium alums, sulphates, or chlorides, zinc chloride, etc. Phosphates, fluorides, thiosulphates, sulphites, bisulphites and free mineral acids should be absent. The sample should not contain over 0.0002 gram iron, as the depth of color will then be too deep for colorimetric comparisons. As low as 0.00001 gram ferric iron may be detected. Ferrous iron produces no color with the reagents, hence the procedure serves for determining ferric iron in presence of ferrous.

The material is dissolved in 20 cc. of pure water, the sample filtered if cloudy, and transferred to a Nessler tube. Dilute potassium permanganate solution is added until a faint pink color is produced and then 5 cc. of a saturated solution of salicylic acid. (The reagent is filtered and the clear solution used.) Comparison is made with standard solutions containing known amounts of ferric iron, the standards containing the same reagents as the sample. If desired the standard iron solution (0.086 gram ferric ammonium alum, clear crystals, dissolved in water containing 2 cc. of dilute sulphuric acid and made to 1000 cc., each cc. contains approximately 0.00001 gram Fe''') is added from a burette to 5 cc. of salicylic acid diluted to 25 cc. in a Nessler tube, until the color of the standard matches the sample. A plunger is used to stir the liquids.

TECHNICAL ANALYSIS OF IRON AND STEEL

The elements carbon, manganese, phosphorus, sulphur, and silicon are invariable constituents of iron and steel, and are always included in an analysis.

Copper and arsenie are sometimes found; aluminum, chromium, nickel, molybdenum, tin, titanium, tungsten, vanadium, and zinc occur in special alloy steels. Minute traces of oxygen, hydrogen, and of many other elementary constituents frequently are present, but are of so little importance that they are seldom considered in an analysis.

The importance of the subject has called for a special chapter on the subject of iron and steel. This may be found in volume II of this work. The individual determinations are given in chapters throughout volume I. We will deal with a few determinations here.

Preparation of the Sample

The sample of borings is taken from several portions of the piece by a drill, free from oil or grease, and stored in a heavy manilla envelope. For carbon determinations samples contaminated by oil or grease should be thoroughly washed with ether before making the determination.



F10. 42.

Total Carbon

The determination is required for an accurate estimation of earbon where the color test indicates the carbon content outside the limits of requirement, or in cases where interfering substances are present. In material where the carbon content is of extreme importance, the color method is not used. Details of the procedure for determining carbon by direct combustion are given in the chapter on Carbon. The following procedure is recommended by the Bureau of Standards:

- (a) In Irons. Two grams of iron are mixed with about twice the weight of purified ferric oxide. The mixture is placed in a platinum boat, which is lined with a suitable bed material, and is burned in a current of oxygen, as described below.
- (b) In Steels. The method is the same as for irons with omission of the ferrie oxide mixture.

Details of Direct Combustion Method. Furnaces and Temperature of Burning. Porcelain tubes wound with "nichrome" wire, provided with suitable heat insulation and electrically heated, are used, and readily give temperatures to 1100° C. Type FB 301 Hoskins tube furnace and the hinged type, Fig. 32b, are satisfactory. The temperature control is by means of an animeter and rheostat in series with the furnace, with occasional check by a thermocouple.

Boats and Lining. Platinum boats provided with a long platinum wire for manipulation in the tube are mostly used; alundum ones occasionally. The bed or lining on which the steel rests is 90-mesh "RR alundum, alkali-free, specially prepared for earbon determination." A layer of this alundum is also placed in the bottom of the combustion tube to prevent the boat sticking to the glaze. A platinum cover for the boat is sometimes used, and is essential when the combustion is forced.

The nature and quality of the bed material are matters of great importance. Alumina as prepared from the sulphate or from alum may not be free from sulphate or alkali, both of which have given serious trouble at the Bureau. The alkali, if present, may not manifest itself by an alkaline reaction until after one or two combustions have been made, using the same bed material. Even the ordinary white "alundum" on the market carries a few hundredths of 1% of alkali. Iron oxide has been tried, and when pure should, apparently, give good service. As yet, however, it has been difficult to obtain or prepare acceptable material for use with steels. Quartz sand gives rise to a fusible slag, which melting before combustion is complete, incloses bubbles of carbon dioxido gas. This defect would probably inhere in any other material of an acid character. The presence in the silica bed after combustion of crystals which appear to be carborundum, have occasionally been noted.

Purity of Oxygen. Blanks. The Bureau makes its oxygen electrolytically, and its content of this element is usually 99 to 99.5%, and sometimes higher. Even with this gas a slight blank is usually obtained. When running a blank, in addition to the usual precautions, the rate at which the oxygen is introduced should be the same as when burning a sample, and the time should be three to five times as long.

Method of Admitting Oxygen and Rate of Combustion. The furnace being at the proper temperature, the boat containing the sample is introduced. Oxygen is admitted either at once or after the boat has reached the temperature of the furnace, as the operator prefers, or us the nature of the steel may demand. The rate of flow of the oxygen varies with the absorption apparatus used and with the preference of the operator, and may be considerably more rapid when absorbing earbon dioxide in soda lime than in un alkaline solution. A rapid flow of oxygen also facilitates the burning of resistant samples. A continuous forward movement of the gas current is maintained at all times. The time for a determination varies, of necessity, with the nature of the sample and the rate of flow of the oxygen, ranging from ten to thirty minutes. The endeavor is to obtain a well-fused oxide. With all samples close packing in a small space is conducive to rapid combustion and to fusion of the resulting oxide.

Authorities differ as to the advisability of allowing the oxide of iron to fuse thoroughly. Even when fusion does take place additional earbon dioxide is obtained very frequently by grinding the oxide and reburning. Often more than one regrinding and reburning is necessary in order to reduce the amount of carbon dioxide obtained to that of the constant blank.

Oxides of sulphur have been found very difficult to eliminate from the gases leaving the tube. Lead peroxide ("nach Dennstedt") heated to 300° C. and sinc at room temperature appear to retain them best.

Attention is called to the inadmissibility of using dry agents of different

¹ Statement of Mr. George M. Berry, of the Halcomb Steel Co.

D ... C ... 1 C ... 1 ...

absorptive power in the same train, in positions where a difference could possibly affect results.

Weighing of Tubes. There is much greater difficulty in securing constant conditions when weighing absorption tubes than is usually considered to be the case. Electrical effects, caused by wiping as a preliminary to weighing, may occasionally cause errors in weight running into the milligrams. The use of counterpoises of equal volume and similar material and shape is recommended.

If tubes are weighed full of oxygen, care is necessary to secure a uniform atmosphere in them. Even though the attempt is made to keep the apparatus always full of oxygen, some air is admitted when the boat is pushed into the combustion tube, and a nuch longer time is required to displace this than is usually allowed, unless the flow of oxygen during aspiration is rapid. The same is true if the tubes are weighed full of air by displacing the oxygen left in them after the steel is burned. Another source of error may arise from the air admitted when putting the boat into the tube, if this air contains much carbon dioxide, as is the case when a gas furnace is used. The boat is usually pushed at once into the hot furnace, and as combustion begins almost immediately, there is no opportunity for displacing this air before the steel begins to burn.

Graphite in Iron

Two grams of iron are dissolved in nitric acid (sp.gr. 1.20), using 35 cc. and heating very gently. The residue is collected on an asbestos felt, washed with hot water, then with a hot solution of potassium hydroxide (sp.gr. 1.10), followed by dilute hydrochloric acid and finally by hot water. After drying at 100° C., the graphite is burned in the same manner as the total carbon, but without admixture of ferric oxide.

Standard Specifications for Carbon

Material	Per Cent Carbon
Automobile Carbon Steel. Boiler and Fire Box Steel Stationary Service. Carbon Steel Bars, Auto Springs. Carbon Steel Bars, Railway Springs.	not over 0.25 0.45-0.65
Carbon Steel Rails. Carbon Tool Steel. Carbon Tool Steel High Speed. Cold Drawn Bessemer Steel Automatie Serew Stoek. Fire Box Steel. Forge Welding Steel Plates Flange. Forge Welding Steel Plates Structural. Lap Welded Scamless Boiler Tubes. Low Carbon Steel Splice Bars. Medium Carbon Steel Splice Bars and Track Bolts. High Carbon Steel Splice Bars. Rivet Steel for Buildings, Cars and Ships. Steel Castings. Quenched and Tempered Steel, Axles, Shafts and Forgings.	{ Bessemer 0.37–0.55
Wrought Solid Carbon Steel Wheels and Tires	Acid 0.60-0.80 Basic 0.65-0.85

Manganese in Iron and Steel

Ammonium Persulphate Method

Small amounts of inauganese may be determined colorimetrically by the persulphate method, provided the sample does not contain over 1.5% of manganese.

Reaction. $2M_{11}(NO_3)_2 + 5(NH_4)_2S_2O_8 + 8H_2O$ = $5(NH_4)_2SO_4 + 5H_2SO_4 + 4HNO_3 + 2HMnO_4$.

0.1 to 0.2 gram of steel, according to the amount of manganese in the sample, is placed in a 10 in, test-tube and 10 cc. of nitric acid (sp.gr. 1.2) are added. The sample is heated in a water bath until the nitrous fumes are driven off and the steel is completely in solution. 15 cc. of AgNO₃ sol. (1.5 g. per l.) are added to the cooled sample, followed immediately with about 1 gram of ammonium persulphate crystals. The solution is warmed (80 to 90° C.) until the color commences to develop, and then for half a minute longer, and then placed in a beaker of cold water until the solution is cold. Comparison is now made with a standard steel treated in the same way, the comparison being made exactly as indicated for determining carbon by the color method. See chapter on Carbon.

Example. If the standard, containing 0.6% Mn, is diluted to 15 cc., each ec.=0.04% Mn. If the sample required a dilution of 20 cc. to match the standard, then $0.04 \times 20 = 0.8\%$ Mn.

Note. If preferred, the sample may be titrated with standard sodium arsenate, one cc. of which is equivalent to 0.1% on basis of 0.1 gram sample.

Lead Oxide Method (Deshey)

Oxidation of the manganese in the steel is effected in a nitric acid solution by addition of red lead (or by lead peroxide); the lead peroxide, formed, oxidizes the manganese nitrate to permanganic acid. The solution is now titrated with standard sodium arsenite, the following reaction taking place:

$$2HMnO_4 + 5Na_3AsO_3 + 411NO_3 = 5Na_3AsO_4 + 3H_2O + 2Mn(NO_3)_2$$
.

0.5 gram of steel is placed in a 150 cc. beaker and dissolved with about 30 cc. of nitric acid (sp.gr. 1.12). After violent action has subsided, the beaker is placed on a hot plate and when the iron has dissolved, 20 cc. of water added. The manganese is now oxidized by adding red lead in small portions at a time, until the solution appears brown with a pinkish purple foaft on the surface. The solution is diluted with hot water until the volume is about 100 cc. and then boiled for a few minutes. It is now placed in a dark closet to cool. (A fresh batch of samples may be started in the meantime.) The solution is carefully decanted off from the peroxide, and with the washings of the peroxide residue, titrated with standard sodium arsenite to the yellowish green end-point. The sodium arsenite is made by dissolving 4.96 grams of pure arsenous acid together with 25 grams of sodium carbonate in 200 cc. of hot water and the solution diluted to 2500 cc. The arsenite is standardized against a steel sample of known manganese content, or against standard permanganate solution.

Bismuthate Method for Determining Manganese, Recommended by the U. S. Bureau of Standards

This is the most accurate method for determining manganese in iron and steel. The procedure is as follows:

Procedure. One gram of drillings is dissolved in 50 ec. of nitric acid (sp.gr. 1.135) in a 200 cc. Erlenmeyer flask. Irons should be filtered. The solution is cooled, about 0.5 gram of sodium bismuthate is added, and it is then heated until the pink color has disappeared. Any manganese dioxide separating is dissolved in a slight excess of a solution of ferrous sulphate or sodium sulphite. The solution is boiled till free from nitrous fumes. After cooling to 15° C., a slight excess of bismuthate is added and the flask is shaken vigorously for a few minutes. Then 50 ec. of 3% nitric acid is added and the solution is filtered through asbestos. A measured excess of ferrous sulphate is run in and the excess titrated against permanganate solution which has been compared with the iron solution on the same day. A great many steels now carry small amounts of chromium as impurity. In such cases titration against arsenite solution is recommended, or removal of the chromium by zine oxide and subsequent determination of the manganese by the bismuthate method.

Permanganate solutions are standardized against sodium oxalate.

Standard Specifications for Manganese

Material	Per Cent Manganese
Automobile Carbon Steels	0.25-0.60
Boiler and Fire Box Steel Stationary Service	
Carbon Steel Bars Auto Springs	0.60-0.80
Carbon Steel Bars R. R. Springs	max. 0.5
Carbon Steel Rails	∫ Bessemer 0.8–1.10
Carbon Tool Steel	
Carbon Tool Steel High Speed	0.15 ±
Cold Drawn Bessemer Steel Automatic Screw Stock	
Fire Box Steel	
Forge Welding Flange and Structural Steel Plates	0.30-0.00
Lap Welded Seamless Boiler Tubes	0.50-0.00
Open Hearth Steel Girders	0.00-0.50 0.70 Ni not under 3.25%
Quenched High Carbon Steel.	not over 0.80
Acid) 0 == 0 +0
Wrought Solid Carbon Steel Wheels and Tires $\left\{ egin{array}{l} \operatorname{Acid} \dots \\ \operatorname{Basie} \dots \end{array} \right.$	0.55-0.80

Determination of Phosphorus

The procedures outlined by the Bureau of Standards are generally used in steel works laboratories.

- (a) Preparation of Solution and Precipitation of Phosphorus. Two grams of sample are dissolved in nitric acid (sp.gr. 1.135) and the solution is boiled until brown fumes no longer come off. Ten cc. of permanganate solution (15 grams to 1 liter) are added, and the boiling is continued. Sodium sulphite solution is added to dissolve the oxide of manganese, and the solution is again boiled and then filtered. With irons the insoluble residue should be tested for phosphorus. After cooling the filtrate, 40 cc. of aminonia (sp.gr. 0.96) are added, the solution is agitated, and when the temperature is at 40° C., 40 ec. of molybdate solution increased and the solution is shaken vigorously for five minutes. After settling out, the yellow precipitate is treated according to one of the following methods, b or c:
- (b) Alkalimetric Method. The precipitate is washed with 1% nitrie acid solution followed by 1% potassium nitrate solution until the washings are no longer acid. The precipitate is dissolved in a measured excess of standardized sodium hydroxide solution and titrated back with standardized nitric acid using phenolphthalein. The solutions are standardized against a steel with a known amount of phesphorus.
- (c) Molybdate Reduction Method. The precipitate is washed ten to fifteen times with acid ammonium sulphate (prepared according to Blair) or until the washings no longer react for iron or molybdenum. It is dissolved in 25 ec. of ammonia (5 cc. ammonia of 0.90 sp.gr. to 20 cc. water). The filter is washed well with water and 10 cc. of strong sulphuric acid added to the filtrate, which is run through the reductor at once and titrated against a N/30 permanganate solution which has been standardized against sodium oxalate.

Standard Specifications for Upper Limits of Phosphorus

of the state of th	
Material	Per Cent Limit of Phosphorus
Automobile Carbon Steels	0.045
Boiler and Fire Box Steel, Stationary Service Acid. Basic.	not over 0.04
Carbon Steel Bars Auto Springs	0.045
Carbon Steel Bars R. R. Springs	0.05
Carbon Steel Rails	max. 0.10
Carbon Tool Steel	
Carbon Tool Steel High Speed	0.01 or more
Cold Drawn Automatic Screw Stock	0.09-0.13
Fire Box Steel	0.05
Forge Welding Flange and Structural Steel Plates	0.04 - 0.06
Lap Welded Seamless Boiler Tubes	0.04
Low, Medium and High Carbon Splice Bars	
Rivet Steel for Ships	∫ Acid 0.06
	L Dagle Cot
Open Hearth Steel Girders	
Steel Castings	Acid 0.07
Diddi Cabutta 3	
Structural Steel for Cars and Ships	Acid 0.06
	(Danie V.O.
Structural Steel for Buildings	Bessemer 0.10
Quenched and Tempered Steel Axles, Shafts and Forgings	0.05
Wrought Solid Carbon Steel Wheels and Tires	0.05

Gravimetric Method. Sulphur by Oxidation

Five grams of iron or steel are dissolved in a 400-ec. Erlenmeyer flask, using 50 cc. of strong nitric acid. A little sodium carbonate is added, the solution is evaporated to dryness, and the residue baked for an hour on the hot plate. To the flask 30 cc. of strong hydrochloric acid are added, and the evaporation and baking are repeated. After solution of the iron in another 30 cc. of strong hydrochloric acid and evaporation to a sirupy consistency, 2 to 4 cc. of the same acid are added, followed by 30 to 40 cc. of hot water. The solution is then filtered and the residue washed with hot water. The sulphur is precipitated in the cold filtrate (about 100 ce.) with 10 cc. of a 10% solution of barium chloride. After forty-eight hours the precipitate is collected on a paper filter, washed first with hot acid (containing 10 cc. of concentrated hydrochloric acid and 1 gram of barium chloride to the liter) until free from iron and then with hot water till free from chloride; or, first with cold water, then with 25 cc. of water containing 2 cc. of concentrated hydrochloric acid to the liter. The washings are kept separato from the main filtrate and are evaporated to recover dissolved barium sulphate.

With iron the paper containing the insoluble residue above mentioned is put into a platinum crucible, covered with sodium carbonate free from sulphur, and charred without allowing the carbonate to melt. The crucible should be covered during this operation. Sodium nitrate is then mixed in and the mass fused with the cover off. An alcohol flame is used throughout. The melt is dissolved in water and evaporated with hydrochloric acid in excess to dryness in porcelain. The evaporation with water and hydrochloric acid is repeated to insure removal of nitrates. The residue is extracted with a few drops of hydrochloric acid and water, the insoluble matter is filtered off, and barium chloride is added to the filtrate. The barium sulphate obtained is added to the main portion.

Careful blanks are run with all reagents.

Note. For volumetric method see chapter on sulphur.

Standard Specifications for Limits of Sulphur

Material	Percentage Limit of Sulphur
Automobile Carbon Steels. Boiler and Fire Box Steel.	0.050
Carbon Steel Bars for Auto Springs	0.045
Carbon Steel Bars for R. R. Springs	0.075-0.150
Carbon Tool Steel Carbon Tool Steel High Speed.	0.01 or more as specined
Fire Box Steel. Forge Welding Flange and Structural Steel Plates	0.050
Lap Welded Seamless Boiler Tubes. Rivet Steel for Ships.	0.045
Steel Castings. Structural Steel for Buildings, Bridges, Cars, Ships.	0.060
Wrought Solid Carbon Steel Wheels and Tires	. 0.0 50

Determination of Silicon

One gram of pig iron, east iron, and high silicon iron, or 5 grams of steel, wrought iron, and low silicon iron are taken for analysis. (By taking multiples of the factor weight 0.4693, SiO₂ to Si, the final calculation is simplified.) The sample is placed in a 250-ee. beaker and 20 to 50 cc. of dilute nitric acid added. If the action is violent, cooling the beaker in water is advisable. When the reaction subsides, 20 cc. of dilute sulphuric acid, 1:1, are added, the mixture placed on the hot plate and evaporated to dense white fumes The residue is taken up with 150 cc. of water containing 2 to 5 cc. of sulphuric acid and heated until the iron completely dissolves.

The solution is filtered and the silica residue washed first with hot dilute hydrochloric acid, sp.gr. 1.1, and then with hot water added in small portions to remove the iron sulphate. The residue is now ignited and weighed as silica.

If there is any doubt as to the purity of the silica, moisten the residue (in a platinum crucible) with strong sulphuric acid and add a few cc. of hydrofluorie acid (crucible cover full), evaporate to dryness, ignite and weigh. The loss of weight is due to siliea.

NOTE. If the ash is colored by iron oxide, silica is determined by difference after expelling the silies by adding 4 to 5 ee. of hydrofluorie acid and a few drops of sulphurie, taking to dryness and igniting the residue.

The following acid inixtures are recommended by the U. P. Ry. For steel, wrought iron and low silicon iron, 8 parts by volume of HNO₃, sp.gr. 1.42; 4 parts of cone. H₂SO₄, sp.gr. 1.84; 6 parts HCl, sp.gr. 1.2 and 15 parts by volume of water. For dissolving pig iron, east iron and high silicon iron, a mixture of 8 parts by volume of strong nitrie acid and 5 parts of strong sulphuric acid, diluted with 17 volumes of water, is used.

Rapid Method for Determining Silicon in Foundry Work. Liquid iron, dropped into cold water from a ladle 3 ft. above the water, will form shot shaped according to forms resulting from its chemical constitution, silicon being an important factor. Round shot, concave upper surface, 1 to 3 in. in diameter, indicate over 2% silicon. Flat or irregular shot indicate low silicon. Shot with elongated tails indicate very low silicon.

Other Methods for Determination of the Less Common Elements in Steel. Other elements more commonly sought in alloy steel are copper, nickel, ehronium, vanadium, tungsten, titanium and molybdenum. Methods for estimation of these elements are given in the chapters dealing with these substances. A.S.T.M. Methods for Steel may be found in Vol. 2.

Standard Specifications for Silicon

Diamonta Opconications for Officon	
Material	Per Cent Silicon
Boiler and Fire Box Plates	not over 0.03
Carbon Steel Bars Auto Springs	1.80-2.10
Carbon Steel Bars R. R. Springs	0.25-0.50
Carbon Steel Rails Bessemer and Open Hearth	0.20
Carbon Tool Steel	0.15+ ⋅
Carbon Tool Steel High Speed	$0.15 \pm$
Cylinder Grado Pig Iron	1.25-1.60
Floor Grado Pag Iron	2.25-2.75
Open Hearth Steel Girders	0.20
Wrought Solid Carbon Steel Wheels and Tires	Acid 0.15-0.35 Basic 0.10-0.30

Tool Steels may contain 0.5±Cr, 0.75±W, 0.25±V, 0.5±Co and other Norm. elements.

LEAD

Pb, at.wt. 207.2; sp.gr. 11.34; m.p. 327°; b.p. 1525°C; oxides, PbO, PbO₂, Pb₂O₄.

DETECTION

Hydrochloric acid precipitates lead incompletely from its cold solution as white PbCl₂, soluble in hot water by which means it is separated from increurous chloride and silver chloride. PbCl₂ forms needle-like crystals upon cooling the extract.

Hydrogen sulphide precipitates black PbS from slightly acid solutions along with the other elements of the group. Yellow ammonium sulphide, sodium sulphide and the fixed alkalics dissolve out arsenic, antimony and tin. The sulphide of lead, together with bismuth, copper and cadmium, dissolve in hot dilute nitric acid, leaving mercuric sulphide insoluble. The extract evaporated to dryness and then to SO₃ fumes, after addition of sulphuric acid, expels nitric acid. Upon adding water to the residue and boiling with a little additional sulphuric acid the sulphates of bismuth, copper and cadmium are dissolved out, lead sulphate remaining as a white residue.

Lead may be further confirmed by dissolving the sulphate in ammonium acetate (barium sulphate is very slightly soluble,) and precipitating the yellow chromate, PbCrO₄, by addition of potassium dichromate solution.

ESTIMATION

The determination of lead is required in valuation of its ores—galena, PbS; anglesite PbSO₄; cerussite, PbCO₅; krokoite, PbCrO₄; pyromorphite, 3Pb₁P₂O₅·PbCl₂. It is determined in lead mattes; certain slags; drosses from hard lead; cupel bottoms; skimmings; lead insecticides (arsenato of lead); paint pigments such as white lead, red lead, yellow and red chromates, etc. It is determined in alloys such as solder, type metal, bell metal, etc. The estimation is necessary in the complete analysis of a large number of ores, especially in minerals of antimony and arsenic. Traces of lead are determined in certain food products where its presence is undesirable.

Preparation and Solution of the Sample

In dissolving lead, its alloys, or ores the following facts will be recalled. Hot, dilute nitric acid is the best solvent of the metal. Lead nitrate is insol-

¹Lead precipitates best from solutions containing 1 ee. of concentrated free hydrochloric acid (sp.gr. 1.19) for each 100 cc. of solution. The sulphide is appreciably soluble if the acidity is increased to 3 cc. HCl per 100 of solution.

Chapter contributed by Wilfred W. Scott.

272 LEAD

uble in concentrated nitric acid, but dissolves readily upon dilution with water. The metal is insoluble in dilute sulphuric acid, but dissolves in the hot, concentrated acid. Although not soluble in dilute hydrochloric, it dissolves in the hot, concentrated acid, especially in presence of the halogens chlorine, bromine and iodine. The metal is soluble in glacial acetic acid. The salts are soluble in hot, dilute nitric acid. In dissolving sulphide ores it should be kept in mind that strong nitric acid will form some lead sulphate which will be precipitated upon dilution of the solution. Oxidation is less apt to occur with the dilute acid. Silicates and slags require fusion with sodium carbonate and potassium earbonate. The cooled mass may then be extracted with hot water to remove silica and the residue containing the carbonates of the heavy metals' dissolved in dilute nitric acid. Lead salts are soluble in ammonium acecate.

Ores, Minerals of Lead, etc. In decomposing lead ores it is well to start with hydrochloric acid, about 20 cc. per gram sample. The pear-shaped flask is convenient for this work. Warm gently but do not boil, add more acid if necessary. If the ore contains galena, PbS, some H₂S is expelled. There is generally a liberation of free sulphur, which floats in globules on the surface of the solution. After the reaction with hydrochloric acid subsides, nitric acid is added and the solution boiled, then follows the addition of sulphuric acid and the solution is evaporated to strong fumes. This expels nitric and hydrochloric acids. On dilution of the solution lead sulphate remains insoluble, with silica and certain insoluble substances, such as barium sulphate, etc. The residue should not contain black particles of undecomposed ore as these are very likely to contain lead. Addition of HF assists decomposition of silicates.

It may be advisable, in certain cases, to open up the ore with nitric acid or agua regia, followed by sulphuric acid and hydrofluoric acid.

Iron Pyrites and Ores with Large Amounts of Impurities with Small Amounts of Lead. Ten grams of the sample or more, if lead is present in very small amounts (less than 0.1%), are taken for analysis, and 50 cc. of a mixture of potassium bromide and bromine solution added (75 grams of KBr dissolved in 400 ee. of water and 50 cc. of bromine added). After ten to fifteen minutes about 50 ce. of concentrated nitric acid are added and after the violent reaction has eeased 25 to 30 cc. of concentrated hydrochloric acid and the solution is evaporated on the hot plate to near dryness. Fifty ec. of C.P. (lead free) concentrated sulphurie acid is now added and the sample taken to fumes of SO, on a sand bath. After cooling, the concentrate is diluted to 500 ec. with water, about 5 ec. of strong sulphurie acid added, the solution heated to boiling and cooled. The precipitate is filtered by decantation onto a fine-grained filter (quality of an S. & S. 590 or B. & A. grade A), the residue boiled with more water containing H₂SO₄ and again decanted. This is repeated until all the iron sulphate is removed. (The filtrates should be kept several hours to see whether any of the lead has passed through the paper in a colloidal condition.) The precipitate is finally poured on the filter and washed with 2% H2SO4. Impure residues are extracted for lead with ammonium acetate.

Solution of Lead Alloys. As a rule these are best decomposed by treating 0.5 to 1.0 gram of the material, or more as the ease may require, with a hot solution of nitrie acid, 1:1, and evaporating the solution to low bulk, but not to dryness. Hot water is now added and the material boiled and the soluble portion filtered off. The insoluble material is digested with concentrated hydrochloric acid to which a little bromine has been added.

LEAD 273

SEPARATIONS

Separation of Lead as Sulphate. Lead is most frequently separated from other metals by precipitation as sulphate, PbSO4, according to the details given under "Preparation and Solution of the Sample." In the presence of much bismuth or iron it is necessary to wash the precipitate with a 10% sulphuric acid solution to ke p the bismuth in solution and to prevent the formation of the difficultly soluble basic ferric sulphate. In absence of appreciable amounts of these elements the lead sulphate is more completely separated by adding to the dilute sulphuric acid solution an equal volume of alcohol, filtering and washing the residue with 50% alcohol.

Separation of Lead from Barium. In the analysis of minerals containing barium, the insoluble sulphate, BaSO₄, will be precipitated with lead. Since barium sulphate is slightly soluble in ammonium acetate it will contaminate the lead in the subsequent extraction by this reagent. The presence, however, of a little sulphuric acid, renders this solubility practically negligible. The sulphuric acid should not exceed 1-2% in the ammonium acetate reagent, as lead sulphate will precipitate if sufficient sulphuric acid is added to the acetate extract. (Lead sulphate is precipitated almost completely if the acetate solution contains 10% sulphuric acid.)

Lead may be separated from barium sulphate by digesting the mixed sulphates with ammonium carbonate solution, whereby the lead sulphate is transposed to lead carbonate and ammonium sulphate, while barium sulphate is not changed. The soluble ammonium sulphate may be washed out with ammonium solution followed by water. Since lead carbonate is s'ightly soluble in the ammonium salt, the filtrate is treated with hydrogen sulphide and the dissolved lead recovered as PbS. The residue containing lead carbonate and barium sulphate is treated with dilute nitric or acetic acid. Lead passes into solution, while barium sulphate remains insoluble.

Extraction of Lead from the Impure Sulphate by Ammonium Acetate. The filter containing the impure sulphate, obtained by one of the procedures for solution of the sample, is placed in a casserole and extracted with about 50 ee. of hot, slightly ammoniacal ammonium acetate, the stronger the acetate the better. The clear liquid is decanted through a filter and the extraction repeated until the residue is free from lead (i.e., no test is obtained for lead with $K_1Cr_2O_7$). A very effective method of extraction is by adding solid ammonium acetate directly to the sample on a filter and pouring over it a hot solution of ammonium acetate. The filtrate containing the pure lead acetate solution may now be examined by one of the following procedures.

Lead sulphate containing arsenie should be dissolved in ammonium acetate, the extract made alkaline and lead precipitated as PbS. Arsenie remains in solution.

GRAVIMETRIC METHODS

Determination of Lead as the Sulphate, PbSO₄

Procedure. The sample having been dissolved according to a method outlined, the lead precipitated as PbSO₄ by addition of an excess of sulphuric acid, and taking to SO₃ fumes, the lead sulphate is filtered off, upon cooling and diluting the sample. The PbSO₄ is washed with water containing 10% H₂SO₄ until free from soluble impurities. If insoluble sulphates or silica are present the lead must be purified. If such impurities are known to be absent (alloys), the sulphate may be filtered directly onto an asbestos mat in a tared Gooch crucible, dried, then ignited to dull red heat, cooled and finally weighed as PbSO₄. In the analysis of ores, however, it is generally advisable to purify the sulphate.

Purification of Lead Sulphate. Details of the procedure have been given under Separations—Extraction of Lead from the Impure Sulphate. The lead sulphate having been brought into solution by extraction with strong ammonium acetate solution, the excess acetic acid is volatilized by evaporation, the residue cooled and diluted with water. An excess of sulphuric acid is added and the precipitated sulphate is filtered off, washed with dilute sulphuric acid and alcohol, dried at about 110° C., or if preferred by ignition at dull red heat, and weighed

PbSO₄×0.6831 = Pb. Pb multiplied by 100 and divided by weight of sample taken equals per cent.

Notes. Lead sulphate may be precipitated from ammonium acetate solution by adding sulphuric acid until the solution contains approximately 10% H₂SO₄.

An acetate extraction may not be necessary, as is generally the case in the analysis of alloys. In analysis of ores, however, PbSO, may be contaminated by sulphates of the alkaline earths and by silica. The difficultly soluble oxides of iron and alumina may also be present.

If arsenic is in the sulphate it will pass into the filtrate with the lead.

Determination of Lead as the Chromate, PbCrO4

This excellent method is applicable to a large class of materials and is of special value in precipitation of lead from an acetic acid solution, the method depending upon the insolubility of lead chromate in weak acetic acid.

Procedure. The solution of the sample, precipitation of the lead as the sulphate and extraction of lead with annuonium acctate have been given in detail,

The filtrate, containing all the lead in solution as the acetate, is acidified slightly with acetic acid and heated to boiling. Lead is precipitated by addition of potassium dichromate solution in excess (10 cc. of 5% K2Cr2O2 solution are generally sufficient). The solution is boiled until the yellow precipitate turns to a shade of orange or red.1 The precipitate is allowed to settle until the supernatant solution is clear. (This should appear yellow with the excess of dichromate reagent.) The PbCrO, is filtered onto an asbestos mat in a tared Gooch crucible, washed with water, dried in an oven at about 110° C. and the cooled compound weighed as PbCrO₄.

$$PbCrO_4\times 0.641 = Pb, \quad \frac{Pb.\times 100}{Wt. \ of \ sample} = per \ cent \ Pb.$$

Impurities, such as iron, copper, eadmium, etc., in the acctate solution of lead seriously interiere in the chromate precipitation. These should be leached out with water containing a little sulphuric acid before extracting the lead sulphate with ammonium acetate. See remarks under section on Traces of Lead.

If a standard solution of potassium dichromate is used in the precipitation of lead the excess of the reagent, upon filtering of the precipitate, may be titrated and the lead determined volumetrically. A known amount of dichronate solution (added from a burette) sufficient to precipitate all the lead and about one-third of the volume in excess is added to the hot solution. After boiling about two minutes the precipitate is filtered off quickly and washed several times with hot water. The filtrate, or an aliquot part of it, is made acid with 5 cc. concentrated sulphuric acid and titrated with standard ferrous sulphate at about 60° C., using potassium ferrieyanide as an outside indicator; the end-point is a blue color produced by the slight excess of the ferrous salt reacting with the indicator. The excess of dichromate may excess of the ferrous sait reacting with the indicator. The excess of dicfirormate may be determined by adding 3 to 4 grants of solid potassium iodide, K1, to the solution diluted to about 500 cc. with water to which 15 cc. of concentrated sulphuric acid has been added. The liberated iodine is titrated with standard thiosulphate, the end-point being colorless, with starch solution internal indicator, changing from blue. Bi, Sb, Ba, Sr and Ca interfere slightly.

One cc. N/10 $K_2Cr_2O_7 = 0.010355$ gram Pb. One cc. N/5 $K_2Cr_2O_7 = 0.02071$ gram Pb.

¹ The yellow precipitate gives high results, since it is difficult to wash. The crystalline orange or red compound may be quickly filtered and washed.

275a LEAD

Determination of Lead as the Molybdate, PbMoO4

This method is rapid and has the following advantages:

a. The sulphation of lead is avoided. b. The acetate extraction is eliminated. c. The precipitate may be ignited. d. The ratio of lead to its molybdate compound is greater than either lead to PbSO₄ or to PbCrO₄, lessening the chance of error through weighing.

Cobalt, calcium, strontium and barium have little effect in presence of

ammonium acctate. In absence of this salt they interfere slightly.

Procedure. The ore or alloy is decomposed with nitric acid or aqua regia as the case may require. (Silica if present is climinated by taking to dryness, dehydrating, taking up with dilute nitric acid and filtering.) To the clear liquid 2 g. ammonium chloride is added and then sufficient ammonium acetate to destroy the excess of free nitric acid, i.e., 2 g. per cach ec. of free HNO₂ present.

Lead is now precipitated by adding 40 cc. of ammonium molybdate per each 0.1 g. of lead present (4 g. per liter+10 cc. acetic acid), stirring the mixture during the addition. After boiling for two or three minutes the precipitated lead molybdate is allowed to settle, then filtered and washed with small

portions of hot water and ignited over a Bunsen burner.

The cooled residue is weighed as PbMoO₄. PbMoO₄ \times 0.5642=Pb.

Notes. If antimony er other members of the group are present in the original sample, it is advisable to dissolve the residue in HCl and reprecipitate the lead with melybdate reagent.

If lead is in the form of the sulphide, as may be the ease in a complete analysis of a substance, it is decomposed with hot dilute HNO₃ and precipitated as PbMoO₄.

Galena is best decomposed by treating with hydrochloric acid to expel sulphur as oxidation of sulphur to sulphute is not desirable in this method. If lead sulphate has formed due to oxidation of sulphur, it is advisable to treat any residue, remaining from the acid extraction, with ammonium acetate, adding the acetate extract to the solution containing the lead.

The sample evaporated to dryness is treated with about 10 ec. of dilute nitric acid (1:1) and a little water then heated and filtered. About 2 grams of ammonium chloride are added and for each ee. of free nitric acid (d. 1.42) two grams of ammonium acctate are necessary (total 10-15 g.). The precipi-

tate generally appears a light eanary yellow or yellowish white.

Washing the precipitate with water containing a little ammonium nitrate prevents the formation of colloidal lead molybdate, which would pass through the filter paper. (Use about 2 g. nitrate per 100 ec.)

The pulp used is paper pulp made by breaking up ashless filter paper and agitating it thoroughly with hot water in a flask. The Editor prefers omitting the pulp and using a fine-grained ashless filter paper, the washing of the precipitate being conducted with wash water containing ammonium nitrate.

LEAD 275b

Electrolytic Determination of Lead as the Peroxide, PbO₂

An electric current passed through a solution of lead containing sufficient free nitric acid will deposit all the lead on the anode as lead peroxide. The method is excellent for analysis of lead alloys.

Procedure. The sample containing not over 0.5 gram lead is brought into solution by heating with dilute nitric acid, 1:1. The solution is washed into a large platinum dish with unpolished inner surface. Twenty to 25 cc. concentrated nitric acid (sp.gr. 1.4) are added and the solution diluted to about 150 cc.

The sample is electrolyzed in the cold with 0.5 to 1 ampere current and 2 to 2.5 volts, the platinum dish forming the anode of the circuit, a spiral platinum wire or a platinum crueible dipped into the solution being the cathode. Three hours are generally sufficient for the deposition of 0.5 gram Pb. Overnight is advisable, a current of 0.05 ampere being used.

A rapid deposition of the lead may be obtained by heating the solution to 60 to 65° C. and electrolyzing with a current $ND_{100} = 1.5$ to 1.7 amperes, the E.M.F. varying within wide limits. Stirring the solution with a rotating cathode aids in the rapid deposition of the PbO₂.

To ascertain whether all the lead has been removed from the solution, more water is added so as to cover a fresh portion of the dish with water. The electrolysis is complete if no fresh deposition of the peroxide takes place after half an hour.

The water is siphoned off while more water is being added until the acid is removed, the current is then broken, the dish emptied of water and the deposits dried at 180° C. and weighed as PbO₂.

The deposit of lead peroxide gently ignited forms lead oxide, PbO, a proeedure recommended by W. C. May, eonfirmed by Treadwell and Hall as giving more accurate results than the peroxide, PbO₂.

> $PbO_2 \times 0.8662 = Pb.$ $PbO \times 0.9283 = Pb.$

Note. The deposits of lead oxide or peroxide may be removed by dissolving off with warm dilute nitric acid.

For volumetric procedur e-titration of the peroxide PbO2 see page 278.

¹ Am. Jour. Sci. and Arts (3), 6, 255.

VOLUMETRIC METHODS

Volumetric Ferrocyanide Method for the Determination of Lead

Although the gravimetric methods for the determination of lead are considered the more accurate, yet the volumetric procedures may be frequently used with advantage. The ferrocyanide method has been pronounced by Irving C. Bull to be the best of the procedures in common use, the results being accurate.

Procedure. Lead sulphate is obtained according to the method outlined under Preparation and Solution of the Sample. The lead sulphate is transferred to a small beaker and gently boiled with 10 to 15 ee. of a saturated solution of ammonium carbonate, the liquid having been added cold and brought up to boiling. After cooling, the precipitate is filtered onto the original filter paper from which the lead sulphate was removed. The lead carbonate is washed free of alkali with cold water. The filter with the precipitate is dropped into a flask containing a hot mixture of 5 ee. of glacial acetic acid with 25 ee. of water. The lead carbonate is decomposed by boiling and the solution diluted to 150 cc.

Titration. The sample warmed to 60° C. is titrated with a standard solution of potassium ferroeyanide, using a saturated solution of uranium acetate. as an outside indicator. The excess of ferroeyanide produces a brown color with the uranium acetate drop on the tile.

Free ammonia must be absent, as it reacts with uranium acetate and gives low results. NH₄OH precipitates reddish brown, gelatinous uranous hydroxide, U(OH)₄.

The bulk of solution to be titrated should be as near as possible to 100 ee., including 10 ee. of 50% acetic acid.

One per cent potassium ferrocyanide reagent is used in the titration. This reagent is standardized against a known amount of lead in solution as an acetate.

A correction of 0.8 ee. is generally necessary on account of the indicator. This is determined by a blank titration.

Antimony, bismuth, barium, strontium and calcium interfere only to a very slight extent, the error being negligible.

¹C. N., 2253, 87, 1903,

The Permanganate Method for Lead

By ALBERT H. LOW

The following method for the determination of lead in ores has proved very satisfactory in the great majority of cases. It depends upon the separation of the lead as sulphate, the conversion of the sulphate to carbonate, the solution of the carbonate in acetic acid, followed by the precipitation of the lead as oxalate. The lead oxalate is then decomposed in dilute sulphuric acid and the separated oxalic acid titrated with standard permanganate.

Ordinary constituents of lead ores do not interfere, with the exception of lime. As high as 10% of CaO in an ore, however, is without effect. Barium interferes only by forming a combination with lead that resists the reactions, with consequent low

results. The remedy is easy and is described below.

Procedure. Decompose 0.5 gram of the orc in an 8-oz., pear-shaped flask, such as is commonly called a "copper-flask." The treatment may usually be a very gentle boiling with 10 cc. of hydrochloric acid for a short time, then adding 5 cc. of nitric acid and continuing the gentle boiling until decomposition is complete. Now add 6 cc. of sulphuric acid and boil over a free flame to strong fumes. Allow to cool.

Add 100 c.c of cold water and 5 ce. of sulphurie acid and heat to boiling. Remove from the heat, add 10 cc. of alcohol (cautiously) and cool under the tap.

Fold a 9-cm. filter with particular care to creasing the fold that will eome next to the precipitate as thin as possible, so it will lie flat and not easily allow material to get under the edge. Filter the mixture through this. Return the first portions of the filtrate if not clear. Wash 6 times with cold water containing 10% of alcohol. Any trace of lead sulphate remaining in the flask will be recovered subsequently.

With a jet of hot water, using as little as possible, rinse the precipitate from the filter, through a short funnel, back into the flask. (In the known or assumed presence of barium, interpolate the following short procedure: Add 10 ee. of hydrochlorie acid and boil over a free flame almost to dryness. Allow to cool, add 20 ee. of water and a few drops of ammonia, sufficient to neutralize the acid.) Place the flask again under the original funnel and pour through the filter 10 ec. of a cold saturated solution of ammonium carbonate. Remove the flask and heat the contents just to boiling, then cool completely under the tap. Pour the cold mixture through the original filter. Wash out the flask well with cold water, pouring through the filter, and then wash filter and precipitate 10 times with cold water containing about 5% of the ammonium earbonate solution. Reject the filtrate.

Again using a jet of hot water, wash the precipitate from the filter into a small beaker. Add 5-6 cc. of glacial acetic acid and heat to boiling. Replace the flask under the funnel and pour the hot acid mixture through the filter. Wash out the beaker with hot water and then wash the filter 10 times with hot water slightly acidulated with acetic acid. (Small amounts of lead earbonate may be dissolved directly upon the filter, without previous transference to a beaker.)

Add to the filtrate 10 ec. of a cold saturated solution of oxalic acid, heat to boiling and then cool completely under the tap. Be particular to get as cold as possible. Now filter the lead oxalate through a 9-cm. filter. Using cold water, wash out the flask thoroughly and then wash filter and precipitate 10 times.

277a LEAD

Place about 25 ec. of cold water in the flask, add 5-6 ec. of sulphuric acid and then about 100 ec. of hot water. Drop the filter and precipitate into this. Wipe out any lead oxalate adhering in the funnel with a small piece of dry filter paper and drop into the flask. Heat the acid mixture nearly to boiling and then titrate it with standard potassium permanganate solution to a faint pink tinge. Calculate the result from the known lead value of the permanganate.

The permanganate commonly used for iron titrations will serve, although rather strong for lead. Theoretically, 1.857 times the iron factor will give the lead factor. Owing to slight losses of lead an empirical factor must be used. This is 1.879 times the iron factor. Based on this factor and on 0.5 gram of ore taken for assay, 1 ee. of a permanganate solution containing 1.544 grams per liter will equal 1% lead. It may be standardized directly on lead as follows: Convert about 0.250 gram of pure lead foil to sulphate by boiling with 6 ee. of sulphuric neid. Continue according to the above entire process. Finally, divide the percentage value of the lead taken by the ee. of permanganate required, to obtain the percentage value of 1 ee. in lead. A comparison of this figure with the iron value of the permanganate may be made, to check the conversion factor given above. The personal equation may cause a slight difference.

Notes. Metallic lead is converted to lead sulphate by boiling with strong sulphuric acid. The reaction takes place with the hot concentrated acid, the metal changing to the white lead sulphate solid, soluble in large excess of sulphuric acid; this is unnecessary,

as decomposition is complete with the amount stated.

Conversion of lead sulphate to carbonate before changing to acetate appears at first thought to be an unnecessary step, but experience has shown that a direct conversion of sulphate to acetate by dissolving in ammonium acetate leaves sufficient sulphate in the solution to cause low results, as much as 10 per cent of lead apparently escaping subsequent conversion to oxalate. In the procedure for converting the lead to carbonate nuy smull amount of lead sulphate remaining does no harm. It frequently occurs that the enrhonate formed does not completely dissolve in acetic acid. If a cloudy solution is obtained, n few drops of ammonia will furnish enough ammonium acetate to dissolve the small amount of sulphate remaining. The precipitation of lead oxalate is not interfered with by the ammonium salt present, a large amount of which, however, should be avoided. Ammonium oxalate may be added in place of oxalic acid.

however, should be avoided. Ammonium oxalate may be added in place of oxalic acid. In the molybdate method, the procedure given for the permanganate method may be followed to the point where the oxalate or oxalic acid is added. This step is omitted and the lead acctate solution is titrated with aumonium molybdate as directed under

this procedure.

LEAD 277b

Volumetric Determination of Lead by the Molybdate Method

Lead is precipitated from an acetic acid solution by a standard solution of ammonium molybdate, the termination of the reaction being recognized by the yellow color produced by the excess of reagent when a drop of the mixture comes in contact with a drop of tannin solution, used as an outside indicator. The method is rapid, but is not as accurate as the chromate-iodide method following.

Reagents

Ammonium Molybdate. 4.26 grams of the salt are dissolved in water and diluted to 1000 cc. On a half gram sample basis 1 cc. of the reagent is equivalent to about 1 per cent lead.

Standardization. Dissolve 0.2 g. of pure lead foil in 5 cc. of strong sulphuric acid by boiling gently in a 250-cc. pear-shaped flask. When the lead has decomposed to sulphate, dilute (on cooling) with water and filter off the PbSO₄. Now follow the details of the procedure used in the method given below, after isolating the lead as sulphate. Note the cc. of molybdate reagent required and divided this into 0.2 to get the equivalent value in terms of lead per ce. of reagent. 1 ce. should be equivalent, approximately, to 0.005 g. Pb.

Tannin Indicator. 0.1 g. tannic acid per 20 ec. water. The reagent should be prepared fresh for each day's analysis.

Procedure

Decomposition. Follow the usual procedure recommended for decomposing lead ores, using HCl, HNO₃ and finally H₂SO₄. Evaporate to strong sulphuric fumes, and take up with water. Filter off the lead sulphate and wash with a 10 per cent sulphuric acid solution, to remove sulphates of the metals, and finally with water containing a little alcohol, remembering the PbSO₄ is slightly soluble in water.

The lead sulphate is now brought into solution as lead acetate by extraction with ammonium acetate slightly acidified with acetic acid. (Use a strong solution of the reagent.) In absence of calcium and barium, the writer prefers to convert the lead sulphate to carbonate by boiling with ammonium carbonate solution, according to the permanganate method for lead (p. 277), and then to the acetate by dissolving the lead carbonate in dilute acetic acid. Thus sulphates are eliminated. The addition of a few drops of ammonia to the acetic acid solution insures the solubility of the lead. (PbSO₄ may be present in small amount and does not readily dissolve in acetic acid.) The results are more concordant in absence of sulphate. The acetate solution of lead is now titrated with the standard molybdic solution.

Titration. The solution is divided into two portions, one being kept in reserve. To one is added the standard solution of ammonium molybdate, from a burette, until a drop of the titrated solution, brought in contact with a drop of tannin indicator, on a white tile, or paraffined surface, gives a brown or yellow color. The reserve solution is now added in portions, the titration being continued, until the last portion has been used and the brown color obtained. This precaution avoids over running the end point.

The Chromate-lodide Method for the Volumetric Determination of Lead

The method depends upon the action of chromates on potassium iodide with a resulting liberation of an amount of free iodine in direct ratio to the chromate present, which in turn is a measure of the amount of lead isolated as lead chromate. The liberated iodine is determined by titration with a standard solution of thiosulphate. The discussion of the reactions that take place, with equations, are given in the notes that follow the directions of the method.

Solutions Required

Ammonium Acetate Extraction Solution. A saturated solution of ammonium acetate, filtered to remove foreign matter if present, is diluted with twice its volume of distilled water and 30 cc. of 80 per cent acetic acid is added per liter of solution.

Hydrochloric Acid Mixture. To a liter of saturated salt solution, filtered if necessary, is added 150 cc. of distilled water and 100 ec. of concentrated hydrochloric acid.

Potassium Dichromate. Saturated solution, filtered if not clear. Starch Solution.

Procedure. 1. Solution of the Sample. Half a gram of the finely divided material (if the factor weight 0.6907 g. is taken, 1 cc. N/10 reagent in final titration is equivalent to about 1% Pb) is dissolved in a beaker or a flask (Low's type) by adding 20 cc. of strong hydrochloric acid and heating gently until the action subsides. If the decomposition is incomplete, about 5 cc. of nitric acid are added and the heating continued.

- 2. About 5 ec. of sulpluric acid are added and the solution evaporated to strong fumes. After cooling, about 50 cc. of water are added and the solution is boiled to dissolve the soluble salts. If the ore is low grade, 5-10 cc. of ethyl alcohol are now added, the precipitate is allowed to settle and then washed by decantation three or four times with 1:15 sulphuric acid (i.e., about 10% solution), and finally transferred to the filter with the dilute acid and washed once with pure cold water.
- 3. By means of a fine jet from a wash bottle (500 ec.) filled with ammonium acetate extraction reagent, heated to near boiling, the precipitate is transferred to the beaker or flask in which the precipitation was made. This may be done by carefully spreading out the filter in the funnel or by breaking the filter and washing the paper free of the lead sulphate with a fine stream of the reagent. If the precipitate does not go into solution, more of the acetate is added and heat gently applied until it dissolves. The solution is now diluted to 150 cc., heated to boiling and 10 cc. of the saturated dichromate solution added and the boiling continued ten minutes. The yellow color of the lead chromate precipitate changes to red. This is important to obtain a precipitate of definite composition.
- 4. The precipitate is filtered, the containing vessel washed out with hot dilute sodium acetate wash solution (50 cc. of the extraction solution diluted to 1000 cc.) and the precipitate washed ten times with the reagent.
- 5. The original beaker or flask is now placed under the funnel and the lead chromate is dissolved on the filter by adding cold dilute nydrochloric acid mixture, stirring up the precipitate with a jet of the reagent, adding the

LEAD 278a

acid until all of the chromate has dissolved and the color has been completely removed from the filter. At least 50 ec. of the reagent should be used.

6. For low grade ores the entire solution is taken and treated with potassium iodide solution; in ease of high grade ores, about half the solution is set aside in reserve, and upon completing the titration of the first portion, the reserve is added and the titration completed. This precaution is taken because a loss of iodine is apt to occur if much iodine is liberated at one time, free iodine being apt to escape as vapor from the easily saturated solution. (The solution is a poor solvent of iodine.) To the solution are added 5 ee. of 25% potassium iodide and the liberated iodine is titrated with N/10 sodium thiosulphate until the iodine color begins to fade; starch solution is now added in sufficient quantity to produce a distinct blue color and the titration continued until the blue color changes to pale green.

A background of white assists in recognition of the end-point. A sheet of white paper placed under the beaker will do, if the base of the stand is

not already white.

Standardization of the Thiosulphate. This is best standardized against metallic lead. 0.6907 gram of pure lead should require 100 ec. of N/10 thiosulphate. 0.2 gram of lead is taken or a fraction of the factor weight (0.6907). The lead foil is dissolved in 5 ec. of sulphuric acid by bringing to vigorous boiling, upon cooling the residue is taken up with water and treated exactly according to the method outlined in steps 2-6 of the regular procedure. 1 ec. of N/10 thiosulphate is equivalent approximately to 0.0069 gram of lead.

Notes. If barium is present in the sample, the residue left from the acetate extraction may contain lead. This is treated with about 10 cc. of strong hydrochloric acid, evaporated to dryness, 25 cc. of the acetate reagent added, the mixture boiled, filtered and the residue washed. The filtrate contains the lead that remained with the residue.

In considering the reactions that take place it must be remembered that it is the combined chromate radical that is responsible for the liberated iodine. The graph-jcal formula represents what takes place:

$$2PbCrO_4$$
 (or $(PbO)_2.Cr_2O_4.3O) + 6KI = 3K_2O + 6I$, etc.

The chromate first formed is probably the normal salt PbCrO₄; this however is unstable and changes with boiling to a stable acid chromate of lead under the conditions of the procedure, hence 4 the atomic weight of lead does not give the exact normal equivalent but the true value is an arbitrary factor, obtained by standardizing the thiosulphate against metallic lead as recommended.

It is evident that Ph is equivalent to 3I. Therefore a normal equivalent of Ph is 3 of its atomic weight, 207.2 divided by 3=69.07, hence 1 cc. of a N/10 solution will

titrate iodine equivalent to .006907 g. Pb.

Since Fe equivalent is 55.84, Fe to Pb = 69.07 divided by 55.84 = 1.237, factor of iron to lead.

Example in Standardization of Sodium Thlosulphate

If 0.2035 g. of lead required 30.05 ee. of thiosulphate solution, then 1 ee. would be equivalent to 0.00677 g. lead.

278b LEAD

Volumetric Chromate-Ferrous-Diphenylamine Method for Determining Lead

The procedure depends upon isolating lead as chromate and titrating hexavalent chromium with standard ferrous salt after dissolving lead chromate in hydrochloric acid. As in the chromate-iodide method reduction of chromium from hexavalent to trivalent form makes the lead equivalent $\frac{1}{3}$ its atomic weight.

Reactions PbCrO₄+2HCl→PbCl₂+H₂CrO₄ H₂CrO₄+3FeCl₂+6HCl→CrCl₃+3FeCl₃+4H₂O,

Reagents-Ferrous Salt Solution. 0.1 N solution of ferrous ammonium sulphate or ferrous sulphate.

Potassium Dichromate or Permanganate—0.1 N solution.

Phosphoric-Sulphuric Acid. 1 volume 85% H₃PO₄ mixed with 1 volume H₂SO₄ (sp.gr. 1.84).

Diphenylamine Indicator. 1 gram of salt dissolved in 100 cc. strong sulphuric acid.

Hydrochloric-Salt Solution. See under Procedure.

Procedure

Decomposition of Sample. The ore is dissolved in HCl and HNO₃ according to standard procedure for lead ores. Alloys are treated with HNO₃. H₂SO₄ is now added and the HCl and HNO₃ expelled by taking to sulphuric acid fumes. Pure lead is decomposed by direct treatment with strong H₂SO₄ and heating. The residue is treated with water and a little alcohol and the lead sulphate filtered off and washed with 10% alcohol solution. The lead sulphate is now dissolved in a saturated solution of ammonium or sodium acetate slightly acidified with acetic acid. The extract is diluted to about 150–200 cc. with water and lead precipitated as chromate (PbCrO₄) by addition of a saturated solution of potassium dichromate (10–15 cc. is ample).

Lead Chromate. The crystalline product is obtained by boiling the precipitate until the yellow color changes to orange red. After cooling under tap water, the precipitate is filtered and washed with a 5% solution of ammonium acetate, until free from the excess of chromate reagent (the wash water

passing through the precipitate colorless).

Solution and Titration. The lead chromate is now dissolved by adding hydrochloric acid-sait solution (a mixture of 1000 cc. saturated solution of NaCl, 120 cc. H₂O and 100 cc. H(1), d. 1.19), 50 to 100 cc. being used. All yellow color being washed from the filter. The chromate solution is diluted to 150-200 cc., 10 cc. phosphoric-sulphuric acid mixture added and 4-6 drops of diphenylamine indicator. The 0.1 N ferrous solution is now added until the color of the chromate changes to green. The excess of ferrous solution is determined by titration with standard dichromate or permanganate, the green color changing to a deep blue.

1 ce. of 0.1 N ferrous solution is equivalent to 0.0069 g. Pb.

Notes. In presence of a large amount of HCl the end point is a change of green to a dark green. The action of HCl may be overcome by adding 1 g. ammonium accetate for each cc. HCl present, the end point is now the characteristic blue mentioned under Procedure.

DETERMINATION OF SMALL AMOUNTS OF LEAD

The determination of minute quantities of lead is required in baking powders canned goods and like products in which small amounts of lead are objectionable. Traces of lead ranging from 5 to 100 parts per nullion (0.0005 to 0.01% Pb) are best determined colorimetrically on 0.5 to 1 gram samples; larger amounts of lead should be determined gravimetrically.

Gravimetric Methods for Determining Traces of Lead

The determination of extremely small amounts of lead cannot be accomplished by the usual methods of precipitation, as the lead compounds remain in solution in a colloidal state. The addition, however, of certain substances, which form amorphous precipitates with the reagents used for throwing out lead causes the removal of lead from the solution by occlusion. For example, the addition of a sufficient quantity of a soluble salt of mercury, copper, or arsenie to a solution containing a trace of lead, and then saturating the solution with H₂S, will cause the complete removal of lead from the solution. Iron and alumina thrown out of the solution as hydroxides will carry down small amounts of lead, and completely remove it from the solution, if they are present in sufficient quantity. Lead may be extracted from finely pulverized substances by means of hot ammonium acetate and precipitated from the extract as lead sulphide. Advantage may be taken of these facts in determining traces of lead in presence of large amounts of other substances.

Amount of the Sample. It is advisable to have the final isolated lead compound over 0.01 gram in weight, hence, in a sample containing 10 parts of lead per million, 800 to 1000 grams of the material should be taken, since a kilogram of the material would contain 0.01 gram, Pb or 0.0156 gram PbCrO₄, or 0.01464 gram PbSO₄, or 0.0177+ gram PbMoO₄. Large samples should be divided into several portions of 100 to 250 grams each, the lead isolated in each, and the final extracts, containing the lead, combined. For the given amount of occluding agent, stated in the procedure, the treated portion should contain not over 0.01 gram lead.

I.—Extraction of Lead with Ammonium Acetate and Subsequent Precipitation

It is frequently desirable to extract the lead from the mass of material and precipitate it from the liquor thus obtained. The procedure worked out by the writer is applicable to determining traces of lead in aluminum salts, but with modifications may be applied to a wide range of substances.

Extraction of Lead. The desired weight of finely powdered substance, in 100-grain portions, is placed in 6-inch porcelain casseroles (1000 ce. capacity). To each portion are added, with vigorous stirring, 500 cc. of lead-free, boiling hot ammonium acctate solution (33%). The reaction is apt to be energetic, so that

¹ The reagent must be boiling, when added, to obtain best results. Experiments have shown that considerable alumina and iron dissolve if the proportion of the reagent falls much below 5 cc. of 33% acctate per gram of sample. With twice this amount of reagent the extract is free from iron and alumina. Small amounts of alumina and iron, however, do not interfere in the lead determination.

eare must be exercised to avoid boiling over. The residue from aluminum salts is crystalline and may be separated from the extract very readily by fill ering through two filter papers in a large Büelmer funnel and applying sue ion. The residue is tamped down to squeeze out the adhering extract and washed with 100 cc. more of hot ammonium acetate followed by 100 to 200 cc. of hot water, again tamped down and sucked as dry as possible. The lead extracts are now combined and lead precipitated as sulphide.

The reagent is made by dissolving one part of lead-free ammonium acetate in two parts of distilled water. The purity of the reagent should be tested.

Precipitation of Small Amounts of Lead. To the solution containing lead is added 2–3 ee. of a 10% copper sulphate or cadmium sulphate reagent. Hydrogen sulphide is passed into the liquor until it is saturated. The copper or cadmium sulphide assists the settling of lead sulphide. Gently warming on the steam bath for half an hour congulates the precipitate and facilitates settling. The liquor is decanted through a double filter in a small Büchner funnel and the residue washed onto the filter with water saturated with H_2S gas.

The precipitate is washed several times with animonium sulphide to remove sulphides of the arsenic group and the residue then dissolved in a hot mixture of hydrochloric and nitric acids (I part HCl₂ 5 parts HNO₃ and 15 parts H₂O). Ten ec. of strong sulphuric acid are added to the solution, and the mixture is evaporated to SO₃ funes but not to dryness. The residue is taken up with 100-125 ec. of water containing 2 cc. of sulphuric acid and boiled to dissolve the soluble salts of iron, alumina, copper, etc. After cooling, one-third the volume of 95% alcohol is added (30-40 ec.), the lead sulphate allowed to settle for an hour or more, then filtered and washed several times with 30% alcohol. The residue is extracted with hot ammonium acctate and lead chromate precipitated from the filtrate, and slightly acid with acetic acid, by adding 10 cc. of potassium dichromate reagent and boiling, according to the standard procedure. (Page 274.)

$PbCrO_4 \times 0.641 = Pb.$

II.—Precipitation of Lead by Occlusion with Iron Hydroxide

Wilkie found that ferrie hydroxide has the property of occluding lead, five parts of Fe(OII), removing one part of lead from solution. Advantage is taken of this property of iron hydroxide in precipitating small amounts of lead.

Procedure. The required amount of material is weighed out in 50-gram lots and brushed into No. 8 beakers. If the material contains organic matter, it is treated with 200-cc. portions of concentrated hydrochloric acid, the mixture heated just below the boiling-point of HCl solution, and potassium chlorate added, a few crystals at a time, until the organic matter is decomposed (hood). If the material dissolves in water, the water solution is treated with 5 cc. of concentrated hydrochloric acid and a few crystals of potassium chlorate and the liquor boiled.

¹ 200 to 300 grams of material may be handled in a 6-inch Büehner funnel.

¹ J. M. Wilkie C. N., 2597, 117, 1909.

Occlusion of lead by zine sulphide, precipitated by H₂S from a formic acid solution, is suggested; iron and alumina would not interfere.

³ Should lead chromate fail to precipitate, the solution should be treated with H_SS to complete saturation, the sulphide collected on a filter, then dissolved in acid and the procedure described above repeated. If the solution still remains clear, the absence of lead is confirmed.

Addition of Ferric Iron. If sufficient iron is not already present, ferric chloride is added in such quantity that the iron content of the sample will be from twenty to fifty times that of the lead (larger amounts of iron will do no harm) present in the solution. Five to 10 cc. of concentrated nitric acid are added and the sample boiled for ten to fifteen minutes.

Precipitation of Iron and Lead. If alumina is present, iron is precipitated by addition of a large excess of potassium hydroxide, the alumina going into solution as potassium aluminate. In absence of alumina, ammonia may be used to precipitate the ferric hydroxide. Lead is completely occluded by the precipitate and carried down. The solution is filtered hot through Baker and Adamson's fast filters, threefold. The filtering must be rapid and the liquid kept hot to prevent clogging of the filters.

Separation of Lead from Iron. The precipitate is dissolved in hot hydrochloric acid (free from lead). The solutions are combined, if several portions of the sample are taken. Concentrated sulphuric acid is added and the sample evaporated to small volume and heated until the white sulphuric acid fumes appear. The usual procedure is now followed for separation of the lead sulphate, acetate extraction of lead and final precipitation of lead chromate.

$$PbCrO_4 \times 0.641 = Pb$$

Note. In place of using alcohol to decrease the solubility of lead sulphate, many prefer to add sulphuric acid so that the acidity of the solution will be 2--10% free H_2SO_4 .

III. Modification of Seeker-Clayton Method for Traces of Lead in Baking Powder

One hundred grams of baking powder are treated with 25 ec. of water followed by 75 ee. of strong hydrochloric acid added in small portions to avoid excess frothing. The mixture is heated until the starch has decomposed (iodine test gives blue color with starch), the solution becoming clear and turning yellow. The free acid is neutralized and when the solution is cold, 400 ec. of lead-free ammonium citrate, saturated with H₂S, are added. Additional H₂S is passed into the slightly alkaline solution, the sulphides of iron and lead allowed to settle, the clear supernatant liquor decanted off, the sulphides collected on a filter and washed. The precipitate is dissolved in nitric acid, lead separated as a sulphate, extracted with acetate and precipitated as dichromate according to the procedure recommended under the acetate extraction method I.

COLORIMETRIC ESTIMATION OF SMALL AMOUNTS OF LEAD

Introduction. Estimation of small amounts of lead by the intensity of the brown coloration produced by the sulphide in colloidal solution was first proposed by Pelouze. The procedure was modified by Warington and by Wilkie to overcome the color produced by accompanying impurities, among these, of iron, which is almost invariably associated with lead. The method is useful in determining traces of lead in drinking water, in food products, baking powders, canned goods, phosphates, aluns, acids such as sulphuric, hydrochloric, citric, tartaric and the like. By this procedure on a grain imple one part of lead per million may be detected and as high as 50 parts may be estimated. For larger amounts of lead, a smaller sample must be taken. Nickel, arsenic, antimony, silver, zine, tin, iron, and alumina, present in amounts such as commonly occur in these materials, do not interfere.

In order to obtain accurate results it is necessary to have the solutions under comparison possess the same general character. "It must be remembered that the tint depends to a large extent on the size of the colloidal particles of lead, which in turn depend upon the nature of the salts in the solution and upon the way that the solution has been prepared." Vigorous agitation, salts of the alkalies and alkaline earths tend to coagulate the colloidal sulphide.

Reagents Required. Standard Lead Solution. A convenient solution may be made by dissolving 0.1831 gram of lead acetate, Pb(C₂H₂O₂)₂·3H₂O in 100 cc. of water, clearing may cloudiness with a few drops of acetic acid and diluting to 1000 cc. If 10 cc. of this solution is diluted to 1000 cc. each cc. will contain an equivalent of 0.000001 gram Pb.

Harcourt suggests a permanent standard made by mixing ferric, copper and cobalt salts. For example 12 grams of FeCl, together with 8 grams of CuCl, and 4 grams of Co(NO₂), are dissolved in water, 400 cc. of hydrochloric acid added and the solution diluted to 4000 cc. 150 ee. of this solution together with 115 cc. of hydrochloric acid (1:2) diluted to 2000 ec. will give a shade comparable to that produced by the standard lead solution above, when treated with the sulphide reagent. The exact value per cc. may be obtained by comparison with the lead standard.

Alkaline Tartrate Solution. Twenty-five grams of C.P. sodium potassium tartrate, NaKC₄H₄O₄·4H₂O, is dissolved in 50 ee. of water. A little ammonia is added and then sodium sulphido solution. After settling some time the reagent is filtered. The filtrate is acidified with hydrochloric acid, boiled free of H₂S and again made ammoniacal and diluted to 100 ec.

Ammonium Citrate Solution. Annuonium citrate solution is prepared in the same way as the tartrate solution abovo, 25 grams of the salt being dissolved in 50 cc. of water.

Potassium Cyanide. Ten per cent solution. The salt should be lead-free. Sodium Sulphide. Ten per cent solution, made from colorless crystals. Sodium sulphide may be made by saturating a strong solution of sodium hydroxide with hydrogen sulphide gas, and then adding an equal volume of the sodium hydroxide. The solution is diluted to required volume, allowed to stand several days, and filtered.

Sodium metabisulphite. Solid salt of Na,S,O.

Apparatus. The color comparison may be made in Nessler tubes, or in a colorimeter. The Campbell and Hurley modification of the Kennicott-Sargent eolorimeter is excellent for this purpose, Fig. 43. The colorimeter is simple in construction and operation.

The tubes for holding the solutions to be compared are those of one of the well-known coloruneters, in which the unknown solution is placed in the left-hand

tube while the color is matched by raising or lowering the level of a standard solution in the right-hand tube by means of a glass plunger working in an attached reservoir.

The accompanying diagram shows the essential features of construction of the eolorimeter employed in the tests described below. The unknown solution is placed in the left-hand tube A, which is 19 cm. long, 3 cm. in diameter, and graduated for 15 cm. The standard solution is placed in the right-hand tube B, which is the same size as A, the graduated portion being divided into 100 divisions of 1.5 mm. each. The tube B is permanently connected by a glass tube with the reservoir C in which the glass plunger D works, so that the level of the liquid in B can be readily controlled by raising or lowering the plunger. As the tube B and reservoir C are made in one piece, the liquid used for the standard solution comes in contact with glass only, thus preventing any possibility of




Fig. 43.—Hurley's Colorimeter.

chemical change due to contaet with the container. The plunger is provided with a rubber collar E, so placed as to prevent the plunger from accidentally striking and breaking the bottom of the reservoir. The tubes A and B, with the connecting reservoir, rest on wooden supports, the one under A and B being provided with holes for the passage of the light, and are held in position by spring clips F. This arrangement allows the glass parts to be readily removed for cleaning and filling. The light for illuminating the solution is reflected upward through the tubes A and B by means of the adjustable mirror G. The best results are obtained by facing the colorimeter toward a north window in order to get reflected skylight through the tubes, care being taken to avoid light reflected from adjacent objects. The black wooden back of the colorimeter serves the double purpose of a support for the parts of the instrument and of a screen, as it is interposed between the color tubes and the source of light.

The light, passing upward through the tubes A and B, impinges on the two mirrors H and I cemented to brass plates sliding in grooves cut at an angle of 45° in the sides of the wooden box J. This box is supplied with a loosely-fitting cover, thus allowing easy access for the purpose of removing and cleaning the

¹Jour. Am. Chem. Soc., **33**, 1112, July, 1911.

mirrors. The mirror H is cut vertically and commented in such a position as to reflect one-half of the circular field of light coming through the tube A. The light passing upward through B is reflected horizontally by the mirror I, through a hole in the brass plate supporting the mirror H. One-half of the circular field of light from the tube B is cut off by the mirror H, the vertical edge of which acts as a dividing line between the two halves of the circular field. The image of one-half of the tube B is then observed in juxtaposition to the opposite half of the image of the tube A.

The juxtaposed images are observed through a tube K, 2.5 cm. in diameter and 16 cm. long, lined with black felt and provided with an eye-piece having a hole 1.5 mm. in diameter. At the point M in the tube K is placed a diaphragm having an aperture 8 mm. in diameter. All parts inside the box J except the mirrors are painted black so that no light except that coming through the tubes A and B passes through the tube K. By having the apertures in the eye-piece and diaphragm properly proportioned only the image of the bottoms of the tubes A and B can be seen, thus preventing interference of light reflected from the vertical sides of the tubes A and B.

A person looking through the eye-piece observes a single circular field divided vertically by an almost imperceptible line when the two solutions are of the same intensity. By manipulating the plunger D, the level of the liquid in B can be easily raised or lowered, thus causing the right half of the image to assume a darker or lighter shade at will. In matching colors with an ascending column in B, that is, gradually deepening the color of the right half of the field, the usual tendency is to stop a little below the true reading while in a comparison with a descending column the opposite is the case.

Procedure. If lead is between 10 to 50 parts per million a I-gram sample is taken. If it is above or below these extremes the amount of sample is regulated accordingly. In materials containing organic matter it is not advisable to take more than a I-gram sample.

Substances containing organic matter, such as starch in baking powder, should be decomposed by fusion with sodium peroxide, sodium or potassium sulphate containing a few drops of sulphuric acid. A Kjeldahl digestion with concentrated sulphuric acid and potassium bisulphate may occasionally be advisable. Sulphuric acid discolored by organic matter should be mixed with 4 to 5 grams of potassium bisulphate, taken to fumes and then diluted with water. The material may be extracted with ammonium acetate and lead determined in the extract. See notes.

To the solution containing the sample are added 10 cc. of tartrate solution (or 20 cc. of citrate solution with phosphates of line, ctc.), 10 cc. of hydrochloric acid and the mixture brought to boiling. Small amounts of ferric iron are now reduced by adding 0.5 gram sodium metabisulphite. Sufficient ammonium hydroxide is added to neutralize the free acid and 5 cc. in excess; then 3 cc. potassium cyanide (to repress any copper color that may be present to reduce higher oxides), and the mixture heated until the solution becomes colorless. The entire solution or an aliquot portion is placed in the comparison cylinder, and diluted to nearly 100 cc. If the Kennicott-Sargent apparatus is used the standard color solution is forced into the adjacent cylinder, until the color in this cylinder matches the one containing the sample. The number of cc. of the standard is noted. This blank is due to the slight color that the solutions of the samples invariably have. Four drops of the sulphide reagent are added to the sample and this is mixed

by means of a plunger, avoiding any more agitation than is absolutely necessary to make the solution homogeneous. After one minute the comparison is again made, the colored standard being forced into the cylinder until its color matches the sample. It is advisable to take several readings with ascending and descending column of standard reagent, taking the average as the true reading.

Calculation. Suppose the standard =0.000001 grain Pb per cc., blank =5 ee., total reading =22 cc., one grain of sample being taken for analysis. Then 22-5=17 cc. =0.0017% Pb or 17 parts per million.

Notes. Iron must be completely reduced before adding ammonium hydroxide and potassium evanide.

Allen's method of reducing iron with so lium metabisulphite is excellent. The salt may be made by passing 80, into a saturated solution of sodium carbonate at boiling temperature, until the liquor is just acid to methyl orange. The water evaporated during the treatment is replaced during the action. Na₂S₂O₄ separates and may be filtered off and the water removed by centrifuging.




Fig. 44.--Cooper Hewitt Mercury Light.

The Cooper Hewitt Mercury light is excellent for colorimetric lead determinations, where an artificial light is desired. The yellow shades appear yellowishgreen and may be matched more readily than the yellows obtained by daylight.

The illustration, Fig. 44, shows the type of light recommended for this work.

If a separation from iron is desired, the lead may be extracted with ammonium acetate solution. Ten grams of the powdered material are mixed with 75 ce. of a 33% ammonium acetate solution 1 (25 grams of the salt dissolved in 50 cc. H₂O), the reagent being added boiling hot. The mixture is diluted to 500 cc., a portion filtered, and the determination made on an aliquot part of the total, following the directions above.

Notes. Nickel up to 0.1%, arsenic up to 0.2%, zinc 0.2%, antimony 0.05%, copper 0.25%, iron up to 1.0%, aluminum 10%, tin up to 1.4% do not interfere with the colorimetric determination of lead.

¹ The ammonium acetate should be free from lead.

STANDARD METHODS OF CHEMICAL ANALYSIS OF PIG LEAD 1

A. Determination of Silver

Weigh 100 grams of the sample into a 3-inch scorifier and heat in a muffle furnace until the assay "covers." Pour into an iron mold and allow to cool. Free the resulting lead button from PbO, scorify again and pour as before. The button last obtained should not weigh over 20 grams and can be cupelled directly. Weigh the silver button obtained upon an assay balance.

Note. If the amount of silver is large, the button should be examined for gold, in the usual manner.

B. Determination of Bismuth

Solutions Required

Sodium Carbonate. Dissolve 100 grams Na₂CO₃ in a liter of distilled water.

Ammonium Carbonate. Make a half saturated solution.

Alkaline Sulphide Wash Solution. Dissolve 200 grams of KOH in a liter of distilled water and mix one part of this solution with 4 parts of H₂S water.

Method

- (a) Determination for Ordinary Amounts of Bismuth. Dissolve 20 grams of the sample in a 400-cc. beaker with 100 cc. of HNO3 (1:4), with the aid of heat. When solution is complete, add dilute ammonia (1:2) with constant stirring, drop by drop from a burette, until a faint opalescence appears. If an actual precipitate is formed, redissolve by the addition of a small amount of IINO3 (1:4) and repeat the addition of ammonia. Now add 5 cc. of HCl (1:9), fill the beaker with hot water, bring to boiling, and allow to stand on a steam bath for two hours. The assay, while standing, must not reach the boiling temperature. Filter through a 7-cm. paper. Transfer the precipitate completely to the paper by means of a "policeman" and wash twice with hot water. Carefully examine the filtrate, washings, and any decanted liquid and reject if clear. Dissolve the precipitate by dropping around the edges, from a 5-ec. pipette, 5 cc. of boiling HCl (1:9), receiving the solution in the original beaker. Wash the paper thoroughly with hot water, fill the beaker with water, bring to boiling, and allow to stand as before. Filter the bismuth oxychloride upon a weighed Gooch crucible, wash thoroughly with water, once with alcohol, once with ether, and dry upon the hot plate. Cool and weigh.
- Note. If time permits, it is convenient to allow the assay to stand over night. In that case, the precipitate of bismuth oxychloride generally settles so completely that the clear supernatant solution can be decanted.
- (b) Determination for Amounts of Bismuth Smaller Than Can Be Determined by (a). Dissolve 100 grams of the sample in 500 ee, of dilute HNO₃ (1:4). When solution is complete, allow to cool and add Na₂CO₃ solution little by little until a slight permanent precipitate has formed. Then add 50 ee, of the Na₂CO₃ solution, bring to boiling, allow to stand warm until the
- ¹ Reprinted by permission from the 1921 Book of the A. S. T. M. Standards of the American Society for Testing Materials.

supernatant liquor is clear again, filter and reject the filtrate. Dissolve the precipitate without washing by slowly pouring hot HNO₂ (1:4) around the edges of the filter paper, using no more acid than necessary. Wash the paper once with hot water and determine bismuth in the filtrate as described in (a).

Note. When the sample contains a small amount of bismuth, it is often difficult to ascertain when the correct amount of ammonia has been added to the nitrate solution. In this case, place a small piece of litmus paper in the solution and add the ammonia very gradually until the litmus paper indicates a neutral reaction.

(c) Determination of Bismuth in Samples Containing Appreciable Amounts of Tin and Antimony. Use a piece of litmus paper as in Note under (b), and after the first precipitation of bismuth oxychloride has been filtered off and washed (see (a)), proceed as follows: Dissolve the bismuth by dropping around the edges of the paper 10 ce. of boiling HCl (1:2), receiving the solution in the original beaker. Discard the paper after washing. Dilute the solution to about 200 ec. with fresh H₂S water and then pass H₂S gas through the hot solution for fifteen minutes. Filter and wash with hot water. Remove any tin or antimony present by washing three times with alkaline sulphide wash solution. Wash the precipitate again with hot water, place it, together with the filter paper, in a 100-ce. beaker, add 20 cc. of HNO₃ (1:4), boil until sulphides are completely dissolved and the paper well pulped. Filter the solution, receiving the filtrate in the original beaker, and wash well. Determine bismuth in the filtrate as in (a).

Notes. When the sample contains comparatively large amounts of tin or antimony, the residue left after the solution of the lead in the nitric acid obscures the opalescence found upon the addition of ammonia.

If the original sample contains more than 0.25 per cent of bismuth, it is preferable

to use only a 10-gram charge.

C. Determination of Arsenic

Method

Dissolve 111.11 grams of the sample in 550 cc. of HNO₃ (1:4). When solution is complete, wash into a graduated liter flask. Add 75 cc. of H₂SO₄ (1:1), cool, and make up to the mark with water. Transfer to a large beaker, rinsing out the flask with 25 cc. of water. Mix thoroughly, allow to settle and filter off 900 cc., equivalent to a 100-gram charge. Evaporate in a large porcelain dish until only enough H₂SO₄ is left to moisten the residue. When cool, wash into a small distilling flask with 60 cc. of HCl (specific gravity 1.20) and 20 cc. of water, cleaning the dish carefully. Add 10 grams of ferrous sulphate and distill, boiling to as small volume as possible. When cool, add 50 cc. more HCl (specific gravity 1.20) and redistill. Pass H₂S gas through the cold distillate for 45 minutes. Filter, and weigh the As₂S₃ on a Gooch crucible, washing in cold water, alcohol and CS₂. After drying and weighing, redissolve with (NH₄)₂CO₃ solution and reweigh the Gooch crucible, calculating the loss in weight to arsenic.

Note. The 25 ec. of water added is equivalent to the volume of precipitated lead sulphate.

D. Determination of Remaining Metals

Solutions Required

Tartaric Acid. Dissolve 50 grams of tartaric acid in 250 ec. of distilled water to which has been added 250 ec. HCl (specific gravity 1.20).

Method

Dissolve 222.23 grams of the sample in 1100 ec. of HNO₃ (1:4), using a 1300-ce. beaker. When solution is complete, examine for color and turbidity. If clear, wash the solution at once into a 2000-cc. graduated flask. In case of a residue (Note 1), however, dilute to about 1100 cc. and allow to stand until the supernatant liquor is clear. Decant as much as possible into a 2000-ce. flask, filter the remainder and receive the filtrate in the same flask. Wash the precipitate well and then place it, together with the filter paper, in a 100-cc, beaker and add 20 cc, of the tartaric acid mixture. Heat to boiling and when the paper is well pulped allow to digest warm for 30 minutes. Now add 50 cc. of hot water, filter and wash. (Note 2.) Carefully dry the residue and ignite. If any appreciable residue remains, brush it into a small silver dish containing 1 gram of molten KOH. Fuse for 5 minutes, and after cooling dissolve in as little hot water as possible and add to the above-mentioned tartaric acid filtrate. Render this solution just alkaline with ammonia and then just acid with HCl, and saturate hot with H2S gas. After digesting for 30 minutes on the steam bath, pass H2S through the solution again for 15 minutes. Filter and wash with slightly acidified H2S water. Reject the filtrate. Wash the sulphides from the paper into the original beaker and add 5 cc. of KOH solution (1:5) for every 25 cc. volume present. Digest hot for 5 minutes and filter through the original paper into a small flask graduated to 110 cc. After washing with H2S water containing a little of the KOH solution, cool the liltrate and make up to the mark. Mix and reserve 100 cc. as alkaline sulphide solution No. 1. The precipitate may be discarded.

Add slowly to the main solution in the 2000-cc. flask 150 cc. of H2SO4 (1:1). After cooling and filling up to the mark, pour into a clean 3-liter flask provided with a rubber stopper. Rinse the flask out with 50 cc. of water, which is equivalent to the volume of lead sulphate present and is added to the portion. After mixing thoroughly by shaking, allow the precipitate to settle and filter off 1800 cc. of the liquid. This is equivalent to a 200-gram charge. Place this in a No. 9 porcelain evaporating dish and evaporate, first over a free flame and later on the hot plate until only enough II2SO4 is left to moisten the residue remaining. Add 50 ec. of water and, after digesting warm for a short time, wash the solution into a 250-ec. beaker, cleaning the dish carefully. Allow the solution to digest on the steam bath for 4 or 5 hours. (Note 3.) Then filter, wash and evaporate the filtrate to 200-250 ec. Place any residue (Note 4), together with the filter paper, in a 100-cc. bcaker and treat with 20 ce. of the tartaric acid mixture. Boil for 5 minutes, dilute with 50 ec. of hot water and filter. Make the filtrate alkaline with ammonia and just acid with HCl, and obtain the tin, antimony and arsenic as previously described, reserving the whole of the alkaline sulphide solution as solution No. 2. Reject the sulphide residue.

To filtrate from the lead sulphate, add ammonia until the neutral point is reached, and then for every 50 cc. of the solution present add 2 cc. of HCl

LEAD . 289

(specific gravity 1.20). Pass H₂S gas into the hot solution until saturated, digest for 30 minutes on the steam bath and again pass H₂S gas into the solution. Filter and wash with H₂S water slightly acidified. (Note 5.) Separate tin, antimony and arsenic in the precipitate with KOH solution as usual, obtaining an alkaline sulphide solution No. 3. (Note 6.)

To sum up, three alkaline sulphide solutions have been obtained, containing tin, antimony and arsenic, a precipitate of metallic sulphides containing

copper, lead, etc., and a solution containing iron, zinc, nickel, etc.

Notes. 1. A residue indicates the presence of antimony, tin possibly arsenic, or sulphur as lead sulphate.

2. It has been found that even this treatment occasionally fails to dissolve stannic

acid completely.

3. If it is preferred, allow solution to stand over night to insure the complete solution of all soluble salts.

4. Any residuo of lead sulphate may contain some tin, antimony, or possibly arsenic. 5. The filtrate will contain any iron, zinc, nickel, cobalt and manganese; while in the precipitate will be found any copper, cadmium, lead, silver, bismuth, tin, antimony and arsenic.

6. When separating the sulphides of arsenic, antimony and tin from sulphides of copper, lead, etc., it is necessary to wash all the sulphides back into the beaker in which they were precipitated. These sulphides sometimes cling so tenaciously to the paper that in dislodging them more water than the 25 cc. specified is required. In this case allow the sulphides to settle and then decant the clear supernatant liquor through the filter until the volume is reduced to 25 cc. Before rejecting decanted fluid always test with H₂S water.

In washing sulphide precipitates with water, much trouble is experienced from the tendency of the precipitate to pass through the filter in the colloidal form. This is particularly true in washing sulphides that have been digested with KOH. Time and trouble will be saved by washing all the sulphides precipitated from mineral acid solutions with H₂S water containing a little of the acid in which they were precipitated. The same is true of sulphides precipitated in or filtered from alkaline solution.

When working with alkaline solutions in which tin is to be determined, avoid the use of Jena or other glass that contains zinc. The zinc content of the glass may influence

tho result.

Determination of Antimony and Tin

Solutions Required

Potassium Iodide. Dissolve 100 grams in a liter of distilled water. Standard Sodium Thiosulphate. Dissolve 24.8 grams of Na₂S₂O₃.5H₂O in 1000 cc. of distilled water, and allow to stand for 24 hours. Standardize against Antimony Metal, c. p., using same quantity of reagents and same procedure as under method. Each cubic centimeter is equivalent to approxi-

mately 0.006 gram of antimouy.

Method

Wash the alkaline sulphide solutions Nos. 1, 2, and 3 into a 600-cc. beaker, and acidify with 5 cc. of HNO₃ (specific gravity 1.42) and 20 cc. of HCl (specific gravity 1.20). Evaporate the solution to dryness on the steam bath. Dissolve the residue in 200 cc. of water, add 10 grams of oxalic acid and 10 grams ammonium oxalate and heat the solution until it is clear. Then pass H₂S gas through the boiling solution for 45 minutes. Filter off the precipitate, consisting of arsenic and antimony sulphides, and wash with hot water. Determine tin electrolytically in the filtrate, continuing the electrolysis until all the oxalic acid is decomposed and the solution becomes alkaline. Dissolve the deposit on the cathode with a small amount of HCl and examine qualitatively for tin.

Dissolve the sulphides of arsenic and antimony in KOH as usual, collecting the filtrate in a 500-ec. Erlenmeyer flask. Add 50 cc. of HCl (specific gravity 1.20) and boil the solution until about 30 ce. are left. Expel the arsenic as chloride. Now oxidize the solution with a pinch of KClO3 and boil until no more chlorine remains. Cool and add 5 cc. potassium iodide solution. Titrate the liberated iodine with N/10 sodium thiosulphate solution, using carbon disulphide as an indicator.

Determination of Copper and Cadmium

Solutions Required

Sodium Chloride (Solution No. 1). Dissolve 1 gram NaCl in 100 grams distilled water.

Sodium Chloride (Solution No. 2). Dissolve 10 grams NaCl in 100 grams distilled water.

Standard Potassium Cyanide. Dissolve 2 grains of KCN in a liter of distilled water and standardize against a known amount of copper as treated in the analysis.

Sodium Carbonate (Solution No. 1). Dissolve 50 grams Na₂CO₃ in 1 liter of distilled water.

Sodium Carbonate (Solution No. 2). Dissolve Na₂CO₃ in distilled water to saturation.

Method

(a) Determination Where Copper Exceeds 0.0025 Per Cent. Place the filter containing the sulphides in a 100-cc. beaker and add 20 cc. of HNO3 (1:4). Heat with occasional stirring until the paper is thoroughly pulped and the sulphides are completely dissolved. Filter into a 250-ee. beaker. Dry the residue, which generally contains a small amount of copper, ignite in a porcelain erucible, boil with 5 cc. of HNO3 (1:1), and wash into the main portion, keeping the volume below 100 cc. Render it strongly alkaline with ammonia, and add 5 grams of potassium cyanide, then saturate it in the cold with H2S gas. (Note 1.) Filter the solution and evaporate the filtrate to a volume of 20 to 30 ce. in a 4-inch porcelain easserole. Boil until solution is complete. Add 20 ce. of H₂SO₄ (1:1) and evaporate the solution under a hood until dense fumes of H2SO4 escape. Cool, dilute, and warm until copper sulphate is all dissolved. Now filter, if necessary, into a 200-ce. beaker, render just alkaline with ammonia, make acid by the addition of 3 cc. of HNO2 per 100 cc. solution, and electrolyze for copper.

Dissolve the precipitate of sulphides in the usual manner with 20 ee. of HNO₂ (1:4). Add 1 ec. NuCl solution No. 1 to the solution, still containing the pulped filter, and digest for one-half hour. Filter off the AgCl, wash and reject. Make the filtrate, not exceeding 100 cc., alkaline with a slight excess of Na₂CO₃ and add 5 grams of KCN. Digest for 1 hour. Filter and wash with Na₂CO₂ solution No. 1. Reject the precipitate of bismuth. Now add a few cubic centimeters of ammonium sulphide solution to the filtrate to precipitate any eadmium as yellow eadmium sulphide. Filter upon a weighed Gooch crucible and weigh as cadmium sulphide. (Note 2.)

Notes. 1. Copper remains in the solution while lead, silver and bismuth and cadmium are precipitated.

2. If an appreciable amount of cadmium sulphide is found, it should be converted LEAD 290a

to and weighed as cadmium sulphate, according to method for cadmium under Standard Methods of Chemical Analysis of Spelter (see page 130) of the American Society for Testing Materials.

(b) Determination Where Copper Is Less Than 0.0025 Per Cent. Place the paper containing the sulphides in a porcelain crucible, dry carefully and ignite. When the carbon has been all burned off, cool and dissolve the residue in 5 to 10 ec. of HNO₃ (1:1). After evaporating to a volume of 1 to 2 cc., add 1 cc. of H₂SO₄ (1:1). Then evaporate the solution until fumes appear, cool, dilute, add a few drops of NaCl solution No. 2, and filter off the lead sulphate and silver chloride. Again evaporate the filtrate until fumes of H₂SO₄ appear, and when cold, dilute and neutralize with Na₂CO₃ solution No. 2. Then add about six drops of concentrated ammonia and titrate the solution with standard KCN solution until the blue color is discharged.

The cadmium can be obtained by making this solution, titrated for copper, strongly alkaline, diluting a little, and adding 5 grams of KCN. Saturate the solution cold with H₂S gas, filter, discard the filtrate and treat the precipitate

for cadmium as described in Method (a).

Determination of Iron

Method

Evaporate the filtrate containing iron, zine, etc., to 100 cc. and oxidize with a few drops of HNO₃. Separate the iron with ammonia as usual, making two separations, and receive the filtrate in a 500-cc. Erlenmeyer flask. Redissolve the iron hydroxide with hot HCl (1:1) or dilute H₂SO₄ and determine the iron volumetrically by any of the standard methods.

Determination of Zinc in Pig Lead

Solutions Required

Nitric Acid (1:4). Mix 200 cc. of IINO₅ (sp. gr. 1.42) with 800 cc. of distilled water.

Sulphuric Acid (1:1). Carefully pour, with stirring, 500 cc. of H₂SO₄ (sp. gr. 1.84) into 500 cc. of distilled water.

Acidulated Hydrogen Sulphide Water. Add 20 cc. of HCl (sp. gr. 1.19) to 1000 cc. of distilled water and saturate with hydrogen sulfide.

Ammonium Thiocyanate Solution (2%). Dissolve 20 g. of NH₄CNS in 1000 cc. of distilled water.

Hydrochloric Acid (1:3). Mix 100 cc. of HCl (sp. gr. 1.19) and 300 cc. of distilled water.

Standard Zinc Solution (0.1 mg. of zinc per cc.). Dissolve exactly 0.1 g. of U. S. Bureau of Standards pure zinc in 5 cc. of HCl (sp. gr. 1.19) and dilute to exactly 1000 cc. with distilled water.

Potassium Ferrocyanide Solution. Dissolve 34.8 gr. of K₄Fe(Cn)₆.3H₂O in 1000 cc. of distilled water.

Method

Dissolve 222.23 g. of the sample in 1100 cc. of HNO₂ (1:4), using a 1300-cc. beaker. When the lead is dissolved, transfer the solution to a 2000-cc. graduated flask and add slowly 150 cc. of H₂SO₄ (1:1). Cool, fill the flask

LEAD 290b

to the mark and then pour the solution into a clean 3000-ee. flask provided with a rubber stopper. Rinse the measuring flask with exactly 50 ee. of water, which is equivalent to the volume of lead sulfate which is present. Mix the solution thoroughly by shaking, allow the precipitate to settle and filter

through a dry filter until 1800 ce. of filtrate has been obtained.

Place exactly 1800 cc. of filtrate (equivalent to a 200-g. charge) in a No. 9 porcelain evaporating dish and evaporate the solution to approximately 100 ee. Transfer the solution to a 600-cc. beaker, neutralize with ammonia, and then add 5 ee. of HCl (sp. gr. 1.19) for every 100 cc. of solution. Warm the solution and pass in a rapid current of hydrogen sulphide until it is saturated. Digest for 30 minutes on the steam bath, add an equal volume of water and again saturate with hydrogen sulfide. Filter and wash with acidulated H2S water.

Discard the precipitate and evaporate the filtrate in glassware containing no zine (such as Pyrcx) until the volume of the solution is approximately 100 ec.

Neutralize the solution with ammonium hydroxide, add 5 g. of citrie acid, and warm until the acid is dissolved. Add small portions of calcium carbonate to the hot citrie acid solution until about 1 g. of calcium eitrate has separated and then pass in a rapid current of H₂S as the solution is allowed to cool. Allow the solution to stand for from 2 to 4 hours, part of the time on a water bath, until the supernatant liquid is clear.

Collect the precipitate on a filter, wash with a 2% solution of ammonium thioeyanate and then dissolve the precipitate in hot dilute hydrochloric acid (1:3). If the solution has a reddish color (due to iron), the zinc must be reprecipitated as above. If the solution is clear, evaporate it to dryness on the steam bath, take up the residue in 3 cc. of HCl (sp. gr. 1.19), add 20 ce.

of water and filter if not perfectly clear.

Transfer the solution (Note 2) to a 50-cc. Nessler jar and dilute to 45 cc. Prepare other Nessler jars containing 3 cc. of HCl (sp. gr. 1.19), definite volumes of standard zine solution, and diluted to 45 ce. Add 5 ee. of potassium ferroeyanide solution to each jar, mix quickly, and compare the turbidities by viewing longitudinally as the jars are held over a sheet of fine print. Add more of the standard zine solution from a burette to the jar which approximates the turbidity of the unknown most closely until the turbidities match each other and calculate the percentage of zinc on the basis of a 200-g, sample or the aliquot portion taken.

Notes. 1. All glassware that contains zinc must be avoided and in umpire work

a blank test should be carried along with the test.

2. The whole solution can be used if the lead contains no more than 0.002 per cent If more zinc is present, it is best to take such an aliquot portion of the solution as will give approximately 4 mg. of zinc and then to add enough HCl to provide 3 cc.
3. For further details concerning the turbidinetric test, consult the "Determination of Small Quantities of Zino" by Mr. Bodansky, in the Journal of Industrial and Engi-

neering Chemistry, Vol. 13, pp. 696-697 (1921).

4. The addition of calcium carbonate with the formation of a precipitate of calcium citrate serves the purpose of giving a clear filtrate, and prevents the loss of colloidal sulphide.

LEAD 290c

Determination of Nickel and Cobalt

Solutions Required

Hydrogen Sulphide Wash Water. To each 100 ce. of hydrogen sulphide water add 20 ce. neutral ammonium acetate.

Method

Render the filtrate just alkaline with ammonia and saturate with H₂S. Heat to boiling and then make just acid with acetic acid, add 20 cc. of neutral ammonium acetate solution, and boil until the sulphides of nickel and cobalt separate out. Filter and wash with warm H₂S wash water. Dry the precipitate and paper in a porcelain crucible and carefully ignite. If there is an appreciable amount of residue after ignition, dissolve by boiling with 10 cc. of aqua regia, wash into a 250-cc. beaker, add 10 cc. of H₂SO₄ (1:1), evaporate until fumes appear, cool, dilute to 200 cc., make alkaline with ammonia, and add 15 cc. of concentrated ammonia. Then electrolyze the solution and weigh the nickel and cobalt as such.

Notes. If the amount of nickel and cobalt is small, it can be weighed as oxide. If the filtrate from the nickel and cobalt sulphides shows a brown color, it indicates that the precipitation has not been complete. In this case render the solution ammoniacal and repeat the above process.

Determination of Lead in Basic Carbonate of Lead

(Corroded White Lead)

Basic carbonate white lead (2PbCO₃.Pb(OH)₂) contains approximately 80 per cent metallic lead and 20 per cent carbonic acid and combined water, with traces of silver, antimony, lead, and other metals. The analysis of basic carbonate white lead can best be carried out by Walker's method.¹

Analysis

Total Lead. "Weigh 1 gram of the sample, moisten with water, dissolve in acetic acid, filter, wash, ignite, and weigh the insoluble impurities. To the filtrate from the insoluble matter add 25 ec. of sulphuric acid (1:1), evaporate and heat until the acetic acid is driven off; cool, dilute to 200 ec. with water, add 20 ec. of ethyl alcohol, allow to stand for two hours, filter on a Gooch crucible, wash with 1 per cent sulphuric acid, ignite, and weigh as lead sulphate. Calculate to total lead (PbSO₄×0.68292=Pb) or calculate to basic carbonate of lead (white lead) by multiplying the weight of lead sulphate by 0.85258.

"The filtrate from the lead sulphate may be used to test for other metals, though white lead is only rarely adulterated with soluble substances; test,

however, for zine, which may be present as zine oxide.

"Instead of determining the total lead as sulphate it may be determined as lead chromate by precipitating the hot acetic acid solution with potassium bichromate, filtering on a Gooch crucible, igniting at a low temperature, and weighing as lead chromate."

¹P. H. Walker, Bureau of Chemistry Bulletin No. 109, revised, U. S. Dept. of Agriculture, pp. 21 and 22.

290d LEAD

The Determination of True Red Lead¹

Solutions Required

1. "Red Lead Solution."—Weigh out into a 1300-cc. beaker, preferably Pyrex glass, 600 g. C.P. "Tested Purity" crystals sodium acetate (360 g. C.P. dried) and 48 g. C.P. potassium iodidc. Make up a solution of 25% acetic acid by mixing 150 cc. C.P. glacial acetic acid with 450 cc. distilled water; 184 cc. 80% acetic acid with 416 cc. distilled water. Now pour about 500 cc. of this 25% acid into the 1300-cc. beaker above mentioned, reserving the remainder. Warm the beaker on the steam bath, stirring occasionally, until a clear solution is obtained. Cool this solution to room temperature and pour it into a 1-liter graduated flask. Then add enough of the reserved 25% acetic acid to make exactly 1000 cc. and mix thoroughly.

2. 1/20 N Sodium Thiosulphate Solution.—Weigh out into a large beaker 25 g. C.P. crystals sodium thiosulphate, add 800-1000 cc. distilled water and stir until dissolved. Wash this solution into a 2-liter graduated flask, make

up to the mark with distilled water and mix thoroughly.

Each 1 cc. of this solution is equivalent to about 1.74% true red lead (using 1 g. charge) but its exact value should be determined by standardizing against pure iodine, or better, against a standard sample of red lead, the "true red lead" content of which is accurately known. The strength of this solution gradually decreases upon standing. It is a good plan, therefore, when analyzing a sample of red lead, to run a parallel determination with the standard red lead, thus ascertaining the exact strength of the thiosulphate solution. This procedure consumes but little extra time and will often prevent error.

3. Starch Indicator Solution.—Weigh out 3 g. of ordinary starch (better soluble starch) into a small beaker, add about 50 ee. cold distilled water and mix to a thin paste. Measure into an 800-ce. beaker 500 cc. cold distilled water, heat to boiling, and pour into it slowly, with constant stirring, the previously prepared starch paste. Then boil for 2 minutes, stirring, and add 5-6 drops of oil of cassia. Allow to stand over night and decant the clear supermatant liquid into a stock-bottle. When prepared in this way the

solution will keep indefinitely.

Method. Weigh 1 g. of sample into a 300-ce. Erlenmeyer flask. Add 25 ee. of distilled water and whirl the mixture into a smooth paste. Then add 30 ee. of the red lead solution and continue whirling until nearly all the red lead has been dissolved. Titrate off once with the 1/20 N thiosulphate, adding the latter rather slowly and keeping the liquid constantly in motion by whirling the flask. When the color of the assay has been reduced to a light yellow, examine it carefully for undissolved particles of red lead. If present, they can often be dissolved by shaking the flask for a short time, but if they dissolve too slowly, they should be crushed by rubbing with a glass rod flattened on end until completely dissolved. The rod should then be removed and washed with a few ce. of water. After the addition of thiosulphate has reduced the color of the assay to a very pale lemon tint and eare has been taken to see that solution of the red lead is complete, add 2 ee. of the starch indicator solution. The assay should then turn blue. Now

¹ Contributed by F. E. Dodge, National Lead Co.

LEAD 290e

finish the titrating by adding the thiosulphate solution, drop by drop, shaking the flask very thoroughly after each addition, until the blue color disappears.

Calculation. Suppose, for instance, that a red lead sample, by this method, requires 24.8 ec. thiosulphate, standard red lead requires 26.5 ee. thiosulphate. Then the per cent "true red lead"

$$\frac{92.00}{26.5} \times 24.8 = 86.1\%$$
 " true red lead,"

92.00% Pb 304 being the true red lead contents of our standard.

Notes. Before analyzing a course sample, "glassmakers'" red lead, for instance, it is necessary to grind the sample, thus rendering it more readily soluble. As a rule, it is not necessary to secure complete solution of the sample before beginning to titrate, for it will generally be found, by the time the titration is nearly finished, that the sample has entirely dissolved. Occasionally, however, a sample dissolves very slowly. In this case titrate until nearly all the feel iodine has been used up. Then warm gently, not over 40-50° C. agricults until the solution is complete and finish the titration as not over 40-50° C., agitate until the solution is complete and finish the titration as usual. The loss of iodine, owing to its small concentration, will be inappreciable, provided that the heating is not too prolonged.

Never attempt to hasten solution of the sample by warming if much free iodine

is present, as this will cause loss of iodine and, consequently, too low a result.

The temperature of the "red lead solution," when used, should be the same as normal room temperature, say 20°-25° C. (68-77° F.). If colder than this, lead iodide is apt to separate out. In this case, however, it may be redissolved by warming gently or adding a small amount of warm water.

The red lead solution should be kept in a moderately cool, dark place, but even a however, it may gradually decompose, with liberation of iodine. The error then, however, it may gradually decompose, with liberation of iodine. The error thereby introduced in a determination is inappreciable, if the thiosulphate is freshly standardized, before use, against a standard sample of red lead, as recommended.

The main consideration, in this method, is to see that the determination is run in exactly the same way and under exactly the same conditions as the standardization of the thiosulphate, by means of the standard sample of red lead, then any small errors in the determination will be offset by similar errors in the standardization.

Theoretical factor for N/10 Na₂S₂O₃ to Pb₃O₄—.03425 per ce. N/20 Na₂S₂O₃ to Pb₃O₄—.017125 per ce.

Modifications for Paste Red Lead or Red Lead from a Mixture with Linseed Oil

A modification of the method of solution in carrying out the determination for true red lead consists in the dispersion of the sample of red lead in a mixture of 7 parts chloroform and 3 parts glacial acctic acid before the addition of the regular "red lead solution." This is an excellent procedure to adopt, since it shortens the time of solution and titration of the sample remarkably. In following the regular procedure in the standard A. S. T. M. method, the red lead solution acts on the sample of red lead very slowly, and in fact the entire sample is not decomposed with resulting liberation of iodine until the titration is nearly completed, the entire operation taking from 10 to 15 minutes. the modification proposed, the sample of red lead after dispersion in the chloroform and glacial acetic acid mixture reacts readily and completely almost at once with the red lead solution, and the entire operation of solution and titration takes only from 3 to 4 minutes. The use of this modification is particularly desirable with red lead after extraction from paste or paint.

Note. It would appear from this that the chloroform and acetic acid mixture is added before the 25 cc. of distilled water.

290f LEAD

Determination of Lead Peroxide in Minium (Red Lead)

Lead per oxide is reduced by oxalic acid according to the reaction: $PhO_2 + H_2C_2O_4 = PbO + 2CO_2 + H_2O$.

The peroxide reduced by an excess of oxalic acid is determined by titrating this excess with standard potassium permanganate.

Procedure. About 0.2 g. minium is heated with 25 cc. of 2N HNO₃ (one volume of HNO₃, sp.gr. 1.2, to two volumes H₂O) and then 50 cc. N/5 oxalic acid added. The solution is heated to boiling and the excess oxalic acid titrated with N/5 potassium permanganate. 1 cc. N/5 KMnO₄=.0239 g. PbO₃.




Fig. 44a. Modified form of Scott Volumeter for Testing Lend Pigments.

Optional Method of Diehl Modified by Topf 1

The method depends of the liberation of iodine from potassium iodide by lead peroxide, which in turn is reduced as shown in the reaction below. The action is carried on in an acetic acid solution in presence of considerable alkali acetate.

$$PbO_2 + 4HI = I_2 + PbI_2 + 2H_2O_1$$

Procedure. About 0.5 gram of the material is dissolved by adding 1.2 g. of potassium iodide and 10 g. of sodium acetate in 5 cc. of 5 per cent acetic acid. The solution is now diluted to about 25 cc. and the liberated iodine titrated with 0.1 N sodium thiosulphate.

P cc. 0.1 N Na₂S₂O₃ titrates iodine equivalent to 0.01036 g. Pb.

Notes. The solution should be perfectly clear and no PhI₁ precipitate present. If present 3-4 g. sodium acetate are added and a few ec. of water. The mixture is shaken until clear and then diluted to 25 cc.

¹ Diehl, Dingl. polyt. J., 246, 196. Topf, Z. anal. Chem., 26, 296 (1887).

MAGNESIUM

Mg, at.wt. 24.32; sp.gr. 1.69-1.75; m.p. 651° 1; b.p. 1120° C.1; oxide MgO.

DETECTION

In the usual course of analysis magnesium is found in the filtrate from the precipitated carbonates of barium, calcium, and strontium. The general procedure for removal of the preceding groups may be found in the section on Separations given on the following page, 292. Magnesium is precipitated as white magnesium ammonium phosphate, MgNH₄PO₄, by an alkali phosphate, Na₂HPO₄, NaNH₄HPO₄, etc., in presence of ammonium elloride and free ammonia. The precipitate forms slowly in dilute solution. This is hastened by agitation and by rubbing the sides of the beaker during the stirring with a glass rod. Crystals soon appear on the sides of the beaker in the path of contact, and finally in the solution.

Baryta or lime water added to a solution containing magnesium produces a white precipitate of magnesium hydroxide.

Both the phosphate and the hydroxide of magnesium are soluble in acids.

ESTIMATION

The element is determined in the complete analysis of a large number of substances; in the analysis of ores, minerals, rocks, soils, eements, water, etc. The following are the more important ores in which the element occurs: Magnesite, MgCO₃; dolomite, CaCO₃·MgCO₃; kieserite, MgSO₄·H₂O; kainite, MgSO₄·KCl·6H₂O; carnallite, MgCl₂·KCl·6H₂O; in the silicates, enstatite, MgSiO₃; tale, H₂Mg₃(SiO₂)₄; meerschaum, forsterite, Mg₂SiO₄; titanate, MgTiO₃; olivine, Mg₂SiO₄·Fe₂SiO₄; serpentine, H₄Mg₃Si₂O₄. It occurs as boracite, 4MgB₄O₇·2MgO·MgCl₂. It is found in sea-water, and in certain mineral waters. It occurs as a phosphate and carbonate in the vegetable and animal kingdoms, especially in seeds and bones.

Preparation and Solution of the Sample

In solution of the material it will be recalled that the metal is soluble in acids and is also attacked by the acid alkali carbonates. It is soluble in ammonium salts. The oxide, hydroxide, and the salts of magnesium are soluble in acids. Combined in silicates, however, the substance requires fusion with alkali carbonates to bring it into solution.

General Procedure for Ores. One gram of the ore is treated with 20 cc. of strong hydrochloric acid and heated gently until the material is decomposed. If sulphides are present, 5 to 10 cc. of strong nitric acid are added and the material decomposed by the mixed acids. If silicates are present and the decomposed

¹ Circular 35 (2d Ed.), U. S. Bureau of Standards.

Chapter contributed by Wilfred W. Scott.

sition is not complete by the acid treatment, the insoluble material is decomposed by fusion with sodium carbonate, or the entire sample may be fused with the alkali carbonate, the fusion is dissolved in hydrochloric acid and taken to dryness. Silica is dehydrated as usual by heating the residue from the evaporated solution. This is taken up with 50 ec. of water containing about 5 cc. strong hydrochloric acid, the silica filtered off and, after removal of the interfering substances according to procedures given under the next section on Separations, magnesium is determined as directed in the sections on Methods.

SEPARATIONS

Removal of Members of the Hydrogen Sulphide Group. Copper, Lead, Bismuth, Cadmium, Arsenic, etc. The filtrate from silica 1 is diluted to about 200 ee. and hydrogen sulphide gas passed in until the members of this group are completely precipitated. The sulphides are filtered off and washed with H₂S water and the filtrate and washings concentrated by boiling. This treatment is seldom necessary in analysis of many silicates and carbonates in which these elements are absent.

Removal of Iron, Aluminum, Manganese, Zinc, etc. The concentrated filtrate from the hydrogen sulphide group, or in ease the treatment with hydrogen sulphide was not required, the filtrate from silica, is boiled with a few cc. of nitrie acid to oxidize the iron (solution turns yellow), about 5 ec. of concentrated hydrochloric acid added, and if manganese is present, 15 to 20 cc. of a saturated solution of bromino water, and the solution made alkaline to precipitate iron, aluminum, manganese. If zinc, cobalt, and nickel are present, these are best removed as sulphides by passing hydrogen sulphide into the ammoniacal solution under pressure. (See Fig. 3 and Fig. 4, pages 42 and 43.)

Separation of Magnesium from the Alkaline Earths. The alkaline earths are precipitated either as oxalates, recommended when considerable calcium is present, or as sulphates, recommended in presence of a large proportion of barium, the magnesium salts being soluble. Magnesium is precipitated from the filtrates as a phosphate, according to directions given later. Details of the separation of magnesium from the alkaline earths may be found in the chapter on Barium, page 59.

An excellent procedure for the separation by means of sulphuric acid is to evaporate the solution to dryness, concentrating first in a porcelain dish and finally to dryness in a platinum dish, and then adding about 50 ee. of 80% alcohol and sufficient sulphuric acid to combine with the alkaline earths and magnesium, with slight excess. This precipitates barium, strontium, and calcium as sulphates, while the greater part of the magnesium is in solution. After settling, the precipitate is filtered and washed free of sulphuric acid by means of absolute alcohol, then with 40% alcohol to remove any magnesium sulphato remaining with the precipitate. Magnesium is determined in the filtrate by expelling the alcohol by evaporation, and then precipitating as magnesium annonium phosphate according to directions given for the determination of this element.

Note. Magnesium is prevented from precipitation as a hydroxide by the presence of ammonium salts. See note, bottom of page 8.

¹ See previous paragraph.

GRAVIMETRIC DETERMINATION OF MAGNESIUM

Precipitation of Magnesium by a Soluble Phosphate as Ammonium Magnesium Phosphate

Magnesium is determined in the filtrate from calcium oxalate by the addition of sodium ammonium phosphate to a hot slightly acid or neutral solution followed by a definite amount of ammonia. The practice of precipitating magnesium from a cold solution necessitates a double precipitation as the composition of the phosphate is considerably modified by that of the solution in which the precipitation takes place, so that it is necessary to adjust conditions by having a definite amount of ammonia, ammonium salts and phosphate for the approximate amount of magnesium present. Accurate results are obtained by precipitation of the compound from a hot solution by the method of B. Schmitz, by addition of the soluble phosphate to a slightly acid solution and then making ammoniacal, or that of W. Gibbs, by precipitation of the amorphous magnesium hydrogen phosphate in a neutral solution and transforming the precipitate to magnesium ammonium phosphate by addition of ammonia to the hot solution. Upon ignition of the precipitate, magnesium pyrophosphate (Mg₂P₂O₇) is formed.

Reactions.

```
A. Na_2NH_4PO_4+MgCl_2=2NaCl+MgNH_4PO_4 (B. Schmitz).
```

B.
$$NaHNH_4PO_4+MgCl_2=NaCl+NH_4Cl+MgHPO_4$$
 and

$$MgHPO_4+NH_3=MgNH_4PO_4$$
 (W. Gibbs).

Decomposition with Heat.

$$2MgNH_4PO_4 = 2NH_4 + H_2O + Mg_2P_2O_7$$
.

The following procedure gives accurate results.

Procedure. The neutral or slightly acid solution, containing magnesium in presence of animonium salts, is heated to boiling and treated, drop by drop, with an excess of sodium or ammonium phosphate, or microcosmic salt (10% solutions), stirring constantly during the addition. Then ammonium hydroxide (sp.gr. 0.96) is added, its volume measuring one-third that of the magnesium solution. The crystalline precipitate is allowed to cool and settle for two hours or more. The supernatant liquid is filtered off, the precipitate washed by decantation two or three times, then transferred to the filter, using dilute ammonia water (2%). The precipitate is dried and then transferred as completely as possible to a weighed platinum crucible, the ash of the filter paper, burned separately, is added and the compound heated gently at first, the crucible being covered until the ammonia is driven off, and then more strongly until the mass is snow white. The residue is cooled in a desiceator and weighed as Mg₂P₂O₁. The ammonium magnesium phosphate may be filtered directly into a weighed Gooch erueible and ignited, thus avoiding the carbon of the filter paper, and shortening the period of ignition, less heat being required to obtain the white magnesium pyrophosphate.

¹ F. A. Gooch and M. Austin, Am. Jour. Sci. (4), 7, 187, 1899. W. Gibbs, C. N. 28, 51, 1873. H. Struve, Zeit, anal. Chem., 36, 289, 1897.

² Z. anal. Chem., 512, 1906.

³ Am. Jour. Sci. (3), 5, 114, 1873.

Factors. $Mg_2P_2O_7 \times 0.3621 = MgO \text{ or } 0.2184 = Mg \text{ or } \times 0.7572$ $= Mg(30, or \times 1.0811 = MgSO_4 or \times 2.2143 = MgSO_4 \cdot 7H_2O_4$

Notes on Magnesium

The ignition is conducted gently at first to gradually oxidize the carbon that the precipitate contains. With rapid ignition the particles are inclosed in the mass in a form that it is almost impossible to completely oxidize, so that the final residue is gray instead of white.

L. L. de Koninck considers that the blackening of the precipitate is frequently due to the presence of organic bases in commercial ammonia and its salts, rather than to the fibers of filter paper occluded in the mass. With caution, the filter and residue may be ignited wet, the heat being low until the filter completely

chars and then being increased, with the cover removed, until the residue is white.

Impurities. The precipitate may contain traces of lime that remained soluble in aminonium oxalate. This may be determined by dissolving the pyrophosphate in dilute sulphuric acid followed by addition of 9 to 10 volumes of absolute alcohol. Calcium sulphate, CaSO, precipitates and settles out on standing several hours. It may be filtered off, dissolved in hydrochloric acid and precipitated as oxalate in the usual way and so determined.

A residue remaining after treating the pyrophosphate with acid is generally SiO₂. The presence of manganese may be detected by dissolving the magnesium pyrophosphate, $M_{\rm E}P_iO_{\rm T}$, in nitric acid and oxidizing with sodium bismuthate. (See method under Manganese.)

Properties of Ammonium Magnesium Phosphate. Readily soluble in dilute acids. One hundred ec. of pure water at 10° C. will dissolve 0.0065 gram. The presence of ammonia greatly decreases the solubility of the salt, e.g., 2.5% ammonia decreases the solubility to 0.00006 gram MgO per 100 ec. The presence of ammonium salts increase the solubility of the precipitate, e.g., 1 gram of ammonium chloride will increase the solubility to 0.0013 gram MgO.3

VOLUMETRIC DETERMINATION OF MAGNESIUM Titration of the Ammonium Magnesium Phosphate with Standard Acid

The procedure known as Handy's volumetric method for magnesium,4 depends upon the reaction MgNH₄PO₄+H₂SO₄=MgSO₄+NH₄H₂PO₄. An excess of standard sulphuric acid is added to the precipitate and the excess of acid titrated back with standard ammonium hydroxide.

Procedure. The method of precipitation of the magnesium ammonium phosphate is the same as has been described under the gravimetric method. The precipitate is washed several times by decantation with 10% ammonium hydroxide solution (1 part NH OH, sp.gr. 0.90 to 9 parts water), and finally on the filter. After draining, the filter is opened out, the moisture removed as much as possible by means of dry filter papers. The residue may be dried in the room for about forty-five minutes or in the air oven at 50 to 60° C. for fifteen to twenty minutes.* When the filter has dried, ammonia will have been expelled. The substance is placed in a dry beaker, N/10 sulphuric acid added in excess (methyl orange indicator), the solution diluted to 100 cc. and the excess of acid titrated with N/10 sodium hydroxide.

One cc. N/10 $H_2SO_4 = 0.002$ grain MgO.

Based on atomic weights of 1916.
 Zeit. analy. Chem., 29, 165, 1890.
 Mellor, "Quantitative Inorganic Analysis," J. B. Lippincott Co., Pub.
 James Otis Handy, Jour. Am. Chem. Soc., 22, 31.
 Low, "Technical Methods of Ore Analysis." Wiley & Sons, Pub.

MANGANESE

Mn, at.wt. 54.93; sp.gr. 7.421; m.p. 1260° 2; b.p. 1900° C1; oxides, MnO, Mn₂O₃, (Mn₃O₄ ignition in air), MnO₂, MnO₃, Mn₂O₇.

DETECTION

In the usual course of analysis manganese is found in the filtrate from the hydroxides of iron, aluminum and chromium, the previous groups having been removed with hydrochloric acid, hydrogen sulphide and animonium hydroxide in presence of animonium chloride. Manganese, cobalt, nickel and zinc are precipitated as sulphides in an animoniacal solution. The sulphides of manganese and zinc are dissolved by cold dilute hydrochloric acid, H₂S expelled by boiling and manganese precipitated as the hydroxide by addition of potassium hydroxide in sufficient amount to dissolve the zinc (sodium zincate). Manganese is now confirmed by dissolving this precipitate in nitric acid and adding red lead or lead peroxide to the strong nitric acid solution. A violet-colored solution is produced in presence of manganese. Chlorides should be absent.

Manganese in soils, minerals, vegetables, etc., is detected by incinerating the substance, treating the ash with nitric acid and taking to dryness, the residue is taken up with water and the mixture filtered. To the filtrate is added a few cc. of 40% ammonium persulphate and a little 2% silver nitrate solution. A pink color is produced in presence of manganese.

Manganese compounds heated with borax in the oxidizing flame produce an anethyst red color. The color is destroyed in the reducing flame.

Fused with sodium carbonate and nitrate on a platinum foil manganese compounds produce a green-colored fusion ("robin egg blue").

ESTIMATION

Manganese may be determined accurately gravimetrically or volumetrically. The former methods may be used for high-grade manganese ores, the latter are generally preferred for determining manganese in steel and in alloys and are applicable to a wide range of substances.

The most important ore of manganese is pyrolusite, MnO₂. Other ores are braunite, Mn₂O₃; hausmannite, Mn₂O₄; manganite, Mn₂O₄·H₂O; albarite, MnS; haurite, MnS₂; dialogite, MnCO₃; rhodonite, MnSiO₄.

Speigeleisen or ferromanganese is an important alloy for the steel industry. In addition to the requirement of the element in the analysis of the above substances it is determined in certain paint pigments—green and violet manganous oxides, in dryers of oils, etc. It occurs in a number of alloys.

¹ Van Nostrand's Chem. Annual—Olsen. Chapter contributed by Wilfred W. Scott.

Preparation and Solution of the Sample

In dissolving the sample the following facts will be recalled: The metal dissolves in dilute acids, forming manganese salts. The oxides and hydroxides of manganese are soluble in hot hydrochloric acid. Manganous oxide is soluble in nitric or in sulphuric acid; the dioxide is insoluble in dilute or concentrated nitric acid, but is soluble in hot concentrated sulphuric acid.

Ores of Manganese. A sample of powdered ore weighing 1 gram is brought into solution by digesting with 25 to 50 ce. of strong hydrochloric acid for fifteen to thirty minutes on the steam bath. If much silica is present 5 to 10 cc. hydrofluoric acid will assist solution. Five cc. of sulphuric acid are added and the mixture evaporated and heated until fumes of sulphur trioxide are evolved. The residue is taken up with a little water and warmed until the sulphates have dissolved. If decomposition is incomplete and a colored residue remains, this is filtered off, ignited in a platinum dish and fused with a little potassium bisulphate. The fusion is dissolved in water containing a little nitric acid and the solution added to the bulk of the sample.

If manganese is to be determined volumetrically the removal of iron is not necessary. If, however, a gravimetric procedure is to be followed, iron and alumina are removed by the basic acetate method given under separations and manganese precipitated in the filtrate. In presence of small amounts of iron and alumina, precipitation with ammonia in presence of ammonium chloride will remove these elements without appreciable loss of manganese, a double precipitation being usually advisable. For volumetric procedures in ores containing over 2% manganese an aliquot portion of the sample is taken for the determination. The portion should not contain over 0.01 gram of manganese.

Sulphide Ores—Pyrites, etc. The sample is either roasted to oxidize the sulphide and then dissolved in hydrochloric acid as above stated or it is treated according to the procedure given for iron pyrites under sulphur.

Slags. These may be decomposed with hydrofluorie and hydrochlorie acid with final expulsion of these acids with sulphuric acid. Manganese is best determined in the extract by a volumetric method.

Iron Ores. The treatment is the same as that recommended for ores of manganese. The residue remaining upon evaporation with sulphuric acid is dissolved in a little water and about 30 cc. of nitric acid (sp.gr. 1.135) added. Manganese is now determined by the bismuthate method.

Alloys. Manganese Alloys. One gram of ferromanganese is dissolved in 50 ee. of dilute nitric acid (sp.gr. 1.135) and oxidized with sodium bismuthate with boiling. The cooled solution is diluted to 500 cc. and 10 to 25 cc. is treated with about 30 cc. of dilute nitric acid and manganese determined by the bismuthate method. The amount of sample taken is governed by the manganese content. This should not exceed 0.01 gram of the element if the volumetric procedure is to be followed.

Manganese Bronze. Five grams of drillings are dissolved in dilute nitrie acid (1.2), in a large beaker, using only sufficient acid to cause solution. If much free acid is present evaporation to small volume is necessary to expel the nitrie acid. The concentrate is diluted to 200 ec. and hydrogen sulphide passed in to precipitate copper. The solution is diluted to 250 ec. and 50 ec. filtered off (=1 gram). The H₂S gas is expelled by boiling, the solution being concentrated to about 15 cc. Twenty-five cc. of nitric acid are added and manganese precipitated

by adding potassium chlorate in small portions. The chlorine is boiled off and the precipitate filtered onto asbestos and washed with concentrated nitric acid. This is now determined volumetrically by treating with an excess of ferrous sulphate of known strength and titrating the excess with standard permanganate.

Ferro-titanium Alloy. This is best decomposed by fusion with sodium earbonate, to which a pinch of sodium peroxide has been added. The fusion is extracted with water and the residue containing iron, manganese and nickel filtered onto asbestos. Manganese is dissolved in 25 to 30 cc. of nitrie acid by treating with SO₂ gas or hydrogen peroxide and manganese determined by the bismuthate method.

Ferro-chromium, Metallic Chromium. These are best decomposed by fusion with sodium peroxide (five times the weight of sample taken), the fusion being made in a nickel crucible. The treatment is now the same as that recommended for ferro-titanium.

Ferro-aluminum, Vanadium Alloys. The method used for steel is suitable to either of these substances.

Molybdenum Alloys. The alloy is decomposed with hydrochloric acid, and iron separated by the basic acetate method, a large excess of acetate being used. Manganese is precipitated as the dioxide by means of bromine and amnionia by the detailed procedure given later. Manganese is dissolved in nitric acid after reduction in the acid solution by addition of a little sodium thiosulphate or SO₂ gas. It is now oxidized to permanganate by means of red lead and determined either colorimetrically or by titration with a standard solution of sodium arsenite.

Tungsten Alloys. These are best decomposed by treating 1 gram of the substance with 5 to 10 cc. of hydrofluoric acid and a few cc. of strong nitric acid and digesting until the solution is complete. The hydrofluoric acid is expelled by taking to dryness, a few drops of sulphuric acid having been added. The residue is taken up with water and boiled with SO₂ water. The solution is made to definite volume and manganese determined volumetrically on an aliquot portion.

Silicon Alloys. One gram of the alloy is treated with 50 cc. of dilute nitric acid (sp.gr. 1.2) and 5 cc. of hydrofluoric acid. The graphite is filtered off and the hot solution treated with sodium bismuthate and kept boiling for about fifteen minutes after the manganese dioxide has been precipitated. The bismuthate method for estimating manganese is recommended.

Iron and Steel. 0.5 to 1 gram of steel is dissolved by heating with 30 to 50 ee. of dilute nitric acid (1.135). The volumetric method by oxidation with sodium bismuthate is generally recommended, no separations of other substances being required, as manganese may be determined directly in the sample.

Pig Iron. One gram of the drillings is dissolved in 30 cc. of dilute nitric acid (1.135 sp.gr.), and as soon as the action has ceased the sample is filtered through a 7-cm. filter and the residue washed with 30 cc. more of the acid. The filtrate containing the manganese is now treated according to the procedure for steel.

¹ Brearly and Ibbotson state that although neither tungsten nor hydrofluoric acid interfere with the bismuthate method of determining manganese, the two combined lead to erratic results, hence the removal of hydrofluoric acid is necessary.

SEPARATIONS

This section includes methods of special separations of manganese from elements that may interfere in its determination. As is frequently the ease, isolation of manganese is not necessary, since it may be determined volumetrically in presence of a number of elements, which would interfere in its gravimetric determination. The analyst should be sufficiently familiar with the material to avoid needless manipulations, which not only waste time, but frequently lead to inaccurate results.

Removal of Elements of the Hydrogen Sulphide Group. This separation may be required in the analysis of certain alloys where a separation of manganese from copper is required.

The acid solution containing about 4% of free hydrochloric acid (sp.gr. 1.2), is saturated with hydrogen sulphide and the sulphides filtered off. Manganese passes into the filtrate. This treatment will effect a separation of manganese from mercury, lead, bismuth, cadmium, copper, arsenic, antimony, tin and the less common elements of the group.

Separation of Manganese from the Alkaline Earths and the Alkalies. The separation is occasionally required in the analysis of clays, limestone, dolomite, etc. It is required in the complete analysis of ores. In the usual course of a complete analysis of a substance, the filtrate from the hydrogen sulphide group is boiled free of H₂S and is treated with a few cc. of nitric acid to oxidize the iron. The solution is made slightly ammoniacal with ammonia, in presence of ammonium chloride, whereby iron, ahminum and chromium are precipitated as hydroxides. The filtrate is treated with hydrogen sulphide or colorless ammonium sulphide, whereby inanganese, nickel, cobalt and zine are thrown out as sulphides and the alkaline earths and alkalies remain in solution.

Separation of Manganese from Nickel and Cobalt

The free acid of the sulphate or chloride solution of the elements is neutralized with sodium carbonate and a slight excess added. It is now made strongly acid with acetic acid and 5 grams of ammonium acetate added for every gram of nickel and cobalt present. The solution is now diluted to about 200 ec. and saturated with hydrogen sulphide, whereby nickel and cobalt are precipitated as sulphides and manganese remains in solution.

Separation of Manganese from Iron and Aluminum, Basic Acetate Method

The procedure effects a separation of iron, aluminum, titanium, zirconium and vanadium from manganese, zinc, cobult and nickel.

The separation depends upon the fact that solutions of acctates of iron, aluminum, titanium, zirconium and vanadium are decomposed when heated and the insoluble basic acetates precipitated, whereas the acetates of manganese, zinc, cobalt and nickel remain undecomposed when boiled for a short time.

 $Fe(C_1H_2O_2)_1+2HOH=2HC_2H_2O_2+Fe(OH)_2\cdot C_2H_2O_2$

The solvent action of the liberated acetic acid is prevented by the addition of sodium acetate which cheeks ionization of the acid. The method requires care and is somewhat tedious, but the results attained are excellent.

Procedure. To the cooled acid solution of the chlorides is added a concentrated aqueous solution of sodium carbonate from a burette with constant stirring until the precipitate that forms dissolves slowly. A dilute solution of the carbonate is now added until a slight permanent opalescence is obtained. the weak reagent and careful addition of the carbonate drop by drop the proper neutralization of the free acid is obtained. With considerable iron present the solution appears a dark red color, fading to colorless as the quantity of iron decreases to a mere trace in the solution. Three ee. of acetic acid (sp.gr. 1.044) are added to dissolve the slight precipitate. The more perfect the neutralization before heating the less amount of reagent required for precipitating iron—an excess of reagent does no harm. If this does not clear the solution in two minutes, more acetic acid is added a drop at a time until the solution clears, allowing a minute or so for the reaction to take place with each addition. The solution is diluted to about 500 ce. and heated to boiling and 6 cc. of a 30% sodium acetate solution added. The solution is boiled for one minute and removed from the flame. (Longer boiling will form a gelatinous precipitate, difficult to wash and filter.) The precipitate is allowed to settle for a minute or so, then filtered, while the liquid is hot, through a rapid filter and washed with hot, 5% sodium acetate solution three times. The apex of the filter is punctured with a glass stirring rod and the precipitate washed into the original beaker in which the precipitation was made with a fine stream of hot, 1:1 hydrochloric acid solution from a wash bottle. (Dilute HNO₂ may be used in place of HCl.)

A second precipitation with neutralization of the acid and addition of sodium acctate is made exactly as directed above. It is advisable to evaporate the solution to small volume to expel most of the free mineral acid before addition of Na₂CO₃ to avoid large quantities of this reagent. The filtrates contain manganese, zinc, cobalt and nickel; the precipitate iron aluminum, titanium, zirconium, vanedium.

Materials Insoluble in Acid

Silico-Manganese, Ferro-Chrome, Ferro-Tungsten. These alloys are best decomposed by fusion with sodium carbonate and magnesium oxide, in proportion of 2 parts Na₂CO₃ and 1 part MgO. The fused mass is broken down in a mortar with water, the paste transferred to a beaker and then water added to make the solution to about 150 cc. Sodium peroxide is added and the solution boiled. The precipitate MnO₂ is allowed to settle and is then washed by decantation. The residue may contain impurities such as SiO₂, etc., from which separations may be necessary.

Manganese in Cast Iron. 1 gram of sample is treated with 25 cc. of dilute nitric acid (1:3) and when all action has ceased the solution is filtered and the residue washed with 30 cc. more of the acid. The filtrate is now examined for manganese according to the method for steel.

The carbide in white irons will prevent the quantitative conversion of manganese to permanganate. Several treatments with sodium bismuthate may be necessary.

Ferro-Silicon. Decompose the sample with hydrofluoric and sulphuric acids and evaporate to fumes. (Use platinum dish.) Take up with dilute nitric acid and proceed as in steels.

Separation of Manganese as Manganese Dioxide. See page 300a.

GRAVIMETRIC METHODS

Determination of Manganese as Pyrophosphate

Manganese is precipitated as animonium manganese phosphate, NH₄MnPO₄, and then ignited to pyrophosphate, Mu₂P₂O₇. The method is known as Gibbs' Phosphate Process. ¹

Procedure. The cold solution of manganese chloride² obtained as directed in previous sections, should be diluted so as to contain not over 0.1 gram of manganese oxide equivalent per 100 cc. of solution. A cold saturated solution of ammonium sodium phosphate (microcosmic salt, 170 grams per liter; 9 cc. precipitates an equivalent of 0.1 gram of the oxide) is now added in slight excess. The solution is made strongly ammoniacal and heated to boiling, the boiling being continued until the precipitate becomes crystalline. After allowing to settle until cold, the precipitate is filtered off (the filtrate being tested with more of the precipitating reagent to assure that an excess had been added), and dissolved in a little dilute hydrochloric or sulphuric acid.

Reprecipitation of the phosphate. The free acid is neutralized with ammonia added in slight excess until the odor is quite distinct, the solution heated to boiling, and a few ec. of additional phosphate reagent added. The erystalline precipitate is filtered into a weighed Gooch crucible, washed free of chlorides with vory dilute ammonia (AgNO₃+HNO₃ test), dried and ignited to the pyrophosphate. The ignition is conducted, as in case of magnesium, by heating first over a low flame and gradually increasing the heat to the full power of the burner. The final residue will appear white or a pale pink.

 $Mn_2P_2O_7\times 0.4996 = MnO$,

 $Mn_2P_2O_7\times 0.3869 = Mn$.

Notes. Zinc, nickel, copper and other elements precipitated as phosphates should be absent from the solution. The separation from iron is generally made by the basic acetate method and manganese precipitated from the filtrate, free of other elements, as the peroxide MnO_2 , by means of bromine added to the ammoniacal solution. Other oxidizing reagents may be used, as has been stated. The dioxide is dissolved in strong hydrochloric acid and the above 1 recipitation effected.

Gibbs, C. N., 17, 195, 1868.

² Some analysts prefer to add the phosphate reagent to the strongly ammoniacal solution, boiling hot.

Determination of Manganese as the Dioxide, MnO₂

The procedure is of special value in the complete analysis of ores where a basic acetate separation of iron and aluminum has been made, and a gravimetric estimation of other constituents in the solution are desired.

The procedure depends upon the principle that manganese in a dilute solution of manganous salt is oxidized to manganese dioxide and so precipitated, when boiled with brownine or certain other oxidizing agents:

$$MnCl_2+Br_2+2H_2O=MnO_2+2HCl+2HBr$$
.

The free acid formed by the reaction must be neutralized either by ammonia or by the presence of a salt of a weak acid such as sodium acetate, otherwise the precipitation of manganese will be incomplete. In presence of ammonium salts much of the bromine is used up reacting with ammonia,

$$MnCl_2+Br_2+3NH_3+2H_2O=MnO_2+2NH_4Cl+NH_4Br+HBr$$
.

At the same time an acid is formed, which reacts with the free ammonia. It is necessary to have the solution ammoniaeal throughout the reaction to prevent resolution of the manganese.

Procedure. To the solution containing manganese is added 4 to 5 grams of sodium acetate (unless already present in excess), the solution being diluted to about 200 cc. Bromine water is added until a distinct color of bromine is evident. The mixture is boiled and kept boiling for ten to fifteen minutes, additional bromine being added in small portions. The precipitate is allowed to settle and filtered off. The filtrate is boiled with additional bromine to ascertain whether the manganese has been completely removed from the solution.

If anumonia is present, as is frequently the case, it is advisable to add more of the reagent from time to time, the solution having a distinct odor of ammonia after the last portion of bromine has been added. When large amounts of manganese are present, several separations may be required to remove the element from the subsequent filtrates.

The precipitated dioxide may be dissolved in sulphuric acid and manganese determined volumetrically or gravimetrically.

It may be ignited directly and weighed as Mn₂O₄.

It may be evaporated with sulphuric acid and manganese determined as MnSO.

Manganates of zinc or calcium will be precipitated if present in large amounts.

Manganese may also be precipitated by animonium persulphate in an animoniaeal solution, potassium chlorate and chloride of lime in presence of zine chloride in a neutral solution.¹

¹ J. Pattinson's Method, Jour. Chem. Soc., 35, 365, 1899.

VOLUMETRIC METHODS

Volhard's Method for Manganese 1

The method is based on the principle that when potassium permanganate is added to a neutral manganese salt all of the manganese is oxidized and precipitated. When this stage is reached any excess of permanganate is immediately evident by the color produced. The calculation of results may be based on the reaction,

 $3MnSO_4 + 2KMnO_4 + 2H_2O = 5MnO_2 + K_2SO_4 + 2H_2SO_4$

or

 $5ZnSO_4+6MnSO_4+4KMnO_4+14H_2O = 4KHSO_4+7H_2SO_4+5ZnH_2 \cdot 2MnO_4$

the ratio in either case being 2KMuO4 = 3Mr.

Procedure. The material decomposed with hydrochloric and nitric acid and taken to fumes with sulphuric acid, as stated for the preparation of the sample, is cooled and boiled with 25 cc. of water until the anhydrous ferric sulphate has dissolved and continue as follows: Transfer the mixture to a 500-cc. graduated flask and add an emulsion of zinc oxide in slight excess to precipitate the iron (C.P. ZuSO₄ precipitated by KOH added to slight alkalinity. The washed precipitate is kept in a stoppered bottle with sufficient water to form an emulsion).

Agitate the flask to facilitate the precipitation and see that a slight excess of zinc oxide remains when the reaction is complete. Now dilute the contents of the flask up to the mark with cold water, mix thoroughly and allow to stand a short time and partially settle. By means of a graduated pipette draw off 100 cc. of the clear supernatant liquid and transfer it to an 8-oz. flask. While the precipitate in the 500-cc. flask may appear large, it actually occupies but a very small space, and any error caused by it may consequently be neglected. Likewise the error in measurement due to change of temperature during the manipulation is insignificant. Heat the solution in the small flask to boiling, add two or three drops of nitric acid (which causes the subsequent precipitate to settle more quickly) and titrate with a standard solution of potassium permanganate. The permanganate causes a precipitate which clouds the liquid and it is therefore necessary to titrate cautiously and agitate the flask after each addition, and then allow the precipitate to settle sufficiently to observe whether or not the solution is colored pink. A little experience will enable one to judge by the volume of the precipitate formed, about how rapidly to run in the permanganate. The final pink tinge, indicating the end of the reaction, is best observed by holding the flask against a white background and observing the upper edges of the liquid. When this point is attained, bring the contents of the flask nearly to a boil once more and again observe if the pink tint still persists, adding more permanganate if necessary. In making this endtest avoid actually boiling the liquid, as a continual destruction of the color may sometimes thus be effected and the true end-point considerably passed. When the color thus remains permanent the operation is ended. Observe the number of cc. of permanganate solution used and calculate the result.

It is customary to use the same permanganate solution for both iron and manganeso. Having determined the factor for iron, this may be multiplied by 0.2952 to obtain the factor for manganese. It will be observed that 2KMnO₄ are required for 3Mn, and in the reaction for iron that 2KMnO₄ are required for 10Fe.

¹ Applicable for high grade ores.

VOLUMETRIC DETERMINATION OF MANGANESE Bismuthate Method

The determination of manganese by the bismuthate method is generally conceded to be the most accurate analytical procedure for determination of

this element in iron and steel. It is simple and rapid, and generally ean be accomplished without a previous separation being necessary. The principle of the process depends upon the fact that under certain eonditions bivalent manganese ean be quantitatively oxidized to permanganie acid by sodium bismuthate. This permanganic acid can now be titrated by a standard reducing agent such as sodium thiosulphate or arsenous acid, or ferorus sulphate.

The application of the bismuthate method to the determination of large amounts of manganese has been made by T. R. Cunningham and R. W. Coltman (Ind. and Eng.




Fig. 45.

Chem., 16, 58, Jan., 1924). They recommend the following procedures:

Determination of Manganese in Manganese Ores

Descriptions of the application of the bismuthate method to the determination of manganese in manganese ores, ferro-manganese, and manganese metal are given in the following paragraphs. The adaptation of the method to other products high in manganese is easily made after the operator becomes familiar with the conditions necessary.

Reagents Required. (1) Concentrated nitric acid (specific gravity 1.42), freed from nitrous oxide by passing air through the solution for half an hour. If air from a compressor is used, it must be freed from oil and dust.

- (2) Nitric acid of specific gravity 1.135, made by adding 500 cc. of the above acid to 1300 cc. of water.
- (3) Dilute nitric for washing, prepared by adding 30 cc. of the concentrated acid described above to 1 liter of water.
- (4) Sodium bismuthate. This reagent generally contains approximately 80% of NaBiO₃. If there is any doubt as to its oxidizing power, it may be tested as follows:

One-half gram is shaken up with 4 grams of potassium iodide and a little water in a stoppered flask. Fifteen cubic centimeters of hydrochloric acid (specific gravity 1.20) are added and the solution is allowed to stand in the dark, with occasional shaking, until the bismuthate has entirely decomposed. The solution is diluted to 300 ee. and titrated with 0.1 N sodium thiosulphate, starch being used as indicator.

1 ec. of 0.1 N Na₂S₂O₃=0.0140 gram NaBiO₃.

- (5) Ammonium persulphate (C. P.).
- (6) Ferrous ammonium sulphate.

(7) Hydrogen peroxide (3%).

(8) Sulphurous acid. Afreshly prepared solution of sulphur dioxide in water.

(9) Standardized 0.1 N potassium permanganate.

Solution of the Ore. Grind the sample to pass 100 mesh and dry at 120° C. for 1 hour. Dissolve 2.0000 grams (±0.0002 gram) by boiling with about 40 cc. of nitric acid (1:1) in a 400-cc. beaker covered with a clock glass, adding hydrogen peroxide in small portions until the violent evolution of oxygen is over and no black particles of ore remain. Rinse the clock glass and sides of the beaker with hot water, and add bismuthate in small (about 0.05 gram) portions, until a permanent precipitate of manganese dioxide forms. Any organic matter is thus destroyed and the excess of hydrogen peroxide removed. Boil for 2 or 3 minutes, and then add sulphurous acid drop by drop until the solution clears. Boil the solution for 5 minutes, and filter it into a 500-ce, volumetric flask. Wash the siliceous residue well with water and ignite it in platinum. Treat the residue with several drops of sulphuric acid (specific gravity 1.84) and sufficient hydrofluoric acid to dissolve the silica, and evaporate the solution until it fumes. Dissolve the residue in water and add to the solution in the flask. Bring the solution to a temperature of about 20° C. and make it up to the mark with water at this temperature.

With artificial manganese dioxide, where the weight of insoluble residue is insignificant, or in case the residue from an ore is floculent and not sandy, the treatment with hydrofluoric and sulphuric acids may be omitted and the ore solution riused directly into the flask. Any barium in the ore will precipitate when the sulphuric acid solution of the residue is added to the main solution, but the barium sulphate does not interfere with the subsequent operations.

Trial Determination. As it is desirable that the back titration with permanganate be not too great (say, from 10 to 20 ee.), it is best, when ores of unknown manganese content are being analyzed, to make a rough preliminary determination of the amount of manganese present, so that the amount of ferrous salt added may not be excessive. For this purpose transfer 25.0 cc. of the well-mixed solution with a pipet to a 300-cc. Erlenmeyer flask and add 12 cc. of nitric acid (specific gravity 1.42) and about 13 cc. of water. Cool this solution, add 1.7 grams of bismuthate, agitate the mixture for 1 minute, dilute with 50 cc. of water, and filter through asbestos, washing the residue with dilute (3%) nitrie acid. Add 2.5 grams (weighed) of the solid ferrous ammonium sulphate to the filtrate and titrate back with the 0.1 N permanganate. Calculate in the usual manner the weight of manganese present in the 25-ce, portion. As 100 ee. will be used in the actual determination, multiply the result by 4, and calculate approximately the amount of bismuthate necessary (26 grams for 1 gram for manganese) and also a weight of ferrous sulphate that will give from 10 to 20 cc. in the back titration. The bismuthate is weighed out roughly, and the necessary ferrous sulphate weighed out to within half a milligram just preceding the titration.

Final Determination. Transfer two 100-cc. aliquot portions with a pipet to 750-cc. Erlenmeyer flasks and add 50 cc. concentrated nitric seid and 50 cc. of water to each. (Total volume, 200 cc.) Cool the solutions (with ice, if possible) and add the calculated amount of bismuthate all at once. Agitate the contents of the flask briskly for 1 minute, add 200 cc. of cold water, and filter

through asbestos, washing the residue with dilute nitric acid (solution No. 3) until the washings do not show the slightest trace of pink.

Place the weighed ferrous salt in a liter beaker and add the contents of the suction flask to it. Stir thoroughly until the permanganic acid has been decolorized and all the salt dissolved. Titrate at once with the standardized 0.1 N potassium permanganate to faint pink color.

Typical Analysis. Two grams of ore were dissolved and made up to 500 cc.; two 100-cc. aliquot portions were exidized and 9 grams of ferrous salt added to reduce the permanganic acid formed.

MANGANESE IN MANGANESE ORE

	Aliquot	Aliquot
	No. 1	No. 2
Back titration, cc		20.2
Equivalent of ferrous salt, cc	228.6	228.6
Difference, cc	208.5	208.4
Weight of manganese, gram	0.2291	0.2290
Percentage of manganese	57.26	57.24

Analysis of Ferromanganese

The weight of sample used is governed by the manganese content; for 80% ferromanganese from 0.25 to 0.30 gram may be used. As there is no difficulty in obtaining a uniform sample, it is preferable to weigh out individual portions of the 100-mesh sample for the determination, instead of using an aliquot part of a large sample. The following procedure as regards the quantity of acid and final volume presupposes the presence of about 0.2 gram of manganese.

When working with high-carbon ferromanganese, dissolve the sample in 60 cc. of nitric acid (specific gravity 1.42) and boil in a flask or covered beaker until nitrous fumes cease to be evolved. If the sample contains over 1% chromium, it is necessary to dilute the solution with an equal volume of water, filter, ignite the residue, and fuse it with a little sodium carbonate, dissolving the melt in the least possible quantity of nitric acid and adding it to the main solution.

Oxidize the carbon present by adding ammonium persulfate, a little at a time, until a total of from 2 to 2.5 grams has been introduced. Boil the solution about 10 minutes, and then add small amounts of bismuthate to the boiling liquid, until a precipitate of manganese dioxide has formed. Dissolve the precipitate by the addition of sulphurous acid, drop by drop, adding an excess of 1 cc. after the precipitate has dissolved to reduce any chromium to the trivalent form. After having boiled the solution for 5 minutes, bring it to a volume of 200 ec., and cool with iee. This cooling is essential in order that any chromium may not interfere, as it would be oxidized by the bismuthate if the solution were at elevated temperatures. The manganese is then oxidized with bismuthate and determined as described under "Analysis of Manganese Ore."

The following data are from typical determinations on a sample of standard high-earbon ferromanganese:

MANOANESE IN FERROMANOANESE

Weight of Sample G.	Ferrous Salt G.	KMnO ₄ Equivalent of Ferrous Salt Cc.	Back Titration Cc.	$0.1 N$ $KMnO_4$ $Consumed$ $Cc.$	Per Cent Manganese
0.2500	7.5	191.3	13.4	177.9	78.15
0.2500	7.5	191.3	13.4	177.9	78.15
0.3000	9.0	229.2	15.7	213.5	78.19

Low-earbon ferromanganese is dissolved directly in nitric acid of 1.135 specific gravity (about 1 ec. for every milligram of manganese present). After preliminary oxidation and reduction of the solution, it is made up to the original volume with nitric acid (specific gravity 1.135) and cooled as a preliminary to the oxidation and determination of the manganese.

Analysis of Manganese Metal

Dissolve 0.2500 gram in 250 cc. of nitric acid (specific gravity 1.135) in a 750-cc. Erlenmeyer flask provided with a cut-off funnel or some similar device to prevent loss by spraying, and make a preliminary oxidation with bismuthate, subsequently reducing with sulphurous acid. If the carbon is high (4%), oxidation with ammonium persulphate should precede the bismuthate oxidation. Dilute the solution to a volume of 250 ce. by adding nitric acid (specific gravity 1.135), cool with ice, and finish the determination as previously outlined. About 6.5 grams of sodium bismuthate are necessary for the oxidation and 9 grams of ferrous salt will reduce the permanganic acid resulting from a 0.2500-gram sample of 95% manganese metal.

TABLE X-MANGANESE IN MANGANESE METAL

No.	Weight of Sample G.	Ferrous Salt G.	KMnO ₄ Equivalent of Ferrous Salt Cc.		0.1 N KMnO ₄ Consumed Ce.	Per Cent Manganese
1	0.2000	8.000	203.8	28.5	175.3	96.29
2	0.2500	9.000	229.2	10.0	219.2	96.32
3	0.2500	9.000	229.2	10.2	219.0	96.24

Notes. The conditions necessary for securing complete oxidation of large quantities

MOTES. The conditions necessary for securing complete oxiditation of marge quantities of manganese and for preventing the permanganic acid from undergoing any appreciable decomposition during the subsequent filtration are summarized below.

Concentration of Nitric Acid. The manganese should be present in a solution containing from 11% (specific gravity 1.002) to 22% (specific gravity 1.135) by weight of nitric acid. If the concentration of nitric acid falls much below 11%, the oxidiation of the concentration of the state of the below 11% of the concentration of the state of the below 11% of the concentration of the state of the below 11% of the concentration of the state o of the manganese will not be complete unless the time of shaking be increased to more

than 1 minute.

Concentration of Manganese. A solution of permanganic acid containing about 0.05 gram of manganese per 100 ec. has the maximum stability, but the weight of manganese can be increased to 0.1 gram in 100 ec. without danger of any material decomposition occurring during the time required for filtering off the excess of bismuthate. When the concentration of manganese rises much above 0.10 gram per

100 cc., the rate of decomposition of the permanganic acid is unduly rapid.

Amount of Sodium Blamuthate Necessary. Approximately 26 grams of sodium bismuthate (79 per cent NaBiO₃) must be used for 1 gram of manganese.

Time of Oxidation. Shaking for 1 minute is sufficient to insure complete oxidation of the manganese to permanganic acid provided the foregoing conditions are adhered to. Chlorides should be removed by taking the solution to fumes with H₂SO₄. residue is dissolved in a small amount of water and the solution is evaporated to fumes a second time to insure the removal of every trace of chloride.

The only common metals that seriously interfere with the determination are cerium, cobalt, and sexivalent chromium. A method for the determination of cerium outlined by Metzger is exactly the same in principle as the bismuthate method for manganese. Any cerium present must therefore be separated as oxalate in acid solution, and the oxalic acid in the filtrate destroyed by evaporation with sulphuric and nitric acids as a preliminary to the determination of manganese.

The pink color produced by large amounts of cobalt interferes with the titration of permanganic acid. This can be overcome by separating the manganese from the

bulk of the cobalt by precipitating it with sodium or potassium chlorate.

While trivalent chromium is in hot solution oxidized to the sexivalent state by bismuthate and by permanganic acid, the error caused by small amounts of trivalent chromium is not appreciable provided the solution is kept cold (10° C.), and is oxidized, filtered, and titrated as rapidly as possible. When more than a small percentage of chromium is present, it should be separated from the manganese by one of the several methods that have been proposed. Precipitation of the manganese from a nitric acid solution with sodium or potassium chlorate with subsequent filtration does not effect complete removal of chromium, but is useful in some cases. Fusion with sodium peroxide followed by filtration will give a complete separation, manganese remaining in the residue as oxide and chromium passing into the filtrate as sodium chromate. Watters precipitates chromium and ferrie iron with zinc oxide and determines manganese in the filtrate, while Cain precipitates chromium and vanadium from a ferrous solution with eadmium carbonate and analyzes the filtrate for manganese. Sexivalent chromium interferes with the determination of manganese by the bismuthate method and must be reduced to the trivalent condition prior to the final oxidation with bismuthate.

Although any vanadium present is reduced by the ferrous sulphate added during the determination, it is re-exidized by an equivalent amount of permanganic acid during

the back titration, the manganese titration as a consequence being unaffected.

Provided accurate volumetric apparatus is available, it is usually preferable to make the manganese solution up to a definite volume and to work on an aliquot portion. The solution should always be given a preliminary oxidation with bismuthate before being made up to volume. Bismuthate is added to the hot solution in small portions until manganese dioxide precipitates, the liquid is boiled for 5 minutes, and then sulphurous acid is added drop by drop until the precipitate has dissolved. Sexivalent chromium should be reduced by SO₂ to trivulent form. The concentration of nitric acid to 1.135 sp.gr. and manganese to 0.0001 gram per cc. are required for best results.

Determination of Permanganic Acid

Ferrous ammonium sulphate is used to reduce the permanganie acid formed. It is added in solid form, weighed to ± 0.5 mg., just before the determination is started. This salt is preferable to ferrous sulphate, as it goes into solution more readily. The manganese value of the ferrous salt must be known, and for this purpose 5.0000 grams (± 0.5 mg.) are titrated with the standard permanganate used. This titration should be made in sulphuric acid solution. If the salt is kept in a well-corked bottle, the standard will suffer practically no change, and having once been well mixed and standardized may be used indefinitely. If preferred, a 0.1 N solution of ferrous ammonium sulphate may be used instead of the solid salt.

The excess of ferrous salt is now titrated with a standardized solution of potassium permanganate, preferably of about 0.1 N strength. The permanganate may be standardized against Bureau of Standards sodium oxalate, according to McBride's recomnendations, by means of pure manganous oxalate as hereinafter described, or against pure anhydrous manganous sulphate. Owing to the difficulty of preparing the latter salt so that it is of theoretical composition, the first two methods of standardization are preferable. After the normality of the solution against sodium oxalate has been determined, the theoretical factor—viz., 1 cc. 0.1 N KMnO₄=0.001099 gram of man-

ganese-may be used.

Correlation of Value of Permanganate Used for Titration with an Absolute Standard

In order to determine the value of the permanganate in terms of manganese.

manganous sulphate prepared in the following manner may be used:

Potassium permanganate (the ordinary C. P. product) was reduced in the presence of sulphuric acid with a little less than the calculated amount of oxalic acid, and the manganese dioxide formed is filtered off and disearded. The solution of manganese sulphate is treated with ammonium carbonate and the resulting manganese earbonate filtered and washed free from sulphates by decantation. This precipitate is added to a boiling solution of oxalic acid, and the manganous oxalate formed filtered and washed free from acid with distilled water. This product is converted to the sulphate by heating to constant weight at 480° to 520° C., with an excess of sulphuric acid. An accurately weighed amount of the pure manganous sulphate (2.7536 grams of MnSO₄, equivalent to 1.0018 grams of manganese) is dissolved and made up to 1 liter with nitric acid (specific gravity 1.135). One hundred and 200-cc. portions of this solution are oxidized with sodium hispatches filtered and water distinct of accurately. are oxidized with sodium bismuthate, filtered, and reduced by addition of accurately weighed amounts of ferrous ammonium sulphate, the excess of which is determined by means of 0.1 N permanganate that had been standardized against sodium oxalate. The relation between the ferrous ammonium sulphate and the permanganate is carefully determined. The results that are obtained, confirm Blum's statement that either manganous sulphate or sodium oxalate may be used as the primary standard for the biamuthate method, or expressed in another form, that the manganese is quantitatively oxidized to the heptavalent state.

Ammonium Persulphate Method for Determining Small Amounts of Manganese by Colorimetric Comparison or by Titration

The process depends upon the oxidation of manganous salts to permanganate by anumonium persulphate in presence of a catalytic agent such as silver nitrate:

$$2Mn(NO_2)_2 + 5(NH_4)_2S_2O_8 + 8H_2O = 5(NH_4)_2SO_4 + 5H_2SO_4 + 4HNO_3 + 2HMnO_4$$

The reaction takes place equally well in sulphuric or in nitric acid solution, or in a mixture of the two. The essential point is the presence of a sufficient amount of silver nitrate catalyst.

Procedure. One gram of orc is dissolved in hydrochloric acid, followed by sulphuric and taken to fumes as directed under Preparation and Solution of the Sample. The sulphate taken up with water is made to a volume of 100 cc. If the color comparison is to be made the solution should be filtered through a dry filter, otherwise the filtration may be omitted. Twenty cc. (equal to 0.2 gram) of the material is taken for the test. In the case of steel, 0.1 to 0.2 gram of the drilling, dissolved in dilute nitric acid, is taken.

Oxidation. The solution is transferred to a test-tube, 1×10 ins., if the color comparison is to be made, or into a 150-cc. Erlenmeyer flask, if the sample is to be titrated. Fifteen ec. of silver nitrate solution (1.5 grams AgNO₁ per liter of water), are added; the solution heated to 80 to 90° °C. by placing the receptacle in hot water, and then 1 gram of ammonium persulphate added. When the color commences to develop the sample is cooled in cold water, while the evolution of oxygen continues. The sample is poured into the comparison tube and the color compared with that obtained from an ore or steel sample of known manganese content, run in the same way.

In the titration method the solution in the Erlenmeyer flask is diluted to about 100 cc., 10 cc. of 0.2% salt solution added, and the sample titrated with standard sodium arsenite until the permanganate color is destroyed. The cc. of the reagent used multiplied by the factor per cc. in terms of manganese equals weight of manganese in the sample titrated.

Note. Arsenious acid reagent is made by dissolving 10 grams of arsenious oxide in water containing 30 grams of sodium carbonate. The solution is diluted to 1 liter. 125 cc. of this solution are diluted to 2000 cc. This latter reagent is standardized against an ore or sample of steel of known manganese content, following the directions given under the procedure outlined.

Oxidation of Manganese to Permanganate by Red Lead

Red lead oxidizes manganese in nitric acid solution to permanganate. The method is suitable for determining this element in steel and iron in presence of molybdenum, aluminum, tungsten, copper and nickel, in amounts such as are apt to be present. The method is given in the chapter on Iron in the Analysis of Iron and Steel.

¹W, V, Cr interfere, but may be removed by precipitation with ZnO emulsion.

Ford-Williams Method for Manganese

In this method manganeso dioxide is precipitated by potassium chlorate from a nitric acid solution. Chlorine dioxide gas that is formed by the reaction is boiled off, the manganese dioxide is dissolved by an excess of ferrous sulphate or oxalic acid and the excess of the reducing agent is titrated with standard potassium permanganate.

Reagents

0.03 N solutions of potassium permanganate, ferrous sulphate (or oxalie acid or sodium oxalato). See manganese in steel for preparation of reagents, chapter on Iron.

Procedure

A sample of about 3 grams of steel is dissolved in 60 ee. of dilute nitrie acid (9 d. 1.2). (For ores see Prep. and Sol. Sample.) The solution is evaporated to about 50 cc. and 50 ce. concentrated nitrie acid added and about 3 grams of potassium chlorate. The solution is boiled for about 15 minutes and the flask removed from the source of heat. (KClO₃ added to boiling HNO₃ will cause an explosion.) 50 ce. more of nitrie acid (d. 1.42) are added and 3 grams of KClO₃ and the solution again boiled. After cooling under water of a tap, the precipitated MnO₂ is filtered onto asbestos (an asbestos mat over a plug of glass wool in a funnel), and is washed with concentrated nitrie acid until free from iron and then with water until free from acid.

The precipitate is now placed in a flask, together with the asbestos, 50 ee. of the standard ferrous sulphate are added and the solution diluted to about 200 ee. The mixture is shaken to dissolve the MnO₂ and the excess of 0.03 N ferrous solution is titrated with 0.03 N potassium permanganate.

Calculation. If the permanganate is standardized against sodium oxalate, the oxalate equivalent of 1 ee. of the permanganate solution multiplied by 0.4099 will give the equivalent manganese per ee., i.e.,

$$Mn + Na_2C_2O_4 = 54.93 + 134.0 = 0.4099$$
.

Note. The nitric acid must be free from nitrous acid as this reduces MnO₂. The permanganate equivalent is 5/3 of the permanganate equivalent of the Volhard's method, in which the valence of manganese is reduced from 7 to 4. Here the valence is reduced to 2.

ANALYSIS OF SPIEGEL IRON FOR MANGANESE¹

Procedure. Weigh 0.5 gram of the sample in a 250-cc. beaker, add 40 ec. dilute HNO₃ (1-2), cover with a watch-crystal, heat over Bunsen burner and finally expel nitrous fumes by boiling down to a small volume (5 ec.). Wash into a 500-cc. graduated flask, fill about half full, neutralize with an emulsion of zinc oxide, adding enough to precipitate the iron and a slight excess. Dilute to the mark, shake well, pour into a 600-cc. beaker and mix by pouring back into the flask and then into beaker. Allow the precipitate to settle, deeant off two 100-ec. portions of clear solution into 350-cc. casseroles. Add 100 cc. water, heat to boiling and titrate with standard KMnO₄, stirring thoroughly with heavy glass rod. Run in about 1 cc. at a time until the end-point is passed. Titrate the second portion, running it up to within 1 cc. of the end-point, and finishing a drop or two at a time, stirring thoroughly between each addition. The burette reading gives percentage of Mn directly.

Permanganate. Dissolve 23.23 KMnO₄ per 12 liters of water. Standardization. Weigh .15 gram C.P. sodium oxalate (Bureau of Standards) into a 400-cc. beaker. Dissolve in 200 to 250 cc. hot water (80 to 90°), add 10 cc. (1:1) sulphuric acid. Titrate at once with KMnO₄.

When .15 gram sodium oxalate is taken, it should consume 36.87 cc. KMnO₄.

DETERMINATION OF MANGANESE IN ORES, OXALIC ACID METHOD?

Half a gram of ore is dissolved in 10 cc. HCl; if sulphides are present 5 cc. HNO₃ are added and the sample heated to effect solution. 5 cc. $\rm H_2SO_4$ are added and the solution evaporated to near dryness to expel the large excess of acid. 100 cc. of water are added and the solution heated to boiling and allowed to stand until all ferric sulphate (anhydrous) has dissolved.

Zinc oxide, either as a powder or suspended emulsion, is added to completely precipitate the iron and then a slight excess, some oxide remaining undissolved. The precipitate is filtered off and washed with hot water 10 times. The filtrate contains the manganese.

3-4 grams of sodium acetate (or 5 cc. saturated solution) to neutralize the acid formed by the subsequent treatment are added, and then an excess of bromine water (saturated solution) and the solution boiled several minutes, adding more bromine if necessary. Bromine vapor should be evident on boiling. MnO_2 precipitates. After settling slightly it is filtered off and washed 10 times with hot water. (If lead is present in the ore it should be removed by adding $K_2Cr_2O_7$ sol, during the zine oxide treatment to remove iron, otherwise lead would precipitate with MnO_2 and give high results.)

The filter with the precipitate is placed in a beaker with an excess of standard oxalic acid (1 cc. $N/10 = 0.0063025 \text{ g} \cdot \text{H}_2\text{C}_2\text{O}_4 \cdot 2\text{H}_2\text{O}$ or $0.0027465 \text{ g} \cdot \text{Mn}$) 50 cc. dilute H_2SO_4 (1:10) are added, the solution heated to boiling (adding more oxalic if any MnO_2 remains). The solution is diluted to 200 cc. with hot water and the excess of oxalic acid titrated with standard KMnO₄ (N/10). The cc. oxalic acid minus cc. KMnO₄ gives cc. oxalic acid used by MnO₂. Each cc. N/10 reagent = 0.0027465 g · Mn.

¹ Procedure communicated to the author by Dr. Breyer. ² Method of A. H. Low modified by W. W. Scott.

MERCURY

Hg, at.wt. 200.61; sp.gr. 13.595; 1 m.p. -38.9°; 2 b.p. 357.33° C; 1 oxides, Hg₂O, HgO.

DETECTION

Metallic mercury is recognized by its physical properties. It is the only metal which is a liquid at ordinary temperatures. The element forms a convex surface when placed on glass.

Mercury in the mercurous form is precipitated by hydrochloric acid as white mercurous chloride, HgCl. This compound is changed by ammonium hydroxide to the black precipitate of metallic mercury and nitrogen dihydrogen mercuric chloride.

Mercury in the mercuric form is not precipitated by hydrochloric acid. The sulphide of the element is thrown out from an acid solution as black HgS. The precipitate first appears white, changing to orange-yellow, then brown and finally to black, as the H₂S gas is passed into the solution. The element is distinguished from the other members of the group by the insolubility of its sulphide in yellow ammonium sulphide and in dilute nitrie acid.

If the mercury sulphide is dissolved in aqua regia, the nitric acid expelled by taking to dryness, then adding hydrochloric acid and evaporating again to dryness, the residue taken up with a little hydrochloric acid, diluted with water, and treated with a solution of stanuous chloride, a white precipitate of mercurous chloride is first formed, which is further reduced to metallic mercury by an excess of the reagent.

ESTIMATION

The metal is found free in the upper portions of cinnabar deposits. As an amalgam with silver it occurs in horn silver. Cinnabar, HgS, is the only ore of mercury of commercial importance. The element has been found in quartz, sandstone, schists, iron pyrites, bituminous substances, eruptive and sedimentary rocks of all ages. It occurs in sulphide ores of other metals—especially in zinc ores.

Preparation and Solution of the Sample

It will be recalled that nitric acid is the best solvent for the metal and its amalgams. The oxides are insoluble in alkalics. Mercurie oxide is dissolved by acids. Hydrochloric acid forms mercurous chloride with the lower oxide, insoluble in dilute hydrochloric acid.

¹Van Nostrand's Chem. Annual—Olsen. ²Circular 35 (2d Ed.) U. S. Bureau of Standards.

Chapter contributed by Wilfred W. Scott.

Ores. If mercury is to be determined by the dry procedure, the finely ground sample may be mixed directly with the flux and determined as directed later.

For opening up the ore for the volumetric method by Seamon see method at close of the chapter, page 312.

For decomposition of ores see also thioeyanate method, page 312a.

SEPARATIONS

Separation of Mercury from the Iron and Zinc Groups, or from the Alkaline Earths and the Alkalies. Mercury is precipitated as a sulphide from an acid solution of the mercuric salt by hydrogen sulphide, together with the members of the hydrogen sulphide group. Sufficient acid should be present to prevent the precipitation of zinc sulphide. Iron, aluminum, chromium, manganese, cobalt, nickel, zinc, the alkaline earths and the alkalies remain in solution.

Separation of Mercury from Arsenic, Antimony, and Tin. The sulphides obtained by passing hydrogen sulphide into an acid solution, prefcrably of the chlorides, are digested with yellow ammonium sulphide solution. Arsenic, antimony and tin dissolve, whereas mercury sulphide remains insoluble. Sulphides of the fixed alkalies dissolve mercury as well as arsenic, antimony and tin, so cannot be used in effecting a separation.

Separation from Lead, Bismuth, Copper and Cadmium. These elements remain with mercury upon removal of arsenic, antimony and tin as their sulphides are insoluble in ammonium sulphide. (CuS slightly soluble.) The precipitated sulphides are transferred to a porcelain dish and boiled with dilute nitrie acid, sp.gr. 1.2 to 1.3. After diluting slightly with water the solution is filtered and the residue of mercuric sulphide washed with dilute nitrie acid and finally with water. If much lead is present in the solution it is apt to contaminate the residue by a portion being oxidized to lead sulphate and remaining insoluble. In this case the residue is treated with aqua regia, the solution diluted and mercury chloride filtered from PbSO₄ and free sulphur. Mercury is best determined as HgS by the ammonium sulphide method described later. Traces of lead do not interfere, as lead is completely removed by remaining insoluble in potassium hydroxide, whereas mercury sulphide dissolves. See method.

Separation from Selenium and Tellurium. The mercury selenide or telluride is dissolved in aqua regia, ellorine water added and the solution diluted to 600 to 800 ee., phosphorous acid is added and the solution allowed to stand for some time; mercurous chloride is precipitated, selenium and tellurium remaining in solution. Selenium and tellurium will precipitate in hot concentrated solutions when treated with phosphorous acid, but not in dilute hydrochloric acid solutions.

Mercury in Organic Substances. The material is decomposed by heating in a closed tube with concentrated nitric acid, or by heating with 10% H₂SO₄ and sufficient (NH₄)₂S₂O₈, added in small portions until the organic matter is decomposed.


GRAVIMETRIC METHODS

Determination of Mercury by Precipitation with Ammonium Sulphide

The following method, suggested by Volhard, is generally applicable for determination of mercury. The element is precipitated by ammonium sulphide as HgS. The precipitate dissolved in caustic is again thrown out by addition of ammonium nitrate to the sulpho salt solution of mercury.

$$Hg(SNa)_2+2NH_4NO_3=2NaNO_3+(NH_4)_2S+HgS.$$

Procedure. The acid solution of the mercuric salt is nearly neutralized by sodium carbonate, and is then heated with a slight excess of ammonium sulphide



reagent, freshly prepared. Sodium hydroxide solution is added until the dark-colored liquid begins to lighten. The solution is now heated to boiling and more sodium hydroxide added until the liquid is clear. If lead is present it will remain undissolved and should be filtered off. Ammonium nitrate is now added to the solution in excess and the mixture boiled until the greater part of the ammonia has been expelled. The clear liquid is decanted from the precipitate through a weighed Gooch crucible and the precipitate washed by decantation with hot water and finally transferred to the crucible and washed two or three times more. The mercuric sulphide is dried at 110° C. and weighed as HgS.

$$HgS \times 0.8622 = Hg$$
 or $\times 0.9307 = HgO$.

Notes. Alumina and siliea are apt to be present in caustic.

Free sulphur may be removed, if present, by boiling with sodium sulphite, $Na_2SO_2+S=Na_2S_O_2$. The sulphur may be extracted with carbon disulphide. The Gooch crucible is placed upon a glass tripod in a beaker, containing carbon disulphide, and a round-bottomed flask filled with cold water is placed over the month of the beaker to serve as a condenser, Fig. 47. By gently heating over a water bath for an hour the sulphur is completely extracted from the sulphide. Carbon disulphide is removed from the precipitate by washing once with alcohol followed by ether. The residue is now dried and weighed.

Determination of Mercury by Electrolysis

Mercury is readily deposited as a metal from slightly acid solutions of its salts. Procedure. The neutral or slightly acid solution of mercurie or mercurous salt is diluted in a beaker to 150 cc. with water and 2 to 3 cc. of nitric acid added. The solution is electrolyzed with a current of 0.5 to 0.1 ampere, and an E.M.F. of 3.5 to 5 volts. A gauze cathode is recommended, or a platinum dish with dulled inner surface may be used. One gram of mercury may be deposited in about fifteen hours (or overnight). The time may be shortened to about three hours by increasing the current to 0.6 to 1 ampere.

The metal is washed with water without interrupting the current and then with alcohol. After removing the adhering alcohol with a filter paper, the cathode is placed in a desiceator containing fused potash and a small dish of mercury. The object of this mercury is to prevent loss of the deposit by vaporization.

The increased weight of the cathode is due to metallic mercury.

Notes. In the electrolysis of mercuric chloride turbidity may be caused by formation of mercurous chloride by reduction, but this does no harm, as the reduction to metallic mercury follows.

Mercury may be electrolyzed from its sulpho solutions, obtained by dissolving its sulphide in concentrated sodium sulphide.

Determination of Mercury by the Holloway-Eschka Process Modified


When inercury sulphide is heated with iron filings metallic mercury is volatilized, iron sulphide being formed. The mercury vapor is condensed on a silver or gold plate. The use of iron for this reduction was suggested by Eschka and his method modified by Holloway. In ores containing arsenic the addition of zinc oxide is recommended. Erdmann and Marchand use lime for decomposing the mercury compound. The reactions may be represented as follows:

$$HgS+Fe=FeS+Hg$$
 or $HgX+CaO=CaX+Hg+O$.

Apparatus. This consists of a deep glazed porcelain crucible, the size depending upon the charge of the sample to be taken. Generally a 30-ce, crucible is used for a 2-gram sample with 4 grams of flux. The crucible is covered

by a silver or gold plate that lies perfectly flat and fits snugly around the edges of the crucible. It may be necessary to grind the top of the receptacle on emery paper to obtain a perfectly level edge.

The crucible is suspended in a hole through an asbestos board or quartz plate, to prevent the flame heating the upper portion of the vessel.



The lid of the crucible is kept cool by a cylindrical condenser of metal through which a stream of water passes. A small Erlenmeyer flask may be used, with a tube passing to the bottom of the flask through a rubber stopper, and a second tube just passing through the stopper.

Holloway has a weight placed on the metal condenser to hold the lid firmly against the crucible. The illustration (Fig. 48) shows the form of the apparatus set up for the run.

Procedure. The sample containing not over 0.1 gram of mercury is placed in the erucible with 5 to 10 grams of fine iron filings and intimately mixed. Additional filings are put over the charge. Sulphide ores containing arsenic are best mixed with about twice the weight of a flux of zine oxide and sodium carbonate in the proportion 4 to 1, and about five times the weight of iron filings added.

The weighed silver cover is placed on the erucible and the apparatus set up as

shown in the illustration, Fig. 48.

The bottom of the crueible is gradually heated with a small Méker flame until it glows slightly. Overheating should be avoided. The upper portion of the crucible should never become hot and the lid should remain cold. After heating for about thirty minutes the system is allowed to cool without disconnecting the condenser. The disk is now removed, dipped in alcohol and dried in a desiceator over fused potash or soda. The increase of weight of the dried disk is due to metallic mercury.

Notes. If the sample contains less than 1% mercury, take 2 grams; if 1 to 2% mercury, take 1 gram; if the sample contains 2 to 5%, take 0.5-gram sample. If high in mercury, grind sample with sand and take an aliquot portion.

It is advisable to repeat the test with a clean foil to be sure that all the mercury has been driven out of the sample. The foil may be freed from mercury by

heating.

VOLUMETRIC DETERMINATION OF MERCURY Seamon's Volumetric Method ¹

Seamon's Volumetric Method. Weigh 0.5 gram of the finely ground ore into an Erlenmeyer flask of 125 cc. capacity. Add 5 cc. of strong hydrochloric acid and allow it to act for about ten minutes at a temperature of about 40°C., then add 3 cc. of strong nitric acid and allow the action to continue for about ten minutes longer. The increary should now all be in solution. Now if lead be present, add 5 cc. of strong sulphuric acid; it may be omitted otherwise. Dilute with 15 cc. of water and then add ammonia cautiously until the liquid is slightly alkaline. Bismuth, if present, will be precipitated. Acidify faintly with nitric acid, filter, receiving the filtrate in a beaker, and wash thoroughly.

Add to the filtrate 1 cc. of strong nitric acid that has been made brownish in color by exposure to the light, and titrate with a standard solution of potassium iodide until a drop of the liquid brought into contact with a drop of starch liquor, on a spot-plate, shows a faint bluish tinge. It is a good plan to set aside about one-third of the mercury solution and add it in portions until the endpoint is successively passed, finally rinsing in the last portion and titrating to the end-point very carefully.

Deduct 0.5 cc. from the burette reading and multiply the remaining cc. used by the percentage value of 1 cc. in increary to obtain the percentage in the ore.

The standard potassium iodide solution should contain 8.3 grams of the salt per liter. Standardize against pure inercuric chloride. Dissolve a weighed amount of the salt in water, add 2 cc. of the discolored nitrie acid and titrate as above. One cc. of standard solution will be found equivalent to about 0.005 gram of mercury, or about 1% on the basis of 0.5 gram of ore taken for assay.

The precipitate of red mercuric iodide which forms during the titration may not appear if the amount of mercury present is very small, but this failure to precipitate does not appear to affect the result.

Iron, copper, bismuth, antimony, and arsenic, when added separately to the ore, did not influence the results in Scamon's tests. Silver interferes. Duplicate results should check within 0.1 to 0.2 of 1%.

^{1 &}quot;Manual for Assayers and Chemists," p. 112.

Volumetric Thiocyanate Method for Mercury 1

A sample containing 0.1 to 0.5 g. Hg placed in a flask is decomposed by adding 10 cc. dilute H₂SO₄ (1:1) and about 0.5 g. KMnO₄ crystals. The mixture is agitated and heated to fumes. The solution cooled is diluted to 50 ec. with cold water, then boiled and the MnO₂ dissolved by adding a few crystals of oxalic acid (small portions at a time).

The solution is filtered, and any residue washed with dilute (1:10) H₂SO₄. The sulphide group are now precipitated with H₂S and filtered off. The precipitate, transferred to a casserole, is digested for some time with dilute HNO₃ (2:1), the solution then diluted with hot water and filtered and the

HgS washed with dilute HNO₃ (1:1).

The HgS is transferred to a flask with a few cc. of hot water and then 5 cc. of strong H₂SO₄ and 0.5 g. KMnO₄ are added and the mixture heated to fumes. Oxalic acid crystals are added until the MnO₂ dissolves and the mixture again heated to fumes to destroy the excess of oxalic acid. The solution, cooled, is diluted to 100 cc. (It should now be clear.)

About 5 ce. of a saturated solution of ferrie ammonium sulphate solution (acidified with HNO₃) are added and the solution titrated with 0.1 N thio-

eyanate solution.

1 cc. 0.1 N thioeyanate = 0.01003 g. Hg.

Solutions. Ferric Indicator. Make a saturated solution of ferrie ammonium sulphate or ferrie sulphate. Add sufficient nitrie acid (freed from nitrous acid by heating) to clear the solution and produce a pale yellow color. 5 cc. of this solution (the Editor prefers less) is used in the test. Ferrie nitrate may be used if the sulphate is not available.

Thiocyanate Reagent. A tenth normal solution may be made by dissolving 7.4 grams of NH₄CNS or 9.2 grams of KCNS in water and diluting to a liter. The solution may be standardized against a standard silver solution, con-

taining 0.01079 grams silver per cc.

40 cc. of the silver solution is measured into a beaker or Erlenmeyer flask and diluted to about 100 cc. The ferric indicator is added and the solution is titrated with the thiocyanate solution. Each addition of the thiocyanate will produce a temporary red color, which fades out as long as there is silver uncombined with thiocyanate. A drop in excess of the thiocyanate produces a permanent faint red color.

¹ By A. H. Low (Chemist-Analyst, 1919, 29, 13).

Mercury in Organic Matter. The compound is decomposed by the method of Carius by heating in a closed tube (see page 145) with strong nitrie acid (d. 1.42). The acid solution is neutralized by addition of sodium hydroxide and sufficient excess of the alkali added to insure a slight excess. Pure potassium cyanide is now added in quantity sufficient to dissolve the mercuric oxide precipitate, and the solution saturated with H₂S gas. Ammonium acetate is added and the solution boiled until nearly all the NH₃ has been expelled. The precipitate is allowed to settle and then filtered off and washed with hot water, and then with hot dilute HCl and again with water. The precipitate is dried at 110° C. and weighed as mercuric sulphide HgS.

Note. Should free sulphur be present its removal is accomplished by extraction with pure ${\rm CS}_3$, see page 310.

MOLYBDENUM

Mo, at.wt. 96.0; sp.gr. 8.6-9.01; m.p. 2500° C; oxides, Mo,O, MoO, MoO;

DETECTION

Molybdenum appears in the hydrogen sulphide group, being precipitated by H_iS in acid solution as the sulphide. It passes into solution by digestion with animonium sulphide or sodium sulphide along with arsenic, antimony, tin, gold and platinum. By addition of metallic zinc, antimony, together with tin, gold and platinum are precipitated as metals while molybdenum remains in solution. Arsenic, that has not volatilized as arsine, is expelled by evaporation. Nitric acid is now added and the solution taken to dryness. Molybdenum is extracted from the residue with ammonium hydroxide.

A dilute solution of annuonium molybdate treated with a soluble sulphide gives a blue solution.

Sodium thiosulphate added to a slightly acid solution of ammonium molybdate produces a blue precipitate with a supernatant blue solution. With more acid a brown precipitate is formed.

Sulphur dioxide produces a bluish-green precipitate if sufficient molybdenum is present, or a colored solution with small amounts. The reducing agents, stannous chloride, or zinc in acid solution, produce a play of colors when they react with molybdenum solutions, due to the formation of the lower oxides. The solution becomes blue, changing to green, brown and yellow.

Molybdenum present as molybdate is precipitated by disodium phosphate as yellow annonium phosphomolybdate from a nitric acid solution. The precipitate is soluble in annonium hydroxide.

A pinch of powdered mineral on a porcelain lid, moistened with a few drops of strong sulphuric acid, stirred and heated to fumes, then cooled, will produce a blue color when breathed upon. The color disappears on heating, but reappears on cooling. Water destroys the color.

Molybdenite is very similar to graphite in appearance. It is distinguished from it by the fact that nitrie acid reacts with molybdenite, MoS₂, leaving a white residue, but has no action upon graphite. The blowpipe gives SO₂ with molybdenite and CO₂ with graphite.

ESTIMATION

The determination is roquired in the ores—molybdenite, MoS₂, (60% Mo); molybdite, MoO₄ (straw yellow); wulfenite, PbMoO₄ (yellow, bright red, olive green or colorless); Ilsemannite, MoO₄+MoO₄; powellite, CaMoO₄; pateraite, CoMoO₄; belonesite, MgMoO₄; eosite, lead-vanado-molybdate; achromatite,

lead molybdate and arsenate with tin oxide and lead chloride. Some iron and copper ores also contain molybdenum.

The metal is determined in certain self-hardening steels and alloys.

The reagents ammonium molybdate and the oxide-molybdic acid, MoO₁, are valuable for analytical purposes. Tests of their purity may be required.

Preparation and Solution of the Sample

In dissolving the substance the following facts should be kept in mind: The metal is easily soluble in aqua regia; soluble in hot concentrated sulphuric acid, soluble in dilute nitric acid, oxidized by excess to MoO₃. It is dissolved by fusion with sodium carbonate and potassium nitrate mixture. It is insoluble in hydrochloric, hydrofluoric and dilute sulphuric acids.

The oxide MoO₂ is but slightly soluble in acids and alkalies; MoO₂ is insoluble in hydrochloric and hydrofluoric acids. MoO₃, as ordinarily precipitated, is soluble in inorganic acids and in alkalies. The oxide sublimed is difficultly

soluble.

Molybdates of the heavy metals are insoluble in water, the alkali molybdates are soluble.

Ores. Molybdenum ores are decomposed by fusion with a mixture of sodium carbonate and potassium nitrate, or with sodium peroxide, in an iron crucible, 0.5 gram of the sample being taken and 10 times its weight of fusion mixture. The melt is disintegrated with about 150 cc. of water, the alkali partly neutralized with $(NH_4)_2CO_3$ and filtered. The molybdenum is in the filtrate, the iron remains in the residue.

It is advisable to dissolve the residue in a little dilute IICl, pour this solution a hot solution of an excess of NaOII and again filter off the iron

hydroxide, adding the filtrate to the first lot.

The combined filtrates and washings are treated with about 5 ec. of a 50% tartaric acid solution or its equivalent in crystals. (This prevents W and V from separating out) and the solution saturated with H₂S. The thiomolybdate solution is made slightly acid with H₂SO₄ (1:2) MoS₃ precipitates. Further details are the same as those given on page 323.

For Acid Decomposition see procedure on page 322.

Steel and Iron. One to 2 grams of the drillings are dissolved, a mixture of 25 cc. HCl and 2 cc. HNO₃, additional HNO₃ (1:1) being added to oxidize the iron, if necessary. (KClO₃ crystals may be used.) A large excess of the oxidizing agent is to be avoided. The solution is evaporated to near dryness and the pasty residue taken up with about 25 cc. water and 10 cc. HCl, and gently heated. A yellow residue is due to WO₃. This is removed by filtration and washed. The filtrate contains the molybdenum. This is now treated according to the procedure given under "Separations" for removal of iron.

Separations

Separation of Molybdenum from Iron. The solution containing the molybdenum is treated very cautiously with 2 N.NaOH solution to neutralize the greater part of the free acid, but not with such an amount that would color the solution red. The yellow solution is heated to boiling.

In a separate vessel is placed 2 N.NaOH in sufficient quantity to combine with all the iron of the sample and about 50% excess (1 ce. of 2 N.NaOH = 0.1 g. Fe) 30 cc. should be sufficient. This solution is heated to boiling

and to it is added the hot solution containing the molybdenum. The sample should be added very slowly, preferably through a special funnel with capillary tube, stirring the solution vigorously during the addition. With care a complete separation of iron, free from molybdenum, may be effected, the molybdenum remaining in solution. The mixture is transferred to a 500 cc. volumetric flask.

The volume is made up to exactly 500 ec. and the precipitate allowed to settle. A portion is now filtered off, the first 5-10 cc. being rejected and the following 250 cc. of filtrate is retained for analysis of molybdenum.

Separation from the Alkaline Earths. Fusion of the substance with sodium earbonate and extraction of the melt with water gives a solution of molybdenum, whereas the earbonates of barium, calcium and strontium remain undissolved.

Separation from Lead, Copper, Cadmium and Bismuth. The sulphides of the elements are treated with sodium hydroxide and sodium sulphide solution and are digested by gently heating in a pressure flask. Molybdenum dissolves, whereas lead, copper, cadmium and bismuth remain insoluble. If the solution of the above elements is taken, made strongly alkaline, and treated with H₂S, the sulphides of the latter elements are precipitated and molybdenum remains in solution. The precipitates are filtered off and the filtrate containing molybdenum is placed in the pressure flask, the solution made slightly acid with sulphurie acid and the mixture heated under pressure, until the liquid appears colorless, MoS₂ is precipitated and may be converted into the oxide as described later.

Separation from Vanadium is effected by a molybdenum sulphide precipitation in acid solution.

Separation from Arsenic. Arsenic, present in the higher state of oxidation, is precipitated by magnesia mixture, added to a slightly acid solution (5 cc. of concentrated hydrochloric acid per 100 cc. of solution for each 0.1 gram arsenic). The solution is neutralized with ammonia (methyl orange), and the arsenic salt filtered off. MoS₂ is now precipitated with H₂S in presence of free sulphuric acid in the pressure flask.

Separation from Phosphoric Acld. Phosphorie acid is precipitated from an ammoniacal solution as magnesium ammonium phosphate. Molybdenum may then be precipitated as the sulphide from the filtrate.

Separation from Titanium. The metals of the ammonium sulphide group are precipitated by adding ammonium hydroxide and ammonium sulphide. Molybdenum remains in solution and passes into the filtrate. H₂S is passed into the solution until it appears red; sulphuric acid is then added until the solution is acid, when molybdenum sulphide precipitates.

Separation from Tungsten. Molybdenum may be precipitated by H₂S as MoS₂ in presence of tartaric acid. Tungsten does not precipitate.

Ether Extraction Method. Ether extracts not only iron but also molybdenum (see p. 248). The ether is evaporated off on a steam bath (avoid a free flame, as ether is inflammable) and the solution taken to near dryness. 10 cc. of sulphurie acid are added and hydrochloric acid expelled by concentration to fumes. After cooling, 100 cc. of water are added and 2-3 grams of ammonium bisulphite, to reduce the iron. The solution is boiled to expel the excess of SO₃ and molybdenum is precipitated by H₃S in a pressure flask. After cooling slowly, the sulphide, MoS, is filtered off, washed and ignited and weighed as MoO₂.

GRAVIMETRIC METHODS FOR THE DETERMINATION OF MOLYBDENUM

Precipitation as Lead Molybdate

Preliminary Remarks. This method, suggested by Chatard, has been pronounced by Brearly and Ibbotson to be "one of the most stable processes found in analytical chemistry." "It is not interfered with by the presence of large amounts of acetic acid, lead acetate, or alkali salts (except sulphates). The paper need not be ignited separately and prolonged ignition at a much higher temperature than is necessary to destroy the paper does no harm. From faintly acid solution lead molybdate may be precipitated free from impurities in the presence of copper, cobalt, nickel, manganese, zine, magnesium and mercury salts." It may be readily separated from iron and chromium. Barium, strontium, uranium, arsenie, cadmium and aluminum do not interfere if an excess of hydrochloric acid has been added to the solution followed by lead acctate and sufficient ammonium acctate to destroy the free mineral acid.

The method is not adapted to use with molybdenite, MoS2, because of the sulphate that forms on oxidation.

Vanadium and tungsten, if present, must be removed.

Special Reagents. Lead Acetate. A 4% solution is made by dissolving 20 grains of the salt in 500 cc. of warm water. A few cc. of acetic acid are added to clear the solution.

Precipitation of Lead Molybdate. The solution acidified with acetic acid (5 ec. per 200 ec.) and free from iron, is heated to near boiling and the lead acetate reagent added slowly until no further precipitation occurs and then about 5% excess. (1 cc. of the 4% lead acetate reagent will precipitate about 0.01 gram of molybdenum.) The precipitate is allowed to settle a few minutes and filtered hot into a weighed Gooch crucible or into a filter paper. (Refiltering first portion if cloudy.)1 The precipitate is washed with hot water until free of chlorides and the excess of the lead acetate.

The precipitate dried and ignited in a porcelain crucible at red heat for about twenty minutes is weighed as PbMoO.

> $PbMoO_4 \times 0.2615 = Mo$. $PbMoO_4 \times 0.3923 = MoO_3$. $Mo \times 3.8241 = PbMoO_4$. $MoO_2 \times 2.5491 = PbMoO_4$.

Determination of Molybdenum as the Oxide, MoO₃

Especially applicable where fusion with an alkali carbonate has been required. Decomposition of Ore. One gram of the ore is fused with 4 grams of fusion mixture, (Na₂CO₂+K₂CO₂+KNO₃), and the cooled melt extracted with hot water. If manganese is present, indicated by a colored solution, it may be removed

by reduction with alcohol, the manganese precipitate filtered off and washed with hot water, the solution evaporated to near dryness and taken up with water, upon addition of nitric acid as stated below.

The solution containing the alkaline molybdate is nearly neutralized by adding HNO, the amount necessary being determined by a blank, and to the cold, slightly alkaline solution, a faintly acid solution of mercurous nitrate is

Norg. Addition of ammonium nitrate to the solution tends to prevent formation of colloidal PbMoO4. Paper pulp (ashless) may be added to assist rapid filtration.

added until no further precipitation occurs. The precipitate consists of mercurous molybdate and carbonate (chromium, vanadium, tungsten, arsenic and phosphorus will also be precipitated if present). The solution containing the precipitate is boiled and allowed to stand ten to fifteen minutes to settle, the black precipitate is filtered off and washed with a dilute solution of mercurous nitrate. The precipitate is dried, and as much as possible transferred to a wntch-glass. The residue on the filter is dissolved with hot dilute nitric acid, and the solution received in a large weighed porcelain crucible. The solution is evaporated to dryness on the water bath and the main portion of the precipitate added to this residue, and the product heated cautiously over a low flame i until the mercury has completely volatilized. The cooled residue is weighed as MoO₃.

$MoO_3 \times 0.6667 = Mo.$

Note. If Cr, V, W, As or P are present a separation must be effected. Molybdenum should be precipitated in an H₂SO₄ solution in a pressure flask as the sulphide by H₂S as given in the following method, and arsenic if present removed by magnesia mixture as indicated in the procedure for separation of arsenic from molybdenum. If these impurities are present the molybdenum oxide may be fused with a very little Na₄CO₄, and leached with hot water and the filtrate treated with H₂S as directed.

Precipitation of Molybdenum as the Sulphide by H₂S

A. Precipitation from Acid Solution. By this procedure molybdenum is precipitated along with members of the hydrogen sulphide group, if present, but free from elements of the following groups:

The cold molybdenum solution slightly acid with sulphuric acid (in presence of Ba, Sr or Ca an HCl solution is necessary) is placed in a small pressure flask and saturated with H₂S, the flask closed and heated on the water bath until the precipitate has settled. The solution is cooled and filtered through a weighed Gooch crucible.

B. Precipitation from an Ammoniacal Solution. By this procedure molybdenum is precipitated with antimony, arsenic, tin if present, but is free from mercury, lead, bismuth, copper and eadmium.

Hydrogen sulphide is passed into the cold ammoniaeal solution of molybdenum (in presence of tungsten or vanadium add tartarie acid) until it assumes a bright red color, it is now acidified with dilute sulphuric acid, the precipitate allowed to settle and the solution filtered through a weighed Gooch crucible.

In either case A or B the precipitate is washed into the Gooch crucible with very dilute sulphuric acid followed by several washings with the acid and then with alcohol until free from acid. The Gooch is placed within a larger nickel crucible and covered with a porcelain lid. After drying at 100° C. it is placed over a small flame and carefully heated until the odor of SO₂ can no longer be detected. The cover is now removed and the open crucible heated to constant weight. The residue consists of MoO₂.

$MoO_2 \times 0.6667 = Mo.$

Note. Arsenic will contaminate the residue if present. The method for its removal has been given.

¹ The oxide, MoO₂, sublimes at bright red heat. The volumetric method is more reliable. See page 319.

VOLUMETRIC METHODS FOR THE DETERMINATION OF MOLYBDENUM OR MOLYBDIC ACID

The Iodometric Reduction Method 1

Principle. When a mixture of molybdic acid and potassium iodide in presence of hydrochloric acid is boiled, the volume having defined limits, free iodine is liberated and expelled and the molybdic acid reduced to a definite lower oxide; by titrating with a standard oxidizing agent the molybdic acid is determined.

Reaction. $2\text{MoO}_2+4\text{Kl}+4\text{HCl}=2\text{MoO}_2\text{I}+\text{I}_2+4\text{KCl}+2\text{H}_2\text{O}$.

Reagents. N/10 solutions of iodine, sodium arsenite, potassium permanganate, sodium thiosulphate.

Analytical Procedure.² Reduction. The soluble molybdate in amount not exceeding an equivalent of 0.5 gram MoO₃ is placed in a 150-cc. Erlenmeyer flask, 20 to 25 ec. of hydrochloric acid (sp.gr. 1.2) added together with 0.2 to 0.6 gram potassium iodide. A short stemmed-funnel is placed in the neck of the flask to prevent mechanical loss during the boiling. The volume of the solution should be about 60 cc. The solution is boiled until the volume is reduced to exactly 25 cc. as determined by a mark on the flask. The residue is diluted immediately to a volume of 125 cc. and cooled. Either process A or B may now be followed.

A. Reoxidation by Standard Iodine. A solution of tartaric acid, equivalent to 1 gram of the solid, is now added, and the free acid nearly neutralized with sodium hydroxide solution (litmus or methyl orange indicator) and finally neutralized with sodium acid carbonate, NaHCO₃, added in excess. A measured amount of N/10 iodine is now run in. The solution is set aside in a dark closet for two hours, in order to cause complete oxidation, as the reaction is slow. The excess iodine is now titrated with N/10 sodium arsenite.

One ee. N/10 iodine = .0144 gram $MoO_3 = .0096$ gram Mo.

On long standing a small amount of iodate is ant to form. This is determined by making acid with dilute HCl and titrating with N/10 sodium thiosulphate.

B. Reoxidation of the Residue by Standard Permanganate. To the reduced solution about 0.5 gram of manganese sulphate in solution is added, followed by a measured amount of N/10 permanganate solution, added from a burette until the characteristic pink color appears. A measured amount of standard N/10 sodium arsonite, equivalent to the permanganate is then run in and about 3 grams of tartaric acid added. The acid is neutralized by acid sodium or potassium carbonate, the stopper and the sides of the flask rinsed into the main solution. The residual arsenite is now titrated by N/10 iodine, using starch indicator.

Notes. Tartaric acid prevents precipitation during the subsequent neutralization with NaHCO₄. A and B.

The addition of manganese salt in B is to prevent the liberation of free chlorine by the action of KMnO₄ on HCl.

In addition to the oxidation of the lower oxides to molybdie acid, potassium permanganate added in B liberates free iodine from 111, it produces iodic acid, and forms the higher oxides of manganese. The standard arsenite, on the other hand, converts free iodine and the iodate to HI and reduces the higher oxides of manganese.

¹ F. A. Gooch and Charlotte Fairbanks, Am. Jour. Sc. (4), 2, 160. ² F. A. Gooch and O. S. Pulman, Jr. Am. Jour. Sc. (4), 12, 449.

Estimation by Reduction with Jones Reductor and Oxidation by Standard Permanganate Solution

Principle. The procedure depends upon the reduction of molybdic acid to Mo₂O₂ by passing its solution through a column of amalgamated zinc into a solution of ferric alum, and subsequent oxidation to MoO₂ by standard potassium permanganate solution.

Reactions. $2\text{MoO}_3 + 3\text{Zn} = \text{Mo}_2\text{O}_3 + 3\text{ZnO}_2$

 $5Mo_2O_3 + 6KMnO_4 + 9H_2SO_4 = 10MoO_3 + 3K_2SO_4 + 6MnSO_4 + 9H_2O_4$

Reagents. Potassium permanganate approximately N/10 standardized against a standard molybdic acid solution.

10% solution of ferric alum.

2.5% solution of sulphuric acid.

Apparatus. Jones Reductor.

R=reductor tube 50 cm. long, 2 cm. inside diameter. Smaller tube prolongation length 20 cm. inside diameter 0.5 cm.

20 em. inside diameter 0.5 em. Zn = column of zinc 40 cm. long. Zn shot 8 mesh to sq.em.;

F = receiving flask;

P=pressure regulator with gauge, set to give pressure in receiving flask of less than 20 cm.

G = platinum eone or gauze with mat of fine glass wool 2 em. thick;

The zine in reductor should be protected from the air by covering with water, stop-cock S being closed when not in use.

Procedure. The receiving flask of the Jones reductor, Fig. 49, is charged with about 30 ec. of 10% ferric alum and 4 ec. of phosphoric acid. Through the 40-cm. column of amalgamated zinc in the reductor are passed in succession 100 ec. of dilute sulphuric acid (2.5% sol.), the molybdic acid in the form of ammonium molybdate dissolved in 10 ec. of water and acidified with 100 ec. of dilute sulphuric acid followed by 200 ec. more of the




Fig. 49.—Jones Reductor.

dilute sulphuric acid and 100 cc. of water. The reduced green molybdic acid upon coming in contact with the ferric alum solution produces a bright red color.

The solution is titrated with N/10 KMnO₄ solution

One cc. of N/10 KMnO₄ =
$$\frac{.0144}{3}$$
 gram MoO₃ = $\frac{.0096}{3}$ gram molybdenum.

¹ W. A. Noyes and Frohman, Jr. Am. Chem. Soc., 35, 919. After a thorough examination of the various methods for determining molybdenum, Messrs. Smoot, Lundell and Holladay pronounce this method to be superior to any other.

Notes on Reductor Technique

Use of the following greatly simplified and correspondingly more rapid reductor technique is recommended by J. A. Holladay.

1. The reductor should contain a column of 20 x 30 mesh amalgamated zinc 3" in diameter and 10 inches long. If the molybdenum solution is given a preliminary reduction by heating with 2 grams of 20 mesh zinc for the purpose




Fig. 49a.—Reductor Tube.

- of precipitating copper (which is subsequently removed by filtration on asbestos), the length of the zine column may safely and advantageously be reduced to 8". The lengths specified apply only to a column \(\frac{3}{4}\)" in diameter; the lengths for tubes of different diameters would have to be determined experimentally. The zine should be as free from iron and as low in other impurities as possible.
- 2. If the reductor has been standing idle for longer than one day it is cleaned by passage of 50 ce. of 6% sulphuric acid, and 50 ce. of water, both at room temperature, a small amount of the water being left in the funnel which forms the reductor inlet. The acid and water are discarded after having been passed through the reductor. These operations are only necessary when the reductor has been standing idle for some time.
- 3. The required amount of ferrie phosphate solution and sufficient water (about 50 cc.) to cause the tip of the reductor outlet tube to dip beneath the surface of the liquid are added to the flask.
- 4. The molybdenum solution (volume 50 to 100 ec., acidity 6% H₂SO₄) which may be at room temperature or slightly warm, is passed through the reductor rapidly. The total time required for the passage of the molybdenum solution and the liquids which follow it need not exceed from 1 to 3 minutes. No advantage results from having the solution hot—on the contrary, the greater action of the hot acid solution on the zine is a disadvantage. No increase in accuracy is obtained by passing the solution through the reductor at a slower rate than that specified.
- 5. When the funuel which forms the inlet of the reductor is nearly but not entirely empty, 150 ec. of water at room temperature are passed through the reductor. In the case of samples containing relatively small amounts of molybdenum, 100 ec. of water is sufficient. In no case is the funnel

permitted to become entirely empty and the stopcock is closed while some of the wash water remains above the surface of the zinc.

Note. It is unnecessary to have this solution hot as is sometimes recommended. This statement is confirmed by recent work of G. E. F. Lundell and H. B. Knowles, U. S. Bureau of Standards, Ind. Eng. Chem.

Method for Determining Molybdenum and Vanadium in a Mixture of their Acids

Principle of the Method. The procedure depends upon the fact that vanadic acid alone is reduced by SO₂¹ in a sulphuric acid solution, whereas both vanadic and molybdic acids are reduced by amalgamated zinc, in each case the reducing agents forming definite lower oxides which are readily oxidized to definite higher oxides by KMnO₄.

Reactions.

SO2 Reduction:

1. $V_2O_6 + SO_2 = V_2O_4 + SO_3$. (No action on MoO₃.)

Zn Reduction:

- 2. $V_2O_5 + 3Zn = V_2O_2 + 3ZnO$.
- 3. $2\text{MoO}_3 + 3\text{Zn} = \text{Mo}_2\text{O}_3 + 3\text{ZnO}_3$

KMnO4 Oxidation:

- 4. $5V_2O_4 + 2KMnO_4 + 3H_2SO_4 = 5V_2O_5 + K_2SO_4 + MnSO_4 + 3H_2O_5$
- 5. $5V_2O_2 + 6KMnO_4 + 9H_2SO_4 = 5V_2O_5 + 3K_2SO_4 + 6MnSO_4 + 9H_2O_5$
- 6. $5\text{Mo}_2\text{O}_3 + 6\text{KMnO}_4 + 9\text{H}_2\text{SO}_4 = 10\text{MoO}_3 + 3\text{K}_2\text{SO}_4 + 6\text{MnSO}_4 + 9\text{H}_2\text{O}_4$

From the reactions "4" and "5" it is seen that three times the amount of $KMnO_4$ is required to oxidize V_2O_2 to V_2O_3 as is required in the case of V_2O_4 , hence—total cc. $KMnO_4$ required in oxidation of the zine-reduced oxides minus three times the cc. $KMnO_4$ required in oxidizing the tetroxide of vanadium formed by the sulphur dioxide reduction =cc. $KMnO_4$ required to oxidize Mo_2O_4 to MoO_3 . From these data molybdenum and vanadium may readily be calculated.

Method of Procedure. A. Vanadic Acid. The solution containing the vanadic and molybdic acids in a 250- to 300-cc. Erlenmeyer flask, is diluted to 75 cc. acidified with 2 to 3 cc. of strong sulphnric acid, heated to boiling and the vanadic acid reduced by a current of SO_2 passed into the solution until the clear blue color indicates the complete reduction of the vanadic acid to V_2O_4 . The poiling is now continued and CO_2 passed into the flask to expel the last trace of SO_2 .

Standard N/10 KMn() is now run into the reduced solution to the characterstic faint pink. From reaction "4," vanadic acid may be calculated.

One ce. N/10 KMnO₄ = .0182 gram V_2O_5 = .0051 gram vanadium.

B. Molybdie Acid. The reduction by Jones' reductor, and titration of the combined acids reduced by amalgamated zinc with N/10 potassium permanganate obution, is carried out exactly as described in the determination of molybdie wid alone. In this case 50 ec. of 10% ferric alum and 8 cc. of the phosphoric wid is placed in the receiving flask.

Calculation. Total permanganate titration in B minus three times the titration A gives the permanganate required to oxidize Mo_2O_3 to MoO_3 . From equation i the molybdic acid may now be calculated.

One cc. N/10 KMnO₄ =
$$\frac{.0144}{3}$$
 gram MoO₃ = $\frac{.0096}{3}$ gram molybdenum.

¹Reduction of vanadium by SO₂ in presence of molybdenum, Graham Edgar, 1m. Jour. Sc., (4) 25, 332. No reduction of MoO₂ when 0.4 gram is present with 5 cc. 1₂SO₄ in 25 cc. volume.

For theoretical considerations and data on accuracy of method see "Methods a Chemical Analysis," F. A. Gooch.

DETERMINATION OF MOLYBDENUM IN ORESI

The commercial ores of molybdenum are molybdenite, the native sulphide (MoS₂), and wulfenite, lead molybdate. Occasionally molybdenum ochre (the trioxide) may be met with, but this mainly occurs in very small proportion associated with molybdenite as an oxidation product of the sulphide.

Molybdenite is sold either as high grade selected mineral or as concentrates which are usually the product of flotation processes. The important determinations in molybdenite are molybdenum, arsenic, copper and phosphorus; sometimes bismuth is present and occasionally lead.

Owing to the complex nature of wulfenite the determination of molybdenum is more difficult and the number of impurities which may be sought for is much greater.

The following methods for the determination of molybdenum in commercial ores and concentrates are the result of co-operative work between the laboratories of the Electro Mctallurgical Company and Ledoux & Company. It is believed that all important sources of error have been considered and eliminated so far as the usual commercial ores are concerned.

Determination of Molybdenum in Wulfenite or Molybdenite

One gram of the finely ground ore is dissolved by treatment with 15 ce. of nitric acid (sp.gr. 1.42) and 7 cc. of sulphuric acid (sp.gr. 1.84) at a temperature just short of boiling in a 150 cc. covered beaker. When practically complete decomposition has been effected, the liquid is evaporated until fumes of sulphur trioxide are freely expelled. After cooling addition is made of about 40 cc. of water, the solution is boiled to dissolve the molybdcnum, cooled to room temperature and filtered into a 250 cc. beaker. The residue, consisting of lead sulphate, silica, etc., is washed with very dilute H2SO4. The residue rarely, if ever, contains Mo, nevertheless it should be examined to make sure that decomposition is complete. To this end it is digested with 15 cc. to 25 cc. of ammonium acetate solution (prepared by mixing 8 ec. of (NH4)OH (0.90) with 10 cc. H₂O and adding 7 ce. of 99% C₂H₄O₂) to remove all lead sulphate. The filter paper is washed with hot dilute acetic acid and with water. It is then ignited in a platinum crucible and the silica is removed by treatment with a drop of sulphuric acid and several cc. of hydrofluoric acid and evaporating to the expulsion of sulphuric acid. If an appreciable residue remains after this treatment, it is fused with potassium pyrosulphate and tested for molybdenum by means of tartaric acid and ammonium sulphide as described later.

'To the solution containing all of the molybdenum there is added sufficient ferric sulphate to provide ten times as much iron as there is arsenic present: from 0.2 to 0.3 gram of iron is usually ample. The acid solution is then nearly neutralized with ammonia (addition of a sufficient amount to impart a red tint to the clear yellow solution is to be avoided), heated nearly to boiling and poured very slowly and with vigorous stirring into 75 cc. of warm ammonia solution (15 cc. (NH₄)OH 1.90 sp.gr. 60 cc. H₂O) contained in a 250 cc. beaker. When it has settled the ferric hydroxide (which will carry down quantitatively all arsenic in the ore) is filtered and washed thoroughly with hot water; it is then dissolved in a slight excess of hot dilute (1 to 4) sulphuric acid and the resulting solution is again heated to boiling and poured into 75 cc. of warm

¹ By James A. Holladay and A. M. Smoot.

ammonia solution as before; the iron hydrate is again washed. The two filtrates, which will contain all the molybdenum, are collected in a 600 cc. beaker. It is essential that arsenic, which is usually present in these orcs, be eliminated, and the method described furnishes a simple and effective way for accomplishing this. The addition of ferric sulphate would be omitted only in case arsenic is known to be absent or when the ore itself carries sufficient iron to take care of the arsenic.

To the combined ammoniacal filtrates there are added 2 grams of tartaric acid and when the acid has dissolved the liquid is saturated with hydrogen sulphide. The presence of tartaric acid is necessary to prevent precipitation of vanadium and tungsten along with the molybdenum. Both of these elements are ordinary constituents of wulfeuite concentrates. Under these conditions the molybdenum remains in the solution as ammonium thiomolybdate, (NH₄)₂MoS₄, which imparts a deep red color to the solution. If a small precipitate of insoluble sulphides separates out, it is filtered off and washed with dilute ammonium sulphide solution; if the solution remains clear this step is omitted. Copper in the amounts usually present remains entirely in solution at this point and is reprecipitated with molybdenum when the solution is subsequently acidified. The thiomolybdate solution is then made slightly acid with sulphuric acid (1 to 2). Molybdenum is thus precipitated as trisulphide.

The cessation of efferveseense on addition of more acid and the disappearance of the red color of the ammonium thiomolybdate mark the point where sufficient acid has been added to complete the reactions.

After heating for a short time, the precipitate is allowed to settle and filtered on an 11 cm. paper and washed thoroughly with hydrogen sulphide water containing a small amount of sulphuric acid.

The filtrate from the molybdenum sulphide sometimes contains appreciable amounts of molybdenum; addition is made to it of 15 cc. of nitric acid (sp.gr. 1.42) and the solution is evaporated to fumes of sulphur trioxide, more sulphuric acid being added if sufficient is not already present. After allowing it to cool, 5 cc. of concentrated nitric acid are added and the solution is again evaporated to fumes. The addition of nitric acid and evaporation to strong fumes is repeated once more to insure the destruction of all organic compounds. After allowing to cool, sufficient water is added to dissolve all salts, two grams of tartaric acid are added, and after addition of an excess of ammonia (sp.gr. 0.90) the warm liquid is thoroughly saturated with washed hydrogen sulphide and filtered. The filtrate is acidified with sulphuric acid (1 to 2) and if after standing for fifteen to thirty minutes in a warm place any molybdenum trisulphide has separated out it is filtered, washed well with hydrogen sulphide water containing a small amount of sulphuric acid, and combined with the main precipitate. The precipitation of the molybdenum as sulphide when carried out as described effects the separation and removal of tungsten, vanadium and chromium.

The molybdenum sulphide precipitate and paper, or precipitates and papers, are put into a 250 cc. beaker and treated with 6 cc. of sulphuric acid (sp.gr. 1.84) and 10 cc. of nitric acid (sp.gr. 1.42) and the liquid is cautiously boiled until dense fumes of sulphur trioxide are freely evolved. After allowing it to cool somewhat, 5 cc. of nitric acid (sp.gr. 1.42) are added and the evaporation is repeated. The evaporation with 5 cc. portions of strong nitric acid is repeated several times until the filter paper has been completely destroyed and

every trace of yellow color, due to carbonaceous matter, has disappeared. When this has been accomplished the solution is fumed strongly for a short while, cooled, 5 cc. of water are added and the liquid is again taken to fumes of sulphur trioxide in order to insure the expulsion of every trace of nitric acid. When cool, addition is made of approximately 75 cc. of water and the contents of the beaker are boiled for a few minutes, which should give a perfectly clear solution. Five grams of granulated zine (0.002% iron or under) are then added and the solution is warned until most of it has dissolved; this results in partial reduction of molybdenum and complete precipitation of copper, which is usually present. The liquid is then filtered on an asbestos or "alundum" filter to remove the undissolved zine and the copper.

All the molybdenum in the solution is then reduced from the sexivalent to the trivalent condition by passage through the zine reductor into a solution of ferrie sulphate containing phosphoric acid—the solution is then titrated with N/10 permanganate. The details of the reductor and the method of preparing it are given on page 319 and 320.

It is essential to run a blank determination, using the same quantity of zine that was used to separate copper and the same volumes of water and acid—passing the solution through the reductor under the same conditions. With good zine the correction may be about 0.2 ec.

Method for Molybdenum in Pure Molybdenite Concentrates

Molybdenum may be determined in the same way as in wulfenite, but owing to the higher Mo content of the material only 0.5 gram may be taken for the determination.

In ease of very pure and high-grade molybdenite, which rarely contains any interfering element except traces of arsenic, the method may be simplified.

It suffices to treat 0.5 gram of the pulp with 10 ee. of strong HNO₃ and 7 ee. of H₂SO₄ and evapoate to fumes. A single treatment usually results in complete decomposition, but if the solution shows any particle of undecomposed material a further addition of 5 ee. of HNO₃ and a second evaporation to fumes may be necessary. In order to remove all HNO₃, the H₂SO₄ solution is diluted by washing down the sides of the beaker with 5 ee. of water and the evaporation to fumes is repeated.

After cooling, 35 cc. of water and ferrie sulphate equivalent to about 0.1 gram of metallic iron are added. The solution is poured into an ammonia solution, the same as in the longer method, the iron hydrate earrying any arsenic is filtered off, dissolved in H₂SO₄ and reprecipitated. The united filtrates contain all the molybdenum; they are concentrated by evaporation to a volume of 150 cc. which also serves to expel the excess of ammonia. The solution is acidulated with H₂SO₄, reduced and titrated as in the longer method.

This method, of course, is not applicable in the presence of vanadium, tungsten or other impurities which might be reduced and reoxidized in the final operations, but it serves very well for the analysis of high grade molybdenite.

Determination of Commonly Occurring Substances in Molybdenum Ores

Determination of Arsenic

Two grams of the 100-mesh sample are treated with 20 cc. of nitric acid (sp.gr. 1.42) and 7 cc. of sulphuric acid (sp.gr. 1.84) in a 150 cc. beaker. The liquid is heated for a short time at a temperature just below the boiling point and is then evaporated until fumes of sulphuric anhydride are freely evolved. The residue is taken up with 40 cc. of water and boiled for a few minutes. Approximately one gram of cuprous chloride and five grams of ferrous aminonium sulphate are added, and transfer is made of the solution to the distillation flask of the apparatus shown on page 39, arsenic chapter, the beaker being rinsed with 40 ec. of hydrochloric acid (sp.gr. 1.20). It is important that the amount of water used be kept to a minimum so as to insure presence of sufficiently concentrated hydrochloric acid in the distillation flask to rapidly and completely volatil-

ize the arsenic.

For distillation of the arsenic, the Knorr Arsenic and Antimony Distillation Apparatus (mentioned above see page 39) is very satisfactory. The rate at which arsenic distills over is greatly influenced by the size and form of apparatus employed; by use of the Knorr apparatus it is rapidly and completely volatilized. After having attached the flask, the inlet funnel is filled about half full of hydrochloric acid (sp.gr. 1.20). The outlet of the condenser tube is caused to dip just beneath the surface of 100 cc. of distilled water in a 350 cc. beaker containing a lump of ice. The solution in the distillation flask is heated to boiling; concentrated hydrochloric acid is introduced through the funnel tobe drop by drop at a rate sufficient to replace the evaporation, or in other words, in amount sufficient to keep the level of liquid in the flask constant. It is necessary to keep a steady flame under the flask; if the solution in the beaker starts to be sucked hack into the condenser tube, the apparatus is quickly raised so as to lift the lower end of the condenser out of the distillate. All of the arsenic will usually distill over in 30 or 35 minutes; at the end of this time the beaker holding the condensate is replaced by another one containing about 100 cc. of water and a lump of icc, and the distillation is continued for another 15 minutes. The second distillate is tested separately to

determine whether it contains any arsenic.

By the above described procedure the arsenic is separated from any other elements likely to be present by volatilization as arsenious chloride, AsCl₃; it may be determined in the resulting solution by either gravimetric or volumetric methods. Where only occasional determinations have to be made, the gravimetric method is perhaps the more convenient. The hydrochloric acid distillate is warmed and saturated with hydrogen sulphide by passage of a rapid stream of gas. Filtration is made of the arsenious sulphide, As₂S₃, and it is washed with hydrogen sulphide water. The yellow precipitate is dissolved in the least necessary amount of annionia (1 to 1) and the paper washed the stream of the control is uissoived in the least necessary amount of ambioma (1 to 1) and the paper washed with hot water; the volume is kept as low as possible, the filtrate being received in a 150 cc. beaker. To the filtrate there are added 6–10 cc. of "perhydrol" (30% H₂O₂) for every 0.1 gram of arsenic supposed to be present; if "perhydrol" is not available, there are used instead 60–100 cc. of 3% hydrogen peroxide (free from phosphorus), but use of the former is preferable since it permits keeping the volume small. It is essential that enough hydrogen peroxide be used to oxidize the assenic completely. essential that enough hydrogen peroxide be used to oxidize the arsenic completely to the arsenic condition. Some commercial brands of hydrogen peroxide contain considerable amounts of phosphorus, making it always necessary to determine it and make a correction for the weight of magnesium pyrophosphate formed from it which would otherwise be counted as arsenic. The resulting solution is evaporated on a hot plate for some time, boiled for ten minutes with the cover glass on, and cooled in ice water. Ten ec. of "magnesia mixture" are added, followed by ammonia (sp.gr. 0.90) to the extent of one-third the volume of the solution, and the liquid is stirred vigorously for some time and then allowed to stand in a cool place for at least 15 hours. The magnesium ammonium arsenate is filtered on a weighed Gooch erueible and washed 10-15 times with small amounts of cold 2.5% ammonia water. It is then drained as completely as possible by suction, dried at 105° C., and heated gradually in an electric muffle furnace to a temperature of 400°-500° C. until no more ammonia is evolved. The temperature is then increased to 800°-900° C. and kept there for about 10 minutes. After having cooled the crucible in a desiceator and weighed it, the amount of arsenic is calculated from the weight of magnesium pyroarsenate, Mg₂As₂O₇, which contains 48.27% arsenic. A "blank" must be run on the reagents used and any arsenic found be deducted.

When more than occasional analyses have to be made, the following volumetric method can be used to advantage; the only superiority of the gravimetric process is that visual evidence of the presence of arsenic is furnished by the yellow arsenious that visual evidence of the presence of arsenic is furnished by the yellow arsenious sulphide. The distillate containing the arsenic in the form of arsenious chloride, As₂Cl₂, is made slightly ammonical, litmus paper being used as indicator, and the solution being kept cool. Sufficient sulphuric acid (1 to 1) to render the liquid slightly acid is next added. To the cold, slightly acid solution there is added 8–10 grams of sodium bicarbonate, 0.3 gram of potassium iodide and several cc. of starch solution (a water solution of Kahlbaum's "Lösliche Starke" or soluble starch is used) and the solution is tituted with a standard liquid solution cash on of which is acqual to 0.001 solution is titrated with a standard iodine solution each ee, of which is equal to 0.001 gram of arsenie. The titration is based on the reaction:

 $KH_2A_8O_3 + l_2 + 2N_8HCO_2 = KHA_8O_4 + 2N_8l + 2CO_2 + H_2O_3$

The reaction between arsenic and iodine is shown by the equation:

 $As_2O_3 + 2l_2 + 2H_2O = As_2O_6 + 4H1.$

A "blank" must be run and deducted.

The iodine solution is prepared by dissolving 3.5 grams of pure resublimed iodine with 7 grains of potassium is include and a very small amount of water. When the iodine has completely dissolved, the solution is diluted to I liter and mixed thoroughly; it is standardized against pure As₂O₃. This is accomplished by carefully weighing 0.0600 gram of pure resublimed As₂O₃ and transferring it to a 350 cc. beaker. Eight to ten grams of sodium bicarbonate and sufficient hot water to dissolve it are added and the solution is heated until the As₂O₃ has completely dissolved. The solution is then diluted to 250 ec., cooled, 0.3 gram of potassium iodide and 2-3 cc. of starch solution are added and the liquid is titrated with the iodine solution to the usual blue end point. The weight of As₂O₃ used (0.0600 gram) contains exactly 0.04545 gram of arsenie so the number of ec. used in the titration, divided into 0.04545, gives the arsenic value of one oc. of the iodine.

Determination of Copper

(a) In Molybdenite. Four grams of finely ground sample are treated with 35 cc. of nitric acid (sp.gr. 1.42) and 10 cc. of sulphuric acid (sp.gr. 1.84) in a 250 cc. beaker provided with a clock-glass cover. The solution is digested at a temperature somewhat below the boiling point until most of the molybdenite has dissolved. Subsequently the liquid is boiled until strong fumes of sulphur trioxide are expelled. After having allowed the beaker and its contents to cool, 50 cc. of water are added and the solution is boiled briskly for a few minutes and filtered on a 9 cm. paper into a 250 cc. beaker. The residue is washed thoroughly with hot water and discarded.

An excess of sodium hydroxide solution is added to the filtrate and the solution is boiled for several minutes and filtered on a 9 cm. paper. The precipitate of ferric hydroxide, etc., is washed with lot water to remove the molybdenum. Solution is then made of this precipitate, which will contain all of the copper, in 30 cc. of hot dilute (1 to 3) sulphuric acid, the paper being washed with about 50 cc. of hot water and the

filtrate and washings being collected in a 150 cc. beaker.

The copper in the solution obtained as above described is completely precipitated in the metallic condition by placing a sheet of pure aluminum (conveniently bent into the form of a triangle 1 inch in height which stands on its edge in the beaker) in the beaker and boiling for about ten ininutes. Complete precipitation is not obtained until the iron has been reduced, when the aluminum should appear clean and the precipitated copper be detached or only loosely adherent. After removal from the source of heat, the clock glass and sides of the beaker are rinsed with a jet of hydrogen sulphide water. The aluminum, the copper content of which should be accurately determined, is weighed before and after use and a correction is applied for the copper introduced from it.

Filtration is made of the solution on a very small filter paper, the copper being transferred to the paper and the aluminum being left as clean as possible in the beaker. The precipitate is washed with hot water and the filtrate and washings are discarded. Solution is then made of the copper in 5 cc. of hot nitric acid (1 to 1), this being accomplished by first dropping the acid over the aluminum and then pouring it on the copper. The aluminum and filter paper are both washed with bot water, the filtrate and washings being collected in a 100 cc. lipless beaker. After boiling the solution to expel oxides of nitrogen, 2 cc. of sulphuric acid (sp.gr. 1.84) are added and determination is made of the copper by electrolysis, a platinum gauze cathode and spiral anode being employed.

Determination of Copper

(b) In Wulfenite. Four (4.0000) grams of the 100-mesh sample are treated with approximately 30 cc. of 10% sodium hydroxide solution in a 250 cc. beaker provided with a clock-glass cover. The solution is boiled briskly for 10 minutes, which is usually sufficient to insure practically complete decomposition of the wulfenite. Addition is then made of about 70 cc. of hot water and the precipitate of iron oxide, etc., which will contain all of the copper, is allowed to settle. The supernatant liquid is decanted through a 9 cm. filter paper and the precipitate is then transferred to the paper and washed well with hot water. The filtrate and washings are discarded. As a result of these operations separation of the copper from practically all of the molybdenum and from the greater part of the lead is accomplished.

The paper containing the residue is returned to the original 250 cc. beaker and treated with 6 cc. of sulphuric acid (sp.gr. 1.84) and 10 cc. of nitric acid (sp.gr. 1.42). The contents of the beaker are cautiously heated until frothing is nearly over, and then boiled briskly until fumes of sulphuric anhydride are evolved. After having permitted the liquid to partly cool, 10 cc. of nitric acid (sp.gr. 1.42) are added and the evaporation to fumes is repeated. The cover glass and sides of the beaker are cleaned with a few cc. of water and the solution is once more evaporated to fumes in order to insure destruction

of all carbonaceous matter from the filter paper and complete expulsion of nitric acid. In practice the total time consumed in making these evaporations is small.

Having allowed the beaker and its contents to cool somewhat, addition is made of 50 cc. of water and the solution is boiled for a short while, cooled, and filtered on a 9 cm. paper into a 150 cc. beaker. The precipitate of lead sulphate, etc., is washed with cold 10% sulphuric acid and discarded, the copper passing completely into the filtrate and washings, which should have a total volume of not more than 100 cc.

The copper in the solution obtained as above described is completely precipitated in the metallic condition by placing a sheet of pure aluminum (conveniently bent into the form of a triangle 1 inch in height which stands on its edge in the beaker) in the beaker and boiling for about ten minutes. Complete precipitation is not obtained until the iron has been reduced, when the aluminum should appear clean and the precipitated copper be detached or only loosely adherent. After removal from the source of heat, the clock-glass and sides of the beaker are rinsed with a jet of hydrogen sulphide water. The aluminum, the copper content of which must be accurately determined, is weighed before and after use and a correction is applied for the copper introduced into the solution from it.

Filtration is made of the solution on a very small filter paper, the copper being transferred to the paper and the aluminum being left as clean as possible in the beaker. transferred to the paper and the aluminum being left as clean as possible in the beaker. The precipitate is washed with hot water and the filtrate and washings are discarded. Solution is then made of the copper in 5 cc. of hot nitric acid (1 to 1), this being accomplished by first dropping the acid over the aluminum and then pouring it on the copper. The aluminum and filter paper are both washed with hot water, the filtrate and washings being collected in a 100 cc. lipless beaker. After boiling the solution to expel oxides of nitrogen, 2 cc. of sulphuric acid (sp.gr. 1.84) are added and determination is made of the copper by electrolysis a relatinguar gauge cathode and spiral anode being employed. the copper by electrolysis, a platinum gauze cathodc and spiral anode being employed.

Determination of Phosphorus

(a) Molybdenite. Four grains of the finely ground sample are treated with 35 cc. of mitric acid (sp.gr. 1.42) and 10 cc. of sulphuric acid (sp.gr. 1.84) in a 250 cc. beaker provided with a cover glass. The liquid is heated at a temperature somewhat below the boiling point until decomposition of the mineral appears to have been secured, when it is boiled until strong fumes of sulphuric anhydride are given off. When the residue has cooled, 40 cc. of water are added and the solution is boiled for several minutes and filtered on a 9 cm. paper into a 300 cc. Erlenmeyer flask. The residue is washed well with het make the cooled and the solution is boiled for several minutes and filtered on a 9 cm. paper into a 300 cc. Erlenmeyer flask. with hot water, ignited in a porcelain crucible and transferred to a platinum crucible and evaporated with 2 or 3 drops of sulphuric acid (sp.gr. 1.84) and several cc. of hydrofluoric acid. After completely expelling the sulphuric acid, any small residue remaining is fused with a pinch of potassium pyrosulphate and dissolved in water and added to the main solution.

A few drops of strong permanganate solution (25 grams per liter) are added to the solution obtained as previously described, and it is boiled to insure complete oxidation of the phosphorus to the tribasic condition. Just sufficient sulphurous acid to decompose the excess of permanganate or separated manganese oxide is then added and the boiling is continued for a few minutes longer. A slight excess of ammonia is added and the ferric hydroxide, etc., which will carry down practically all of the phosphorus, is filtered and washed thoroughly with hot water. Solution is made of the precipitate in hot dilute (sp.gr. 1.135) nitric acid and the phosphorus is precipitated with "molybdate

solution" and determined as described for wulfenite.

(b) Wulfenite. Two (2.000) grams of the agate ground sample of wulfenite are treated with 20 ec. of nitric acid (sp.gr. 1.42) and 10 ec. of sulphurie acid (sp.gr. 1.84) in a 150 ec. beaker. The liquid is heated for a short while at a temperature just below the boiling point and then boiled until funes of sulphurie anhydride are freely evolved. The residue is taken up with 40 ec. of water, boiled a few minutes, cooled, filtered into a 300 ec. Erlenmeyer flask, and the lead sulphate, silica, etc., are washed with cold 10% sulphurie acid and discarded.

A few drops of strong permanganate solution (25 grams per liter) are added to the filtrate from the lead sulphate and it is boiled to insure complete oxidation of the phosphorus to the tribusic condition. Just sufficient sulphurous acid is added to decompose the excess of permanganate or separated manganese oxide and the boiling is continued

for a minute or two longer.

The acid solution is nearly neutralized with ammonia, partly cooled, and to it there are added one gram of tartaric acid and then a slight excess of ammonia. If less than 2 grams of sample should be employed, as in case of very high phosphorus ores, correspondingly less tartaric is to be used, since an excess tends to prevent complete precipi-

tation of the phosphorus.

Twenty ce. of "magnesia mixture" and 4 or 5 glass beads (6 mm. diameter) are added to the warm solution and it is thoroughly chilled by immersion in a mixture of crushed ice and salt. The contents of the flask arc then vigorously shaken (an efficient shaking machine can be used to advantage) for about 15 minutes, the solution being chilled several times during the slaking. The glass beads aid in starting the precipitation of the magnesium ammonium phosphate. Fifteen cc. of ammonia (sp.gr. 0.90) are next introduced and the contents of the flask are again thoroughly chilled and shaken briskly for 10–15 minutes longer. The flask is then packed in ice in a refrigerator and allowed to stand for 15 hours.

The magnesia precipitate, which may contain small amounts of basic magnesia compounds, iron, and possibly tartrates, is filtered on a 9 cm. paper and washed thoroughly with cold 10% ammonia water. The glass beads are transferred to the filter but no attempt is made to remove all of the precipitate from the flask. Under the conditions described, molybdenum, tungsten, and vanadium should all pass completely

into the lltrate.

Solution is made of the magnesium ammonium phosphate in the least necessary amount of hot dilute hydrochloric acid and the paper is washed with hot water. The filtrate and washings are caught in the same 300 cc. Erlenmeyer flask and evaporated down to a volume of approximately 5 cc. After cooling, addition is made of 10 cc. of a saturated solution of sulphurous acid, the flask and its contents are permitted to stand in a warm place for 5 or 10 minutes, 20 cc. of hydrochloric acid (sp.gr. 1.20) are added and the solution is evaporated to a bulk of about 5 cc. to expel completely arsenic. Twenty cc. of nitric acid (sp.gr. 1.42) are added and the solution is again boiled down to a volume of about 10 cc. in order to eliminate practically all of the hydrochloric acid. After having been diluted with 50 ec. of water, the solution is oxidized by boiling with an excess of strong permanganate solution (25 grams per liter) and then cleared by the addition of a few cc. of sulphurous acid. The liquid is boiled for a minute or two to expel nitrous fumes, and then cooled. A piece of litmus paper is dropped into the solution and a slight excess of ammonia (sp.gr. 0.90) is added. This is followed by addition of an excess of 1 or 2 cc. of colorless nitric acid (sp.gr. 1.42). The temperature of the solution is brought to 40° C. and the phosphorus is precipitated by addition of 40 cc. of "molybdate solution" and hye minutes' vigorous shaking. Determination is made of the phosphorus in the ammonium phosphomolybdate by either the Alkalimetric or the Molybdenum Reduction (Emmerton) Method.

of 'molybdate solution' and nive ninutes vigorous snaking. Determination is made of the phosphorus in the ammonium phosphomolybdate by either the Alkalinetrie or the Molybdenum Reduction (Emmerton) Method.

The "magnesia mixture" is prepared in the following manner: Fifty-five grams of crystallized magnesium chloride, MgCl₂-6H₂O, or twenty-five grams of the anhydrous salt, are dissolved in water and filtered. Fourteen grams of ammonium chloride are dissolved in water, a little bromine water and a slight excess of ammonia are added and the solution is filtered. The two solutions are mixed, sufficient ammonia is added to give a decided odor, and enough water is added to bring the volume up to one liter. The solution is allowed to stand for several days with occasional vigorous shaking and is filtered into one or more ceresin bottles. Ten ce. of the reagent will precipitate about

0.065 gram of phosphorus.

NI, at. wt. 58.69; sp. gr. 8.6-8.9; m. p. 1452° C.; ozides, NIO, NI2O1, NI4O4.

DETECTION

After bringing the sample into solution by one of the methods described under Preparation and Solution of the Sample, silica is removed, if present, in the usual manner, by evaporating the solution to dryness in the presence of an excess of hydrochloric acid, dissolving the residue and boiling with hydrochloric acid and filtering off the silica.

Hydrogen sulphide is then passed through the solution to remove the elements precipitated by this reagent. The filtrate from this precipitation is then boiled to expel the excess of hydrogen sulphide and a little nitric acid added to oxidize any ferrous iron to the ferric state. (See page 331, Separations.) Ammonium hydroxide is then added to precipitate iron, aluminum and chrominm. Cobalt, nickel, manganese and zinc are precipitated from the filtrate by adding a solution of colorless ammonium sulphide or by passing hydrogen sulphide through the ammoniacal solution. Manganese and zine are separated from the precipitate by washing with cold hydrochloric acid of about 1.035 sp.gr. A small quantity of the precipitate is fused with borax in the loop of a clean platinum wire. A green color in the cool bead indicates nickel. Fairly small quantities of cobalt interfere with this test, so if the bead is colored blue it will be necessary to make further tests for nickel.

Dimethylylyoxime will precipitate nickel as oxime from an acetic acid solution containing sodium acetate and in this manner separate it from cobalt, manganese and zinc. After precipitating iron, aluminum and chromium and filtering them off, the solution is slightly acidified with hydrochloric acid, then is neutralized with sodium hydroxide, and acidified with acetic acid. A solution of dimethylglyoxime is added, when nickel, if present, will be precipitated as a flocculent red precipitate.

Nickel may be detected in the presence of cobalt by adding a solution of sodium hydroxide to the solution of cobalt and nickel until a slight precipitate is formed, then somewhat more potassium cyanide than is necessary to redissolve the precipitate and finally two volumes of bromine water. Warm gently and allow to stand for some time. If a precipitate of nickel hydroxides separates, filter, wash and test with the borax bead.

Nickel may also be detected in the presence of cobalt by precipitating the eobalt as nitrite, as described in the chapter on cobalt, and then precipitating the nickel as hydroxide with sodium hydroxide and bromine water and testing the precipitate with the borax bead.

Alpha benzildioxime added to an ammoniaeal solution of nickel precipitates an intensely red salt having the composition C₂₄H₂₂N₄O₄Ni. This precipitate is very voluminous. Silver, magnesium, chromium, manganese and zinc do not interfere with this reaction.

Chapter by W. I. Savell, Paul D. Mercia and Thos. Fudge.

ESTIMATION

The determination of nickel is required, principally, in the analysis of ores, metallic nickel and its alloys, but is also required in the analysis of metallic cobalt and cobalt products as well as in a host of miscellaneous materials.

In the majority of cases the results of a nickel determination are calculated in terms of metallic nickel. Even in the determination of nickel in nickel-plating solution the results are calculated in terms of metallic nickel since this is the factor by which the solutions are controlled.

Preparation and Solution of the Sample

The materials in which nickel occurs ordinarily, may, in general, be brought into solution by treatment with acids, but in the case of some refractory ores and alloys, a fusion is required first to make the acid treatment effective. When treating ores containing sulphides or arsenides a strong oxidizing treatment is necessary to break up these compounds. Metallic nickel may be dissolved easily in nitric acid, more slowly in hydrochloric acid and still more slowly by sulphuric. Nickel alloys may be dissolved in a mixture of hydrochloric acid and nitric acid.

General Procedure for Ores. One gram of the finely powdered ore is weighed into a porcelain dish and mixed intinately with 3 grams of powdered potassium chlorate. The dish is covered with a watch-glass and 40 cc. concentrated nitric acid added slowly. The dish is allowed to stand in a cool place for a few minutes, then placed on a water bath and digested until the sample is completely decomposed, stirring the mixture frequently with a glass stirring rod, and adding a little potassium chlorate from time to time until the decomposition is complete. The watch-glass is then removed and any particles that may have spattered on it are washed back into the dish and the evaporation continued to dryness. This evaporation to dryness is repeated with the addition of 10 cc. of concentrated hydrochloric acid, and the silica dehydrated by heating for an hour or more in an air oven at 110° C. The dry residue is moistened with concentrated hydrochloric acid and the sides of the dish washed down with hot water, the mixture heated to boiling and allowed to boil for a few minutes, then withdrawn from the heat and filtered, hot, after the insoluble matter has settled.

Treat the filtrate for the removal of interfering elements as directed under

Separations.

Fusion Method. The above method is used where it is desired to determine insoluble matter or "gangue." As a method of bringing the nickel in the sample into solution it is quite satisfactory and when the insoluble matter burns to a pure white ash the ignited residue may be weighted as silica, but in some cases this method does not give sufficient information regarding the composition of the gangue.

If it is necessary to make a complete analysis it is usually better to fuse the sample with the sodium and potassium carbonate mixture containing a little potassium nitrate and then treat in the usual manner to determine silica.

Potassium Bisulphate Fusion. In the treatment of nickel and cobalt oxides these are ground to a fine powder and a representative sample of 1 gram is fused with 10 grams of potassium bisulphate. This may be done in a porcelain or silica crucible or dish. The melt is extracted with water and the silica filtered off.

A small casserole has been found to be very useful for this fusion.

Solution of Metallic Nickel and Its Alloys. From 17to 5 grams of the well-mixed drillings are treated with a minimum quantity of nitrie acid and 20 cc. 1:1 sulphuric acid added and the solution evaporated to fumes of sulphur trioxide. Allow the fuming to continue for ten minutes. Dilute earefully with a little water and filter off the insoluble. Continue as directed in the following detailed analyses.

It may be necessary to use a mixture of mitric and hydrochloric acids to bring certain alloys into solution, after which the procedure is the same as above.

SEPARATIONS

Separation of the Ammonium Sulphide Group, Containing Nickel from the Hydrogen Sulphide Group. Mercury, Lead, Bismuth, Copper, Cadmium, Arsenic, Antimony, Tin, Gold, Molybdenum, etc.

The hydrogen sulphide group elements are precipitated from an acid solution (HCl) by H₂S, and removed by filtration, nickel, etc., passing into the filtrate.

Separation of the Ammonium Sulphide Group from the Alkaline Earths and Alkalies. Nickel is precipitated with other members of the group by passing H₂S into its ammoniacal solution, or by adding (NH₄). Solution. The alkaline earths and alkalies are not precipitated.

Separation of Nickel from Cobalt. This procedure can be carried out in exactly the same manner as the method given for the determination of nickel by precipitation of nickel with dimethylglyoxime, since cobalt is soluble as oxime. In case more cobalt is present than nickel a larger excess of the reagent must be used. The excess of acid is best neutralized with ammonium hydroxide. If both metals are to be determined, cobalt may be determined electrolytically in the filtrate.

An alternate method is to determine the cobalt and nickel as oxides, or metal by electrolysis, together. The oxides, or plate, are dissolved in nitric acid and the nickel determined in the solution, cobalt being found by difference.

For other methods see Separation of Cobalt from Nickel, under Cobalt, page 168. Separation of Nickel from Manganese. Nickel is precipitated by dimethylglyoxime from an acetic acid solution containing sodium acetate, manganese

being determined in the filtrate.

Separation of Nickel from Zinc. Zine does not interfere in the dimethylglyoxime precipitation of nickel when ammonium salts are present. It is advisable to precipitate the nickel in a dilute acetic acid solution, thus avoiding the addition of a large amount of ammonium salts as would be necessary if the precipitation took place in an ammoniacal solution. Zinc readily remains in solution, and may be determined in the filtrate from the nickel oxinue precipitate. The following procedure is recommended:

The solution containing the two metals is neutralized with ammonium hydroxide and then made just slightly acid with acetic acid and sodium acetate added. Dimethylglyoxime solution is now added to the solution, which is nearly boiling, and the procedure given for the determination of nickel by this reagent is followed.

Separation of Nickel from Iron. Nickel cannot be separated satisfactorily from iron by precipitating the latter with ammonium hydroxide, as some of the nickel is invariably occluded by the ferric hydroxide precipitate. Two modifications of the oxime method may be used.

(1) The iron, if present as a ferric salt, is converted into a complex salt by

adding from 1 to 2 grams of tartaric acid, and the solution diluted to 200 or 300 ec., boiled and the nickel precipitated as the oxime in an amnioniacal solution by the prescribed method. Iron forms no oxime under these conditions.

The iron may be precipitated from this filtrate by colorless ammonium sul-

phide and the sulphide converted to ferric oxide (Fe₂O₂) by ignition.

(2) Ferric iron is reduced to the ferrous condition by warming with sulphurous acid, in a nearly neutral solution. If the original solution has an excess of acid, it is treated with a solution of sodium hydroxide until a permanent precipitate is formed. This is dissolved with a few drops of hydrochloric acid and the iron reduced by adding from 5 to 10 cc. of a saturated solution of sulphur dioxide or by passing dioxide through the solution. The solution is diluted to 200 or 300 ec. and the solution of dimethylglyoxime added in slight excess, followed by sodium acctate until a permanent precipitate of nickel oxime is formed. After adding 2 grams more of sodium acctate the solution is filtered immediately. The iron is precipitated from the filtrate by oxidizing with bromine water and adding ammonium hydroxide to precipitate the basic acctate of iron.

Procedure (1) is suitable for the determination of nickel in iron and steel.

Separation of Nickel from Aluminum. This method is the same as proeedure (1) given above.

Separation of Nickel from Chromium. This separation cannot be carried out in an acetic acid solution. From 1 to 2 grams of tartaric acid are added and from 5 to 10 cc. of a 10% ammonium chloride solution, subsequently. The solution is made ammoniacal, but no precipitate should form. If the solution becomes cloudy, it is acidified with hydrochloric acid and additional ammonium chloride added and again made ammoniacal and the nickel precipitated as oxime according to directions given from this precipitation.

GRAVIMETRIC METHODS FOR THE DETERMINATION OF NICKEL

Precipitation of Nickel by Alpha Benzildioxime

The alcoholic solution of alpha benzildioxime gives an intensely red precipitate of C₂₈H₂₂N₄O₄Ni, when added to anunoniacal solutions containing nickel. The reaction is more characteristic for nickel than is that with dimethylglyoxime and is more delicate. In a volume of 5 cc. (according to F. H. Atack), 1 part of nickel in 2,000,000 parts of water may be detected. In the presence of 100 times as much as cobalt only a faint yellow color is produced by the cobalt. One part of nickel per million of water will cause precipitation with the compound, whereas no precipitate is formed with dimethylglyoxime under the same conditions. With glyoxime iron produces a pink color, with alpha benzildioxime ferrous salts give a faint violet color, hence do not interfere in the detection of nickel. Silver, magnesium, chromium, manganese, and zinc do not interfere. Since the niekel precipitate with this reagent is exceedingly voluminous it is advisable to have not more than 0.025 gram of nickel in the solution in which the nickel is being determined. The method is adapted to the detection and determination of minute traces of the element up to small amounts of less than 10% nickel.

Reagent, Alpha Benzildioxime. This may be prepared by boiling 10 grams of benzil (not necessarily pure) with 8 to 10 grams of hydroxylamine hydrochloride in methyl alcohol solution. After boiling for three hours the precipitate is filtered off and dried, washed with hot water and then with a small amount of 50% alcohol, and dried. This dried precipitate consists of pure benzildioxime (m.p. 237° C.). A further yield may be obtained by boiling the filtrate with hydroxylamine hydrochloride. The reagent is prepared by dissolving 0.2 gram of the salt per liter of alcohol to which is added ammonium hydroxide to make 5% solution, sp.gr. 0.96 (50 ee. per liter).

Procedure. A slight excess of the warmed solution of the above reagent is stirred into the ammoniaeal solution containing nickel and the whole heated on the water bath for a few moments to coagulate the precipitate. Quantitative precipitation is complete after one minute. The liquid is filtered through a Gooch erueible, with suction, or onto a filter paper, for which a counterpoise has been selected. The counterpoise paper is treated in exactly the same manner as the one containing the precipitate. The precipitate is washed with 50% alcohol, followed by hot water, and is then dried at 110° C. In weighing the precipitate the counterpoise filter is placed in the weight pan of the balance. The precipitate contains 10.93\% nickel. Weight of C281122N4O4Ni\times 0.1093 = Ni.

Notes. Acetone may be used instead of alcohol as a solvent of the reagent. compound is more soluble in acctone than in alcohol.

The precipitate does not pass through the filter as does the compound with directly-

glyoxinie.

The method is affected by the presence of nitrates, hence these must be removed hy evaporation of the solution with sulphuric acid to fumes, before the addition of the reagent to the nickel solution.

In the presence of cobalt an excess of the reagent must be used, as in the case of

the dimethylglyoxime precipitation.

In the presence of iron and chromium Rochelle salt, sodium citrate or tartarie acid are added to prevent precipitation of the hydroxides of these metals upon making the solution alkaline.

In the presence of manganese a fairly large excess of the reagent is required, the

solution being slightly acid with acetic acid.

Zinc and magnesium are kept in solution by addition of ammonium chloride.

Large amounts of copper must be removed by precipitating with hydrogen sul-

phide before addition of the reagent.

The nickel salt with the reagent forms an extremely voluminous precipitate so that a concentration of 0.09 gram of nickel per 250 cc. is as high as is desirable. The process is applicable to the determination of nickel in the filtrate obtained in the separation of zinc after the removal of the hydrogen sulphide, formic acid, etc.
Method by F. W. Atack, The Analyst, 38, 448, 318. Cockhurn, Gardiner and

Black, Analyst, 38, 439, 443.

Precipitation of Nickel by Dimethyl-glyoxime

Preliminary Considerations. This method has been demonstrated by O. Brunek to be the most accurate and expeditious procedure known for nickel. By this method 1 part of nickel may be detected when mixed with 5000 parts of cobalt or 1 part of nickel may be detected in 400,000 parts of water. The nickel precipitate with this reagent is almost completely insoluble in water and is only very slightly soluble in acetic acid, but is easily decomposed by strongly dissociated acids, so that the precipitation is incomplete in neutral solutions of nickel chloride, sulphate or nitrate. If, however, the free acid formed is neutral-

ized with sodium, potassium or ammonium hydroxides or by addition of the acetate salts of these bases, nickel will be completely precipitated, not even a trace being found in the filtrate.

"The quantitative determination of nickel in the presence of other metals is a simple operation. The nickel should be in the form of a convenient salt.

"The concentration of the solution does not matter; the precipitation can take place either in a solution of the greatest concentration, or in a very dilute solution. The reaction is not hindered by the presence of ammonium salts."

Iron, aluminum, chromium, cobalt, manganese and zinc do not interfere. Theoretically 4 parts of dimethylglyoxime, added as a 1% alcoholic solution, are necessary; a certain excess does no harm provided the alcohol volume does not exceed more than half that of the water solution containing the nickel salt, as alcohol has a solvent action on the oxime. The compound is very stable and volatilizes undecomposed at 250° C.

An excess of ammonium hydroxide is also to be avoided in the solution in which

the precipitation takes place.

It has been observed that the precipitate of nickel with dimethylglyoxime may be safely ignited to the oxide NiO without loss, if the filter is first carefully charred without allowing it to take fire, then gradually heated to redness.

Procedure. Such an amount of the sample should be taken that the nickel be not over 0.1 gram, as glyoxime of nickel is very voluminous and a larger amount would be difficult to filter. If cobalt is present it should not exceed 0.1 gram in the sample taken.

If hydrogen sulphide has been used to precipitate members of the second group, it is expelled by boiling the acid solution and the volume brought to 250 ce.

One or 2 grams of tartaric acid are added to prevent the precipitation of the hydroxides of iron, aluminum and chromium by ammonium hydroxide (this treatment is omitted if these are absent), and 5 to 10 cc. of a 10% solution of ammonium chloride added to keep zine and manganese in solution, should they be present. Ammonium hydroxide is now added until the solution is slightly alkaline. If a precipitato forms, ammonium chloride is added to clear the solution, followed by ammonium hydroxide to neutralize the acid. The solution should remain clear after this treatment, otherwise the ammonium chloride is added in solution or as salt until the solution of the sample will remain clear. It is then heated to nearly boiling and the alcoholic solution of dimethylglyoxime added until the reagent is approximately seven times, by weight, the weight of nickel present. Ammonium hydroxide is now added until the solution has a distinet odor of this reagent. The precipitation of the searlet red nickel salt is hastened by stirring. It is advisable to place the mixture on the steam bath for fifteen to twenty minutes to allow the reaction to go to completion before filtering. The precipitate is filtered off, into a platinum sponge Gooch crucible, sometimes known as a Neubauer Gooch crucible. (Other forms of Gooch crucible are used for this purpose, but the Neubauer crucible has been found to be most satisfactory.) The precipitate is dried for about two hours at 110 to 120° C. and weighed as C.H. N.O.Ni, which contains 20.32% Ni.

Weight of precipitate multiplied by 0.2032 = weight of nickel.

¹ If the sample contains more than 0.1 gram of cobalt, a large excess of ammonium hydroxide and dimethylglyoxime is necessary to prevent its precipitation, hence it is advisable to take such weights of samples that the cobalt content will be less than this weight.

In place of a Gooch crucible a tared filter paper may be used. It must be remembered, however, that a blank filter paper of the same kind as used for the precipitate must be used as a counterbalance, after treating in exactly the same manner as the one containing the precipitate. This is necessary because it has been found that filter paper loses weight during washing and drying.

Precipitation of Nickel by Electrolysis 1

This precipitation is conducted in exactly the same manner as the one described under Cobalt for the Precipitation of Cobalt by Electrolysis, and requires that the same precautions be exercised in the practice of the method.

In the presence of cobalt the two elements may be determined together by electrolysis as described below and the deposited metal redissolved and the two elements separated by one of the methods given under Cobalt or Nickel.

Procedure. After the sample has been brought into solution by one of the methods outlined under Preparation and Solution of the Sample, the solution is evaporated with 20 cc. of 1:1 sulphuric acid for every gram of metal in the sample. The evaporation is continued until the solution has fumed strongly for ten minutes. Cool carefully and dilute with 20 cc. of water. Heat the solution to nearly boiling and pass hydrogen sulphide for one hour to precipitate members of the second group. This long treatment is necessary to insure complete precipitation of arsenic. Filter and boil to expel hydrogen sulphide. Add 5 cc. nitric acid to insure oxidation of iron compounds to the ferric state and add ammonium hydroxide until just slightly alkaline. Filter off the ferric hydroxide and wash with water containing a small quantity of ammonium hydroxide. To recover occluded nickel dissolve the precipitate in hydrochloric acid and reprecipitate the iron with addition of a little hydrogen peroxide. Combine the filtrates. Evaporate to about 250 cc. and add 50 cc. of strong ammonium hydroxide and electrolyze as described under Cobalt, page 170.

The increase in weight of the electrode is the weight of cobalt and nickel in the sample. The percentage of cobalt and nickel in the sample is found by multiplying the increase in weight of the electrode by 100 and dividing by the weight of the sample.

Note. The deposition of cobalt and nickel by the above method has been found to be the most accurate of the electrolytic methods. In the solutions containing the organic acids there is always more or less carbide deposited on the cathode with the metal. This causes high results,

Nickel in Metallic Nickel

This determination may be made in the manner described under Precipitation of Nickel by Electrolysis, separating cobalt before or after the electrolysis or by the method described under Precipitation of Nickel by Dimethylglyoxime. The latter method is recommended.

Nickel in Cobalt and Cobalt Oxide

The dimethylglyoxime precipitation is used in combination with the electrolytic precipitation. See chapter on Cobalt.

¹ W. J. Marsh, J. Phys. Chem., 18, 705-16, 1914.

VOLUMETRIC DETERMINATION OF NICKEL

Determination of Nickel in Alloys

This method, as described by S. W. Parr and J. M. Lindgren, consists of a modification of the dimethylgloxime method. The precipitation takes place in the usual manner and the precipitate is dissolved in sulphurie acid and the excess titrated with a standard solution of potassium hydroxide.

Procedure. The alloy is dissolved in nitrie or hydrochloric acids and if iron, aluminum or chromium are present twice their weight of tartarie acid is added to prevent their precipitation. If chromium is present anumonium chloride is also added. If manganese or zinc is present hydrochloric acid should be used and most of the free acid evaporated. Add a few cc. of hydrogen peroxide to oxidize any ferrous iron to the ferrie state. Dilute to 300 or 400 cc. and neutralize the free acid by sodium acetate. Heat the solution to nearly boiling and add five times as much dimethylglyoxime, in 1% alcoholic solution, as the nickel present. Then completely neutralize with ammonium hydroxide, using a very slight excess (or the solution may be neutralized with sodium acetate). Heat until all the nickel is precipitated. Filter and wash. Place the precipitate and filter in a beaker, add an excess of 0.05N sulphuric acid, dilute to 200 cc., heat until solution is complete and titrate back with 0.1N potassium hydroxide solution, taking the first faint yellowish tinge as the end-point. The solutions are standardized against pure nickel.

Note. Cobalt should not exceed 0.1 gram per $100\ \mathrm{cc}$, and an excess should be used of the dimethylglyoxime.

Nickel in Nickel-plating Solutions

In most cases it is quite unnecessary to separate the cobalt from the nickel in making this determination and, as the principal impurity is usually iron, the best practice is to follow the method given under Precipitation of Cobalt by E'ectrolysis, page 170.

If ehlorides or organic matter are present in the solution the preparation of the solution for electrolysis is accomplished in the following manner:

From the well-stirred solution in the plating tank, withdraw about 200 cc. and place in a small beaker. Prepare a 100-cc. burette by thoroughly cleaning it with the sulphuric acid and potassium bichromate mixture and distilled water. Wash finally with a few ec. of the nickel solution and fill the burette with the solution from the plating tank.

Run 66.7 ec. into an evaporating dish and add 2 ec. 1:1 sulphuric acid. Evaporate to fumes of sulphur trioxide and allow to fume strongly for ten minutes. Dissolve in a little water. Dilute to 200 ec. carefully, neutralize with a solution of ammonium hydroxide and add 50 cc. of strong ammonium hydroxide and electrolyze. (See Precipitation of Cobalt by Electrolysis.)

The increase in weight of the cathode in grains multiplied by 2 gives the weight in ounces of niekel in one United States gallon of the plating solution.

¹ S. W. Parr and J. M. Lindgren, Trans. Am. Brass Founders' Assoc., 5, 120-9.

NICKEL 336a

Potassium Cyanide Method for Nickel¹

The method is rapid and accurate and is especially adapted for determining nickel in steel. Iron, manganese, chromium, zinc, vanadium, molybdenum and tungsten do not interfere. Copper, however, should be removed if present. The method depends upon the selective action of potassium cyanide for nickel in preference to silver iodide, used as an indicator, the reactions taking place as indicated, the solution being slightly alkaline with ammonia—

(a) $Ni(NH_2)_6SO_4 + 4KCN = K_2Ni(CN)_4 + K_2SO_4 + 6NH_3$

(b)
$$AgI + 2KCN = KAg(CN)_2 + KI$$
 (N.B. $4KCN \approx Ni$) (N.B. $2KCN \approx Ag$)

Reagents.

N/10 Silver Nitrate.—10.788 grams of pure silver are dissolved in nitric acid and made to 1000 cc. or 16.99 g. of the silver nitrate salt. (See Index for reagent.) 1 cc. \approx 0.01302 g. KCN.

If preferred the reagent may be made to be equivalent to about 0.001 gram Ni per cc. by dissolving 5.85 grams of AgNO₃ per liter.

Potassium Iodide. -25% solution.

N/10 Potassium Cyanide.—13.5 grams of pure KCN are dissolved in water, 5 grams of KOH added and the solution made to 1000 ec.

The cyanide solution is standardized against the silver nitrate solution.

If it is desired to have a solution equivalent to 0.001 g. Ni, 5 grams of KCN per liter is the approximate strength required.

Standardization of the Cyanide.—Fifty cc. of the KCN solution are diluted to about 150 cc., 5 cc. of the KI reagent added and the solution titrated with the standard AgNO₃ reagent until a faint permanent opalescence is obtained. A drop of the KCN solution should be sufficient to clear this. Note the number of cc. required and calculate the normality factor of the cyanide in terms of the silver nitrate reagent.

Example.—Suppose 49 cc. of the silver nitrate reagent were required for the 50 cc. of the cyanide solution, then the normality would be $49 \div 50 \times N/10$ or 0.98 N/10.

1 cc. N/10 solution is equivalent to 0.002934 gram nickel.

The reagent may be standardized against a nickel steel of the U. S. Bureau of Standards, following the procedure given below and calculating as follows:

Nickel factor =
$$\frac{\text{Gram Ni in standard taken}}{\text{(cc. KCN required)} - \text{(cc. KCN equivalent to 5 cc. AgNQ3)}}$$

Citric Solution.—200 grams of (NH₄)₂SO₄, 150 cc. concentrated NH₄OH and 120 grams of citric acid per 1000 cc.

Procedure.1

One gram of the steel drillings or such an amount of material as contains not over 0.1 g. Ni, is dissolved in a beaker with 20 cc. of hydrochloric acid (1:1). When action ceases 10 cc. of nitric acid (1:1) are added and the solution boiled until the red nitrous acid fumes are driven off.

About 100 ee. of the citrate solution are added. If 2 per eent. or more of chromium is present the amount of citrate solution is doubled. The solution is now diluted to about 250 cc.

Exactly 5 ee. of the standard silver nitrate solution are now added from a pipette or burette, and then ammonium hydroxide, drop by drop, until the cloudiness caused by the silver chloride just disappears. Two ee. of the potassium iodide solution are now added.

The solution is titrated with the standard potassium eyanide solution with constant stirring until the turbidity just disappears. The end point is reached when there is no longer a distinction in clearness of the drop of the reagent and its surrounding liquid to which it is added.

If the end point is passed, a measured amount of silver nitrate (5-10 ee.) is added and the eyanide titration repeated.

Calculation.—Deduct the ee. KCN equivalent of the total silver nitrate solution used from the total ee. of the KCN solution required in the titration. The remainder is the potassium cyanide required by the nickel.

The cc. KCN required by Ni multiplied by the factor for Ni = gram nickel in the sample.

- 1. A large excess of ammonia is to be avoided as the AgI is soluble in a large excess.
 - 2. The presence of sulphates increases the sensibility of the end point.
- 3. The silver nitrate solution should not be stronger than that indicated in the method as there is danger of the iodide of silver settling out as a curdy precipitate in stronger solutions.
- 4. A white film is apt to form on the surface of the liquid if exposed to the air for some time. This produces no error.

Carnot's1 Gravimetric Oxide Method for Nickel

Sodium earbonate is added to the nickel solution, in slight excess until alkaline. Nickel is now precipitated with ammonia or ammonium earbonate from a boiling solution. The precipitate is filtered, washed and ignited to oxide, NiO, and so weighed.

Determination of Nickel in Nickel Steel—Ether Extraction Cyanide Titration Method

The following procedure is recommended by the A. S. T. M.

Reagents Required

Hydrochloric Acid. -600 ee. HCl (d. 1.2) dil. with 400 ee. water.

Nitric Acid.-1000 ee. IINO3 (d. 142) and 1200 ec. water.

Potassium Iodide.—20 grams per liter.

Silver Nitratc. -0.5 g. per liter.

Potassium Cyanide.—4.589 grams KCN per liter. The reagent is stand-

¹ A. Carnot, Jour. Chem. Soc., 1918, II, 133.

NICKEL 336c

ardized against nickel steel of known nickel content as determined by the gravimetric dimethylglyoxime method.

A sample of 1 gram of steel is dissolved by addition of 20 ce. Procedure. of the dilute hydrochloric acid and then the iron oxidized by addition of 2 cc. of strong nitrie acid (d. 1.42) and the solution boiled to expel the brown nitrogen fumes. After cooling the solution is transferred to an 8-oz. separatory funnel, hydrochloric acid being used to rinse out the containing beaker into the funnel. The solution is shaken with 50 ec. of ether for about 5 minutes, then allowed to settle for 1 minute and the lower clear layer drawn into a second separatory funnel (8-oz.). To the first ether solution are added 10 ce. of strong HCl (d. 1.2), cooling, and then shaking as before. After settling 1 minute the lower layer is drawn into the second separatory funnel. 50 cc. of ether arc added to the second separatory funnel, the solution shaken for 5 minutes, then settled 1 minute, and the lower clear layer drawn into a 150-ce, beaker. The ether is expelled by gentle heat. 0.2 gram of potassium chlorate is added, the solution boiled to decompose the chlorate, then diluted to 100 ce. with hot water, and made faintly ammoniacal and boiled for 5 minutes. The manganese dioxide is filtered off and washed with hot water. To the filtrate are added 10 ce. of strong hydrochloric acid, the solution heated just short of boiling and copper precipitated with H2S, and filtered off and washed with hot water. The filtrate is boiled to expel H2S, and the boiling continued until the volume is reduced to about 100 cc. The solution is cooled, made distinctly ammoniacal, 10 cc. each of silver nitrate and potassium iodide solutions added and the solution titrated with standard potassium cyanide to a clear solution.

Determination of Bismuth in Metallic Nickel

Dissolve 20 grams of nickel drillings in 200 ce. 1 to 1 nitric acid in an 800-cc. beaker. Add 5 grams of potassium chlorate, boil for ten minutes. Cool and add 75 ce. of sulphuric acid. Evaporate until funing strongly, cool. Add 600 ce. of water, boil gently to insure solution of all the bismuth sulphate. Cool again, filter and wash with 1 to 10 sulphuric acid. Do not allow to stand too long before filtering, some basic bismuth sulphate may separate. Pass a current of hydrogen sulphide gas through for onc half hour. Bismuth, copper, arsenic, antimony, etc., are precipitated as sulphides. Filter, washing with hot water. Rinse the precipitate as completely as possible into a beaker, add 3 or 4 grams of pure potassium cyanide, warm gently for some time. Bismuth sulphide will remain undissolved. Filter through same filter as before, in order to act upon traces of sulphides that could not be washed into the beaker, and wash with hot water. Place the filter and precipitate into a 100-cc. lip beaker and heat with 10 cc. of I to I nitric acid until the separated sulphur is clean and the filter well disintegrated. Dilute a little and then filter and wash thoroughly with 1 to I nitric acid. Partially neutralize the filtrate with ammonia, but without producing any permanent precipitate, and then add a solution of ammonium earbonate in very slight excess. Heat nearly to boiling for some time until the bismuth carbonate has settled well, and then filter and wash with hot water. Dry the precipitate and transfer it to a small weighed porcelain crucible, removing it from the paper as completely as possible. Burn the latter carefully and add the ash to the precipitate in the crucible. Ignite the whole at a low red heat, cool and weigh as Bi₂O₃, which contains 89.68 per cent of bismuth.

Determination of Lead in Metallic Nickel

Dissolve 20 grams of nickel drillings in 200 cc. of 1 to 1 nitric acid in a 1200-cc. beaker. Evaporate to 100 cc. Add 100 cc. sulphuric acid and evaporate to heavy fumes.

Cool and add 800 cc. water. Boil gently to insure solution of sulphates, cool and add 200 cc. of 95 per cent alcohol, stir and allow to stand over night.

Filter off the lead sulphate and wash two or three times with 2 per cent sulphuric acid and once with cold water. Place filter paper, containing the lead sulphate, in a beaker and add 10 grains of slightly aminoniacal animonium acetate and 50 cc. of water. Boil a few minutes. Filter and wash with hot water.

Filtrate, containing all the lead in solution as the acetate, is acidified slightly with acetic acid and heated to boiling. Precipitate lead by adding 20 cc. of a 5 per cent solution of potassium dichromate. Boil until precipitate changes to orange or red.

Allow precipitate to settle over night.

Filter the lead chromate on a weighed Gooch crucible. Wash with water and finally with alcohol. Dry at 110° C., and weigh as PbCrO₄, which contains 64.10 per cent of lead.

Determination of Aluminum in Metallic Nickel

Dissolve 10 grams of nickel drillings in 100 ce. dilute nitric acid (one part water, two parts nitric acid) in a 600-cc. covered beaker, add 1 or 2 grams potassium chlorate, boil for one hour, add about 100 cc. cold water and about 5 grams ammonium chloride, make slightly alkaline with aumonia. Transfer to a 500-cc. platinum dish. Boil a few minutes, filter off iron and aluminum hydrates and wash with hot water two or three times.

The precipitate is again transferred to 500-ce. platinum dish by redissolving in 1 to 3 hydrochloric acid, add a few grams of ammonium chloride, make slightly alkaline with ammonia. Boil a few minutes, filter off iron and aluminum hydrates and wash with hot water two or three times. Repeat re-dissolving and ammonia precipitation with addition of a few grams of ammonium chloride. After final re-precipitation transfer the precipitate to 100-cc. platinum dish by washing and dissolving the precipitate in 1 to 3 hydrochloric acid. Evaporate to dryness on a steam bath. Add 2 grans pure sodium hydrate and about 2 co. of water. Fuse at low temperature for ten minutes. Cool and add about 50 cc. of water. Place on steam bath for a few minutes. Transfer to a 500-ec. platinum dish, add 300 ec. of water. Filter into a 500-ec. casserole containing 30 ec. of hydrochloric acid. Evaporate the filtrate to dryness on the hot plate. Add 50 ec. 1 to 3 hydrochloric acid, boil and filter into a 200-ec. platinum dish. Add a few grams of anymonium chloride to the filtrate and make it slightly alkaline with ammonia. Boil a few minutes, filter on ashless paper, wash with hot water. Ignite in a small platinum crucible and weigh as Al₂O₃ which contains 53,00 per cent of aluminum.

Nore. If the aluminum oxide should contain a small amount of chromium, it should be fused with sodium peroxide and the chromium determined by color. Deduct the weight of chromium oxide found from the weight of aluminum oxide.

Note. Run a blank analysis; that is, add to it all the reagents, and subject the contents to the same operations as the samples of drillings and at the same time. Deduct any alumina contained from the result of the actual assay. If this blank amounts to .004 gram, the reagents are unfit for the above analysis and the determination should be repeated with other reagents.

This method is devised for Metallic Nickel as furnished by The International Nickel Company (Huntington Works).

NICKEL 336e

Method of Determining Silicon, Tungsten and Chromium in Metallic Nickel

Dissolve 1 gram of drillings in 50 cc. 1 to 1 hydrochloric acid in a 200-cc. lip beaker. Add a few drops of nitric acid at intervals until sample has decomposed. Add a few drops of intrie acid at intervals until sample has decomposed. Add 5 cc. nitric acid, boil down to 10 cc. Add about 50 cc. of water and boil for five minutes and filter. Wash well with 5 per cent hot hydrochloric neid and finally with water. Evaporate filtrate to dryness, take up in 25 cc. of 1 to 1 hydrochloric acid, dilute to 50 cc., boil, filter and wash with hot water. Ignite the two precipitates in a weighed platinum crucible, being careful not to heat above a red heat. Cool and weigh.

Add 3 drops of sulphuric acid and 5 cc. hydrofluoric acid, evaporate and ignite at low and heat. Cool and weigh.

low red heat. Cool and weigh.

Loss equals SiO₂×.4693 equals Silicon.

To purify it, fuse it with 5 grams sodium The residue is impure tungstic oxide. carbonate, dissolve and filter off residuc. Wash with hot water, ignite, weigh and subtract from weight of impure tungstic oxide.

WO₃×.793 cquals Tungsten.

Add to the filtrate which contains the Chromium 15 cc. of sulphuric acid plus 15 cc.

of nitric acid and evaporate to funics.

Add 25 cc. nitric acid, dilute to 200 cc., boil until salts are all dissolved. Oxidize by adding slowly 3 grams potassinun permanganate dissolved in a small amount of water until a permanent color remains, showing an excess of permanganate. Decompose the excess of permanganate by boiling twenty minutes. A precipitate of manganese dioxide should remain. If none remains, add more potassium permanganate. Keep volume of solution approximately constant. Filter off manganese dioxide, cool to room temperature, dilute to 350 cc., add an excess of standard ferrous ammonium sulphate and titrate excess with standard potassium permanganate to a pink color which remains one minute.

Having found by titration the excess of ferrous ammonium sulphate and deducted this from the total amount of the salt used, the weight of the remainder multiplied by .04427 equals Chromium, or the Iron value of the ferrous ammonium sulphate multiplied

by .31 equals Chromium.

Method for Determining Arsenic, Antimony and Tin in Metallic Nickel

Dissolve 5 grams of the nickel drillings in 50 cc. of 1 to 1 nitric acid in a 145-cc. covered silica erneible. Cool and add 10 cc. sulphuric acid, evaporate until fumes of sulphuric acid are given off copiously, cool, then add 25 cc. water, evaporate until the fumes of sulphuric acid are almost all driven off, cool and add about 30 grans of potassium bisulphate (fused). Finse and keep in a fused condition for one half hour. Cool and transfer the fusion after breaking it up in a porcelain mortar to 16-oz. distilling flask (as per drawing). Allow the outlet of the condenser to dip about one half inch into beaker half full of cold water, then add 5 grams anhydrous ferrous sulphate to the distilling flask, then add 150 cc. hydrochloric acid and distil to about 30 cc., then add 50 cc. more hydrochloric acid and distil again to about 30 cc., remove beaker containing water and distillate and place another beaker half full of cold water under the outlet of the condenser. Again add 50 cc. hydrochloric acid and distil to about 30 cc. Pass hydrogen sulphide gas through both distillates to precipitate the arsenic as arsenous sulphide. All the arsenic should be in the first distillate. The second distillate is made so as to see if all the arsenic has been distilled over. Filter the arsenous sulphide to the state of the second distillate is made to be a second distillate in the first distillate over. on weighed Gooch crueible, wash with hot water, then with alcohol, ether, and carbon bisulabiled described the state of th bisulphide, dry at 100° C. and weigh as As₂S₃ which contains 60.93 per cent of arsenic.

To the solution in the distilling flask add 400 cc. hot water, then transfer to 800-cc.

lip beaker, nearly neutralize with ammonia, then add 8 cc. hydrochloric acid, heat to boiling, pass stream of hydrogen sulphide gas through solution to saturation, then let stand for two or three hours, filter off antimony, tin and copper sulphides, wash precipitate quickly and thoroughly with hot water, then wash the precipitate into a 200-cc. lip beaker and wash filter with dilute sodium sulphide solution, add a few crystals of sodium sulphide to solution in the beaker, let stand in warm place for an hour, then filter off the copper sulphide, wash with dilute sodium sulphide solution, the filtrate 336f NICKEL

contains all the antimony and tin. Evaporate the filtrate to about 20 cc., then pour in hot concentrated solution of exalic acid. This will dissolve the tin sulphide and leave the antimonous sulphide undissolved. Pass hydrogen sulphide gas through the boiling solution for half an hour, filtre off antimonous sulphide on weighed Gooch crucible, wash quickly and thoroughly with hot water, place Gooch crucible on steam plate and add furning nitric acid, evaporate until dry, then heat to a dull red heat, cool and weigh as Sb₂O₄ which contains 78.97 per cent of antimony.

Add to the filtrate from the antimonous sulphide 30 cc. hydrochloric acid and 4 grams potassium chlorate, evaporate to about 25 cc., nearly neutralize with ammonia, dilute to 150 cc. with hot water, pass hydrogen sulphide gas through hot solution for half hour, filter on weighed Gooch crucible, wash quickly and thoroughly with hot water, place Gooch crucible on steam plate, add funing nitric acid, evaporate until dry, then heat to a dull red heat, cool, and weigh as SnO₂ which contains 78.80 per cent of tin.

Note. Blank should be run on everything used in the above determinations and at the same time, if any arsenic, antimony or tin is found in the blank, it should be deducted.

Method for Determining Zinc in Nickel

Dissolve 5 grams of drillings in 75 cc. of 1:1 nitric acid in a 400-cc. beaker. Dilute to 350 cc. Cool and plate out the copper over night with .3 ampere. After the copper is all plated, pour the solution and water used in washing off cathode into a 500-cc. beaker.

Add 30 ee. of hydrochloric acid and take to dryness on a steam bath. Add 10 ec. of hydrochloric acid and again take to dryness. Take up in 100 ec. of water and 3 ec.

hydrochloric acid. Boil and filter off any silica.

Add a concentrated solution of sodium carbonate to the filtrate until a distinct precipitate of nickel and zine carbonates remain. Carefully dissolve this precipitate by adding 1 per cent sulphuric acid, stirring for at least two minutes after each addition of acid. (Great care should be taken in adding the 1 per cent sulphuric acid because if more than just enough to dissolve the carbonates is used, no zine sulphido will precipitate.) Add 2 grams ammonium sulphate. Dilute to 400 cc. and cool.

Connect a tube to hydrogen sulphide gas and pass gas through solution using a tube which has been drawn to one millimeter diameter at the end. Pass the gas through for 40 minutes. Disconnect and allow to stand for three hours. Filter through a double ashless paper and wash two or three times with hot water, containing hydrogen

sulphido.

To free the zino sulphide of traces of nickel, dissolve in 50 cc. of 1:6 sulphurio acid. Dilute to 100 cc. and boil off the hydrogen sulphide gas. Cool and make slightly alkaline with ammonia.

Mako acid with acetic acid. Add an equal volume of 50 per cent acetic acid.

Cool and precipitate the zinc sulphide as before. Allow to settle three hours. Filter through a double ashless paper. Wash with hot water containing hydrogen sulphido.

Place filter paper containing zine sulphide into a small porcelain evaporating dish. Ignite and keep at a temperature of about 800° C. for one hour. Cool and weigh as

zino oxide, which contains 80.34 per cent zine.

The procedures on pages 336c to 336f are methods of The International Nickel Company that have been contributed by Dr. Paul D. Mercia and Mr. Thos. Fudge.

NITROGEN

Element. N₁, at.wt. 14.01; D. (air) 0.9674; m.p. -210° ; b.p. -195.5° C.; oxides, N₂O, N₂O₂, N₂O₃, N₂O₄, N₂O₅.

Ammonia. NH₃, m.w. 17.03; D. (air) 0.5971; sp.gr. liquid 0.6234; m.p. -77.3°; b.p. -38.5° C. Crit. temp. 130°; liquid at 0° with 4.2 atmospheres pressure. Commercial 28% NH₃, sp.gr. 0.90.

Nitric Acid. HNO₃, m.w., 63.02; sp.gr. 1.53; m.p. -41.3; b.p. 86° C. Boiling-point of commercial 95% acid is a little above 86° , but gradually rises to 126° and the strength of acid falls to 68.9%, sp.gr. is then 1.42. The acid now remains constant, the distillate being of the same strength.

DETECTION

Element. Organic Nitrogen. Organic matter is decomposed by heating in a Kjeldahl flask with concentrated sulphuric acid as described under preparation and solution of the sample. Ammonia may now be liberated from the sulphate and so detected.

Nitrogen in Gas. Recognized by its inertness towards the reagents used in gas analysis. The element may be recognized by means of the spectroscope.

Ammonia. Free ammonia is readily recognized by its characteristic odor. A glass rod dipped in *hydrochloric acid* and held in fumes of ammonia produces a white cloud of ammonium chloride, NH₄Cl.

Moist red lilmus paper is turned blue by ammonia. Upon heating the paper the red color is restored, upon volatilization of ammonia (distinction from fixed alkalies).

Nessler's Test. Nessler's reagent added to a solution containing ammonia, combined or free, produces a brown precipitate, NHg₂I·H₂O. If the amnioniacal solution is sufficiently dilute a yellow or reddish-brown color is produced, according to the amount of ammonia present. The reaction is used in determining ammonia in water.

Salts of ammonia are decomposed by heating their solutions with a strong base such as the hydroxides of the fixed alkalies or the alkaline earths. The odor of aminonia may now be detected.

Nitric Acid. Ferrous Sulphate Test. About 1 to 2 cc. of the concentrated solution of the substance is added to 15 to 20 cc. of strong sulphuric acid in a test-tube. After cooling the mixture, the test-tube is inclined and an equal volume of a saturated solution of ferrous sulphate is allowed to flow slowly down over the surface of the acid. The tube is now held upright and gently tapped. In the presence of nitric acid a brown ring forms at the junction of the two solutions.

¹The reagent is made by dissolving 20 grams of potassium iodide in 50 cc. of water, adding 32 grams of mercuric iodide and diluting to 200 cc. To this is added a solution of potassium hydroxide—134 grams KOH per 260 cc. H₂O.

Chapter contributed by Wilfred W. Scott.

The test for nitrate may be made according to the quantitative procedure given for determining of nitrie acid (see later). It should be remembered that ferrous sulphate should be present in excess, otherwise the brown color is destroyed by the free nitric acid. Traces of nitric acid in sulphuric produce a pink color with the sulphuric acid solution of ferrous sulphate. (See Determination of Nitric Acid—Ferrous Sulphate Method.)

Ferro- and ferricyanides, chlorates, bromides and bromates, iodides and

iodates, chromates and permanganates interfere.

Diphenylamine Tests for Nitrates. (C₆H₆)₂NH dissolved in sulphuric acid is added to 2 or 3 cc. of the substance in solution on a watch-glass. Upon gently warming a blue color is produced in presence of nitrates. Nitric acid in sulphuric acid is detected by placing a crystal of diphenylamine in 3 or 4 ee. of the acid and gently warming. Cl', Cl', Br', I', Mn'm, Cr', Se', Fe'' interfere.

Copper placed in a solution containing nitrie acid liberates brown fumes.

Phenolsulphonic Acid Test. See chapter on Water Analysis.

Detection of Nitrous Acid. Acetic Acid Test. Acetie acid added to a nitrite in a test-tube (inclined as directed in the nitric acid test with ferrous sulphate), produces a brown ring. Nitrates do not give this. If potassium iodide is present in the solution, free iodine is liberated. The free iodine is absorbed by ehloroform, earbon tetrachloride or disulphide, these reagents being colored pink. Starch solution is colored blue.

Nitrous acid reduces iodic acid to iodine. The iodine is then detected with

starch, or by earbon disulphide, or carbon tetrachloride.

Potassium Permanganate Test. A solution of the reagent acidified with sulphurie acid is decolorized by nitrous acid or nitrite. The test serves to detect nitrous acid in nitric acid. Other reducing substances must be absent.

ESTIMATION

Occurrence. Element. Free in air to extent of 78%+ by volume and 76%- by weight.

Air weight of 1 liter = 1.293 grams. With oxygen as 32, air = 28.95.

COMPOSITION OF AIR. ON THE BASIS OF 1000 LITERS OF ATMOSPHERE

Element.	Liters per 1000 l.	Weight per 1000 l. grams	Per cent by Vol.	Per cent by Wt.
Nitrogen. Oxygon. Argon. Carbon dioxide. Hydrogen. Neon. Helium. Krypton	209.9 9.4 0.3 0.1 0.015 0.0015 0.00005	975.80 299.84 16.76 0.59 0.01 0.01339 0.00027 0.00018 0.00003	78 1 21.0 0.9 0.04	75.47 — 23.19 — 1.296 + 0.045

Nitrogen is found combined in nature as potassium nitrate (saltpeter), KNO₄; sodium nitrate (Chili saltpeter), NaNO₄, and to a less extent as ealcium nitrate,

Ca(NO₂)₂. It occurs in plants and in animals, in the substances proteids, blood, musele, nerve substance, in fossil plants (eoal), in guano, ammonia and ammonium salts.

Free nitrogen is estimated in the complete analysis of gas mixtures. In illuminating gas the other constituents are removed by combustion and absorption and the residual gas measured as nitrogen.

Total nitrogen in organic substances is best determined by decomposition of the materials with sulphuric acid as described later, and estimating the nitrogen from the ammonia formed.

Combined nitrogen in the form of ammonia and nitric acid specially concerns the analyst. In the evaluation of fertilizers, feedstuffs, hay, fodders, grain, etc., the nitrogen is estimated after conversion to ammonia. Ammonia, nitrates and nitrites may be required in an analysis of sewages, water, and soils. Nitrie acid is determined in Chili saltpeter, in the evaluation of this material for the manufacture of nitric acid or a fertilizer, the nitrate being reduced to ammonia and thus estimated.

We will take up a few of the characteristic substances in which nitrogen estimations are required, e.g., in organic substances as proteids, in soils and fertilizers; in anuuonium salts, nitrates, and nitrites, free amuionia in ammioniacal liquors, nitric acid in the evaluation of the commercial acid and in mixed acids.

In general nitrogen is more accurately and easily measured as ammonia, to which form it is converted by reduction methods. Large amounts are determined by titration, whereas small amounts are estimated colorimetrically. Nitric acid and nitrates may be determined by direct titration by the Ferrous Sulphate Method outlined later. The procedure is of value in estimation of nitrates in mixed acids. The nitrometer method for determining nitrates (including nitrites), and the free acid in mixed acids, is generally used by manufacturers of explosives.

Preparation of the Sample

It will be recalled that compounds of animonia and of nitric acid are generally soluble in water. All nitrogen compounds, however, are not included. Among those which are not readily soluble the following deserve mention: compounds of nitrogen in many organic substances; nitrogen bromophosphide, NPBr₂; nitrogen selenide, NSc; nitrogen sulphide, N₄S₄; nitrogen pentasulphide, N₂S₅; ammonium antimonate, NH₄SbO₃·2H₂O; ammonium iodate, HN₄IO₄ (2.6 grams per 100 cc. H₂O); ammonium chlorplatinate, (NH₄)₂PtCl₅ (0.67 gram); ammonium chloriridate, (NH₄)₂IrCl₆ (0.7 gram); ammonium oxalate, (NH₄)₂C₂O₄·H₂O (4.2 grams); ammonium phosphomolybdate, (NH₄)₄PO₄·12MoO₅ (0.03 gram); nitron nitrate, C₂₀H₁₅N₄·HNO₅.

Organic Substances

By oxidation of nitrogenous organic substances with concentrated sulphuric acid, containing mercuric oxide, or potassium permanganate, the organic matter is destroyed and the nitrogen is changed to ammonia, which is held by the sulphuric acid as sulphate. Nitrates are reduced by addition of salicylic acid, sinc dust, etc., previous to the oxidation process. Practically all the procedures are based on the Kjeldahl method of acid digestion. The modification, commonly known as the Kjeldahl-Gunning-Arnold Method, is as follows:

Method in Absence of Nitrates. Weight of Sample. Fertilizers 0.7 to 3.5 grams. Soils 7 to 14 grams. Meat and meat products 2 grams. Milk 5 grams. The amount of the substance to be taken should be governed by its nitrogen content.

Acid Digestion.² The material is placed in a Kjeldahl flask of about 550 cc. capacity. Approximately 0.7 gram of mercuric oxide or an equivalent amount




Fig. 50.

Apparatus for Determining Nitrogen.

of mctallic mercury together with 10 grams of powdered potassium sulphate followed by 20 to 30 cc. of concentrated sulphurie acid (sp.gr. 1.84) are added. The flask is placed in an inclined position, resting in a large circular opening of an asbestos board. The flask is heated with a small flame until the frothing has ceased. (A piece of paraffin may be added to prevent extreme frothing.) The heat is then raised and the acid brought to brisk boiling, the heating being continued until the solution becomes a pale straw color, or practically water white. (In ease of leather, scrap, cheese, milk products, etc., a more prolouged digestion may be required. With a good flame from one-half to one hour of acid digestion is generally sufficient to completely decompose the material.) The flask is now removed from the flame and after cooling the solution is diluted with about 200 cc. of water and a few pieces of granulated zinc added to prevent "bumping" (50 mg. or so of No. 80 granulated zinc). The solution is now alkalized strongly by addition of a

mixture of sodium hydroxide and sodium sulphide solution (about 75 cc. of a mixture containing 25 grams of NaOII and 1 gram Na₂S). Phenolphthalein indicator added to the solution will show when the acid is neutralized. The flask is connected by means of a Hopkins distillation tube (Fig. 53) to a condenser and about 150 cc. of the solution distilled into an excess of standard sulphuric acid and the excess of the acid determined by titration with standard softum hydroxide. (Methyl red indicator.)

The ammonia may be absorbed in a saturated solution of boric acid and titrated directly with standard acid. (Methyl orange indicator.)³

One cc. N/10 $H_2SO_4 = 0.001704$ gram NH₃.

¹See data of approximate nitrogen contont in certain nitrogenous substances, Jour. Ind. Eng. Chem., 7, 357, 1915.

664, 1914.

² Fig. 50 shows a compact apparatus with several sets of flasks and condensers, which enable half a dozen or more determinations to be made at one time.

² L. W. Winkler, Z. angew. Chem., 27, 1, 630-2, 1914. E. Bernard, ibid., 27, 1,

In Presence of Nitrates. The procedure differs from the former in the preliminary treatment to reduce the nitrates. The material in the flask is treated with a mixture of 30 to 35 cc. of strong sulphuric acid containing 1 gram of salicylic acid and the mixture shaken and allowed to stand for five to ten minutes with frequent agitation. About 5 grams of sodium thiosulphate are now added and the solution heated for five minutes. After cooling, mercuric oxide or metallic mercury and potassium sulphate are added, and the solution treated as directed above.

Notes. Mercurie oxide or metallic mercury are added as a catalyzer to assist the oxidation of the organic matter. The digestion process is shortened considerably by its use. In place of mercurie oxide or the metal, copper sulphate may be used. In this case the addition of sodium sulphide is omitted. Copper sulphate acts as an indicator in the neutralization of the sample with caustic.

Potassium sulphide is added to remove the mercury from the solution and prevent the formation of mercur-ammonium compounds, which are not completely decomposed

by sodium hydroxide.

Ferric chloride, FeCl₃, may be used in place of copper or mercury salts or oxides to assist in the oxidation of organic matter.

Soils. Available Nitrates. Five hundred to 1000 grams of the air-dried soil is extracted with 1 to 2 liters of water containing 10 to 20 grams of dextrose. Fifteen to twenty hours of leaching is sufficient. An aliquot portion is taken for analysis.

Ammonium Salts. The sample is placed in the distillation flask with splash bulb as described in the modified Kjeldahl procedure for organic substances, and the material decomposed with ammonia-free caustic solution. The ammonia is distilled into an excess of standard acid or a saturated solution of boric acid (neutral to methyl orange), and the ammonia determined as usual, either by titration of the excess of acid, or by direct titration with acid, according to the absorbent used.

Nitrates. The sample, broken down as fine as possible, is dissolved in water, decomposed with Devarda alloy and distilled as described by the modified Devarda methods given later.

Nitrites. The material, dissolved in water, is titrated with standard permanganate solution according to the procedure described later.

Mixtures of Ammonium Salts, Nitrates, and Nitrites. Ammonia is determined by distillation with caustic as usual. The nitrite is titrated with permanganate. Total nitrogen is determined by the modified Devarda methods. Nitric acid is now estimated by difference, e.g., from the total nitrogen is deducted the nitrogen due to ammonia together with the nitrogen of the nitrite and the difference calculated to the nitrate desired. The nitrate may be determined in presence of nitrite and ammonia by direct titration with ferrous sulphate. The detailed procedures may be found under the Volumetric Methods.

Nitric Acid in Mixed Acid. This is best determined by the ferrous sulphate method for nitric acid. The nitrometer method is also excellent.

SEPARATIONS

Ammonia. No special separation need be considered in the determination of ammonia. The general method has already been mentioned by which ammonia is liberated from its salts by a strong base and volatilized by heat. This effects a separation from practically all substances.

Nitric Acid. The compound may be isolated as the fairly insoluble, crys-

talline nitron nitrate, C20H18N4. HNO3 by the following procedure.

Such an amount of the substance is taken as will contain about 0.1 gram nitric acid, and dissolved in about 100 cc. of water with addition of 10 drops of dilute sulphuric acid. The solution is heated nearly to boiling and about 12 cc. of nitron acetate solution added (10 grams of nitron in 100 ee. of 5% acetic acid).² The solution is cooled and placed in an ice pack for about two hours, and the compound then transferred to a Gooch or Munroe crucible (weighed crucible if gravimetric method is to be followed), and after draining, it is washed with about 10 to 12 cc. of ice-water added in small portions. The nitrate may now be determined gravimetrically by drying the precipitate to constant weight at 110° C., 16.53% of the material being due to NO₂.

The base diphenyl-endo-anilo-hydro-triazole (nitron) also precipitates the following acids: nitrous, chromic, chloric, perchloric, hydrobromic, hydrodic, hydroferro- and hydroferricyanic, oxalic, pieric and thiocyanic acids. Hence these must be absent from the solution if precipitation of nitric acid is desired for

quantitative estimation.

Removal of Nitrous Acid. Finely powdered hydrazine sulphate is dropped into the concentrated solution. (0.2 gram substance per 5 or 6 cc.)

Chromic acid is reduced by addition of hydrazine sulphate.

Hydrobromic acid is decomposed by chlorine water added drop by drop to the neutral solution, which is then boiled until the yellow color has disappeared.

Hydriodic acid is removed by adding an excess of potassium iodate to the neutral solution and boiling until the iodine is expelled.

PROCEDURES FOR THE DETERMINATION OF COMBINED NITROGEN

Ammonia

The volumetric procedures for determination of ammonia are preferred to the gravimetric on account of their accuracy and general applicability. The following gravimetric method may occasionally be of use:

Gravimetric Determination of Ammonia by Precipitation as Ammonium Platinochloride, (NH₄)₂PtCl₆

Ammonia in ammonium chloride may be determined gravimetrically by preeipitation with chlorplatinic acid. The method is the reciprocal of the one for determining platinum.

Procedure. The aqueous solution of the ammonium salt is treated with an excess of chlorplatinic acid and evaporated on the steam bath to dryness. The residue is taken up with absolute alcohol, filtered through a weighed Gooch crueible, and washed with alcohol. The residue may now be dried at 130° C. and weighed as (NH₄)₂PtCl₄, or it may be gently ignited in the covered crucible until

¹ M. Busch, Ber., **28**, 861 (1905), Treadwell and Hall, "Analytical Chemistry." Keep nitron reagent in a dark-colored bottle.

ammonium chloride has been largely expelled and then more strongly with free access of air. The residue of metallic platinum is weighed. If the ignition method is to be followed, the ammonium platinic chloride may be filtered into a small filter, the paper with the washed precipitate placed in a porcelain crucible and then gently heated until the paper is charred (crucible being covered) and then more strongly with free access of air until the carbon has been destroyed.

Factors.¹ $(NH_4)_2PtCl_6 \times 0.2400 = NH_4Cl$, or $0.08095 = NH_4$, or $\times 0.0767 = NH_4$. $Pt \times 0.5453 = NH_4Cl$, or $\times 0.1839 = NH_4$, or $\times 0.1736 = NH_4$.

AMMONIA

VOLUMETRIC METHODS FOR DETERMINATION OF

Two conditions are considered:

A. Estimation of free ammonia in solution.

B. Determination of ammonia in its salts-combined ammonia.

Analysis of Aqua Ammonia

Provided no other basic constituent is present, free ammonia in solution is best determined by direct titration with an acid in presence of methyl orange or methyl red as indicator.

Procedure. About 10 grams of the solution in a weighing bottle with glass stopper is introduced into an 800-cc. Erlenmeyer flask containing about 200 cc. of water and sufficient ½ normal sulphuric acid to combine with the ammonia and about 10 ec. in excess. The flask is stoppered and warmed gently. This orces out the stopper in the weighing bottle, the ammonia combining with the acid. Upon thorough mixing, the solution is cooled, and the excess of acid s titrated with half normal caustic.

One ec. $\frac{1}{2}$ N. $H_2SO_4 = 0.0085$ gram NfI_4

Factor. $H_2SO_4 \times 0.3473 = NII_3$.

Note. The aqua anunonia exposed to the air will lose ammonia, hence the sample should be kept stoppered. This loss of ammonia is quite appreciable in strong unmoniacal solutions.

Determination of Combined Ammonia. Ammonium Salts.

Strong bases decompose ammonium salts, liberating ammonia. This may be listilled into standard acid or into a saturated solution of borie acid (neutral to nethyl orange) and titrated.

Procedure. About 1 gram of the substance is placed in a distillation flask see Fig. 50) and excess of sodium or potassium hydroxide added and the immonia distilled into a saturated solution of borie acid or an excess of standard ulphuric acid. Ammonia in boric acid solution may be titrated directly with tandard acid (methyl orange or methyl red indicator) or in case a mineral acid

¹ Factors recommended by Treadwell and Hall, "Analytical Chemistry," 2, John Wiley & Sons.

was used to absorb the ammonia, the excess of acid is titrated with standard caustie solution.

One cc. half normal sulphuric acid = 0.0085 gram NH₂.

One cc. normal acid = 0.01703 gram NH₃.

Factors. $H_2SO_4 \times 0.3473 = NH_3$ and $NH_3 \times 2.8792 = H_2SO_4$.

ANALYSIS OF AMMONIACAL LIQUOR

The crude liquor by-product from coal gas in addition to ammonia contains hydrogen sulphide, carbon dioxide, hydrochloric acid, sulphuric acid, eombined with ammonia, also sulphites, thiosulphates, thiocyanates, cyanides, ferrocyanides, phenols.

Determination of Ammonia

Volatile Ammonia. This is determined by distillation of the ammonia into an excess of standard sulphurie acid and titrating the excess of acid. With the exception that caustic soda is omitted in this determination, the details are the same as those for total ammonia as stated in the next paragraph.

Total Ammonia. The true value of the liquor is ascertained by its total ammonia content. Ten to 25 ec. of the sample is diluted to about 250 ec. in a distilling flask with a potash connecting bulb, as previously described, 20 ec. of 5% sodium hydroxide are added and about 150 ee. of solution distilled into an excess of sulphuric acid. The excess is then titrated according to the standard procedure for ammonia.

One cc. N. $H_2SO_4 = 0.01703$ gram NH₂.

Fixed Ammonia is the difference between the total and the volatile ammonia.

Carbon Dioxide

Ten ce. of the liquor are diluted to 400 cc. and 10 ce. of 10% amnioniaeal calcium ehloride added and the mixture, placed in a flask with Bunsen valve, is digested on the water bath for two hours. The precipitated ealcium carbonate is washed, placed in a flask and an excess of N/2 HCl added and the excess acid titrated with N/2 NaOH.

N/2 HCl = 0.011 grain CO₂.

Hydrochloric Acid

Ten ce. of the liquor is diluted to 150 cc. and boiled to remove ammonia. Now hydrogen peroxide is added to oxidize organic matter, etc., the mixture being boiled to remove the excess of the peroxide. Chlorine is titrated in presence of potassium chromate as indicator by tenth normal silver nitrate after neutralizing with dilute nitrie acid.

One ee. N/10 AgNO₃ = 0.00364 gram HCl.

Hydrogen Sulphide

To 10 ee. of the liquor are added an excess of ammoniacal zinc ehloride or acetate, the mixture diluted to about 80 cc. and warmed to 40°. After settling for half an hour the zinc sulphide is filtered off and washed with warm water (40 to 50°); the precipitate is washed from the filter into an excess of N/10 iodine solution, the sulphide clinging to the paper washed into the main solution with hydrochloric acid. The mixture is acidified and the excess iodine titrated with N/10 sodium thiosulphate.

One cc. N/10 I = 0.0017 gram H_2S or 0.0016 gram S.

Sulphuric Acid

250 cc. of the liquor is concentrated to 10 cc., 2 cc. of concentrated hydrochloric added and the mixture heated to decompose any thiosulphate, sulphide or sulphite present. The concentrate is extracted with water, filtered and made to 250 cc. The sulphuric acid is now precipitated in an aliquot portion with barium chloride.

 $BaSO_4 \times 0.4202 = H_2SO_4$, or $\times 0.1374 = S$ present as H_2SO_4 .

Total Sulphur. Fifty cc. of the liquor is run by means of a pipette into a deep beaker (250 cc. capacity), containing an excess of bromine covered by dilute hydrochloric acid. The mixture is evaporated to dryness on the steam bath and the residue taken up with water and diluted to 250 cc. Sulphur is now precipitated as barium sulphate as usual, preferably on an aliquot portion.

For a more complete analysis of crude liquor determining sulphite, thiosulphate, thiocyanate, hydrocyanic acid, ferrocyanic acid, and phenols the analyst is referred to Lunge, "Technical Methods of Chemical Analysis," Part II, Vol. II, D. Van Nostrand Co.

Determination of Traces of Ammonia

The determination of traces of ammonia is best accomplished by the colorimetric method with Nessler's reagent. Details of the procedure are given in the chapter on water analysis.

NITRIC ACID. NITRATES

The alkalimetric method for determining free nitric acid, and the complete analysis of the commercial product are given in the chapter on Acids. Special procedures for determining the combined acid are herein given.

Gravimetric Method for Determining Nitric Acid by Precipitation as Nitron Nitrate, C₂₀H₁₆ N₄·HNO₃

As in ease of ammonia the volumetric methods are generally preferable for determining nitric acid, combined or free. Isolation of nitric acid by precipitation as nitron nitrate may occasionally be used. The fairly insoluble, erystalline compound, C₂₀H₁₄N₄·HNO₄ is formed by addition of the base diphenyl-endo-

anilo-hydro-triazole (nitron) to the solution containing the nitrate as directed under Separations. The precipitate washed with ice-water is dried to constant weight at 110° C. 16.53% of the compound is NO₂.

Note. The following acids should not be present in the solution, since their nitron salts are not readily soluble: nitrous, chromic, chloric, perchloric, hydrobromic, hydrojodic, hydroferrocyanic, hydroferricyanic, oxalic, picric and thiocyanic acids.

hydroiodic, hydroferrocyanic, hydroferricyanic, oxalic, pieric and thiocyanic acids. Solubility of less soluble nitron salts in 100 ec. of water. Nitron nitrate = 0.0099 gram, nitron bromide = 0.61 gram, iodide = 0.017 gram, nitrite = 0.19 gram, chromate = 0.06 gram, chlorate = 0.12 gram, perchlorate = 0.008 gram, thiocyanate = 0.04 gram. (Treadwell and Hall, "Analytical Chemistry, Quantitative Analysis.")

VOLUMETRIC METHODS

Direct Estimation of Nitrates by Reduction to Ammonia. Modified Devarda Method ¹

An accurate procedure for the determination of nitrogen in nitrates is Allen's modification of the Devarda method. The method is based upon the quantitative reduction of nitrates to ammonia in an alkaline solution by an alloy consisting of 45 parts of aluminum, 50 parts of copper and 5 parts of zine. The ammonia evolved is distilled into standard sulphuric acid and thus estimated. The method, originally designed for the valuation of sodium or potassium nitrates, is also of value in the determination of nitric acid, nitrites or ammonia. In the latter case the alloy is omitted.

Reagents Required. Devarda's Ailoy. Forty-five parts aluminum, 50 parts copper and 5 parts zinc. The aluminum is heated in a Hessian crucible in a furnace until the aluminum begins to melt, copper is now added in small portions until liquefied and zinc now plunged into the molten mass. The mix is heated for a few moments, covered and then stirred with an iron rod, allowed to cool slowly with the cover on and the crystallized mass pulverized.

Standard Sulphuric Acid. This is made from the stock C.P. acid by dilution so that 1 ec. is equal to 0.0057 gram H₂SO₄, 100 ec. of acid of this strength being equivalent to approximately 1 gram of sodium nitrate. (A tenth normal acid will do, a smaller sample being taken for analysis.) Since it is necessary to standardize this acid against a standard nitrate, it is advisable to have an acid especially for this determination rather than a common reagent for general use.

Standardization of the Acid. 11.6 grams of standard potassium nitrate, equivalent to about 9.6 grams of NaNO₃, is dissolved and made to volume in the weighing bottle (100 cc.), and 10 cc. is placed in the Devarda flask, reduced and the ammonia distilled into 100 cc. of the acid, exactly as the following method describes. The temperature of the acid is noted and its value in terms of H₂SO₄, KNO₃ and NaNO₃ stated on the container. The acid expands or contracts 0.029 cc. for every degree centigrade above or below the temperature of standardization, per 100 cc.

Standard Potassium Nitrate. The purest nitrate that can be obtained is recrystallized in small crystals, by stirring, during the cooling of the supersaturated concentrated solution, and dried first at 100° C. for several hours and then

¹ Paper by W. S. Allen, General Chemical Company, Eighth International Congress of Applied Chemistry.

at 210° C. to constant weight. Chlorides, sulphates, earbonates, lime, magnesia and sodium are tested for and if present are determined and allowance made.

Standard Sodium Hydroxide. This should be made of such strength that 1 cc. is equal to 1 cc. of the standard acid, 2 cc. methyl red being used as indicator. Ten cc. of the acid are diluted to 500 cc. and the alkali added until the color of the indicator changes from a red to a straw color.

Methyl Red Solution. 0.25 gram of methyl red is dissolved in 2000 cc. of 95% alcohol; 2 cc. of the indicator is used for each titration. As the indicator is sensitive to CO₂, all water used must first be boiled to expel carbonic acid. (Baker & Adamson, manufacturers of methyl red.)

Sodium Hydroxide—Sp.gr. 1.3. Pure sodium hydroxide is dissolved in distilled water and boiled in an uncovered casscrole with about 1 gram of Devarda's alloy to remove ammonia. This is cooled and kept in a well-stoppered bottle.

Apparatus. This is shown in the accompanying illustration, Fig. 51. It consists of the Devarda flask connected to the scrubber K, filled with glass wool. This




Fig. 51.—Devarda's Apparatus.

scrubber is heated by an electric coil or by steam passed into the surrounding jacket. The scrubber prevents caustic spray from being carried over into the receiving flask O. The form of the apparatus can best be ascertained from the sketch.

Weighing bottle with graduation at 100 cc. and a 10-cc. dropper with rubber bulb is used for weighing out the sample in solution. See Fig. 52.

Preparation of the Sample

Weight. It is advisable to take a large sample if possible, e.g., 100 grams of NaNO₁, 119 grams of KNO₁ or about 80 grams of strong HNO₂ (95%) or more




Fig. 52.
Weighing Bottle

and Dropper.

if the acid is dilute. Solids are taken from a large sample, all lumps being broken down. After dissolving in water the sample is made up to 1 liter. (Scum is broken up by addition of a little alcohol.) One hundred ec. of this solution is placed in the weighing bottle, which has been previously weighed being perfectly clean and dry. The difference is the weight of the 100-ec. sample.

Manipulation. All parts of the apparatus are washed out with CO₂-free water. All water used in this determination should be boiled to expel CO₂. Ninety-eight ec. of the standard acid is placed in flask O and washed down with 2 to 3 ec. of water. Two ee. of the standard acid is placed in flask P and washed down with 10 ec. of water and 13 to 14 drops of methyl red indicator added. Connections are made between the flasks and the scrubber. (The correction is made for the acid, the temperature being noted at the time of withdrawal.) A casserole, filled with cold water, is placed under F (see illustration).

The stem E is removed from the Devarda flask and 10 cc. (or more) of the nitrate added by means of the dropper in the weighing bottle, a funnel having been inserted in the flask. The bottle reweighed gives the weight of the sample removed, by difference. The nitrate is washed down with 10 cc. of water and 25 ce. of 20% caustic added (free from NH₂), the alkali washed down with 10 ec. more of water and then 3 grams of Devarda alloy placed in the flask by means of dry funnel. The stein E is quickly replaced, the stopcock being turned to close the tube. The reaction begins very soon. If it becomes violent, the reaction may be abated by stirring the water in the casserole, thus cooling the sample. After the energetic action has abated (five minutes), the easserole with the cold water is removed and the action allowed to continue for twenty minutes, meantime heat or steam is turned on in the scrubber. E is connected at C to the flask B containing caustic to act as a scrubber. It is advisable to have a second flask containing sulphurie acid attached to the caustic to prevent ammonia from the laboratory entering the system. A casserole with hot water is placed under F and the burner lighted and turned on full. A gentle suction is now applied at R, the stop-cock D being turned to admit pure air into the evolution flask; the rate should be about 5 to 6 bubbles per second. The suction is continued for thirty minutes, hot water being replaced in the casserole as the water evaporates. The heat is now turned off and the apparatus disconnected at M and J. The contents of this elbow and the condenser are washed into the flask O. The acid in O and P poured into an 800-cc. beaker and rinsed out several times. The volume in the beaker is made up to 500 cc., 1 cc. of methyl red added, and the free acid titrated with the standard caustic. The end-point is a straw yellow.

Calculation. The ce. of the back titration with caustic being deducted, the volume of the acid remaining (e.g., combined with ammonia) is corrected to the standard condition. Expansion or contraction per 100 ec. is 0.029 ec. per each degree C. above or below the temperature at which the acid was standardized. If the acid is exactly 0.057 gram H₂SO₄ per ec., the result multiplied by 0.989 and

divided by the weight of the sample taken gives per cent nitrate. (In terms of NaNO3.)

The Weight of the Sample. Ten times the difference of the weighings of the bottle W before and after removal of the 10 cc. and the product divided by the weight of the 100 ce. of the solution equals the weight of solid taken.

Example. Weight of the bottle +100 cc. sample = 218 grans. Weight of the bottle

=112 grams, therefore weight of 100 cc. NaNO₃ = 106 grams.

Weight of the bottle+100 cc. sample = 218. Weight after removal of 10 cc = 207.4 grams, therefore sample taken = 10.6 grams, including the added water. Now from

above the weight of the actual sample taken $= 10.6 \times 10 \div 106 = 1$ grant. Temperature Correction. Temperature of standardization $= 20^{\circ}$ C.

Temperature of the sulphuric acid when taken for the analysis = 31° C. Back titration of the The eorrect volume = $(100-2) - ((31-20) \times 0.029) = 97.681$ caustie = 2 ec. H_1SO_4 combined with ammonia from the reduced nitrate. $97.681 \times 0.989 + 1 = 96.62\%$ NaNOs.

Factors. $H_2SO_4 \times 2.06107 = KNO_3$ or $\times 1.7334 = NaNO_3$ or $\times 1.2850 = HNO_3$.

 $H_2SO_4 \times 0.9587 = HNO_2$ or $\times 0.3473 = NH_3$.

 $NH_3 \times 3.6995 = HNO_3$ or $\times 4.9906 = NaNO_3$ or $\times 4.0513 = NaNO_2$.

 $NaNO_3 \times 1.1894 = KNO_3$ and $KNO_3 \times 0.8408 = NaNO_3$.

ANALYSIS OF NITRATE OF SODA

The following impurities may occur in nitrate of soda: KNO3, NaCl, Na₇SO4, Na₂CO₃, NaClO₃, NaClO₄, Fe₂O₃, Al₂O₃, CaO, MgO, SiO₂, H₂O, etc. In the analysis of sodium nitrate for determination of NaNO, by difference, moisture, NaCl, Na₂SO₄ and insoluble matter are determined and their sum deducted from 100, the difference being taken as NaNO3. Such a procedure is far from accurate, the only reliable method being a direct determination of niter by the Devarda method given in detail. The following analysis may be required in the valuation of the nitrate of soda.

Determination of Moisture

Twenty grams of sample are heated in a weighed platimm dish at 205 to 210° C, for fifteen minutes in an air bath or electric oven. The loss of weight multiplied by 5 = per cent moisture. (Save sample for further tests.)

Insoluble Matter

Ten grams are treated with 50 ce. of water and filtered through a tared Gooch. The increased weight dried residue (100° C.) multiplied by 10 = per cent insoluble matter. (Save filtrate.)

Sodium Sulphate

The moisture sample is dissolved in 20 cc. hot water and transferred to a porcelain crueible. It is evaporated several times with hydrochloric acid to dryness to expel nitric acid. (Until no odor of free chlorine is noticed when thus treated.) Fifty cc. of water and 5 cc. hydrochloric acid are now added and the sample filtered. Any residue remaining is principally silica. The filtrate is heated to boiling, 10 cc. of 10% barium chloride solution added, and the precipitated sulphate filtered off, ignited and weighed.

 $BaSO_4 \times 3.0445 = per cent Na_2 SO_4$.

Iron, Alumina, Lime, and Magnesia

These impurities may be determined on a 20-gram dried sample, the material being dried and evaporated as in case of the sodium sulphate determination. The filtrate from silica is treated with animonium hydroxide and Fe(OH)₁ and Al(OH)₂ filtered off. Lime is precipitated from the iron and alumina filtrate as oxalate and magnesia determined by precipitation as phosphate from the lime filtrate by the standard procedures.

Sodium Chloride

The filtrate from the insoluble residue is brought to boiling and magnesia, MgO (Cl free), is added until the solution is alkaline to litinus. 0.5 ce. of 1% potassium chromate (K₂CrO₄) solution is added as an indicator and then the solution is titrated with a standard solution of silver nitrate until a faint red tinge is seen, the procedure being similar to the determination of chlorides in water by silver nitrate titration. The cc. AgNO₃×factor for this reagent×10 = per cent NaCl.

Silver nitrate is standardized against a salt solution.

Carbonates

This determination is seldom made. CO₂ may be tested for by addition of dilute sulphuric acid to the salt. Effervescence indicates carbonates. Any evolved gas may be tested by lime water, which becomes cloudy if CO₂ is present. For details of the procedure reference is made to the chapter on Carbon.

DETERMINATION OF NITRIC NITROGEN IN SOIL EXTRACTS

Vamari-Mitscherlich-Devarda Method

Procedure. Forty cc. of water, a small pinch of magnesia and one of magnesium sulphate are added to flask D of the Mitscherlich apparatus (Fig. 53). Twenty-five cc. of standard acid and 60 cc. of neutral redistilled water are placed in flask F; 250 or 300 cc. of aqueous soil extract are placed in a 500-cc. Kjeldahl flask, 2 cc. of 50% sodium hydroxide added, the mouth of the flask closed with a small funnel to prevent spattering, and the contents of the flask boiled for thirty minutes. The water which has boiled off is replaced, and, after cooling, 1 gram of Devarda's alloy (60 mesh), and a small piece of paraffin are added and the flask connected with the apparatus; reduction and distillation are carried on for forty minutes. The receiver contents are then cooled, 4 drops of 0.02%

solution of methyl red added, the excess acid is nearly neutralized, the liquid boiled to expel CO₂, cooled to 10 to 15° and the titration completed.




Fig. 53.—Mitscherlich's Apparatus for Nitrogen Determination.

B. S. Davisson¹ recommends an improved form of scrubber, shown in Fig. 53a to be used in place of the Hopkins bulb (Fig. 53). The bulb and adaptor are made of Pyrex glass. Steam condenses in the bulb and the condensate acts as a scrubber preventing alkali mist from being carried over with the ammonia. During the test ammonia is completely volatilized into the absorption The bulb of the adaptor, flask. shown as II, prevents back suction into the distillation flask.




Fig. 53a.-Davisson's Scrubber.

¹ Reference B. S. Davisson, Ohio, Ag. Exp. Station, J. Ind. Eng. Chem., 11, 465 (May, 1919).

Determination of Hydroxylamine-Method of Raschig¹

Hydroxylamine in hot acid solutions reduces ferric salts to ferrous condition quantitatively according to the reaction:

$$2NII_2OII + 2Fe_2(SO_4)_3 = 4FeSO_4 = 2H_2SO_4 + N_2O + H_2O.$$

The amount of ferrous iron formed is a measure of the hydroxylamine originally present.

Procedure. Approximately 0.1 gram of hydroxylamine salt is dissolved in a little water in an Erlenmeyer flask and 30 ee. of cold saturated solution of ferrie-ammonium alum added, followed by 10 ec. of dilute sulphuric acid (1:4). The solution is heated to boiling and kept at this temperature for five minutes, then diluted to 300 ce. and titrated immediately with standard permanganate solution.

1 ee. $N/10 \text{ KMnO}_4 = 0.001652 \text{ g. NH}_2OII.$

lodometric Determination of Nitrates—Method of Gooch and Gruener²

By this method the nitrate to be estimated is treated, in an atmosphere of carbon dioxide, with a saturated solution of manganous ehloride (erystallized) in concentrated hydroehloric acid, the volatile products of the reaction (nitrogen dioxide, chlorine, etc.) are now distilled and eaught in a solution of potassium iodide. The iodine set free is titrated by a standard solution of thiosulphate.

Procedure. The nitrate and the manganous mixture (saturated solution of crystallized manganous ehloride and strong hydroehlorie aeid—20 cc. per 0.2 gram sample) following it are introduced into the pipette shown in Fig. 53a (marked III) suction being applied, if necessary, at the end of the absorption train (VI). The current of CO_2 is started immediately after putting in the mixture. When the air has been replaced by CO_2 , heat is applied to the retort III and the distillation continued until nearly all the liquid has passed over into the receiver IV, which is cooled by water. (See illustration.) The contents of the receivers are united and the bulbs washed out by passing the wash water directly through III and IV. Introduction of manganous chloride into the distillate does not influence the accuracy of the titration. The liberated iodine is titrated with standard sodium thiosulphate as soon as possible after

For discussion of the two methods see paper by Wm. C. Bray, Miriam E. Simpson and Anna A. MacKenzie, Jour. Am. Chem. Soc., 41, 9, 1362, Sept., 1919.

² "Methods in Chemical Analysis," by F. A. Gooch. F. A. Gooch and H. W. Gruener, Am. Jour. Sci. (3), XLIV, 117.

¹ Hydroxylamine may also be determined by reduction with an excess of titanous salt in acid solution with exclusion of air, and the excess titrated with permanganate.

Reaction: 2NH₂OH+Ti₂(SO₄)₃ = (NH₄)₂SO₄+4TiOSO₄+H₂SO₄.

admitting air to the distillate, since traces of dissolved nitric oxide reoxidized by the air would react with the iodide liberating more iodine.




Fig. 53b. Gooch-Gruener Apparatus.

DETERMINATION OF NITROGEN OF NITRATES (AND NITRITES) BY MEANS OF THE NITROMETER

The nitrometer is an exceedingly useful instrument employed in the accurate measurement of guses liberated in a great many reactions and has therefore a number of practical applications. It may be used in the determination of carbon dioxide in carbonates; the available oxygen in hydrogen dioxide; in the valuation of nitrous ether and nitrites; in the valuation of nitrates and nitric acid in mixed acids.

The method for the determination of nitrogen in nitrates, with which we are concerned in this chapter, depends on the reaction between sulphuric acid and nitrates in presence of mercury:

$$2KNO_{2}+4H_{2}SO_{4}+3Hg=K_{2}SO_{4}+3HgSO_{4}+4H_{2}O+2NO.$$

The simplest type of apparatus is shown in the illustration, Fig. 54. The graduated decomposition tube has a capacity of 100 cc. It is connected at the base by means of a heavy-walled rubber tubing with an ungraduated leveling tube (b). At the upper portion of (a) and separated from it by a glass stop-cock (s) is a bulb (c) of about 5 cc. capacity; a second stop-cock enables completely enclosing the sample, as may be necessary in volatile compounds. The glass stop-cock (s), directly above the graduated chamber, is perforated so as

by using the formula

to establish connection with the tube (d) when desired and the graduated

cylinder (a). Procedure. The tube (b) is filled with mercury and the air in (a) now displaced by mcrcury, by turning the stop-cock to form an open passage between (a) and (d) and then raising (b). A sample of not over 0.35 gram potassium nitrate or a corresponding amount of other nitrates, is introduced into (c), the material being washed in with the least amount of water necessary (1 to 2 cc.). By lowering (b) and opening the stop-cock s the solution is drawn into the decomposition chamber, taking care that no air enters. This is followed by about 15 cc. of pure, strong sulphuric acid through s₁ and s, avoiding admitting air as before. NO gas is liberated by the heat of reaction between the sulphuric acid and the water solution. When the reaction subsides, the tube (a) is shaken to mix the mercury with the liquor and the NO completely liberated. The gas is allowed to eool to room temperature and then measured, after raising or lowering (b) so that the column of mercury is the calculated excess of height above that in (a) in order to have the gas under atmospheric pressure. The excess of height is obtained by dividing the length of the acid layer in (a), in millimeters, by 7 and elevating the level of the mercury in (b) above that in (a) by this quotient; i.e., if the acid layer = 21 mm. the mercury in (b) would be 3 mm. above that in (a). The volume of gas is reduced to standard conditions

 $V' = \frac{V(P - w)}{760(1 + 0.00367t)}.$

V' =volume under standard conditions; V =observed volume; P =observed barometric pressure in mm.; w =tension of aqueous vapor at the observed temperature, expressed in millimeters; t =observed temperature.

One cc. gas = 4.62 milligrams of KNO₃, or 3.8 milligrams NaNO₃ or 2.816 milligrams HNO₃.

Du Pont Nitrometer Method 1

The Du Pont nitrometer, Fig. 55, is the most accurate apparatus for the volumetric determination of nitrates. By use of this, direct readings in per cent may be obtained, without recourse to correction of the volume of gas to standard conditions and calculations such as are required with the ordinary nitrometers.

The apparatus consists of a generating bulb of 300 cc. capacity E with its reservoir F connected to it by a heavy-walled rubber tubing. E carries two glass stop-cocks as is shown in illustration. The upper is a two-way stop-cock connecting either the cup or an exit tube with the chamber. D is the chamber-reading burette, calibrated to read in percentages of nitrogen, and graduated from 10 to 14%, divided in 1/100%. Between 171.8 and 240.4 cc. of gas must be generated to obtain a reading. A is also a measuring burette, that may be used in place of D where a wider range of measurement is desired. "It is used for the measurement of small as well as large amounts of gas. It is most commonly graduated to hold 300.1 milligrams of NO at 20° C. and 760 mm. pressure and this volume is divided into 100 units (subdivided into tenths) each unit being equivalent to 3.001 milligrams of NO. When compensated, the gas from

¹See paper by J. R. Pitman, Jour. Soc. Chem. Ind., p. 983, 1900.

ten times the molecular weight in milligrams of any nitrate of the formula RNO₁ (or five times molecular weight of $R(NO_3)_2$) should exactly fill the burette. This simplifies all calculations; for example the per cent nitric acid in a mixed acid would be

$$\frac{R63.02}{100W} = \text{per cent HNO}_3.$$

R= burette reading, W= grams acid taken." 1 C is the compensating burette very similar in form to the chamber burette D. B is the leveling bulb, by the




Fig. 54.—Nitrometer.

Fig. 55.—Du Pont's Nitrometer.

raising or lowering of which the standard pressure in the system may be obtained. The apparatus as shown in Fig. 55 is mounted on an iron stand. As in the more simple form of apparatus, previously described, mercury is used as the confining liquid. The parts are connected by heavy-walled rubber tubing, wired to the glass parts.

¹ A. W. Betts, Chemist, E. I. DuPont de Nemours Powder Co., in letter to author.

Standardizing the Apparatus. The apparatus having been arranged and the various parts filled with mercury, the instrument is standardized as follows: 20 to 30 cc. of sulphuric acid are drawn into the generating bulb through the cup at the top, and at the same time about 210 cc. of air; the cocks are then closed, and the bulb well shaken; this thoroughly desiccates the air, which is then run over into the compensating burette until the mercury is about on a level with the 12.30% mark on the other burette, the two being held in the same relative position, after which the compensating burette is sealed off at the top. A further quantity of air is desiceated in the same manner and run into the reading burette so as to fill up to about the same mark; the cocks are then closed, and a small piece of glass tubing bent in the form of a U, half filled with sulphuric acid (not water), is attached to the outlet of the reading burette; when the mercury columns are balanced and the enclosed air cooled down, the eock is again carefully opened, and when the sulphuric balances in the U-tube, and the mercury columns in both burettes are at the same level, then the air in each one is under the same conditions of temperature and pressure. A reading is now made from the burette, and the barometric pressure and temperature carefully noted, using the formula

$$V_{t} = \frac{V_{o}P_{o}(273+t)}{P_{t}273},$$

the volume this onclosed air would occupy at 29.92 ins. pressure and 20° C. is found. The cock is again closed and the reservoir manipulated so as to bring the mercury in both burettes to the same level, and in the reading burette to the calculated value as well. A strip of paper is now pasted on the compensating burette at the level of the mercury, and the standardization is then complete.

Another rapid method of standardizing is to fill the compensating chamber with desiccated air as stated in the first procedure and then to introduce into the generating chamber 1 grain of pure potassium nitrate dissolved in 2 to 4 cc. of water, the cup is rinsed out with 20 ec. of 66° Béaume sulphuric acid, making three or four washings of it, each lot being drawn down separately into the bulb. The generated gas formed after vigorous shaking of the mixture, as stated under procedure, is run into the measuring burette. The columns in both burettes are balanced so that the reading burette is at 13.85 (=per cent N in KNO₃). A strip of paper is pasted on the compensating burette at the level of the mercury, and standardization is accomplished. By this method the temperature and pressure readings, and the calculations are avoided.

Procedure for Making the Test. Salts. One gram of sodium or potassium nitrate, or such an amount of the material as will generate between 172 to 240 ee. of gas, is dissolved in a little water and placed in the cup of the generating bulb.

Liquid Acids. The acid is weighed in a Lunge pipette and the desired amount run into the funnel of the generating bulb, the amount of acid that is taken being governed by its nitrogen content.

The sample is drawn into the bulb; the funnel is then rinsed out with three or four successive washings of 95% sulphuric acid, the total quantity being 20 ce.

To generate the gas, the bulb is shaken well until apparently all the gas is

¹ Standardization with "C. P. KNO₃ is the better, as it is less tedious and is not subject to the correction errors that cannot be escaped when standardizing with air. The KNO₃ must be of undoubted purity."—A. W. Betts.

formed, taking care that the lower stop-cock has been left open, this cock is then closed and the shaking repeated for two minutes. The reservoir is then lowered until about 60 ce. of mercury and 20 ce. of acid are left in the generating bulb. There will remain then sufficient space for 220 cc. of gas.

Note. If too much mercury is left in the bulb, the mixture will be so thick that it will be found difficult to complete the reaction, a long time will be required for the residue to settle and some of the gas is liable to be held in suspension by the mercury, so that inaccurate results follow.

The generated gas is now transferred to the reading burette, and after waiting a couple of minutes to allow for cooling, both burettes are balanced, so that in the compensating tube the mercury column is on a level with the paper mark as well as with the column in the reading burette; the reading is then taken.

If exactly one gram of the substance is taken the percentage of nitrogen may be read directly, but in ease of other amounts being taken, as will invariably be the case in the analysis of acids, the rendings are divided by the weight of the substance and multiplied by 4.5 to obtain the per cent of nitric acid monohydrate present.

The procedure may be used for determining nitrites as well as nitrates.

Determination of HNO3 in Oleum by Du Pont Nitrometer Method 1

About 10 ce. oleum are weighed in a 30-cc. weighing bottle, 10 ec. 95% reagent sulphuric acid added and mixed by shaking. This mixture is transferred to the nitrometer reaction tube and the weighing bottle and nitrometer cup rinsed with three 5-cc. portions of the reagent sulphuric acid which is drawn into the reaction tube. This is vigorously shaken for three minutes and the gas then passed to the measuring tube and allowed to stand for about five minutes, after which the mercury levels are adjusted and the reading taken.

It is obvious that this determination includes any nitrons acid in the oleum.

Combined Nitric Acid

The nitrie acid in nitrates may be determined by titration with ferrous sulphate. The nitrate dissolved in a little water is run into strong sulphuric acid and titrated with standard ferrous sulphate according to the procedure described for determining free nitric acid in mixed acids (Vol. II, Acids).

Determination of Free Nitric Acid

Other acids being absent, free nitric acid may be determined by titration with standard alkali. Details for the analysis of nitric acid in presence of commonly occurring impurities are given in Volume II in the chapter on Acids.

1 ce. N/1 NaOH = 0.063018 g. HNO₃

¹ By courtesy of E. I. du Pont de Nemours Powder Co.

DETERMINATION OF NITRITES

Gravimetric Method of Buovold²

One and one fourth to 1.5 gram of AgBrO₃ is dissolved in 100 ec. of water and 110 ec. of 2 N. acetic acid, in an Erlnmeyer flask. 200 cc. of the nitrite solution (1 g. NaNO₂) are added from a burette, stirring the mixture during addition of the nitrite. A pale green precipitate is obtained. 30 ec. of H_2SO_4 (1:4) are added, the mixture warmed to 85°. When the yellow precipitate settles it is filtered on a Gooch and washed with hot water, then dried and weighed as AgBr+AgCl—chlorine is determined on a separate portion and AgCl deducted. AgBr×0.9070 = NaNO₂. The method is specially applicable to nitrites high in chlorine.

Volumetric Permanganate Method

Principle. Potassium permanganate reacts with nitrous acid or a nitrite as follows:

$$5N_2O_3+4KM_1O_4+6H_2SO_4=5N_2O_5+2K_2SO_4+4M_1SO_4+6H_2O_5$$

$$5HNO_2+2KMnO_4+3H_2SO_4=5HNO_3+K_2SO_4+2MnSO_4+3H_2O_1$$

Since $2KMnO_4$ in acid solution has five available oxygens for oxidation of substances (e.g., $2KMnO_4 = K_2O.2MnO + 5O$ equivalent to 10H) the molecular weights of the constituents divided by 20 in the first equation and by 10 in the second would represent the normal weights per liter, e.g., $5N_2O_3$ divided by 20 = 76 divided by 4 = 19 grams N_2O_4 per liter. $4KMnO_4$ divided by 20 or $2KMnO_4$ divided by 10 = 158.03 divided by 5 = 31.61 grams of $KMnO_4$ per liter for a normal solution. In the second equation if Na represents the univalent element we would have $5NaNO_2$ divided by 10 or 69 divided by 2 = 34.5 grams per liter. Hence 1 cc. of a normal $KMnO_4$ solution would oxidize 0.019 gram N_2O_3 or 0.0345 gram $NaNO_2$ to form N_2O_4 and $NaNO_3$ respectively.

Organic matter is also oxidized by KMnO4 hence will interfere if present.

Special Reagents.

N/5 Potassium Permanganate. The solution contains 6.322 grams KMnO₄ per liter.

N/5 Sodium Oxalate. Na₂C₂O₄ reacts with KMnO₄ as follows:

$$5Na_2C_2O_4 + 2KMnO_4 + 8H_2SO_4 = K_2SO_4 + 2MnSO_4 + 5Na_2SO_4 + 10CO_2 + 8H_2O_4$$

Hence 5Na₂C₂O₄ divided by 10 or 134 divided by 2=67 grams per liter=a normal sodium oxalate solution. A N/5 solution requires 13.4 grams Na₂C₂O₄ per liter.

^a Chem. Ztg. 38, 28, C. A. 8, 1250 (1914).

Preparation of the Sample.

Soluble Nitrites. Ten grams of the nitrite are dissolved in water and made

to 1000 ce.; 10 ee. contain 0.1 gram of the sample.

Water-insoluble Nitrites. 0.5 to 1.0 gram of the nitrite according to the amount of nitrous acid present is taken for analysis. An excess of KMnO₄ solution is added, followed by dilute H₂SO₄ and the excess standard permanganate titrated with sodium oxalate according to directions given under Procedure.

Nitrous Acid in Nitric Acid and Mixed Acids. This is present generally in very small amounts so that a large sample is taken. The amount and details of the procedures are given under the special subject.

For routine work where a number of daily determinations are made, a

50-ee. burette is generally preferred.

Trial Run. If the approximate strength of the salt is not known the following test may be quickly made to ascertain whether more than 50 cc. of solution is necessary and the approximate amount of KMnO₄ required for oxidation.

Ten ce. of the solution together with 100 cc. of water are placed in a 4-in. casserole and about 10 cc. of dilute H₂SO₄, 1:1, added. Standard KMnO₄ from a 50-ce, burette is now run into the sample until a permanent pink color is obtained. The ee. of KMnO₄ multiplied by 5 = the approximate amount of permanganate solution required for oxidation of 50 cc. of sample. An excess of 5 to 10 cc. should be taken in the regular run.

Titration of Nitrite. Sufficient standard N/5 KMnO₄ to oxidize the sample to be titrated (as ascertained by the trial run) and 10 cc. excess are placed in a casserole. The solution is acidified with 10 ee. of dilute (1:4) $\rm H_2SO_4$ and 50 ee. of the nitrite solution is added slowly with constant stirring. The sample is placed on a hot plate until the mixture reaches a temperature of 70° to 80° C. and 25 ec. more of the dilute $\rm H_2SO_4$ added. The excess permanganate is now titrated with N/5 Na₂C₂O₄, the oxalate being added slowly until the permanganate color is destroyed. Five cc. excess of the oxalate are added and the exact excess determined by titrating the hot solution with N/5 KMnO₄ to a faint pink color. The total permanganate solution taken minus the oxalate titration = ee. KMnO₄ required by the nitrite.

Standard ferrous sulphate, FeSO₄, may be used, in place of sodium oxalate.

The titration then may be conducted in the cold.

One ee. N/5 $KMnO_4 = 0.0038$ g. N_2O_3 , or 0.0069 g. $NaNO_2$, or 0.0085 g. KNO_2 .

Detection of a Nitrate in a Nitrite Salt

Iridium salts are colored blue by IINO₃ but no color is produced by HNO₂. Use a 0.025% solution of IrO₂ or $(NH_4)_2$ IrCl₆ per 100 cc. of 98-99% H_2SO_4 and heat to boiling. The solution should be kept in a stoppered bottle. Into the hot reagent in a test tube is dropped the solid substance tested. A blue color is produced by nitrates. If the nitrite is in solution, make alkaline with KOH, evaporate to dryness and test the residue. Chlorine interferes, but not FeCl₂.

Determination of Pyridine in Ammonium Nitrate¹

Dissolve 250 g. of sample in 300 cc. of distilled water, using a 1000 cc. Kjeldahl or Florence flask. Add a few drops of methyl orange and neutralize with 10% sodium hydroxide solution. Then add 15 cc. excess of 10% sodium hydroxide solution. Set up apparatus, note Fig. 55a, using 300 cc. hypobromite solution in the second flask and receiving the distillate in 25 cc. N/10




FIG. 55a.—APPARATUS FOR PYRIDINE.

The whole is set around a single ring stand. The hypobromite flask is 2 in. by 14 in. The hypobromite, 300 cc., occupies 71 in. of the height at the start of the test.

sulfuric acid. Distil until 100 cc. of distillate have been collected. The heating should be very slow until all the ammonia, driven off, has been destroyed. This point will be indicated first by an acid reaction of the methyl orange in the first flask and second by the gradual reduction of the amount of nitrogen given off, in very small bubbles, in the hypobromite. At this point the hypobromite flask should not be warm enough to burn the hand (not above 70° to 75° C.). It is now safe to increase the heat so that boiling occurs in the hypobromite in 10 to 15 min. and 100 cc. of distillate comes over in 20 to 25 min. after active boiling starts.

Titrate the liquid in the receiver, using N/10 sodium hydroxide solution with methyl orange as the indicator.

¹ Ref. R. M. Ladd, Jour. Ind. Eng. Chem., Vol. 11, no. 6, page 552 (June, 1919). By courtesy of the author.

Record the end-point; add $\frac{1}{2}$ cc. of phenolphthalein (1:1000) solution and continue the titration until a red color which will persist for 30 sec. appears. Subtract the methyl orange end-point from that obtained with phenolphthalein, and multiply the difference by 0.0079. The result is the pyridine bases in grams. Methyl orange indicates pyridine plus ammonia. Phenolphthalein indicates ammonia. Difference is due to pyridine.

Notes. Because of the fact that the methyl orange and phenolphthalein endpoints are never quite the same and because an absorption of carbon dioxide by the sodium hydroxide solution may bring it about that they vary still more widely, it is necessary to standardize the solutions used to both end-points and to make a correction for their normal difference. This correction should be checked by a new standardization at least once a week. We found that with our solutions this difference was usually about 0.4 ec.

In case it is desired to use a sample of a different size, maintain the proportions indicated above, except that the total solution in the first flask should always be about 500 oc

The hypobromite solution is made up as follows: 100 g. sodium hydroxide are dissolved in 800 ec. of water, 25 cc. of liquid bromine are added, and the mixture shaken until the bromine is entirely dissolved and made up to 1,000 cc. The solution should be made up a day in advance. It will maintain its strength for at least a week if kept in a stoppered, dark bottle. It will be brown in color. Should the brown color disappear during the distillation it would mean that an excess of ammonia is present. This should also be indicated and eliminated from the calculations by the double endpoint ealled for, but in case this happens it is well to repeat the test, using more of the hypobromite solution.

The reactions involved and the calculations on which the proportions are based are indicated in the following equations:

$$NaOII + NH4NO3 \rightarrow NH3 + H2O + NaNO3$$

15 cc. 10% sodium hydroxide solution contains 1.5 g. sodium hydroxide 1.5 g. sodium hydroxide will free 0.6375 g. ammonia

$$2NH_3 + 3NaBrO \rightarrow 3H_2O + N_2 + 3NaBr$$

34 357

0.638 g. ammonia is destroyed by 6.699 g. sodium hypobromite

$$2NaOII + Br_2 \rightarrow NaBrO + NaBr + H_2O$$

80 160 119

25 cc. bromine = 79.5 g. bromine

300 ce. solution contains 17.7 g. hypobroinite (approx.)

DETERMINATION OF NITROGEN IN STEEL 1

For the determination of nitrogen in steel, a modification of the method first published by A. H. Allen and modified by Prof. J. W. Langley is used.

By the following method the sample and standard distillates are prepared under similar conditions, and when treated with Nessler reagent, develop colors nearly identical in quality or tone, but proportional in intensity to the ammonia present.

If the Nessler reagent is carefully prepared and works properly, the color in sample and standard will develop almost instantly and is fully developed in less than one minute. The solutions treated with such reagent remain clear or do not cloud appreciably on standing for ten minutes; however, the comparison is best made after standing one minute, and all difficulty due to clouding avoided.

The difficulties of comparison are also reduced to a minimum by using an aliquot part of the distillate in the manner to be described instead of that corresponding to the whole sample.

Preparation of Reagents

Hydrochloric acid of 1.1 sp. gr., free from ammonia, which may be prepared by distilling pure hydrochloric acid gas into distilled water free from ammonia. To do this, take a large flask fitted with a rubber stopper carrying a separatory funnel-tube and an evolution-tube, fill it half full of strong hydrochloric acid, connect the evolution-tube with a wash-bottle connected with a bottle containing the distilled water. Admit strong sulphuric acid free from nitrous acid to the flask through the funnel-tube, apply heat as required, and distill the gas into the prepared water.

Test the acid by admitting some of it into the distilling apparatus, described farther on, and distilling it from an excess of pure caustic soda, or determine the amount of ammonia in a portion of hydrochloric acid of 1.1 sp. gr., and

use the amount found as a correction.

Note. The ammonia-free hydrochloric acid may also be prepared as follows: Dilute concentrated hydrochloric acid to specific gravity 1.10 and without addition of sulphuric acid distill it.

Hydroehloric acid of this strength distills without change in concentration.

The first 100-cc, distillate from one litre of acid will usually contain all the ammonia and is rejected; the portions distilled thereafter being collected for use but must, of course, be tested as usual to make sure it is free from ammonia.

Solution of caustic soda, made by dissolving 300 grams of fused caustic soda in 500 cc. of water and digesting it for 24 hours at 50° C. on a copper zinc couple, made, as described by Gladstone and Tribe, as follows:

Place from 25 to 30 grams of thin sheet zinc in a flask and cover with a moderately concentrated, slightly warm solution of copper sulphate. A thick, spongy coating of copper will be deposited on the zinc. Pour off the solution in about ten minutes and wash thoroughly with cold distilled water.

Nessier Reagent. Dissolve 35 grams of potassium iodide in a small quantity of distilled water, and add a strong solution of mercurio chloride little by little, shaking after each addition until the red precipitate formed dissolves. Finally the precipitate formed will fail to dissolve, then stop the addition of the mercury salt and filter. Add to the filtrate 120 grams of caustic soda dissolved in a small amount of water, and dilute until the entire solution measures I litre. Add to this 5 ec. of saturated aqueous solution of mercuric chloride, mix thoroughly, allow the precipitate formed to settle, and decant or siphon off the clear liquid into a glass-stoppered bottle.

¹ Methods of Analysis used in Laboratories of the Titanium Alloy Manufacturing Co. Contributed by L. E. Barton.

Standard Ammonia Solution. Dissolve 0.0382 gram of ammonium chloride in 1 litre of water. 1 ee. of this solution will equal 0.01 milligram of nitrogen.

Distilled Water Free From Ammonia. If the ordinary distilled water contains ammonia, redistill it, reject the first portions coming over, and use the subsequent portions, which will be found free from ammonia. Several glass cylinders of colorless glass of about 160 cc. capacity are also required.

The best form of distilling apparatus consists of an Erlenmeyer flask of about 1500 ee. capacity, with a rubber stopper, carrying a separatory funnel-tube and an evolution-tube, the latter connected with a condensing-tube around which passes a constant stream of cold water. The inside tube, where it issues from the condenser, should be sufficiently high to dip into one of the glass cylinders placed on the working table.

Method of Determination

Distillation of Sample

In a distilling flask of 1000 to 1500 ec. capacity, fitted with separatory funnel and connected with condenser, place 40 cc. prepared caustic soda solution; add 500 cc. distilled water and distill until the distillate gives no reaction with Nessler reagent.

Dissolve a 5-gram sample of the steel in 40 ec. of ammonia-free hydrochloric acid, and by means of the separatory funnel add the solution slowly to the contents of the distilling flask, washing in finally with ammonia-free water.

Distill and collect 150 ee, of distillate in a graduated flask. Cork the flask and set aside. Experience has shown that 150 ce, of distillate will contain all the nitrogen in the sample.

Preparation of Standard

After distilling the sample—the apparatus then being free from ammonia but containing the residue of sample and reagents—25 cc. of standard ammonium ehloride solution and 150 ee. of ammonia-free water are added to the contents of the flask, and distillation continued until a *standard* distillate of 150 ee. is collected in a graduated flask.

As before, the single distillate will contain all the ammonia from 25 cc. of standard solution.

To the standard distillate is added 6 ce. of Nessler reagent; and since the standard ammonium chloride solution is equivalent to .00001 g. nitrogen per cc., 1 ce. prepared standard distillate is equivalent to $\frac{25 \times .00001}{156} = .000001$, 6 g. nitrogen per cc. = .00016% nitrogen when using one gram sample.

Comparison and Determination

To make the determination, 30 cc. of sample distillate, equal to one gram of sample, are placed in one of a pair of Nessler jars and the color developed by addition of 1 cc. Nessler reagent.

The standard and sample are allowed to stand one minute to fully develop the color.

Into the other jar the standard distillate is run from a burette until the colors in standard and sample jars are of the same intensity; the final comparison being made after bringing the contents of the jars to the same volume by addition of ammonia-free water to one or the other.

The number of ce. of standard distillate multiplied by .00016 gives the percentage of nitrogen in the steel.

DETERMINATION OF CONVERTER EFFICIENCY IN OXIDATION OF AMMONIA TO NITRIC ACID

In place of determining the total ammonia used and the total products of oxidation, samples may be taken, during the operation, of gases entering and leaving the converter and analyzed according to the following simple and accurate procedure suggested by Gaillard; ¹ a method successfully used by the American Cyanamide Company at Warners, N. J., and by the United States nitrate plants at Sheffield and Muscle Shoals, Ala.

Principle. The gas to be analyzed is drawn into an evacuated bulb which has previously been weighed, and the increased weight due to the sample is obtained. The ammonia or nitrogen oxides in the bulb are then absorbed and titrated, and the percentage by weight of combined nitrogen in the gases is determined. The efficiency is the ratio of the combined nitrogen in the exit and inlet gases.

Sources of Error. Error may be eaused by:

- (a) Water condensation in the sampling tube during sampling.
- (b) Air leakage into the tube during sampling.
- (c) Ammonia escaping oxidation being drawn into the bulb. In presence of ammonia a cloudiness is readily observed.
- (d) Changes in temperature, barometric pressure, and moisture conditions between successive weighings of the same bulb.

These errors are rendered negligible by careful manipulation. (The writer would suggest that a similar bulb tare weight be used and the procedure for weighing recommended in combustion carbon determinations be followed.)

¹ Ind. Eng. Chem., 11, 745 (1919).

On the right hand side of the illustration below is shown the bulb in the process of evacuation by means of a vacuum pump operated by an electric motor. Attached to the system is a mercury gauge or barometer which gives the degree of evacuation of the bulb.




Fig. 55b. Evacuation and Weighing of Bulbs for Converter Efficiency in Ammonia Oxidation.

On the left hand side of the illustration is shown a balance with a bulb suspended for weighing after being evacuated. It is advisable to have a bulb on the right hand arm of the balance acting as a tare weight. This counteracts the buoyancy error of the air, increasing the delicacy of weighing. If the stopcoeks are not absolutely tight, the bulb will gain in weight owing to an intake of air.

PHOSPHORUS

P4, at.wt. 31.02; sp.gr. { yellow 1.831; m.p. } 44°, t.p. } 290°C; oxides, P1O1, P1O2; acids, H2PO2, H2PO3, H2PO3, H4PO3, H4PO3, H4PO3,

DETECTION

Element. Phosphorus is recognized by its glowing (phosphoroscence) in the air. The element is quickly oxidized to P₂O₅; if the yellow modification is slightly warm (34° C.) the oxidation takes place with such energy that the substance bursts into flame. The red form is more stable. It ignites at 260° C.

Boiled with KOH or NaOH it forms phosphine, PH₂, which in presence of accompanying impurities is inflammable in the air.

Phosphorus oxidized to P₂O₅ may be detected with ammonium molybdate, a yellow compound, (NH₄)₃PO₄·12MoO₃·3H₂O, being formed.

Acids. Hypophosphorous Acid, H₃PO₂, heated with copper sulphate to 55° C. gives a reddish-black compound, Cu₂H₂, which breaks down at 100° to H and Cu. Permanganates are reduced immediately by hypophosphorous acid. No precipitates are formed with barium, strontium or calcium solutions. Zinc in presence of sulphuric acid reduces hypophosphorous acid to phosphine, PH₂.

Phosphorous Acid, H₂PO₃. Copper sulphate is reduced to metallic copper and hydrogen is evolved, no Cu₂H₂ being formed as in case of hypophosphorous acid. Pernanganates are reduced slowly. Added to solutions of barium, strontium or calcium white phosphites of these elements are precipitated. Alkali phosphites are soluble in water, while hypophosphites are not readily soluble.

Orthophosphoric Acid, H_3PO_4 . Annuonium phosphomolybdate precipitates yellow ammonium phosphomolybdate from slightly nitric acid solutions. The precipitate is soluble in ammonium hydroxide.

Metaphosphoric Acid, HPO₃. Converted by nitric acid in hot solutions to the ortho form. Metaphosphoric acid is not precipitated by anumonium molybdate.

Pyrophosphoric Acid, H_1P_2O_7. Converted to orthophosphoric acid in hot solutions by nitric acid. No precipitate is formed with animonium molybdate.

COMPARISON OF ORTHO, META AND PYROPHOSPHORIC ACIDS

Reagent.	Orthophosphoric acid.	Metaphosphoric acid.	Pyrophosphoric scid.
Ammonium molybdateAlbumin Zinc sulphate, cold, in excessSilver nitrate in neutral solution Magnesium salts	Yellow ppt.,	No ppt. Coagulated No ppt. White ppt., AgPO ₃ No ppt.	No ppt. Not coagulated White ppt. White ppt., Ag,P ₁ O ₇ No ppt.

y i

Phosphorous acids are distinguished from phosphoric acids by the phosphine formed with the former when acted upon with zinc.

Acid phosphates are distinguished from normal phosphates as follows: Neutral silver nitrate added to an acid phosphate liberates free nitric acid (Litmus test), the following reaction taking place:

$$3AgNO_3+Na_2HPO_4=Ag_3PO_4+2NaNO_3+HNO_3$$
.

The solution resulting when silver nitrate is added to normal phosphate solution is neutral.

 $3AgNO_3 + Na_3PO_4 = Ag_3PO_4 + 3NaNO_3$

ESTIMATION

The determination of the pentoxide of phosphorus is required in a large number of substances, since it is widely distributed in the form of phosphates—ealcium phosphate, Ca₃(PO₄)₂; fluor apatite, 3Ca₃(PO₄)₂·CaF₂; chlor apatite, 3Ca₃(PO₄)₂·CaCl₂; vivianite, Fe₃(PO₄)₂·8H₂O; wavelite, 2Al₂(PO₄)₂·Al₂(OH)₄·9H₂O; pyromorphite, 3Pb₃(PO₄)₂·PbCl₂; phosphates of iron and calcium in phosphate ores, hence in slags of the blast furnace. It occurs in fertile soils, bones, plant and animal tissues.

The chemist is especially concerned in the determination of phosphoric acid (P_2O_b) , in the evaluation of materials used for the manufacture of the acid—bone ash and phosphate rock (see tablo below). Generally, determinations of line, iron and alumina are also desired and frequently a more complete analysis. In the analysis of phosphoric acid certain impurities occurring in the crude material used are determined, e.g., iron, lime, magnesia, sulphuric, hydrochloric and hydrofluoric acids, etc. Phosphoric acid is determined in the evaluation of phosphate fertilizers, phosphates used in medicine, phosphate baking powders, etc.

The element is determined in iron, steel, phosphor bronzes, and other alloys.

Typical Analyses * Charlestown Spanish Sombrero Redonda. Canadian Bone Ash. Substance Phosphate. Phosphorite. Phosphate. Phosphates Phosphate. 33.38 37.68 39.55 27.1735.1235.47Phosphoric oxide. 3.300.57Sulphur trioxide... 4.10 7.40 Carbon dioxide.... 4.43 4.9647.16 51.33 51.04 44.03 Lime..... 52.46Magnesia..... 1.02 0.37trace 0.89 +Fe 20.17 Fe₂O₂, 1.44 Alumina...... 2.59 1.02 8.85 0.17Al₂O₃, Ferric oxide 0.432.38 4.01 F. etc. Fluorine, etc..... 0.87 0.42 =6.88Alkaline salts..... 3,71 2.029.70 4.29 0.515.60 Silica—sand, etc....

*Thorpe, "Dictionary of Applied Chemistry," Longmans, Green & Co.

Preliminary Remarks. Practically all procedures for the determination of phosphorus depend upon its oxidation to ortho phosphoric acid and its precipitation by ammonium molybdate from a nitrie acid solution as ammonium phospho-molybdate. It may now be determined either gravinetrically or volumetrically. Two procedures are of importance in the gravimetric deter-

mination of phosphorus; the first depends upon the direct weighing of the yellow phosphomolybdate, dried at 110° C.; the second, on the conversion of the yellow precipitate to the magnesium salt and its ignition to pyrophosphate. Two volumetric procedures, which are of special value in the determination of small amounts of phosphorus as in case of phosphorus in iron and steel, are to be recommended for their rapidity and accuracy. One of these is to dissolve the ammonium phosphomolybdate in a known amount of standard caustic, titrate the excess of alkali with standard acid, which indicates the alkali required to neutralize the molybdic acid in the yellow precipitate. From this the amount of phosphorus present may be calculated. A second procedure of equal accuracy and rapidity is to dissolve the molybdate in ammonia, add an excess of sulphuric acid, pass the warm solution through a column of zinc and titrate the reduced molybdic acid with standard potassium permanganate, the amount of permanganate required being a measure of the phosphorus present.

The impurities interfering in the procedures are siliea and arsenic acid. The first may be eliminated by dehydration of the silicic acid in the solution and its removal as insoluble SiO₂ by filtration. Arsenic in small quantities does not interfere under certain conditious; in large quantities its removal is imperative.

Preparation and Solution of the Sample

Amount of the Sample Required. For accurate results it is advisable to take a fairly large sample, 5 to 10 grams, and when it has been dissolved, to dilute to a definite volume, 500 or 1000 cc. Aliquots of this solution are taken for analysis.

Iron Ores, Phosphate Rock and Minerals. Five to 10 grams of the pulverized material placed in a 3-in, porcelain dish are digested for an hour with 50 to 100 cc. of concentrated hydroehloric acid (sp.gr. 1.19), the dish being covered by a clock-glass and placed on a steam bath. The acid is now diluted with half its volume of water and the solution filtered into a porcelain dish of sufficient capacity to hold the filtrate and washings. The residue is washed with dilute hydrochloric acid (1:1) until free of visible iron discoloration. The filtrate and washings are evaporated rapidly on a hot plate to small volume and then to dryness over the steam bath. Meanwhile the insoluble residue and filter are ignited in a 20-cc. platinum crucible over a Méker burner or in a muffle furnace and the residue fuscil with ten times its weight of sodium carbonate. The fusion is removed by inserting a platinum wire into the molten mass, allowing to cool and then gently heating until the mass loosens from the crucible, when it may be removed on the wire. The cooled mass on the wire and that remaining in the crucible are dissolved in dilute hydrochloric acid, and the filtered solution added to the main solution. The combined solutions are evaporated to dryness, and heated gently to dehydrate the silica. The residue is taken up with a few cc. of hydrochloric acid, the solution diluted, filtered and the SiO₂ washed with dilute nitric acid solution. The combined filtrates are made up to 500 or 1000 cc. Aliquots of this solution are taken for analysis.

Iron and Steel. Five to 10 grams of the drillings or filings are dissolved in an Erlenmeyer flask with 50 to 100 cc. of dilute nitric acid, 1:1, more acid being added if necessary. When dissolved, a strong solution of KMnO₄ is added until a pink color appears; on boiling brown manganese dioxide forms in the solution if a sufficient amount of permanganate has been added. This is dis-

solved by adding 2% sodium sulphite solution in just sufficient quantity to dissolve the precipitate. The solution is diluted to a convenient volume for analysis. Where a number of determinations are to be made, it is advisable to weigh the amount of sample desired for the determination and to precipitate the ammonium phosphomolybdate in the flask in which the drillings have been dissolved.

Ferro-Silicon, Iron Phosphide and Acid Insoluble Alloy Steels. Decomposition is best accomplished by fusing 1-2 grams with 10-15 grams of a mixture of sodium carbonate and magnesium oxide (2:1). (A blank should be run on the reagents and allowance made for any phosphorus present.) The fusion is dissolved in hydrochloric acid, then taken to dryness and the SiO₂ filtered off. The SiO₂ is treated with HF and a few drops of H₂SO₄ in a platinum dish and taken to fumes. The residue is fused with Na₂CO₂, and the fusion dissolved in HCl and the solution added to the main filtrate containing the iron and phosphate, etc. This filtrate is concentrated to near dryness, 10 cc. nitric acid added and the evaporation repeated. This concentrate is diluted to about 25 cc. and phosphorus precipitated with ammonium molybdate solution as usual.

Ferro-Titanium, Metallic Titanium. The fusion, obtained as directed for ferro-silicon, is extracted with water to dissolve out the sodium phosphate. The residue is fused with sodium carbonate and again extracted with water. The water extracts of the two fusions is examined for phosphorus. The extracts are made acid with nitric acid, the solution evaporated to near dryness, nitric acid added and the concentrated solution treated as directed for steel. Iron, in this case, has been removed with titanium.

Materials Containing Tungsten. The alloy is dissolved in dil. HNO₃ and evaporated to dryness, HCl is now added and the solution again evaporated to dryness, the residue is taken up with HCl and again evaporated. This residue is extracted with dil. HCl and washed with acid animonium nitrate.

Iron and phosphorus are in solution, Si and W remain insoluble.

Ores Containing Titanium. Titanium may be recognized by the red color produced by hydrogen peroxide, H₂O₂, added to the sulphuric acid extract; also by the reduction test with zinc, which eauses a play of colors, the solution becoming colorless by the reduction of iron, then, in presence of titanium, pink, purple and finally blue. (Vanadium gives similar tests.) Solutions containing titanium frequently appear milky when the solution is diluted before filtering off the insoluble residue. Since titanium forms an insoluble compound with phosphoric acid and iron oxide ¹ the final residue, obtained by the method of solution for ores, phosphate rock and minerals, should be moistened with sulphuric acid and the silica expelled with hydrofluoric acid. The solution is evaporated to dryness and to SO₄ fumes, the residue fused with sodium carbonate and taken up with boiling water. TiO₂ remains insoluble, while P₂O₅ passes into the filtrate.

Determination of Phosphorus in Organic Matter. Decompose the organic matter with nitric acid in a sealed tube according to the method of Cassius

described on page 145, and determine the phosphoric acid formed.

Soluble Phosphates, Phosphate Baking Powder, etc. A water extract is generally sufficient to get the material in solution. In case iron, alumina, lime and magnesia salts are present, as may occur in baking powders, an extraction with dilute 3% nitric acid is necessary. It is advisable to dissolve a 5- to 10-gram sample and take an aliquot part of the solution made up to a definite volume. Before precipitating with ammonium phosphomolybdate, 5 grams of ammonium

GRAVIMETRIC METHODS FOR DETERMINATION OF PHOSPHORUS

A. Direct Weighing of the Ammonium Phosphomolybdate Precipitation of Ammonium Phosphomolybdate

Precipitation of ammonium phosphomolybdate is common to all subsequent methods for determination of phosphorus.

Reaction.

 $H_4PO_4+12(NH_4)_2M_0O_4+21HNO_3=(NH_4)_3PO_4.12M_0O_3+21NH_4NO_3+12H_2O_4+12H_3O_4+12H_3O_4+12H_3O_3+12H_3O_4+12H_3O_3+12H_3O_$

Amount of Sample Required for Analysis. In volumetric procedures the amount of sample should be such that the phosphorus content will be between 0.005 and 0.05 gram phosphorus. In gravimetric procedure twice this amount is desirable.

Ammonium Molybdate Reagent. See pages 368, and the chapter on Reagents.

Precipitation. The free acid of the solution is nearly neutralized by addition of ammonium hydroxide. In analysis of phosphate rock or materials comparatively low in iron, it is advisable to add ammonium hydroxide in quantity sufficient to cause a slight permanent precipitate followed by just sufficient HNO. to dissolve the precipitate. In iron and steel analysis ammonium hydroxide is added until the precipitated iron hydroxide dissolves with difficulty and the solution becomes a deep amber color or cherry red. In analysis of soluble phosphates, litmus paper dropped into the solution indicates the neutral point. Nitric acid is added to the neutral or slightly acid solution, 5 cc. of acid for every 100 ee. of solution. A volume of 150 to 200 ee, of solution is the proper dilution for samples taken in amounts above recommended. To the warm solution (not over 80° C.) ammonium molybdate is added, 60 cc. of the reagent being required for every 0.1 gram of P₂O₅ present. The solution is stirred, or shaken, if in a flask, until a cloudy precipitate of ammonium phosphomolybdate appears. It is then allowed to settle on the steam bath at a temperature of 40 to 60° C., for one hour, then again agitated and allowed to settle in the cold for an hour longer. The filtrate should be tested with additional ammonium molybdate for phosphorus. The yellow precipitate is filtered and washed with 1% HNO: solution followed by a 1% solution of KNO₄, or NH₄NO₃ or (NH₄)₂SO₄ as the special case requires. Filtration through asbestos in a Gooch crucible is to be recommended. When a large number of determinations are to be made, as in ease of iron and steel, filter paper is more convenient.

A. Direct Weighing of the Ammonium Phosphomolybdate

The sample being dissolved and the ammonium phosphomolybdate precipitated according to directions already given above, the supermatent solution is filtered through a weighed Gooch crucible and washed twice by decantation with dilute nitric acid (1%), the precipitate washed into the Gooch, followed by two washings with 1% KNO₃ or NH₄NO₃ (neutral solutions) and finally with water. The precipitate, free from contaminating impurities, is dried for two hours in an oven at 110° C., then cooled in a desiccator and weighed. Weight of precipitate×0.0165 = P, or ×0.03784 = P₂O₄.

Note. If this procedure is to be followed it will be convenient to take 1.65 grams sample, if the phosphorus content will allow. Each 0.01 gram of precipitate will then squal 1% P.

B. Determination of Phosphorus as Magnesium Pyrophosphate

Magnesia Mixture. For precipitation of ammonium magnesium phosphate, 110 grams of magnesium chloride (MgCl₂·6H₂O) are dissolved in a small amount of water. To this are added 280 grams of ammonium chloride and 700 cc. of ammonia (sp.gr. 0.90); the solution is now diluted to 2000 cc. with distilled water. The solution is allowed to stand several hours and then filtered into a large bottle with glass stopper. Ten cc. of the solution should be used for every 0.1 gram P_2O_5 present in the sample analyzed. As the reagent becomes old it will be necessary to filter off the silica that it gradually accumulates from the reagent bottle.

Procedure. The ammonium phosphomolybdate, obtained as directed (page 365), is filtered onto a $12\frac{1}{2}$ S. & S. No. 589 filter paper and washed four or five times with dilute 1% HNO₃. The precipitate is now dissolved from the filter by a fine stream of hot anunonium hydroxide, 1:1, catching the solution in the beaker in which the precipitation was made. The solution and washings should be not over 100 to 150 cc. Hydrochloric acid is added to the cooled solution to neutralize the excess of ammonia, the yellow precipitate, that forms during the neutralization, dissolving with difficulty, when sufficient acid has been added. To the cooled solution cold magnesia mixture is added drop by drop (2 drops per second) with constant stirring. Ten cc. of the reagent will precipitate 0.1 gram P₂O₅. When the solution becomes cloudy the stirring is discontinued and the precipitate allowed to settle ten minutes. Ammonium hydroxide is added until the solution contains about one-fourth its original volume of strong ammonia (e.g. 25 cc, NH₄OH, 90 to 100 ee. of solution). The solution is stirred during the addition and them: allowed to settle for at least two hours. It is filtered preferably, through a Gooch crucible (or through an ashless filter paper), and the precipitate washed with dilute ammonium hydroxide, 1:4, then placed in a porcelain crucible, a few drops of saturated solution of ammonium nitrate added and the precipitate heated over a low flame till decomposed (or until the paper chars). The lumps of residue are broken up with a platinum rod and again ignited over a Scimatico or Méker burner, the heat being gradually increased. If the heating is properly conducted, the resultant ash will be white or light gray, otherwise it will be dark. The addition of solid ammonium nitrate aids the oxidation in obstinate cases, but there is danger of slight mechanical loss. The crucible is cooled in a desiccator and the residue weighed as magnesium pyrophosphate.

 $Mg_2P_2O_7\times 0.2787 = P$ and $Mg_2P_2O_7\times 0.6379 = P_2O_6$.

Direct Precipitation of Magnesium Ammonium Phosphate

In the absence of heavy metals whose phosphates are insoluble in an amnoniacal solution, the magnesia mixture may be added directly to the neutral solution containing the phosphate, without previous precipitation of ammonium phosphomolybdate. The magnesium ammonium phosphate is washed and ignited according to directions given above, and weighted as magnesium pyrophosphate.

The use of the Gooch erucible for the ammonium phosphomolybdate and the ammonium magnesium phosphate precipitates is reconvended in preference

to filter paper. See precautions on page 375.

VOLUMETRIC METHODS FOR THE DETERMINATION OF PHOSPHORUS

These volumetric procedures are especially applicable for determining small amounts of phosphorus such as are present in steel and in alloys.

C. Alkalimetric Method

The method is based on the acid character of ammonium phosphomolybdate, the following reaction taking place with an alkali hydroxide:

 $2(NH_4)_3.12M_0O_3.PO_4+46N_0OH = 2(NH_4)_2HPO_4+(NH_4)_2M_0O_4+23N_{82}M_0O_4+22H_2O.$

From the reaction 46 molecules of sodium hydroxide are equivalent to one molecule of P_2O_5 , hence 1 cc. of N/10 solution of sodium hydroxide neutralizes the yellow precipitate containing an equivalent of .000309 gram of P_2O_5 . (N equivalent of P=31+23=1.35.)

Solutions Required. Nitric Acid for Dissolving: Mix 1000 ec. of HNO2,

sp.gr. 1.42, and 1200 cc. of distilled water.

Nitric Acid for Washing: Mix 20 ec. of HNO₃, sp.gr. 1.42, and 1000 cc. of distilled water.

Ammonium Molybdate: Solution No. 1. Place in a beaker 100 g. of 85 per cent molybdie acid, mix it thoroughly with 240 cc. of distilled water, add 140 cc. of NH₄OH, sp.gr. 0.90, filter and add 60 cc. of HNO₃, sp.gr. 1.42.

Solution No. 2. Mix 400 ee. of HNO₂, sp.gr. 1.42, and 960 ee. of distilled water.

When the solutions are cold, add solution No. 1 to solution No. 2, stirring constantly; then add 0.01 gram of ammonium phosphate dissolved in 10 ec. of distilled water and let stand at least 24 hours before using.

Potassium Nitrate, 1 per cent: Dissolve 10 g. of KNO, in 1000 ee. of

distilled water.

Phenolphthalein Indicator: Dissolve 0.2 g. of phenolphthalcin in 50 ce. of

95 per cent ethyl alcohol and 50 ec. of distilled water.

Standard Sodium Hydroxide: Dissolve 6.5 g. of purified NaOH in 1000 ec. of distilled water, add a slight excess of 1 per cent solution of barium hydroxide, let stand for 24 hours, decant the liquid, and standardize it against a steel of known phosphorus content as determined by the molybdate-magnesia method, so that 1 cc. will be equivalent to 0.01 per cent of phosphorus on the basis of a 2-g. sample (see notes). A 0.1 N or N/10 solution contains 4 g. NaOH (100%) per 1000 ec.

Protect the solution from earbon dioxide with a soda-lime tube.

Ferric Chloride: Dissolve 100 g. of ferric chloride (phosphorus free) in 100 cc. of distilled water.

Standard Nitric Acid: Mix 10 ec. of HNO₃, sp.gr. 1.42, and 1000 ec. of distilled water. Titrate the solution against standardized NaOH, using phenolphthalein as indicator, and make it equivalent to the NaOH by adding distilled water. 0.1 N or N/10 solution contains 6.3 g. HNO₂ per 1000 cc.

Determination of Phosphorus in Ores and Minerals. See page 371.

Determination of Phosphorus in Iron and Steel. See page 1045, Vol. II.

Determination of Phosphorus in Copper Alloys

In a 400-ee. easserole dissolve 1 g. of copper alloy metal in 10 ee. of HNO₁, sp.gr. 1.42. Add 20 ee. of HCl, sp.gr. 1.20, and evaporate to dryness. with HCl, evaporate to dryness again, and bake to dull redness. Moisten with HCl again (add 3 ee. of ferric ehloride solution unless iron is already present) and dilute to about 200 cc. with distilled water. Add NH₄OH. sp.gr. 0.90, until the basic salts of copper have dissolved and the solution has become a deep blue. Boil, allow to settle, and filter on a loosely woven filter paper. Wash with dilute ammonia and with hot water. Dissolve the preeipitate on the filter with hot dilute HCl, dilute the solution to about 200 ee., add NH₄OH, sp.gr. 0.90, until the precipitate which forms at first dissolves rather slowly, and saturate with H₂S gas. Filter off and reject the precipitate. Boil the filtrate to expel H₂S, and add HNO₃, sp.gr. 1.42, until the iron is oxidized. Add NH₄OH, sp.gr. 0.90, until the solution is alkaline. Boil and filter on a loosely woven filter paper. Wash with dilute ammonia and with hot water. Dissolve the precipitate on the filter with HNO₃ (sp.gr. 1.42), receiving the solution in a 350-ec. Erlenmeyer flask. Add NH4OH, sp.gr. 0.90, until the iron is entirely precipitated, and then add HNO₅, sp.gr. 1.42, eautiously until the solution just becomes clear. Bring the solution to a temperature of about 80° C., and add 40 cc. of ammonium molybdate at room temperature. Allow to stand for one minute, shake or agitate for 3 minutes, and filter on a 9-cm. paper. Wash the precipitate three times with the 2 per cent HNO₃ solution to free it from iron, and continue the washing with the 1 per cent KNO₃ solution until the precipitate and flask are free

Transfer the paper and precipitate to a solution flask, add 20 ec. of distilled water, 5 drops of phenolphthalein solution as indicator, and an excess of standard NaOH solution. Insert a rubber stopper and shake vigorously until solution of the precipitate is complete. Wash off the stopper with distilled water and determine the excess of NaOH solution by titrating with standard HNO₃ solution. Each cubic centimeter of standard NaOH solution represents 0.01 per cent of phosphorus.

Accuracy. Duplicate determinations should eheck within 0.01 per eent of phosphorus.

Notes. The ammonium-molybdate solution should be kept in a cool place and should always be filtered before using.

All distilled water used in titrations should be freed from carbon dioxide by boiling or otherwise.

Method for Steel

Procedure. Preparation of the sample. Consult pages 364 and 366. After oxidation of the sample by adding a strong solution of KMnO₄ and soiling, and dissolving the precipitated MnO₂ by reduction with sodium ulphite, the greater part of the free acid is neutralized by addition of ammonia. The solution will appear a deep eherry red color. No iron precipitate should be present. Ammonium phosphomolybdate is now precipitated by addition of ammonium molybdate according to the procedure outlined on page 366. This is filtered into a Gooch crueible containing asbestos, and washed once

or twice with water containing 1% nitric acid, and then several times with a 1% neutral solution of potassium nitrate until the washings are free of acid, as indicated by testing with litmus paper. The asbestos mat containing the precipitate is transferred to a No. 4 beaker, 100 cc. of CO₂ free water added, followed by about 20 cc. of N/10 NaOH measured from a burette. The crucible is rinsed aut with 5 to 10 cc. of N/10 NaOH, the exact amount being noted and then with water, adding the rinsings to the main solution. Phenolphthalein indicator is added, and the excess of eaustic titrated with N/10 HNO₂. The total NaOH added minus the acid titration equals the cc. of the caustic required to react with the yellow precipitate.

One cc. of 0.1 N or N/10 NaOH = 0.000136 gram of P.

The exact factor should be determined as directed under Reagents.

(b) Method for Ores. See pages 364-367.

D. Zinc Reduction and Titration with Potassium Permanganate

Permanganate. Ferrie-Alum Method. This method is based on the assumption that ammanium phosphomolybdate, $(NH_4)_3.12MoO_3.PO_4$, is reduced, in acid solution, by zinc, the molyhdic acid, MoO_3 , farming the lower axide Mo_2O_3 , in which form it reacts with ferric iron in the receiving flask, reducing a corresponding equivalent of ferric salt to ferrous condition, being itself oxidized to MoO_3 . When the ferric salution is not placed in the receiving flask, a slight oxidation takes place, the oxide Mo_24O_{37} apparently being formed.

Special Apparatus Required

Jones' Reductor. Details of the reductor are given under the determination of iron by the permanganate method, also under the Volumetric Determination of Molybdenum.

Solutions Required.

Dilute Ammonia. Mix 100 cc. of NH₄OH, sp.gr. 0.90, and 900 cc. of distilled water.

Dilute Hydrochloric Acid. Mix 500 ee. of HCl, sp.gr. 1.20, and 500 cc. of distilled water.

Dilute Sulphuric Acid for Dissolving. Mix 200 cc. of H₂SO₄, sp.gr. 1.84, and 800 cc. of distilled water.

Dilute Sulphuric Acid for Reductor. Mix 500 cc. of H₂SO₄, sp.gr. 1.84, and 500 ec. of distilled water.

Ammonium Molybdate. Solution No. 1. Place in a beaker 100 g. of 85 per cent molybdic acid, mix it thoroughly with 240 cc. of distilled water, add 140 cc. of NH₄OH, sp.gr. 0.90, filter and add to 60 cc. of HNO₃, sp.gr. 1.42.

Solution No. 2. Mix 400 cc. of HNO₃, sp.gr. 1.42, and 960 cc. of distilled water.

When the solutions are cold, add solution No. 1 to solution No. 2, stirring constantly, then add 0.1 g. of ammonium phosphate dissolved in 10 cc. of distilled water, and let stand at least 24 hours before using.

Acid Ammonium Sulphate. Mix 25 cc. of H₂SO₄, sp.gr. 1.84, and 1000 ec. of distilled water, and then add 15 cc. of NH₄OH, sp.gr. 0.90.

Ferric Alum. Dissolve 200 g. of ferric ammonium sulphate crystals in

¹ If a large quantity of yellow precipitate is present, five minutes should be allowed for the alkali to react before titrating the excess with standard acid.

1950 ec. of distilled water. Add 50 ee. of H₂SO₄, sp.gr. 1.84, and 80 ce. of phosphoric acid, 85 per cent.

Potassium Permanganate. Dissolve from 3.0 to 3.2 g. of KMnO₄ in 1000 ee. of distilled water. Allow the solution to stand for about one week, and then filter it through an asbestos filter. Standardize by using about 0.200 g. portions of pure sodium oxalate—29.85 ee. of 0.1 N solution. See pages 13 and 790.

Standard for Phosphorus in Steel. The exact value of the permanganate solution may be accurately and rapidly determined in terms of phosphorus by standardizing against a sample of standard steel containing a known amount of phosphorus, the ultimate standard being steel drillings furnished by the Bureau of Standards. The drillings are dissolved in nitrie acid, oxidized with KMnO₄, the excess of the reagent being destroyed by sulphite solution. Ammonia is added until the solution becomes a deep amber color. The phosphorus is precipitated as ammonium phosphomolybdate. The following procedure is the same as is given in the volumetric method following: The permanganate titration of the reduced molybdic acid divided into the amount of phosphorus known to be present in the solution will give the value of the permanganate in terms of phosphorus.

Wt. of P in sample ec. KMnO₄ required = amount of P per cc. of KMnO₄.

In a 400-cc, casserole dissolve I g, of the metal in 10 cc. of HNO₃, sp.gr. 1.42. Add 20 cc. of HCl, sp.gr. 1.20, and evaporate to dryness. Moisten with HCl, evaporate to dryness again, and bake to dull redness. Moisten with HCl again, and dilute to about 200 cc. with distilled water and filter if cloudy. To the solution add NH4OH, sp.gr. 0.90, until the iron is entirely precipitated, and then add HNO2, sp.gr. 1.42, cantiously until the solution just becomes elear, the solution having an amber color. Bring the solution to a temperature of about 80° C., and add 40 ce. of ammonium molybdate at room temperature. Allow to stand for one minute, shake or agitate for 3 minutes, filter on a 9-cm. paper, and wash very thoroughly (about 25 times) with acid ammonium sulphate. Dissolve the precipitate on the paper using 50 ec. of dilute ammonia. Add 10 ee. of H2SO4, sp.gr. 1.84, and immediately pass the solution through a Jones reductor, which has the reductor tube prolonged and reaching nearly to the bottom of the flask, dipping into 50 cc. of ferric-alum solution.1 Wash through the reductor with 150 cc. of distilled water, and follow with an additional 100 ec. of distilled water. Titrate with standard KMnO₄.

By this method the molybdenum in passing through the reductor is reduced entirely to the form Mo_2O_3 , and is oxidized by the ferric alum to the form MoO_3 , an equivalent amount of iron being reduced to the ferrous condition. As the yellow precipitate contains one atom of phosphorus to each twelve molecules of MoO_3 , and as three atoms of oxygen oxidize two of molybdenum, eighteen oxygens or thirty-six irons are equivalent to one phosphorus. Therefore, the iron value of the permanganate multiplied by the factor $P/36 \times Fe$ (or 0.01540) gives the value of the permanganate in terms of phosphorus.

Accuracy. Duplicate determinations should cheek within 0.005 per cent of phosphorus.

¹ It is not required to heat the solution for reduction as is sometimes stated in text books.

Notes. The ammonium-molybdate solution should be kept in a cool place and

should always be filtered before using.

A blank determination should be made on corresponding amounts of acid and water, passing through the reductor into the usual amount of ferric-alum solution in the flask. A small quantity of liquid should always be left in the reductor funnel, and air

should never be allowed to enter the reductor.

Description of the Jones reductor is given on pages 319 and 320.

In absence of ferric iron the reduced molybdate is an amber or brown color. During titration with KMnO4 the color changes to a reddish yellow and fades to a colorless solution, and then the permanganate pink color is obtained.

Calculation. Case 1. If ferric sulphate is in the receiver (6Mo₂O₃+18O = 12MoO₂ in the molecule containing 1P), 18O are equivalent to 36H, hence N/10 P according to this reaction equals at.wt. P divided by $(36 \times 1000) = P$ for 1 ce. of N/10 KMnO₄= .0000862 g. P.

Case 2. No ferric sult in receiver. $Mo_{24}O_{37}+35O=24MoO_3+2P.(35O)$ =70H). Dividing by 2 we get at.wt. P divided by $(35 \times 1000) = P$ for 1 cc. of N/10 KMnO₄=.0000887.

Nores. In case the alkalimetric method is chosen, it will be necessary to wash the precipitate free of acid by washing with neutral ammonium nitrate. (Washing with pure water is prohibited owing to the solubility of the precipitate.) A litmus paper test of the filtrate coming from the funnel is the usual practice of ascertaining whether this washing is complete. Sufficient time should be allowed for the standard alkali to react with the precipitate before addition of standard acid in the titration of the excess alkali, otherwise the results will be low; this is specially true if much "yellow precipitate" is present. If the permanganate method has been chosen, washing the precipitate with amnionium sulphate is the general practice, as the presence of nitrate salts in the precipitate would cause error in this reduction method.

As ammonium molybdate is apt to deteriorate after standing for several weeks, it is advisable to test the reagent before use. A fresh solution should be made up

overy ten or fifteen days.

In precipitating phosphorus it must be remembered that overheating the solution will cause the precipitation of molybdic oxide; should this be suspected, the magnesium

phosphate method will correct results.

Special Steels and Alloys. Steels containing titanium, tungsten, vanadium, etc., require a special treatment in preparing these for analysis, in the determination of

phosphorus. Directions are given for these on the following page, 370a.

Ferro-Silicon, Iron Phosphide and Acid-Insoluble Alloy Steels. Decomposition is best accomplished by fusing 1-2 grams with 10-15 grams of a mixture of sodium carbonate and magnesium oxide (2:1). (A blank should be run on the reagents and allowance made for any phosphorus present.) The fusion is dissolved in hydrochloric acid, then taken to dryness and the SiO₂ filtered off. The SiO₂ is treated with HF and a few drops of H₃SO₄ in a platinum dish and taken to furnes. The residue is fused with Na-CO₂ and the fusion dissolved in HCl and the solution added to the residue. with Na₂CO₂, and the fusion dissolved in HCl and the solution added to the main filtrate containing the iron and phosphate, etc. This filtrate is concentrated to near dryness, 10 cc. nitric acid added, and the evaporation repeated. This concentrate is diluted to about 25 cc. and phosphorus precipitated with ammonium molybdate solution as usual.

Ferro-Titanium, Metallic Titanium. The fusion, obtained as directed for ferrosilicon, is extracted with water to dissolve out the sodium phosphate. The residue is fused with sodium carbonate and again extracted with water. The water extracts of the two fusions are examined for phosphorus. The extracts are made acid with nitric acid, the solution evaporated to near dryness, nitric acid added and the concentrated solution treated as directed for steel. Iron, in this case, has been removed with titanium.

Preparation of Cast Iron and Alloy Steels for the Determination of Phosphorus. Cast Iron. One gram or more of the sample is dissolved in 50 ee. of dilute nitric acid, the solution evaporated to dryness and baked at 200° C. for an hour, 15 ec. of hydrochloric acid (d. 12) are added and the solution again evaporated to dryness. 15 ec. hydrochloric acid are added to the residue and 20-30 ee. of water and the silica is filtered off and washed with water. The filtrate is evaporated to pasty consistency, 15 ee. of nitric acid are added and the solution evaporated to near dryness, this treatment is repeated and the residue then taken up with 15 cc. of water. Phosphorus is now precipitated

according to the directions for phosphorus in the steel solution.

Iron Containing Titanium. The material is treated as in ease of cast iron. Any residue remaining from the nitric acid evaporation is treated with HF and H2SO4 as in ease of cast iron. (Use platinum dish.) The residue remaining from the HF treatment is taken up with a little HCl and filtered. The filtrate being added to the main solution containing iron and phosphorus. The solution is heated to boiling and an ammonium acid sulphite solution is added, dropwise (2 cc. of NH₄OH saturated with SO₂ and 10 cc. NH₄OH). A precipitate will form, which dissolves. In case it does not, on stirring, the solution is cleared by adding a few drops of HCl, and the addition of sulphite continued. When all but 1-2 cc. of the reagent is added, the solution Ammonium hydroxide is now added drop by drop to the hot solution until a slight greenish precipitate is formed in the solution, which remains undissolved on stirring. Now the remaining 1-2 cc. of the sulphite is added. If a precipitate forms (titanium hydroxide) which does not redissolve on stirring, HCl is added drop by drop until the solution clears. The odor of SO2 should be evident. If not, more sulphite should be added and the solution again eleared. 5 ce. HCl are added, CO2 passed through the solution, which is heated to boiling to expel excess of SO₂, the iron remaining in the reduced form. Sufficient ferric ehloride is now added to combine with all the phosphorus and a slight exeess.

The solution is cooled under tap water and ammonium hydroxide added drop by drop until green ferrous iron precipitate redissolves, and then a white precipitate of titanium hydroxide and ferric phosphate remains and an additional drop causes a distinct reddish tint and the appearance of a green precipitate with one more. If the red color does not appear, the green precipitate is dissolved with a few drops of HCl and additional ferric chloride solution is added. The addition of ammonia is now repeated. A reddish color of

excess of ferric hydroxide should be evident.

A few drops of acetic acid (d. 1.04) are added to dissolve the green precipitate, the red remaining undissolved, and 1 ec. excess. The solution is diluted to about 450 cc. with hot water, boiled 1 minute, then rapidly filtered, and washed once or twice with hot water. The filtrate passes through clear, but will become cloudy upon oxidation of iron.

The residue is dried, separated from the filter, the latter burned and its ash added to the main residue. This is mixed with 5 grams of sodium carbonate and about 0.2 g. potassium nitrate and fused in a platinum crucible for half an hour. The fusion is extracted with water and the solution filtered. The filtrate contains all the phosphorus as sodium phosphate.

 1 Traces of P in residue are recovered by treating with HF and $\rm H_1SO_4$ and expelling $\rm SiO_2$

PHOSPHORUS

The filtrate is acidified with nitric acid and evaporated to near dryness, then taken up with a few cc. of water and to a volume of 25 ec. is added the ammonium molybdate solution according to the procedure for iron and steel. The procedure from this stage is the same as for steel.

Vanadium Steels. In presence of vanadium the ammonium phosphomolybdate will be contaminated with vanadium, so that its presence requires a special treatment. If less than 2.5% is present, the regular procedure for steel is followed with the exception that just before adding the ammonium molybdate, 5-10 ec. nitric acid are added.

If more than 2.5% of vanadium is present, the following procedure is recommended by C. M. Johnson (J. I. E. C., 11, 113 (1919)): 1 gram of steel is treated in a covered 250-cc. parcelain dish with a mixture of 30 cc. concentrated hydrochloric acid and 30 ec. concentrated nitric acid, and the solution is heated for an hour. The cover is rinsed off into the main solution, 100 cc. of strong nitric acid is added and the solution evaporated to dryness and baked for 5 minutes at 200° C. The oxides are dissolved in 35 ee, of concentrated hydrochloric acid and the solution evaporated to about 10 ee. 10 cc. of nitric acid are added and the covered solution heated for a few minutes, The solution is filtered through asbestos, on a small wad of glass wool in a The vanadium oxide residue is washed 15 times with small portions of a solution containing 200 cc. concentrated nitrie acid, 100 cc. water and 20 grams of ferric nitrate (free from phosphorus). The filtrate is concentrated to 10 cc. If a precipitate forms V₂O₄, it is filtered off and the washing repeated, the filtrate is again evaporated and filtered if necessary. If no precipitation occurs in the filtrate upon concentration, 40 cc. of nitric acid are added and the phosphorus precipitated with ammonium molybdate 1 as usual.

Note. Vanadium may also be precipitated by concentration to about 20 cc., neutralizing the greater part of the acid and adding ammonium chloride solid to saturation. The precipitate is washed with a saturated solution of NH₄Cl.

¹ Johnson recommends aumonium molybdate that contains 55 grams of ammonium molybdate, 50 grams of ammonium nitrate, 40 cc. ammonium hydroxide, and 700 cc. water. After heating for half an hour, the solution is diluted to 1000 cc. The solution is allowed to settle for 24 hours and is filtered. It is slightly ammoniacal.

Report of the Committee on Research and Analytical Methods-Phosphate Rock 1

The following tentative standard methods for sampling and determination of moisture, phosphoric acid and iron and alumina in phosphate rock are recommended to the Division.

Methods of Sampling and Determination of Moisture

I. Gross Sample. A. Car Shipments. One hundred pounds sample per ear.

1. Sampling from the Car. In sampling car shipments in the car at least ten scoopshovelsful, aggregating 100 lbs., shall be taken from each ear at approximately equal distances from each other so as to average the ear. Carc shall be taken to see that each scoopful shall cover the entire face of the pile from floor to top.

2. Sampling from the Cart or Barrow. A small hand scoopful of 1 to 2 lbs. shall be taken from each eart or barrow either as it is being loaded or as it leaves the car.

B. Cargo Shipments. One hundred pounds minimum sample per vessel.

1. Sampling in Hoisting Tub. In sampling cargoes generally running from 1000 tons upward a small hand scoopful shall be taken from approximately every tenth tub before it is hoisted from the hold.

2. Sampling from Conveyor. It unloading is being done with automatic hucket and conveyor, periodical sections of the entire discharge of the conveyor shall be taken of such intervals and quantity as to give a sample equivalent to approximately 1 lb. per each 10 tons of cargo.

3. Sampling from Conveying Vehicle. Samples shall be taken with a hand scoop from various ears at such regular intervals and in such quantities as to give approx-

imately 1 lb. for each 10 tons of cargo.

II. Laboratory Sample. The resulting gross sample obtained by any one of the methods outlined shall be crushed to pass a four-mesh screen, thoroughly mixed on a clean, hard surface and quartered down to a 10-lb. average sample.

A. Crushing. This 10-lb. sample shall all be crushed to pass an eight-mesh

sereen.

B. Mixing and Quartering. This eight-mesh sample shall be carefully mixed and quartered down to two 2-lb. samples.

C. Grinding. 1. Moisture Sample. One of these 2-lb. samples shall be held in an air-tight container. This sample is to be used for the determination of moisture.

2. Analytical Sample. The other 2-lb. sample shall be further mixed and quartered

down to a 2- or 4-oz. sample which is then to be ground to pass a sixty-mesh screen or preferably a sixty-five mesh screen. This sample is to be used for the analytical determination.

NOTE. It is essential that the taking of the gross sample be done with small hand scoops and that the practice of taking the sample in the hand be absolutely prohibited, for it has been found that there is considerable selective action in the liner materials sifting through the fingers while a scoop retains the entire sample.

The dimensions of the screens referred to above are to be as follows:

No. of Mesh	Size of Opening Inches	Diameter of Wire Inches
4	0.185	0.065
8	0.093	0.032
65	0.0082	0.0072

III. Determination of Moisture. Moisture is to be determined on both the moisture sample and analytical sample. Of the moisture sample not less than 100 grams are to be weighed out for each determination. Of the analytical sample approximately 2 grams are to be weighed out for each determination. Both are to be dried to constant weight at a temperature of 105° C. in a well-ventilated oven, preferably with a current of dry air passing through the oven. The containers in which moisture is determined should be provided with well-fitting covers so that the samples may be cooled and weighed in the well-covered container.

IV. Calculation of Results. The percentages of phosphoric acid and iron and alumina as determined on the analytical sample are to be calculated to a moisturefree basis and subsequently to the basis of the original sample as shown by the moisture content of the moisture sample.

Determination of Phosphoric Acid

Reagents. To be prepared as in Official Methods, A. O. A. C. Bureau of Chemistry, Bulletin 107 (Rev.), 1910, p. 2. Preparation of reagents (e), (d), (e) and (f), except that the ammonium nitrate solution in (d) is changed to 5% instead of 10%.

Method of Solution. To 5 grams of the sample add 30 ec. of cone. hydrochloric acid (sp.gr. 1.20) and 10 cc. of cone. nitrie acid (sp.gr. 1.42) and boil down to a syrupy consistency. The residue, which should be nearly solid after cooling, is taken up with 5 cc. of conc. nitric acid and 50 cc. of water. Ileat to boiling, cool, filter and make up to 500 cc. through the filter. This procedure eliminates practically all of the silica and it is necessary to filter as quickly as possible after digestion so

as to avoid redissolving the silica.

Determination. Draw off an aliquot portion of 50 cc., corresponding to 0.5 gram, neutralize with ammonia, then add nitric acid until the solution is just clear. Add 15 grams of ammonium nitrate (free from phosphates), heat the solution to 50° C. and add 150 cc. of molybdate solution. Digest at 50° C. for fifteen minutes with frequent stirring. Filter off the supernatant liquid and test the filtrate with molybdate solution to see if precipitation has been complete. (If not, add more molybdate to the filtrate and digest for fifteen minutes longer.) Wash with 5 per cent ammonium nitrate solution by decantation, retaining as much of the precipitate as possible in the beaker. Dissolve the precipitate in the beaker in the least possible quantity of amnionium hydroxide (sp.gr. 0.90) and dilute this solution with several times its volume of hot water. Dissolve the remainder of the precipitate on the filter with this solution, washing beaker and filter with hot water and keeping the volume of the filtrate between 75 and 100 ce. Neutralize with hydrochlorie acid, cool to room temperature and add 25 ec. of magnesia mixture from a burette, drop by drop, stirring vigorously with a rubber-tipped rod, then add 15 cc. of ammonium hydroxide (sp.gr. 0.90) and allow to stand for four hours or overnight at room temperature. The time of standing may be reduced to two hours if kept in a refrigerator or still better in an ice-water bath. Filter through a platinum or porcelain Gooch crucible, fitted with a platinum or asbestos mat carefully made and ignited to constant weight. Wash with 2.5% ammonium hydroxido until practically free from chlorides; dry, ignite, cool and weigh as magnesium pyrophosphate. If desired, filtration may be made through an ashless filter paper, igniting in the usual manner. Calculate to P_2O_4 by multiplying by 0.6378 (log 80468).

Determination of Iron and Aluminum together as Phosphates

I. Solutions Required: 1. Ilydrochloric acid (I:1); prepared by mixing 1 part by volume of concentrated HCl (sp.gr. 1.19) with 1 part of distilled water.

2. A saturated solution of ammonium chloride, which should be filtered before

3. A 25% solution of ammonium acetate, faintly acid to litinus paper.

4. A solution of animonium phosphato (10%), prepared by dissolving 20 grams of (NK4)₂HPO₄ in 180 co. of distilled water and filtering. (This should be prepared frequently in small quantity, as it attacks glass containers on standing.)

5. A standard solution of ferrous ammonium sulphate, containing iron equivalent

to about 0.0100 gram of Fe₂O₂ in 10 cc. and 50 cc. conc. HCl per liter.

6. A solution of calcium and magnesium phosphates for blank determinations, prepared as follows: Dissolve 4 grams of MgO and 35 grams of CaCO: (both free of fron and aluminum) in 100 ec. concentrated HCl, add an aqueous solution of 30 grams of (NH4)2HPO4, make up to 2 liters and filter.

7. A solution of ammonium nitrate (5%) for washing precipitates. About 400 cc.

are required for each determination.

All reagents used should be as pure as practicable and all solutions should be free

of suspended matter.

II. Preparation of Rock Solution. Place 2.5 grams of pulverized rock with 50 ee. of 1:1 HCl in a graduated 250-cc. flask, the glass of which contains less than 1%

of iron and aluminum oxides.1 Boil gently with occasional shaking for one hour in such a manner as to avoid concentrating the solution to less than half of its original volume, dilute, cool to room temperature, make up to volume and mix; filter immediately through a dry filter into a dry flask, discarding the first few co. of the

filtered solution.

Pipette a 50-cc. aliquot, representing 0.5 gram of rock, into a platinum dish and evaporate nearly to dryness. Cool, take up with a few cc. of water and when the salts are loosened from the dish, add 5 cc. of 1:1 sulphuric acid and evaporate to fumes. Increase the temperature and evaporate nearly to dryness.4 Cool, dilute with about 50 cc. of distilled water, add 10 cc. of conc. HCl and heat, with occasional stirring, until sulphates are dissolved. Filter into a 600-cc. Jena glass beaker through a 9-cm. paper (S. & S. No. 597), washing the paper thoroughly with dilute HCl and hot water.

III. First Precipitation with Ammonium Acetate. To the solution in the beaker, add 25 cc. of the standard iron solution when the amount of combined iron aluminum oxides in the rock does not exceed 5% and 50 cc. of the standard iron solution when the combined oxides exceed 5%. Oxidize with about 3 cc. of bromine water and boil in covered beaker for about fifteen minutes to expel the excess of bromine. Rinse cover and sides of beaker with distilled water and cool to room tem-

perature.

(Run a blank determination containing 10 cc. of 1:1 HCl, 25 cc. of the calcium and magnesium phosphate solution, and the same quantity of standard iron solution

as is added to the rock solution.)

Add 100 cc. of saturated ammonium chlorido solution, 6 3 cc. of 10% ammonium phosphate solution, 2 drops of methyl-orange indicator and conc. aminonium hydrate pnospnate solution, z drops of methyl-orange indicator and cone aminonium hydrate (free of spangles and dissolved mineral matter) to alkaline reaction. Then add dilute HCl (about 1:20) drop by drop, with constant stirring, until the solution becomes faintly acid and the pink color of the methyl orange is just restored. Dilute to 450 cc. with distilled water, heat to boiling, and add 25 cc. of 25% ammonium acetate solution. Continue heating for about five minutes, after adding ammonium acetate, filter on a 12.5 cm. ashless filter paper (S. & S. No. 589 "White Ribbon"

1 Experiments have shown that the solution cannot be made in flasks made of glass containing a higher percentage of alumina, because the fluorine in the rock partially dissolves the glass and adds alumina to the solution. Neither "Nonsol," "Jena" nor "Weber's" resistant glass "R" is suitable. Flasks mado of glass containing little alumina, such as "Kavalier," "F Z resistant glass" or other Bohemian glass of lower alumina content have proven satisfactory. See "Chemical Glassware,"

P. H. Walker, J. Am. Chem. Soc., 27, 865.

This may be accomplished by heating the flask over a low Bunsen flame or on a hot plate which is just hot enough to keep the solution boiling. A glass tube about 12 ins. long by in. in diameter with a bulb in the middle makes a very satisfactory

condenser when placed in the neck of the flask

denser when placed in the first of the HCl as possible before adding sulphuric a lit is advisable to remove as much of the HCl as possible before adding sulphuric as as to minimize the chances of loss by effervescence or bumping. The evapoacid so as to minimize the chances of loss by effervescence or bumping. ration may be conducted in glass beakers of low alumina content. Kavalier glass has been used satisfactorily. In no case should the evaporation be conducted in porcelain.

It is best to remove as much sulphuric acid as possible so that the calcium sulphate

which might hold iron will dissolve readily in HCl.

It has been found that when iron oxide is present in considerable excess over aluminum oxide the precipitation of the phosphates is more complete, the combined phosphates are more readily ignited to constant weight, and the precipitate does not become red on ignition.

• Ammonium chloride in large quantity increases the solubility of calcium and

magnesium phosphates and decreases the solubility of iron and aluminum phosphates.

This method of adjusting acidity was suggested by F. B. Carpenter and was

found to give satisfactory results.

*All our work has confirmed Brown's statement (see Wiley's "Principles and Practice of Agricultural Analysis," 2d edition, 1908, Vol. II, p. 245) that the separation from calcium under the conditions of the method depends upon sufficient dilution.

is suitable), in a 3-in. rapid filtering funnel, keeping the contents of the beaker and funnel hot. Wash three times with hot 5% ammonium nitrate solution, each time cutting the precipitate loose from the filter and stirring it thoroughly with the stream from the wash bottle and filling to within about 1 in. of its upper edge. About 30 ce. are required for each washing. Return the precipitate to the precipitating beaker by washing it out of the filter with a stream of hot water. Dissolve the precipitate with dilute HCl (1:6), pouring about 50 cc. through the filter in successive washings and using about 25 cc. to wash down inside the beaker. Finish filter paper with distilled water.

IV. Second Precipitation with Ammonium Acetate. Cool the solution to room temperature, add 50 cc. saturated ammonium chloride solution, 4 cc. of 10% ammonium phosphate solution, 2 drops of methyl orange, and adjust acidity as before. Dilute to 300 cc. with distilled water. Heat to boiling, add 15 cc. of 25% ammonium acetate solution and continue heating for about five minutes. Filter on the same paper as used for the first filtration, scrubbing the inside of the beaker with a rubber-tipped stirring rod and rinsing with hot 5% ammonium nitrate solution. Wash the precipitate ten times with hot 5% ammonium nitrato solution, each time cutting the precipitate loose, stirring it thoroughly as before and breaking up all lumps that it may

contain. About 300 cc. of wash solution are required.

As a precautionary measure, boil the filtrate and washings from both the first

and second precipitates, and recover any additional precipitate.

V. Ignition of Precipitate. Transfer filter with precipitate to a weighed deepform porcelain crucible (40 mm. in diameter is a good size) and heat gently over a low flame until the contents are dry, increase the temperature a little and continue heating until the paper is charred, increase the temperature again and continue heating until the paper is entirely burned. Ignite the uncovered ² porcelain crucible for one-hour periods over blast lump No. 4 Mcker burner to constant weight, each time cooling to room temperature in desiceator before weighing. Deduct the weight of blank from each determination, and after subtracting the weight of FePO4 equivalent to the amount of iron found in 0.5 gram of rock by titration, calculate the remainder to Al_2O_4 . $AlPO_4 \times 0.4184 = Al_2O_4$.

Determination of Iron

I. Solutions Required. 1. Standard Potassium Permanganate, N/40, containing 0.79015 gram of KMnt₄ per liter, and having a value of 0.001996 (or practically 0.002) gram of Fe₂O₃ per ec. Standardize with pure sodium oxalate (Bureau of Standards standards standards standard sample No. 40.)

2. Stannous Chloride. Dissolve 50 grams of the crystallized salt in 100 cc. of hot cone. IlCl and make up to 1 liter with distilled water.

3. Mercuric Chloride. Prepare a cold saturated solution.

4. Manganese Solution. (Preventive solution): (a) Dissolve 200 grams of crystallized manganese sulphato in 1000 cc. of water. (b) Pour slowly, with constant stirring, 400 cc. of cone. sulphuric acid into 600 cc. of water and add 1000 cc. of phos-

- phoric acid of 1.3 sp.gr. Mix solutions (a) and (b).

 II. Analytical Procedure. Determine iron according to Jones' and Jeffrey's modification of the Zimmernann-Reinhardt method as follows: Place in a 250-cc. beaker an aliquot of the rock solution, containing not more than 5 ec. of conc. better an adjust of the fock solution, containing not note that occording the solution and reduce with the smallest possible excess of stannous chloride, added drop by drop while agitating the solution. Wash sides of beaker with distilled water and cool rapidly. Add 10 cc. of mercuric chloride solution and stir vigorously for about thirty seconds. Pour the mixture into a large porcelain casserole or dish containing 20 cc. of the manganese solution in about 500 cc. of water which has just been tinted with the permanganate solution.
- 1 Tho contents of the funnel will remain hot if the solution in the beaker is kept hot over a low flame and filtration is fairly rapid.

Heat over Bunsen to redness before placing over blast in order to prevent loss

of precipitate by blowing out of crucible.

Analyst, 34 (1909), 306.

Barneby has shown that only a short interval of time is necessary between the addition of morcuric chloride and manganese sulphate, if the solution is thoroughly agitated. J. Am. Chem. Soc., 36 (1914).

Titrate with N/40 permanganate solution, to original tint and correct result by the volume of KMnO₄ required for a blank containing the same quantity of HCl (diluted), adding 2 or 3 drops of stannous chloride to the hot solution, cooling, adding 10 cc. of mercuric chloride and titrating similarly.

When the rock solution contains carbonaceous matter it is necessary first to oxidize this with a little potassium chlorate, evaporate to dryness to eliminate chlorine,

and redissolve with 5 ee. conc. HCl and about 10 ec. of water.

Calculate the Fe₂O₃ found to FePO₄, using the factor 1.8898, and after deducting from the weight of combined phosphates found, calculate the difference (AlPO₄) to Al₂O₃.

Volumetric Determination of Free Phosphoric Acid

Phosphoric acid may be titrated directly by means of standard sodium or potassium hydroxide. The choice of the indicator is important as may be seen by the following reactions:

HaPO₄+NaOH = $\rm H_2O+NaH_2PO_4$ (neutral to methyl orange, acid to phenolphthalein), $\rm H_3PO_4+2NaOH=2H_2O+Na_2HPO_4$ (neutral to phenol, and acid to methyl orange). The slight dissociation of Na₂HPO₄ causing an alkaline reaction to phenolphthalein prevents the endpoint being sharp. This dissociation may be repressed by titrating in a cold concentrated solution containing sodium chloride. The first reaction with methyl orange indicator is more satisfactory. By the electrometric method J. S. Coye has proven that the endpoint of phenolphthalein is the full color of the alkaline salt, not a faint pink.

Reference is made to the chapter on Acidimitry and Alkalimitry, Volume 2, for

titrating phosphoric acid in presence of its salts.

Sources of Error in the Determination of Phosphoric Acid

McCandless and Burton have shown! that discrepancies in the gravimetric determination of phosphorus in high grade materials are chiefly due to variations in the amount of HCl used in neutralizing the amnoniacal solution of the yellow precipitate. A solution made neutral, using lithnus paper as indicator, has the proper neutrality. Plus errors are caused by adding the acid in excess of the neutral point, and minus

errors by having ammonia in excess of neutrality.

The yellow precipitate contained in a small filter (7.5 cm.) is dissolved by adding NH₄OH drop by drop from a burette in just sufficient amount to dissolve the precipitate. The filter is washed free of the phosphate, the washing continued until the volume of the filtrate is 100–150 cc. To the cooled filtrate is added, drop by drop, dilute HCl (1:1), with constant stirring, until the color of the litmus paper, placed in the solution, changes to a violet, verging on blue rather than red. Magnesia mixture is now added, drop by drop, in slight excess. After 15 minutes NH₄OH (sp.gr. 0.90) is added, 12 cc. NH₄OH to 100 cc. filtrate or 18 cc. NH₄OH, if the volume is 150 cc. The precipitate is washed thoroughly with 2.5% NH₄OH water, and finally with a strong NH₄NO₃ solution in ammonia water. The Gooch and asbestos is ignited over the blast lamp before use.

¹ J. M. McCandless, J. O. Burton, Ind. Eng. Chem., 16, 1267, Dec., 1924.

PLATINUM

Pt, at.wt. 195.23; sp.gr. 21.48; m.p. 1755° C.; oxides PtO, PtO,

DETECTION

Platinum is a gray, lustrous, soft and malleable metal. It is not altered by ignition in the air, but fuses in the oxy-hydrogen flame. It does not dissolve in any of the single acids, but a fusion with acid potassium sulphate attacks the metal slightly. The action of chlorine in general, and nitro-hydrochloric acid (aqua regia), the main solvent, converts the metal to hydrochlorplatinic acid, H₂PtCl₅, which forms many double salts, or platinichlorides. If platinic chloride is gently heated it breaks up into platinous chloride, PtCl₂, and chlorine.

If, however, the platinum is alloyed with silver, it dissolves in nitrie acid to a

yellow liquid, provided sufficient silver is present in the alloy.

The oxides can be formed by carefully igniting the corresponding hydroxides. These are very unstable, decomposing into metal and oxygen by gentle ignition.

The chlorides are the most important compounds of platinum. Two complex acids are formed with hydrochloric acid when the metal is dissolved in aqua regia.

PtCl₄+2HCl=H₂PtCl₆ (chloroplatinic acid), orange-red crystals.

PtCl₂+2HCl=H₂PtCl₄ (chloroplatinous acid), only known in solution.

An aqueous solution of the former is yellowish-orange, while an aqueous solution of the latter is dark brown, the former being hy far the more important.

Potassium iodide precipitates platinum iodide, but it dissolves quite readily, giving a pink to a dark blood-red liquid, depending on the concentration of the solution. Nitric acid should be absent. Heat destroys this color, as well as hydrogen sulphide, sodium thiosulphate and sulphite, sulphurous acid, mercuric chloride and certain other reducing reagents.

Hydrogen sulphide precipitates black platinum disulphide, PtS₂, with the other elements of the hydrogen sulphide group. The solution should be hot, as precipitation takes place more quickly. It is difficultly soluble in ammonium sulphide. It will be found in the extract with the arsenic, antimony, tin, gold, molybdenum, etc., and is precipitated with these elements upon addition of hydroehloric acid. Platinum sulphide is soluble in aqua regia. Addition of MgCl₂ solution prevents formation of colloidal PtS₂.

Ammonium chloride added to a concentrated solution of platinum ehloride precipitates yellow (NH₄)₂PtCl₅, which is slightly soluble in water, and less so in dilute ammonium chloride solution and alcohol.

Potassium chloride precipitates yellow K₂PtCl₅, which is slightly soluble in water, but insoluble in 75% alcohol.

Chapter by R. E. Hickman and Edward Wichers.

Ferrous sulphate precipitates metallic platinum on boiling from a neutral solution. Neutralize with Na₂CO₃. Free mineral acids (except dilute H₂SO₄) prevent the precipitation (difference from gold).

Stannous chloride does not reduce platinum ehloride to metal, but reduces hydrochlorplatinie acid to hydrochlorplatinous acid.

Oxalic acid does not precipitate platinum (difference from gold).

Sodium hydroxide with glycerine reduces hydrochlorplatinic acid on warming to black metallic powder.

Formic acid precipitates from neutral boiling solutions all the platinum as a black metallic powder.

Thallium protoxide precipitates from the platinum bichloride solution a pale yellow salt, thallium platinochloride. When the salt is heated to redness it leaves an alloy of thallium and platinum.

Sodium hydroxide added to platinic chloride and then acidified with acetic acid produces a pale yellow to orange precipitate of platinic hydroxide, Pt(OH)₄. This dissolves in acids readily, except acetic acid.

Metallic zine, magnesium, iron, aluminum and copper are the most important metals that precipitate metallic platinum.

$$H_2PtCl_6+3Zn=3ZnCl_2+H_2+Pt.$$

ESTIMATION

Platinum may be present under the following conditions:

1. Native grains usually accompanied by the other so-called platinum metals, iridium, palladium, ruthenium, rhodium, osmium, and gold and silver (alloyed with one or more of the allied metals).

Ore concentrates containing the native grains as above with the base metals, iron, copper, chromium, titanium, etc. The associated minerals high in specific gravity in the gravels may be expected to appear with the platinum nuggets, such as chromite, magnetite, garnet, zircon, rutile, small diamonds, topaz, quartz, cassiterite, pyrite, epidote, and serpentine; with gold in syenite; orcs of lead and silver.

- 2. Scrap platinum containing, oftentimes, palladium, iridium, gold, silver and iron.
- 3. Small amounts of platinum in the presence of large amounts of iron, silica, carbon, magnesia: platinum residues, nickel and platinum contacts, photography paper, jewelers' filings and trimmings, dental and jewelers' sweeps and asbestos, etc.
 - 4. Platinum alloyed with silver, gold, tungsten, nickel, copper, lead, etc.
 - 5. Platinum solutions and salts.

Preparation and Solution of the Sample

The best solvent for platinum is aqua regia. The metal is also acted upon by fusion with the fixed alkalies—sodium or potassium hydroxide and sodium peroxide or potassium or sodium nitrate; also by chlorates in the presence of

HCl. Platinum, when highly heated, alloys with other metals, as lead, tin, bismuth, autimony, silver, gold, copper, etc. The element dissolves in nitric acid when alloyed with silver. This gives a method for the determination of gold in the presence of silver and platinum alloy.

All salts of platinum are soluble in water. The less soluble salts are the chloroplatinates of potassium, ammonium, rubidium, and caesium. Heat increases

the solubility while the presence of alcohol decreases the solubility.

Ores. When the free grains of platinum, gold and osmiridium are desired the following method is recommended: Five to 10 grams of the ore are taken from a well-mixed pulverized sample and placed in a large platinum dish that has been weighed. Twenty-five to 50 ec. of strong hydrofluoric acid together with 5 to 10 ec. of concentrated sulphuric acid is mixed with the ore in the dish and evaporated on the water bath, when SiF4 and the excess of HF are expelled. The material is gently heated until SO, fumes are given off. This is repeated with HF if necessary. The material is washed into a casserole with about 200 ec. of hot water and digested over a water bath for fifteen or twenty minutes, and is then washed by decautation, several times pouring the supernatant liquor through a filter to save any floating material that might be washed out. The filter is cautiously burned and the residue is added to the unattacked material. This is transferred from the dish to a beaker or a porcelain dish and treated with aqua regia. The platinum and a small amount of iridium that dissolves with the platinum on account of its being alloyed can be precipitated with ammonium elloride. The remaining residue in the dish will be a small amount of sand and osmiridium. The silica is driven off with HF as described above and the bright grains weighed as osmiridium, or the sand and osmiridium are fused with silver and borax, then extracted with dilute uitric acid, leaving the osmiridium grains free from sand.

Platinum Scrap. One-half gram to a gram is dissolved in aqua regia and evaporated with HCl to get rid of the IINO₂.

If the platinum is alloyed with a large amount of copper, silver, lead and other impurities, a sample of 1 to 5 grams is dissolved in 15 to 25 ec. of HNO₃, whereby the copper, silver, lead and other impurities alloyed with the platinum as well as a large amount of platinum will dissolve. The residue after washing will be platinum and gold. These are dissolved in aqua regia as described above and the platinum precipitated with ammonium chloride. The platinum is recovered from the nitrie acid solution and added to the aqua regia solution and the whole is evaporated to get rid of the HNO₃.

Small Amounts of Platinum in the Presence of Large Amounts of Iron; Iron Scale, Fe₂O₃; Sulphate of Iron, Magnesia, Sulphate of Magnesia, Silica, etc. The material is earefully weighed and the coarse scales are separated from the finer material containing the platinum by passing the fines through a 20-in. mesh or fluor wire sieve. The coarse scale seldom contains platinum, but it is advisable to quarter this down to 1 kilogram or a fairly good-sized sample and test for platinum on a portion of the ground sample. This can be tested by a wet or a fire assay. The fines are quartered down to about 1 kilogram and ground to pass a 60- to 80-in. mesh sieve. One hundred to 500 grams of the material are taken for analysis. This is placed in one or more casseroles, depending on the amount taken. Each 100-gram portion is extracted by digestion on the steam bath with about 300 to 400 cc. of 10% H₂SO₄. The iron, magnesia, etc., soluble in H₂SO₄ will go into solution, leaving the platinum with the

insoluble residue. Filter (a Büchner funnel may be necessary) and wash the residue with water. Test the filtrate for platinum and if any is present precipitate with zinc as described below.

After the filter is ignited in a large platinum dish, the residue is moistened with H₂SO₄, and HF is added completely covering the material. The solution is evaporated on the water bath until SO₃ fumes are given off. If necessary, repeat the treatment with H₂SO₄ and HF until all the silica is driven off as SiF₄. The residue is transferred to a casserole and digested with aqua regia according to directions given under Ores and Platinum Scrap. It is sometimes very difficult to precipitate all of the platinum in the presence of a large amount of iron, magnesia, etc., not having the solution concentrated enough for the platinum. It is advisable to reduce the platinum by iron or zinc, filter, wash with water and redissolve the black metallic platinum in aqua regia. The HNO₃ is expelled by evaporation and adding concentrated HCl from time to time and finally the platinum is precipitated with ammonium chloride.

SEPARATIONS

A careful review of the paragraph on Detection will be very helpful oftentimes in making separations from other metals and substances.

Separation of Platinum from Gold. The platinum is precipitated first with annuous chloride, as (NH₄)₂PtCl₆. After the precipitate has settled it is filtered and washed free from gold with 20% ammonium chloride solution and alcohol. The gold is precipitated with a concentrated solution of ferrous sulphate or iron protochloride as metallic gold. (See also page 387a.)

Oxalic acid precipitates the gold, leaving the platinum in solution. The oxalic acid is added and the solution heated until the gold is entirely precipitated. Filter and wash the precipitate of metallic gold free from platinum. The filtrate is evaporated as far as possible without crystallizing, and the platinum is precipitated with ammonium chloride as (NH₄)₂PtCl₆, or it may be reduced with zinc and the black dissolved in aqua regia and treated as described above.

Separation of Platinum from Iridium. The platinum and the iridium are precipitated by iron or zinc and the black residue is washed free from impurities and the platinum is dissolved in dilute aqua regia with gentle heating, leaving the iridium as metallic iridium. The platinum solution is evaporated as described above and precipitated with NH₄Cl as (NH₄)₂PtCl₆.

If the platinum and iridium are precipitated together, the salt is filtered and washed with ammonium chloride solution and finally ignited. The sponge is redissolved and evaporated as above to expel the HNO₃. The platinum and the iridium are precipitated with NaOII, which brings down the platinum and iridium as Pt(OH)₄ and Ir(OH)₄. Boil this mixture with alcohol, which reduces the Ir(OH)₄ to Ir(OH)₃, but does not affect the Pt(OH)₄. Dissolve these hydroxides in HCl, forming PtCl₄ and IrCl₅ in solution, and the platinum is precipitated with NH₄Cl free from iridium.

See Deville-Stas-Gilehrist method on page 390.

Separation of Platinum from Palladium. Platinum is precipitated with ammonium chloride, and palladium is precipitated from the filtrate by means of dimethylglyoxime (1% alcoholic solution).

Palladium may be precipitated in presence of platinum by adding a one per cent solution of dimethylglyoxime (1% salt in 95% alcohol) to the cold, slightly acid eliloride solution of the elements. If the solution is hot the palladium precipitate will be badly contaminated with platinum. (E. Wiehers.)

Separation of Platinum from Ruthenium. From the chloride of platinum and ruthenium the metals are precipitated with ammonium or potassium chloride and filtered. The filter is washed with dilute ammonium chloride solution or dilute potassium chloride solution and alcohol until free from ruthenium. If a large quantity is handled it may be necessary to ignite to platinum sponge and dissolve in aqua regia, expel the HNO₃ as described above, and reprecipitate with NH₄Cl, filter and wash free from ruthenium. (See also page 387a.)

Separation of Platinum from Rhodium. The separation is accomplished by adding freshly precipitated barium earbonate to the chloride solution of platinum and rhodium, previously brought nearly to the neutral point by addition of sodium hydroxide. After boiling for two or three minutes rhodium hydroxide precipitates. The precipitate is filtered off, dissolved in HCl, the solution again nearly neutralized and the rhodium precipitation repeated.

Other platinum metals will also precipitate if present. These should be removed prior to the separation of platinum and rhodium. (E. Wiehers.)

Separation of Platinum from Osmium. Both metals are reduced with zinc as a fine black powder. The metallic residue is washed and carefully ignited at a high temperature under a hood, as the fumes are poisonous and disagreeable like chlorine. The osmium will be converted into OsO4, which is very volatile. The residue is dissolved in aqua regia and the platinum is precipitated with NH4Cl. See Osmium.

GRAVIMETRIC METHODS FOR THE DETERMINATION OF PLATINUM

A. Weighing as Metallic Platinum

- 1. When the platinum contains only a small amount of impurities a sample of \(\frac{1}{10} \) gram or more is taken and dissolved in aqua regia. The solution is gently heated until all is dissolved, adding another portion of aqua regia if necessary. The solution is evaporated, adding HCl from time to time in order to expel the HNO₁. Filter and evaporate again to concentrate the solution. Precipitate with ammonium chloride. After stirring, let stand until the precipitate, (NH₄)₂PtCl₄, settles, overnight if convenient. Filter, wash with alcohol or ammonium chloride solution and alcohol, and ignite to metal, in a reducing atmosphere, or ignite slowly in paper filter. Cool in a desiceator and weigh as metallic platinum.
 - $\frac{\text{Wt. of Pt found}}{\text{Wt. of sample taken}} \times 100 = \text{per cent of Pt in the material.}$
- 2. When the platinum solution contains a large amount of impurities, as iron, nickel, magnesia, etc., it is advisable to reduce the platinum to black metallic platinum with zine, iron or magnesium as follows: The solution is made acid (2 to 5% free HCl) by adding HCl. The Zn, Fe or Mg is added in small quantities at a time until the solution becomes colorless or until the platinum is completely precipitated.¹ After action has ceased the platinum black metal is filtered onto an ashless filter paper and washed with warm dilute HCl to remove any excess Zn, Fe, or Mg that might be present. The filter and its contents are

 $^{^1\,\}text{FeCl}_2$ in presence of HCl has a solvent action on platinum, hence the iron should be completely reduced.

carefully ignited and afterwards dissolved in aqua regia and treated as directed under A, 1.1

3. If none of the other Hydrogen Sulphide Group metals are present the platinum can be precipitated by hydrogen sulphide, filtered, washed with hot water and ignited to metal. If impurities are present in the sulphide, dissolve in aqua regia and proceed as under A, 1. The solution should be boiling and have an acidity of 3% HCl or H₂SO₄.

B. Weighing as a Salt

1. The procedure is the same as under A. The (NH₄)₂PtCl₆ precipitate is washed on a weighed Gooch crucible with alcohol. The crucible and contents are dried at a temperature below 100°. Cool in a desiccator and weigh as (NH₄)₂PtCl₆.

2. After proceeding as described under A, the platinum is precipitated with potassium chloride as K₂PtCl₆. Transfer to a weighed Gooch crucible and wash well with alcohol. Dry below 100°, cool in a desiccator and weigh as K₂PtCl₆.

C. Determination of Platinum by Electro-analysis

When platinum solutions are acidulated with sulphuric acid and acted upon by a feeble current they give up the metal as a bright deposit upon the electrode. If platinum is used as the electrode, first coat it with a layer of copper and deposit the platinum upon the copper. Wash with water and alcohol and after drying weigh.

Wt. of electrode+Cu+Pt-Wt. of electrode+Cu=Wt. of Pt.

Dr. E. F. Smith, in his work on "Electro-Analysis" recommends that the K_1PtCl_4 be dissolved in water and slightly acidulated with H_2SO_4 (2 or 3% by vol.) and after heating to about 60 to 65° and electrolyzing with $N.D._{100} = .05$ ampere and 1.2 volts, the platinum will be completely precipitated in from four to five hours in a perfectly adherent form. A rotating anode will precipitate the platinum much quicker.

¹ If iron and lead are suspected, the platinum residue is washed with 10% solution of ammonium chloride and then with 10% solution of ammonium acetate and finally with 80% alcohol.

with 80% alcohol.

Factor (NH₄)₂PtCl₅ to Pt=0.4393.
Factor K₂PtCl₅ to Pt=0.4013.

PALLADIUM

Element, Palladium. Pd. at.wt. 106.7; sp.gr. 11.9; m.p. 1549° C.; oxides, PdO, PdO2.

DETECTION

This metal is also found associated with platinum and iridium as well as ruthenium, rhodium, and osmium. It occurs in the metallic state sometimes with gold and silver. It resembles platinum as to luster and color. Palladium sponge when heated slightly gives a rainbow effect due to the formation of oxides. Hydrogen passed over the sponge restores it to the original color. It dissolves in HNO₃ and boiling H₂SO₄. HCl has little action upon it. It is readily soluble in aqua regia, forming PdCl₂. PdCl₄ is unstable.

Palladium monoxide, PdO, is formed by a long-continued heating of the spongy metal in a current of oxygen at a temperature from 700 to 840° or by heating a mixture of a palladium salt with potassium carbonate. The pure hydrated oxide is best prepared by the hydrolysis of the nitrate.

It acts as a powerful oxidizing agent to organic substances, and is reduced to metal by hydrogen peroxide.

Palladium dioxide, PdO₂, is obtained in an impure hydrated form as a brown precipitate by the addition of caustic soda to potassium palladichloride. This is soluble in acids, but becomes less soluble when preserved. It can be obtained free from alkali and basic salts by the anodic oxidation of the nitrate, but it is not quite free from monoxide. The dioxide very readily decomposes into the monoxide and oxygen, and cannot be obtained in the anhydrous state. It acts as a vigorous oxidizing agent and decomposes hydrogen peroxide.

Alkalies precipitate in a concentrated solution a dark-brown precipitate soluble in an excess of the reagent. If boiled a brown palladous hydroxide is precipitated. The anhydrous oxide is black.

Ammonia added to a concentrated solution gives a flesh-red precipitate. Pd(NH₃)₂Cl₆, soluble in excess of ammonia. If HCl is added to this solution, the yellow compound of palladosamine chloride, Pd(NH₃Cl)₂, is deposited.

Sulphur dioxide precipitates the metal from the nitrate or sulphate solution but not from the chloride.

Cuprous chloride precipitates the metal from the sulphate, nitrate and chloride solution when they are not too strongly acid.

Mercuric cyanide precipitates a yellowish-white gelatinous precipitate, Pd(CN)₂, insoluble in dilute acids, but dissolving in ammonia and in potassium cyanide to K₂Pd(CN)₄.

Potassium iodide precipitates black palladous iodide, PdI2, insoluble in water, alcohol, and other, but soluble in an excess of reagent (Rk also ppts.).

Hydrogen sulphide precipitates black palladous sulphide, PdS, soluble in HCl and aqua regia, but insoluble in (NH₄)₂S.

Ferrous sulphate slowly produces a black precipitate of metallic palladium from the nitrate.

¹ "Treatise on Chemistry," Roscoe and Schorlemmer.

Ammonium chloride precipitates palladium as (NII4)2PdCl4 from the nitrate.

Formic acid, zinc and iron reduce to metallic palladium.

Soluble carbonates precipitate brown palladous hydroxide, Pd(OH)₂, soluble in excess, and reprecipitated on boiling.

Phosphuretted hydrogen gas precipitates palladium phosphide. (Difference from Pt, Rh, and Ir.)

Alcohol precipitates, on boiling, metallic palladium.

Alkaline tartrates and citrates form yellow precipitates in a neutral solution from the nitrate.

Stannous chloride produces a brownish-black precipitate, soluble in hydrochloric acid to an intense green solution.

Potassium bisulphate attacks the metal readily.

An alcoholic solution of iodine dropped on the metal will turn black.

Acetylene gas passed through an acidified solution containing Pd produces a brown precipitate which, upon ignition, yields Pd. In this way Pd may be quantitatively separated from Cu.

ESTIMATION

Palladium is determined in alloys, ores, jeweler's sweeps, etc.

Preparation and Solution of the Sample

The solubility of palladium has been taken up under Detection. Palladium when alloyed with platinum, or an alloy of platinum, iridium and palladium, dissolves with the other metals in aqua regia as the chloride When palladium is alloyed with silver the palladium and silver are dissolved in HNO₃, from which the silver can be separated.

Separations

Separation of Palladium from Platinum and Iridium. The chlorides of palladium, platinum and iridium in solution must be free from HNO₃. The platinum and the iridium are precipitated with NH₄Cl, leaving the palladium in solution. The precipitate is put on a filter and washed free from Pd with NH₄Cl solution and alcohol.

Separation of Palladium from Silver and Gold. At least three times the weight of the gold in silver should be present in the alloy in order to separate the silver and palladium from the gold. The silver and the palladium will dissolve in HNO₃, leaving the gold as the residue. This is filtered off and the silver may be precipitated with HCl. The silver chloride is filtered off and washed with hot water acidulated with HCl until free from palladium. Since AgCl tends to retain palladium it is advisable to redissolve the silver with HNO₃ after reduction of AgCl and reprecipitate the chloride to obtain a complete separation of palladium.

Separation of Palladium from Platinum. The chlorides of platinum and palladium being free from HNO₃ and having an excess of HCl is diluted with water. A 10% solution of potassium iodide is added until all of the palladium is precipitated. Avoid adding a large excess. The precipitate of PdI₂ is filtered off and washed free from platinum and alkali with water slightly acidulated with HCl. The filter is ignited to metallic sponge in a current of hydrogen. See glyoxime method on page 379.

GRAVIMETRIC METHODS FOR THE DETERMINATION OF PALLADIUM

1. The palladium is precipitated from the solution by granulated zinc, the solution having a small amount of free hydrochloric acid. The residue, after the zinc is dissolved, is put on a filter and washed free from impurities. Ignite the filter and dissolve in a small amount of aqua regia and evaporate to a syrupy consistency. Dilute with a small amount of water and add a few drops of HNO₃; precipitate the palladium with NH₄Cl crystals. Heat for a few minutes and let cool. Filter, wash with alcohol, and ignite. Reduce in hydrogen or moisten with formic acid to reduce to metal any oxide that may have formed. Dry and weigh as metallic palladium.

2. With the solution containing about one-fifth the volume of free HCl, the palladium is precipitated with 10% KI solution. Heat to nearly boiling, filter, wash free from iron, etc., with 1:4 HCl. Ignite, cool, reduce in hydro-

gen or moisten with formic acid, dry and weigh as metallic Pd.

3. The filtrate from the platinum precipitation or the nearly neutral solution containing the Pd is made to about 150 cc., and the Pd is precipitated by adding a solution of dimethylglyoxime (1% solution in alcohol). Bring to boiling and let stand overnight if convenient. Filter on a weighed Gooch crucible and wash with hot water slightly acidified with HCl, then with alcohol. Dry and weigh as $(C_8H_{14}N_4O_4)Pd$, which contains 31.67% Pd.

4. The nitric acid in the palladium solution is expelled by evaporating with HCl. Neutralize the chloride solution almost completely with sodium carbonate and mix the solution with a solution of mercuric cyanide, Hg(CN)₂, and heat gently for some time. Let stand until cool, overnight if convenient. A yellowish-white precipitate of Pd(CN)₂ is formed. Filter, wash with 1% Hg(CN)₂ solution, ignite and reduce in hydrogen to metal, or reduce with formic acid, dry, and weigh as metallic Pd.

5. The filtrate from the platinum precipitation is made neutral or slightly alkaline with Na₂CO₃ solution and an excess of formic acid is added. Boil until all the palladium is precipitated or the solution becomes clear. Filter, wash with hot water, ignite, reduce in hydrogen or with formic acid and weigh

as metallic Pd.

DETERMINATION OF PLATINUM AND PALLADIUM¹

Special Methods

Gold Bar. Dissolve a 100-gram sample in aqua regia, and expel the nitrie acid by evaporation and the addition of small amounts of hydrochloric acid. Take up with a few cc. of dilute hydrochloric acid. If there should be present a large amount of reduced gold, add a few drops of nitric acid and heat the solution for a few minutes. Dilute to 800 cc. with water, and let it stand in a cool place until solution clears. Filter off silver chloride and wash it with cold water. Pass sulphur dioxide gas through the filtrate to reduce the gold (palladium, etc., is also reduced). Decant the clear solution on a tight filter paper, and wash several times with hot water by decantation. Then pour over the gold in the beaker, 50 cc. of nitric acid, and boil for a few minutes to dissolve the reduced palladium. Add 50 cc. of hot water and filter on the same filter paper and wash several times with hot water. Add 15 cc. of sulphuric acid to the filtrate, evaporate and heat to heavy fumes. Cool, dilute to 200 cc. with water and boil for a few minutes, and filter off any gold and lead sulphate if present. Now pass hydrogen sulphide gas through the hot solution to precipitate the sulphides of platinum and palladium, ctc. Filter and wash with hot water. Place the filter paper with the precipitate in a porcelain crucible, dry, burn and ignite. Now touch the residue with the reducing flame of a Bunsen burner to reduce to metal any oxide of palladium that may have formed. Dissolve the residue with a few cc. of aqua regia, and transfer the solution to a tall 300-cc. beaker, and evaporate carefully to dryness on a steam or sand bath. Then moisten the residue with hydrochloric acid and evaporate to dryness again. Moisten the dry residue once more with hydrochloric acid and evaporate to dryness.

Now take up with 16 cc. of hydrochloric acid and 4 cc. of water, cover beaker and boil gently for a moment. Filter on a small filter paper and wash with a small stream of hot water. Discard the residue. Dilute filtrate to 60 cc., cover beaker and heat to near boiling point. Then add 16 grams of ammonium chloride and heat gently to near boiling until all ammonium chloride is in solution. Remove beaker from the hot plate, and let it stand over night in a cool place. Filter rapidly (using suction) on a tight, double filter paper, and wash with ammonium chloride solution (200 grams per liter of water). As the ammonium chloroplatinate is somewhat soluble if exposed to air, the precipitate should be covered with the wash solution all the time during filtration. Then before the ammonium chloride solution is all sucked through, wash once or twice with 95% grain alcohol. Save filtrate for palladium determination. Place the filter paper with the precipitate in a porcelain crucible, so that the precipitate does not come in contact with the sides of the crucible; if it docs, a platinum mirror will form, that cannot be removed. Dry gently and smoke off the filter paper (without burning it with a flame), and finally ignite at a bright red heat. Cool and weigh metallic platinum.

Add to the filtrate from the ammonium chloroplatinate precipitate, 16 cc. of nitric acid, stir, cover beaker, placing a glass triangle under the watch glass, and let it stand over night on steam plate. When the solution is supersaturated, as indicated when half of the solution is filled with ammonia salts,

¹ Contributed by F. Jaeger, Chemist, Nichols Copper Co.

remove the beaker from the steam plate and cool the solution. Filter off the ammonium chloropalladate just like the platinum salt and wash with ammonium nitrate solution (200 grams per liter of water). Finally wash with 97% grain alcohol. The solubility of ammonium chloropalladate is greater than of the platinum salt when exposed to air, therefore great care must be taken in filtering it. Place the precipitate with the filter paper in a porcelain crucible, dry, smoke off filter paper and finally ignite at a bright red heat. When cool, reduce any oxide that may have formed with the reducing flame of a Bunsen burner. Cool and weigh metallic palladium.

To confirm that all platinum and palladium is precipitated, neutralize the filtrate from the ammonium chloropalladate with a saturated solution of sodium carbonate, then add 30 cc. of formic acid, and boil for about one hour. Any platinum or palladium if still present will be precipitated as black powder.

NOTE. All evaporations should be made on a steam or sand bath, if not

incomplete precipitation of platinum will be obtained.

Refined Silver. Weigh out 1,000 gram sample and dissolve it with dilute nitric acid. Filter off the gold and any undissolved platinum, and then separate the gold from the platinum as described under "Gold Bar," and add the solution to the main filtrate. Dilute the filtrate from the gold residue, so that there will be 10 grams of silver per liter of solution, and then add a slight excess of hydrochloric acid to precipitate all the silver. Stir well and let it settle. Decant the clear solution and wash the precipitate on a Buechner funnel with cold water. Evaporate the filtrate to a small volume. Now mix the silver chloride, with about ten times its weight, with soda ash (which contains a small amount of corn starch) and dry. Place the mass in 30 grams crucibles, and finse for about 30 minutes. Pour in molds. When cool, hammer off excess of slag, and finally boil with hydrochloric acid to clean the silver buttons. Then dissolve with dilute nitric acid and precipitate silver as silver chloride as already described. Another silver chloride precipitation will be necessary to separate all platinum and palladium from the silver.

Combine all filtrates and evaporate to dryness on steam plate. Take up with a few cc. of hydrochloric acid and water, filter off the silver chloride and wash with cold water. This small amount of silver chloride carries down considerable—platinum and palladium. Therefore place the filter paper with the silver chloride in a 3-inch scorifier, dry, add 40 grams of test lead and a pinch of borax and scorify. Then cupel the lead button. Dissolve the silver buttons with dilute nitric acid and reprecipitate silver with hydrochloric acid. Finally when the pure white color of the silver chloride indicates that it is free from platinum and palladium, evaporate the filtrate to dryness on steam plate. Take up with 16 cc. of hydrochloric acid and 4 cc. of water. Boil for a minute, filter, and precipitate platinum and palladium as described under "Gold Bar."

Copper Anode Slimes. Take a 1,000-gram sample. Weigh out 3 gram portions into 3-inch scorifiers and mix each with 40 grams of test lead and a pinch of borax and lithurge. Scorify and cupel. Dissolve silver buttons with dilute nitric acid, and proceed as described under "Refined Silver."

Determination of Platinum and Palladium in Refined Gold¹

The sample may be in the shape of drillings, but from a bar it is easier to roll the gold into a thin ribbon.

Fifty grams² of gold sample is sufficient for gold which has been parted with sulphuric and nitric acids,

Dissolve sample in a 1,500 cc. beaker with 50 cc. of nitric acid (1.42) and 150 cc. of hydrochloric acid (1.19) using no water. Heating is not necessary. After complete solution of the sample, evaporate solution to a syrup of about 40 cc. volume, taking care not to evaporate too far, otherwise, some gold will become reduced and separate out; add 100 cc. of hydrochloric acid and re-evaporate the solution to syrup, repeating this operation four times in order to remove all nitric acid.

After the last evaporation, dilute with hot water, boil, add about 50 cc. hydrochloric acid (1.19) to clear up solution: volume of solution should be about 500 cc.

To the boiling solution³ gradually add a mixture of 50 grams ammonium oxalate and 50 grams oxalic acid, which should precipitate all the gold, but should there be any doubt add more of the mixture of the salts. Dilute the solution to about 1,000 cc. in volume and allow to settle in a warm place over night.

Filter off the gold, washing by decantation into a 1,500 cc. beaker. For extreme accuracy, this gold may be redissolved, re-evaporated and reprecipitated, this time with sulphur dioxide gas. This is more of a precautionary measure, for as a rule, no platinum or palladium will be found with the gold.

To the solution from the gold add 5 grams of 30 mesh C.P. zinc. This precipitates any gold left in the solution along with the silver, platinum, palladium, tellurium, copper, etc.

Filter as soon as precipitation is complete and wash by decantation keeping as much of the precipitate in the beaker as possible. Ignite filter paper and transfer residue and precipitate to a 250 cc. beaker, dissolve in 10 cc. aqua regia and after complete solution, add 5 cc. sulphuric acid (1.84) evaporate to fume of SO₃ and finne well, cool, dilute to 100 cc. bring solution to boiling and add 1 drop of hydrochloric acid to precipitate the silver, filter in a 400 cc. beaker, dilute filtrate to 200 cc. volume, add 5 cc. hydrochloric acid (1.19),

¹ Contributed by S. Skowronski, Chemist, Raritan Copper Works, Perth Amboy, N. J.

² For gold which has been electrolytically refined by the Wohlwill process, 100 grams of gold should be taken as a sample, doubling the quantity of acid necessary for the solution.

³ Sulphur dioxide gas is not recommended for the precipitation of gold as gold bullions contain a trace of tellurium, and in the presence of tellurium, palladium is precipitated as a telluride by sulphur dioxide gas. The gold precipitated with oxalic acid is free from palladium telluride and therefore may be reprecipitated with sulphur dioxide gas if a reprecipitation is thought necessary.

⁴ The platinum and palladium after solution in aqua regia, and addition of sulphurie acid, should be well funed, in order to reduce any gold remaining in the solution to the metallic condition, it is very essential that all the gold is removed at this stage,

otherwise it is liable to contaminate the palladium di-methyl glyoxime.

and precipitate palladium with .5 grams of dimethyl glyoxime dissolved in 50 cc. of boiling water.

Palladium dimethyl glyoxime, canary yellow in color, which possesses the same physical characteristics as the corresponding nickel salt, at once separates out. Allow to settle in a warm place for about five minutes. Filter in a Gooch crucible, wash with hot water, dry at 110° C. and weigh. Factor .3168.

To the filtrate from the palladium add 2 grams of 30-mesh C.P. zinc, which precipitates the platinum. Filter, ignite, precipitate and dissolve in aqua regia. Remove nitric acid by three evaporations with hydrochloric acid (1.19), taking care not to evaporate solution to dryness. After the last evaporation, take up with not more than 10 cc. of water, and a few drops of hydrochloric acid. If necessary, filter, keeping volume of 10 cc. add 2 grams of ammonium chloride, stir well, add 10 cc. of alcohol, and let stand one hour with an occasional stirring.

Filter off ammonium chlor-platinate in small Gooch crucible and ignite

to platinum in the usual manner.

Separation of Platinum and Gold. In place of the procedures given on page 379 it is often preferable to precipitate gold first by means of sulphur dioxide, then reprecipitating with oxalic acid from weakly acid solution to obtain gold free from platinum.

Separation of Platinum and Ruthenium. According to Deville and his co-workers the animonium chloride separation is unsatisfactory owing to contamination of the animonium chlor-platinate with ruthenium. The ruthenium may be separated by volatilization with chlorine passed into the alkaline solution of platinum and ruthenium. See page 387b.

⁵ Palladium is best precipitated with di-methyl glyoxime in a 3-5% acid solution, gold if present will be reduced to the metallic condition and should be removed before hand. Alcohol is not recommended as the solvent for the dimethyl glyoxime, as it slows up the precipitation of the palladium. A hot water solution works quicker, and should be filtered to remove insoluble matter before addition to the palladium solution.

The precipitation should be carried out in a cold solution, since platinum will contaminate the palladium precipitate if the dimethylglyoxime reagent is added to a

hot solution.

⁶ Any solutions containing platinum should never be evaporated to dryncss, as platinum is easily reduced in baking to the "platinous" condition which is not precipitated with anmonium chloride.

QUANTITATIVE SEPARATION OF THE ELEMENTS OF THE PLATINUM GROUP

Dissolve the material in aqua regia and filter off the insol. Ignite the residue and fuse in a nickel crucible with Na₂O₂. Cool, place NaOH and distriction in the solutions of distriction in the solutions of the containing a little water and acidify with HCl. Combine the solutions along in distriction of the Na₂O₂. Cool, place

RARER ELEMENTS OF THE ALLIED PLATINUM METALS

IRIDIUM

Element, Iridium. Ir. at.wt. 193.1; sp.gr. 22.3; m.p. 23.50° C.? oxides, IrO2, Ir2O3.

DETECTION

Iridium is found associated with platinum. The element is insoluble in all acids, including aqua regia. Chlorine is the best reagent which forms the chlorides of iridium and yields compounds with other chlorides as K_2IrCl_6 , which is insoluble. If the element is heated in a stream of chlorine in the presence of potassium chloride there forms a salt, K_2IrCl_6 , which is sparingly soluble and is used in the separation of iridium.

The oxide, Ir₂O₃ is formed when K₂IrCl₆ is mixed with sodium earbonate and gently fused at a dull red heat.

 $2K_2IrCI_6 + 4Na_2CO_3 = Ir_2O_3 + 8NaCI + 4KCI + 4CO_2 + O.$

The fusion is dissolved in water containing ammonium chloride; filter the residue and after ignition, to expel the ammonium chloride, is treated with dilute acid in order to remove the small quantity of alkali. A bluish-black powder is thus obtained which begins to decompose when heated above 800 degrees, and at temperatures somewhat above 1000 degrees is completely broken up into oxygen and the metal.

The dioxide, IrO₂, is a black powder obtained by heating the hydroxide in a current of carbon dioxide. It is insoluble in acids.²

Caustie Alkalies produce in a boiling solution a dark-blue precipitate of Ir(OII)₄ insoluble in all acids except HCl.

Potassium chloride forms the double salt of K₂IrCl₆, which is black and is difficulty soluble in water.

Ammonium chloride precipitates black (NII₄)₂IrCl₆, which is difficulty soluble in water.

Hydrogen sulphide precipitates black Ir₂S₃, soluble in (NH₄)₂S.

Metallie zine precipitates from an acid solution black metallie iridium.

Formic acid and sulphurous acid precipitate black metallic iridium from hot solutions.

Lead acetate gives a grny-brown precipitate.

"Treatise on Chemistry," Roscoc and Schorlemmer.

Chapter contributed by R. E. Hickman and Edward Wichers.

ESTIMATION

Substances in which iridium is determined are: platinum scrap, jewelers' sweeps, contact points, ores. Iridium is weighed as the metal.

Preparation and Solution of the Sample

Platinum serap and contact points, etc., containing iridium dissolve with difficulty in aqua regia, depending on the amount of iridium present. The alloy is dissolved more quickly if it is rolled or hammered to a very thin sheet or ribbon. The alloy of platinum and iridium with an iridium content up to 10% dissolves in aqua regia slowly; an alloy of iridium content of 15% dissolves in aqua regia very slowly and the aqua regia will likely have to be replenished from time to time. An alloy of 25% iridium is practically insoluble in aqua regia. The filings from sweeps, etc., can be dissolved by aqua regia the same as the scrap. After expelling the $11NO_3$ the platinum and the iridium are precipitated together with NH₄Cl as $(NH_4)_2PtCl_6$ and $(NH_4)_2IrCl_6$. The iridium imparts a pinkish to a scarlet color to the salt.

If the iridium content is too high to be dissolved in aqua regia the metal can be mixed with NaCl, heated to a dull real heat in a porcelain or silica tube, and moist chlorine passed over the mixture. The iridium will be in the form of a chloride which dissolves in water. After filtering the solution and evaporating with IICl, the iridium as well as the platinum is precipitated with NH₄Cl or H₂S. This is a convenient way on a larger scale to dissolve osmiridium in ores. The writer has had good results with this operation.

When the iridium is contaminated with a large amount of impurities, it may be reduced from the solution with zine, and the impurities dissolved by HNO₃ and dilute aqua regia; the residue is washed and dried as iridium.

Clean osmiridium grains are also brought into solution by a fusion of KNO₃, NaNO₃ or KClO₃ and NaOH or KOH, leaving the iridium as 1r₂O₃.

SEPARATIONS

Separation of Iridium from Platinum. See Separation of Pt from Ir.

If the platinum and iridium are alloyed with at least ten times their weight of silver or lead and the alloy dissolved in HNO₃, the silver or lead and the platinum dissolves, leaving the iridium insoluble. After washing the residue, treat with a small amount of dilute aqua regia to dissolve any platinum that may be present.

Separation from Osmium. Osmium is removed by distillation. See Os. For other separations see under Rh and Ru. See all section 3 following.

GRAVIMETRIC METHODS FOR THE DETERMINATION OF IRIDIUM

1. By Reduction with Zinc

The solution of iridium or iridium and platinum is treated with C.P. granulated zine and 5% free HCl. The iridium and the platinum are precipitated as fine black metal. The black metal is washed free from impurities and the platinum is dissolved in dilute aqua regia as described under the Separations. The insoluble portion is dried, ignited, reduced with hydrogen and weighed as metallic iridium.

2. By Igniting the Salt (NH₄)₂IrCl₆

The percentage of iridium in the salt may be judged fairly well by the color, by comparing with standard iridio-platinum salts. The salt is filtered, washed with alcohol and carefully ignited and weighed as iridio-platinum sponge metal. The percentage of iridium in the sample can be calculated from the weight of the iridium obtained. The two metals are treated as stated under 3 below.

3. By Obtaining it as a Residue

The iridium and the platinum, etc., are alloyed with at least ten times its weight of silver and the alloy dissolved in HNO₃. The residue will be a small amount of platinum, gold, if any present, and iridium. Add a small amount of dilute aqua regia, which will dissolve the gold and the rest of the platinum, leaving the iridium as a black residue. This is filtered, washed and ignited, reduced by hydrogen and weighed as metallic iridium.

One part of the iridium material is alloyed with ten parts of lead. This is packed in a graphite capsule, and the whole embedded in charcoal in an ordinary assay crucible. Heat to a high temperature in a furnace for several hours. When the crucible and contents are cold, remove the lead and clean well. Treat the lead with dilute HNO₃, thus removing the lead and leaving the iridium as the residue. Wash thoroughly and treat the residue with dilute aqua regia, which leaves the residue as pure iridium. If other metals of the platinum group are present, see separations under those metals.

4. Determination of Iridium

Method of Deville and Stas, Modified by Gilehrist 1

1. Lead Fusion. Fuse the carefully sampled platinum alloy with 10 times its weight of granular test lend for a period of one hour at a temperature of about 1000°. A covered erueible, whose outside dimensions are 4 em. in diameter and 7 cm. in height, machined from Acheson graphite, is suitable for fusions made with 20 to 40 grams of lend. The inside of the crueible should possess a slight taper to facilitate the removal of the ecoled ingot. Do not pour the fusion from the crueible, but allow it to solidify, since the iridium has largely settled to the bottom of the crueible. The crueible is best heated with an electric furnace.

¹ Raleigh Gilchrist, U. S. Bureau of Standards, Jour. Am. Chem. Soc., 45, 2820 (1923).

- 2. Disintegration with Nitric Acid. Brush the cooled lead ingot free from carbon with a camel's hair brush and place it in a beaker. Add nitric acid of the concentration one volume of nitric acid (d. 1.42) to 4 volumes of water, using 1 ec. of acid per g. of lead. Place the beaker on the steam bath or on a hot-plate, which maintains the temperature of the solution at about 85°. Disintegration of the lead ingot is usually complete in about two hours and leaves a rather voluminous, grayish-black mass. Dilute the solution to twice its volume and decaut the liquid through a double filter, consisting of a 9-em. paper of fine texture, on which is superimposed a 7-em. paper of looser texture. Wash the residue quite thoroughly with hot water and pass the washings through the filters. The residue is not transferred to the filters at this point. The lead nitrate solutions and washings are best caught in an Erlenmeyer flask to make easier the detection of the presence of any residue which has passed through the filters. This is done by whirling the liquid in the flask. Return the filters to the beaker without ignition.
 - 3. Solution of the Lead-Platinum Alloy with Aqua Regia. Add in order -15 cc. of water, 5 cc. of hydrochloric acid (d. 1.18) and 0.8 cc. of nitric acid (d. 142) for each gram of the platinum-alloy sample taken. Heat the solution in the beaker on the steam-bath or on a hot-plate which maintains the temperature at about 85°. The lead-platinum alloy is usually completely dissolved within one and a half hours. Dilute the solution with twice its volume of water and filter through a double filter similar to the one used for the lead nitrate solution, the iridium, insoluble in aqua regia, is in the form of fine crystals, possessing a bright metallic luster and having a high density. Pass the clear solution through the filter first and then transfer the thoroughly macerated paper. It is very important to examine the beaker to see that no iridium remains. To do this the interior of the beaker is wiped with a piece of filter paper to collect any metal adhering to the sides. Then by whirling a small quantity of water in the beaker any iridium remaining gravitates towards one place whence it can be removed with a piece of paper. Wash the filters and iridium thoroughly, first with hot water, then with hot dilute hydrochloric acid (1:100), and lastly with hot water. The chlorplatinic acid filtrate and washings should be examined for iridium, which may have passed through the filters, in the manner described under the nitrie acid treatment. The last washings should be tested for the absence of lead.
 - 4. Ignition and Reduction of the Iridium. Place the washed filters and iridium in a porcelain crucible and dry, before igniting in air. After the destruction of the filter paper, ignite the iridium strongly with the full heat of a Tirrill burner. After all the carbon is burned out, cover the crucible with a Rose lid, preferably of quartz. Introduce into the crucible a stream of hydrogen, burning from the tip of a Rose delivery tube (a quartz tube preferred). After five minutes remove the burner and a few minutes later extinguish the hydrogen flame by momentarily breaking the current of hydrogen. This is best done by having a section of the rubber delivery tube replaced by a glass tube, one end of which can easily be disconnected. Allow the iridium to cool in an atmosphere of hydrogen and then weigh as metallic iridium.

Notes. In commercial analysis no effort is made to correct the weight of iridium for small amounts of ruthenium. Correction, if desired, can be made according to the original directions of Deville and Stas. ("Procés-verbaux, Comité International des Poids et Mesures," 1877, p. 185.)

The correction for iron can be made by the procedure

suggested by W. H. Swanger, U. S. Burcau of Standards. The iridium is fused with zipe, the excess zine removed with hydrochloric acid, and the zine-iridium alloy fused with potassium pyrosulphate. The fusion is digested with dilute sulphuric acid, which leaves a residue of iridium free from iron but contaminated with silica. Silica is now removed by the usual manner and pure iridium remains. This purification is necessary if iron is present in the sample since this separates with iridium. Palladium, rhodium and gold have no effect in the determination. Ruthenium separates quantitatively with the iridium. The loss of weight of iridium during the ignition periods is insignificant.

RUTHENIUM

Element, Ruthenium. Ru. at.wt. 101.7; sp.gr. 12; m.p. 2450° C.? oxides, Ru₂O₃, RuO₄.

DETECTION

This element is found in platinum ores, and as laurite, Ru₂S₂. It is barely soluble in aqua regia and insoluble in acid potassium sulphate. It dissolves when fused with KOH and KNO₃. The solution of the fusion when dissolved in water forms potassium rathenate, K₂RuO₄, from which HNO₃ precipitates the hydroxide, which is soluble in HCl. The treatment with chlorine and KCl at a high temperature yields a salt of K₂RuCl₆. The salts that are most common are K₂RuCl₅ and K₂RuCl₆.

The oxide, Ru₂O₃, is formed when finely divided ruthenium is heated in the air, forming a blue powder which is insoluble in acids. It can also be obtained by heating the trihydroxide, Ru(OII)₃, in dry carbon dioxide which forms a black, scaly mass.¹

Ruthenium dioxide, RuO₂, is obtained byroasting the disulphide or sulphate in contact with air. It is likewise formed when the metal is fused in an oxidizing atmosphere, when it burns with a sparkling smoky flame, and evolves an ozone-like smell.¹

Ruthenium tetroxide, RuO₄, is formed in small quantities when the metal is heated at 1000° in a current of oxygen, although when heated alone it decomposes about 106°. It is prepared by passing chlorine into a solution of potassium nitrosachlororuthenate, or of potassium ruthenate or sodium ruthenate prepared by fusing the metal with sodium peroxide; the liquid becomes heated and the tetroxide distills over and is deposited in the receiver. The moist oxide quickly decomposes. In the dry state it is fairly stable, but decomposes in sunlight with the formation of lower oxides. It dissolves slowly in water, and the solution when it contains free chlorine or HCl may be kept without alteration for some days if light be excluded, but when pure slowly deposits a black precipitate.¹

In addition to the above oxides, salts corresponding to the acidic oxides RuO₃ and Ru₂O₇ have been prepared.

Potassium hydroxide precipitates a black hydroxide easily soluble in HCl. Hydrogen sulphide slowly produces brown Ru₂S₃.

Ammonium sulphide precipitates brownish black sulphide.

Metallic zinc precipitates metallic ruthenium, the solution first turning blue. Potassium sulphocyanate gives on heating a dark brown solution.

Silver nitrate gives a rose red precipitate.

Mercurous nitrate produces a bright blue precipitate.

Zinc chloride produces a bright yellow precipitate which darkens on standing.

¹ "Treatise on Chemistry," Roscoe and Schorlemmer.

Potassium iodide after a time by heating precipitates the black sesquiiodide.

ESTIMATION

Ruthenium is generally estimated in alloys and ores or residues.

Preparation and Solution of the Sample

When ruthenium is alloyed with platinum or gold, aqua regia dissolves these metals, forming the chlorides of platinum, gold and ruthenium. The ruthenium in ores is in the form of an alloy with platinum or osmiridium. This is fused with KNO₃ and KOH in a silver crucible, the osmium and the ruthenium forming salts as described above, while the iridium remains as an oxide.

Separations

Separation of Ruthenium from Platinum. The two metals are precipitated with KCl and the potassium rutheniochloride is dissolved out with cold water containing a very small amount of KCl and alcohol. The ruthenium is then precipitated from an acid solution by additions of granulated zinc.

A separation may be made by alloying with silver and dissolving the platinum and silver by HNO₃, the ruthenium remaining as the residue.

From a concentrated solution of these metals precipitate the platinum with NH₄Cl. Evaporate the filtrate with potassium nitrate to dryness and boil the residue with alcohol when the residual platinum will remain behind and the ruthenium goes into solution.

Separation of Ruthenium from Iridium. The two metals are fused with KOH and KNO₃ as described above, the ruthenium forming a salt soluble in water and the iridium remaining as an oxide.

To the solution of the two metals, sodium nitrite is added in excess, with sufficient sodium carbonate to keep the liquid neutral or alkaline. The whole is boiled until an orange color appears. The ruthenium and the iridium are converted into soluble double nitrites. Sodium sulphide is then added, small quantities at a time until the precipitated ruthenium sulphide is dissolved in the excess of alkaline sulphide. At first the addition of the sulphide gives the characteristic crimson tiut due to ruthenium, but this quickly disappears and gives a bright chocolate-colored precipitate. The solution is boiled for a few minutes, and allowed to become perfectly cold and then dilute HCl cautiously added until the dissolved ruthenium sulphide is precipitated and the solution is faintly acid. The solution is filtered and the precipitate washed with hot water. The filtrate will be free from ruthenium.

The fusion with KOH and KNO₃ as described above is dissolved in water in a flask or retort; chlorine is passed through this solution and thence into two or three flasks containing a solution of KOH and alcohol. The two or three flasks which form the condensing apparatus should be kept as cold as possible. The ruthenium is transformed into volatile RuO₄ which condenses in the flasks, while the iridium remains in the retort.

¹ "Select Methods in Chemical Analysis," Sir Wm. Crookes.

Separation of Ruthenium from Rhodium. The mixed solution of the two metals is treated with potassium nitrite as described above. The orange-yellow solution is evaporated to dryness upon the water bath and treated with absolute alcohol. The rhodium remains undissolved and can be filtered off and washed with alcohol. The rhodium salt can be ignited with NH₄Cl and after washing yields metallic rhodium. See Separation of Rhodium from Ruthenium.

Separation of Ruthenium from Osmium. See Separation of Osmium from Ruthenium.

GRAVIMETRIC METHODS FOR THE DETERMINATION OF RUTHENIUM

Ruthenium is weighed as the residue or metallic ruthenium after it has

been separated from the other metals.

The residue containing ruthenium or osmiridium is fused in a silver erucible with five grams KOH and one gram KNO₃ at a low temperature from one-half to one hour. The mass is cooled and extracted with water. The orange-colored solution containing potassium ruthenate is gently distilled in a current of chlorine whereby the volatile ruthenium tetroxide passes over into the receivers. All connections should be ground glass so that no Ru will be reduced in the joints. The solution in the distilling flask must be kept alkaline to prevent iridium chloride from distilling over with the Ru. Add a small piece of KOH after the first distillation and distill as before. Oftentimes it will be necessary to fuse again with KOH and KNO₃ and distill as stated above. Continue to pass chlorine through the alkaline solution until all effervescence ceases. Disconnect the chlorine and draw air through the apparatus, heating the solution nearly to boiling.

1. Receivers containing KOH solution (10 to 15% KOH) and alcohol.

- a. This alkaline solution containing the ruthenium tetroxide distillate is evaporated to a smaller volume and the ruthenium is precipitated by boiling with absolute alcohol. Filter, wash well with hot water, dilute HCl and again with hot water. Ignite, reduce in hydrogen and weigh as metallic Ru.
- b. The alkaline solution from the receivers is made acid with HCl and the Ru is precipitated from the hot solution with hydrogen sulphide gas. Filter, wash, ignite at a high temperature, reduce in hydrogen and weigh as metallic Ru.
 - 2. Receivers containing hydrochloric acid.
- a. This acid solution containing the ruthenium tetroxide distillate is heated to nearly boiling and the ruthenium is precipitated with hydrogen sulphide gas as under 1b.
- b. The acid solution containing the Ru is evaporated to a concentrated solution and transferred to a weighed porcelain crucible. Evaporate to dryness, bake and ignite. Reduce in hydrogen and weigh as metallic Ru.
- c. Ruthenium may be estimated by precipitation with magnesium from solutions of its salts. The precipitate is washed with dilute sulphurie acid to remove excess of magnesium, dried, ignited in a current of hydrogen, cooled in carbon dioxide and weighed as metal.¹

¹ Text Book of Inorganic Chemistry, Vol. IX, Part I. J. N. Friend.

RHODIUM

Element, Rhodium. Rh. at.wt. 102.91; sp.gr. 12.1; m.p. 1950° C.; oxides, RhO, Rh₂O₃, RhO₂.

DETECTION

Rhodium is found only in platinum ores. It is a white metal, difficultly fusible, and insoluble in acids. Rhodium, however, dissolves in aqua regia when alloyed with platinum, to a cherry red solution. It is also soluble in molten phosphoric acid and dissolves when fused with acid potassium sulphate with the formation of $K_2Rh(SO_4)_3$. If the metal is treated with chlorine in the presence of sodium chloride there forms a soluble salt, Na_2RhCl_6 .

Rhodium monoxide, RhO, is obtained by heating the hydroxide Rh(OH)_s, by cupellation of an alloy of rhodium and lead, or by igniting the finely-divided metal in a current of air. It is a grey powder with a metallic appearance, and is not attacked by acids, and when heated in hydrogen is reduced with evolution

of light.1

The oxide, Rh₂O₃, is obtained as a grey iridescent spongy mass by heating the nitrate. It is also formed as a crystalline mass when sodium rhodochloride is heated in oxygen. It is perfectly soluble in acids ¹

Rhodium dioxide, RhO₂, is obtained by repeated fusions of the metal with KOH and KNO₃. It is attacked neither by alkalies nor by acids and is reduced by hydrogen only at a high temperature.¹

Hydrogen sulphide precipitates rhodium sulphide, when passed into a

boiling hot solution containing rhodium.

Potassium hydroxide precipitates at first a yellow hydroxide, $Ph(OH)_3 + H_2O$ soluble in an excess of the reagent. If boiled, a dark gelatinous precipitate separates. A solution of Na_3RhCl_6 does not show this reaction immediately, but the precipitate appears in the course of time. An addition of alcohol eauses a black precipitate immediately.

Ammonium hydroxide produces a precipitate which dissolves in excess NH4OH on heating. Addition of HCl now produces a yellow precipitate,

insoluble in HCl but soluble in NH4OH.

Potassium nitrite precipitates from hot solutions a bright yellow precipitate of double nitrite of potassium and rhodium.

Zinc, iron and formic acid precipitate rhodium as a black metal.

Hydrogen reduces rhodium salts.

To detect small amounts of rhodium in the presence of other metals, evaporate the solution and displace with a fresh solution of sodium hypochlorite; the yellow precipitate formed is soluble after an addition of acetic acid. After a long agitation the solution changes to an orange-yellow color and after a short time the color passes and finally a grey precipitate settles and the solution turns sky-blue.²

² Prescott and Johnson.

¹ "Treatise on Chemistry," Roscoe and Schorlemmer.

ESTIMATION

Rhodium is estimated mainly in ores, thermo couples and salts.

Preparation and Solution of the Sample

When rhodium is estimated in thermo couples or other alloys of platinum and rhodium the wire or sample is rolled to a thin ribbon and dissolved in aqua regia. Both metals will go into solution, forming the chlorides of rhodium and platinum. The aqua regia will have to be replaced from time to time, as the alloy dissolves slowly.

The rhodium from salts is precipitated with zine and the black metallic rhodium cleaned with dilute aqua regia, filtered, washed, ignited and reduced with hydrogen.

Some alloys and ores are alloyed with silver and the silver and platinum are dissolved in HNO₃. The residue is cleaned with aqua regia, dried, and weighed as metallic rhodium. If the residue is ignited reduce with hydrogen.

The material or residue containing rhodium is fused with KHSO₄ for some time at a low red heat and the mass leached with hot water acidified with HCl. The rose-red solution contains the rhodium. Several fusions are generally necessary.

Separations

Separation of Rhodium from Platinum. Alloys and ores containing platinum and rhodium dissolve slowly in aqua regia as stated above. After expelling the HNO₃ add NH₄Cl. The precipitate is filtered and washed with dilute ammonium chloride solution, which dissolves the rhodium salt. A very small amount of rhodium will color the filtrate pink to a rose-red color, depending on the amount of rhodium present. A green tinge in the ammonium chloroplatinate indicates the presence of rhodium.

A solution of NaOll is added to the HCl solution of the two metals until yellow rhodium hydroxide begins to separate. After neutralizing, the volume of the solution should be so adjusted that the estimated total content of Pt and Rh does not exceed 1 gram per 100 ec. A mixture of equal volumes of solutions containing 90 grams of crystallized barium chloride and 36 grams of anhydrous sodium earbonate per liter, respectively, is added. Not less than 5 ee. of each solution is taken. After the suspension of barium earbonate is added, the solution is rapidly heated to boiling and boiled for two or three minutes. The residue is filtered off and washed several times with a hot 2% solution of sodium chloride, after which it is returned, with the filter paper, to the original beaker and digested with 25 cc. HCl (1HCl to 4H2O) until solution is complete. Dilute with water and filter off the paper pulp. Adjust the volume to about 150 ce., heat to incipient boiling for 30 to 45 minutes while a current of hydrogen sulphide is passed in. After the precipitation the rhodium sulphide is filtered off at once, washed with water containing a little ammonium chloride, and ignited in a weighed porcelain crucible. The ignited sulphide is reduced and cooled in hydrogen, and weighed as metallic Rh.1

Separation of Rhodium from Iridium. See Separation of Rh from Pt.

A separation can be made by adding sodium nitrite in excess to the solution of the two metals, with a sufficient quantity of sodium carbonate to make the

¹ Edward Wichers, The Jour, Am. Chem. Soc., Aug. 1924.

solution neutral or alkaline; this is boiled until the solution assumes a clear orange color. The rhodium and iridium are converted into soluble double nitrites. A solution of sodium sulphide is added in slight excess and the liquid made slightly acid. The rhodium is precipitated as dark-brown rhodium sulphide.

A solution of rhodium and iridium is evaporated with HCl and displaced with a large excess of acid sodium sulphite, NaHSO₃, and allowed to stand sometime when a pale yellow double salt of rhodium and sodium sulphite slowly separates out while the solution becomes nearly colorless. Wash out the precipitate, and heat with hot concentrated H₂SO₄ till the sulphurous acid is driven off. Heat the material in a crucible until rid of all free sulphurie acid. Then the iridium is dissolved out as a sulphate with a deep chronegreen color, while a double salt of sodium sulphate and rhodium oxide remains behind. This is flesh color insoluble in water and acids. Boil with aqua regia, wash, dry, heat and it decomposes into rhodium and sodium sulphate.¹

Rhodium can also be separated from iridium, when the latter is present as an iridic salt such as $Ir(SO_4)_2$, by precipitating the mixed salts with caustic potash, dissolving the hydroxides in dilute sulphuric acid and adding eacsium sulphate. The sparingly soluble rhodium caesium-alum separates in the cold, and can readily be purified by recrystallization and then by electrolysis.²

The residue of rhodium and iridium is melted or scorified with test lead. The lead button is cleaned and dissolved in dilute HNO₃. After filtering and washing the residue, do not ignite, but wash the contents of the filter into a beaker and fume with H₂SO₄ from one to three hours. When cool, dilute with water and let stand over night: The residue contains the iridium and a small amount of PbSO₄, while the solution contains the rhodium as the sulphate. To make a further separation from impurities present, the sulphate solution is made alkaline with NaOH and boiled. Let stand until cold and filter off the rhodium hydroxide. Digest with HCl until all the hydroxide has dissolved. Filter and wash with hot water. Evaporate the filtrate to dryness, dissolve in hot water and add about 15 ec. of sodium nitrite solution (40% NaNO₂). Heat until all action eeases, then add sodium carbonate to the hot solution until no more precipitate forms. Let cool, filter and wash with hot water. Acidify the filtrate with dilute acetic acid and add potassium chloride solution (20% KCI) until all the Rh is precipitated. Let stand over night at 50 to 60° C. When cold, filter the white precipitate, washing with 20% KCl solution containing a little NaNO2. The white precipitate of potassium rhodium nitrite is digested with HCl, filtered and washed with hot water. Evaporate the HCl solution to dryness, add ammonium formate and heat until dry. Ignite, reduce in hydrogen and cool in CO2, wash free from salts with hot water, ignite and reduce in hydrogen as before and weigh as metallic Rh.

Separation of Rhodium, Platinum and Palladium. Having the three in solution precipitate the platinum with NH₄Cl as described under Platinum. After filtering off the (NH₄)₂PtCl₆ precipitate, and after neutralizing the filtrate with Na₂CO₃ add mercuric cyanide to separate the palladium as Pd(CN)₂ as described under palladium. The filtered solution is evaporated to dryness with an excess of HCl. On treating the residue with alcohol, the double

Hand Book of Chemistry," Dammer.
 Treatise on Chemistry," Roscoe and Schorlemmer.

chloride of rhodium and sodium is left undissolved as a red powder. By heating this in a tube through which hydrogen is passed the rhodium is reduced to the metallic state and the sodium chloride is washed out with water leaving a

grey powder of metallie rhodium.

The residue containing these three metals is scorified with test lead, and the resultant lead button eupelled with silver. The silver bead is dissolved in dilute HNO₂; the solution filtered, washed with hot water, ignited, and the residue treated with dilute aqua regia to dissolve any platinum or palladium that may be present. Filter, wash with hot water, ammonia water, and again with hot water. Ignite and reduce in hydrogen as metallic Rh.

Separation of Rhodium from Ruthenium. The solution containing the two metals is treated with sodium nitrate as above and evaporated to dryness. The residue is powdered and treated in a flask with absolute alcohol. After

filtering and washing with alcohol the rhodium remains undissolved.

The substance or residue containing the rhodium and ruthenium may be fused with KHSO₄ in a porcelain or platinum crueible causing the rhodium to go into solution as already described. The ruthenium remains insoluble.

GRAVIMETRIC METHODS FOR THE DETERMINATION OF RHODIUM

I. The solution containing rhodium is treated with zinc and the residue is washed well with hot water acidulated with HCl. The residue is then cleaned with dilute aqua regia and the black metallic rhodium is filtered off, dried,

and ignited in hydrogen. Cool and weigh as metallic rhodium.

2. The metals may be melted with lead or silver and the buttons dissolved in dilute HNO₃, leaving a residue which is treated with dilute aqua regia to dissolve any platinum that might be present. The residue is treated with salt and chlorine and the melt dissolved in water as described under Iridium. The iridium is precipitated with NH₄Cl and the rhodium with zinc. The rhodium black is cleaned with dilute aqua regia, filtered, washed and ignited. Reduce in hydrogen and weigh as metallic rhodium.

3. The solution containing the rhodium is made alkaline with KOH and then acid with formic acid, boil, and the rhodium will be precipitated as finely divided metallic rhodium. After filtering proceed in the usual manner.

- 4. After the platinum and the palladium are climinated, the residue of Ir, Rh and Ru is fused with KHSO₄ in a porcelain crucible and the melt dissolved in water. Filter, wash with hot water, and after acidulating with HCl the Rh is precipitated with C.P. powdered zinc, hydrogen sulphide gas or both. Filter, wash with hot water and ignite. Clean the residue with dilute HNO₅, then with dilute aqua regia, wash with hot water, ignite in hydrogen and weigh as metallic Rh.
- 5. The residue containing Ir, Rh, Ru and Os is fused with five grams KOH and one gram KNO₃, and the Ru and Os are distilled with chlorine as explained under ruthenium. The solution in the distilling flask is zinced well, filtered, washed and ignited. The residue of impure Ir and Rh is scorified with test lead, the lead button dissolved in dilute HNO₃ and the residue treated with H₂SO₄ as explained under Separation of Rh from Ir. The clear rhodium sulphate solution is treated with C.P. powdered zinc, hydrogen sulphide gas or both, and the precipitate is treated as explained above and weighed as metallic Rh.
- 6. The solution from the distilling flask is zinced well as explained above. The residue is filtered, washed, ignited and boiled with a few cc. of HNO₃ and boiled with H₂SO₄ for one to three hours as explained above. The rhodium sulphate solution is made alkaline with KOH and boiled with alcohol until all the rhodium is precipitated and the solution is clear. Filter, wash with hot water, dilute HNO₃ and again with hot water. Ignite, reduce in hydrogen and weigh as metallic Rh.
- 7. Rhodium is conveniently estimated by precipitation with magnesium from solutions of its salts. The precipitate is washed with dilute H₂SO₄ to remove excess of magnesium, dried, ignited in a current of hydrogen, cooled in carbon dioxide and weighed as metal.¹

¹ Text Book of Inorganic Chemistry, Vol. IX, Part I. J. N. Friend.

OSMIUM

Element, Osmium. Os. at.wt. 190.9; sp.gr. 22.4; m.p. 2700° C.? oxides, OsO, Os₂O₃, OsO₂, OsO₄.

DETECTION

Osmium occurs with platinum ores as a natural alloy with iridium (Osmiridium) and remains undissolved in the form of hard, white metallic-looking grains when the ores are treated with aqua regia. The chlorides, OsCl₂ and OsCl₄, combine with the alkali chlorides. Through the action of HNO₃, aqua regia or heating in a stream of moist chlorine, osmic tetroxide is formed. OsO₄ is very volatile and the fumes are poisonous. It is detected readily by the odor when heated, as the fumes are highly corrosive and disagreeable like chlorine. Chlorine passed over hot osmium mixed with KCl gives K₂OsCl₆, which dissolves in cold water.

The oxy-hydrogen flame oxidizes the metal but does not melt it. When strongly heated in contact with air, the finely divided osmium burns and is converted into OsO₁, commonly called osmic acid.

Osmium monoxide, OsO, is obtained when the corresponding sulphite mixed with sodium carbonate is ignited in a current of carbon dioxide. It is a greyish-black powder insoluble in acid.

The oxide, Os₂O₃, is a black insoluble powder obtained by heating its salts with sodium earbonate in a current of earbon dioxide.¹

Osmium dioxide, OsO₂, is obtained from its salts in a similar way to the foregoing oxides. It is likewise formed when its hydroxide is heated in a current of earbon dioxide.¹

Osmium tetroxide, OsO₄. Very finely-divided metallic osmium oxidizes slowly at the ordinary temperature, and at about 400° takes fire with formation of OsO₄. The denser the metal the higher is the temperature needed for oxidation.¹

Hydrogen sulphide precipitates dark brown osminm sulphide, OsS₂, but only in the presence of some strong mineral acid; from an aqueous solution of osmic acid there forms a dark brownish-black sulphide, OsS₄. These are insoluble in animonium sulphide.

Potassium hydroxide precipitates reddish-brown osmium hydroxide, Os(OH).

Ammonium hydroxide precipitates the osmium hydroxide.

Zinc and formic acid precipitate black metallie osminm.

Hydrogen reduces osmium compounds to the metal.

Potassium nitrite added to a solution of osmic acid reduces it to osmous acid which unites with an alkali forming a beautiful red salt.

Sodium sulphite yields a deep violet coloration and a dark blue osmium sulphite separates out gradually.

Phosphorus reduces osmium from an aqueous solution.2

Mercury precipitates osmium from an aqueous solution of osmic acid mixed with HCl.

Stannous chloride produces a brown precipitate, soluble in HCl to a brown fluid.

1 "Treatise on Chemistry," Roscoe and Schorlemmer.

ESTIMATION

Osmium is estimated mainly in osmiridium and platinum residues.

Preparation and Solution of the Sample

After the platinum is extracted the residue or osmiridium is mixed with two or three times its weight of common table salt. The mixture is put in a porcelain or silica tube and heated to a dull red heat; moist chlorine is then passed through the tube and thence through receivers containing KOH and C₂H₅OH to catch the Os and Ru that pass over. The mass is cooled and dissolved with water. After several treatments the entire group of platinum metals will be in solution.

The osmium material may also be fused with KOH and KNO₃ and the melt dissolved in water. The osmium will be in solution as potassium osmate, K_2OsO_4 , while the iridium remains as residue.

Cold selenie acid has no appreciable action on osmium; at about 120°, however, the metal is dissolved to a colorless solution which contains selenious acid and OsO₄, but no selenate.⁴

Separations

In most eases osmium is separated from the other metals present by distillation or volatilization. See next page.

1 "Chemical Abstracts," April 10, 1918.

GRAVIMETRIC METHODS FOR THE DETERMINATION OF OSMIUM

The osmium is very difficult to ascertain on account of the element being

very volatilc.

1. The potassium osmate, K2OsO4, solution is put in a small retort and boiled with HNO3, the OsO4, is conducted into receivers containing NaOH solution and C₂H₆OH. After acidifying with a little HCl the osmium can be precipitated with Na₂S₂O₃ as a brown precipitate of OsO₄ which is filtered. washed, dried and weighed as the oxide, or reduced in hydrogen and weighed as the metal. The osmate solution from the receivers above is heated gently and strips of aluminum are plunged in; the osmium will be deposited in metallic form, while the aluminum dissolves in the soda. Carc must be taken not to add too much aluminum, as an aluminate might be precipitated which is troublesome. When the solution is discolored, the dense precipitated osmium is washed by decantation with water to remove the sodium aluminate, and then with 5% H₂SO₄ solution to remove the excess aluminum. The osmium is dried in a bell-jar filled with hydrogen, then heated to a dull redness and cooled in a current of hydrogen. The osmium is weighed as the metal. As a cheek the osmium may be driven off in the form of OsO4 by heating to redness with plenty of air, or better, in a current of oxygen and weighing again.1

2. The osmate solution from the condensing receivers or from the fusion of KOH and KNO₃ containing the ruthenium and osmium is placed in a retort and HCl is added. A slow current of air or oxygen is passed through the retort and thence through receivers containing KOH and alcohol similar to the ones mentioned above. These receivers are kept as cold as possible. The osmium is distilled over as OsO₄ while the ruthenium remains in the retort. Combine the solutions in the receivers and proceed to determine the osmium

as described above.

3. The potassium or sodium osmate solution from the receivers above or where osmium tetroxide is dissolved in potassium hydroxide solution and alcohol is heated at 40 or 50° to form potassium osmate. A slight excess of dilute sulphuric acid is added and then 10 cc. more of alcohol in order to prevent reoxidation. After ten or twelve hours, a bluish-black deposit settles, while the supernatant liquid is colorless and free from osmium. The precipitate is filtered, washed with aqueous alcohol, and converted into metallic

osmium by reduction in a current of hydrogen.

4. The residue containing osmium is fused with five grams KOH and one gram KNO₃ in a silver crucible as explained under ruthenium. Add HNO₃ slowly to the distilling flask which is connected to receivers containing NaOH solution and alcohol (10% NaOH and 10% C₂H₃OH). Draw the distillate over gently with the aid of the vacuum, the same as for the chlorine distillation under ruthenium. Continue the HNO₃ until strongly acid and then boil for a short time. Transfer the alkaline solution containing the O₅O₄ distillate to a beaker and pass in hydrogen sulphide gas while the solution is heating until saturation; then add HCl until the solution is distinctly acid and continue to saturate the hot acid solution with hydrogen sulphide gas. Let stand over night, filter through a weighed Gooch crucible, washing well with hot water. Ignite in hydrogen, cool in CO₂ and weigh as metallic O₃.

¹ "Select Methods of Chemical Analysis," Sir Wm. Crookes.

ASSAY METHODS OF PLATINUM ORES, ETC.

Take from 10 to 30 grams of the material and place in a 2½- or 3-in. scorifier with about 20 to 30 grams of test lead and cover with litharge. Fuse in a muffle for a half hour. When cool clean the lead button thoroughly and dissolve the lead with dilute nitric acid (1:5). When the lead is dissolved, filter, and wash the residue with hot water till free from lead. Dry the filter and transfer the bulk of the residue to a small glass beaker. Burn the filter, and add the ash to the main residue. This is treated with dilute aqua regia to remove any gold, platinum, etc., that may be present. Filter and wash thoroughly with hot water and ignite at a low temperature for a short time only, as osmium will volatilize. Weigh as osmiridium. (See Ir and Os.)

Take another portion of 10 to 30 grams of the material and treat with aqua regia two or three times. This will bring the platinum and the alloys (except osmiridium) into solution. After filtering make up the volume to 500 to 1000 ee., depending on the amount of platinum present. Take two or three portions of 25 to 50 ec. of the solution and evaporate to nearly dryness with additions of HCl to get rid of the HNO₃. Take up with a small amount of water and add ammonium ehloride. Digest on the water bath and let eool overnight if convenient. Filter onto an ashless filter and wash with dilute ammonium chloride solution and alcohol. Ignite cautiously and weigh as platinum and iridium sponge. For the determination of iridium see under Iridium.

The filtrate from the platinum precipitation is treated with ferrous sulphate to precipitate the gold. Digest and filter out the gold. Ignite and alloy with silver and part for gold.

In the filtrate from the gold precipitation the palladium and rhodium are treated with zine and HCl until the solution is eolorless. Filter, wash well with hot water and dilute HCl.

Ignite, reduce in hydrogen, cool and weigh as Pd and Rh. Treat with HNO₃. Filter, wash well, ignite and reduce in hydrogen, cool and weigh as metallic rhodium. The difference is palladium, or determine this as described under palladium.

In the revision of the ehapters on platinum, palladium and the other metals of the group a considerable number of suggestions by Dr. Edward Wichers of the U. S. Bureau of Standards, have been included by revising the statements of previous editions. The chemistry of the platinum metals is a field of much variance of opinion and the methods for isolation of these elements are far from perfect. We feel, however, that the chapters present the latest and best work on the subject.—Editor.

	,
•	
Ø	
-	
S OF PLATINUM METALS!	ķ.
	۲,
프	
\mathbf{z}	
Z	
-53	
5	
Н	
-	
닏	,
PH	÷
	٠,
O	
m	
-	
-	
~	
SALTS	
Ö	
v	
KEACTIONS	•
Ö	
×	
۲	
၁	!
<	
7	
×	

• • • • • • • • • • • • • • • • • • •	Ruthenium (RuCla).	Rhodium (RhCl ₄).	Palladium (PdCls).	Osmium (OsCL).	Iridium (IrCL).	Pletinum (PtCI.).
Coloure Hydrogens enlighide	Dark brown	Red	Brownish yellow	Yellow.	Dark brown	Yellow
at 80° C	Azure-blue color on prolonged treatment	Brownish black ppte., Rh ₃ S ₂	Brownish black ppte., PdS	Brownish black Brownish black ppte., OsS. ppte., Ir.S.	Brownish black ppte., Ir,S.	Brownski black ppte., PtS.
	Dark brown ppte., Ru, difficultly sol.	Dark brown ppte., Dark brown ppte., Black ppte., PdS, Dark ppte., in Brown ppte., Ir.S., Brown ppte., PdS, Rh.S., insoluble in excess sol. in excess soluble in excess soluble in excess soluble in excess soluble in excess soluble.	Black ppte., PdS, insoluble in excess	Dark ppte., in- sol. in excess	Brown ppte., Ir ₂ S ₃ , soluble in excess	Brown ppte., Pts soluble in exce
Caustic alkalies	Huner mexcess stocks distributed or desired oxide famour pite. Rh(OH uble in excess.)	Yellow-brown ppte., Rh(OH), soluble in excess	Yellowish brown Brownish red basic salts soluble 0s0, 2H,0 in excess	Brownish red OsO ₂ .2H ₂ O	Green solution Brownish black double chloride	Dark ppte. of PtOr.xHrO
Aramonium* hydroxide on warming	droxide on warm- ing	Slow decolorization Decolorized	Decolorized	Yellowish	ppicer Bright color	Slow decolorization
Saturated * NH,Cl sofittion.	I Brown ppte.	No ppte.	No ppte.	brown ppte. Red ppte.	Black ppte.	Yellow ppte.,
Saturated KCl solution	Violet cryst. ppte. Red cryst. ppte., KRhCls		Red ppte. of K.PdCl.	Brown cryst. ppte, K-OsCl.	Brown cryst. Brownish red ppte.	
(1:1000)	No change	No change	Dark ppte.	No change	Yellow color	Slow red-brown
Hg(CN); solution	No change	No change	White pate., Pd(CN):	No change	No change	No change
KCNS, 1 per cent.	Dark violet color Yellow color	Yellaw color	Unchanged	Unchanged	Decolorized .	Increased yellow
Hydrazine in hydrochloric ² acid	Yellow color	Yellow color	Black ppte., metallic Pd	No change	Yellow color	Black ppte., metallic Pt
Dimethyl * glyoxime Metallic zino	Yellow ppte. Ppte., Ru	No change Ppte., Rh	No change Ppte., Rd	No change Ppte., Os	No change Ppte., Ir	No change Ppte., Pt




PLATE III

POTASSIUM, SODIUM AND OTHER ALKALIES

Sodium, Na, at.wt. 23.00; sp.gr. 0.9735; m.p. 97.6°; b.p. 877.5° C.; oxides Na₂O, Na₂O₂.

Potassium, K, at.wt. 39.10; sp.gr. 0.875; m.p. 62.5°; b.p. 757.5° C.; oxides K_2O , K_2O_4 .

Lithium, Ll, at.wt. 6.94; sp.gr. 0.534; m.p. 186°; b.p. >1400° C.; oxide Ll₄O₄; Rubidium, Rb, at.wt. 85.44; sp.gr. 1.532; m.p. 38.5°; b.p. 696° C.; oxides Rb₂O₂, Rb₂O₂, Rb₂O₄.

Caesium, Cs, at.wt. 132.81; sp.gr. 1.87; m.p. 26.37°; b.p. 670° C.; oxides Cs₂O, Cs₂O₂, Cs₂O₃, Cs₂O₄.

DETECTION

Detection of Sodium

Sodium is usually identified by the color which it imparts to the flame or by means of the spectroscope. The solution is prepared as directed under Preparation and Solution of Sample, and is freed from all constituents other than the chlorides of magnesium and the alkalies according to the methods given under Separations. With exceedingly small amounts of sodium, it may be necessary to remove the magnesium also. After acidifying with hydrochloric acid, a drop of the solution is brought into the flame by means of a loop of platinum wire. In the presence of sodium, the flame assumes an intense yellow color, which is usually sufficient to identify the element. The results may be confirmed by examining the flame in the spectroscope, when the characteristic yellow sodium line will be prominent even in the presence of traces of sodium. The spectrum of sodium is shown on Plate II. As a matter of fact, the ever-presence of the sodium line is a hindrance to the success of the method, but by observing the sudden change in the intensity of the line, little trouble will be experienced in detecting exceedingly small amounts of the metal.

Sodium may also be detected by precipitation as sodium pyroantimonate, $H_2Na_2Sb_2O_7$. H_2O , from a sufficiently concentrated neutral or weakly alkaline solution by means of a solution of acid potassium pyroantimonate. The precipitate comes down in granular or crystalline form, and its formation is hastened by rubbing the sides of the vessel with a glass rod. In making this test, magnesium must also be previously removed from the solution.

In waters and soluble salts, it is usually sufficient to test directly the concentrated solution in the flame or spectroscope.

Chapter contributed by W. B. Hicks.

Detection of Potassium

For the detection of potassium in insoluble compounds, bring the sample into solution by one of the methods given under Preparation and Solution of Sample. In other cases, prepare a strong solution of the material to be tested. Where only very small amounts of potassium are present, remove all the constituents from the solution except the chlorides of magnesium and the alkalies as directed under Separations. In the presence of considerable amounts of potassium, small quantities of other constituents will not materially interfere with the flame and spectroscopic tests. After acidifying with hydrochloric acid, bring a drop of the solution to be tested into the non-luminous flame by means of a platinum wire and observe the color produced through a Merwin color screen. In the presence of potassium, a distinct reddish-violet coloration will be apparent. This must not be confused with the color caused by large amounts of sodium, which appear bluish-violet through the screen. Comparison with the coloration produced by pure salts is advisable. If necessary, confirm the results by examining the flame in the spectroscope. In the presence of a moderate amount of a volatile potassium compound, a bright red line will be readily seen in the red portion of the spectrum, and a less distinct violet line will be visible far out in the violet rays.

Potassium may be identified by precipitation as cobaltic nitrite. For this purpose place a small quantity of the solution to be examined in a test tube, acidify slightly with acetic acid, add about an equal quantity of the sodium nitrite solution, prepared by dissolving 125 grams of sodium nitrite (NaNO₂) in 250 cubic centimeters of distilled water, and about half as much of cobalt nitrate solution, prepared by dissolving 25 grams of cobalt nitrate (Co(NO₃)₂· 6H₂O) in 100 cubic centimeters of distilled water and adding 50 cubic centimeters of concentrated (glacial) acetic acid. Mix and allow the mixture to stand until effervesceuce ceases and the cherry-red solution is transparent. If an appreciable amount of potash is present a yellow precipitate will have settled to the bottom of the test tube. By comparing the volume of the precipitate with that produced when a known quantity of potassium chloride is used, an idea of the amount of potash present can be obtained. Ammonium salts produce a similar precipitate.

Potassium chloroplatinate, perchlorate, acid tartrate, picrate, silico-fluoride, and phospho-tungstate are all sparingly soluble in water while the corresponding sodium salts are readily soluble. Precipitation of these compounds from solution may be used in the identification of potassium.

Silicate rocks and minerals may be tested for potash by mixing the finely powdered material with an equal quantity of pure calcium carbonate, moistening with hydrochloric acid, and examining a small amount of the wet mixture on a platinum loop in the flame.

¹ The Merwin color screens are manufactured and sold by G. M. Flint, 84 Wendell Street, Cambridge, Mass., at 50 cents apiece, and are far superior to the ordinary cobalt glass.

Detection of Lithium

Bring the sample into solution as directed under Preparation and Solution of Sample, and separate the alkali chlorides from other constituents according to the methods under Separations. Digest the dry chlorides with amyl alcohol or with a mixture of absolute alcohol and other, filter, and evaporate the filtrate to dryness. Moisten the residue with dilute hydrochloric acid and examine it in the spectroscope. A bright red band and a faint orange line make up the flame spectrum of lithium Plate II. These lie between the sodium line and the red potassium line and are easily recognized.

Lithium salts impart a carmine-red color to the flame, which is obscured by sodium, and by large amounts of potassium. But by the proper use of a color screen, the lithium flame may be recognized in the presence of large amounts of sodium.

Confirmation of the presence of lithium may be had by the formation of the sparingly soluble lithium phosphate or lithium fluoride.

Detection of Rubidium and Caesium

In the usual course of analysis, these rare elements are separated along with sodium, potassium, and lithium from all other bases. In order to detect rubidium and eacsium, extract the dry chlorides of the alkali metals with a few drops of hydrochloric acid and 90% alcohol. This will dissolve most of the rare alkalies along with some sodium and potassium. Evaporate the solution to dryness, dissolve in a very small amount of water, and add chloroplatinic acid solution. Rubidium, caesium, and potassium chloroplatinates will be precipitated. Filter and wash the residue repeatedly with hot water to remove the potassium salt, which is much more soluble than rubidium and caesium chloroplatinates. During this treatment, examine the residue from time to time in the spectroscope. As the rubidium and caesium salts are concentrated through washing, their spectra will gradually become visible.

The flame spectrum of rubidium consists of two red lines at the extreme left end of the spectrum, 3 orange lines rather close together just to the left of the sodium line, and a narrow and a broad line between the violet and indigo portion of the spectrum.

Caesium has one narrow orange line, one broad yellow line just left of the sodium line, one green line, and two broad blue lines close together.

The spectra of rubidium and caesium are shown on Plate II.

ESTIMATION

The estimation of sodium and potassium is required in the analysis of rocks, clays, soils, ashes of plants, waters, brines, saline deposits, salts of the alkalies, many technical products, and in other cases. The determination of potassium is of special importance in the analysis of fertilizers. The estimation of lithium is desired in the analysis of lithium minerals, frequently in mineral waters, occasionally in rocks, and in certain other special cases. The estimation of rubidium and caesium is seldom required.

Preparation and Solution of Sample

Procedure for Rocks and Other Insoluble Mineral Products. For silicate rocks and other silicious material, bring the alkalies into solution, according to the J. Lawrence Smith or the hydrofluoric acid method, as directed on page 416. For products which are dissolved by hydrochloric acid, effect the solution by acid digestion, expel the excess of acid by evaporation, and remove other constituents as directed under Separations.

Procedure for Soils.¹ Digest 10 grams of moisture-free soil with 100 cc. of hydrochloric acid of a constant boiling-point (sp.gr. 1.115) in a 300-cc. Erlenmeyer flask fitted with a ground-glass or rubber stopper and a reflux condenser. Digest continuously for ten hours on the steam bath, shaking the flask every hour. After settling, decant the solution into a porcelain dish. Wash the insoluble residue onto a filter with hot water, and continue the washing until free from chlorides, adding the washings to the original solution for evaporation. Oxidize the organic matter present in the solution with a few drops of nitric acid and evaporate to dryness on a water bath. Moisten with hydrochloric acid and dissolve in hot water and evaporate a second time to complete dryness and until the excess of hydrochloric acid is completely removed. Moisten the ecoled residue with strong hydrochloric acid and dissolve in hot water. Filter into a 250-cc. graduated flask, wash free from chlorides, and dilute to the mark. Use an aliquot of 100 cc. for the determination of the alkalics.

Procedure for Fertilizers.² Potash salts. Boil 10 grams of the sample with 300 cc. of water for thirty minutes, wash into a 500-cc. graduated flask, eool, dilute to the mark, mix and pass through a dry filter. Determine the potassium in a 25-cc. aliquot representing 0.5 gram of the original substance, according to either the modified chloroplatinate or the Lindo-Gladding method.

Mixed fertilizers. Boil 10 grams of the sample with 300 cc. of water for thirty minutes, and wash into a 500-cc. graduated flask. Add to the hot solution a slight excess of ammonia and sufficient ammonium oxalate to precipitate all the lime, cool, dilute to the mark, mix, and pass through a dry filter. Evaporate

U. S. Dept. Agr., Bu. of Chem., Bull. 107 (revised), 14, 1907.
 U. S. Dept. Agri., Bu. Chem. Bull. 107 (revised), 11, 1907.

50 cc. of the filtrate to dryness and ignite gently to remove ammonium salts. Dissolve in water, filter, and determine the potassium according to the modified chlorplatinate ¹ or the Lindo-Gladding method.

Organic compounds. When it is desired to determine the total potash in organic substances such as cottonseed meal, tobacco stems, etc., saturate 10 grams with strong sulphuric acid, and ignite in a muffle at low red heat to destroy organic matter. Add a little strong hydrochloric acid, warm slightly to loosen the mass from the dish, dissolve in water, filter, and determine the potassium according to the medified chloroplatinate or the Lindo-Gladding method.

If for any reason it is desired to use either the chloroplatinate or the perchlorate method in the determination of potassium, interfering substances, including

sulphates, must first be removed from the solution.

Procedure for Ashes of Plants. Boil 20 grams of the sample with 30C cc. of water for thirty minutes, filter into a 500-cc. flask, and wash the residue thoroughly with hot water. Cool, dilute to the mark and mix. Take aliquots for the determination of the alkalies. The solution may also be prepared by digestion with hydrochloric acid.² This treatment is preferable when all the constituents of the ash are to be determined.

Procedure for Saline Residues, Soluble Salts, Brines, etc. In the case of water-soluble products, the convenience of the analyst usually determines the manner of preparing the solution. Usually it is preferable to weigh out a convenient portion, to make up the solution to definite volume, and to take an aliquot for each determination. As a general rule, a sample should be taken sufficient to give about a half gram of solids. Strong brines should be weighed and not measured.

SEPARATIONS

Separation of the Alkali Metals from other Constituents

Separation from the Hydrogen Sulphide and Ammonium Sulphide Groups of Metals

The alkali metals are usually weighed as chlorides or sulphates, and in general before undertaking their determination, all other bases and acids must first be separated from them. The hydrogen sulphide and the ammonium sulphide groups of metals are seldom to be found in solutions in which the determination of the alkalies is desired. If these are present, however, they may be readily precipitated by means of hydrogen sulphide and ammonium sulphide as detailed on pages 168 and 292.

Separation from Silica

Acidify the solution with hydrochloric acid and evaporate it in a platinum or porcelain dish on the water bath until the odor of hydrochloric acid in the dry residue can no longer be detected. Break up the dry mass with a platinum or glass rod, cool, moisten with a minimum amount of concentrated hydrochloric

² Lunge, "Technical Methods of Analysis," 2, 456, 1911. D. Van Nostrand Co., New York.

¹ If this method is used, it will not be necessary to remove the calcium by addition of ammonia and ammonium oxalate.

406 POTASSIUM, SODIUM AND OTHER ALKALIES

acid, dissolve in a small quantity of water, filter and wash the residuo free from chlorides. In the presence of much silica, repeat the operation.

Separation from Iron, Aluminum, Chromium, Titanium, Uranium, Phosphorie Acid, etc.

If phosphorie acid is present in amounts insufficient to combine with all the iron, alumina, etc., or is absent altogether, heat the solution to boiling, add a few drops of nitric acid to oxidize the iron, add gradually an excess of ammonia, boil for a minute or so, allow the precipitate to settle, and filter. Wash the precipitate free from chlorides with hot water.

If phosphoric acid is present in the solution in excess of that required to combine with the iron, alumina, etc., heat the solution to boiling, oxidize with nitric acid, add a slight excess of ferric chloride solution, and precipitate with ammonia as described above.

When the precipitate is considerable, it should be dissolved in hydrochloric

acid, and the precipitation repeated.

If chromates are present, these must first be reduced to the chromic salt. For this purpose, add 10 to 15 cc. of hydrochloric acid and a small amount of alcohol to the solution and heat on the water bath or hot plate for a few minutes. Heat to boiling and precipitate with ammonia as directed above. The reduction may also be done by boiling with sulphurous acid.

Separation from Sulphates

Precipitate the sulphate radical as BaSO₄ by the addition of a slight excess of barium chloride to the hot solution as directed on page 497 for the determination of SO₄. Remove the excess of barium chloride by addition of ammonia and ammonium carbonate.

The two operations may be combined as follows: Add a slight excess of barium chloride to the hot solution and boil for a few minutes. Then, without filtering off the BaSO₄, add an excess of ammonia and ammonium carbonate, allow the precipitate to settle, filter, and wash free from chlorides.

Separation from Barium, Calcium and Strontium

To the not too concentrated solution, add a slight excess of ammonia and ammonium carbonate, heat to boiling, allow the precipitate to settle, filter and wash the residue a few times with hot water. Dissolve the precipitate, which is likely to contain small amounts of the alkalies, in a little dilute hydrochloric acid, and repeat the precipitation with ammonia and ammonium carbonate. Filter and wash the residue. Evaporate the combined filtrates to dryness in a platinum or porcelain dish and ignite cautiously at a very faint red heat to remove ammonium salts. Dissolve the residue in a little water, add a few drops of ammonia, ammonium carbonate, and animonium oxalate, and allow to stand for several hours in order to precipitate the last traces of the alkaline earths. Filter and wash the residue free from chlorides.

¹ This procedure does not give faultless results as some of the potassium is carried down with the precipitate and lost,

Separation from Iron, Aluminum, Chrominum, Barium, Calcium, Strontium, Phosphates, Sulphates, etc., in One Operation

To the hot solution add a slight excess of barium chloride and boil for a few minutes. Then, without filtering off the BaSO₄, add an excess of ammonia and ammonium carbonate, heat to boiling, and allow the precipitate to settle. Filter and wash free from chlorides with hot water. After evaporating the filtrate to dryness, removing the ammonium salts by ignition, and dissolving the residue in a little water, precipitate the last traces of barium and calcium by addition of a few drops of ammonia, ammonium carbonate, and ammonium oxalate. By this procedure a small portion of the alkalies is retained by the precipitate and lost.

Separation from Boric Acid

Acidify the solution strongly with hydrochloric acid and evaporate to dryness. Stir up the residue with 15 to 20 cc. of pure methyl alcohol and caniously evaporate on a water bath at not too high a temperature. Moisten the esidue with a drop or two of concentrated hydrochloric acid, add 15 cc. of methyl leohol, and again take to dryness. Repeat the evaporation with methyl alcohol, third time. This should be ample for the complete removal of half a gram f B-O₂.

Separation from Magnesium

Mercuric Oxide Method. After removing other bases and acids, evaprate the solution of the chlorides to dryness, expel anumonium chloride by entle ignition, and dissolve the residue--except for the small amount of magesium oxide present-by warming with a little water. Add an excess of merurie oxide in the form of a thin paste prepared by shaking up freshly precipiated mercurie oxide in water. Evaporate the mixture to complete dryness on ie water bath with frequent stirring, dry thoroughly and ignite gently at first ad then more strongly until all the mercuric chloride present has been volatilized. Be careful not to inhale the finnes.) The whole of the unchanged mercuric oxide sed not be expelled by ignition. Digest the residue, composed of the excess of ercurie oxide, the precipitated magnesium oxide, and the alkali chlorides, with small amount of hot water, filter rapidly, and wash with successive portions hot water, first by decantation and then on the filter, but do not prolong the peration unnecessarily. If desired, determine the magnesium in the residue by pelling the mercuric oxide by ignition and weighing the magnesium oxide. cidify the filtrate, which contains the alkalies, with hydrochloric acid, evaporate dryness, gently ignite, cool and weigh. If the residue contains a small aount of magnesium, as it usually does, determine the magnesium in an aliquot d apply the necessary correction. The mercuric oxide should be tested for kalies by volatilizing a portion and testing the residue.

The Barium Hydroxide Method. Evaporate the solution, which may conin chlorides, sulphates or nitrates, to dryness and gently ignite to remove amonium salts. Warm the residue with a small amount of water and treat e hot neutral solution so obtained with baryta water until no more precipitate formed and barium hydroxide remains in slight excess. Boil, filter and wash

¹ Fresenius, "Quantitative Chemical Analysis," 1, 610, 1908, John Wiley & Sons, w York.

408 POTASSIUM, SODIUM AND OTHER ALKALIES

the precipitate with hot water. If desired, determine the magnesium in the residue. Treat the filtrate, which contains the alkalies, barium and a trace of magnesium, with an excess of ammonia and ammonium earbonate to remove the barium. Acidify the filtrate with hydrochloric acid and evaporate to dryness, ignite and weigh. This residue will contain a small amount of magnesium which may be determined in an aliquot and a correction applied.

Remark. The barium hydroxide method is applicable in the presence of lithium.

The Ammonium Phosphate Method.¹ To the hot solution, add an excess of ammonia and ammonium chloride, and precipitate the magnesium by adding a slight excess of ammonium phosphate. Allow the mixture to stand an hour or so, filter and wash the residue with 2% ammonia solution. Expel most of the free ammonia from the filtrate by evaporation, acidify very slightly with hydrochloric acid, and add an excess of ferric chloride solution, which should color the solution slightly yellow. Neutralize the solution with ammonium earbonate, heat to boiling, and filter off the basic ferric phosphate, washing the residue with hot water. Evaporate the filtrate to dryness, ignite to expel an monium salts, and determine the alkalies in the residue. Magnesium may also be separated by precipitation as magnesium ammonium arsenate ² or magnesium ammonium earbonate.¹

Separation of the Alkali Metals from One Another

Separation of Sodium from Potassium

After weighing the sodium and potassium together as chlorides, dissolve the residue in water and precipitate the potassium as chloroplatinate or perchlorate according to one of the methods detailed under Determination of Potassium.

Separation of Lithium from Sodium and Potassium

Extract the dry chlorides with anyl alcohol as prescribed under the Gooch method, or with alcohol saturated with hydrochlorie acid gas as detailed under the Rammelsberg method.

Separation of Lithium and Sodium from Potassium, Rubidium, and Caesium

Precipitate the potassium, rubidium, and caesium as chloroplatinates as described under the chloroplatinate method for the estimation of potassium. Evaporate the filtrate to dryness and ignite gently with a little oxalic acid to reduce the platinum, or else dissolve the residue in water and pass a current of hydrogen through the hot solution to reduce the platinum. In any case, filter off the reduced platinum and determine lithium and sodium in the filtrate.

¹ Fresenius, op. cit.

² Browning and Drushel, Am. J. Sci. (4), 23, 293, 1907.

METHODS FOR DETERMINATION OF SODIUM Determination as Sodium Chloride

Sodium is commonly weighed as NaCl when it is already present as such or after conversion of other forms into the chloride. In the case of salts of volatile acids, such as nitrates for instance, the transformation is made by evaporating the solution to dryness with hydrochloric acid repeatedly or until only the chloride remains. When the sodium is present as a salt of a non-volatile acid, the latter is removed and the transformation effected according to the methods under Separations.

Usually the solution in which sodium chloride is to be determined will contain ammonium salts from some previous operation. In such cases, proceed as follows: Evaporate the sodium chloride solution, which must contain no other non-volatile substance, in a platinum dish to complete dryness on the water bath. Cover the dish with a watch-glass, and cautiously dry the residue in an air bath at 110 to 130° C. Make sure that no loss of sodium chloride is sustained by decrepitation during drying and subsequent ignition. Heat the dish and contents over a free flame held in the hand and moved back and forth under the dish in order to remove animonium salts. But to avoid loss of sodium chloride by volatilization, take care not to heat the dish to more than a faint redness in any one spot and not to raise the temperature of the salt above incipient fusion. 'Cool the residue, dissolve it in a little water, and filter from the carbonaceous matter into a weighed platinum dish. Acidify the filtrate with hydrochloric acid and evaporate it to dryness on the water bath. Dry the residue at 100 to 130° C. in an air bath, ignite cautiously over a free flame, taking the precautions mentioned above to prevent loss of sodium chloride, cool in a desiccator, and weigh.

Determination as Sodium Sulphate

Sodium is often determined by weighing as Na₅O₄ when it is present as such or after conversion of other forms into the sulphate. In the case of salts of volatile acids, the change into the sulphate is made by simply evaporating the solution with a slight excess of sulphuric acid. With salts of non-volatile acids, the transformation is effected according to the methods under Separations. When the sodium is present as an organic salt, the substance is moistened with concentrated sulphuric acid and carefully heated over a free flame nutil fumes cease to come off. The residue is dissolved in water and filtered from the carbonaceous matter.

As a rule the solution in which sodium sulphate is to be determined will contain an excess of sulphurie acid. In such cases, evaporate the solution to dryness in a weighed platinum dish, and cautiously ignite the dry residue until fumes cease to come off. Cool, add a lump of ammonium earbonate to the contents of the dish, and ignite a second time at dull red heat until no more fumes are given off. Cool in a desiccator and weigh as Na₂SO₄. Repeat the ignition with the addition of ammonium carbonate until a constant weight is obtained.

In ease an excess of sulphuric acid is not present, evaporate the solution to dryness in a weighed platinum dish, ignite, cool in a desiccator and weigh as Na₅SO₄.

Determination by Difference

Ordinarily sodium and potassium are weighed together as chlorides or sulphates as detailed above for sodium. Potassium is then determined by one of the methods given below, and the value for sodium obtained by difference.

METHODS FOR DETERMINATION OF POTASSIUM

Determination as Potassium Chloride or Potassium Sulphate

Potassium may be weighed as chloride or sulphate. The procedure is the same as that described for sodium. Observe, however, that the potassium salts are a little more volatile than the corresponding sodium salts, so that greater care must be taken not to lose potassium by volatilization.

The Chloroplatinate Method

Application. This method is applicable in the presence of the chlorides of sodium, lithium, magnesium, calcium, and strontium.

Principle. Potassium chloroplatinate is practically insoluble in strong alcohol while the other chloroplatinates are readily soluble.

Procedure. Treat the aqueous solution of the alkali chlorides contained in a small porcelain dish with slightly more than enough chloroplatinic acid to convert all the chlorides present into the corresponding chloroplatinates. The chloroplatinic acid solution should contain the equivalent of 1 gram of platinum in each 10 cc. Evaporate the solution on the steam bath to a syrupy consistency, i.e., until solidification occurs on cooling. Flood the cooled residue with a small quantity of alcohol of at least 80% strength, grind thoroughly with a postle made by enlarging the end of a glass rod, and allow to stand one-half hour. Pour the liquid through a previously weighed Gooch crucible containing an asbestos mat, and before adding more alcohol, rub up the residue again with the glass pestle. Now continue the washing by decantation with small portions of alcohol until the wash liquid becomes colorless. Transfer the precipitate to the erucible and wash two or three times with alcohol. Dry at 130° C., cool in a desiccator, and weigh. Repeat the drying until a constant weight is obtained. Multiply the weight of K2PtCle by 0.161 to obtain the weight of K; by 0.194 to obtain K2O; and by 0.307 to obtain KCl.

Remarks. This method is considered to be the most accurate known for the estimation of potassium. Care should be taken not to conduct the evaporation at too high a temperature nor let it go too far, as this may cause the formation of anhydrous sodium chloroplatinate, which dissolves slowly in alcohol. Too large a volume of alcohol for washing should be avoided, as K₂PtCl₃ is slightly soluble in alcohol, especially that of 80%. For this reason 95% alcohol is preferable for the washing.

Instead of using a Gooeh crucible, the precipitate may be filtered on paper, dried, washed through the filter with hot water into a weighed platinum dish, evaporated to dryness, and heated at 130° C. to constant weight.

¹ For methods of preparing chloroplatinic acid from scrap platinum and from platinum residues, see Precht, Z. Anal. Chem., 18, 509, 1879; Vogel and Haefeke, Landw. Vers. Sta., 47, 134, 1896.

The Modified Chloroplatinate Method 1

Application. The method is applicable in the presence of chlorides, sulphates, phosphates, nitrates, carbonates, borates and silicates, salts of sodium, barium, calcium, strontium, magnesium, iron and alumina, and is especially suited for the estimation of potassium in salines, potassium salts, and fertilizers in which only the potassium is desired.

Principle. On evaporating a solution containing potassium with a slight excess of chloroplatinic acid, the potassium is completely transformed into potassium elloroplatinate which is insoluble in strong alcohol, while any of the other chloroplatinates which may be formed are either dissolved or decomposed by alcohol, so that the excess of chloroplatinic acid may be readily removed. After dissolving the K₂PtCl₄ along with any other soluble salts contained in the residue in hot water, the platinum is precipitated from the solution by magnesium, and from the weight of platinum so obtained, the amount of potassium present is enleulated.

Procedure. To the solution slightly acidified with hydrochloric acid, add chloroplatinic acid solution slightly in excess of that necessary for the complete precipitation of the potassium present and evaporate the solution on the steam bath to a syrupy consistency, i.e., until solidification occurs on eooling. Flood the cooled residue with a small quantity of alcohol of at least 80% strength, grind thoroughly with a pestle made by enlarging the end of a glass rod, and allow to stand one-half hour. The alcoholic solution should be colored if an excess of chloroplatinic acid has been used. Pour the liquid through a small filter, using suction if desired, and before adding more alcohol, rub up the residue again with the pestle. Now continue the washing by decantation with small portions of alcohol until the wash liquid becomes colorless. Three or four washings usually suffice. Transfer the precipitate to the filter and wash two or three times with alcohol.

Dissolve the precipitate of K_2PtCl_6 along with any other soluble salts present in hot water, washing it through the filter into a beaker of convenient size. To the hot solution add about 4 ec. of concentrated HCl and approximately 0.5 gram magnesium ribbon pressed into the form of a ball for every 0.2 gram potassium present, stirring the solution and holding the magnesium at the bottom of the beaker by means of a glass rod. A lump of stick magnesium weighing about 0.4 gram is preferable to the ribbon. When the action has practically ceased, add a few ec. of hydrochloric acid and allow the fluoceulent platinum to settle, preferably by allowing the beaker to set for an hour on the hot plate. The supernatant liquid should be perfectly clear and limpid like water if reduction is complete. To make sure, add more magnesium, in which case the solution will darken if reduction be incomplete. To the completely reduced solution, add concentrated hydrochloric acid, and boil to dissolve any basic salts, filter on paper or a Gooch, wash thoroughly with hot water, ignite in platinum or porcelain and weigh. Pt×.4006=K or ×.4826= K_2O .

Remarks. If the solution contains very large amounts of iron, alumina, or silica, it is perferable to remove the greater part of these before proceeding to the determination of potassium. Care should be taken to insure the complete removal of the soluble chloroplatinates from the residuc without the use of an

¹ Hicks, J. Ind. Eng. Chem., 5, 650, 1913.

excessive amount of alcohol, and also that the subsequent reduction of the potassium chloroplatinate with magnesium be complete.

Lindo-Gladding Method 1

Application. This method is applicable in the presence of chlorides, sulphates, and phosphates of the alkalies and magnesium.

Principle. The potassium is precipitated as K₂PtCl₆, and the soluble chloroplatinates removed by washing with 80% alcohol. The impurities in the precipitate are then washed out by a strong solution of ammonium chloride saturated with K₂PtCl₆, and the wash solution is removed by again washing with alcohol. The purified K₂PtCl₆ is finally dried and weighed.

Procedure. To the solution, slightly acidified with hydrochlorie acid, add an excess of chloroplatinic acid solution, and evaporate on the water bath to a thick paste. Treat the residue with 80% alcohol, avoiding the absorption of ammonia. Wash the precipitate thoroughly with 80% alcohol both by decantation and on the filter, continuing the washing after the filtrate is colorless. Wash finally with 10 cc. of anunonium chloride solution prepared as follows: Dissolve 100 grams of pure anunonium chloride in 500 cc. of water, add from 5 to 10 grams of potassium chloroplatinate, and shake at intervals of six to eight hours. Allow the mixture to settle over night and filter. Repeat the washing with successive portions of the ammonium chloride solution five or six times in order to remove the impurities from the precipitate. Wash again thoroughly with 80% alcohol, dry for thirty minutes at 100° C. and weigh as K₂PtCl₆. The precipitate should be perfectly soluble in water. Multiply the weight of K₂PtCl₆ by 0.161 to obtain the weight of K; by 0.194 to obtain K₄O; and by 0.307 to obtain KCl.

The Perchlorate Method²

Application. This method is applicable in the presence of chlorides and nitrates of barium, calcium, magnesium and the alkali metals, and also in the presence of phosphates. Sulphates should not be present.

Principle. The separation depends on the insolubility of potassium perchlorate, and the solubility of sodium and other perchlorates in 97% actohol.

Procedure. To the neutral or slightly acidified solution, add twice as much perchlorie acid as is required to convert all the bases present into perchlorates and evaporate on the water bath with stirring to a syrupy consistency. Add a little hot water and continue the evaporation with constant stirring until all the hydrochloric acid is expelled and heavy funes of perchloric acid are given off. Avoid excessive loss of perchloric acid. Stir up the cooled mass thoroughly with 20 cc. of 97% alcohol to which 0.2% perchloric acid has been added, but avoid breaking up the potassium perchlorate crystals too finely or else they may pass through the filter. Allow the mixture to settle, and decant the alcohol off through a Gooch crucible. Repeat the washing once by decantation and then warm to remove the alcohol. Dissolve the residue in hot water, add about a half gram of perchloric acid and evaporate again until fumes of perchloric acid are given off. Wash the residue once by decantation and then several times on the filter. Remove the adhering wash-liquid by washing with pure 97% alcohol, dry at 130° C., and weigh. Multiply the weight of KClO₄ by 0.2825 to obtain the weight of K; by 0.3402 to obtain K₂O.

¹ U. S. Dept. Agri., Bu. Chem. Bull. 107 (revised), 11, 1907.

¹ Wense, Zeit. Angew. Chem., 691, 1891; 233, 1892. Caspari, Zeit. Angew, Chem., 68, 1893.

Other Methods

Among the more important of other methods which have been proposed and used for the determination of potassium, may be mentioned the cobaltinitrite method,1 which has been studied by the Association of Official Agricultural Chemists and considered to be unreliable; 2 the bitartrate method; 3 the colorimetric method; 4 and the spectroscopic method.5

Determination of Sodium and Potassium by Indirect Method

After removing all other constituents, weight he sodium and potassium as chlorides. Dissolve the weighed residue in water and determine the chlorine gravimetrically by precipitation as AgCl or volumetrically by titration with standard silver nitrate (potassium chromate indicator). From the weight of the combined salts and the weight of the chlorine, calculate the amount of sodium and potassium as follows:

Let x = weight of NaCl + KCly =weight of Cl. Then Na = 3.004y - 1.428x; K = 2.428x - 4.004y.

The method is satisfactory when sodium and potassium are present in about equal quantities.

Determination of Magnesium, Sodium and Potassium in the Presence of One Another

In the usual course of analysis, magnesium, sodium and potassium are separated as chlorides from all other constituents. Instead of going through the tedious process of separating the magnesium from the alkalies, the magnesium, sodium, and potassium may be accurately determined in the presence of each other as follows:

Treat the solution containing these constituents with slightly more than enough sulphuric acid to convert all three bases into sulphates, evaporate it to dryness on the water bath, and ignite gently at first and then at dull red heat to break up bisulphates and expel the excess of sulphuric acid. To hasten the decomposition of the bisulphates, cool, add a lump of ammonium carbonate, and heat a second time. Cool in a desiceator and weigh. Repeat the heating with the addition of ammonium carbonate until a constant weight is obtained. Dissolve the residue in water and dilute to definite volume. Determine the potassium in one portion according to one of the methods described above, and the magnesium in a second portion as described on page 293. Deduct the weight of magnesium and potassium sulphates from the weight of the combined sulphates to obtain the amount of sodium sulphate.

Addie and Wood, J. Chem. Soc., 77, 1076, 1900; Drushel, Am. J. Sci. (4), 24, 433, 1907; 26, 329, 555, 1908; Bowser, J. Am. Chem. Soc., 33, 1752, 1911.
 U. S. Dept. Agri. Bu., Chem., Bull. 132, 137, 152, 159.
 Bayer, Chem. Zeit., 17, 686, 1893.
 Cameron and Failyer, J. Am. Chem. Soc., 25, 1063, 1903; Hill, J. Am. Chem. Soc., 26, 1063,

Gooch and Hart, Am. J. Sci. (3), 24, 448, 1891.

METHODS FOR DETERMINATION OF LITHIUM

Determination as Lithium Chloride

Lithium may be weighed as LiCl. The procedure is practically the same as that described for sodium, but since lithium chloride is very hygroscopie, this salt must be weighed out of contact with the air. For this purpose the lithium chloride is ignited in a platinum crucible, cooled in desiceator, and the crucible and contents weighed in a glass-stoppered weighing bottle.

Determination as Lithium Sulphate

Lithium is weighed preferably as Li₂SO₄. The procedure is the same as that described for sodium, but since lithium bisulphate is easily broken up on heating, it is not necessary to ignite with ammonium carbonate.

The Gooch Method 1

Principle. Lithium ehloride is readily soluble in anyl alcohol, while sodium and potassium ehlorides are not.

Procedure. Concentrate the solution as far as possible by evaporation. transfer it to a 50-ee. Erlenmeyer flask, add a small amount of amyl alcohol and heat cautiously on an asbestos plate until the water has been expelled and the boiling-point of the solution rises to about that of pure amyl alcohol (132° C.). To prevent bumping during this treatment, pass a current of dry air through the solution. When all the water has been removed, the sodium and potassium chlorides, together with some LiOH will separate from the solution. Decant the solution through a filter and wash the residue several times with hot amyl alcohol. Moisten the residue with dilute hydrochloric acid, dissolve in a little water and repeat the extraction with amyl alcohol. If much lithium chloride is present, it will be necessary to repeat the extraction with amyl alcohol three or four times. Evaporate the combined filtrates and washings to dryness and dissolve in a little dilute sulphurie acid. Filter from the carbonaceous matter into a weighed platinum dish, evaporate to dryness, and remove the excess of sulphuric acid by gentle heating. Ignite the residue at dull redness, cool in a desiceator. and weigh as Li₂SO₄.

. Remarks. For very accurate work, account must be taken of the fact that the lithium sulphate obtained according to the procedure just described always contains small amounts of potassium and sodium sulphates, if these metals were originally present. To correct for this, deduct 0.00041 gram for every 10 ec. of the filtrate exclusive of the washings in case only sodium chloride was present, or 0.00051 if only potassium chloride was present, and 0.00092 if both sodium and potassium chlorides were present.

¹ Proc. Am. Acad. Arts. Sci., 22 (N. S. 14), 177, 1886.

415

The Rammelsberg Method 1

Principle. Anhydrous lithium chloride is soluble in equal parts of alcohol and ether which have been saturated with hydrochloric acid gas, while the chlorides of sodium and potassium are practically insoluble in this mixture.

Procedure. Evaporate the solution of the chlorides to dryness in a small flask provided with a two-hole stopper. During the evaporation, pass a current of dry air through the flask. Place the flask containing the dry residue in an oil or air bath and heat for half an hour at 140 to 150° C., during which time pass dry hydrochloric acid gas through the flask. Cool in a current of hydrochloric acid gas, treat the residue with a few cc. of absolute alcohol which has been saturated with hydrochloric acid gas, and add an equal volume of absolute ether. Close the flask tightly and allow it to stand with frequent shaking for twelve hours. Pour the solution through a filter, wet with the alcohol-ether mixture and wash the residue three times by decantation with the alcohol-ether mixture. Add a few more ec. of the alcohol-ether saturated with hydrochloric acid gas to the contents of the flask and allow to stand again for twelve hours. Pour the liquid through a filter, and wash the residue by decantation with the alcoholether mixture until the residue tested in the spectroscope shows the complete absence of lithium. Carefully evaporate the combined alcohol-ether extract to dryness on a lukewarm water bath. Dissolve the residue in sufficient dilute sulphurie acid to convert all the lithium into the sulphate, transfer the solution to a weighed platinum dish, evaporate to dryness on the water bath, and finally ignite gently. Cool the residue in a desiccator and weigh as lithium sulphate.

Note. Lithium may also be precipitated and weighed as Li₁PO₆, or it may be precipitated as LiF³ and then changed into the sulphate and weighed.

Spectroscopic Method 4

Dissolve the lithium salt containing small amounts of sodium and potassium resulting from the separation by the Gooch or Rammelsberg methods in 5 or 10 cc. of water, depending on the amount of lithium present. Gradually add measured amounts of this solution to a known volume of water—testing the solution from time to time in the spectroscope—until the lithium line appears. When only traces of lithium are present, it is better to dissolve the lithium salt in a little water and dilute to the vanishing point of the lithium line. Make the spectroscopic examination as follows: Prepare a loop by winding a platinum wire four times around a No. 10 wire. Plunge the loop into the solution, and remove with the axis parallel to the surface of the water. Evaporate the drop to-dryness carefully, ignite in the Bunsen flame, and observe through a good spectroscope.

Before undertaking the determination, standardize the instrument and platinum loop by carrying out the determination with known amounts of lithium.

The method gives satisfactory results when only an approximation is desired. For weighable amounts of lithium, the Gooch method is preferable.

is included in this bulletin.

Treadwell, "Analytical Chemistry," 2, 55, 1911. John Wiley & Sons, N. Y.
 Mayer, Ann. Chem. Pharm., 98, 193, 1856. Merling, 3 Anal. Chem., 18, 563,

³ Carnot, 3 Anal. Chem., 29, 332, 1890. ⁴ Skinner and Collins, U. S. Dept. Agri. Bu. Chem., Bull. 153. A good bibliography

Determination of Sodium, Potassium, and Lithium in the Presence of One Another

Weigh the combined bases as sulphates, observing the precautions detailed under Determination of Sodium, dissolve in water and dilute to definite volume. In one portion determine the potassium and in a second portion determine the lithium by the Gooch or Rammelsberg method. Obtain the value for the sodium by difference.


Determination of the Alkalies in Silicates

J. Lawrence Smith method 1

Principle. By heating the substance with 1 part animonium chloride and 8 parts calcium carbonate, and leaching the sintered mass with water, the alkalies are obtained in solution in the form of chlorides along with some calcium, while the remaining metals are for the most part left behind as insoluble oxides, and the silica is changed to calcium silicate.

Procedure. Triturate 0.5 gram of the finely powdered mineral with an equal quantity of pure ammonium chloride in an agate mortar, add 3 grams of precipitated calcium carbonate 2 and mix intimately with the former. Transfer the

mixture to a platinum crucible (preferably the J. Lawrence Smith alkali crucible), rinsc the mortar with 1 gram of calcium carbonate and add to the contents of the crucible. Place the covered crucible in a slightly inclined position with the top protected from the heat of the flame This can be done by setting the crucible in a hole in a cylinder of fire clay, as shown in Fig. 56. Gradually heat the crucible over a small flame until no more ammonia is evolved, but avoid heating sufficiently to cause the evolution of ammonium chloride. This should require about fifteen minutes. Then raise the temperature until finally the lower three-fourths (and no inore) of the crucible is brought to a red heat, and maintain this tem-



perature for one hour. Allow the crucible to cool and remove the sintered cake by gently tapping the inverted crucible. Should this not be possible, digest the mass a few minutes with water to soften the cake, and then wash it into a large porcelain or platinum dish. Heat the covered dish with 50 to 75 cc. of water for half an hour, reduce the large particles to a fine powder by rubbing

¹ Am. J. Sci. (3), 1, 269, 1871; Hillebrand, U. S. Geol. Survey Bull. 422, 171, 1910.

² Blank determinations should be run on the calcium carbonate, and corrections made for its alkali content.

with a pestle in the dish, and decant the clear solution through a filter. Wash the residue four times by decantation, transfer it to a filter, and wash with hot water until a few cc. of the washings give only a slight turbidity with silver nitrate. To make sure the decomposition of the mineral has been complete, treat the residue with hydrochloric acid. No trace of undccomposed mineral should remain undissolved.

The aqueous extract obtained in the above operation contains the chlorides of calcium and the alkalies. To remove the calcium, treat the solution with ammonia and ammonium earbonate, heat to boiling, filter and wash the residue. As this precipitate invariably retains some alkali salts, it should be dissolved in hydrochloric acid and the precipitation repeated. Evaporate the filtrate to dryness in a platinum or porcelain dish, and expel the amnionium salts by gentle ignition over a moving flame. After cooling, dissolve the residue in a little water, and add a few drops of ammonia and ammonium oxalate to remove the last trace of calcium. After standing several hours, filter off the calcium oxalate, receive the filtrate in a weighed platinum dish, evaporate to dryness and ignite gently to remove aminonium salts. Moisten the cooled mass with hydrochloric acid to transform any carbonate into chloride, and again evaporate to dryness and ignite. Cool in a desiceator and weigh the combined chlorides. Dissolve in water, and if an insoluble residue remains, filter off, weigh and deduct from the weight of the chlorides. Determine the potassium by one of the methods already described, and obtain the value for sodium by difference.

The Hydrofluoric Acid Method

Weigh out a half-gram sample of the finely powdered mineral, place in a small platinum dish or a large platinum crucible, moisten with a few drops of water, and add about 10 cubic centimeters of hydrofluoric acid and about 2 cubic centimeters of dilute sulphuric acid. Hold the dish with the tongs and heat it and its contents cautiously over the free flame for a few minutes. Evaporate the solution on the steam bath to complete dryness, and during this evaporation agitate the solution occasionally by giving the dish a gyratory motion with the tongs. This treatment is nearly always sufficient to decompose the mineral, but if decomposition seems incomplete add more hydrofluoric acid and evaporate a second time, agitating the mixture frequently. With refractory silicates it may be desirable to digest the mineral with the acid mixture in a covered crucible for an hour or so. Heat the dish and its contents on a radiator to expell the excess of hydrofluoric and sulphuric acids. Cover the residue with dilute hydrochloric acid and digest on a steam.bath until solution is complete, adding more water and acid if necessary. Flakes of organic matter which remain undissolved may be neglected. Remove the iron, alumina, calcium, etc., by the methods described under "Separations." Finally weigh the magnesium, sodium, and potassium as sulphates as described on page 413 and determine the potassium according to the modified chloroplatinate or Lindo-Gladding method. An alternative procedure is to remove sulphates and magnesium also as described under "Separations," weigh the alkalies as chlorides, and determine the potash by any of the methods already described. It should be noted however that potash is carried down with barium sulphate, and the loss thus occasioned may be appreciable.

¹ Hillebrand, W. F., U. S. Geol. Survey Bull. 422, p. 31, 1910 (reprinted, 1916). A large porcelain crucible serves well as a radiator for this purpose.

418 POTASSIUM, SODIUM AND OTHER ALKALIES

Test for Hydroxide. A small amount of the material dissolved in CO₂ free water is treated with an excess of BaCl₂ solution and filtered. Phenolphthalein added to the filtrate will produce the characteristic red color if an alkali hydroxide is present in the sample.

Sodium Chloride, Table Salt

U. S. Standard Specifications. Table salt must contain not over

Barium chloride	0.05%
Calcium and magnesium chlorides	0.5%
Calcium sulphate	1.4%
Water insoluble matter	

In addition to these impurities, salt frequently contains combined Fe₂O₃, Al₂O₅, K₂O, P₂O₅, CO₂.

Outline of Method for Examination

Moisture. A 10 gram sample is dried to constant weight at 100° C. and the loss of weight noted.

Insolubles in Water. A fifty gram sample is dissolved in 200 cc. of water and filtered on a weighted, dry filter paper. The residue is washed five times with small portions of water and then dried at 100° C. for an hour. The increased weight = water insolubles. It is advisable to run side by side a second filter, which is washed and also dried in the same way, the paper being used as a tare weight.

The filtrate from the insoluble matter is diluted to exactly 500 cc. in a volumetric flask and used for the following tests.

Sulphur Trioxide. 100 ec. of the above solution equivalent to 10 grams of sample is oxamined for SO₂ by addition of BaCl₂ sol. and the BaSO₄ filtered off and weighed.

Barium. If SO₃ is present above, Ba will not be found in the solution. If SO₃ is absent, test for Ba by addition of H_2SO_4 to 100 cc. of the solution, by the standard procedure. BaSO₄ × 0.8923 = BaCl₂.

Lime. After removal of Fe₂O₃ and Al₂O₃ by addition of NH₄OH (100 cc. solution) CaO is determined by precipitation as oxalate by regular method.

Magnesia. MgO is determined in the filtrate from CaO by concentrating this and precipitating phosphate salt as usual.

.P₂O₅. This is determined by precipitation as ammonium phosphomolybdate according to the standard procedure. $(NH_4)_2HPO_4.12MoO_3 \times .038 = P_2O_5$.

Fe₂O₄ and Al₂O₅. Determined on a 10-gram sample. See page 69. If Fe₂O₄ alone is desired determine colorimetrically. (See page 258.)

Alkalies in Alunite. The ore is mixed with pure silica and is run by the J. L. Smith method.

Alkalies Volumetric Determination. Sce chapter in Vol. 2.

RADIUM

Ra, at.wt.225.95;m.p. about 700 degrees C.; half period 1580 yr.; chloride RaCl₂.

In 1895 Roentgen discovered X-rays. In the following year Becquerel, while studying the phosphorescent properties of some potassium uranium salt which he had prepared about fifteen years before, noticed that it was capable of producing an effect on a photographic plate without exposure to light. The plate was wrapped in several thicknesses of black paper, being perfectly opaque to ordinary light, and then placed with the uranium salt in a dark chamber. Pictures of coins and other articles were made in this way. These effects were found to be due to radiations from the disintegration products of ordinary uranium. Uranium decomposes in succession into the following products: Uranium X1, Uranium X2, Uranium II, Ionium, Radium, Emanation, Radium A, Radium B, Radium C, Radium D, Radium E, Radium F (polonium), Radium G (lead). There are about thirty-five members in the three radioactive families—uranium, thorium, and actinium. Uranium and thorium are the only ordinary elements that are strongly radioactive. Potassium and rubidium give off some beta radiation. The actinium series scems to be a side chain of the uranium family.

The Curies discovered radium in 1898. It is the most important of the radioactive elements.

Kinds of Radiation. Three kinds of radiation are emitted by the various radioactive substances: alpha (α) particles, beta (β) particles, and gamma (γ) rays. Rutherford showed that the alpha particles are doubly positively charged helium atoms. They have an initial velocity of from 1/20 to 1/15 that of light. The beta praticles are singly charged atoms of negative electricity, commonly known as electrons. They have an initial velocity from some substances approaching that of light. The gamma rays are very short waves in ether, and therefore have the general properties of light. They resemble X-rays but are much shorter than any X-rays that have yet been produced. They also have a much higher penetrating power. On account of the very high electrical effects of these radiations and also on account of the extremely small quantities of some of the radioactive substances it is necessary to depend for their detection and determination on the electroscope. The rays ionize the air and this discharges the electroscope.

The Lind instruments, made by the Sachs-Lawlor Company of Denver, Colorado, and distributed by the Denver Firc Clay Company of Denver, are very satisfactory for radium determinations. These instruments may be obtained from any laboratory supply house. Methods for the determination of radium are found in the second volume.

Chapter contributed by L. D. Roberts.

Detection

Radium discharges the electroscope of the alpha ray instrument. However, other radioactive elements do also. There are only three elements that give a gas called emanation as a product. These elements are actinium, radium and thorium. They can all be distinguished by collecting the gas and observing its rate of decay. The time required for one half of the gas to decay is known as the half-period. The half-period of actinium emanation is 3.9 sec., radium emanation 3.85 days, thorium emanation 54 sec. In preparing samples for the alpha ray test they should be ground to about the same mesh. If the sample causes the leaf to move faster than it moves when the chamber is empty, the specimen is radioactive. The time is taken with a stop-watch.




Fig. 56a.

Estimation

Radium is determined by the following methods: I, Alpha Ray; II, Emanation; III, Gamma Ray. The determination with the alpha ray instrument is only approximate and depends on having the samples in the same physical condition as much as possible. The discharge of the leaf is influenced by the fineness of the sample. Also the compound that the element is found in makes a difference. The emanating power of radium chloride is greater than that of radium sulfate, or oxalate. This method is used in the mining camps because it is simple and requires very little equipment. The emanation method is more accurate and is usually used at the plant and laboratory. The


gamma ray method is used when the sample cannot be removed from its container, and also for very high grade material. Tubes of emanation prepared for therapeutic use are determined in this way.

The Alpha Ray Method

The alpha ray instrument consists of an electroscope head A (Fig. 56a) and the chamber B. Head A contains an aluminum or gold leaf attached to a metal rod and a reading telescope so placed as to read the deflection of the leaf when charged. B is the chamber to receive the sample. A spring from the metal rod in A connects this with a rod which extends into B. On the end of the latter is placed a disk. The rays discharge the leaf through this disk and The rod in the chamber is insulated from the case with amberoid, made by subjecting amber powder to great pressure. A is charged by means of a battery, or an abouite rod can be used. The battery is made by connecting seventy-five to a hundred French cells (or Eveready Tungsten No. 703) of about five volts each in series. It is best to ground the negative end and connect A by a floating wire to the positive pole of the cell which will give the desired deflection of the leaf. The case of the chamber is connected to the ground wire. A tube of distilled water is placed in the circuit to prevent the shorting of the batteries. Care should be taken not to charge the leaf enough to throw it against the case. The "natural Leak" is found by taking the time for the leaf to move over forty divisions, and calculating the divisions per second. Less than forty divisions may be taken if the time for forty divisions is quite long. If the leaf moves at the same rate over the whole scale, any part may be taken. The sample is placed in the plate for solids, and this is made exactly level full. The plate containing the sample is placed in a pan to protect the instrument from receiving active matter. The pan with its contents is now placed in the chamber B. As the charged leaf passes 8 (or some other chosen starting place) the stop watch is started. The watch is stopped at 4. The rate of discharge is calculated in divisions per second, and the natural leak is subtracted. A standard is run in exactly the same way. Since the rate of discharge is directly proportional to the amount of radium present, the amount of radium in the sample may be found by comparing its rate of discharge with that of the standard. This method gives approximate results. If the samples are of the same general character, the results may be in very good agreement, checking those obtained by the emanation method very closely.

Emanation Method

I. Carbonate Fusion. About 2 grams of a mixture of sodium and potassium carbonates are placed in a platinum boat about 2 in. long, $\frac{1}{2}$ in. wide and



in. deep. Larger boats may be used for low grade samples where large amounts are taken for analysis. From 0.05 to 1 gram of the sample should be weighed in the boat. The boat is now filled level full of the fusion mixture. The fusion is made over flame, or better, in an electric furnace at about 1000° C.

The boat should be put in the furnace while the furnace is cool. This will allow the fusion to dry and melt slowly, thus tending to prevent "boiling" over. The analyst will learn by practice how fast to heat up the furnace. When thoroughly fused and while still at the highest temperature, suddenly chill the fusion by dipping the boat in water, being careful not to allow water to run into the boat and wet the fusion. This chilling causes the mass to draw away from the boat and in the acid treatment slip out of the boat. The mass




Fig. 56c.

is also made more porous so that the acid attacks it much better. If very little silica is present, the chilling is not necessary. However, it does no harm. The boat with the fusion is sealed in a glass tube as shown in Fig. 56b. The tube should be no larger than necessary. A number of tubes should be prepared n advance by having one end sealed. After standing from one to five or more

days (this time depends on the amount of radium present and on the time the result is demanded, the fourth day is usually about right; this gives a little more than a 50 per cent. recovery of the emanation), the emanation surrounding the boat is drawn into an evacuated chamber. The chamber may be evacuated by means of an aspirator on the water faucet or by a pump. To draw the emanation from the tube to the evacuated chamber a rubber tube




Fig. 56d.

is placed on one end of the sealed tube and connected to the chamber with a capillary tube intervening to prevent broken glass from being drawn into the chamber, and a glass stopcock is connected by a rubber tube on the other end. The tip of the scaled tube next to the chamber is broken with a pair of pliers and the stopcock of the chamber opened for an instant. The other tip is broken and the glass stopcock opened for an instant. The stopcock of the chamber is opened again and closed after an instant. Air is let in through the glass stopcock again. After air is taken through about three times the chamber is ready to receive the emanation from the burette. It is necessary to use only a small part of the vacuum to draw the emanation from the sealed tube. The tube is broken and the boat is folded in a filter paper in such a manner that the paper will hold the boat in the neck of the flask until the flask is connected

with the apparatus as shown in Fig. 56c. About 4 in. of a stick of sodium hydroxide is placed in the leveling bulb D. Boiling water is poured on this and the solution is raised in the burette about three-fourths of its height, having stopcock E closed and F open. F is now closed and the leveling bulb hung on hook G. Flask C contains 1-1 HNOs; or if the fusion is hard to disintegrate 3 parts of acid to 2 of water is used. The boat is shaken into the nitric acid and stopcock E opened immediately. A bunsen burner flame is applied to the flask and the acid brought to boiling. The boiling is continued for 10 to 30 minutes according to the nature of the fusion. The heating must be regulated so that the solution in the burette is not driven too low. If the flask is heated too strongly the gas may be prevented from escaping through tube H by raising leveling bulb D. The burette is now connected to the chamber by means of a micro-drying bulb A containing sulfuric acid. The stopcock of the chamber is opened very slightly. Then the stopcock of the burette is opened slowly but fully. The stopeock of the chamber is now regulated till the flow of gas is such that the liquid in the burette rises steadily but not too fast. When the liquid rises to the stopcock the stopcock is turned and air let in till the level is about one-fourth down the tube. The air is drawn into the chamber till the liquid again reaches the stopeoek. The air is again let in as before. The stopeock is opened into the chamber again and the liquid poured out of the leveling bulb. Air is drawn through the column till the chamber is full. The burette is disconnected, and the chamber set away to be read at the end of three hours. Just before time to make the reading the electroscope head is placed on the chamber and charged for fifteen minutes, and the chamber is opened to atmospheric pressure by opening the stopcock for only an instant, Fig. 56d. From three to ten readings with the stop watch are taken over forty small divisions, say from 8 to 4. The temperature and pressure are noted. If these vary greatly from the conditions at which the instrument was standardized, the correction of the discharge must be made. The rate of discharge will be proportional to the pressure and inversely proportional to the temperature. The discharge is calculated in divisions per second. The natural leak, or still better, the blank is subtracted from this. This discharge is compared with that of a standard.

Example of a Determination and Calculation.

0.5 g. of sample sealed Oct. 1 at 5:00 P.M.
Boiled off Oct. 5 at 8:30 A.M.
Time of recovery 3 days, 15½ hours
Recovery factor for 3 days, 15 hr. 0.47926
½ hr. 0.00193

0.4812
log. of 0.4812 -1.6822
eolog. of 0.4812 .3178

A-II Time of discharge over 40 divisions of head A on chamber II. 92.5 see

B-II Time of discharge over 40 divisions of head B on chamber II. 100 scc. 1.6021 log. of 40


1.9661 log. of 92.5

-1.6360 -1.6330 log of 0.4295
.4325 -9.9450 standardization of instrument
.0030 blank .3178
.3010 to change ½ g. to gram.
2.6567 to change grams to pounds
3.3010 to change pounds to tons

-2.1545

14.3 mg. of radium per ton.

B-II is calculated in the same way. The standardization of this particular instrument was -9.9825. The last four numbers are the same in the two cases. The number for the standardization of the instrument is the log of the number of grams of radium necessary to discharge the leaf one division per



Fro. 56e.

second. This is obtained by running through the instrument pitchblende or a radium solution the radium content of which is accurately known. In all cases the natural leak or a blank must be subtracted.

The instrument is charged 15 minutes before the readings are made in order to allow the active deposits of Radium A, B and C to collect on the wall of the chamber. The leaf system should be charged positively. The readings are taken at the end of three hours after the emanation is drawn into the chamber because the activity increases to a maximum at that time. For the first part of the period the increase is very rapid. The maximum is actually reached at the end of four hours, but between three and five hours the change is very slow.

As soon as the readings are made the instruments must be freed from emanation by drawing dry air through them, the air being dried by sulfuric acid.

II. Bisulfate Fusion. A pyrex test tube 1.1/8 in. in diameter and 8 in. long is filled about 1 full of fused potassium bisulfate. Sodium bisulfate or a mixture of both potassium and sodium bisulfates may be used. From 0.05 to 5 grams of the finely ground sample should be added, the amount depending on the radium content of the sample. The tube is filled about \frac{3}{4} full of potassium bisulfate. In adding the last bisulfate care should be taken to carry down any of the sample adhering on the side of the tube. The mixture is now thoroughly fused, continuing till reaction is complete. The test tube is removed from the flame and held in a nearly horizontal position and slowly turned while the melt solidifies. A very small amount of barium carbonate is dropped into the tube. About \$\frac{1}{4}\$ of a gram is sufficient. In cases of carnotite ores, slimes, and tails the fusion will be yellow. As soon as the tube is cool enough to be handled a rubber stopper carrying two outlet tubes drawn out to rather fine tips (see figure) is inserted. If this is done as soon as possible there will be a partial vacuum in the tube when it cools and this will indicate when the emanation is taken off that there has been no leak. One of the outlet tubes should extend about one fourth way down the test tube and the other just through the stopper. After emanation has recovered at least one day the tube is connected to an evacuated chamber as shown in Fig. 56e. Microdrying bulb A contains water or sulfuric acid and acts as an indicator to show when the current of air into the chamber is correctly regulated. B contains the fusion; C sodium hydroxide solution; D sulfurie acid. The tip near A is broken with a pair of pliers. On account of the vacuum in B air rushes through A. Immediately after breaking the first tip the second should be broken. The stopcock of the chamber is slowly opened till air bubbles rather slowly through A. The tube containing the fusion is earefully heated until all the fusion is melted. It is boiled for at least five minutes, or till the chamber is about to atmospheric pressure. During the heating, a steady current is maintained throughout the heating by regulating the stopcock of the chamber. The chamber is disconnected and set away to be read at the end of three hours. The procedure is the same from this point as in the carbonate fusion method.

The Gamma Ray Method

The sample is placed in the holder at such a distance as will cause a reasonable rate of discharge—about one division per second. A standard is then placed at the same distance and the two rates of discharge compared. The natural leak should be subtracted from each reading. The quantities of radium are proportional to the rates of discharge.

In the gamma ray instrument the lead plate and the brass case of the chamber stop all the radiation except the gamma rays.

See Fig. 56f.

Method for Solutions

A measured volume of the solution is placed in a 150 cc. pyrex flask and dilute nitric acid added, filling the flask about one-half full. A little barium nitrate should be added to prevent the precipitation of radium sulfate. The solution is boiled to expel all the emanation. In the Colorado Sc hool of Mines

a special flask with a long $\frac{1}{4}$ in. neek is used. This is sealed off in the flame while the solution is nearly boiling. The ordinary flask may be used by inscrting a rubber stopper earrying a tube which can be sealed. Or the neek of a pyrex flask can be drawn out and sealed. With the rubber stopper the cinanation sometimes leaks. The special flasks are made by the Denver Fire Clay Company. After the emanation has recovered for one or more days the flask is connected to the burette by a light-walled rubber tube as in Fig. 56c. The tip is broken and heat is applied to the flask. On breaking the tip the rubber



tube collapses if the flask has not leaked. When the pressure in the tube is about atmospherie the stopeoek is opened slightly from time to time until the gas goes into the burette, and then opened wide. The solution is boiled for about ten minutes. The gas is then drawn into an evacuated chamber, as described in the other methods. The calculation may be made in milligrams per liter.

Notes

The earbonate method is similar to that given in bulletin 104, U.S. Burcau of Mines.

The bisulfate method of which the method here given is a modification was first published by Howard H. Barker in the Journal of Industrial and Engineering Chemistry for July, 1918, and improved by the Radium Company of Colorado.

Radium is found principally in earnotite and pitchblende. The largest earnotite deposits in the world are in southwestern Colorado and southeastern Utah. Uranium ores eontain radium; the ratio of radium to that of uranium is 3.4 x 10⁻⁷; or, there are 3.4 parts of radium to 10,000,000 of uranium.

Radium salts correspond chemically to those of barium. In water barium sulfate is 100 times as soluble as radium sulfate.

Radium is used in the treatment of certain malignant growths and in luminous paints. Some of the radioactive elements have furnished the means of studying atomic structure.

Emanation should not be allowed to remain in the chambers any longer than is necessary. Air dried by sulfurie acid should be drawn through them.

The percent of U₃O₈ multiplied by 2.6 gives the milligrams of radium pe ton in ores. This holds good unless the ratio has been disturbed by leaching or some other cause.

References.

Bulletin 70 U. S. Bureau of Mines. Bulletin 104 U. S. Bureau of Mines. Radioactive Substances and Their Radiations. E. Rutherford. G. P. Putnam's Sons, New York.

The Chemical Effects of Alpha Particles and Electrons. S. C. Lind. The Chemi-

cal Catalog Company, Inc., One Madison Ave., New York.
Introduction to the Rarer Elements. Philip E. Browning. John Wiley and Sons,

Introduction to the Earer Flements. Finish E. Drowning. John Whey and Sons, Inc., New York.
Practical Measurements in Radioactivity. W. Makower and H. Geiger. Longmans, Green, and Co., Fourth Ave. and 30th St., New York.
The Interpretation of Radium and the Structure of the Atom. 4th Ed. Frederick Soddy. G. P. Putnam's Sons, New York.
Bulletin 16. Radium, Uranium, and Vanadium Deposits of Southwestern Colorado.
Colorado Geological Survey, Boulder, Colorado.

TABLE OF RADIUM EMANATION RECOVERY (KOLOWRAT)

l		Quantity Formed			t .			Δ t		Quantity Formed	Δ per
Days	Hours	1 - 4 - 11	hour 0.00	Days	Hours	1 - e -ht	hour 0.00	Days	Hours	1 - e - ht	bour 0.00
	0	0.00000	747	2	4	0.32294	504	9	8	0.81363	1377
- 1	1	0.00747	742	2 2 2 2	. 6	0.33302	496	9	12	0.81913	1326
	2	0.01489	736	2	8	0.34295	489	9	18	0.82709	1268
l	3	0.02225	730	2	10	0.35274	482	10	0	0.83470	1212
	4	0.02955	726	2	12	0.36237	475	10	6	0.84197	1159
	5	0.03681	719	2	14	0.37187	468	10	12	0.84893	1108
1	6	0.04400	715	2	16	0.38122	461	10	18	0.85558	1059
- 1	7	0.05115	709	2 2 2 2	18	0.39043	454	11	0	0.86193	1013
- {	8	0.05824	703	2	20	0.39950	447	11	6	0.86801	0968
	9	0.06527	699	3	22	0.40844	440	11	12	0.87381	0925
l	10	0.07226	693	3	0	0.41725	432	11	18	0.87937	0885
- {	11	0.07919	688	3	3	0.43022	422	12	0	0.88467	0846
- 1	12	0.08607	683	I 3	6	0.44289	413	12	6	0.88975	0809
	13	0.09290	678	3	9	0.45529	404	12	12	0.89460	0775
	14	0.09968	672	3	12	0.46741	395	12	18	0.89924	0739
	15	0.10640	668	3	15	0.47926	386	13	0	0.90367	0701
- (16	0.11308	663	3	18	0.49084	378	13	8	0.90928	0660
- (17	0.11971	657	3	21	0.50217	369	13	16	0.91457	0622
- 1	18	0.12628	653	4	0	0.51325	361	14	0	0.91954	0586
	19	0.13281	648	4	3	0.52408	353	14	8	0.92423	0552
- 1	20	0.13929	643	4	6	0.53467	345	14	16	0.92864	0519
	21	0.14572	639	4	9	0.54502	337	15	0	0.93279	0489
	22	0.15211	633	4	12	0.55514	330	15	8	0.93671	0461
_ {	23	0.15844	629	4	15	0.56504	323	15	16	0.94039	0434
1	0	0.16473	624	4	18	0.57472	315	16	0	0.94387	0409
1	1	0.17097	620	4	21	0.58418	308	16	8	0.94713	0385
1	2	0.17717	614	5	0	0.59343	3004	16	16	0.95021	0362
1	3	0.18331	611	5	4	0.60545	2915	17	0	0.95311	0341
1	4	0.18942	605	5	8	0.61711	2829	17	8	0.95584	0321
1	5	0.19547	601	5 5	12	0.62842	2745	17	16	0.95841	0303
1	6	0.20148	597	5	16	0.63941	2664	18	0	0.96084	0281
1	7	0.20745	592	5	20	0.65006	2585	18	12	0.96421	0257
1	8	0.21337	588	6	0	0.66040	2509	19	0	0.96729	0235
1	9	0.21925	583	6	4	0.67044	2435	19	12	0.97010	0214
1	10	0.22508	579	6	8	0.68018	2363	20	0	0.97268	0196
1	11	0.23087	575	6	12	0.68963	2293	20	12	0.97503	0179
1	12	0.23662	570	6	16	0.69881	2225	21	0	0.97718	0164
1	13	0.24232	567	6 7	20	0.70771	2160	21	12	0.97914	0150
1	14	0.24799	562		0	0.71635	2096	22	0	0.98094	0137
1	15	0.25361	557	7 7	4	0.72473	2034	22	12	0.98258	0125
1	16	0.25918	554		8	0.73286	1974	23	0	0.98408	0114
1	17	0.26472	549	7 7	12	0.74076	1915	23	12	0.98545	0104
1	18	0.27021	545		16	0.74842	1859	24	0	0.98670	0095
1	19	0.27566	542	7	20	0.75586	1804	24	12	0.98784	0087
1	20	0.28108	537	8	0	0.76307	1751	25	0	0.98889	0080
1	21	0.28645	533	8	4	0.77007	1699	25	12	0.98985	0073
1	22	0.29178	529	8	8	0.77687	1649	26	0	0.99072	0064
1	23	0.29707	525	8	12	0.78346	1600	27	0	0.99225	0053
2	0	0.30232	522	8	16	0.78986	1553	28	0	0.99353	0044
Z	1	0.30754	517	8	20	0.79607	1507	29	0	0.99459	0037
2 2 2 2	2	0.31271	514	9	0	0.80210	1462	30	0	0.99548	
4	3	0.31785	509	9	4	0.80795	1419			1.00000	

Figures 232, 233 and 235 were drawn by M. Ettington. 35

SELENIUM AND TELLURIUM¹

DETECTION

Se, at.wt. 79.2; sp.gr. { Cryst. 4.82; m.p. 217° } b.p. 690°; oxide, SeO₂. Te at.wt. 127.5; sp.gr. 6.27; m.p. 452; b.p. 1390°; oxides, TeO₂ ,TeO₃.

Selenium and tellurium are commonly detected by precipitation with sulphur dioxide in hydrochloric acid solution. A selenium solution containing strong hydrochloric acid in the cold gives with either sulphur dioxide gas or the aqueous solution the amorphous red variety which, on warming, goes to the gray crystalline form. Tellurium solutions in presence of dilute hydrochloric acid with sulphur dioxide yield black elementary tellurium.

Hydrogen sulphide gives with selenious acid solutions a precipitate which is at first lemon yellow but on standing changes over to a red, due to the dissociation of yellow sulphide of sclenium into sulphur and amorphous red selenium. Tellurous solutions with hydrogen sulphide give at first a red brown precipitate which rapidly darkens due to dissociation into elementary tellurium and sulphur. Both of the sulphides are soluble in alkaline sulphide solutions.

Stannous ehloride, ferrous sulphate, hydroxylamine hydroehloride, hydrazine hydroehloride, phosphorous acid, or hypophosphorous acid added in the eold to selenious solutions give red elementary selenium, which goes over to the black variety on warming. Potassium iodide added in excess to a hydrochloric acid solution of either a selenite or selenate gives, in the cold, red selenium together with iodine. On warming the iodine distils and the red selenium goes over into the gray form.

A tellurium solution yields black elementary tellurium when treated with stannous chloride, hypophosphorous acid, hydrazine hydroehloride or with metals like zinc, aluminum, and magnesium.

Neutral selenious solutions with barium chloride give a precipitate of barium selenite which is soluble in hydrochloric acid. Neutral sclenates with barium chloride yield insoluble barium sclenate, which, like all sclenates, is decomposed with the evolution of chlorine and subsequent reduction to the sclenite which dissolves in the hydrochloric acid.

The few soluble alkaline tellurites give with barium chloride a white precipitate of barium tellurite which is soluble in hydrochloric acid. Barium tellurate is precipitated when a tellurate solution is treated with barium chloride. It is decomposed by hydrochloric acid, yielding chlorine and forming barium tellurite which dissolves in hydrochloric acid.

Sulphuric Acid Test. Selenium or a selenide with eoncentrated sulphuric, gently warmed or fuming sulphuric acid, in the cold, gives a green color, the intensity of which varies from a light green to an almost opaque greenish black, depending on the amount of selenium present. When the green solution is added to water, red elementary selenium is precipitated. This red selenium when boiled in the diluted acid changes into the gray crystalline form. The

Chapter contributed by Victor Lenher.

green color in the strong sulphuric acid is destroyed by warming the solution a few minutes. This test is not applicable to an oxidized selenium compound.

Tellurium or a telluride, but not oxidized tellurium compounds, gives in the cold with fuming sulphuric acid or with warm concentrated sulphuric acid a red color, the intensity of which depends on the amount of tellurium present. When the red solution is poured into water, black elementary tellurium is precipitated. When the red solution is warmed, sulphur dioxide is evolved, the red color disappears and if much tellurium is present, white crystals of the basic sulphate of tellurium separate.

The sulphuric acid test is frequently of no value when both of the elements are present, since the red of the tellurium may obscure the green of the sclenium.

Qualitative Detection of Selenium and Tellurium in Complex Mixtures

First Method. The substance is treated with aqua regia or with a mixture of hydrochloric acid and potassium chlorate, and the free ehlorine is expelled by warming at a temperature below boiling in order to avoid loss of volatile chlorides. The solution is then diluted and filtered to remove insoluble matter. Should tellurous acid precipitate on diluting with water, it can be redissolved by hydrochloric acid. The acid solution is treated with sulphur dioxide gas, or sodium acid sulphide. The formation of a precipitate indicates the possible presence of selenium, tellurium, or gold. (1) If the precipitate is allowed to scttle, the liquid poured off, and the precipitate warmed with strong nitric acid, selenium and tellurium will dissolve leaving the gold insoluble. The nitrie acid solution can be evaporated with hydrochloric acid to destroy the nitric acid and then treated in concentrated hydrochloric acid solution with sulphur dioxide gas. If selenium is present, it will appear as a red precipitate which on warming goes to the gray crystalline. The selenium precipitate can be filtered off through an asbestos filter and the solution when diluted with water and more sulphur dioxide added gives a black precipitate of elementary tellurium. (2) The sulphur dioxide precipitate containing possible selenium, tellurium, and gold can after washing be treated directly with hot concentrated sulphuric acid in order to get if possible the characteristic selenium or tellurium colors.

Second Method. Crude selenium or tellurium containing material from any source whether oxidized or non-oxidized can be fused with five to six times its weight of potassium cyanide. Tellurium forms potassium telluride, selenium forms selenocyanate and sulphur, which is invariably present, gives sulphocyanate. Extraction of the fused mass with water gives a purple solution if tellurium is present, the selenocyanate and sulphocyanate being colorless. The heavy metals remain insoluble, and can be removed by filtration. When a current of air is bubbled through the solution, the purple color is discharged and black elementary tellurium is precipitated. This tellurium can be filtered off and verified by the sulphuric acid test.

The selenocyanate and sulphocyanate from the air oxidation of the potassium telluride solution can be treated under a good hood with hydrochloric acid, when hydrocyanic acid is set free and red selenium is precipitated. The selenium can be confirmed by conversion to the black variety by heat or the sulphuric acid test can be applied.

SEPARATIONS

Separations of selenium and tellurium from other elements can be readily accomplished. Heating of the selenide and telluride combinations or mixtures in chlorine gas affords a separation from the metals whose chlorides are non-volatile.

Heating of sclenites or tellurites in a current of hydrochloric acid gas forms volatile ScO₂.2HCl or TeO₂.2HCl, while the sclenates or tellurates give ehlorine in addition. This treatment with hydrochloric acid gas, when applied to the oxidized sclenium and tellurium compounds, is an excellent means of separation from the metals whose chlorides are non-volatile.

Both of these elements can be separated from most of the more common elements by the general principle of reducing their compounds and precipitating them in elementary form by means of sulphur dioxide, hydrazine or hydroxylamine. Gold is precipitated at the same time but can be separated by treating the well-washed precipitate with nitric acid, sp.gr. 1.25, which will dissolve the selenium and tellurium but not the gold. The nitric acid solution can then be carefully evaporated with hydrochloric acid to destroy the nitrie, and convert to chloride solution.

Separations of Selenium and Tellurium

Keller's method is to separate the selenium and tellurium from each other by making use of the principle that selenium is completely precipitated by sulphur dioxide from strong hydrochloric acid solution while tellurium is not.

Procedure. The two elements are separated from the other elements by sulphur dioxido in dilute hydrochloric acid solution. The washed precipitate is dissolved in nitric acid and the solution evaporated to dryness on the water bath. The residue is dissolved in 200 cc. of hydrochloric acid, sp.gr. 1.175, and the solution warmed to expel all free nitric acid. The solution is then saturated with sulphur dioxide gas at 15-22° C. The precipitated selenium is allowed to settle, washed first by decantation with cold hydrochloric acid, sp.gr. 1.175, then with cold water to displace the acid and finally treated in the beaker with boiling water which transforms the red sclenium into the black granular variety. The selenium is brought on a Gooch crucible washed with alcohol and dried at 105° C. The tellurium is precipitated in the filtrate by diluting with water, adding more sulphur dioxide and hydrazine hydrochloride as in the gravimetric method for tellurium. The tellurium is finally washed with water, then alcohol, dried at 105° C. and weighed.

Separation of Selenium and Tellurium. Distillation Method

The following method is excellent for determining selenium and tellurium in alloys.

Procedure. The apparatus having been set up as is shown in the cut, Fig. 57, 0.5 gram of the alloy containing selenium and tellurium is placed in the distilling flask D and 30 ce. of H₂SO₄ (sp.gr. 1.84) added. All connections are made tight.

A current of dry HCl gas is allowed to flow into the distilling flask and the contents of the flask heated to 300° C. (The H₂SO₄ should not fume and the temperature should be kept below the boiling point of this acid, otherwise the

acid distilling into the reservoir R would interfere with the precipitation of selenium by SO_1 .) Selenium distills as selenium chloride into R, while tellurium remains in the distillation flask. During the distillation, SO_1 gas is passed into R, to reduce the selenic salt in solution and precipitate metallic selenium.

The distillation is continued for two or three hours, keeping the temperature of the distillation flask at about 300° C. (i.e., below the boiling-point of H_2SO_4). The contents of the receiver R is transferred to a 400-cc, beaker, and the distillation continued into fresh HCl to assure complete volatilization of sclenium from the flask D. The contents of the receiver and any of the metal adhering to the glass wool, or the glass of the vessel, are combined. (The adhering sclenium is dissolved off with a little Bromine-Potassium Bromide solution.)




Fig. 57. Apparatus for Determining Selenium and Tellurium.

Fig. 57 shows a convenient apparatus for routine determinations of selenium and tellurium in alloys. Hydrochloric acid gas is generated by allowing strong hydrochloric acid to flow into concentrated sulphuric acid (see A and B in drawing Fig. 57). The gas is dried by passing it through strong sulphuric acid (C in figure). A mercury pressure gauge, arranged to allow gas to blow out at a pressure of 3 or 4 pounds, prevents accident occurring due to stoppage in the system.

Determination of Selenium. The solution in the beaker is saturated with SO₂, then heated to boiling and the precipitated selenium allowed to settle several hours, or overnight. The precipitate is filtered into a weighed Gooch crueible, then washed with hot water and finally with alcohol. The residue is dried for an hour at 100° C. and weighed.

$$\frac{\text{Weight of Se} \times 100}{0.5} = \% \text{ Se.}$$

Determination of Teilurium. The residue in the distilling flask is transferred to a 600-ce. beaker containing 150 ce. of cold water. Ten ec. of 3% Fe(NO₃)₃ solution is added, and made ammoniacal, and then heated to boiling; the precipitate filtered off on a large filter and washed with hot water. The precipitate is dissolved in hot dilute HCl and the solution nearly neutralized with NH₄OH. The slightly acid solution is saturated with H₂S, the precipitated tellurium filtered off on an S. and S. No. 589, $12\frac{1}{2}$ cm. filter, and washed with H₂S water.

The precipitate is dissolved off the paper into a small beaker with a mixture of equal parts of HCl and bromine-potassium bromide solution. The paper is washed with water keeping the volume of the solution as small as possible. The

filtrate should contain 20% HCl.

Tellurium is precipitated by saturating the solution with SO₂. The precipitate, after heating to boiling, is allowed to settle for several hours and filtered onto a weighed Gooch. It is washed with hot water and then with alcohol and dried for an hour at 100° C., cooled in a desiceator and weighed.

$$\frac{\text{Weight of Te} \times 100}{0.5} = \% \text{Te}.$$

ESTIMATION

Selenium and tellurium closely resemble sulphur in chemical properties. They have crystalline and amorphous forms. The elements occur in nature frequently associated with sulphur. Selenium is frequently present in iron pyrites, hence is found in the flue dust of lead chambers of the sulphurie acid plant, and as an impurity in sulphurie acid, prepared from pyrites containing selenium.

Ores—Selenium. In copper and iron pyrites; meteoric iron. In the rare minerals clausthalite, PbSe; lehrbachite, PbSe·HgSe; onofrith, HgSe·4HgS;

eucairite, CuSe · Ag. Se; crookesite, (CuTlAg)Sc. 1

Tellurium. Occurs in tellurides and arsenical iron pyrites. Frequently associated with gold, silver, lead, bismuth and iron. In the minerals—altaite, PbTe; calaverite, AuTe₂; coloradolite, HgTe; nagyagite, (AuPb)₂(TeSSb)₃; petzite, Ag₂AuTe₂; sylvanite, AuAgTe₄; telluride, TeO₂ (tellurium ochre); tetradymite, Bi₂Te₂.

¹ Thorpe, "Dictionary of Applied Chemistry."

QUANTITATIVE METHODS FOR SELENIUM

Selenium is most commonly precipitated as element by either sulphur dioxide, hydroxylamine or hydrazine. This reduction to element at the same time separates the selenium from most of the elements except tellurium and gold. When hydroxylamine hydrochloride or hydrazine hydrochloride is the precipitating agent, the material is usually most conveniently brought into hydrochloric acid solution and converted if necessary into the selenious state. From this selenious solution, which may be acid, neutral or ammoniacal, these reducing agents on boiling precipitate elementary selenium which can he brought on a Gooch crucible, washed with hot water, dried at 105°, and weighed.

Sulphur Dioxide Method

The addition of sulphur dioxide to a solution of sclenious acid or a sclenite which is strongly acid with hydrochloric acid is one of the oldest and best methods of precipitating elementary sclenium. A sclenate or sclenie acid must first be reduced to a sclenite or sclenious acid by warming with hydrochloric acid, after which sulphur dioxide can be introduced.

It is sometimes convenient to produce the sulphur dioxide by the addition of sodium acid sulphite or of sodium sulphite. This procedure is satisfactory but should be accompanied by a blank test on the sulphite with hydrochloric acid, since the sulphites, on standing, not uncommonly give a precipitate of sulphur on acidification.

The best procedure in the precipitation of selenium by sulphur dioxide is to pass the gas slowly through the selenious containing solution which is strongly acid with hydrochloric acid. The gas should be passed into the solution at a temperature of 15-22° C. When the solution smells strongly of sulphur dioxide gas, the beaker is removed and allowed to stand for a half hour, in order that the selenium may settle. The supernatant liquor is decented through a previously weighed Gooch crueible, and the selenium washed first by decentation with strong hydrochloric acid, after which one treatment with cold water is used to wash the precipitate in the beaker. After again decanting, hot water is poured into the beaker containing the precipitate when the flocculent red selenium turns black and granular. It is then filtered, washed with hot water, followed by alcohol and dried at 105° C. to constant weight.

If the temperature in the solution during the precipitation of the selenium rises above 22°, the selenium agglomerates and occludes impurities which cannot be washed out. If the temperature is below 15°, the precipitation is either incomplete or very much delayed.

Evaporation of selenious acid should be made on the water bath rather than at a higher temperature since there is an appreciable loss of selenium dioxide when heated above 100° C. In the reduction of selenates or selenic acid to the selenious condition by means of hydrochloric acid, the temperature must never exceed that of the steam bath or considerable selenium may be lost.

Potassium Iodide Method

Potassium iodide added to a sclenious solution containing free hydrochloric acid gives a precipitate of elementary sclenium, iodine being liberated simultaneously.

 $SeO_2 + 4HI = Se + 2H_2O + 2I_2$.

With samples containing less than 0.1 gram selenium satisfactory results are obtained but with larger amounts iodine is likely to be occluded.

Procedure. The sample containing selenious acid or a sclenite in a dilution of 400 cc. is acidified with hydrochloric acid, 3-4 grams of potassium iodide are added and the iodine liberated is boiled off. The selenium is brought on a Gooch crucible washed with hot water, dried and weighed. Gooch and Pierce ¹ suggest the use of sodium arsenite and iodine solutions in carrying out the method volumetrically.

The thiosulphate method of Norris and Fay 2 consists in treating a hydrochloric acid solution of selenious acid with a measured excess of standard sodium thiosulphate solution and then titrating the excess of thiosulphate with an iodine solution.

$$H_2SeO_4 + 4Na_2S_2O_3 + 4HCl = 4NaCl + Na_2S_4SeO_6 + Na_2S_4O_6 + 3H_2O.$$

Selenates or selenic acid can be analyzed by boiling with hydroehloric acid when chlorine is evolved which can be collected and titrated.

¹ Amer. Jr. Sci. (4), I, 31. ² Amer. Chem. Jr., 23, 119.

QUANTITATIVE METHODS FOR TELLURIUM

Tellurium can be determined gravimetrically and separated from most of the elements except selenium and gold by a number of reducing agents. The oldest method, that of Berzelius, is the use of sulphur dioxide in slightly acid solution. Black elementary tellurium is precipitated but complete precipitation is much delayed even when the solution is warm. The hydrochloric acid solution of the tellurium should always be allowed to stand twenty-four hours. The tellurium is then conveniently brought on a Gooch crucible and the filtrate further digested after the addition of more sulphur dioxide. Very frequently more tellurium settles out on standing twenty-four hours longer. After all of the tellurium is collected on a Gooch crucible, it is washed and dried at 105° C. as quickly as possible in order to avoid the slight superficial oxidation which always takes place with tellurium which has been precipitated in this manner.

Hydrazine hydrochloride used as a reducing agent for the precipitation of elementary tellurium gives fairly good results but complete precipitation as with sulphur dioxide is somewhat delayed.

The use of sulphur dioxide and hydrazine hydrochloride together is the most accurate as well as the most rapid method for the determination and is applicable to both tellurites and tellurates, as well as to the free acids.

Hydrazine Hydrochloride-Sulphur Dioxide Method

The tellurium, either as a derivative of the dioxide or as a tellurate, should be present in a solution which has an acidity of approximately ten per cent free hydrochloric acid, and it is preferable that the solution be concentrated, for otherwise the precipitate will be so finely divided that it will be difficult to wash. The solution is heated to boiling, 15 cc. of a saturated solution of sulphur dioxide is added, then 10 cc. of a fifteen per cent solution of hydrazine hydrochloride followed by 25 cc. of sulphur dioxide solution. The boiling is continued until the precipitate settles in such a way that it can be easily washed, which should not take more than five minutes. The precipitated tellurium is brought on a previously weighed Gooch crucible washed with hot water until all of the chlorides are removed, after which the water is displaced by alcohol, and the crucible and contents dried at 105° C.

Tellurates or telluric acid can be analyzed by boiling with hydrochloric acid when chlorine is given off.

$$H_2\text{TeO}_4 + 2\text{HCl} = H_2\text{TeO}_2 + \text{Cl}_2$$
.

The chlorine evolved may be passed into potassium iodide solution and the liberated iodine titrated by sodium thiosulphate or an arsenite solution.

¹ Hydrazine hydrochloride is prepared ordinarily from the sulphate according to the directions given in "Organic Chemical Reagents," Vol. III, page 42, University of Illinois Bulletin, Vol. 19, No. 6, 1921. Hydrazine sulphate is conveniently made from sodium hypochlorite and ammonis. Organic Syntheses, Vol. II, pages 37–40, Wiley & Co., 1922.

Precipitation as Tellurium Dioxide

Browning and Flint 1 utilize the insolubility of tellurium dioxide as a means of separation from the readily soluble sclenious acid. Sclenium and tellurium are precipitated by sulphur dioxide from a hydrochloric acid solution. The elements are filtered, washed and dissolved in hydrochloric acid containing sufficient nitric acid to effect solution and then evaporated to dryness on the water bath.

Procedure. The material is dissolved in hydrochlorie acid or in a ten per cent solution of potassium hydroxide, using 2 cc. per 0.2 gram of oxide. The solution, if alkaline, is slightly acidified with hydrochlorie acid and then diluted to 200 cc. with boiling water. Dilute ammonium hydroxide is now added in slight excess, and is followed by the faintest excess of acetic acid. Crystalline tellurium dioxide separates out completely on cooling and can be brought on a Gooch crucible dried at 105° C. and weighed.

Notes

Tellurium. The element dissolves in hot concentrated hydrochloric acid. On dilution of the solution a precipitation of H₂TcO occurs. Treated with concentrated nitric acid or aqua regia H₂TeO₄ forms. With sulphuric acid the compound H₂TeO₂ forms and SO₂ is evolved. Tellurium is insoluble in carbon disulphide. The oxides TeO and TcO₂ are soluble in acids, TeO₃ being not readily soluble. All the oxides dissolve in hot potassium hydroxide solutions.

Care must be exercised to avoid overheating acid extracts in the preparation of the sample, since loss by volatilization is apt to occur; this is especially true of the halogen compounds of selenium and tellurium, the former being more volatile than the latter

Fusion Method. The finely powdered substance is intimately mixed with about five times its weight of a flux of sodium carbonate and nitrate (4:1) and heated gently in a nickel erucible, gradually increasing the heat, until the charge has fused. When the molten mass appears homogeneous, it is cooled and extracted with water. Sodium sclenate and tellurate pass into solution and are separated from most of the heavy metals. The water extract is acidified with hydrochlorie acid and boiled until no more free chlorine is evolved. (Test with starch iodide paper. Cl=blue color.) Metallic sclenium and tellurium may be precipitated by passing sulphur dioxide into the hydrochloric acid solution.

Keller has shown that tellurium is not precipitated by SO₂ in strong hydroehloric acid solutions (sp.gr. 1.175), whereas selenium is precipitated. Diluted with an equal volume of water (acidity 12 to 20% of above) both tellurium and selenium are precipitated by SO₂.

¹ Amer. Jr. Sci. (4), 1909, 28, 112.

METHODS AT REFINERIES Commercial Selenium

A half-gram portion of the material ground to 100 mesh is placed in a 150-cc. beaker, and 10 cc. of water are added, followed by 15 cc. conc. nitric acid. After the sample has dissolved in the beaker, which is covered with a watch glass, it is evaporated to dryness on the water bath, and taken up in 10 cc. conc. hydrochloric acid and 20 cc. of water in the cold. The insoluble matter is filtered off and the solution received in a 400-cc. beaker. Sufficient conc. hydrochloric acid is added to make the solution 70 pcr cent conc. hydrochloric acid.

The sclenium is precipitated at room temperature by passing a slow current of sulphur dioxide gas through the solution at the rate of two small bubbles per second, stirring frequently, to granulate the sclenium. It is recommended that the temperature of the solution be maintained at 60 to 70° F. by placing the beaker in a vessel of running water.

When complete precipitation has been effected and the solution smells strongly of sulphur dioxide, the beaker is removed and allowed to settle for a half hour. The supernatant liquor is decanted through a previously weighed Gooch crucible; the precipitated sclenium in the beaker is washed three times with cone, hydrochloric acid and once with cold water, decanting each time through the crucible. To the precipitate in the beaker 25 cc. of cold water are added, followed by hot water and vigorous stirring until the sclenium turns black and granular. It is then filtered, washed with hot water followed by alcohol, and dried at 105° to constant weight. After weighing, the crucible can be gently heated to expel the sclenium, in order to obtain a check on its purity. A residue may consist of silica or gold.

Tellurium in the filtrate is recovered by adding three gm. of powdered tartaric acid, diluting with four times its bulk of hot water, then adding 25 ec. ammonium hydroxide and saturating with sulphur dioxide gas. After the sulphur dioxide treatment, which takes but a few minutes, the solution is brought to boiling and allowed to stand for two hours on a hot plate. The granular elementary tellurium is brought on a previously weighed Gooch crucible, washed with hot water, dried at 105° and weighed.

The important laboratory details suggested by Greenwood 1 are:

1. Evaporation of the selenious acid should be made on the water bath rather than on a hot stove in order to avoid loss by volatilization. There is an appreciable loss of selenium dioxide when heated above 100° C. even in the presence of sodium and potassium chlorides. This fact has been verified in Lenher's laboratory.

2. If the temperature of the solution during the precipitation of selenium is above 70° F., the selenium agglomerates and occludes impurities, which cannot be washed out. If the temperature is below 60° F., the precipitation is either incomplete or very much delayed.

3. If the precipitated sclenium is not granular, it cakes during the drying

and retains moisture even at 110°.

Lead, copper and iron in selenium are determined in a sample of from 10 to 25 gm. which is dissolved in 50 to 75 cc. conc. nitric acid in a 375-cc. casserole and evaporated to dryness. The volatile selenium dioxide is expelled

¹ Eng. and Min. Jr. (1915), 100, 1012.

by carefully raising the temperature. The non-volatile residue is dissolved in 10 ec. cone. nitric acid and 5 ec. cone. hydrochlorie acid, evaporated to 5 ec., when 5 ec. concentrated sulphuric acid are added and evaporated to fumes; it is allowed to cool, 75 cc. of water are added and allowed to stand over night, when the lead sulphate is filtered off and weighed as usual. The filtrate from the lead is treated with hydrogen sulphide, the precipitate is ignited to burn off selenium, tellurium and arsenie, the residue dissolved in nitric acid and the eopper determined volumetrically. The filtrate from the precipitation of the eopper is boiled to expel the hydrogen sulphide, oxidized hy a few crystals of potassium chlorate, and the iron precipitated in the usual manner by ammonia.

An alternate method for the determination of iron in selenium is to weigh 10 gm. of the sample into a porcelain dish, ignite at a red heat until the selenium appears to be completely driven off. The residue is sometimes weighed and reported as "non-volatile matter." This residue is fused with sodium carbonate, treated with dilute sulphuric acid, the solution reduced with zinc, and the iron titrated with a weak solution of permanganate.

Insoluble in commercial selenium. 10 to 25 grams are dissolved in a 375-ce. casserole, in conc. nitric acid, and evaporated to dryness; conc. hydrochloric acid is added and the silica delaydrated. The insoluble is taken up in hydrochloric acid and water, filtered off, ignited and weighed.

Selenium and tellurium in metallic tellurium. A 0.5-gram sample of the finely powdered metal is treated with 10 cc. of conc. sulphurie acid and fumed until all the tellurium has dissolved; after which it is cooled and 20 cc. water and 50 cc. conc. hydrochloric acid are added.

Selenium is precipitated from the cold solution by passing in sulphur dioxide gas for 3 to 4 minutes, after which it is filtered through a Gooch crucible, washed three times with hydrochloric acid (2 parts conc. acid to 1 water), then with hot water and finally with alcohol, dried and weighed. To obtain a cheek on the purity of the selenium the Gooch crucible is ignited and reweighed.

The tellurium-containing filtrate is diluted to about 700 cc., heated to nearly hoiling, a few grams of hydrazine hydrochloride added and a rapid current of sulphur dioxide gas is passed in for 15 minutes, or until the tellurium separates readily; it is then brought on to a Gooch filter, washed with hot water, finally with alcohol. The elementary tellurium is dried for one hour at 105° and weighed.

A selenium and tellurium procedure used for a number of years in one of the refineries consists in dissolving in nitric acid, adding a pinch of salt, evaporating to dryness, taking up in 25 cc. hydrochloric acid (1:1) and bringing to boiling. The insoluble matter is filtered off, the solution diluted to 150 cc. and sulphur dioxide passed through the boiling solution. A few grams of hydrazine hydrochloride are added and sulphur dioxide again passed in after which the solution is boiled a few minutes. The precipitated selenium and tellurium are filtered off, dissolved in nitric acid with the addition of a pinch of salt, and the solution evaporated. The residue is taken up in about 200 cc. conc. hydrochloric acid, the solution boiled about ten minutes and the selenium brought on a Gooch crucible where it is washed with hot water, then alcohol, dried and weighed.

The tellurium-containing filtrate is diluted with water to three times its volume and saturated with sulphur dioxide; a few grams of hydrazine hydro-

chloride are added, boiled a few minutes, the tellurium is brought on a Gooch crucible, washed with hot water, then with alcohol, dried and weighed.

Selenium and tellurium in blister or pig copper are commonly determined

by the method of Keller, using samples of 50 grams or less.

Selenium and tellurium in electrolytic copper slimes are determined by treating a 0.5-gram sample of the slime in a 250-cc. beaker with 10 cc. conc. sulphuric acid, heating until the sample is decomposed and nothing remains but a white residue. After cooling, 20 cc. of water are added, followed by 2 cc. conc. hydrochloric acid, the solution is agitated to coagulate the silver chloride which is then filtered off. The acidity of the filtrate is brought up to about 32 per cent by adding conc. hydrochloric acid and the sclenium and tellurium separated by sulphur dioxide, following the customary procedure.

Selenium in lead slimes. A 2-gram sample is fused with a mixture of 8 grams sodium carbonate and 2 grams nitrate in a nickel crucible. The cold fusion is extracted with water and filtered. The filtrate is acidified with hydrochloric acid and heated until chlorine is expelled. To the solution is added an equal volume of hydrochloric acid, and sulphur dioxide gas is added until the red precipitate becomes granular. The selenium can be brought on an asbestos filter, washed with hydrochloric acid, redissolved in hydrochloric

acid and potassium chlorate and reprecipitated by sulphur dioxide.

Tellurium in lead slimes. 1 gram of slimes is treated with a mixture of 10 cc. conc. sulphuric acid, 10 cc. conc. nitric acid, and 20 cc. water, and evaporated to fumes. After cooling, 40 cc. water and about 2 grams tartaric acid are added. The solution is boiled and filtered. The residue is washed back into the original beaker, 5 to 10 cc. conc. sulphuric acid are added, and again evaporated to fumes; 40 cc. of water are added and the solution boiled and filtered. The two filtrates are united and treated with hydrogen sulphide The sulphides are filtered on paper washed with hydrogen sulphide water, washed back into the beaker, and a little sodium bicarbonate added followed by about 4 cc. of 10 per cent sodium sulphide solution. The solution is brought to boiling, digested for 12 hours, and filtered through the filter previously used. The sulphide-containing filtrate is acidified with dilute sulphuric acid and treated with hydrogen sulphide gas to render it granular. The sulphide precipitate, after filtration, is dissolved in nitric acid with the addition of 10 cc. conc. sulphuric acid and evaporated to fumes of sulphuric acid. It is then diluted with water and boiled after adding about 2 grams of tartaric acid. The solution is cooled, diluted to about 60 cc. with water, and after adding 40 cc. conc. hydrochloric acid, is again treated with hydrogen sulphide. The precipitate is filtered off, washed with 1:1 hydrochloric acid, dissolved in hydrochloric acid and potassium chlorate, warmed gently to expel the excess of chlorine, tartaric acid is again added, any residue filtered off, and the filtrate made strongly acid with hydrochloric acid. The selenium is then precipitated by sulphur dioxide.

The filtrate containing the tellurium is diluted with warm water, and the

tellurium precipitated and weighed as usual.

Selenium and tellurium in flue dust. 2 grams are dissolved in hydrochloric acid and potassium chlorate on a water bath, and the excess of chlorine expelled by gentle heat. The insoluble matter is filtered off and washed with concentrated hydrochloric acid, and the filtrate is treated with sulphur dioxide gas. The selenium and tellurium are brought on a Gooch crucible, washed,

then dissolved in hydrochloric acid and potassium chlorate, about 2 grams of tartaric acid are added, followed by conc. hydrochloric acid, and the selenium is precipitated by sulphur dioxide, filtered off and weighed. The filtrate is diluted to three times its volume with warm water, and the tellurium is precipitated by sulphur dioxide, collected and weighed.

Flue Dust and Niter Slag

Flue dust or niter slag from Doré furnaces can be analyzed for water-soluble sclenium and tellurium by boiling a 1-gram sample with water, filtering and washing with hot water, keeping the volume down to 20 cc. To this filtrate are added 200 cc. conc. hydrochloric acid; the solution is chilled with icewater; and sulphur dioxide is passed in, the sclenium and tellurium being separated by the method of Keller.

The insoluble sclenium and tellurium are transferred from the filter to a 50-ce. beaker, conc. nitric acid and conc. hydrochloric acid are added, and the solution evaporated at 50° C. or below. It is recommended to evaporate twice more with hydrochloric acid, keeping the temperature at 50° C. or below. The residue is taken up in hydrochloric acid (1:2) and filtered, after which 100 ec. conc. hydrochloric acid are added and the selenium and tellurium in the filtrate are separated by the Keller method.

Commercial Sodium Selenite

To 1 gram of the sample in a 50-cc. beaker are added 10 cc. of water and 5 drops of hydrochloric acid and shaken gently until solution is complete. After filtering out the insoluble matter, a large excess of conc. hydrochloric acid is added to the filtrate and sclenium is precipitated by sulphur dioxide. In the filtrate from the sclenium, the tellurium can be recovered by diluting with warm water and passing in more sulphur dioxide.

Selenic Acid

20 grams of the sample are quickly transferred to a tightly stoppered weighing bottle. After weighing, the acid is put into a liter flask, dissolved in water, and made up to the mark. A 25-cc. portion is measured out and treated with an excess of conc. hydrochloric acid and the sclenium precipitated by sulphur dioxide. If tellurium is present, it can be recovered in the filtrate.

Selenium in Glass 1

In ruby glass where selenium is present in quantities of about 0.25%, a two-gram sample is evaporated with hydrofluoric and nitric acids. This evaporation is repeated several times without ignition. The nitrates are then transferred to a small Erlenmeyer flask and the nitric acid destroyed by adding hydrochloric acid. Care must be taken not to boil the solution or selenium will volatilize. A high concentration of the hydrochloric acid must be maintained in order to hold the tellurium in solution. Sulphur dioxide is next passed into the solution when elementary selenium is precipitated, washed, dried and weighed as usual.

¹ Method furnished by the Corning Glass Works.

In glasses where selenium is used as a decolorizer and in which the selenium is present to the extent of less than .0025%, Cousen recommends dissolving the glass in nitric and hydrofluoric acids and determining the selenium colorimetrically by phenyl hydrazine hydrochloride, keeping the selenium from precipitating by adding gum arabic. A yellow to a yellowish red solution is obtained which is compared with a color standard containing a known amount of sodium selenite.

Selenium and Tellurium in Refined Copper

The success and accuracy of determining small amounts of impurities, is to collect these impurities from a large sample, and to do the necessary chemical work in a small volume of solution.

Ferric hydroxide when precipitated from a copper solution has the peculiar property of forming insoluble compounds with As, Sb, Se and Te.

For complete precipitation, the iron contents must be at least thirty times the combined As, Sb, Se and Te and must be entirely precipitated from the solution.

The iron is best added by means of the ferrous salt (FcSO₄+7H₂O) dissolved in water and oxidized to the ferric salt with HNO₃. Roughly the iron content of FeSO₄+7H₂O is 20%, or one-fifth of the weight of ferrous sulphate.

Weigh 100 grams of drillings into a 1300 cc. beaker, cover with water and add gradually 350 cc. HNO₃ (1.42). When the copper is in solution, boil out all red fumes, dilute to 700 cc. with warm water and neutralize with NH₄OH until just enough copper hydroxide has been formed to cover the bottom of the beaker; then add the required amount of oxidized ferrons sulphate in solution. Stir well, dilute to 900 cc. and boil for at least one hour, settling on the warm plate over night. Filter on a 15 cm. filter.

Treat the filtrate with ammonia until a precipitate of copper hydroxide has formed to cover the bottom of the beaker and half the quantity of oxidized FeSO₄+7H₂O added previously, is again added and the solution boiled for one hour, allowing to settle over night on the warm plate. Filter on a 15 cm. filter. It is absolutely necessary that no iron salts be left in this filtrate, either in solution, or as hydrate, therefore, this filtrate had best be tested with ammonia and refiltered on a 15 cm. filter. The three precipitates on the 15 cm. papers are treated as one, dissolved in the least quantity of warm H₂SO₄ (1-1), the papers washed well with hot dil. H₂SO₄ (1-20) and filtered into a 600 cc. beaker. Make strongly ammoniacal, boil well and filter, washing the precipitate well and free from the folds into the apex of the filter. Refilter the filtrate to catch any iron that has washed through. The papers are spread open and the precipitates dissolved in 25 cc. warm HCl (1-1) in a 250 cc. beaker, using as little hot water as possible to remove the yellow stains.

Filter the solution into a 400 cc. beaker, washing with as little hot water as possible. To the filtrate add four times its volume of conc. HCl and cool.

Pass SO₂ gas through this liquid at the rate of one bubble per second, keeping the solution cool.

Filter off the precipitated Se on a tared Gooch crucible wash with cold water and alcohol, dry at 60° C. for two hours, then at 105° C. to constant weight.

Weigh as metallic Se.

Expel the Se from the crucible and reweigh as a check on the weight and the purity of the precipitate.

Tellurium

To the filtrate from the precipitated Se, add 2 grams of tartaric acid in order to keep the Sb in solution, dilute to 600 ee. with hot water, add 50 cc. conc. NH₄OH, and saturate the solution with SO₂ gas. Boil for two minutes and allow to settle 4-6 hours.

Filter the Te on a tared Gooch crucible, wash with hot water and finally with alcohol, dry at 115° C. to constant weight.

Weigh as metallic Te.

VOLUMETRIC DETERMINATION OF SELENIUM AND TELLURIUM

Iodometric Determination of Selenic, or Telluric Acid—Reduction with Hydrochloric Acid and Distillation

The method depends upon the reduction of selenie or telluric acid to selenious or tellurious acid by heating with hydrochloric acid, the evolved chlorine being a measure of the acids in question. The chlorine absorbed in potassium iodide solution liherates its equivalent of iodine, which may readily be determined by titration with standard thiosulphate. The following reactions illustrate the change that takes place:

$$K_2SeO_4+4HCl = 2KCl+H_2SeO_3+H_2O+Cl_2,$$

 $K_2TeO_4+4HCl = 2KCl+H_2TeO_3+H_2O+Cl_2,$

1 Cl. =1 I = $\frac{\text{Se}}{2}$ or $\frac{\text{Te}}{2}$ = 63.75 grains Te or 39.6 grains Sc per liter normal solution.

According to Gooch and Evans over 30% of strong hydrochloric acid (sp.gr. 1.20) should be present. Dilute hydrochloric acid having a strength of 10% of HCl, sp.gr. 1.2, does not react with liberation of chlorine. Care must be taken not to prolong the boiling after the solution reaches a concentration of half strength, since over reduction may take place and the metals be liberated.

Procedure. The sample containing the selenate or tellurato is treated with 75 ec. of hydrochloric acid, containing 25 cc. of strong HCl, sp.gr. 1.20, per 0.2 gram of the existence of the existe

¹Te is best precipitated by SO₂ gas in a 20-30% HCl solution and the strong (80%) HCl solution from the Se precipitation is best neutralized to 25-30%, by the use of ammonia.

SILICON

Si, at. wt. 28.06; sp.gr. amor. 2.00.; crys. 2.49; m.p. 1420° C.; oxides SiO, SiO,

DETECTION

The finely ground sample together with a small quantity of powdered calcium fluoride is placed in a small lead cup I cm. in diameter and depth (see Fig. 58), and a few drops of concentrated sulphuric acid added. A lead cover, with a small aperture, is placed on the cup, and the opening covered with a picce of moistened black filter paper. Upon this paper is placed a moistened pad of ordinary filter paper. The cup is now gently heated on the steam bath. At the end of about ten minutes a white deposit will be found on the under side of the black paper, at the opening in the cover, if an appreciable amount of silica is present in the material tested.



A silicate, fused with sodium earbonate or bicarbonate in a platinum dish and the carbonate decomposed by addition of hydrochloric acid with subsequent evaporation to dryness, will liberate silicon as silicie anhydride, SiO2. The silica placed in a platinum dish is volatilized by addition of hydrofluoric acid, the gaseous silicon fluoride being formed. A drop of water placed in a platinum loop, held in the fumes of SiF4, will become cloudy owing to the formation of gelatinous silieic acid and fluosilieic acid,

$$3SiF_4 + 3H_2O = H_2SiO_3 + 2H_2SiF_6$$

If a silicate is fused in a platinum loop with microcosmic salt, the silica floats around in the bead, producing an opaque bead with weblike structure upon cooling.

ESTIMATION

The gravimetric procedure is the only satisfactory method for the estimation of silica. The substance in which the clement is combined as an oxide or'as a silicate is decomposed by acid treatment or by fusion with an alkali carbonate or blearbonate, the material taken to dryness with addition of hydrochloric acid, whereby the compound silica is liberated. If other elements are present the silica is volatilized by addition of hydrofluoric acid and estimated by the loss of weight of the residue.

The element silicon has no important application. Its use for electrical resistance has been suggested. A rod 10 cm. long with cross section of 40 sq.mm. has a resistance of 200 ohms against a carbon rod of the same dimensions of 0.15

Chapter contributed by Wilfred W. Scott.

SILICON

Impure silica finds use in fluxes in manufacture of glass; pure silica for nanufacture of silica ware. With caustic it forms an adherent sodium e. Silicon carbide, carborundum, is used for refractory purposes, fire zinc muffles, coke ovens. Crystolon, the crystalline form, is used as an ive, in making grinding wheels, sharpening stones, etc.

mbined as SiO, and in silicates the element is very widely distributed in 3 and is a required constituent in practically every complete analysis of minerals, soils, etc. It is present in certain alloys, ferro-silicon, silicon

le. etc.

ie element is scarcely attacked by single acids, but is acted upon by nitricfluoric acid mixture. It dissolves in strong alkali solutions. Silica is sposed by hydrofluoric acid and by fusion with the fixed alkali carbonates iroxides.

Preparation and Solution of the Sample

meral Considerations. The natural and artificially prepared silicates may ouped under two classes: 1. Those which are decomposed by acids. 2. es not decomposed by acids. The minerals datolite, natrolite, olivine nany basic slags are representative of the first class, and feldspar, orthopumice and serpentine are representative of silicates not decomposed by

(See more complete list under List of More Important Silicates, page 433.) rst division simply require an acid treatment to isolate the silica, the latter

equire fusion with a suitable flux.

technical analysis, in cases where great accuracy is not required, the residue ning, after certain conventional treatments with acids, is classed as silica. nay consist of fairly pure silica or a mixture of silica, undecomposed silibarium sulphate and certain acid insoluble compounds. For accurate ses this insoluble residue is not accepted as pure silica, unless impurities, are apt to be found with the silica residue, are known to be absent from the ial under examination.

though the procedure for isolation of silica is comparatively simple, errors

rise from the following causes:

Imperfect decomposition of the silicate.

Loss of the silica by spurting when acid is added to the carbonate fusion, Slight solubility of silica, even after dehydration, especially in presence ium chloride and magnesia.

Loss due to imperfect transfer of the residue to the filter paper.

Mechanical loss during ignition of the filter and during the blasting, due

draft whirling out the fine, light silica powder from the crucible.

Error due to additional silica from contaminated reagents or from the porceshes or glassware in which the solution was evaporated. A blank of 0.01% e sodium carbonate will make an error of 0.1% per gram sample in an ry fusion where 10 grams of the flux are required.

Error due to loss of weight of the platinum crucible during the blasting. Incomplete removal of water, which is held tenaciously by the silica. ermore, weighing of the residue should be done quickly, as the finely divided

tends to absorb moisture.

vo general procedures will be given for treatment of the acid decomposad undecomposable silicates. It is frequently advisable to use these two lures in conjunction, extracting the material first with acid, and then fusing the insoluble residue with sodium carbonate; this procedure is used when a gritty residue remains after the acid extraction. Following the general procedures for decomposition of silicates, certain special methods will be given.

List of Most Important Silicates. Silicates decomposed by acids. Allanite; allophane; analcite; botryolite; brewsterite; calanine; chabasite; croustedtitite; datolite (hydrated silicate and borate of Ca with Al and Mg); dioptase; culytite; gadolinite; gahlenite; helvite; ilvaite (silicate ferrous and forrie iron with Al₂O₃, CaO and MgO); laumonite; melinite; natrolite (hydrated silicate of Al and Na with Fe and CaO); okenite; olivine (silicato of Fe and Mg); peetolite; prehenite (hydrated Al and Ca silicate with Fe, Mn, K, Na, etc.); teproite; wernerite; woolastomite; zaolite. Silicates undecomposed by acids. Albite; audalusite; augite; axinite; beryl; carpholite; cyanite; diallage, epidote (silicate of Fe, Al and Ca with FeO, Mn, Mg, K, Na); euclase; feldpsar (silicate of K, Na, Al, Fe, Ca and Mg); garnet; iolite; labradorite; (micas of K and Mg); orthoclase; petalite; pinite, prochlorite; pumice; serpentine; sillimanite, talc, topaz, tourmaline (Fe₂O₂, FeO, Mn, Al, Ca, Mg, K, Na, Li, SiO₂, B₂O₃, P₂O₅, F); vesuvianite.

Preparation of the Substance for Decomposition

If the material is an ore or mineral it is placed on a steel plate within a steel ring and broken down by means of a hardened hammer to small lumps and finally to a coarse powder. A quartered portion of this is air dried and ground as fine as possible in an agate mortar and preserved in a glass-stoppered bottle for analysis.

Analyses are based on this air-dried sample. If moisture is desired it may be determined on a large sample of the original material. Hygroscopic moisture is determined on the ground, air-dried sample, by heating for an hour at 105

to 107° C.

Decomposition of the Material, General Procedures Silicates Decomposed by Acids

Acid extraction of the silicates. 0.5 to 1 gram of the finely pulverized material placed in a beaker or easserole is treated with 10 to 15 ee. of water and stirred thoroughly to wet the powder.1 It is now treated with 50 to 100 cc. of strong hydrochloric acid and digested on the water bath for fifteen or twenty minutes with the beaker or easserole covered by a watch-glass. If there is evidence of sulphides (pyrites), etc., 10 to 15 ce. of concentrated nitric acid are now added and the containing vessel again covered. After the reaction has subsided, the glass cover is raised by means of riders and the mixture evaporated to dryness on the water bath. (This evaporation may be hastened by using a sand bath, boiling down to small bulk at comparatively high temperature, then to dryness on the water bath. Decomposition is complete if no gritty particles remain. A flocculent residue will often separate out during the digestion, due to partially dehydrated silicic acid, hydrated silicic acid, Si(OH), is held in solution.) The silicic acid is converted to silica, SiO, the residue taken up with dilute hydrochloric acid, silica filtered off, washed with water acidified with hydrochloric acid, and estimated according to the procedure given later.

¹Water is added to the sample and then acid, as strong acid added directly would cause partial separation of gelatinous silicic acid, which would form a covering on the undecomposed particles, protecting them from the action of the acid.

Silicates Not Decomposed by Acids

Fusion with Sodium Carbonate or Sodium Bicarbonate. 0.5 to 1 gram of the air-dried, pulverized sample is placed in a large platinum crucible or dish in which has been placed about 5 grams of anhydrous sodium carbonate. The sample is thoroughly mixed with the carbonate by stirring with a dry glass rod, from which the adhering particles are brushed into the erucible. A little carbonate is sprinkled on the top of the mixture and the receptacle covered. It is heated to dull redness for five minutes and then gradually heated up to the full capacity of a Méker burner. When the mix has melted to a quite clear liquid. which generally is accomplished with twenty minutes of strong heating, a platinum wire with a coil on the immersed end is inserted in the molten mass, and this allowed to cool. The fusion is removed by gently heating the erucible until the outside of the mass has melted, when the charge is lifted out on the wire, and after cooling disintegrated by placing it in a beaker containing about 75 cc. dilute HCl (1 part HCl to 2 parts H₂O), covering the beaker to prevent loss by spattering. The erucible and lid are cleaned with dilute hydrochloric acid, adding this acid to the main solution. When the disintegration is complete, the solution is evaporated to dryness and silica is estimated according to directions given later.

If decomposition is incomplete, gritty material will be found in the beaker upon treatment of the fusion with dilute acid. If this is the case, it should be filtered off and fused with a second portion of sodium carbonate, and the fusion treated as directed above.

Notes. Fusions with soluble earbonates are generally best effected with the sodium salt, except in fusions of miobates, tantalates, tungstates, where the potassium salt is preferred on account of the greater solubility of the potassium compounds. Sodium alone has an advantage over the mixed carbonates, $Nu_xCO_2+K_xCO_3$, as silica has a high melting-point and a flux, which fuses at 810° C., is more apt to cause disintegration of the silicate than the mixture, which melts at 690° C.

integration of the silicate than the mixture, which melts at 600° C.

Prolonged blasting is undesirable, as it renders the fusion less soluble. Aluminum and iron are also rendered difficultly soluble, when their oxides are heated to a high

temperature for some time.

If the melt is green, it is best to dissolve out the adhering melt from the crucible with dilute nitric acid, as a manganate (indicated by the color), if present, will evolve free chlorine by its action on HCl and this would attack the platinum.

Fluorides.¹ In presence of fluorides the melt is extracted with water (an acid extraction would volatilize some of the silica), and the extract filtered off from the insoluble carbonates. To the filtrate is added about 5 grams of solid ammonium carbonate, and the mix warmed to 40° C. and allowed to stand for several hours. The greater part of the silica is precipitated. This is filtered off and washed with water containing ammonium carbonate. Preserve this with the insoluble carbonate for later treatment. The filtrate, containing small amounts of silicic acid, is treated with 1 to 2 ce. of ammoniacal zinc oxide solution (made by dissolving C.P. moist zinc oxide in ammonia water). The inixture is boiled to expel ammonia and the precipitate of zinc silicate filtered off. The precipitate is washed into a beaker through a hole made in the filter, and the adhering material dissolved off with dilute HCl, enough being added to dissolve the remaining residue. This is evaporated to dryness and silica separated as usual. Meantime the insoluble carbonate is dissolved with HCl, evaporated to

¹ Sodium bicarbonate may be used in place of the earbonate with excellent results.

445

dryness and any silica it contains recovered. Finally all three portions of silica are combined, ignited and silica estimated as usual.

Special Procedures for Decomposing the Sample

Treatment of Iron and Steel for Silica. One gram of pig-iron eastings, or 5 grams of steel are taken for analysis, both the fine and coarse drillings being taken in about equal proportion. (Fine particles contain more silicon than the coarse chips.) Twenty to 50 cc. of dilute nitric acid (sp.gr. 1.135) are added to the sample in a 250-cc. beaker or small casserole, and this covered. If the action is violent, cooling, by placing the beaker in cold water until the violent action has subsided, is advisable. Twenty cc. of 50% sulphuric acid are added and the solution evaporated on the hot plate to SO, funes. After cooling, 150 cc. of water are added and 2 to 5 cc. dilute sulphuric acid. The mixture is heated until the iron completely dissolves and the silica is filtered off onto an ashless filter, washed with hot dilute hydrochloric acid (sp.gr. 1.1), and with hot water until free from iron. The residue is ignited and the silica estimated according to the procedure given later.

Pig iron and cast iron may be decomposed by digestion with a mixture of 8 parts by volume of HNO₃ (sp.gr. 1.42), 5 parts of H₂SO₄ (sp.gr. 1.84), and 17 parts of water.

Steel and wrought iron may be disintegrated by a mixture of 8 parts by volume of HNO₃ (sp.gr. 1.42), 4 parts H₂SO₄ (1.84), and 15 volumes of water.

Ferro Silicons. Dilute hydrochloric acid, 1 volume of acid (sp.gr. 1.19), with 2 volumes of water is a better solvent than the strong acid.

Steels Containing Tungsten, Chromium, Vanadium and Molybdenum. Fusion with potassium acid sulphate, KHSO4, in a platinum dish, or sodium peroxide in a nickel crucible will generally decompose the material. Sodium peroxide is of special value in decomposing chromium alloys.

Silicon Carbide, Carborundum. This is best brought into solution by fusion with potassium hydroxide in a nickel crucible. Sulphuric, hydrochloric, nitric acids, or aqua regia have no effect upon this refractory material.

Sulphides, Iron Pyrites, etc. These require oxidation with strong nitric acid or a mixture of bromine and carbon tetrachloride, followed by nitrie, exactly according to the procedure given for solution of pyrites in the determination of sulphur. The sample is taken to dryness and then hydrochloric acid added and the solution again evaporated. The residue is dehydrated and silica determined as usual.

Slags and Roasted Ores. Digestion with hydrochloric acid according to the first general procedure is best. The addition of nitric acid to decompose sulphides may be necessary.

Decomposition of silicates by fusion with lead oxide (method of Jannasch), and calcium carbonate and ammonium chloride (method of Hillebrand), are of value when sodium is desired on the same sample. The procedures are given under chapters on Sodium and Potassium.

Note. K_1CO_2 is preferred to Na_2CO_2 for fusion of tungstates, niobates and tantalates on account of the greater solubility of the potassium salts. For corundum and alumina silicates Na_2CO_2 is preferred as double salt of potassium and aluminum are less soluble than the sodium salt.¹

Fluorides of silicon are fused with boric acid, BF, is volatilized, SiF, is not formed. P. Jannasch.²

¹J. L. Smith, Am. Jour. Sci. (2), 40, 248, 1865. C. N., 12, 220, 1865. ² Ber., 28, 2822, 1896.

446 SILICON

PROCEDURE FOR THE DETERMINATION OF SILICON AND SILICA

As has been stated, the gravimetric method for determination of silica is the only satisfactory procedure for estimation of this substance. The oxidation of the element and its isolation have been dealt with in the section Preparation and Solution of the Sample. The following directions are for purification

and final weighing of the element in the form of its oxide, silica, SiO2.

Extraction of the Residue-First Evaporation. The residue, obtained by evaporation of the material after decomposition of the silicate, by acids or by fusion, as the case required, is treated with 15-25 cc. of hydrochloric acid (sp.gr. 1.1) covered and heated on the water bath 10 minutes. After diluting with an equal volume of water, filtration is proceeded with immediately, and the silica is washed with a hot solution consisting of 5 cc. hydrochloric acid (sp.gr. 1.2) to 95 cc. of water and finally with water. This filtration may be performed with suction. The filtrate and washings are evaporated to small volume on a sand bath and then to dryness. This contains the silica that dissolved in the first extraction.

Second Evaporation. The residue obtained from evaporation of the filtrate is dehydrated for 2 hours at 105-110° C.1 and extracted with 10 cc. of hydrochloric acid (sp.gr. 1.1) covered and heated on the water bath for ten minutes diluted to 50 cc. with cold water and filtered immediately, without suction. The residuc is washed with cold water containing 1 cc. concentrated hydrochloric acid to 99 cc. water, the washed residue containing practically all the silica, that went into solution in the first extraction, is combined with the main silica residue. This is gently heated in a platinum crucible until the filters are thoroughly charred, and then ignited more strongly to destroy the filter carbon and finally blasted over a Méker burner for at least thirty minutes, or to constant weight, the crucible being covered. After cooling the silica is weighed. For many practical purposes this residue is accepted as silica, unless it is highly colored. For more accurate work, especially where contamination is suspected (silica should be white), this residue is treated further.

Estimation of True Silica. Silica may be contaminated with BaSO₄, TiO₂, Al₂O₃, Fe₂O₃, P₂O₃ combined (traces of certain rare elements may be present). The weighed residue is treated with 3 cc. of water, followed by several drops of concentrated sulphuric acid and 5 cc. of hydrofluoric acid, HF (hood). After evaporation to dryness, the crucible is heated to redness and again cooled and weighed. The loss of weight represents silica, SiO₂.3

Dehydration of silica is aided by the presence of lime and retarded by magnesia. In presence of the latter a soluble magnesium silicate will form if the dehydration is conducted at a temperature much above 110° C., hence it is better to avoid this

by taking more time and heating to 100 or 105° as recommended.

Sodium chloride has a solvent action on silica, the reaction of HCl on sodium silicate being reversible; 2HCl+Na₂SiO₁ = 2NaCl+Ha₂SiO₂. An evaporation of the filtrate to dryness will recover the greater part of the silica thus dissolved.

Not more than 0.1% of the original SiO₂ may still be in solution.

Silicic acid cannot be completely dehydrated by a single evaporation and heating,

nor by several such treatments, unless an intermediate filtration of silica is made. If, however, silica is removed and the filtrate again evaporated to dryness and the residue heated, the amount of silica remaining in the acid extract is negligible. (See Article by Dr. W. F. Hillebrand, Jour. Am. Soc., 24.)

Notes. Lenher and Truog make the following observations for determining silica: 1. In the sodium carbonate fusion method with silicates, there is always a non-volatile residue when the silica is volatilized with hydrofluoric and sulphuric acids.

2. The non-volatile residue contains the various bases, and should be fused with sodium carbonate and added to the filtrate from the silica when the bases are to be determined.

3. In the dehydration of the silica from the hydrochloric acid treatment of the

fusion, the temperature should never be allowed to go above 110°.

4. Dehydrated silica is appreciably soluble in hydrochloric acid of all strengths. With the dilute acid used, this error is almost negligible.

5. Dehydrated silica is slightly soluble in solutions of the alkaline chlorides. As

sodium chloride is always present from the sodium carbonate fusion, an inherent error is obviously thus introduced. 6. The dehydrated silica along with the mass of anhydrous chlorides must not be

treated first with water, since hydrolysis causes the formation of insoluble basic chlorides

of iron and aluminum, which do not dissolve completely in hydrochloric acid.
7. Hydrochloric acid (sp.gr. 1.1) in minimum amount should be used first to wet the dehydrated chlorides and should be followed by water to bring the volume to about 50 cc., after which the silica should be filtered off as quickly as possible.

8. Pure silica comes quickly to constant weight on ignition. Slightly impure silica frequently requires long heating with the blast flame in order to attain constant weight, and is then common'y hydroscopic.

9. Evaporations of the acidulated fusion in porcelain give practically as good results

as when platinum is used.

10. Filtration of the main bulk of the silica after one evaporation is desirable, inasmuch as the silica is removed at once from the solutions which act as solvents.

11. Dehydration of the silica under reduced pressure has no advantages over the common evaporation at ordinary atmospheric pressure.

12. Excessive time of dehydration, viz., four lours, possesses no advantages.

13. Excessive amounts of sodium carbonate should be avoided, since the sodium chloride subsequently formed exerts a solvent action on the silica. The best proportions are 4-5 sodium carbonate to 1 of silicate. Less than 4 parts of sodium carbonate is frequently insufficient completely to decompose many silicates.

14. The non-volatile residue has been found to be invariably free from sodium.

Pure silica, on fusion with sodium carbonate, subsequently gives no non-volatile residue.

ANALYSIS OF SILICATE OF SODA

Determination of Na₂O

Five grams of the sample arc dissolved in about 150 cc. of water and heated: 1 cc. of phonolphthalein is added and then an excess of standard sulphuric acid from a burette. The excess acid is titrated with standard sodium hydroxide to a permanent pink.

 $H_2SO_4 \times 0.6321 = Na_2O$.

Silica. Ten grams of the sample are acidified with hydrochloric acid and evaporated to dryness on the steam bath. The treatment is repeated with additional hydrochloric acid and then the residue taken up with 5 cc. of the acid and 200 cc. of water. The residue is digested to dissolve the soluble salts, filtered, washed and ignited. Silica is determined by loss of weight by volatilization of the silica with hydrofluoric and sulphuric acids. The filtrate is made to 1 liter.

Iron and Alumina. Five hundred cc. (5 grams) of the filtrate from the silica determination are oxidized with HNO; and the iron and alumina precipitated with ammonia, washed, ignited and weighed as Al₂O₂ and Fe₂O₂. The residue is dissolved by digestion with hydrochloric acid or by fusion with sodium acid

¹ Victor Lenher and Emil Truog, Jour. Am. Chem. Soc., 38, 1050, May, 1916.

sulphate, and subsequent solution in hydrochloric acid. Iron is determined by titration in a hot hydrochloric acid solution with standard stannous chloride, SnCl₂, solution as usual. If only a small amount of precipitate of iron and alumina is present, as is generally the ease, solution by hydrochloric acid is preferable to the fusion with the acid sulphate. The latter is used with larger amounts of the oxides.

Lime, CaO. This is determined in the filtrate from iron and alumina by precipitation as the oxalate and ignition to CaO.

Magnesia, MgO. This is determined in the filtrate from lime by precipitation with sodium ammonium phosphate. The precipitate is ignited and weighed as $Mg_1P_2O_7$ and ealeulated to MgO. Precipitate×0.3621 = MgO.

Combined Sulphuric Acid. One hundred ee. of the filtrate from the siliea determination (=1 gram) is treated with BaCl₂ solution and sulphurie acid precipitated as BaSO₄.

$$BaSO_4 \times 0.4202 = H_2SO_4$$
 or $\times 0.3430 = SO_4$.

Sodium Chloride. Ten grams of the siliente of soda are dissolved in 100 ee. of water and made acid with HNO₃ in slight excess and then alkaline with MgO. Cl is titrated with standard AgNO₃ solution.

Water. This is determined either by difference or by taking 10 grams to dryness and then heating over a flame and blasting to constant weight.

Note. For detailed procedures for each of the above see special subject.

ANALYSIS OF SAND, COMMERCIAL VALUATION

Silica. Two grams of the finely ground material are fused in a platinum erucible with 10 grams of fusion mixture $(K_2CO_3+Na_2CO_3)$ by heating first over a low flame and gradually increasing the heat to the full blast of a Méker blast lamp. When the fusion has become clear it is cooled by pouring on a large platinum eover. The fused mass on the eover and that remaining in the platinum crucible are digested in a covered beaker with hot hydrochlorie acid on the steam bath. The solution is now evaporated to dryness, taken up with a little water and 25 ee. of concentrated HCl and again taken to dryness. Silica is now determined by the procedure outlined under the general method on page 436.

Ferric Oxide and Alumina. The filtrate is oxidized with crystals of solid potassium ehlorate, KClO₃, and iron and aluminum hydroxides precipitated with ammonia. The precipitate is filtered, washed, ignited and weighed as Al₂O₂+Fe₂O₃.

Calcium Oxide. To the ammoniaeal filtrate 10 ec. of ammonium oxalate solution are added, the solution heated to boiling and the precipitate allowed to settle until cold. The solution should not be over 200 ce. The calcium oxalate is filtered off, washed and ignited. The residue is weighed as CaO.

Magnesium Oxide. The filtrate from the lime is made strongly ammoniacal and 10 ee. of sodium ammonium phosphate added. The solution during the addition is allowed to stand cold for some time, three to four hours. The precipitate is filtered and washed with dilute ammonia (1 of reagent to 3 parts of water), then ignited and weighed as Mg₂P₂O₇. This weight multiplied by 0.3621 = MgO.

For more detailed directions see the individual subjects under the chapters devoted to the element.

SILICON 449

Silicon in Cast Iron and Steel

One gram of pig iron, cost iron, and high silicon iron, or 5 grams of steel, wrought iron, and low silicon iron are taken for analysis. (By taking multiples of the factor weight 0.4693, SiO₂ to Si, the final calculation is simplified.) The sample is placed in a 250-cc. beaker and 20 to 50 cc. of dilute nitric acid added. If the action is violent, cooling the beaker in water is advisable. When the reaction subsides, 20 cc. of dilute sulphuric acid, 1:1, are added, the mixture placed on the hot plate and evaporated to dense white fumes. The residue is taken up with 150 cc. of water containing 2 to 5 cc of sulphuric acid and heated until the iron completely dissolves.

The solution is filtered and the silica residue washed first with hot dilute hydrochloric acid, sp.gr. 1.1, and then with hot water added in small portions to remove the iron sulphate. The residue is now ignited and weighed as silica.

NOTE. If the ash is colored by iron oxide, silica is determined by difference, after expelling the silica by adding 4 to 5 cc. of hydrofluoric acid and a few drops of sulphuric, taking to dryness and igniting the residue.

The following acid mixtures are recommended by the U. P. Ry. For steel, wrought iron and low silicon iron, 8 parts by volume of HNO₃, sp.gr. 1.42; 4 parts of conc. H₂SO₄, sp.gr. 1.84; 6 parts HCl, sp.gr. 1.2 and 15 parts by volume of water.

Silicon in Ferro Silicon

Decompose the alloy with Eschkas mixture (Na₂CO₃-MgO) fusing in a platinum (or nickel) crucible. Dissolve the fusion in HCl and evaporate to dryness. Bake the residue at 135° and take up with HCl and water. Filter, wash and ignite to SiO₂. If titanium is present make a cold acid extraction and digest for one hour with dilute HCl. Take to fumes with 2 ec. H₂SO₄. Take up with water, filter, wash and ignite residue to SiO₂.

 $SiO_2 \times 0.4693 = Si$

Causes of Error in Silica Determinations

F. G. Hawley (Min. Eng. Jour., March 31, 1917) states the following:

It has been shown that there are three main sources of crror in the method commonly used for the determination of silica: A plus error from the small amount of SiO₂ from the flux; another plus error due to impurities retained by the SiO₂; and a minus error due to the solubility of SiO₂ in HCl.

By far the largest and most troublesome error is the one due to the solubility of the SiO₂ in the HCl. This error is much greater than most chemists realize.

The amount of freshly precipitated SiO₂ that dissolves in HCl, depends on the following conditions: First, the amount of acid present; second, the strength of the acid; third, the temperature; and fourth, the length of time the silica is in contact with the acid. There may be other conditions governing the solubility of SiO₂ in HCl but these seem to be the principal ones. By far the most important is the amount HCl, but these seem to be the principal ones. By far the most important is the amount of acid used.

Most chemists use acid of about the same strength to treat the dehydrated silica, and the assays are brought to a boil, insuring the same temperature, and are boiled for a fairly uniform length of time. Few, however, consider the importance of using a definite amount of acid. It seems to be a prevalent idea that the amount of silica dissolved by the acid solution is proportional to the amount of SiO₂ in the sample. When a small bulk of acid is used, this is certainly not the case. Experiments prove clearly that when a small amount of SiO₂ is present, the amount dissolved is proportional to the quantity of acid solution present and not to the amount of SiO₂ in the sample. 450 SILICON

Recommended Procedure for Silica (Hawley's Method)

A modification of the peroxide method, as used for routine work, is as follows: Weigh 0.5 gram of pulp into a 30 ce. nickel crucible and add one scoopful (about 4 grams) of flux composed of equal parts of sodium peroxide and sodium hydroxide. Mix the pulp and flux, and if the sample is known to contain over 50% of SiO₂ put on a cover to prevent loss. Fuse at a low temperature, beginning much below redness and increasing very slowly until a dull red is reached.

and increasing very slowly until a dull red is reached.

When the fusions are made as described the nickel crucibles can be used from 20 to 40 times, but if the temperature is too high, or if there is too much sodium peroxide

in the flux, they will burn out much quicker.

Remove the crucibles and partly cool; place in 4-in. casseroles, and cover the crucibles with 2-in. watch glasses so placed that a slight opening is left on one side. Through this opening squirt in 2 or 3 cc. of warm distilled water from a wash bottle. This should start a vigorous reaction between the water and the flux. As soon as the action has somewhat diminished add 3 or 4 cc. more water and continue to do this until the fused mass is disintegrated. Toward the end the water should be added with enough force to thoroughly stir the contents. If the crucible gets too cold or the water is not hot enough, the action may cease before the melt is loosened from the crucible; and if too hot the contents may boil over. With a little practice the right conditions are readily found. As soon as the action ceases and the crucible is a little over half full, rinse off the watch glass and from a large burette add about 10 cc. of 60% HCl in small portions so as to avoid too violent reaction; then add 90% HCl until it is in excess. The crucible should now be about full and everything in solution except possibly a little gelatinous silica.

except possibly a little gelatinous silica.

With the fingers or platinum-tipped tongs, remove the crucible, rinse, and place the casserole on the hot plate to evaporate. No harm is done if it boils gently at first. When about half evaporated, place the casserole on an iron or aluminum ring so made that the bottom of the casserole is kept about one-quarter inch above the hot plate. These rings are very beneficial in preventing spitting. When the residue has become dry, cover with a watch glass and bake at about 125° C. for 30 min.; remove and when cool add 15 cc. of 60% HCl and turn about so as to moisten all parts of the residue. Allow to stand a short time and then put on the hot plate, and with cover still on, boil for 3 min. Remove and allow to cool, rinse the sides down with the minimum amount of warm distilled water, and swirl around to loosen any crust still adhering to the sides. The NaCl does not all dissolve, but will readily do so in the wash water.

It is very necessary that the casserolc should not be heated after rinsing down the sides with water. After standing a few minutes, transfer the contents to a filter and wash twice with warm water; then once with hot dilute HCl and add a little to the casserole. Rub the sides and bottom of the casserole to loosen any adhering SiO₂ and rinse into the filter. This SiO₂ is ground rather fine by the rubbing and has a tendency to clog the filter, hence it is better to add this after the main portion has been partly washed. Wash the filter twice again with water, place in a crucible, partly dry, and ignite strongly for ten minutes. Weigh the SiO₂ as soon as cool, for it is hygroscopic. A correction is now made for the SiO₂ lost in solution, which under these conditions will amount to about 0.4%. A deduction is made for impurities in the SiO₂ and the SiO₂ from the flux. These gains about balance the solubility loss. Occasional tests should be made to check these losses and gains.

Ag, at.wt. 107.88; sp. gr. 10.50-10.57; m.p. 960.5° C.; b.p. about 1950° C.; oxides, Ag₁O, Ag₁O₂

DETECTION

A trace of silver in most substances is detected with greatest certainty by furnace assay methods.

The wet method of detection of silver most commonly practiced, depends upon observation of the properties of the precipitate formed by the addition of a not excessive amount of alkaline chloride to a cold nitric or sulphuric acid solution of the substance undergoing examination. One-tenth milligram of silver precipitated as silver chloride in a cold 200-cc. acid solution gives a very perceptible opalescence to the liquid.

Silver chloride is white when freshly precipitated, tinted pink when palladium is present; in colorless liquids on exposure to light turns brown, violet, blue or black. By agitation, heating or long standing the precipitate becomes coagulated or granular and in such a state is retained by an ordinary filter. The presence of some forms of organic matter prevents coagulation.

Silver chloride is dissolved by concentrated hydrochloric acid; raising the temperature of the acid assists the action. It is dissolved by sodium thiosulphate, alkali cyanides, mercuric nitrate, and alkaline chlorides.

From mercurous chloride, silver chloride, except when constituting a small proportion of the precipitate, is distinguished by its solubility without decomposition in ammonia. Precipitation from its animoniacal solution is accomplished by acidifying. Lead chloride, precipitable also by hydrochloric acid, is not flocculent, does not coagulate, but dissolves quite freely by heating. Addition of hydrochloric acid to a solution of silicon, tellurium, thallium, tungsten or molybdenum may produce a precipitate, in each case, easily distinguishable from that of silver chloride, but may mask traces of the salt.

Silver, in a cold solution containing free nitric acid, only a small amount of colored salts and no mercury, may be detected through the formation of a white precipitate, similar in appearance to silver chloride, by addition of a slight excess of an alkaline thiocyanate.

When a solution of silver salt is added to a mixture of 20 cc. ammonium salicylate (20 grams, salicylic acid neutralized with ammonia, a slight excess added and the whole made up to 1000 cc.) and 20 cc. of a 5% solution of ammonium persulphate added, an intense brown color is produced, which will detect the presence of a 0.01 milligram of silver. Lead does not affect the test.

When it appears that the chloride or thiocyanate test for silver is not positive on account of the presence of other precipitable elements, the precipitate, after it

Chapter contributed by W. G. Derby.

settles, is filtered through the finest quality of paper, and the mixture of the ash of the incinerated filter with dry potassium carbonate heated on charcoal with a mouth blowpipe. If silver is present and not associated with a large amount of palladium, there will be found on the charcoal pellicles of the color characteristic of silver, which have no white or yellow sublimate when melted in the oxidizing flame of the blowpipe. The pink palladium salts of silver precipitated by a chloride or thiocyanate before the blowpipe produces metal which is dull in appearance and not readily melted.

Notes. Silver may be recognized in a solution of concentration 1 to 240,000 by the reduction of its salts with alkaline formaldchyde. Whitby's 2 method of detection and estimation of small amounts of silver depends upon the formation of a yellow color through addition of sucrose and sodium hydrate. Ammonium hydrate interferes, but bismuth, cadmium, copper, mercury of either valence, lead or zine, in amounts equal to that of the silver, do not.³ Maletesta and DeNola add to the solution to be tested a few drops of a solution of nitrate of chromium and then potassium hydrate to alkalinity. A brownish turbidity or black precipitate of silver oxide forms. The limit of sensitiveness is 0.5 milligram in 100 cc.

ESTIMATION

Silver is determined in copper, lead, silver, sulphur or other ores, in copper and lead furnace by-products, and in lead by furnace assay methods, in which a preliminary acid treatment of the sample is rarely employed; in native copper ore, in copper, copper alloys, gold, gold alloys and in the slime from the electrolytic refining of copper or lead by furnace methods, in which a preliminary acid treatment of the sample is employed, in silver alloys by volumetric or gravimetric methods: in mercury by a gravimetric method; in cyanide mill solution or solutions containing much organic matter by furnace process on the residue obtained by evaporation or precipitation; in silver plating electrolyte by electrolysis.

Solubility. Nitrie acid, dilute or concentrated, attacks silver rapidly when hot. The presence of a soluble chloride, iodide or bromide in the solvent or substance will retard and may prevent solution. Unless oxidizing agents are present, dilute sulphuric acid has practically no action on massive silver, but hot, strong acid commences to be an active solvent at a concentration of 75% H₂SO₄. Hydroehloric acid attacks silver superficially. The action of alkaline hydrates or earbonates in solution is inappreciable; in a state of fusion, slight.

Furnace Assay Methods. These will be described in the chapter devoted to that subject.

Armani and Barboni, Zeit. Chem. Ind. Kolloide, 6, 290.
 Zeit. Anorg. Chem., 67, 62; C.A., 4, 1444.
 Bull. Chim. Farm., 52, 533.

GRAVIMETRIC METHODS FOR THE DETERMINATION OF SILVER

Precipitation as Silver Chloride 1

Introductory. Although silver might be determined as an iodide or bromide, the fact that these halides are more sensitive to light than the chloride, and decompose more readily, with liberation of the halide and the formation of sub-halides, has led to the precipitation of silver as the chloride.

Reaction. AgNO₃+HCl=HNO₃+AgCl.

Reagents. Hydrochloric Acid. One volume of strong HCl (sp.gr. 1.19) diluted with five volumes of water (sp.gr. of dilute HCl 1.035); 1 ee. eontains 0.074 g. of HCl, equivalent to 0.219 g. of Ag.

Nitric Acid. One volume of strong HNO₃ diluted with 1.6 volumes of water (sp.gr. of acid is 1.2); 1 cc. contains 0.38 g. of HNO₃, which would dissolve 0.64 g. of Ag.

1. Preparation of the Sample. Solution. Silver Alloys. Place 0.5-1.0 gram of the alloy in an Erlenmeyer flask and add 5 ee. of the dilute nitrie acid. Heat gently until the alloy is dissolved and the brown fumes are expelled. The solution is now diluted to about 100 ee. and the silver precipitated as stated below.

Soluble Silver Salts. The salt is weighed into a weighing bottle; 1.0-2.0 grams are sufficient for a determination. The solution is now diluted to about 100 cc. and the silver precipitated as stated below.

The Halides of Silver. These are best brought into solution by fusion with about six times the weight of the sample of sodium earbonate. This converts the silver into the carbonate and the halide combines with sodium and is dissolved out in water. The silver carbonate is washed free of the halide and then dissolved out in dilute nitrie acid.

Ores of Silver. These may be brought into solution by digestion with nitric acid, the residue remaining is treated as stated above under halides of silver. Unless the ore is very high in silver, it is preferable to make the analysis by Fire Assay.

2. Precipitation of Silver Chloride. Heat the solution to boiling and add from a burette, drop by drop, 5 ec. of dilute hydrochloric acid. This is sufficient to precipitate over 1 gram of silver. The excess of acid is desired as the chloride is less soluble in free hydrochloric acid.

Note. The chloride is soluble in strong hydrochloric acid, hence a large excess is undesirable. Shaking or vigorously stirring the mixture will clear a cloudy solution. This is necessary to coagulate the silver chloride, as the fine suspended silver chloride will pass through the filter paper.

- 3. Filtration: (Procedure if Filter Paper is Used). Decaut the clear solution into the filter. Test the filtrate with a drop of dilute HCl to make sure all the silver is precipitated. Now wash two or three times by decantation, using hot water containing 1 cc. of HNO₃ per 100 cc. of distilled water. Transfer the silver salt to the filter and continue washing until free from chlorides. Six to eight additional washings should be sufficient.
 - 4. Dry the filter and silver salt in the oven at 100-110 degrees C.
- 5. Remove as much of the silver chloride as possible from the paper, placing the salt on a glazed sheet of paper, covering it with a watch glass.

¹ Contributed by Wilfred W. Scott.

- 6. Ignite the filter in a crucible (whose weight has been ascertained), then add to the ash a drop of nitric acid and a drop of hydrochloric acid. Heat gently to expel the acids. (Handlo the crucible with tongs. Do not place on the table.)
- 7. Transfer the chloride from the glazed paper to the crucible and heat gently until the salt just begins to fuse on the sides of the crucible.

8. Cool in a desiccator for fifteen to twenty minutes.

9. Weigh as AgCl, making an allowance for the weight of the crucible. $AgCl \times 0.7526$ gives the weight of Ag in the salt.

10. Calculate the per cent silver from the weight of sample taken.

3a. Procedure if a Gooch Crucible is Used. Prepare a Gooch crucible with a fairly thick pad of asbestos fibre (1/8 in. thick). Wash once with alcohol and dry to constant weight at 110 degrees C. Keep a record of the weight.

4a. Wash the precipitate by decantation, pouring the washings through the Gooch, with application of suction. Transfer the chloride to the crucible and wash free of chlorides.

5a. Finally wash once with alcohol and dry at 110 degrees C. to constant weight.

6a. Calculate the percentage of silver as directed in the first method.

NOTES. Solubility of the silver halides. Milligrams of salt per 100 cc. of water. AgCl 0.00017; AgBr 0.00004; AgI 0.00001.

Interferences. Antimony, mercury, and lead interfere and should be removed if present.

Paper is separated in the first procedure as the carbon reduces the salt to metallic silver, causing low results.

Gooch. If the asbestos fibre is poor, a loss of the fibre will occur during washing of

the precipitate, causing low results.

Light. Strong light will affect the salt causing the formation of the subhalide of A drop of nitric followed by a drop of hydrochloric This treatment is necessary only when a darksilver and the liberation of chlorine. acid will restore the original form. colored salt is obtained by light action.

Large Samples. It is frequently advisable to dissolve larger samples than stated.

The solution is made to 500 cc. and a portion taken for analysis.

Solubility. Nitric acid, dilute or concentrated, attacks silver rapidly The presence of a soluble chloride, iodide or bromide in the solvent or substance will retard and may prevent solution. Unless oxidizing agents are present, dilute sulphuric acid has practically no action on massive silver, but hot, strong acid commences to be an active solvent at a concentration of 75% H₂SO₄. Hydrochloric acid attacks silver superficially. The action of alkaline hydrates or carbonates in solution is inappreciable; in a state of fusion, slight.

Determination as Silver Cvanide

In the analysis of mercury, the nitric acid solution of the metal is nearly neutralized with a solution of sodium carbonate. Potassium cyanide solution is then added until the precipitate, which first forms, is dissolved. Then under a hood with strong draft, dilute nitric acid is added in slight excess of the quantity required to combine with the base in the amount of potassium cyanide present. The precipitate of silver cyanide, practically insoluble in dilute nitric or hydrocyanic acid, is coagulated by stirring or long standing and filtered from the cold solution of mercuric nitrate by use of a tared paper-bottomed Gooch crucible. The preeipitate is washed with cold dilute nitric acid (1-10) until a test of the washings with hydrogen sulphide shows the absence of mercury. The crucible is dried at 100° to constant weight.

 $AgCN \times 0.8057 = Ag$.

Notes. Determination of silver as metal through precipitation with hypophosphorous acid 2 as silver sulphide or as silver chromate 4 are methods of doubtful technical application.

Exner, using a platinum dish as the cathode and a 2-in. diameter bowl-shaped spiral anode revolving 700 R.P.M., deposited 0.4900 gram from about 125 ee. of a hot electrolyte containing 2 grams potassium eyanide in ten minutes at N.D. 100 2 amps.

The above methods presume the absence of other metals precipitable under the conditions mentioned.

Electrolytic Method b

According to the strength of the silver bath 10 or 20 cc. are filtered into a tared 200-cc. platinum dish and according to the greater or smaller excess of cyanide present, ½ to 1 gram of potassium cyanide in solution is added. The electrolyte diluted to about a half inch from the edge of the dish is kept, by a flame underneath, at a temperature of 60°-65° C. during the period of electrolysis at $N.D._{100} = 0.08$ amp.

Complete precipitation, which requires three to three and a half hours, is recognized by test with ammonium sulphide. Without interruption of the current, by use of a siphon, displacement of the electrolyte with water is accomplished. The dish is rinsed with alcohol and ether, dried at 100°, weighed and silver obtained calculated to grams per liter or cubic foot.

Notes. Benner and Ross 6 deposit 0.15 gram in twenty minutes with a current of 3 amperes from 50 ee. of electrolyte containing 8 grams potassium cyanide and 2 grams potassium hydrate on a 9-gram platinum gauze cathode.

- ¹ Z. anal. Chem., 48, 79. L. E. Salas in communication with the author.

 ² Mawrow and Mollow, Zeit. anorg. Chem., 61, 96.

 ³ Gooch and Bosworth, Am. J. Sci., 27, 241.

 ⁴ J. A. C. S., Sept., 1903, 900.

 ⁵ Langbein, "Electro-Deposition of Metals," 6th Ed.

- J. A. C. S., July, 1911, 1106.

VOLUMETRIC METHODS FOR DETERMINATION OF SILVER Volhard's Thiocyanate Method ¹

This method is especially adapted to the determination of silver in cold dilute nitric acid solution. The method is based on the greater affinity of silver ions than ferric for thiocyanate ions. When the silver has been precipitated as thiocyanate, the ferric indicator reacts with the thiocyanate producing the characteristic red color.

Reactions: $AgNO_2+KCNS=KNO_3+AgCNS$ ppt. $Fe(NO_3)_2+3KCNS=3KNO_3+Fe(CNS)_3$ red

Note. Mercury and palladium, highly colored salts of cobalt and nickel, copper if over 60% in the sample, nitrous acid and chlorine interfere and should be absent.

Ferric Indicator. Saturated Solution. Make 100 cc. of a saturated solution of ferric ammonium sulphate or ferric sulphate. Add sufficient HNO₃ (freed from nitrous acid by heating) to clear up the solution and produce a pale yellow color, .5 cc. of this reagent is used in a test. Ferric nitrate may be used in place of sulphate.

Standard Silver Solution. A N/10 solution contains per liter 10.788 grams of silver, or 16.989 grams of AgNO₃. A solution containing 0.005 gram of Ag per cc. is a convenient strength.

Dissolve 1.0 gram of pure silver foil in 10 cc. of dilute HNO₃, 1:1.6 (sp.gr. 1.2). Boil to expel the nitrous oxides and dilute to 200 cc. 1 cc. will contain 0.005 gram of silver.

Thiocyanate Reagent. Dissolve 7.4 grams NH₄CNS or 9.2 grams of KCNS in water and dilute to 1000 cc. Standardize the solution against the standard silver solution. Half this strength is used for the weaker silver solution above.

Standardization. Measure 50 cc. of the standard silver solution into a beaker or an Erlenmeyer flask and dilute to 100 cc.

Add .5 cc. of the ferric indicator.

Titrate with the thiocyanate reagent until a permanent red tint is obtained. Each addition of the reagent will produce a temporary red color which fades immediately as long as any silver remains uncombined with the thiocyanate. A trace of excess of the reagent produces a permanent faint red color.

Note the cc. required and calculate the value of 1 cc. in terms of silver. 50 cc. of the standard silver solution contains 0.25 g. of Ag.

Some prefer to have the thiocyanate exactly equal in strength to the silver solution. Should this be desired, dilute to the necessary volume and again starfdardize against the silver solution.

The value of 1 cc. should be recorded on the container.

Determination of Silver in the Unknown

Weigh 0.25-0.3 gram of the alloy and dissolve in an Erlenmeyer flask by addition of 5 cc. of dilute HNO₃ (sp.gr. 1.2). Heat to expel lower oxides.

Cool, dilute to about 100 cc. and add 5 cc. of the ferric indicator.

Titrate with the standard thioeyanate reagent to a permanent faint red color.

From the cc. of the reagent used, calculate the amount of silver present in the sample taken.

Divide the result by the amount of sample taken and multiply by 100 = per cent Ag in the alloy.

¹Contributed by Wilfred W. Scott.

GAY-LUSSAC METHOD

This very accurate method is especially adapted to the valuation of silver bullion, but may be applied in principle to the determination of silver in a nitric acid solution which contains as little as 100 milligrams of the metal, providing the volume of the solution is not so large or color so deep as to make a precipitate of silver chloride equivalent to 0.1 milligram of silver indistinguishable. Metals that interfere are mercury and tin.

The method is founded upon the almost absolute insolubility of silver chloride or bromide in cold dilute nitric acid and the property of the precipitate becoming so completely coagulated through agitation that it settles speedily, leaving a liquid sufficiently clear to permit of observance of any precipitate produced by further addition of precipitant.

Reactions: AgNO₃+NaCl=NaNO₃+AgCl \(\) $AgNO_3 + NaBr = NaNO_3 + AgBr \downarrow$

The use of a bromide is preferable to a chloride salt as a reagent, ehiefly because on account of the greater insolubility of silver bromide, the end-point of the operation of titration is more sharply defined.

The presence of free sulphurie acid is prejudicial to a very close determination, because of the volume of liquid required to keep silver sulphate in solution, and also because the result of agitation after addition of precipitant is apt to be a fine precipitate which does not readily settle.

The factor of volume change per degree change of temperature from 15 to 21° C. is approximately 0.00012; from 20 to 26°, 0.00019; from 25 to 31° C., 0.00024.

Although the approximate precipitating value should be known by previous test, it is the better practice to determine the exact value by running two or more cheeks of pure silver simultaneously with each batch of assays than to apply the temperature correction factor.

Apparatus. The apparatus required eonsists of a pipette which will deliver approximately 100 ce. with an accuracy of not over 5 milligrams variation in weight of the standard solution at constant temperature be tween successive deliveries, 10 ce. burettes with glass stopcocks; and 8-oz. narrow mouth, round, flint-glass bottles with high, tightly fitting stop- Fig. 59. Apparatus for Gay-Lussac Method. pers; the assay bottles should be of a quality which will endure heating in a steam bath or on a hot plate.



Since the end-point by the Gay-Lussac method depends upon the observance of cessation of precipitation, it is evident, in order to avoid undue tediousness in its operation, that the silver content of the amount of sample taken for assay should be known within a few milligrams.

METHOD OF U. S. MINTS

U. S. Mint Modification of the Gay-Lussac Method for Silver 1

This method is used in all three of the United States Mints and the U. S. Assay Office, New York City, for determining silver in ingots and fine silver has been found very satisfactory both as regards speed and accuracy.

Standard Solutions. Two standard salt solutions are regularly used in the determinations. The first is called a "normal" and the second a "decimal" solution

The first or. "normal" solution is made of such concentration that 100 cc. of it will precipitate exactly 1002 milligrams of silver. 5.43 grams of C. P. sodium chloride are dissolved in water and diluted to make one liter of solution. It is kept in a large 40-liter earboy and is siphoned off as needed.²

The decimal solution is made by diluting 100 cc. of the "normal" solution to a liter.

Standardization

The normal solution must be standardized at frequent intervals because of temperature changes which affect the concentration of the solution. The factor of volume change per degree change of temperature from 15 to 21 degrees C. is approximately 0.00012; from 20 to 26 degrees, 0.00019; from 25 to 31 degrees, 0.00024.

The standardization is earried out as follows:

Solution and Precipitation. A "proof" of 1004 milligrams of fine silver is carefully weighed out, placed in a glass-stoppered 8-oz. bottle and dissolved in 10 ee. of 1:1 nitrie acid on a hot plate. Then 100 ee. of "normal" salt solution, sufficient to precipitate 1002 grams of silver, are added from an upright stationary pipette. The pipette is filled by means of a siphon controlled by a stopcock convenient to the right hand. After filling, the left forefinger is placed over the pipette, the rubber hose connection removed from the bottom, and the bottle containing the dissolved proof placed underneath, when the forefinger is removed, allowing the contents to drain into the bottle, shaking the bottle once or twice to mix the solution. Then 2 cc. of the decimal solution are added by means of a small pipette graduated in ee. and held in the hand, and the stoppered bottle is placed in the shaker.

The shaker violently agitates the solution and causes the precipitate to

coagulate and settle. The bottle is removed after four minutes.

More agitation than is absolutely necessary should be avoided, due to the increasing tendency of the precipitate to become granular and settle slowly.

¹ Communicated to W. W. Scott by F. C. Bond, Humid Assayer, Denver Mint, Colorado.

² 40 liters are made up at one time by the Denver Mint. The strength of the solution may be regulated by the size of the pipette used. At the Denver Mint 4.82608 grams per liter are taken of the C. P. NaCl, since the pipette delivers more than 100 ec.

Titration. The bottle containing the coagulated precipitate is best placed upon a shelf in a window through which only reflected light enters, at such a height that the top of the solution is upon a level with or slightly above the eye. The shelf is backed by a blackened board which covers the window under the shelf and extends nearly to the top of the bottle.

The bottle stands a moment to allow the precipitate to settle and 1 cc. of the decimal salt solution is added from the hand pipette. The solution is shaken by moving the top of the bottle through a small are once or twice and the reading is taken after 10 seconds. A slight white cloud forming at the top of the solution and more pronounced when viewed from below constitutes a "show" and indicates that only a small portion of the cc. added was needed to precipitate the remaining silver. This is the desired condition for a proof.

The reading is taken as a "show," "quarter," "half," "three quarters," and "one"; according to the portion of the cc. of salt solution necessary to precipitate the remaining silver. If the cloud is deep enough to indicate that all of the cc. has been used, the bottle should be placed in the shaker and the precipitate coagulated, after which another cc. is added and the reading taken as hefore with the addition of one cc.

The assignment of the proper value to the precipitate is difficult for the novice and experience in comparison is of much more value than any description could be. However it may be stated that a slight precipitate extending through the upper half of the solution after a slight uniform shake should be called a "quarter," a precipitate of the same appearance throughout the solution is a "half," a heavier precipitate throughout is called "three quarters," while a still denser precipitate is read "one" and should he confirmed by shaking and adding another cc., which should yield a "show," a very faint cloudiness.

The "show" of the proof influences the reading of the determinations and its appearance should be kept constantly in mind, since a "quarter" on a determination means that one quarter of a cc. more of the decimal salt solution was used in precipitating silver than was used in the proof. Thus the proof reading or "show" is taken as zero and the concentration of the "normal" solution should be adjusted so that the proof gives as light a show as possible.

Procedure. In the following determinations it is advisable to run a standard of proof silver side by side with the sample bullion for comparative purposes.

Fine Silver. For silver bullion 998 parts fine or above a sample of 1005 milligrams is weighed out, dissolved, precipitated and titrated as described under Standardization.

In case 1 cc. was added, gave a heavy precipitate, was agitated and a second cc. added which gave a "half," the reading would be $1\frac{1}{2}$ and the silver would be

$$\frac{1002+1\frac{1}{2}}{1005} = \frac{1003.5}{1005} = 998.5 \text{ fine.}$$

In case a large number of samples are to he run, tables may be prepared for each fourth of a ec. which will make the above calculation unnecessary.

Coin Ingots. In determining the silver in silver coins or in silver coin

ingots as they come from the melting room, which are usually within 1½ points of 900 fine, the sample weighed is 1115 milligrams. The color given to the solution by the copper base need not interfere with the titration.

Notes on the Method

Determinations may be made on silver bullion of almost any grade if the approximate fineness is previously determined by fire assay or the Volhard method. It is ordinary practice to weigh up the sample at the next figure even five milligrams above that calculated. Thus if it is found from preliminary assay that 1082 milligrams of bullion will contain approximately 1002 milligrams of silver, 1085 milligrams will be unified out for an approximately 1002 milligrams of silver, 1085 milligrams will be weighed out for a sample.

Interfering Elements. There are very few substances which will be found in bullion in sufficient quantity to interfere with the process. The presence of free sulphuric acid is detrimental to a very close determination.

The use of a bromide is considered as preferable to a chloride as a reagent but the chloride is commonly used.

An eyeshade assists in making the readings accurately.

Fig. 59a.1

The chloride precipitate is reduced to a blue subchloride on standing in the sunlight so that the bottle should be exposed to the light as little as possible.

A set of twelve samples, with the bottles transported in a suitable wire frame, is usually run at one time.

A decimal solution of silver nitrate of equal strength with the decimal salt solution may be used for back titration, however the end-point is less distinct and it is advisable to weigh out a larger sample.

Duplicates are commonly run.

Tables giving the fineness for different classes of materials examined for each reading facilitate calculations and are recommended for use.

To determine the \(\frac{1}{2}, \frac{1}{2}\) and \(\frac{2}{3}, \text{ a beginner should have a pipette, graduated in 1 ce., holding 5 to 7 ce. length for hand use with one cc. divided in the \(\frac{1}{3}, \frac{1}{3}, \text{ and he should use the same until he is familiar with the density of precipitates produced by one cc. with silver equivalent to the above fractions.

WEIGHT TAKEN 1115 MG.

	0	1	2	3	4	5	6
0	896.9	897.7	898.6	899.6	900.4	901.3	900.2
	897.1	898.0	898.9	899.8	900.7	901.6	902.5
	897.3	898.2	899.1	900.0	900.9	901.8	902.7
	897.5	898.4	899.3	900.2	901.1	902.0	902.9

No pipette is of use in the practice of the Gay-Lussac method which shows any tendency to spatter at the beginning or ending, or yields a quickly following or clinging drop at the completion of discharge. The film of liquid adherent to the inner surface of the body of a good pipette will drain without sign of rivulet effect and be retained by the capillary of the discharge tube for at least a minute.

In the following table the left hand column represents the milligrams of bullion to be taken, the top line indicates the cc. of decimal solution required in addition to the 100 cc. of normal solution, the figures at the intersecting lines give the fineness of the bullion.

Ascertain the approximate fineness by a preliminary assay, consult the 0 column for the nearest corresponding figure slightly higher, the figure on the left of this is the weight of bullion to be taken. Now if the test required, in addition to the 100-cc. normal solution. 4 cc. decimal solution and 1115 milligrams of bullion were taken, the fineness of the bullion would be 900.4. See table under Silver Coin Bullion.

High Grade Bullion

Milli- grams of Bul- lion	0	1	2	3	4	5	6	7	8	9	10
1000 1005 1010 1015 1020 1025 1030 1035 1040 1045 1050	1000.0 995.0 990.1 985.2 980.4 975.6 970.9 966.2 961.5 956.9 952.4 947.9	962.5 957.9 953.3	997.0 992.1 987.2 982.4 977.6 972.8 968.1 963.5 958.8 954.3 949.8	998.0 993.1 988.2 983.3 978.6 973.8 969.1 964.4 959.8 955.2 950.7	999.0 994.1 989.2 984.3 979.5 974.8 970.0 965.4 960.8 956.2 951.7	1000.0 995.0 995.3 985.3 980.5 975.7 971.0 966.3 961.7 957.1	991.1 986.3 981.5 976.7 972.0 967.3 962.7 958.1	997.0 992.1 987.2 982.4 977.7 972.9 968.3 963.6 959.0 954.5	998.0 993.1 988.2 983.4 978.6 973.9 969.2 964.6 960.0 955.4	999.0 994.1 989.2 984.4 979.6 974.9 970.2 965.5 960.9	1000.0 995.1 990.2 985.4 980.6 975.8 971.1 966.5 961.9 957.3
Silver Coin Bullion											
	0	1	2	3	4	5	6	7	8	9	10
1095 1100 1105 1110 1115 1120 1125 1130 1135 1140 1145 1150	885.0 881.1 877.2 873.4	910.0 905.9 901.8 897.8 893.7 889.8 885.8	915.1 910.9 906.8 902.7 898.6 894.6 890.7 886.7 882.8 878.9 875.1 871.3	916.0 911.8 907.7 903.6 899.5 895.5 891.6 887.6 883.7 879.8 876.0 872.2	917.0 912.7 908.6 904.5 900.4 896.4 892.4 888.5 884.6 880.7 876.9 873.0	913.6	902.2 898.2 894.2 890.3 886.3	919.8 915.4 911.3 907.2 903.1 899.1 895.1 891.1 887.2 883.3 879.5 875.7	920.5 916.4 912.2 908.1 904.0 900.0 896.0 892.0 888.1 884.2 880.3 876.5	921.5 917.3 913.1 909.0 904.9 900.9 896.9 892.9 889.0 885.1 881.2 877.4	922.4 918.2 914.0 909.9 905.8 901.8 897.8 889.8 889.9 886.0 882.1 878.3

Recovery of Silver from Silver Residues

Convert the residues to silver chloride by treating with hydrochloric acid and filtering off the chloride and washing. Dissolve the chloride in ammonium hydroxide added in slight excess. Add sodium hyposulphite, Na₂S₂O₄ (not thiosulphate, Na₂S₂O₃). Metallic silver is formed. Thiosulphate gives silver sulphide. Photographers' residues containing "hypo" yield silver sulphide.

Combination Methods

Combination of the operations of the Gay-Lussae and Volhard methods have been devised to avoid the tediousness incident to the performance of the Gay-Lussac method by the unexperienced. By the modified methods the amount of sample to be weighed out is determined by preliminary assay, and is dissolved in the same manner as in the practice of the Gay-Lussac method, but with the added precaution to decompose nitrous acid in the silver solution by gentle boiling when completion of the titration is to be accomplished by the Volhard method.

The operation of the combination methods consists briefly of precipitation of all but a few milligrams of silver by a standard solution of alkali thiocyanate, chloride or bromide added from the Stas pipette and estimation of the excess of silver with a decimal solution of thiocyanate or by a colorimetric or nephelometric method.

The procedure favored by the writer is to use a standard solution of potassium bromide as the pipette precipitant. After the liquid is cleared by shaking, it is decanted as completely as possible into a 500-cc. Erlenmeyer flask. The precipitate is washed by five 30-cc. portions of water containing a little nitrous-free nitric acid, each portion being shaken before decanting. Using the same amount of ferric indicator as in the check assays, decimal thiocyanate solution is added until not a very deep tint remains permanent after vigorous agitation. Decinormal silver solution is then added until the tint is discharged. When the assay is sufficiently free of copper or other colored salts to permit accurate matching of tints, the decanted liquid, which may contain particles of silver bromide without interference, is titrated with decimal thiocyanate to the appearance of a tint which will match that of the check assays. Except when colored salts are present in such quantity as to make recognition of the point of bleaching of the ferric thiocyanate coloration uncertain, the extreme range of error is 0.3 part per 1000.

For colorimetric method, see Smith, I.M.M Bull. No. 28. Determination of the residual silver in the filtrate from the thoroughly washed silver bromide precipitate is practicable by use of a suitable nephelometric apparatus.

Denige's Cyanide Method 2

Silver which has been precipitated as chloride may be determined volumetrically by dissolving the precipitate with a measured quantity of a standard solution of potassium cyanide of about decinormal strength.

$$AgCl+2KCN = KAg(CN)_2+KCl$$
.

Potassium iodide is then added and the excess of standard potassium cyanide solution determined by addition of potassium iodide and titration to the first appearance of a permanent precipitate with decimormal silver nitrate.

$$AgNO_3 + KI = AgI + KNO_3$$
; $AgI + 2KCN = KAg(CN)_2 + KI$.

Nor's. If the last portion of the precipitate of silver chloride dissolves with difficulty in the potassium cyanide, the liquid may be decanted into another beaker and solution completed with ammonia. The solutions are combined.

¹ Richards and Wells, Am. Chem. J., 235, 1903; Richards, ibid., 510, 1906; Richards, Com. 8th Int. Cong. Ap. Chem., Sec. 1, 423.

² Clennell, "The Cyanide Handbook," 433.

Miscellaneous Volumetric Methods

Silver may be determined by addition from a burette of a portion of a known volume of its neutral or slightly acid solution to a standard solution of sodium chloride which contains a little potassium chromate or bichromate and sufficient chlorine-free magnesium oxide emulsion to neutralize free acid. The end-point is indicated by the formation of a reddish or brown precipitate.

By Pisani's Method 1 a standard solution of iodide of starch is added to a very dilute neutral solution of nitrate of silver until the fluid becomes permanently blue.

By Vogel's Modification of Pisani's Method, the silver solution, which may contain free acid, is titrated with standard starch iodide solution after addition of nitric acid containing nitrous acid.

By Andrews' Modification, the standard solution of starch iodide is added to a solution of silver nitrate which contains so much ferrous nitrate or sulphate that iron will be in excess of the silver present.

$$2AgNO_3+2Fc(NO_3)_2+I_2=2AgI+2Fe(NO_3)_3$$

By Gooch and Bosworth's Method, silver is determined by precipitating with an excess of potassium chromate, dissolving the precipitate in ammonia, reprecipitating by boiling to low volume and determining iodometrically either the chromate ion combined with the silver, or that remaining after precipitating the silver with a known amount of standard potassium chromate.

Nephelometric Method

This method is practicable for the determination of a small concentration of silver in a clear and colorless liquid. Less than 2 mi ligram; of silver can be estimated with considerable accuracy by matching the opalescence produced by a drop of hydrochloric acid with that from a known quantity in a liquid of the same volume, depth and temperature. Intensity of opalescence attains the maximum in about five minutes after precipitation. Standard silver solution is made by dissolving 500 mill'g ams standard silver (see Preparation at close of chapter) with several cc. of dilute nitric in a liter flask and making the solution up to the mark. For most technical determinations the apparatus may consist of clear glass cylinders (color tubes) of suitable size. More accuracy can be arrived at by use of a nephelometer of refined construction, for example 6 the combination of a projection lantern and a Duboscq colorimeter.

Preparation of Pure Silver. The volumetric methods used for the determination of high percentages of silver, employ solutions which should be standardized by metal of the highest purity. For the preparation of this metal, the electrolytic method as described below is preferred by laboratories which are suitably equipped.

- Robière, Bull. Soc. Chim., 17, 306, 1915; J. S. C. I., Oct. 30, 1915, 1073.
 Fresenius, "Quantitative Analysis."
 Zeit. für Anorg. Chem., 26, 175.

- 4 Am. J. Sci., 27, 302.

1.

- ⁵ Am. Chem. Soc. Chem. Abs., Aug. 10, 1909, 1735. ⁶ Wells, Am. Chem. J., **35**, 99, 508; Richards, Am. Chem. J., **35**, 510; Dienert, Compt. rend., 159, 1117.

For the manufacture of a large quantity-several pounds-a basket-like support for the anode is made of several glass rods bent so that they will hang from the rim of a tall 1000-cc. or larger beaker or battery jar and dip into the receptacle about an inch.

Smaller anodes may be supported by the positive wire or by a cloth bag fixed in place by a string under the flare of the rim of the beaker. In any arrangement for the support of the anode, allowance of room should be made for the introduction and free movement of an L-shaped stirring rod.

The cathode may consist of sheet silver or of platinum foil, and lies flat on the bottom of the beaker. The immersed length of the silver or platinum wire leading from the eathode should be covered with rubber tubing.

Commercial silver, usually about 999 fine, may be used for the anode, but by retreatment of the deposit, very impure silver may be used, providing that the quantity of tellurium present is very low. The presence of tellurium will exhibit itself in the impossibility of obtaining the desired coarsely crystalline deposit.

Tellurium in moderate quantities may be removed by melting the silver in a crucible or scorifier, adding niter, permitting the silver to nearly freeze, raising the temperature and pouring into a hot crucible or scorifier in which the operation is repeated, preferably in a muffle furnace, until the surface of the silver is without streaks or spots when cooled to near freezing. An oxidizing atmosphere about the molten metal should be maintained. On the basis of 172 grams silver per cubic inch an anode mould for any convenient amount of silver may be shaped from 4-in, pieces of 1-in, square rod on a smooth iron plate. Just before the anode bar sets in the mould, a silver terminal strip or wire is plunged into it.

After easting the contact wire or strip and the surface of the anode about it with sealing wax, the anode is wrapped with filter paper, held firinly in place by string or rubber bands. If the anode weighs half a pound or more, the anode is also wrapped with cotton flannel which has been washed with water until free of chloride. A porous

dish, eylinder or filter cone can be used instead of filter paper and cloth.

The electrolyte contains about 4% of C.P. silver nitrate and half a per cent of chlorine-free nitrie acid in distilled water, and fills the beaker or jar so it wets only the lower surface of the anode.

The current, of about 0.1 ampere per square inch of eathode surface at the start, is raised after deposition has proceeded for a few minutes to the limit at which a coarsely

crystalline deposit can be maintained.

Inasmuch as the electrolysis proceeds at a rate of 4 grams per ampere hour, some attention is required to break up short circuits and to pack down the rather bulky deposit. The deposit, if coarse, can be washed very easily free of electrolyte, and after

heating to near redness is in the form preferred for use by many assayers.

Other methods which may be employed consist of dissolving the crude silver with Other methods which may be employed consist of dissolving the crude silver with nitric acid about 1.20 sp.gr. or with hot concentrated sulphuric acid, if platinum is present, separating the gold and platinum by filtration, precipitating AgCl with not too large an excess of HCl, stirring the precipitate until it coagulates, washing repeatedly with hot water until a washing is obtained which shows no precipitate with H_2S , reducing the silver chloride by contact with pure zine, wrought iron or the silver terminal of a carbon-silver couple aluminum foil, and washing with hot dilute HCl until a test of the decanted liquid indicates absence of the precipitating element. The dried silver, mixed with about 1% of dry sodium carbonate, is packed into a clay crucible, the inside of which has been glazed with borax glass and covered with a layer of crushed charcoal layer of crushed charcoal.

The sodium carbonate is omitted in case it is desired to melt silver refined by

electrolysis.

The silver melted in the tightly covered crucible is poured into an iron mould which

has been chalked or black leaded.

By Knorr's method, a solution of silver nitrate from which excess of nitric acid has been removed by evaporation is freed of metallic impurities by adding enough sodium carbonate to precipitate one-tenth of the silver, boiling and filtering. The silver in the filtrate is precipitated by sodium carbonate and the precipitate decomposed without addition of reducing reagent, by melting in a crucible. Excess sodium carbonate carried down with the precipitate of silver carbonate will cover the fusion and such as adheres tightly to the metal is readily removed by hydrochloric acid. The metal should be smelted under charcoal.

If the cover of the charcoal is omitted or burned away during the fusion, the molten metal is capable of absorbing oxygen from the atmosphere to the extent of about 0 25% of its weight. This gas is expelled during the passage of the metal into the solid state and produces a casting which cannot be rolled into smooth sheets

The most convenient size and shape of castings for rolling is but little larger than a

lead pencil. Before rolling, the casting is cleaned of particles of the mould wash After rolling to about cardboard thickness, the sheets may be cut up into strips of convenient size and length, then digested with dilute hydrochloric acid (1 to 5 of water) washed with ammonia and finally with pure water.

The silver then should be dried and annealed by heating to redness. It is best preserved in a glass-stoppered, salt-mouth bottle and should be exposed to laboratory atmosphere as little as possible.

The purity of each batch of silver made should be compared by use of the Gay-Lussac

method with standard silver, the purity of which has been determined by analysis of a 50- or 100-gm. portion for Se and Tc, As, Sb, Pb, Cu, Au, and the element employed in reducing silver chloride, if the reduction method was followed in the manufacture of the metal.

THE FIRE ASSAY FOR GOLD AND SILVER

Definitions. Fire assaying is a branch of quantitative chemical analysis in which metals are determined in ores and metallurgical products by extracting and weighing them in the metallic state. The methods employed involve slag-melting temperatures and the use of reducing, oxidizing and fluxing reagents, and are in principle the same as those used in metallurgy.

The metals ordinarily determined by fire assaying are gold, silver and platinum. Antimony, bismuth, lead and tin ean be determined in this way

also, but the results are usually more or less inaccurate.

An ore is a mineral aggregate from which one or more metals can be extracted at a profit.

Metallurgical products include a large number of metal-bearing mixtures and compounds, ranging from high grade gold and silver bullion to very weak cyanide and sulphate solutions.

The constituents of an ore arc usually divided into two general classes, the valuable minerals containing the *metals*, and the non-valuable minerals or gangue. A similar classification can be made in the case of many metallurgical products. In gold and silver bullion and other alloys all of the components arc metallic, and the assaying problems involve simply the separation of metals.

General Outline

With ores and metallurgical products containing non-metallic elements the process consists, briefly, in the production of two liquids, liquid lead containing the valuable metals, and liquid slag containing the waste matter or gangue. The two liquids separate from each other by reason of the great difference in specific gravity. The valuable metals are separated from the lead and from each other by taking advantage of differences in chemical properties. The slag is discarded.

In the operation of the process the gold and silver, and platinum, if present, are collected from the metal-bearing portion of the ore or metallurgical product by means of molten lead reduced from litharge or lead oxide. The gangue

is converted into a fusible slag by means of reagents known as fluxes.

The effectiveness of the fire assay in separating gold, silver and platinum from ores and metallurgical products depends upon two properties of these metals: first, their weak affinity for non-metallic elements, especially at high temperatures, and second, their very great affinity for molten lead. The collection of the precious metals in the lead, therefore, is the simplest part of the process. The fluxing of the gangue is much more difficult, and requires considerable knowledge and skill. If the fluxing is properly performed, the collection of the valuable metals usually takes care of itself.

Reagents. A flux is a substance which when heated in contact with some difficultly fusible compound either combines with it or takes it into solution,

¹ By Irving A. Palmer, Professor of Metallurgy, Colorado School of Mines.

in each case producing a compound or mixture which is easily fusible at ordinary furnace temperatures. The principal fluxes and other reagents used in fire assaying are described in the following paragraphs.

Litharge or oxide of lead, PbO, melting point 883° C., has several important uses. It furnishes the lead which collects the precious metals; it readily eombines with silica, producing easily fusible silicates; and it acts as an oxidizing and desulphurizing agent. It is a very strong basic flux.

Sodium carbonate, Na_2CO_3 , melting point 852° C., is a powerful basic flux. It combines with silica and alumina, producing fusible silicates and aluminates. When molten it has the property of dissolving or holding in suspension a number of refractory gangue materials. To some extent, also, it acts as an oxidizing and desulphurizing agent. Potassium carbonate, K_2CO_2 , melting point 894° C., is rarely used in fire assaying because of its greater cost.

Borax glass, Na₂B₄O₇, melting point 742° C., is an acid flux used for combining with or dissolving the basic and some acid constituents of the gangue, producing easily fusible complex borates and mixtures of borates and other compounds. Even silica dissolves to some extent in molten borax glass.

Silica, SiO₂, melting point 1755° C., is a strong acid flux. It combines with metallic oxides and produces silicates which in many cases are considerably more fusible than silica itself.

Granulated lead or test lead is used in the scorification assay, which is conducted under oxidizing conditions, and in which, therefore, litharge could not be employed as a source of lead.

Lead foil or sheet lead is used in the assay of gold and silver bullion. It, as well as the granulated lead, should be free from silver and bismuth.

Flour is known as a reducing agent. It contains carbon, which reduces lead from litharge. Charcoal was formerly used for this purpose, but it is not so convenient.

Argol or crude cream of tartar, KHC₄H₄O₆, is both a basic flux and a reducing agent. On being heated it decomposes as follows:

$$2KHC_4II_4O_6+heat\rightarrow K_2O+5II_2O+6CO+2C$$
.

It is effective in assays requiring strong reducing action and low temperatures.

Iron is sometimes used as a desulphurizing and reducing agent. It decomposes most of the heavy sulphides, yielding the metals and iron sulphide.

Potassium nitrate, KNO₃, melting point 339° C., is a powerful oxidizing agent. It is used to neutralize the effect of an excess of reducing substances in the material to be assayed. High sulphur ores, if assayed without previous roasting, require the addition of nitre to the charge. In contact with a reducing agent two molecules of potassium nitrate give up five atoms of oxygen, as shown in the following equation:

$$4KNO_3+5C\rightarrow 2K_2CO_3+3CO_2+2N_2$$
.

The potassium oxide coming from the decomposition of the nitre acts as a basic flux.

Common salt, NaCl, melting point 819° C., is a neutral substance sometimes used as a cover for crucible fusions to exclude the air. When molten it rests on top of the charge and does not enter into it.



Fig. 59a. Oil Muffle Furnace.

All of the reagents used must be pure and in a finely divided condition. Sodium carbonate shows a tendency to form lumps. These should be broken up and the entire mass put through a moderately fine screen.

Furnaces and Equipment. The major operations in fire assaying are usually conducted in muffle furnaces. The muffle is a box-like receptacle made of fire clay, so placed in the furnace that it is heated on top, bottom and all sides except the front. In it are placed the refractory vessels containing the material to be assayed. There is thus no direct contact with the fuel or products of combustion. The fuel used may be coal, oil, gasoline or gas.

Cupels. The separation of the precious metals from the lead alloys produced in fire assaying is effected in small shallow vessels of bone ash, known as cupels. The material consists mainly of calcium phosphate, with small percentages of magnesium phosphate, calcium fluoride and calcium carbonate. It is a product of the burning of animal bones, preferably those of the sheep. It should be ground fine enough to pass a 40-mesh screen, in which case about 50 per cent of it will pass a 150-mesh screen. The cupels are made by moistening the bone ash with a small amount of water and then compressing it in the cupel mould, which consists essentially of a ring and die. The bone ash

is forced into the shape dersied at a considearble pressure, so as to insure sufficient rigidity in the cupel. The amount of water needed varies, but should be as low as possible. The cupels should be dried very slowly, so as to avoid



F10. 59b. Muffle Furnace.

cracking. By using high pressures good cupels can be made from perfectly dry bone ash.

The requirements of a good cupel are that it should be infusible at ordinary furnace temperatures, that it should not be attacked by metallic oxides, that it should be porous, and that it should be sufficiently rigid to permit of considerable handling.

Cupels can be made of Portland cement, magnesia, or of mixtures of these materials with bone ash. They are considerably cheaper but not so satisfactory as those made of bone ash alone.

The Assay-Ton System. As the precious metals are bought and sold by the Troy system of weights and measures, and ores by the Avoirdupois system, considerable time would be lost in calculating assay results, were there no way of avoiding it. To simplify the calculation Prof. C. F. Chandler, of Columbia University, invented the assay-ton system of weights. The assay-ton is equal to 29.1663 milligrams. As there are 29,1663 Troy ounces in an Avoirdupois ton of 2000 pounds, the number of milligrams and fractions of a

milligram of precious metals found in an assay-ton of ore corresponds to the number of Troy ounces in an Avoirdupois ton.




Fig. 59c. Cross Section of Two-Muffle Assay Furnace.

Sampling. It goes without saying that good results in assaying presuppose accurate sampling. Silver is reported in assay certificates to the nearest tenth of an ounce; gold usually to the nearest one hundredth of an ounce. One tenth of an ounce means one part in 291,667; one hundredth of an ounce, one part in 2,916,667. In the preparation of the sample, therefore, the ratio between the weight of any fractional portion and the weight of the largest particle in it must be very large, so that the accidental inclusion of a number of rich pieces in any portion shall not affect the results beyond the limits of error assaying. The final pulp sample should be of a fineness ranging from 80-mesh, in the case of low grade silver ores, to as fine as 200-mesh in the case of non-uniform gold ores. Small particles of metallic gold in the material necessitate fine grinding and very thorough mixing. It is a good rule to mix all pulp samples on a rubber cloth before weighing the portions for assay.

Balances and Weights. The balances used in fire assaying are somewhat different from those found in chemical laboratories. They are known as flux, pulp and assay balances. The assay balances are for weighing the gold and silver, often exceedingly small in amount, and are the most delicate type of commercial balances made. They should be quick in action and not liable to changes in adjustment. The beam should be short, light and rigid. The

balance should be sensitive to .01 milligram at least. It need not have a capacity of more than .5 gram but should be accurate with that load.




Fig. 59d. Apparatus for Fire Assay.

In large laboratories separate balances are furnished for weighing the gold. These balances should be adjusted before each weighing and should be handled with the greatest of care. In the assay of gold ores, when using a half assayton portion, every error of .01 milligram in weighing the gold means a variation in the value of the ore of forty cents per ton.

The Crucible Assay. This method of fire assaying is adapted to the great majority of gold and silver ores and to many metallurgical products. The process consists in treating a weighed portion of the sample, carefully mixed with the necessary reagents, in a fire-clay crucible. In order to do this effectively the character of the material to be assayed must be known. Thus, ores may be oxides or sulphides. They may be basic, acid or neutral. They may be strongly oxidizing or strongly reducing. Each case requires a particular method of treatment.


The amount of sample usually taken is one half assay-ton, run in duplicate. Twenty-gram fire-clay crucibles are used, that is, crucibles capable of holding twenty grams of ore and the necessary reagents. In most cases the total charge will fill the crucible to within one inch of the top.

Lead Reduction with Oxidized Ores. Experience has shown that the best results are obtained when the lead reduced from the charge amounts to from 25 to 30 grams. If the ore is oxidized, a reducing agent must be added to precipitate the necessary lead. Flour is the reagent ordinarily used, although charcoal or argol can be substituted for it. The lead is reduced according to the following equation:

2PbO+C→2Pb+CO₂

That is, 12 parts of carbon theoretically will reduce 414 parts of lead from

litharge. Hence, the theoretical reducing power of earbon is $\frac{414}{12}$ or 34.5. In practice, the reducing power of charcoal is found to range between 25 and 30, and that of flour from 10 to 12. Argol has a reducing power of about 8 or 9. In most oxidized ores, therefore, from $2\frac{1}{2}$ to 3 grams of flour will be required to reduce from 25 to 30 grams of lead from the litharge.



If the ore contains ferric oxide, manganese dioxide, or some other easily reducible oxide, more flour must be added. Some iron-manganese ores require as much as 5 grams of flour to throw down the necessary lead. With unknown ores the right amount can be determined only by trial.

Lead Reduction with Sulphide Ores. In the ease of ores containing sulphides, arsenides or other reducing substances, there will be a reduction of lead without the addition of earbon. In fact it is usually necessary to add an oxidizing agent to prevent the precipitation of too much lead. The following reactions show the effect of a number of sulphide minerals when heated in contact with litharge and sodium carbonate.

- (1) $PbS+3PbO+Na_2CO_3=4Pb+Na_2SO_4+CO_2$,
- (2) $ZnS+4PbO+Na_2CO_3=4Pb+ZnO+Na_2SO_4+CO_2$,
- (3) $2\text{FeS}_2 + 15\text{PbO} + 4\text{Na}_2\text{CO}_3 = 15\text{Pb} + \text{Fe}_2\text{O}_3 + 4\text{Na}_2\text{SO}_4 + 4\text{CO}_2$.

The sodium carbonate induces the complete oxidation of the sulphur to SO₃, with the formation of the very stable compound sodium sulphate. In the absence of an alkaline carbonate most of the sulphur is oxidized to SO₂ only, and the amount of lead precipitated is correspondingly decreased.

Reaction (3) shows that pyrite has a greater reducing power than flour itself. If, therefore, a half-assay-ton of ore consisting mainly of pyrite were to be subjected to a crucible fusion, without the addition of some oxidizing agent, anywhere from 100 to 150 grams of lead would be reduced. This would be entirely too much for the subsequent process of cupellation. In order to prevent the reduction of an excessive amount of lead, potassium nitrate is added to the charge. The following reactions show the oxidizing power of this reagent:

- (4) $2KNO_3 + 5Pb = 5PbO + K_2O + N_2$,
- (5) $2\text{FeS}_2 + 6\text{KNO}_3 = \text{Fe}_2\text{O}_3 + 4\text{SO}_3 + 3\text{K}_2\text{O} + 3\text{N}_2$.

Reaction (4) shows that 202 parts of nitre will oxidize 1035 parts of lead to litharge. The theoretical oxidizing power of nitre, as measured against

lead, is, therefore, 5.12. Reaction (5) when compared with reaction (3), given above, shows that 606 parts of nitre will exidize the pyrite needed to




Fig. 59f. Assay Balances for Small Weights.

reduce 3105 grams of lead from litharge. Here again the oxidizing power of nitre is shown to be 5.12. In practice, it is found to be somewhat less, more nearly 4.5.

The fire assay of sulphide ores, therefore, involves either a preliminary assay, or a calculation from the chemical analysis, in order to determine the amount of nitre to be added. With unknown ores it is better to make a preliminary fusion, using 5 grams of the ore, 75 grams of litharge, 20 grams of sodium earbonate and 10 grams of borax glass. The button of reduced lead is weighed and its weight divided by 5. This gives the reducing power of the ore. From this can be calculated the reducing power of one half assayton of the ore, and the amount of nitre necessary to add in order to cut down the weight of the reduced lead to about 30 grams. An excess of silica or borax glass decreases somewhat the amount of lead by causing the formation of difficultly reducible lead silicates or borates.

Amount of Litharge. The amount of litharge for a half assay-ton charge

usually ranges from 60 to 75 grams. Only about half of this is needed to produce the 25 to 30 grams of metallic lead used as the collector. The excess litharge serves to prevent the reduction of other base metals, such as antimony, bismuth, iron, copper and zinc, to help flux the silica, to act as a solvent for some of the refractory gaugue materials, and to make sure that every particle of the ore in the crucible is in close proximity to one or more particles of litharge. In special cases it may be advisable to use a very large excess of litharge, as in the assay of rich gold telluride ores, zinc precipitates and saturated cupels.

Amount of Sodium Carbonate. The amount of sodium carbonate to be used depends somewhat upon the character of the ore, although the modern practice is to use about the same quantity in assaying a great variety of ores and metallurgical products. The principal function of the sodium carbonate is to flux the silica and alumina, which are nearly always present in greater

or less degree. The reactions are as follows:

- (6) $Na_2CO_3 + SiO_2 = Na_2SiO_3 + CO_2$,
- (7) $2Na_2CO_3 + SiO_2 = Na_4SiO_4 + 2CO_2$,
- (8) $Na_2CO_3 + Al_2O_3 = Na_2Al_2O_4 + CO_2$.

The two silicates and the aluminate are both quite fusible at ordinary furnace temperatures.

The silicates used in assaying and in metallurgy are usually classified according to the ratio between the oxygen in the acid radical and that in the base. Only four of these type silicates are of any practical importance. They are shown in the following table:

Sub-silicate		
Mono- or singulo-silicate	2RO,	SiO_2
Sesqui-silicate	4RO,	3SiO ₂
Bi-silicate	RO,	SiO_2

In the above silicates, the ratios are $\frac{1}{2}$ to 1, 1 to 1, $1\frac{1}{2}$ to 1, and 2 to 1, respectively.

Reactions (6) and (7) show that to flux one part of silica to bi-silicate and mono-silicate requires about 1½ parts and 3½ parts, respectively, of sodium carbonate. If the half assay-ton of ore, therefore, consisted of almost pure quartz, it would take 25 grams of sodium carbonate to flux it to sodium bi-silicate, and 50 grams to flux it to the mono-silicate. As a matter of fact, the bi-silicate slag is satisfactory in this case. In general, the acid silicates have lower melting points but greater viscosity than the basic silicates. The excess litharge in the charge also combines with silica, and may thus produce more basic silicates. At any rate, a mixture of silicates usually has a lower melting point than that calculated from the melting points of its components.

Reaction (8) shows that 1 part of sodium carbonate is required to flux 1 part of alumina.

In practice from 30 to 35 grams of sodium carbonate are used in a half-assay-ton charge. In many cases this may seem to be a large excess. It must be remembered, however, that this reagent serves also to assist in the oxidation of the sulphides through the formation of sodium sulphate, that it has a solvent effect upon refractory oxides and other substances, and that it

increases the bulk of the charge, thus protecting the ore from the action of the air and from the excape of the more volatile metals and their compounds. Being very fusible itself, an excess also serves to increase the fusibility of very refractory charges.

Amount of Borax Glass. The rational formula of borax glass, Na_2O , $2B_2O_3$, shows that it is an unsaturated compound and can take up more of the base. This base may be sodium oxide or one or more of the heavier oxides. The result of the addition is a fusible complex borate. This is shown in the following reaction:

(9) Na_2O , $2B_2O_3 + 5CaO = Na_2O$, 5CaO, $2B_2O_3$.

The compound produced is a mono-borate and shows the fluxing of 1.4 parts of lime by one part of borax. The solvent power of borax glass for various substances has been referred to above. In practice it does not matter whether there is chemical combination or solution. What is desired is perfect liquidity at furnace temperatures.

The amount of borax glass ordinarily used in a half-assay-ton charge varies from 10 to 15 grams. If the ore is very basic and refractory, more borax should be used. As in the case of sodium earbonate, an excess of borax glass ordinarily can do no harm, as it is quite fusible.

Some assayers use siliea in the assay of very basic ores. It is a good flux for iron and manganese oxides, producing fusible silicates. It is also very cheap. It cannot be used in excess, because of its very high melting point.

Assay Slags. The slags produced in crucible fusions in fire assaying are often very complex mixtures of silicates, borates, oxides and other compounds. In the molten state there can be chemical combination, solution and suspension, all at the same time. Ordinarily it is quite useless to attempt the formation of a definite silicate or borate. If a sufficient amount of the proper fluxes is used, and a high temperature at the finish, there is usually no trouble in getting a good fusion. As a general rule the greater the complexity of the slag the lower its melting point.

Weighing and Mixing the Charge

It is usually most convenient to mix the charge within the crucible. The fluxes should be put in first, the most bulky one at the bottom. They should be measured rather than weighed, in order to save time. Only the flour and nitre need to be measured accurately. The ore is carefully weighed on a pulp balance and placed on top of the fluxes. The mixing is best done by means of a steel spatula, and should be very thorough. Good mixing is shown by the uniform appearance of the charge. The fluxes should be free from lumps. The practice of using a salt or borax cover on the charge is not so common as it was. Ordinarily it is not necessary. When a salt cover is used in assaying rich ores, there is some danger of the production of volatile silver and gold chlorides. Borax glass as a cover is expensive.

Fusing the Charge. The fusion of the charge is best conducted in a muffle furnace, although it can be made in a coke furnace, or even in a blacksmith's forge. The crucibles should be placed in the muffle when the latter is at a bright red heat. The temperature is then gradually raised until at the end of 45 minutes it reaches a light yellow heat, say 1150° C. Sulphide ores should be run rather more quickly than oxide ores, so as to oxidize the sulphides before they have a chance to melt down into a matte. If the heat be raised too rapidly, there is danger of boiling over, due to the large volume of gases liberated.

The erueible fusion may be divided roughly into three stages. first the preliminary heating stage, accompanied by some reduction of lead from litharge, the partial fusion and decomposition of nitre if present, the partial reduction of higher oxides, and some fluxing of siliea by sodium earbonate and litharge. During the second stage most of the chemical reactions take place and the entire charge seems to be in a state of violent agitation. Lead is reduced from the litharge by flour, sulphur or other reducing agent, and the multitude of small shots piek up the adjacent particles of gold and silver. Gold tellurides and silver sulphides are decomposed by litharge, setting the metals free. Sodium carbonate and borax react upon the acid and basic constituents, respectively, of the charge, and produce slags. Alumina and other oxides either combine with these reagents or dissolve in the slag mixture. There is a copious evolution of gases, such as earbon dioxide, earbon monoxide, sulphur dioxide, and nitrogen. The third stage is known as the period of quiet fusion. It is for the purpose of completing the slagforming reactions and of rendering the slag as liquid as possible. This enables all of the small particles of lead to fall down through the slag, collecting the remaining traces of gold and silver. The latter are washed out of the slag much as a shower of rain sweeps the dust partieles out of the air. The slag must be thoroughly liquid in order to insure a perfect separation from the lead.

A high temperature at the beginning of the fusion should be avoided, as it not only increases the chances of boiling over, but may cause some volatilization of compounds of the precious metals. After these metals are reduced and alloyed with lead, the temperature can be raised with less danger of loss. A row of empty crucibles or a prism of coke should be placed in front of the crucibles containing the fusions, and the muffle door should be kept closed.

The time required ranges from 40 to 55 minutes, according to conditions. A long-continued fusion at a low temperature usually means a small lead button and an imperfect collection of the gold and silver.

The period of quiet fusion should last about 10 to 15 minutes. The crucibles are then taken out of the muffle, tapped gently with a whirling motion, to collect stray shots of lead, and the contents poured into conical iron moulds. The greater part of the slag should be poured off first, so as to avoid splashing of the lead against the sides of the mould. When cold the lead buttons are taken out and hammered into rough cubes, so as to remove the adhering slag. The lead buttons are now ready for cupellation.

Crucible Charges. It is impossible to give a crucible charge that would be satisfactory in every case. Modifications in the amount and kind of reagents must be made to suit the character of the material to be assayed. However, the variations are not so great as is generally supposed, and many assayers use stock fluxes for a great variety of ores and metallurgical products. Changes are made only when the conditions seem to require them.

The following table gives the approximate amount of the different reagents used in an ordinary crucible fusion:

 $\begin{array}{lll} \text{Ore} & & \frac{1}{2} \text{ assay-ton} \\ \text{Sodium earbonate} & & 25 \text{ to } 35 \text{ grams} \\ \text{Borax glass} & & 10 \text{ to } 15 \text{ grams} \end{array}$

Flour or Nitre As required. (See Preliminary Assay)

Litharge 60 to 75 grams.

The Scorification Assay. The scorification assay is used principally in those cases in which an undue amount of interfering base metals would be reduced along with the lead if crucible fusions were made. Thus, if a crucible fusion be made upon an ore containing copper or antimony, either of these two metals will be reduced along with the lead and produce a button which is difficult to cupel. Even with sulphide ores there is a considerable reduction of the copper or antimony, as is shown in the following reactions:

- (10) $Cu_2S + 3PbO + Na_2CO_3 = Cu_2 + 3Pb + Na_3CO_4 + CO_2$,
- (11) $Sb_2S_3 + 9PbO + 3Na_2CO_2 = Sb_2 + 9Pb + 3Na_2SO_4 + 3CO_2$

Nickel and cobalt are reduced in the same way.

In the scorification assay the operations are carried out under oxidizing conditions so as to prevent the reduction of the interfering metals. Metallic lead is used as the collector and is added as such. The flux is mainly litharge, coming from the oxidation of the lead, and a small amount of borax.

The operation is conducted in shallow fire-clay dishes known as scorifiers, from 2 to 3 inches in diameter. The amount of ore taken is usually $\frac{1}{10}$ assay-ton, sometimes $\frac{1}{5}$ or $\frac{1}{20}$ assay-ton. About 25 grams of granulated lead are spread over the bottom of the scorifier and the ore then added and thoroughly mixed with the lead. The mixture is then covered with about 25 grams more of granulated lead and one or two grams of borax glass. Usually from 5 to 20 portions of the ore are weighed up so as to lessen the chances of error. The scorifiers are placed in a muffle heated to redness and the door closed. As soon as the lead melts the door is opened, in order to admit air and increase the rapidity of the oxidation. The ore is seen to be floating on

the lead. The latter begins to oxidize and the litharge produced in turn oxidizes the sulphides in the ore, assisted by the oxygen of the air. temperature at this point must be low in order to prevent volatilization of gold and silver. The ore is not protected by a large bulk of fluxes as it is in the crucible assay. As the oxidation proceeds, a ring of slag, mainly litharge, begins to form around the bath of lead. The ore gradually disappears, the gold and silver going into the molten lead and the gangue combining with or dissolving in the litharge. Owing to the strong oxidizing conditions, most of the eopper and practically all of the antimony present go into the slag. As the ring of slag increases, the temperature is raised. Finally, the lead becomes completely covered, and the muffle door is closed in order that the slag may become thoroughly liquid. The contents of the scorifiers is then poured into conical moulds, as in the case of the crucible fusions. The lead buttons should weigh from 15 to 20 grams. Very small buttons usually mean low results. With high copper material it is sometimes necessary to scorify two or three times and to use a large amount of lead. The buttons are cleaned and cupelled in the usual way.

The scorification assay is not adapted to ores containing volatile constituents, such as tellurides, arsenides and metallic zinc. Carbonates and highly oxidized ores are also unsuited to this method. If the ore contains much basic gangue it should not be scorified, as there is not enough acid flux to take eare of it. Low grade gold ores are not usually assayed by scorification because of the small amount of ore taken. In practice the method is limited to ores and metallurgical products containing considerable quantities of antimony, copper, nickel and cobalt. It is a standard method for the assay of copper matte. Scorification is also sometimes used to reduce the size of and to purify lead buttons produced in the crucible method.

Cupellation. Cupellation is the process by which the gold and silver are separated from the lead and other base metals with which they are alloyed. The eupcls have already been described. They must be thoroughly dry and somewhat heavier than the lead buttons that are to be cupelled. A bone ash cupel will absorb about its own weight of litharge, but the absorption becomes slower when the saturation point is approached.

In the cupcllation process the lead is oxidized to litharge which is taken into the pores of the cupcl by capillary attraction. This takes place because litharge is molten at the temperature of the operation. Most of the other base metal oxides are infusible at this temperature. When in moderate amounts, however, they dissolve in the liquid litharge and are carried into the cupel. If the lead contains much copper and antimony, the oxides of these latter metals accumulate on the cupel and may ruin the assay. Hence the need for scorification in these eases.

The eupels should be heated in the muffle for at least 20 minutes before putting in the lead buttons. Cupellations are best started at a bright red heat, say about 900° C. As soon as the buttons are put into the cupels, the muffle door should be closed. If the temperature is too low, an infusible oxide will form on the lead as soon as the latter is melted and refuse to go into the eupel. The disappearance of this film of oxide on further heating is referred to as the "opening" or "uncovering" of the lead. Sometimes it is necessary to hasten the opening by means of a burning stick of wood placed

immediately over the cupel. This reduces the oxide and at the same time raises the temperature. When all of the cupellations are uncovered, the muffle door is opened and the temperature lowered rapidly to the lowest possible point at which the operation can proceed. This must be done because a temperature higher than necessary increases the loss of gold and silver. This loss occurs by absorption into the cupel and by volatilization. If the temperature falls too low, the buttons "freeze"; that is, the litharge, which melts at 883° C., solidifies on top of the liquid lead, which melts at 327° C., and the operation stops.

At first thought it would seem that a temperature slightly above 883° C. would be the proper one for cupellation. As a matter of fact the temperature of the muffle need not be above 750° C. This is due to the fact that the oxidation of the lead generates a considerable amount of heat, and the buttons are thus hotter than either the muffle or the cupels. A good indication of the right cupellation temperature is the formation of solid flakes of litharge, known as "feathers," upon the inner edge of the cupels. The volatilized litharge strikes the comparatively cool bone ash and sublimes as flake crystals.

The presence of impurities usually increases the loss of gold and silver, and adds to the difficulties of the operation. Copper or niekel in quantity may cause the buttons to freeze even at moderately high temperatures. Antimony causes the formation of a hard, infusible crust of lead antimonate which retains silver and which often splits the top of the eupel.

The surface of the lead in the cupel is convex, owing to the high surface tension of the metal. During cupellation the drops of molten litharge can be seen rolling off of the lead and disappearing into the eupel. The surface tension of the melted litharge is less than the attractive force of the bone ash. In scorification, where the vessel is not porous, the litharge forms a concave surface and climbs up the sides of the scorifier. This explains in part the high gold losses in the cupellation of lead containing gold and tellurium. Some of the gold telluride passes into the cupel just as in the case of litharge. Gold telluride is also more volatile than metallic gold.

As the operation proceeds, the lead and other base metals gradually oxidize and disappear. Copper and bismuth are less readily oxidized than lead, and hence tend to remain until most of the lead has gone. The temperature should be raised slightly at this point in order to prevent the buttons from solidifying before the base metals are completely oxidized. Small amounts of these metals usually remain, even in a well-conducted eupellation. The melting point of gold and silver being considerably higher than the temperature of the muffle, the buttons solidify soon after the base metals are gone. At the moment of solidification the buttons flash or "blick," owing to the release of the latent heat of fusion. If the buttons are large and consist mainly of silver, they may "sprout" or "spit" on being withdrawn quickly. This is due to dissolved oxygen which escapes when the button solidifies. The sprouting may be prevented by eovering the silver button with a hot inverted cupel as soon as the eupellation is finished, and allowing the covered eupel to remain in the muffle for several minutes. This insures a slow cooling of the silver bead. After cooling the buttons are removed from the eupel by means of foreeps and the adhering bone ash brushed off. The buttons are then weighed on an assay balance to the nearest one-tenth of a milligram. If a half-assay-ton of ore was used, the results multiplied by two equal the ounces

per ton of combined gold and silver.

Cupellation involves the greatest precious metal losses of all the processes in fire assaying. For that reason it must be conducted with eare and skill. The loss in silver ranges from 1 to 2 per cent, even under favorable conditions. If there are large amounts of impurities, or if a very high temperature is used, the silver loss may be several times as great. The gold loss is less than that of silver and should not be more than $\frac{1}{2}$ of 1 per cent. In all cases the percentage losses of gold and silver increase as the amounts in the ore decrease.

Parting. Parting is the separation of gold from silver in an alloy containing these metals, and is effected in fire assaying by means of nitric acid. This acid converts the silver into soluble silver nitrate, but is almost without action upon the gold. In order to part readily the alloy must contain at least three times as much silver as gold. Even at this ratio it is difficult to dissolve all of the silver. In practice, it is better to have a much larger proportion of silver, except in the assay of gold and silver bullion. If the buttons produced in the assay of an ore are known to contain enough gold to render parting difficult or impossible, they are subjected to the process known as inquartation. The buttons after weighing are wrapped with about 10 times their weight of pure silver foil in 3 to 5 grams of sheet lead and then cupelled. The resulting buttons are flattened and parted in the usual manner.

An important point in parting is the strength of the acid. If a strong acid is used at first, the gold in the button is liable to break up into a fine powder which is difficult to manage without loss. By using a rather weak acid, containing from 10 to 20 per cent of HNO₃, the gold has a tendency to coalesce into a coherent mass which can be washed and weighed as one piece. The treatment with weak acid is always followed by one with a stronger acid, in order to remove the last traces of silver. The second acid should be about 1.26 sp.gr., made by diluting the concentrated acid with its own volume of water. In the case of buttons containing a small proportion of gold, the first acid should be very weak, not more than 10 per cent HNO₃. With more gold a stronger acid can be used, although the weak acid is usually effective,

except when the buttons are very large.

The parting may be done in porcelain capsules or in small glass flasks, known as parting flasks. Only a few cubic centimeters of acid are necessary. This should be heated to boiling and the flattened beads then dropped into it. Solution of the silver begins immediately. At the end of about 20 minutes, or when all visible action has ceased, the weak acid solution is decanted into a white casserole, earefully avoiding the loss of any gold. About 3 cubic centimeters of the stronger acid is now added to each flask or capsule and then heated almost to the boiling point. The heating is continued for at least 10 minutes, when all of the silver should be in solution. The acid is then poured off and the gold washed three times by decantation with ehlorine-free water. If eapsules are used, the water is drained out as completely as possible and the eapsules then placed on a hot plate or in front of the muffle for drying. If parting flasks are used, a fire-elay annealing cup is inverted over the top of each completely filled flask and the flask then quickly reversed, allowing the gold to fall quietly into the annealing eup. After removing the flask by a quick side motion, the water is poured off of the gold and the cup placed

on the hot plate. The final process is known as annealing. The capsules or annealing cups are placed in the muffle and heated to low redness for about 5 minutes. The heating causes the brownish-black spongy or fibrous gold to coalesce into a dense flake or bead having the characteristic yellow color of the metal. The annealing also serves to drive off any volatile impurities which may be present, and to render it easier to separate any specks of dust or dirt from the gold. After cooling the gold is weighed on a delicate balance to the nearest .01 milligram—with a little care to the nearest .005 milligram. The weight of the gold is deducted from the weight of the button before parting and the difference represents the silver in the portion taken for assay.

The Assay of Bullion

Bullion is an alloy of gold and silver with variable amounts of one or more of the base metals, and is the semi-final product of most non-ferrous metallurgical plants. In lead smelting this product is usually known as base bullion, in copper smelting as blister copper, and in amalgamation and cyanide processes as retort bullion or doré silver. The base metals may include antimony, arsenie, bismuth, cobalt, copper, lead, mercury, nickel and zine. Small amounts of sclenium and tellurium are usually present, as well as traces of the platinum group of metals. In all cases the assay of bullion resolves itself into a problem of the separation of metals from each other, there being practically no non-metallic elements present.

Bullion Sampling. The sampling of bullion involves some difficulties not encountered in the sampling of ores. Most alloys on solidifying segregate to some extent, so that the cooled metal is never uniform in composition. Whenever possible the samples should be taken from the thoroughly stirred molten alloy and then chilled quickly, either by pouring into water or by pouring into small moulds with thick metal sides and bottoms. When there is danger of oxidation, this method of course is not entirely satisfactory. In impure bullion there is often a very uneven distribution of the gold and silver, and it is necessary to drill or saw entirely through the bar in order to obtain accurate results. In copper anode plates and other forms of blister copper the plates or bars are drilled in series, so that the combined sample represents a proper percentage of drillings from all parts of each piece. Lead bullion is sometimes sampled in a similar manner, although in this case the bars are usually punched instead of being drilled. The modern tendency is to take melted samples of all metallic products, even in the ease of blister copper.

The Assay of Lead Bullion. The assay of lead bullion ordinarily involves only eupellation and parting. The bullion is often impure, however, and it may then be advisable to scorify the weighed portions before eupelling. If the sample contains much copper or antimony, it should always be scorified. The precious metal loss in scorification is less than it is in eupellation, especially in the case of an impure bullion requiring a high temperature in order to eupel it.

Lead bullion is usually run in four portions of one half assay-ton each. The four silver buttons are weighed separately and if there is a satisfactory agreement in the weights, the average is taken and the result multiplied by two. The buttons are parted in pairs, thus saving time in washing and weighing. Great care should be exercised in the cupellation of lead bullion and in the subsequent parting, as the bullion is a high grade product, and ordinarily no correction is made for losses in the cupel or otherwise.

The Assay of Copper Bullion. Copper bullion may be assayed by the scorification method, but the results are satisfactory only in the case of the gold. The silver obtained is always much too low. Most of the loss can be recovered by assaying the slag and cupels, but this requires additional time and materials.

The best way to determine gold and silver in copper bullion is to use the so-called combination method, in which the copper is first removed by solution in acid. Formerly nitric acid was used for this purpose, but it was found that the results were usually low in gold. There was a tendency for some of the

gold to go into solution. The nitric acid method is a convenient way of determining the silver, as the copper dissolves very rapidly in nitric acid,

and the precipitation of silver as chloride is very complete. For the assay of both gold and silver the sulphuric acid-mercuric nitrate method is recommended. One assay-ton of the finely ground, well-mixed copper borings is treated in a large beaker with 30 ee. of water and 10 cc. of a solution of mercuric nitrate containing 25 grams of mercury per liter. The beaker is well shaken so as to amalgamate the copper, and 100 cc. of concentrated sulphuric acid then added. The beaker is covered, placed on a hot plate and heated until all of the copper is dissolved. This will require from one to two hours, according to the temperature and fineness of the sample. The beaker is now removed and the solution is allowed to cool. 100 cc. of cold water are added, the mixture stirred, and then 400 ec. of boiling water added, with further stirring until all copper sulphate has dissolved. A solution of common salt is now added, just sufficient to precipitate all of the silver and mercury. Only a slight excess must be used, as silver chloride is soluble in strong sodium ehloride solution. The beaker is replaced on the hot plate and the contents boiled so as to congulate the silver chloride. The beaker is then removed, the solution diluted to 600 cc. with cold water and allowed to cool. The solution is then filtered through double filter papers, and the bcaker and filter washed with hot water. The bcaker should be wiped out with a filter paper and this added to the material in the filter. The filter and its contents are now transferred to a 2½-inch glazed scorifier and the filter paper burned off at a low temperature, so as to avoid loss of silver. After the paper is burned off, 30 grams of test lead are added and the material scorified until 12 to 15 grams of lead remain. The scorifier is poured and the lead button eupelled at as low a temperature as possible. The gold and silver are parted in the usual way. The results are very accurate.

The object of the mercuric nitrate is to hasten the solution of the copper by forming a galvanic couple. It prevents also the formation of copper

sulphide which is insoluble in dilute sulphuric acid.

Assays should be made in duplicate or triplicate.

The Assay of Gold and Silver Bullion

In the fire assay of gold and silver bullion a correction must always be made for the metal losses, because of the great value of the bullion and because the refining losses on a commercial scale are considerably less than the losses in assaying. The assays are, therefore, always run with a check or "proof center." The check is an artificial sample made up so as to have as nearly as possible the exact composition of the bullion to be assayed. Two checks and three portions of the bullion, all five of the same weight, are cupelled and parted under exactly the same conditions. The weights of gold and silver found in the bullion samples are then corrected by adding or subtracting the loss or gain experienced by the gold and silver in the checks. In the assay of gold bullion there is sometimes a gain in the weight of the gold, due to the imperfect climination of the copper. This, however, should be the same in both checks and bullion samples. Results are reported in "fineness" or parts per 1000.

Silver Bullion or Doré Bullion Assay. A sample of about 500 milligrams of the bullion is accurately weighed out on the assay balance. The weight need not be an even 500 milligrams but its exact amount should be recorded. The bullion is wrapped in from 6 to 8 grams of sheet lead and cupelled with the formation of feathers of litharge. The button is covered with a hot cupel to prevent sprouting. The cupel and button are drawn out of the muffle gradually, and the button is then cleaned, flattened and parted in the usual way. To the weight of the silver a loss of from 1 to 1½ per cent is added. The weight of the comparatively small amount of gold can be taken as it is. The weight of the eriginal button, less the sum of the corrected silver weight and the weight of the gold, represents the amount of base metal. This is usually copper, but may be one or more of a number of other metals. The assayer can usually determine what metals are present by the appearance of the bullion and that of the cupel.

Two checks are now prepared by weighing in each case pure gold, pure silver and pure copper or other base metal in the amounts as found in the preliminary assay just described. Three 500-milligram portions of the bullion are also weighed up. The checks and bullion samples are each wrapped in an amount of sheet lead corresponding to that in the following table, taken from Bugbeo's "Text-book of Fire Assaying":

Lead Ratio in Cupellation

Fineness of Au. and Ag.	Wt. of Lead	Fineness of Au. and Ag.	Wt. of Lead
950	5 grams	750	11 grams
900	7 ''	700	12 "
850	8 ''	650	13 "
800	10 ''	600	15 "

The table shows that as the base metal, usually copper, increases, the amount of lead must be increased.

Cupellation is performed in a single row of cupels, all of the same size. The cheeks are placed in the second and fourth cupels. The heat should be

kept low enough to allow of the formation of feathers of litharge until at the finish, when the temperature must be raised.

The beads are cleaned, weighed, flattened and parted. The amount of gold and silver loss in the checks is determined and the proper correction applied to the weights of gold and silver found in the bullion samples.

If the bullion contains antimony, the process must include scorification, which is applied to checks and samples as well. When bismuth, selenium or tellurium is present in quantity, the silver must be separated by means of solution in nitric acid and subsequent precipitation as chloride.

Gold Bullion Assay. The assay of gold bullion is in principle the same as that of silver bullion. As the gold is usually in excess of the silver, however, the process involves inquartation, with the use of a stronger first acid than

when parting ordinary silver buttons.

U. S. Mint Method. Sample portions of 500 milligrams are taken for assay. A preliminary expellation is made as in the case of doré bullion. The amount of silver to be added for the final assay is determined by the touchstone method. The cupelled gold and silver button is rubbed on a piece of black jasper and the streak made compared with those made by alloys of known composition. This gives the fineness within 2 per cent, which is close enough. A ratio of silver to gold of 2 to 1 is used in making up the checks. If no copper is present, about 3 or 4 per cent is added as it facilitates the removal of the last traces of lead in cupellation. The cupelled buttons are flattened by hammering, annealed at a red heat, and then passed through a pair of jeweller's rolls, until they are converted into fillets about 2½ inches long and ½ inch wide. The fillets are again annealed and rolled up into "eornets" or spirals. Sufficient space should be left between the turns to permit of easy contact with the acid. The parting is done by boiling for 10 minutes in nitric acid of 1.28 sp.gr., and then transferring to another vessel containing acid of the same strength and boiling for 10 minutes longer. The cornets are then washed three times with distilled water, dried, annealed and weighed.

The proofs usually show a slight gain in the weight of the gold, so that the correction is made by subtracting the gain from the average weight of the

gold found in the sample portions.

The gold after parting should be in one piece and have smooth edges, as otherwise there is danger of loss.

The Assay of Cyanide Solutions

A number of methods have been devised for the determination of gold and silver in eyanide solutions. Only two of these methods will be described here.

Evaporation in Lead Tray. This method is adapted to cyanide solutions containing only small amounts of base metals or other impurities. A small tray or boat is made of lead foil, capable of holding the amount of solution to be assayed. A wooden block or form is used to make the trays if many assays are required. The solution has about the same specific gravity as water, so that 29.2 cc. are assumed to be equal to an assay-ton. An amount of solution varying with its richness is put into the lead tray and slowly evaporated to dryness on the hot plate. The lead tray is then folded up and cupelled in the usual manner.

The Chiddey Method. This method, first described by Alfred Chiddey,

is adapted to almost every grade and character of cynnide solutions. From 1 to 20 assay-tons of solution are heated in a beaker or evaporating dish. To the solution is added from 10 to 20 ec. of a 10 per cent solution of lead acetate containing 40 cc. of acetic acid per liter. From ½ to 2 grams of zinc dust or zinc shavings is then added. The gold, silver and lead immediately begin to precipitate on the zinc. The solution is heated for about 20 to 25 minutes, but not to boiling. The lead should confesce into a spongy mass. Boiling the solution is liable to break up the sponge. The excess zine is now dissolved by adding slowly 20 cc. of hydrochloric acid of 1.12 sp.gr. The heating is continued until effervescence ceases. It may be necessary to stir slightly in order to make sure that all zine is dissolved. The solution is now decanted off and the lend sponge washed two or three times with water. The excess water is squeezed out of the sponge with the fingers, the sponge further dried by pressing between filter paper and then rolled into a ball with lead foil and the necessary silver for parting. A hole should be left in the lead foil for the escape of steam. The ball is then dried and eupelled.

As the lead sponge begins to break up and go into solution as soon as all of the zine is dissolved, no time should be lost in decanting the solution after

the zinc has disappeared.

Special Methods of Assay. There are many ores and metallurgical products that require special methods for the determination of the gold and silver that they contain. It is impossible to refer to these methods here. A knowledge of the composition of the sample, however, will usually enable the skilled assayer to so modify the ordinary processes as to obtain satisfactory results.

For further details in regard to standard and special methods of fire assaying the reader is referred to such works as "A Manual of Fire Assaying," by Chas. H. Fulton, published in 1911, and "A Textbook of Fire Assaying,"

by Edward E. Bugbee, published in 1922.

Summary. General Outline.

An assay ton (A.T.) or multiple is taken, of the 80-200-mesh ore or 20-mesh shavings of metals and is heated with a flux of lead oxide, a suitable slag forming material and a reducing or oxidizing reagent as the case requires, (see preliminary assay below), in order to obtain by reduction about 18 g. of lead from the lead oxide. The molten lead alloys with the silver and gold (and copper) and sinks to the bottom of the melt. The charge is cooled and the slag hammered off the lead and the button or cube of lead is heated on a bone ash cupel in presence of air. The bone ash absorbs the oxides of lead (and copper) leaving the precious metals in the form of a bead. As the last trace of lead is removed a play of colors is seen with a final flash of light as the alloy of silver and gold appears ("blick"). The combined gold and silver button is weighed, the silver now dissolved (parting) from the gold and the residual gold weighed. The difference between the first and second weight is due to silver.

Preliminary Assay. This is to ascertain the nature of the material as neutral, oxidizing or reducing products require different treatment. Usually one-sixth of the charge of ore is taken with the regular charge of flux, without a reducing or oxidizing agent. A typical example of a charge is one-sixth A.T. of ore, 100 g. litharge, 20 g. sodium bicarbonate and 5 g. borax. Using this charge the following cases will illustrate the method of interpretation.

A. Reducing Ores. Suppose a 2 g. Pb button is obtained. This is equivalent to $2 \times 6 = 12$ g. on a customary charge of 1 A.T. of ore. Additional reducing agent is necessary to get the 18 g. Pb desired. 1 g. charcoal reduces

about 30 g. Pb, hence $(18 - 12) \div 30 = 0.2$ g. charcoal required.

On the other hand suppose a 4 g. Pb button results, equivalent to 24 g. with full charge of orc. It is necessary to add an oxidizing agent to counteract the reducing action of the ore to the extent of 24 - 16 = 6 g. Pb excess. 1 g. NaNO₃ oxidizes 4 g. Pb. Therefore $6 \div 4 = 1.5$ g. NaNO₃ is required.

B. Neutral and Oxidizing Ores. In this case no lead is reduced. A second run must be made with say 1 gram of charcoal (30 g. Pb equivalent). If 30 g.

Pb results the ore is neutral and $18 \div 30 = 0.6$ g. charcoal is required.

On the other hand suppose 28 g. Pb results, then the ore is an oxidizer and 1 A.T. of the ore will oxidize $2 \times 6 = 12$ g. Pb. To counteract this $12 \div 30 = 0.4$ g. charcoal is necessary and $18 \div 30 = 0.6$ g. charcoal to reduce 18 g. Pb, making a total of 0.4 + 0.6 = 1 g. charcoal required.

Precaution. All reagents used should be tested by regular assay.

A 20-25 gram button of lead is generally required in the assay of orcs high in silver.

Solution Assay. Place 10 assay tons of the solution in a 1000 cc. bcaker. Add about 30 cc. of a 20% lead acetate solution (the amount being governed by the strength of the solution). Dilute to about twice the volume and heat. Add about 5 grams of zine shavings, heat until solution clears. Add 30-40 cc. HCl. When clear, decant off solution, wash the lead and squeeze into a button. Assay the button.

The writer is indebted to Mr. W. G. Dcrby for several cuts appearing in

tlus chapter.

DETERMINATION OF PLATINUM, PALLADIUM, GOLD AND SILVER 1

Platinum, Palladium and Gold. Scorify the lead buttons from two or more $\frac{1}{2}$ assay ton crucible fusions together, adding at least six times as much silver as the combined weight of the Pt, Pd and Au present, and cupel hot. In rich materials such as slines or concentrates, two $\frac{1}{2}$ assay ton fusions suffice, but low-grade ores may require 10 or more $\frac{1}{2}$ assay ton fusions combined for each determination.

Part the silver beads with HNO₂ (1:6), followed by stronger parting acid (1:1) and wash with water as usual. All Pd goes into solution, together with considerable Pt. The residue consists of Au plus some Pt. Dissolve residue in strong aqua regia and reserve the solution (solution A). Precipitate the silver in the nitric-acid solution—containing Ag, Pd and some Pt—with HCl. Practically all the Pt will remain in solution; but the precipitated AgCl is pink in color and contains considerable Pd. Filter off the AgCl, scorify and cupel it and part again with HNO₂ (1:6); all should dissolve. Re-precipitate the Ag with HCl. The liquid now contains most of the remaining Pd, but some is co-precipitated with AgCl. Filter off the AgCl and add the filtrate to the first filtrate from AgCl. Again scorify and cupel the silver chloride, dissolving the silver in nitric acid as before and re-precipitating the silver as chloride. In most cases the filtrate from this silver chloride contains all the remaining Pd. If however, the AgCl is distinctly pink, another separation must be made.

Unite all filtrates from AgCl precipitations and evaporate to small bulk, adding the aqua-regia solution of the Au and Pt (solution A). The liquid now contains all the Au, Pt and Pd present in the original ore, together with traces of Ag due to solubility of AgCl in excess of HCl, and also traces of Pb gathered from the lead retained in the silver buttons from several re-cupellations.

Evaporate the liquid to dryness on the steam bath; take up with dilute HCl (1:3) and evaporate again to dryness; take up with five drops of HCl and 40 cc. H₂O. Pay no attention to any insoluble residue of AgCl or PbCl₂.² Precipitate the gold by adding, say, 3 gm. of oxalic acid to the solution and boiling it. Let stand over night and filter off the Au. If Pt and Pd are high, it is necessary to re-dissolve the Au in aqua regia, evaporating with HCl to dryness and repeating the oxalic-acid precipitation, uniting the filtrate with that from the first gold precipitation. Burn the filter containing the gold and scorify it with six times its weight of silver and a little test lead; cupel, part and weigh the gold as usual.

To the oxalic-acid filtrates from Au add 5 cc. of HCl and make volume up to 150 cc.; heat to boiling and precipitate Pt and Pd with a rapid current of H_2S in hot solution, passing the current of gas for some time and keeping the solution hot during precipitation. Filter and wash the Pt and Pd sulphides

¹ By A. M. Smoot, Eng. and Mining Journal, April 17, 1915.

² In materials rich in palladium the small amount of AgCl + PbCl₂ may be distinctly pink in color and retain weighable quantities of Pd. If this is the case, the Pd may be recovered in the solution from the nitric acid parting of the gold. To do this, precipitate the silver in this liquid by adding HCl, filter off the silver chloride and evaporate the filtrate to dryness. Take up with a drop of HCl and a little water, let stand over night and filter through a very small filter. This liquid may be added to solution B before precipitating palladium with glyoxime.

with H_2S water containing a little HCl. Wash the precipitate from the filter with a fine water jet into the original beaker; spread the filter paper (which will contain a small amount of precipitate impossible to wash off) with the precipitate side down over the lower side of a watch glass-cover. Add aqua regia to the precipitate in the beaker and place the cover on the beaker; warm gently to dissolve the Pt and Pd sulphides. The fumes arising from the acid dissolve the traces of Pt and Pd adhering to the filter paper. When solution is complete and filter paper is white, remove the watch-glass cover and wash

the paper with hot dilute HCl thrown against it in a fine stream.

Evaporate the aqua-regia solution to dryness, take up the residue with HCl and evaporate again to dryness to remove all HNOs. Take up the residue with two or three drops of HCl and about 2 ec. of H₂O. The solution is usually perfectly clear, but it may be slightly cloudy owing to the presence of a little AgCl in it. No attention need be paid to this however. Add 5 to 10 ee. of a saturated solution of NH4Cl, stir well and allow to stand over night. Platinum is precipitated as ammonium-platinum chloride—(NII₄)₂PtCl₆. Filter and wash the precipitate with 20% NH₄Cl solution. All Pd passes into the filtrate which is reserved (solution B). Dissolve the Pt precipitate in boiling hot 5% H₂SO₄; heat the liquid to actual boiling and precipitate with H₂S as before, filtering and washing with H2S water. Burn the filter and precipitate at a low temperature in a scorifier; add six times as much Ag as Pt, scorifying with lead, cupel and part the silver bend containing the platinum with H2SO4; decant off the silver solution and wash once with strong H2SO4, followed by 50% H₂SO₄ until practically all the silver is washed away; finally wash with water, anneal and weigh. A minute quantity of Ag is retained with the platinum, but it can usually be neglected. In very important work where the amount of platinum is large dissolve in aqua-regia, evaporate the solution to dryness, take up with a drop of HCl, dilute largely with water and let the AgCl settle over night; filter on a small paper, cupel it with a little sheet lead and deduct the weight from the weight of platinum. This refinement need not be considered in materials running less than 15 or 20 oz. to the ton.

It may seem an unnecessary step to precipitate the platinum as sulphide, scorify it with silver and part it as described in the foregoing. General practice has been to ignite the ammonium-platinum-chloride precipitate and weigh the metallic residue. When this is done, however, there is danger of losing considerable platinum, which is carried away mechanically during the decomposition of the compound; furthermore, it is extremely difficult (if not impossible) to collect the finely divided residue for weighing, and the precipitate invariably contains lead and silver. Precipitation as sulphide, scorification and capellation with excess silver and parting with sulphuric acid overcome the difficulties

inherent in handling the ammonium precipitate.

The palladium is all contained in the filtrate and washings from the platinum ammonium-chloride precipitates (solution B). Add to this solution at least seven times as much di-methylglyoxime as there is Pd present (in any ease, at least 0.1 gm. glyoxime). The precipitant should be dissolved in a mixture of two-thirds strong HCl and one-third water. Dilute the liquid to 250-300 cc., heat on a steam bath for half an hour and let stand over night. Pd is precipitated as a voluminous yellow, easily filtered glyoxime compound $C_4H_{14}N_4O_4Pd$, containing, when dried at 110° C., 31.689% of Pd. Filter the Pd precipitate on a weighed Gooch crucible and wash it, first, with dilute HCl,

half and half, then with warm water and finally with alcohol; dry it at 110° to 115° C. and weigh. The disadvantage of weighing palladium on a Gooch crucible is overcome—at least to some extent—by the fact that the Pd compound contains a relatively small amount of Pd—less than one-third of its weight. This compound may also be weighed on carefully counterpoised papers; but it is better to use Gooch crucibles, if they are available, because of the relatively strong acid which is required for washing. The object in using half-and-half hydrochloric acid as a wash liquid is to dissolve out any excess of the glyoxime precipitant. This is easily soluble in moderately strong HCl, but is substantially insoluble in water.

Determination of Silver in Ores and Concentrates Containing Platinum and Palladium

Make the usual crucible fusion on one-quarter, one-half or full assay ton, according to the amount of silver present. Instead of cupelling the lead button, hammer it free from slag and dissolve it in dilute nitrie acid. Most of the silver passes into solution together with palladium, and perhaps a trace of platinum; but gold and most of the platinum remain insoluble. The gold and platinum retain an appreciable proportion of silver which cannot be washed out. Filter out the insoluble residue and wash it thoroughly with hot dilute nitrie acid, followed by hot water. Scorify the residue once more with a little lead and dissolve the lead button as before, filtering into the beaker containing the first filtrate. In this liquid precipitate the silver as AgCl by adding standard NaCl in sufficient quantity; stir well, and if the amount of silver is small, add about ½ cc. of strong H₂SO₄ to form a precipitate of lead sulphate. Let the silver chloride, or the silver chloride plus lead sulphate, settle over night or until the supernatant liquid is clear; filter through double filter papers; ignite and scorify the residue of silver chloride with test lead.

If the amount of the palladinm contained in the sample is small, the silver bead obtained by cupeling the lead button obtained by scorifying the silver chloride may be considered as sufficiently pure for ordinary purposes. It contains, of course, some palladinm, and in accurate silver determinations the lead button from the first silver chloride precipitation should be re-dissolved and the silver re-precipitated, filtered and scorified as before. The amount of palladium retained after the second precipitation and scorification is so small as to be negligible.

STRONTIUM

Sr", at.wt. 87.62; sp.gr. 2.54; m.p. 900°C; oxides SrO and SrO1.

DETECTION

Strontium is precipitated with barium and calcium, in the filtrate, from the ammonium sulphide group, by addition of ammonium carbonate to the ammoniacal solution. The precipitate is dissolved in acetic acid and treated with potastassium dichromate, and the barium filtered off as BaCrO₄. Strontium and calcium in the filtrate are separated from the excess of potassium chromate by reprecipitation as carbonates by the addition of ammonium carbonate, the precipitate again dissolved in acetic acid and the excess of free acid neutralized with ammonia. Strontium may now be precipitated from the concentrated solution by boiling with an equal volume of a saturated solution of calcium sulphate.

Sodium Sulphate Test. A saturated solution of the salt added to a solution containing strontium chloride, made strongly acid with acetic acid, and the mixture boiled, will produce a distinct precipitate if strontium exceeds 0.0015 normal. Calcium does not precipitate until 1.3 normality is reached.

Flame Test. Strontium, preferably in the form of the chloride in a hydrochloric acid solution, placed on a platinum loop and held in a colorless flame, colors the flame crimson. (Lithium gives a red color, calcium a yellowish-red.) The test is best confirmed by means of the spectroscope.

The Spectra of Strontium. Eight bright bands; 6 are red, 1 orange, 1 blue. Two of these, known as strontium β and γ , are red, the orange is strontium α and the blue strontium δ . The delicacy of the test is 0.6 milligram Sr per cc. The test is very much more delicate with the arc spectra, e.g., 0.03 milligram Sr per cc. See chapter on barium, Preliminary Tests under Separations.

ESTIMATION

Strontium never occurs free in nature. It is found principally in the ores celestine, SrSO₄, and strontianite, SrCO₂. It generally accompanies calcium in the various forms of calcite and aragonite. It occurs with barium in hary-tocelestine, and is found in barytes. It also occurs associated with barium as a silicate in brewsterite, Al₂O₂·H₄(BaSr)O₂·(SiO₂)₄·3H₂O. It is found in traces in certain mineral waters and in sea-water.

The compounds of strontium are used for medicinal purposes; for red fire in pyrotechnics; for the manufacture of iridescent glass; the dioxide for bleaching purposes; the sulphide for luminous paint; the hydroxide for refining of beetroot sugar, being preferable to lime, as the saccharate of strontia is more granular.

Chapter contributed by Wilfred W. Scott.

Preparation and Solution of the Sample

The following facts regarding solubility may be of value in the determination of strontium. 100 ce. of water dissolves 1.74 grams Sr(OH)₂·H₂O at 20° C. The hydroxide is less soluble than that of barium. The peroxide dissolves to the extent of only 0.008 gram per 100 ce. 20° C. One hundred ee, of water dissolves 0.0011 gram ¹ SrCO₂ (18°); 0.0114 gram SrSO₄ at 18° and 0.0104 at 100°; the presence of sulphuric acid decreases this solubility, i.e., 0.00083 gram SrSO₄; 0.0051 gram SrC₂O₄·H₂O at 18° and 5 grams at 100° C.; the presence of oxalic acid decreases this solubility. The sulphate dissolves in concentrated sulphuric acid, and is appreciably soluble in HCl, HNO₂, HC₂H₃O₂, NH₄Cl, NH₄NO₂, NaCl, MgCl₂. The earbonate and oxalate are soluble in mineral acids.

The procedure for the treatment of ores and strontium products is the same as those described for barium and calcium. We refer to the chapters on these elements for the preparation of the strontium solution.

SEPARATIONS

Separation of Strontium from Magnesium and the Alkalies. The procedure is the same as the one given in detail under barium for the separation of the alkaline earths from magnesium and the alkalies. Either the oxalie acid method or precipitation of strontium as a sulphate in presence of alcohol will accomplish this separation. If a sulphate precipitation is made it will be necessary to fuse the sulphate with sodium carbonate to get it into solution or to effect further separation from members of the ammonium carbonate group, should these be present.

Separation of Strontium from Calcium.² Strontium and calcium are converted into the nitrates and taken to dryness and all water expelled by heating to 140° C. for an hour or more. The nitrates are now extracted with equal parts of absolute alcohol and anhydrous ether or by boiling with amyl alcohol at 130° C. (hood). Strontium remains insoluble and calcium goes into solution as the nitrate. Strontium nitrate may require further solution in water, evaporation to dryness, heating and extraction to remove calcium completely, should this be present in large excess. The nitrate of strontium is dissolved in water and strontium determined by one of the procedures given later. See detailed procedure for separation under Barium.

Separation of Strontium from Barium. The procedure is given in detail under chapter on Barium. In brief one of the following methods may be used: Stroatium and barium in a mixture of the nitrates are separated from calcium by treatment with ether-alcohol nrixture, in which Ba(NO₃)₂ and Sr(NO₃)₂ are insoluble. The nitrates dissolved in water are separated by precipitating barium as BaCrO₄ from a faintly acetic acid solution, strontium remaining in solution.

If preferred, barium may be first removed as a chromate, strontium and calcium precipitated from an ammoniaeal solution by (NH₄)₂CO₂ as carbonates, the earbonates converted to nitrates and Sr(NO₂)₂ separated from Ca(NO₂)₂ in an ether-alcohol solution or by amyl alcohol. Details of the separations are given under Barium.

¹ Treadwell elaims solubility =0.00055, i.e., 1 part SrCO₂ in 18,045 parts of water.

² Advantage may be taken of the insolubility of strontium sulphate in ammonium sulphate in separating it from the soluble calcium salt.

GRAVIMETRIC METHODS

Strontium may be conveniently determined either as the sulphate, the carbonate or as the oxide. The first procedure is considered the best by authorities.

Determination as Strontium Sulphate, SrSO₄

Procedure. A slight excess of dilute sulphuric acid is added to the neutral solution of strontium, and then an equal volume of alcohol. The mixture is stirred well and settled for several hours, or overnight, if more convenient. The precipitate, SrSO₄, is filtered onto a small ashless filter and washed first with 50% alcohol containing a little sulphuric acid, then with alcohol until free of acid. The precipitate is dried and the paper and the greater part of the salt ignited separately, then combined and weighed as SrSO₄.

Factors. $SrSO_4 \times 0.477 = Sr$, or $\times 0.8037 = SrCO_3$, or $\times 0.5642 = SrO$.

Determination as Strontium Carbonate

Strontium carbonate is not readily decomposed by ignition as is calcium carbonate, so that its determination in this form may be satisfactorily made.

Procedure. The carbonate is precipitated by adding ammonium carbonate

receaure. The carbonate is precipitated by adding animonium carbonate in slight excess ¹ to the animoniacal solution of strontium, heated nearly to boiling. The solution is allowed to stand for several hours and filtered cold. The washed strontium carbonate and filter are ignited gently and the cooled residue weighed as SrCO₂.

Factors. $SrCO_3 \times 0.5935 = Sr$, or $\times 1.2443 = SrSO_4$, or $\times 0.702 = SrO_2$.

Determination as Oxide, SrO

Strontium is precipitated as the oxalate by addition of ammonium oxalate to the slightly ammoniacal solution. The precipitate is filtered and washed with water containing ammonium oxalate. The residue is ignited and weighed as SrO.

Factors. $SrO \times 0.8456 = Sr$, or $\times 1.7726 = SrSO_4$, or $\times 1.4245 = SrCO_2$.

VOLUMETRIC METHODS

The volumetric methods for determining strontium presuppose its isolation from other elements.

Alkalimetric Method, Titration with Standard Acids

Either the carbonate or the oxide of strontium may be titrated with standard hydrochloric or nitric acids. The compound is treated with a known amount of standard acid added in excess, using methyl orange indicator. The solution is heated below boiling to complete the reaction and, upon cooling, the excess of acid is titrated with standard alkali.

One ec. normal acid = 0.04381 gram Sr, or 0.05181 gram SrO, or 0.07381 gram SrCO₂.

¹ N. B. Avoid a large excess of (NH₄)₂CO₄. NH₄Cl has a solvent action on SrCO₄.

Titration of the Chloride with Silver Nitrate

Strontium chloride, free from other chlorides, may be determined indirectly by titration of its combined chlorine with silver nitrate by Mohr's method, using potassium chromate indicator. One cc. N. AgNO₁=0.04381 gram Sr.

The oxide or carbonate is slightly supersaturated with hydrochloric, then taken to dryness and heated at 120° C. in the air bath to expel the excess of acid. Chlorine is determined on an aliquot portion.

SULPHUR

S, at.wt. 32.065; sp.gr. 2.035; m.p. 111°; b.p. 444.53°; oxides S₁O₁, SO₁, SO₁, SO₁, S₁O₁; principal acids H₁S₁O₄, H₁SO₁, H₂SO₄, H₂SO₄, and H₂S₁O₄.

DETECTION

The following tests include the detection of free sulphur and its more important combined forms.

Element. Sulphur is a polymorphous, yellow, brittle, odorless and tasteless solid; existing in the rhombic, monoclinic and triclinic crystalline forms, and also in an amorphous state. At 111° i t melts to a pale yellow liquid; at 180° it thickens to a dark gum-like material, containing a large percentage of amorphous sulphur; at 260° it becomes a liquid again, and at 444.53° it boils, giving off a brownish-red vapor.

The important commercial forms of elemental sulphur are: Flowers of Sulphur, consisting of rhombic sulphur and not less than 30% of amorphous sulphur with a small amount of occluded free acid; Powdered Sublimed Sulphur (often called Flour Sulphur, a confusing term that should be abolished), consisting essentially of finely ground sublimed sulphur all in the rhombic form though at times a small percentage of amorphous sulphur is present; Refined Brimstone and Roll Sulphur (in some sections termed Virgin Lump Sulphur), consisting entirely of sublimed sulphur in the rhombic form; Powdered Brimstone (often termed Commercial Flour, Superfine Flour and the like); and Brimstone or Crude Lump Sulphur. In these commercial sulphurs the physical form and the presence of certain small amounts of impurity are the characteristics of most importance as all the varieties named, even the Brinistones, usually contain in excess of 99.5% available sulphur.

Heated in the air sulphur burns with a blue flame, and is oxidized to SO₂, a gas with a characteristic pungent odor. This gas passed into a solution of potassium permanganate will decolorize it, if SO₂ is in excess of the amount that

will react with the KMnO₄ in the solution.

If sulphur is dissolved in a hot alkali solution and a drop of this then placed on a silver coin, a stain of black Ag₂S will be evident, due to the action of the sulphur.

Sulphides. Hydrogen sulphide, H₂S, is liberated when a sulphide is treated with a mineral acid. This gas blackens moist lead acetate paper. H₂S has a very disagreeable odor, which is characteristic.

Sulphates. A white compound, BaSO, is precipitated in presence of free hydrochlorie acid when a solution of barium chloride is added to a solution of a sulphate.

Insoluble sulphates are decomposed by boiling or fusion with alkali carbonates, forming water-soluble alkali sulphates.

Chapter contributed by Wilfred W. Scott with additions by Charles A. Newhall.

Sulphites. Sulphur dioxide, SO₂, is evolved when a sulphite is treated with hydrochloric acid. The odor of the gas is characteristic.

Sulphur dioxide decolorizes a solution of potassium permanganate. (Use

very dilute solution.)

Sulphites are distinguished from sulphates by their failure to form a white precipitate, when barium chloride is added to the solution acidified with hydrochloric acid; also by the fact that H₂S is formed when zinc is added to a solution of a sulphite, acidified by hydrochloric acid.

Thiosulphates. Sulphur dioxide is evolved and free sulphur precipitated when a thiosulphate is acidified with dilute mineral acids. In presence of

oxidizing agents sulphides will also liberate free sulphur.

Thiosulphates are strong reducing agents.

ESTIMATION

The determination of sulphur may be required in a great variety of substances, minerals, rocks, sulphur ores, acids, salts, water, gas, coal and other organic matter, insecticides, fungicides, stock medicants, fertilizer and other agricultural materials.

The substance occurs in nature principally in the following forms:

Element. Found free, generally mixed with earthy matter. The commercial product is exceedingly pure and may contain over 99.5% S.

Sulphur Dioxide. The gas, together with free sulphur, is found in volcanic

regions.

Hydrogen Sulphide. Occars in mineral waters and in the air, from decaying

organic matter.

Sulphide Ores. Iron pyrite, Fe₅2 (30 to 50% S); ferro ferric sulphide, Fe₅O₅-5FeS; pyrrhotite, Fe₇S₈; copper pyrites, CuFeS₂; realgar, As₅S₂; orpiment, As₅S₃; galena, PbS; cinnabar, HgS; zinc blende, ZnS.

Sulphate Ores. Gypsum, CaSO₄·2H₄O, very abundant; barytes, or heavy spar, BaSO₄; celestite, SrSO₄; kieserite, MgSO₄·H₂O; bitter spar or Epsom salts, MgSO₄·7H₂O; Glauber salt, Na₂SO₄·10H₂O; sulphates of alkalies in animal

and plant fluids.

The gravimetric determination of sulphur, by procedures of technical importance, depends upon its precipitation as barium sulphate, BaSO₄, after converting it into sulphuric acid, or a soluble sulphate, if not already in this form. Oxidation of free sulphur, sulphides, sulphites, metabisulphites, thiosulphates may be accomplished by either dry or by wet methods, details of which are given under

subsequent procedures.

The volumetric methods of determining sulphur depend upon titration with oxidizing agents, or by acids, or by alkalies, according to the form of the sulphur compound, or by means of a substance forming an insoluble compound with sulphuric acid. For example sulphides are treated with a strong mineral acid (HCl), the evolved H₂S absorbed in a suitable reagent, and the sulphide formed is titrated with standard iodine. Sulphites may be determined either by oxidation with iodine or by titration with an acid in presence of methyl orange. Acid sulphites or metabisulphites may be determined by the iodine titration or by titration with an alkali in presence of phenolphthalein. Thiosulphates are titrated with iodine.

Preparation and Solution of the Sample

Sulphide. Sulphides of Na, K, Cs, Rb, Ca, Sr, Ba, Mg, Mn, Fe are soluble in dilute mineral acids. The sulphides of Ag, Hg, Pb, Cu, Bi, Cd, Co, Ni require strong acids for decomposition. These are also insoluble in sodium hydroxide and potassium hydroxide solutions. As, Sb and Sn sulphides are insoluble in dilute acids, but soluble in alkalics.

Sulphate. With exception of BaSO₄, CaSO₄, SrSO₄ and PbSO₄, sulphates are soluble in water.

Thiosulphate. Nearly all are soluble in water.

Sulphite. With exception of the sulphites of the alkalies, sulphites of the nictals are difficultly soluble in water, but readily decomposed by acids.

Decomposition of Sulphur Ores

The wet procedure for oxidation and decomposition of sulphur ores is given in detail under the Gravimetric Methods, page 498. This process is used for the valuation of the ore, and is applicable to a wide range of substances.

Fusion Method. One gram of the finely ground ore (80 mesh) is intimately mixed with 6 grams of zine oxide-sodium carbonate mixture (2 parts ZnO+1 part Na₂CO₂), placing 2 grams more of the mixture over the charge. The material is fused and sulphur extracted according to the procedure described for coal—Eschka's method.

Sulphur in Coal, Eschka's Method

One gram of coal is intimately mixed with 3 grams of Eschka's compound, consisting of 2 parts of porous, calcined magnesia and 1 part of anhydrous sodium carbonate. The mixture, placed in a platinum crucible, is covered with about 2 grams more of Eschka's compound. The charge is placed in an open platinum crucible, which is protected from the flame by a shield, as shown in Fig. 65. If possible, a sulphur-free flame should be used to avoid contaminating the material. With proper precautions, the shield will prevent this. Heating in a crucible electric furnace completely avoids sulphur contamination. The mixture is heated very gradually, to drive off the volatile matter, the charge being stirred frequently with a platinum wire to allow free access of air. The heat is increased, after half an hour, to a dull redness. When the carbon has burned out, the gray color having changed to a yellow or light brown, the heat is removed and the crucible cooled.

The powdered fusion is digested with 100 cc. of hot water for half an hour, and the clear liquor decanted through a filter into a beaker. The residue is washed twice more with hot water, by decantation, and finally on the filter, until the volume of the total filtrate amounts to about 200 cc. About 5 cc. of bromine and a little hydrochloric acid are added, and the solution boiled. Sulphuric acid is now precipitated as BaSO₄ by addition of barium chloride to the hot solution, and sulphur determined by the first of the gravinetric procedures.

Sulphur in Rocks, Silicates, and Insoluble Sulphates

The material in finely powdered form is fused in a large platinum crueible with about six times its weight of sodium carbonate (sulphur free) mixed with about 0.5 gram of potassium nitrate. The charge is protected from the flame

by an asbestos board or silica plate with an opening to accommodate the crucible snugly, as shown in Fig. 65. The fusion is extracted with water, the filtrate evaporated to dryness and silica dehydrated. The residue is moistened with strong hydrochloric acid, then taken up with a little water, boiled free of CO₂, and silica filtered off. The filtrate contains the sulphate, which is now precipitated as barium sulphate according to one of the standard procedures.

Barium Sulphate. This is transposed by fusion with sodium carbonate, as stated above. Barium parbonate remains in the water-insoluble residue. It is advisable to wash the residue in this case with hot sodium carbonate solution, to insure complete removal of the sodium sulphate. The filtrate is acidified with

HCl, boiled free of CO2 and BaSO4, then precipitated.

Lead Sulphate. This may be transposed by digesting the compound with a strong solution of sodium rarbonate saturated with CO₂, keeping the solution at boiling temperature for half an hour or more. The sulphate will be in solution and the lead is precipitated as the water-insoluble carbonate.

Strontium or calcium sulphates may be transposed by the procedure described for lead.

SEPARATIONS

Substances Containing Iron

In precipitating barium sulphate, in presence of ferric salts, from hot solutions by the gravimetric procedure commonly followed, considerable iron is carried down by the precipitate. Since Fe₂(SO₄)₃ loses SO₃ upon ignition, and since Fe₃O₄ weighs much less than BaSO₄, low results will be obtained. Hence the removal of iron is necessary, or a method should be followed in which iron does not interfere. It is found that barium sulphate precipitated from a large volume of cold solution, in which the iron has been reduced to ferrous condition, is free from iron. Details of this procedure are given in the second of the gravimetric methods, page 498.

If sulphur is to be precipitated from hot solution of comparatively small volume (200 to 400 ce.), it is necessary to remove iron. This is accomplished by precipitating this as Fe(O11), by addition of animonium hydroxide in decided excess (5 to 10 cc. excess of strong NH₄O11, sp.gr. 0.90). If the solution is barely neutralized with animonia, the iron hydroxide carries down considerable of the sulphate. Even with the precaution recommended some of the combined sulphurie acid is occluded by the precipitate, so that it is necessary to recover this by dissolving the precipitate with hydrochloric acid and reprecipitating the ferric hydroxide with an excess of animonia. The combined filtrates are now treated with barium chloride, upon acidification with hydrochloric acid, according to the procedure first given, page 497, and the sulphate determined.

Separation of Sulphur from Metals Forming an Insoluble Sulphate

This is accomplished by fusion of the compound with sodium carbonate and extraction of the mass with water. The metal remains with the residue and the sulphate of the alkali passes into solution. For details see subject under Preparation and Solution of the Sample, page 494.

Nitrates and Chlorates. These are carried down with the precipitate as barium salts if they are present in appreciable amount. They may be removed from the solution by evaporation to dryness with hydrochloric acid.

Silica. Silica will be carried down with the barium sulphate precipitate if present in appreciable amounts. It is removed by evaporation of the solution with hydrochloric acid, dehydrating the silicic acid, taking up with HCl and water and filtering.

Ammonium and Alkali Salts. These have a negligible effect on the precipitate of BaSO₄ if this is precipitated from a large volume, according to the second gravimetric procedure.

GRAVIMETRIC DETERMINATION OF SULPHUR Precipitation as Barium Sulphate

Preliminary Remarks. The procedure depends upon the insolubility of barium sulphate, BaSO4, in neutral or slightly acid solutions. It was formerly the general practice to precipitate the sulphur by adding a 10% barium chloride solution to the hot sulphate solution, which had been diluted from 200 to 400 cc., according to the amount of sulphur that was present (not over 0.2 gram sulphur per 100 cc.), containing 1 to 3 cc. of free concentrated hydrochloric acid per 100 cc. of solution. Special precautions were given to have the solution boiling hot, and to avoid having a volume of over 400 cc., a smaller sample being taken in high sulphur ores, rather than increase the volume. Extended experiments have shown that it is preferable to precipitate the sulphate from a large volume of cold solution. The product obtained is less apt to occlude impurities, the crystals are larger than those obtained in hot concentrated solutions, and do not pass through the filter. Precipitation may be made in presence of large amounts of iron, copper and other impurities. The procedure requires large beakers of 2- to 21-liter capacity. special precipitating cups, and a suction apparatus, as shown in Figs. 60, 61, 62 and 63. This apparatus may not always be available, and occasionally it is advantageous to precipitate the sulphur in a small volume, specially when the sulphur content of the material is low, hence, although the second procedure is generally recommended, the older method is also included.

I. Precipitation of Barium Sulphate from Hot Solutions

Procedure. The sulphur should be present in solution either as free sulphuric acid or as a sulphate salt. The solution is made acid by addition of hydrochloric acid (phenolphthalein indicator), and then 4 cc. added in excess (HCl, sp.gr. 1.2). After diluting to a volume of 400 cc. with hot water, the mixture is heated to boiling, and a 10% solution of barium chloride added in a fine stream, through a funnel with a capillary stem, or from a burette, at the rate of 10 cc. in two to ten minutes. The reagent is added in slight excess of that required to react with the sulphuric acid or sulphate. (Ten cc. of 10% BaCl₂.2H₂O solution will precipitate about 0.13 g. of sulphur.) The beaker is placed on a steam buth and the pre-

¹ E. Hintz and H. Weber recommend adding 100 cc. of N/10 BaCl₂ solution, boiling hot, to the hot sulphate solution all at once in place of slowly, as recommended in general practice. (See Treadwell and Hall, "Analytical Chemistry," 2, 3d Edition, p. 460.)

eipitate allowed to settle for about two hours. The solution is filtered through a fine grade of filter paper (B. & A. grade A, or S. & S. grade No. 90), or through a tared Gooch erucible. Since the precipitate frequently passes through the filter it is advisable always to pass the solution through the same filter a second time. The precipitate is washed ten times with hot water, then dried, and ignited gently over a Bunsen burner, or in a muffle, for half an hour. (Blasting is not necessary, nor desirable.) The white BaSO₄ is cooled in a desiceator, and then weighed. If a filter paper has been used in place of a Gooch crucible, the ignition is best made in a porcelain crucible, with free access of air, the ignited sulphate, upon cooling, is brushed out of the crucible and so weighed.

Factors. BaS()₄×0.1373 = S, or ×0.4202 = H₂S()₄, or *×0.3766 = FeS, or ×0.2744 = S()₂, or 0.3430 = S()₃, or ×0.4115 = S()₄.

Note. If much iron or alumina is present it is advisable to precipitate the sulphate from a large volume, by the second method, rather than attempt to remove these substances. If BaSO₄ is present in the original material its weight should be included with that of the precipitate.

II. Precipitation of Barium Sulphate from Cold Solutions— Large Volume

Introduction. The method worked out by Allen and Bishop, General Cnemical Company, is especially adapted to the determination of sulphur in iron pyrites and materials high in sulphur, 30 to 50% sulphur, but by varying the amount of material used the range may be extended from smaller to greater amounts. The finely ground sample is oxidized by means of a mixture of bromine and potassium bromide, followed by nitric acid. The nitric acid is expelled by evaporation to dryness, followed by a second evaporation with hydrochloric acid, which dehydrates the silica. Iron is now reduced to the terrous condition and the silica and residue, undissolved by addition of hot water and HCl, is filtered off. The sulphur is precipitated in a large volume of cold solution, by barium chloride solution, as BaSO₄ and so weighed.

Reagents. Bromine Potassium Bromide Solution. 320 grams of potassium bromide are dissolved in just sufficient water to cause solution and mixed with 200 ee. of bromine, the bromine being poured into the saturated bromide solution. After mixing well the solution is diluted to 2000 ec.

Bromine—Carbon Tetrachloride Solution. Carbon tetrachloride saturated with bromine.

Barium Chloride, anhydrous, $5^{C'}_{10}$ solution; or crystals, $6^{C'}_{10}$ solution.

Procedure. Preparation of Sample. The sample ground to pass 80-mesh sieve is carefully mixed and quartered down to 10 grams. This is dried for one hour at 100° C, and then placed in a weighing tube.


A factor weight, 1.373 grams of the sample, is placed in a deep beaker, 300 cc. capacity, 2½ by 4½ ins.

Oxidation of Sulphur. Ten ec. of the bromine-potassium bromide mixture for pyrrhotite ore, or bromine-carbon tetrachloride reagent for pyrites ores, are added and the beaker covered with a dry watch-glass cover. After standing

¹ Paper before Eighth International Congress of Applied Chemistry: "An Exact Method for the Determination of Sulphur in Pyrites Ores," W. S. Allen and H. B. Bishop.

fifteen minutes in the cold bath (a casserole of water will do), with occasional shaking of the beaker, 15 ec. of strong nitric acid are added and the mixture


allowed to stand fifteen minutes longer, at room temperature, and then warmed on an asbestos board on the steam bath until the reaction has apparently ceased and the bromine has been volatilized. The beaker is now placed within the ring of the steam bath so that the lower portion is exposed to steam heat. The solution is evaporated to dryness, the cover of the beaker being raised above the rim by means of riders (U-shaped glass rods), Fig. 60, 10 ec. of strong hydro-



chloric acid are now added and the solution again evaporated to dryness to expel the nitric acid. The silica is dehydrated by heating in the air oven at 100° C. for one hour, or overnight if preferred.

Reduction of Iron. Four ec. of hydrochloric acid (sp.gr. 1.20), followed five minutes later by 100 cc. of hot water, are added, the sides of the beaker and the cover being rinsed into the solution. The riders being removed, the sample is gently boiled for five minutes to insure the solution of the sulphate. After cooling for about five minutes, approximately 0.2 gram powdered aluminum is stirred into the solution, keeping covered during the intervals between stirring. When the iron has been reduced, the solution becoming colorless, the sample is filtered into a 2500-ec. beaker, through a 12½ cm. filter paper (S. & S. No. 590 or B. & A. No. A). The beaker should be copped out and the residue on the filter washed nine times with hot water, filling the filter funnel and draining each time.

Precipitation of the Sulphur. The solution in the large beaker is diluted to 1600 cc. with cold water and 6 cc. HCl (sp.gr. 1.20) added, and mixed by



Apparatus for Precipitating Sulphur.

special files are the column chloride solution is now added by means of a special delivering cup (Figs. 61 and 62), which should drain at the rate of 5 cc. per minute. 125 cc. of barium chloride solution are added for ores containing 30 to 50% sulpling, the factor weight being taken. The solution is not stirred while the barium chloride is being added, but when the cup has drained, the solution is mixed by stirring. The BaSO₄ is allowed to settle, two or

three hours being advisable, overnight being preferred.

Filtration. The clear solution is filtered through a weighed Gooch crucible (35 ec.), using suction. This is best done by the automatic arrangement shown in Fig. 63. The beaker containing the solution is placed on a shelf; a siphon dipping to within half an inch of the precipitate at the bottom of the beaker is connected to the Gooch crucible by means of a tightly fitting stopper. The Gooch and thistle tube are best connected by heavy rubber tubing. The

suction flask, or bottle, should have a capacity of about 3 liters. A Geissler stop-cock passes through the rubber stopper in the suction flask to relieve the




Fig. 63.—Apparatus for Filtering Barium Sulphate.

pressure when the Gooch is to be removed. The precipitate is washed onto the asbestos mat in the crucible and washed with cold water six times, the beaker being copped out as usual.

Ignition. The precipitate is dried by placing the erucible on an asbestos board over a flaine for twenty-five minutes and then heated over a direct flame for thirty minutes.

Calculation. $BaSO_4 \times 10 = per eent S$. (If factor weight is taken.)

 $BaSO_4 \times 0.1373 = gram S$.

Notes and Precautions

Although barium sulphate is only slightly soluble in water, it is appreciably soluble in the salts of the alkalies (Na, K and NII4), and in a large excess of hydrochloric acid.

Barium sulphate occludes salts, especially nitrates and chlorides. Ferric chloride is carried down with this precipitate, though ferrous ehloride is not; hence the reduction of iron is necessary. Occlusion of iron causes low results, as will be seen from the fact that with heating of Fe₂(SO₄)₃, SO₂ is volatilized, the salt decomposing to Fe₂O₂+SO₃. With the iron reduced the precipitate burns

perfectly white, whereas with ferrie iron present the precipitate is invariably red or yellow. Aluminum powder used by W. H. Seamon, for reduction of iron in determination of sulphur, suggested its value in the method above given.

Potassium bromide is added to the bromine mix as a diluent to prevent too vigor-

ous a reaction. Cooling the solution is for the same purpose as a loss of sulphur will result if the reaction is violent. This is especially the case in pyrrhotite ore.

Otto Folin 2 shows that precipitation of BaSO4 in a large volume of cold solution produces large crystals.

Mechanical loss and reduction of BaSO4 is avoided by the Gooch crucible.

The method has been thoroughly tested in the laboratorics of the Gen. Chem. Co. and has become a standard method for sulphur.

Evolution Method for Determining Sulphur in Iron, Steel, Ores, Cinders, Sulphides and Metallurgical Products

Introduction. The method depends upon the fact that hydrogen sulphide is evolved when a sulphide is acted upon by a strong acid such as hydrochloric acid. This gas, absorbed by a suitable reagent, may be determined gravimetrically by weighing directly the precipitated sulphide, or by oxidation of either the hydrogen sulphide evolved or the sulphide formed in the absorbing reagent.

Chemical Engineer, September, 1908.

Journal of Biological Chem., 1, 131-159.

Gravimetrically. (a) Evolution of H₂S into solutions of ZnCl₂, KOH, KMnO₄, AgNO₂, Hg(CN)₂, H₂O₂, Br+HCl and subsequent oxidation to sulphate when necessary, and precipitation as BaSO₄. (b) Absorption of H₂S by neutral or alkaline solutions of AgNO₂. (c) Absorption of HS is solutions of AgNO₃. (d. and weighing the precipitated sulphide H.S in solutions of AgNO, CdCl, and weighing the precipitated sulphide.

and precipitating sulphur as BaSO4. It may be determined volumetrically 1 by titrating the precipitated sulphide with iodine or by titrating the acid, formed by the reaction, with standard caustic. The iodine and caustic titrations may be made on the same run, or the sulphide may be weighed and the filtrate containing the free acid titrated, thus double checking results. The following reaction takes place when the gas is evolved and absorbed by neutral cadmium sulphate:

H₂S+CdSO₄=CdS precipitate+H₂SO₄ free acid.

The method is especially adapted to the determination of sulphur in iron and steel or in metallurgical products containing small amounts of sulphide. It

may be applied to products containing larger amounts of sulphur as sulphides or sulphates, the latter condition requiring a special preliminary treatment.

The method is not applicable for determining free sulphur or sulphur in


iron pyrites.

Reagents. Iodine Solution. Two strengths of this reagent should be at hand for general work:

For iron and steel and low sulphur briquettes, etc. = .01 to 0.5% S..... N/30 I For sulphur products containing over 0.5% S..... N/10 I

Starch Solution. Made from a good grade of soluble starch, I gram per 200 ec. of water. Fresh solutions are desirable, as the deteriorated material produces a greenish-brown color in place of the delicate blue desired. Flocks of insoluble starch will eause the same difficulty.

Cadmium Chloride or Cadmium Sulphate Solutions. Ammoniacal Solution. Fifty-five grams of CdCl₂·2H₂O or 70 grams of the sulphate are dissolved in 500 ee. of distilled water. To this are added 1200 ee. NH4OH (sp.gr. 0.90) Fig. 64.—Scott's Apparatus for Determinand the solution diluted to 2500 cc. The solution is of such strength that



ing Sulphur in Iron and Steel.2

50 ec. will precipitate approximately 0.175 gram sulphur evolved as H₂S. This is equivalent to about 3.5% sulphur on a 5-gram sample.

¹ Volumetrically. (a) Absorption in a solution of KOII, CdCl₂ or CdSO₄, ZnCl₃ or ZnSO₄, Na₂HAsO₂ and titration with iodine solution. (b) Absorption in iodized KI and titration of the excess of iodine with Na₂S₂O₃ solution. (c) Absorption in a neutral solution of a metallic salt and titration of the liberated acid. (d) Absorption in caustic alkali and addition to an acid solution of a reducible salt, e.g., Fe₂O₃ and titration of the lower oxide, FeO Apparatus designed by W. W. Scott.

Neutral Solution. To be used where titration with caustic is desired. Seventy grams of $CdSO_4$ are dissolved in water and made up to 2500 ee. The solution should be neutral to methyl orange, otherwise add the requisite amount of H_2SO_4 or NaOH necessary, determined by titration of an aliquot portion.

Hydrochloric Acid. One part concentrated acid to an equal volume of dis-

tilled water.

Sulphuric Acid. One volume of concentrated acid to four volumes of distilled water.

Reducing Mixture for Reduction of Sulphates. Five parts of NaHCO, 2 parts of C.P. aluminum powder and 1 part of pure carbon, best made by charring starch. A blank should be determined on this material and allowance made accordingly.

Stannous Chloride. Ten-per cent solution.

Fine Granular Aluminum or Zinc Metal. Sulphur free, 20 mesh.

Apparatus. The apparatus shown in the illustration, Fig. 64, is the author's 'modification of the form used at Baldwin Locomotive Works. This consists of an Erleuneyer flask Λ of about 500-cc. capacity with large base. With material in which violent foaming occurs, during the evolution of hydrogen sulphide, it is advisable to use a wash bottle with large base, in preference to an Erlenmeyer flask. Through a rubber stopper is inserted a thistle tube with glass stop-cock D, by which the acid is introduced into the flask. The hydrogen sulphide passes through a potash connecting bulb with trap as shown. A hole blown in the side of the tube prevents liquid being swept through. Connected to the potash bulb is the absorption bulb C, which is suspended by a wire attached to the thistle tube. The apparatus is compact, so that on a large hot plate, 30 by 20 ins., a dozen outfits may readily be accommodated. With the use of this apparatus the writer has been able to make over seventy-five determinations of sulphur in steel in an ordinary day's run.

Preparation and Amount of Sample

The amount of material to be taken for the determination depends upon the sulphur content as shown by the following table:

to take for Analysis. grams 5 25
•

The class of material will govern the method of procedure.

Iron and Steel. A 5-gram sample of drillings or finely divided material is treated directly in the evolution flask with hydrochloric acid, 1:1, and the hydrogen sulphide absorbed in ammoniaeal cadmium chloride. The sulphide formed is titrated with iodine.

Iron Ore Briquettes and Materials Containing Sulphates. Low Sulphur. Preliminary Reduction. A 5-gram sample is intimately mixed with an equal weight of reducing mixture (NaHCO₂+Al+C) and wrapped in a 9-cm. ashless filter. The charge is placed in a 50-cc. nickel crucible with cover. The crucible

is inserted helf way into an asbestos board or perforated silica plate (see Fig. 65) and after covering, placed over a low flame of a Méker blast burner. The

flame of the blast is gradually increased during the first five minutes and the charge blasted for about twenty minutes. The erucible will appear a bright red and carbon monoxide gas escaping from under the crucible lid will burn. The loss of sulphur, however, is not appreciable. The erueible is cooled without removing the cover. When cold the fused mass is quickly pulverized and placed in the dry evolution flask containing a mat of aluminum granules or C.P. zine dust or granulated tin. Hydrogen sulphide is best evolved with hydrochloric acid to which 4 or 5 cc. of 10% stannous chloride has been added to reduce ferrie iron. The gas is absorbed in ammonical cadmium chloride and the cadmium sulphide formed titrated with iodine.

Iron Sulphide for Available H2S. Since this product runs over 20% available hydrogen sulphide not over 0.5 gram sample should be taken. The H2S is evolved by addition of dilute sulphuric acid, 1:4, in place of hydrochloric acid, and is absorbed by neutral cadmium sulphate. The acid formed by the reaction is titrated by standard N/10 NaOH.




Fig. 65.

Sodium Sulphide or Water-soluble Sulphides for Available H2S. Ten grams dissolved in water and diluted to 1000 ce.; 50 ec. = (0.5 gram) taken for analysis.

Details of Procedure

Evolution of Hydrogen Sulphide. One-half to I gram of aluminum or zine granules, 20 mesh, is placed over the bottom of the evolution flask and the sample placed above this mat of metal. The stopper with the thistle tube and condenser is inserted snugly into the neck of the flask. An absorption bulb containing about 20 cc. of distilled water is attached to the condenser. This bulb serves as a trap for the HCl that is driven out of the flask during the boiling. To this bulb is attached a second bulb containing 50 ec. of ammoniacal cadmium chloride. A third bulb may be attached if the sulphur content of the material examined is high; this, however, is seldom necessary when ammoniacal cadmium chloride is used. The rubber stopper and all rubber connections being air tight, 100 ec. of warm HCl, 1:1, is poured into the flask through the thistle tube, the stem of which should now dip well below the acid. The stopcock is closed during the violent action of the acid on the sample and opened when this has subsided. The acid trap prevents loss of H2S through the thistle tube. The apparatus is now placed on the hot plate and the sample boiled vigorously for about twenty minutes. The flask is taken off the hot plate and the contents allowed to cool. At this stage it may be advisable to draw a current of air through the apparatus to sweep out any residual H2S that may remain in the flask. Hydrogen gas is preferable to air.

(a) The contents of the bulbs are poured into a 600-cc. beaker containing about 400 ce. of distilled water. The bulbs are washed out first with water and then with dilute acid. The excess of ammonia is neutralized with concentrated HCl, 5 ee. of starch solution added and the sulphide immediately titrated with standard iodine, additional hydrochlorie acid being added from time to time during the titration to insure complete decomposition of the sulphide. The liquid appears yellowish red, orange, purplish red and finally a deep blue. Since the sulphide, when present in appreciable quantity, decomposes slowly, the solution should be strongly acid at the completion of the titration, and five minutes should be allowed for a permanent end-point.

Knowing the amount of iodine necessary, a check run may be made by adding to the neutral solution an excess of iodine followed by 5 ee. of starch solution and a large excess of concentrated hydrochloric acid. The excess of iodine is titrated with N/10 thiosulphate, Na₂S₂O₂, solution. (Arsenous acid will not do.) This procedure will prevent the loss of H₂S, which is apt to occur in

samples high in sulphide.

(b) An alternate method is frequently advisable in high sulphurs. The precipitate is separated from the solution containing ammonia by filtration. The eadmium sulphide is now placed in the 600-cc. beaker with water and an excess of iodine run in. Starch is added, followed by hydrochloric acid. The excess of iodine is titrated with sodium thiosulphate, Na-S₂O₂. By this method the heat action during the neutralization of ammonia is avoided and only the precipitate is titrated.

When the iodine titration exceeds 50 cc. of N/10 iodine, a smaller amount of the sample should be taken for analysis; the iodine titration for amounts of sulphur exceeding 0.1 gram is not satisfactory, owing to a fading end-point. The method for determining available hydrogen sulphide in high sulphide products, dealing with the titration of the free acid formed during the reaction, permits of larger samples being taken. Details of this method are given on page 509.

One ce, N/10 iodinc = 0.001604 gram S.

Tenth Normal Equivalents

```
One ec. of N/10 iodine = 0.001704 gram H<sub>2</sub>S
                            =0.004396 gram FeS
        "
                  "
                            =0.003904 gram Na<sub>2</sub>S
                  . .
                            =0.003607 gram CaS
        . .
                  "
                            =0.008471 grain BaS
                  ..
                            =0.00561 gram Sb<sub>2</sub>S<sub>3</sub>
                  "
                            =0.011959 \text{ gram PbS}
        "
                  . .
                            =0.011634 gram HgS
        "
                  . .
                            =0.004782 gram CuS
        "
                            =0.007224 gram CdS
         "
                            =0.004872 \text{ gram ZnS}
         "
                  . .
                            =0.003269 \text{ gram Zn}
```

Combustion Method for Evaluation of Sulphide Ores. When a sulphide ore (pyrrhotite) is heated to redness in presence of oxygen both sulphur dioxide and trioxide are evolved. The first may be absorbed in suitable reagents and estimated volumetrically or gravimetrically. The trioxide mist is best retained by asbestos and weighed. The combustion furnace with silica tube used for determinations of carbon is adapted for sulphide ores. The finely powdered

dry sample, spread in a thin layer in a 3-inch porcelain boat, is placed in the red hot tube and burned in a current of oxygen, which has been purified by passing through sodium hydroxide, strong sulphurie acid and phosphorus pentoxide. The trioxide mist is removed by passing the evolved gases through an asbestos filter (P2O2 bulb with asbestos in one arm adjacent to the combustion tube and P₂O₄ in the other). The SO₂ is absorbed in a mixture of bromine and nitric acid, and the sulphuric acid formed is titrated after removing the reagent by evaporation; or it is absorbed in an excess of standard iodine, the excess titrated with sodium arsenite or thiosulphate, and sulphur calculated. The iodine method is preferable to the bromine, as it is more rapid and the reagent less disagreeable to handle. The gravimetric method is the most reliable. The dioxide is absorbed in chromic acid (caustie will not give correct results owing to its affinity for carbon dioxide, a product of combustion of the free and combined carbon, that are generally present in sulphide ores. Pyrrhotite frequently contains as much as 1% carbon) and weighed. The combustion method cannot be recommended for extreme accuracy. The procedure may be used for the estimation of available sulphur, but does not give the total sulphur of the orc, since .2 to .5% remains in the cinder. Error may result from the following causes: (1) Incomplete combustion of the sulphur-due to sublimation of the sulphur to cooler zones of the combustion tube, and to a fine mist of sulphur passing unburned into the asbestos, where it is retained with SO: and weighed as such. (2) Error due to combined water of the ore. The results are apt to be .05 to 0.5% lower than those obtained by the barium sulphate procedures, the sulphur of the einder being ineluded with the available sulphur.

VOLUMETRIC METHODS FOR DETERMINING SOLUBLE SULPHATES

Combined sulphuric acid in soluble sulphates is best determined gravimetrically; occasionally, however, a volumetric procedure is of technical value. A number of volumetric methods are based on the insolubility of barium sulphate. Two general procedures deserve mention: addition of barium chloride in known amount in slight excess of that required by the sulphate, and titrating the excess either with a soluble carbonate or a chromate; or addition of barium chromate and titrating the alkali chromate formed by the reaction. The sulphate is also determined by precipitation with a weak organic base benzidine, added in form of the hydrochloride salt; the benzidine sulphate, filtered off, is titrated with caustic. The typical procedures given below will meet general requirements for the volumetric determination of sulphates.

Determination of Sulphur by Titration with Barium Chloride and Potassium Chromate—Wildenstein's Method Modified 1

Reaction.

Na₂SO₄+BaCl₂=BaSO₄+2NaCl and excess BaCl₂+K₄CrO₄=BaCrO₄+2KCl.

Procedure. The substance containing the sulphate in solution is diluted to 50 cc. in a small flask, acidified with hydrochloric acid, if necessary heated to

¹ See "Volumetric Analysis," Sutton, 10th Ed., p. 350.

boiling, and precipitated with a slight excess of N/4 barium chloride added from a burette (1 ee. BaCl₂ = 0.01 gram SO₂). The precipitate settles rapidly, so that a large excess of the reagent may readily be avoided. The mixture is eautiously neutralized with ammonia, free from earbonate (CO2 may be precipitated with CaCl₂ solution), the solution heated to boiling, and N/4 potassium chromate added from a burette in .5 ee. portions, each time removing the flask from the heat, allowing the precipitate to settle and examining the clear solution. A faint yellow color will appear as soon as the excess of barium has been precipitated and a few drops of the chromate in excess are present in the solution. The value of the chromate being equivalent to the barium chloride ec. per ec., the difference between the two titrations is due to the barium chloride required by the sulphate.

One ec. N/4 BaCl₂ = 0.01 gram SO₃.

Notes. Salts of the alkalies, alkaline earths (Sr and Ca) and zine and eadmium do not interfere. Nickel, cobalt and copper, however, give colored solutions which prevent the yellow chromate being seen. Should the latter be present, the end-point may be recognized by using ammoniacal lead acetate as an outside indicator (1 vol. NH₄OH+4 vols. PbC₂H₄O₂·3H₄O, 5% sol.), the indicator and titrated solution being mixed drop per drop on a white tile. A yellowish red color indicates the presence of chromate.

Precipitation of the Sulphate with Barium Chromate and Titration of Equivalent, Liberated Chromate with Iodine and Thiosulphate, Hinman's Method.¹

The sulphate, precipitated by barium chromate, liberates an equivalent amount of chromic acid, which is determined by treating with potassium iodide and titrating the liberated iodine with thiosulphate.

Reactions. $Na_2SO_4 + BaCrO_4 = BaSO_4 + Na_2CrO_4$ $Na_{1}CrO_{4}+3KI+8HCl=2NaCl+3KCl+CrCl_{3}+4H_{6}O+3I$. $2Na_2S_2O_2+I_2=2NaI+Na_2S_4O_6$.

Procedure.2 The solution of the sulphate, containing not over 2 per cent of SO₁, if acid, is almost neutralized with potassium hydroxide, then heated to boiling, and an excess of barium eliromate solution added. After boiling for one to five minutes, the hot solution is neutralized by adding calcium carbonate until no further effervescence occurs. The precipitate is filtered off and washed with hot water. The combined filtrates containing the chromate liberated by the sulphate through double decomposition, is acidified with 5 ee. strong

¹ Treadwell and Hall, "Analytical Chemistry," 2, 4th Ed., p. 716. Am. Jour. Sci. and Arts, 114, 478. ² See p. 716.

The barium chromate used should be free from soluble chromate, barium carbonate or soluble barium salt. The compound may be prepared by precipitating with potassium chromate added to a boiling solution of barium chloride. The precipitate is washed with boiling water containing a little acetic acid, and finally with pure water, and then dried. Four grams of the dry salt are dissolved in a liter of normal hydro-

chloric acid.
In presence of iron, sinc and nickel, the solution is neutralized with ammonium hydroxide and an excess added; after boiling, the solution is filtered. By using ealcium carbonate insoluble basic chromates of these elements would be formed, and low results for SO₂ would follow. This is avoided by the use of ammonia.

hydrochloric acid per each 100 ec. of filtrate and an excess of potassium iodide added. Iodine equivalent to the chromic acid is liberated. This is titrated with N/10 sodium thiosulphate.

One ec. of N/10 thiosulphate =0.003269 gram H₂SO₄. 1

Benzidine Hydrochloride Method - Raschig

Benzidine sulphate, C12H1(NH2)2. H2SO4, is scarcely soluble in water containing hydroehlorie acid. The weak base benzidine is neutral to phenolphthalein and the acid in its sulphate may be titrated with an alkali.2 The method gives reliable results in the analysis of all sulphates, provided no substances are present which attack benzidine, and provided the amount of other acids and salts present is not too great.3

 $N_{82}SO_4 + C_{12}H_8(NH_2)_2 \cdot 2HCl = 2N_8Cl + C_{12}H_8(NH_2)_2 \cdot H_2SO_4$ and Reaction. $C_{12}H_8(NH_2)_2 \cdot H_2SO_4 + 2NaOH = C_{12}H_8(NH_2)_2 \cdot 2H_2O + Na_2SO_4.$

Reagent. Benzidine hydrochloride is prepared by taking 6.7 grams of the free base, or the corresponding amount of the hydrochloride and mixing into a paste with 20 cc. of water in a mortar. Twenty cc. of hydrochloric acid (sp.gr. 1.12) are added and the mixture diluted to exactly 1000 ec. One ec. of this solution corresponds to 0.00357 grain H₂SO₄. The solution has a brown color. Brown flakes are likely to separate out on standing, but these do no harm.

Procedure. The sulphate solution is diluted with water so that there is at least a 50-cc. volume for each 0.1 grain sulphuric acid present. An equal volume of the reagent is vigorously stirred in, and the precipitate allowed to settle for ten minutes. The solution is filtered onto a double filter, placed on a porcelain, perforated plate in a funnel (a Büchner is O.K.), gentle section being applied. The last portions of the precipitate are transferred to the filter by means of small portions of the clear filtrate, and the compound then washed with 20 cc. of cold water added in small portions and sucked dry with each addition. The precipitate and filter are placed in an Erlenmeyer flask, 50 cc. of water added, and the mixture shaken until homogeneous. Phenolphthalein indicator is now added, the mixture heated to about 50° C. and titrated with N/10 sodium hydroxide. When the end-point is nearly reached, the liquid is boiled for five minutes, and the titration then completed.

One cc. N/10 = 0.004904 gram H_2SO_4 .

Determination of Free Sulphuric Acid

Other free acids being absent, sulphuric acid may be accurately determined by titration with standard alkali. The method for determining sulphuric acid in presence of commonly occurring acids, and in mixed acids are given in Volume II, in the chapter on Acids, Vol. II.

1 cc. N/1 NaOH = 0.04904 g. H₂SO₄.

 1 N/10 Na₂S₂O₃= $\frac{H_{2}SO_{4}}{200}$ =98.08+30=3.269.

² Method suggested by Raschig, Z. a. Chem., 617 and 818, 1903.

² Friedheim and Nydegger (Z. a. Chem., 9, 1907) have found that there should not be more than 10 mol. HCl, 15 mol. HNO₂, 20 mol. HC₂H₂O₂, 5 mol. alkali salt, or 2 mol. ferric iron present to 1 mol. H₂SO₄. See Treadwell and Hall, "Analytical Chemistry," pp. 714–716.

DETERMINATION OF PERSULPHATES

Ferrous Sulphate Method

Ferrous salts in cold solutions are oxidized to ferric form by persulphates. Advantage is taken of this action in the quantitative determination of persulphates. Reaction. $2\text{FeSO}_4 + \text{H}_2\text{S}_2\text{O}_8 = \text{Fe}_2(\text{SO}_4)_3 + \text{H}_2\text{SO}_4$.

Reaction. $2\text{FeSO}_4 + \text{H}_2\text{S}_2\text{O}_4 = \text{Fe}_2(\text{SO}_4)_2 + \text{H}_2\text{SO}_4$

Procedure. About 2.5 grams of the persulphate are dissolved in water and diluted to 100 cc. Ten ec. of this solution, equivalent to one-tenth of the sample, weighed out, are placed in a flask and a considerable excess of standard ferrous sulphate solution 2 added, say 100 ce. measured out from a burette. The solution is diluted with an equal volume o' hot, distilled water (70 to 80° C.), and the excess ferrous sulphate titrated with N/10 potassium permanganate. This titration is deducted from the permanganate equivalent of 100 cc. of the ferrous solution taken (if this amount was used). The difference is due to persulphate oxidation.

One ec. N/10 KMnO₄ = 0.009708 gram $H_2S_2O_8$; or = 0.0114 gram (NH₄)₂S₂O₈; or = 0.01352 grain $K_2S_2O_8$.

Oxalic Acid Method

Oxalic acid, in presence of silver sulphate, reduces persulphates in accordance with the reaction, $H_2C_2O_4 + 1I_2S_2O_8 = 2H_2SO_4 + 2CO_2$.

$H_1C_2O_4 + H_2S_2O_6 = 2H_2SO_4 + 2CO_2$

Procedure. About 0.5 gram of the persulphate is placed in an Erlenmeyer flask, 50 cc. of N/10 oxalic acid added, together with 0.2 gram silver sulphate in 20 cc. of 10% sulphuric acid solution. The mixture is heated on the water bath for about half an hour to expel carbon dioxide. When the evolution ceases the liquid is diluted to 100 cc. with warm water and titrated warm (about 40° C.) with N/10 potassium permanganate. The excess of oxalic acid is titrated, the difference is due to oxidation by the persulphate.

For calculation see factors in previous method.

Alkali Titration of the Boiled Solution

The aqueous solutions of potassium, sodium, and barium persulphates are decomposed by boiling as follows (M = metal Na, K, or Ba):

 $2M_2S_2O_8 + 2H_2O = 2M_2SO_4 + O_2 + 2H_2SO_4$

Procedure. About 0.2 g. of the persulphate salt is dissolved in 200 ec. of water and the solution boiled about 15 minutes, then cooled and titrated with N/10 NaOH, using methyl orange indicator.

1 cc. N/10 NaOH = 0.02008 g. BaS₂O₈4H₂O, or 0.01191 g. Na₂S₂O₈ or

Ammonium persulphate cannot be determined by the above method but may be determined by the ferrous sulphate method-which see above.

¹ Method suggested by Le Blanc and Eckardt, C. N., 81, 38. ** Method suggested by Le Bianc and Lekarut, U. N., 31, 33.

**About 30 grams of ferrous sulphate or ferrous ammonium sulphate crystals are dissolved in 900 cc. of water and the volume made to 1000 cc. with concentrated sulphuric acid. The reagent is standardized against N/10 potassium permanganate and the value per oc. in terms of the standard permanganate noted, the cc. permanganate solution required divided by the cc. of ferrous sulphate solution taken for titration, gives value of the reagent in terms of the permanganate.

The solutions are best verified upon a persulphate of known purity.

The solutions are best verified upon a persulphate of known purity.

DETERMINATION OF SULPHUR IN COMBINATION AS SULPHIDES, SULPHITES, BISULPHITES, METABISULPHITES, THIOSULPHATES, SULPHATES. AND HYDROSULPHITES

Available Hydrogen Sulphide in Materials High in Sulphide Sulphur. Iron Sulphide, Sodium Sulphide, etc.

Evolution Method. Since it is desired to obtain the H₂S that ordinarily would be obtained when the sulphide is treated with a strong acid, the mat of metallic aluminum or zinc and the addition of stannous chloride solution used

in the procedure given on page 503 is omitted here.

Procedure. 0.5 to 1 gram of the sulphide is placed in the dry evolution flask. All connections are now made as directed in the general procedure. Three absorption bulbs containing neutral solution of cadmium sulphate are connected to the condenser, and supported by wires attached to the thistle tube and the arm of the condenser. All connections being tight, 100 cc. of dilute sulphuric acid, 1:4 are added through the thistle tube and H₂S evolved. The procedure is now the same as described on page 503.

Titration. When the evolution of the I1₂S is complete, the bulbs containing the precipitate are captical into a beaker and carefully washed out. The precipitate is now filtered and washed five or six times until free of acid. Methyl orange is added to the filtrate and the free acid titrated with N/10 NaOH.

The precipitate may be titrated with iodine according to (b) under general method of procedure, using an excess of iodine, followed by starch and acid and then titrating back with sodium thiosulphate solution. A double cheek may thus be obtained. See page 504.

If it is desired to weigh the CdS precipitate, it is best to evolve the H₂S into a neutral solution of cadmium salt. The precipitate formed in a neutral or slightly acid solution is crystalline and easily filtered, whereas that formed in an ammoniacal solution is gelatinous.

When a neutral CdSO₄ or CdCl₂ solution is used, Il₂S should be evolved by sulphuric acid and not by hydrochloric acid, as the latter is volatile, and will pass through the condensing bulb recommended in the general procedure.

One cc. N/10 NaOH = .001704 gram H₂S " = .004396 gram FeS = .003904 gram Na₂S.

Hydrogen Sulphide and Soluble Sulphides

Direct titration of hydrogen sulphide water, and soluble sulphides in solution may be made in absence of other substances acted upon by iodine. The solution containing the sulphide is added to an excess of N/10 iodine solution, made acid with hydrochloric acid, and the excess iodine titrated with N/10 sodium thiosulphate. The following reaction takes place:

H.S+I,=2HI+S. The ec. Na₂S₂O₃ are subtracted from ec. I=I reacting

with H₂S. One cc. N/10 iodine = 0.00174 gram H₂S.

Nore. The soluble sulphide may be determined gravimetrically by oxidizing with bromine, the reagent being added until the solution is colored brownish red, the excess of the halogen removed by boiling and the sulphate precipitated as BaSO₄.

Determination of a Sulphide and a Sulphydrate in Presence of Each Other

When a mixture of sulphide and sulphydrate is treated with iodine the following reactions take place:

$$H_2S+I_2=2HI+S$$
 and $NuHS+2I_2=NuI+HI+S$.

It will be noticed that the acidity produced by the first reaction is twice that caused by the iodine action on the sulphydrate, and that the acidity in the latter titration remains unaffected. The reactions with the alkali salts is effected by addition of a standard iodine solution containing a known amount of hydrochloric acid. The reactions in this case are as follows:

 $Na_2S+2HCl=2NaCl+H_2S$ and $NaSH+IICl=NaCl+H_2S$. The iodine reacts with the H_2S as follows: $H_2S+I_2=2HI+S$.

From the second set of reactions it is evident that the quantity of hydriodic acid formed by the action of iodine on the sulphide is equivalent to the hydrochloric acid required to decompose the sulphide, so that the acidity remains unchanged. On the other hand with sulphydrate, NaSH, the hydriodic acid formed by the iodine oxidation, is twice the equivalent of hydrochloric acid required to decompose the acid salt. Hence it is evident that the acidity is a measure of the quantity of sulphydrate present in the mixture. From the second set of reactions the following procedure is devised.

Procedure. To a measured amount of N/10 iodine solution containing a measured amount of N/10 hydrochloric acid (the mixture diluted to 400 cc.) is added the solution containing the sulphide and sulphydrate from a burette, until the stirred solution becomes a pale yellow color. (The cc. of solution added is noted and its equivalent of the sample calculated.) Starch is now added and the excess of the iodine titrated with N/10 sodium thiosulphate. The cc. of thiosulphate in terms of N/10 solution subtracted from the cc. N/10 iodine solution taken give cc. iodine required by the sample added. The acidity of the solution is now determined by titration with N/10 sodium hydroxide. The cc. NaOH required by the HI give total NaOH minus cc. N/10 HCl present in the iodine solution.

Calculation. A. Ce. N/10 iodine required by the sample minus twice the cc. of N/10 NnOH required by HI formed by the reaction multiplied by 0.003903 give weight of Na₂S, (i.e., cc. I - 2 cc. NaOH)×0.003904 = gram Na₂S,

B. Cc. N/10 NaOH required by the HI multiplied by 0.00560 gives gram weight of NaHS. Or in brief: cc. NaOH ×0.005608 = gram NaHS.

The above weights multiplied by 100 and divided by the weight of sample used in the iodine titration give per cent of constituents in the sample.

The method is of value in the analysis of nlkali sulphides in absence of other compounds, which are decomposed by hydrochloric acid and which react with iodine.

Determination of Thiosulphate in Presence of Sulphide and Sulphydrate

The sulphide and sulphydrate sulphur is removed from the solution by adding an excess of freshly precipitated cadmium carbonate. The solution is filtered and diluted to a definite volume and the thiosulphate determined on an aliquot

portion by running it into an excess of N/10 iodine solution and titrating the excess of iodine with N/10 thiosulphate solution.

One ce. N/10 iodine = 0.024822 gram Na₂S₂O₃ · 5H₂O.

Determination of Sulphates and Sulphides in Presence of One Another

In one portion of the sample the sulphide is decomposed and the hydrogen sulphide expelled by boiling the solution (in presence of CO₂ replacing air in the flask) after acidifying with hydrochloric acid. The sulphate sulphur may now be precipitated as BaSO₄ by the usual methods.

In a second portion total sulphur is determined after oxidizing the sulphide with an excess of bromine and boiling out the excess of halogen. Total sulphur minus sulphate sulphir = sulphide sulphir.

The sulphide may be oxidized with fuming nitric acid by boiling the solution in a flask with reflux condenser. The nitric acid is expelled by evaporating the solution down to a moist residue. The sulphate is now precipitated by taking up the residue with water, adding HCl and then sufficient BaCl₂ to cause complete precipitation.

Determining the Sulphur in Thiocyanic (Sulphocyanic) Acid and its Salts

Oxidation of the sulphir may be accomplished as described for sulphides in the preceding method either by means of bromine or by furning nitric acid. The sulphur is then precipitated as BaSO₄ as usual.

Determination of Sulphurous Acid (SO₂ in Solution) Free, or Combined in Sulphites, Acid Sulphites, Metabisulphites and Thiosulphates

Gravimetric Method, Oxidation to Sulphate and Precipitation as BaSO₄. Sulphur dioxide, free or combined in a soluble salt, may be oxidized to SO₄ or sulphate by means of an oxidizing agent such as chlorine, or bromine, or hydrogen peroxide (alkaline solution). The sulphuric acid or sulphate may be then precipitated and determined as BaSO₄ in the usual way.

Procedure. The halogen (bromine preferred) is added (in a water-saturated solution) in large excess to the sample, the free halogen then boiled out, and sulphurie acid precipitated, from a solution made slightly acid with hydrochloric acid, by addition of a solution of barium chloride, according to the standard procedure.

If hydrogen peroxide is used, the solution should be made alkaline with ammonia and the peroxide added, the excess boiled out, and the solution then made acid as directed above.

 $BaSO_4 \times 0.3517 = H_2SO_2$, or $\times 0.5401 = Na_2SO_2$, or $\times 0.4458 = NaHSO_2$, or $\times 0.3387 = Na_2S_2O_2$, or $\times 0.2745 = SO_2$.

Note. If hydrogen peroxide is used, it should be tested for H₂SO₄ and allowance made accordingly.

Volumetric Methods

Titration with Iodine. Sulphurous Acid, Sulphites, Metabisulphites, Thiosulphates. Sulphurous acid, combined or free, may be titrated with iodine solution, the following reaction taking place:

$$SO_2 + 2I + 2H_2O = H_2SO_4 + 2HI$$
.

The titration is accomplished by adding the solution of sulphurous acid, sulphite, or thiosulphate to the iodine, not in the reverse order, since in the latter order low results are obtained, unless the solution is very dilute (less than 0.04% SO₄).1

Procedure. Five grams of the sample (sulphurous acid solution titrated directly) are dissolved in a little water and transferred to a 500-ce. graduated flask, then made to volume. Each cc. of this solution contains 0.01 gram of the sample: 100 ec. of N/10 iodine, or their equivalent if the solution is stronger or weaker, are placed in a beaker together with a few drops of hydrochloric acid. A portion of the sample in a 100-cc. burette is now run into the iodine, with constant stirring, until the color of the free iodine has almost faded out; a little starch solution is now added and the titration continued to the complete fading of the blue color.

Since each ce, of the sample contains 0.01 gram of the material, it follows that the 100-ec, iodine equivalent in terms of the material titrated expressed to the fourth decimal place as a whole number, if divided by the ee. of the sample required, will give the per cent of the substance sought, provided other titratable substances are absent.

Example. Suppose sodium sulphite is being titrated, then since 100 cc. of N/10 iodine are equivalent to 0.6304 gram Na₂SO₅, 6304 divided by the ce. Na₂SO₂ solution required gives per cent Na₂SO₃. If 63 cc. were required the salt would be 100% pure.

NOTE. When the iodine equivalent is over unity, it is necessary to take a larger sample per 500-cc, volume to avoid having a titration of over 100 cc. For example in the analysis of sodium thiosulphate, a 20-gram sample is diluted to 500 cc. and a portion of this added to 100 cc. of N/10 iodine solution. In this case it must be kept in mind that each cc. of the sample contains 0.04 gram of thiosulphate and the percentage calculated accordingly upon completing the titration.

If the titration of the iodine is made in a casserole, the end-point may readily be

recognized without the addition of starch.

Equivalents. 100 cc. N/10 iodine solution will oxidize:

Sodium sulphite (auhydrous), Na₂SO₃ = 0.6304 gram, or 0.3203 gram SO₂.

Sodium sulphite, Na₂SO₂.7H₂O = 1.2606 grams.

Acid sodium sulphite, NaHSO₂ = 0.5204 gram.

Sodium metabisulphite, Na₂S₂O₅ (anhydride of NaHSO₂) = 0.47535 gram.

Sodium thiosulphate, $Na_{1}S_{2}O_{3} \cdot 5H_{2}O = 2.4822$ grams.

Norz. Hydrogen sulphide er sedium sulphide are also titrated with iodine. Equivalents fer 100 ce. N/10 iodine =0.1704 gram H₂S, or 0.3904 gram Na₂S.

¹ A secondary reaction takes place, the hydriodic acid formed reducing the SO₂ to S, e.g., SO₂+4HI=2H₂O+2I₂+S. (J. Volhard, Ann. d. Chem. u. Pharm., 242, 94.) The solution, if not too dilute, will show a distinct separation of sulphur. (Treadwell and Hall, "Analytical Chemistry," 2, 3d Ed.) Raschig believes that a loss of SO₂ occurs, due to evaporation. (Z. Angew. Chem., 580, 1904.) See Sutton, "Volumetric Analysis," 10th Ed., pp. 128, 129. Gooch, "Methods in Chemical Analysis," 1st Ed. pp. 364-368. 1st Ed., pp. 364-368.

Determination of Sodium Thiosulphate. The iodine titration is described on page 512. See also the chapter on iodine.

Acidimetric and Alkalimetric Methods

Titration of Sulphites, Acid Sulphites (Metabisulphite) or Sulphurous Acid. The choice of indicator is important as the titration with one may be different from that obtained in presence of another. For example the titration of sulphurous acid by an alkali in presence of phenolphthalein is twice the titration necessary to obtain an alkaline reaction with methyl orange. The reason for this is evident by the fact that Na₂SO₄ is neutral to phenolphthalein and alkaline to methyl orange, whereas NaISO₄ is neutral to methyl orange but is acid to phenolphthalein. Advantage is taken of this in the analysis of salts containing a mixture of the normal and acid salts.

Reaction. With phenolphthalein H₂SO₃+2NnOH = Na₂SO₃+2H₂O.

With methyl orange H₂SO₃+NaOH = NaHSO₂+H₂O.

On the other hand if a salt is being titrated, methyl orange cannot be used for the titration of metabisulphita or acid sulphite, since these salts are neutral to this indicator, here phenolphthalein is required and an alkali titration made.

Reaction. NaHSO₁+NaOH = Na₂SO₃. (Na₂S₂O₃+H₂O) = 2NaHSO₃.)

Again if sodium sulphite, Na₂SO₃, is to be titrated, phenolphthalein would not do as an indicator, since Na₂SO₃ is neutral to this indicator. Here an acid titration is required with methyl orange indicator present:

$$2Na_2SO_3 + H_2SO_4 = 2NaHSO_3 + Na_2SO_4$$

A. Sulphurous Acid

For the alkali titration of this acid it is advisable to use methyl orange as indicator, since this is not affected by carbon dioxide, which is very frequently present.

Reaction. $H_2SO_1 + NaOH = NaHSO_1$.

One ec. N/I NaOH = 0.06407 gram SO₂, or = 0.08209 gram H₂SO₂.

B. Sodium Metabisulphite

Sodium acid sulphite does not exist in dry form, since the salt loses water and the anhydride Na₂S₂O₅ results. This is analogous to sulphurous acid, which exists only in water solution. It has been found that the acid sulphite solution evaporated to crystallization yields a product, which though dried with extreme care, forms the anhydride salt, Na₂S₂O₄. For correct report, therefore, the solid should be reported as metabisulphite, and the solution of the salt as acid sulphite.

Since metabisulphite in solution, or acid sulphite, is neutral to methyl orange, phenolphthalein indicator must be used and an alkali titration made. Carbon

dioxide-free water and reagents should be used.

Reaction. Na₂S₁O₃+H₂O = 2NaHSO₃ and NaHSO₂+NaOH = Na₂SO₃+H₂O. Procedure. 9.507 grams of the finely ground powder are dissolved in about 50 ec. of cold saturated salt solution, to which has been added from a burette 50 cc. of normal sodium hydroxide. The salt solution should be made neutral to

phenolphthalein. One cc. of 0.1% solution of the indicator is added and the excess acid sodium sulphite titrated with normal sodium hydroxide until a permanent faint pink color is obtained.

Since the normal equivalent of the salt has been taken for analysis the cc. alkali titration, including the 50 cc. originally present, will give the percentage

directly in terms of Na₂S₂O₆.

Note. The NaCl serves to give a sharp and more permanent end-point. It may be necessary to add more of the indicator towards the end of the titration.

C. Sodium Sulphite, Na₂SO₃

Sodium sulphite, Na₂SO₃, is neutral to phenolphthalein and alkaline to methyl orange. The titration of this salt is accomplished by addition of standard acid in presence of methyl orange.

Reaction. $2Na_2SO_4 + H_2SO_4 = Na_2SO_4 + 2NaHSO_3$.

Procedure. The normal factor weight (12.6 grams) of the salt is dissolved in about 250 cc. of distilled water, 1 cc. of methyl orange added, followed by normal sulphuric acid, added from a burette until a faint orange end-point is obtained. As in the case of the metabisulphite, each cc. of normal sulphuric acid equals 1% Na₂SO₃. Hence the percentage is obtained directly from the burette reading.

Notes. Organic coloring matter may be removed from the solution by filtering

through charcoal.

If sodium carbonate is present, it will also be titrated. A correction must be applied for this. In the presence of sodium carbonate the solution will be alkaline to phenolphthalein. An approximate estimation of this may be obtained by titration with normal acid in presence of this indicator, remembering that sodium bicarbonate, NaHCO₃, is neutral to phenolphthalein, hence twice this titration must be deducted from the total methyl orange titration, i.e., Na₂CO₃+H₂SO₄ (M.O.) = Na₂SO₄+H₂CO₂ and 2Na₂SO₃+H₂SO₄ (P.) = 2NaHSO₄+2NaHCO₃. (Alkaline hydroxides will also be titrated.) CO₂ may also be obtained by the standard procedure under carbon, tho SO₂ being oxidized by addition of chromic acid. Na₂CO₃×1.5 = equivalent Na₂SO₄.

Sodium carbonate may be detected in a sulphite or metabisulphite by adding cold, dilute acetic acid (25%) to the dry powdered salt. An effervescence is due to the presence of carbonate, since a sulphite or metabisulphite does not effervesce under similar conditions.

Determination of Sulphites, Metabisulphites, Thiosulphates, Sulphates, Chlorides and Carbonates in Presence of One Another

1. Sodium Sulphite, Na₂SO₃

This is determined by titration with standard acid in the presence of methylorange indicator according to the standard procedure previously described. It a carbonate is present, allowance must be made for this as stated

One cc. N/1 H₂SO₄=0.126 gram Na₂SO₂. Calculate to per cent. Na₂CO₂×1.5 = equivalent Na₂SO₂.

2. Sodium Metabisulphite, Na₂S₂O₅

This is determined by titration with a standard alkali in the presence of phenolphthalein indicator according to the procedure previously described.

One cc. N/1 NaOH = 0.09507 gram Na₂S₂O₃. Calculate to per cent.

3. Sodium Thiosulphate, Na₂S₂O₃

One gram of the mixed salts is placed in 100 cc. of N/10 iodine solution, and the excess of iodine titrated with N/10 sodium thiosulphate according to the standard procedure.

4. Sodium Sulphate

The sample is dissolved in a little water, hydrochloric acid added, and the solution boiled to expel all of the SO₂. Barium sulphate is now precipitated and determined according to the standard procedure.

$$BaSO_4 \times 0.6086 = Na_2SO_4$$

Note. The amount of the sample required is governed by the per cent Na₂SO₄ present.

5. Sodium Chloride

The sample is dissolved in water, nitric acid added and the solution boiled until all the SO₂ has either been volatilized or oxidized. The chlorine of the chloride is now precipitated with silver nitrate from a hot solution by the usual procedure.

$$AgCl \times 0.4078 = NaCl.$$

Note. The amount of the sample taken is governed by the per cent of NaCl present.

6. Sodium Carbonate, Na₂CO₃

Carbon dioxide is evolved from the mixture by means of chromic and sulphuric acids, the former being used to oxidize the SO₂ of the sample. The evolved gas is bubbled through a mixture of strong sulphuric and chromic acids to remove any SO₂ that may have escaped oxidation. Fig. 20. The CO₂ is absorbed either in caustic and weighed or is passed into a standard solution of barium hydroxide and titrated according to the standard procedures given under carbon.

Note. The amount of the cample taken is governed by the per cent of Na₂CO₃ present.

ESTIMATION OF SODIUM HYDROSULPHITE

Standard Indigo Solution. To about 150 cc. concentrated sulphuric acid in a casserole, are added 4.2 grams of indigo, slowly with stirring. The solution is kept at 80° C. for an hour in an oven, stirring once or twice during this time. After cooling the solution it is made up to four liters with distilled water. This reagent ; is now standardized against N/50 KMnO₄ solution. To do this 25 cc. of the indigo

> solution is diluted in a casserole with 300 cc. of water and titrated with N/50 KMnO4 reagent.

> 1 cc. N/50 KMnO4 is equivalent to 0.0015 g. indigotin.

> 1.505: 1 = gram indigotine : x, where x=gram Na₂S₂O₄ in 25 cc. Indigo solu-

> $\frac{2\times10,000}{\text{cc. titration}} = \% \text{ Na}_2\text{S}_2\text{O}_3 (2.5 \text{ grams of})$ solid) or grams per liter (25 cc. sample made up to 500 cc.).




Fig. 65a.

Procedure

Titration of Sodium Hydrosulphite Against Standard Indigo Solution. Fifty cc. of standard indigo solution are pipetted into a 300 cc. Erlenmeyer flask. The titrating apparatus as well as the 500 ec. volumetric flask are filled with CO2 gas (C2H2 may be used in place of CO₂). Two and a half grams of the solid are now taken, or 25 cc. of the solution (if the material is already dissolved as a 10% solution) and placed in the 500 cc. flask and made to mark with distilled water. The flask is stoppered and connections made with the burette, etc., as shown in Fig. 65a. The burette is filled with the sample and the flask containing the indigo solution is placed under the burette as shown in the figure. The air s displaced from the apparatus by CO2, the flow of this gas being continued

The hydrosulphite solution is now added to the indigo during the titration. solution until it changes from the blue to a yellow or brown color.

Factor for Indigo = % Na₂S₂O₄ in solids, or grams per liter in liquids.

Norms. The hydrosulphite solution should be made alkaline with NaOH, then made up rapidly to volume and titrated in an atmosphere of CO, to prevent oxidation. The size of the sample may be varied, but the titration should be over 10 cc. The tip of the burette should dip below the surface of the indigo until near the end-point, then withdrawn and the titration completed with the tip above the surface.

The above method was outlined by J. H. Brackett.

DETERMINATION OF FREE SULPHUR IN A MIXTURE

Free sulphur is an essential constituent in many types of mixtures and the method of estimation will vary with the nature of the other ingredients.




Fig. 66. Sanders' Extraction Apparatus.

Hydrated lime, chalk, gypsum, dry lime sulphur, calcium arsenate, nicoteno sulphate in infusorial earth carrier, sodium polysulphide, sodium chloride, epsom salts, and the usual fertilizer materials are the substances most commonly found in the mixtures now on the market. All commercial forms of sulphur are found in these mixtures and the value of the mixture usually depends largely on which form of sulphur was used. For examplc, an insecticide dust containing coarse crude or refined sulphur, instead of flowers or superfine. would be valueless even though the ehemical analysis showed that the mixture contained the specified percentage of total sulphur. Therefore, the inicroscope and a little ingenuity will indicate the proper combination of methods to follow.

From 1 to 10 grams of the material, depending upon the amount of sulphur present, is extracted in a Soxhlet extractor (see modified form, Fig. 66) with earbon bisulphide (freshly distilled) for twelve hours. The extract is evaporated to dryness, adding 10 cc. of bromine-carbon tetrachloride mixture together with 15 cc. of nitric acid. The residue is taken up with 10 cc. of hydrochlorie acid, diluted with 150 cc. of distilled water, heated to boiling and the sulphuric acid precipitated with 10% barium chloride solution, washed, dried, ignited and weighed according to the procedure for sulphur.

 $\frac{\text{BaSO}_4 \times 100 \times 0.1373}{\text{Weight of sample}} = \% \text{ free rhombic sulphur.}$

After extraction earefully dry the thimble and contents. Examine under a microscope a small portion of the dried material. Remaining sulphur if present will be in the amorphous form and have the characteristic "droplet" structure seen in flowers of sulphur. Presence of much sulphur at this stago indicates that flowers of sulphur was used in the mixture, and the proper procedure to follow will depend on the nature of the other constituents. If a soluble sulphate such as nicotene sulphate or epsom salts is indicated, then an aliquot of the residue in the extraction thimble can be leached with hot water and the sulphur determined by one of the usual methods after wet oxidization. If an insoluble material such as gypsum is indicated, then the free sulphur may be burned off in the air and the combined sulphur determined in the residue after solution by one of the standard methods; the total sulphur having first been determined in another aliquot after wet oxidization with bromine and nitric acid. What-

ever procedure is followed, the content of amorphous sulphur is calculated by difference and thus the percentage of flowers established by adding the amount thus found to the CS₂ soluble sulphur.

Sanders' extraction apparatus has several advantages that make this apparatus desirable for laboratory use, where a number of daily extractions are required. As may be seen from Fig. 66, by simply removing the glass stopper D the cylinder may be charged without disconnecting the apparatus, as is necessary with the Soxhlet type of apparatus. The extraction is carried on with the traps A and B closed, the siphon t-t' acting automatically as in case of the Soxhlet. With A closed and B open the apparatus may be used as a reflux condenser. The solvent liquid may be drawn off by opening A. With B closed and A open the apparatus may be used as a condenser and the ether, chloroform, carbon disulphide, etc., distilled from C. The globe-shaped Soxhlet condenser may be replaced by Allihn's or Liebig's condenser, if desired. The ball form, however, is more compact.

EVALUATION OF SPENT OXIDE FOR AVAILABLE SULPHUR

Spent oxide is the by-product of gas works, and refers to the spent Fe₂O₃ used in the serubber for the removal of hydrogen sulphide from the gas. The FeS, as in case of pyrites, is used in the manufacture of sulphuric acid, and is evalued by its available sulphur content.

Total Sulphur. The oxide is sampled, brought into solution and the sulphur determined exactly as is given under the standard method for determination of sulphur in pyrites ore.

Residual Sulphur. Two grams of the material are ignited to expel volatile sulphur, a porcelain erucible being used. The residue is treated with strong hydrochloric acid and after digestion on the steam or water bath is diluted with water and filtered. (If SiO₂ is present evaporation to dryness is necessary.) Sulphur is determined in the filtrate as usual.

Available Sulphur. The per cent of residual sulphur is subtracted from the per cent total sulphur, the difference being available sulphur.

Iron. This may be determined on an ignited sample according to a standard procedure for iron. See chapter on Iron.

¹ J. McC. Sanders, Proc. Chem. Soc., 26, 227-228, 1910. The Analyst, 35, 556, 1910.

ANALYSIS OF REFINED SULPHURS AND BRIMSTONE

The impurities in commercial sulphurs and brimstones are seldom more than a few tenths per cent. Arsenic, acidity, chlorine, and the amount of amorphous sulphur present (CS₂ insoluble) are required. Also the fineness and specific volume (degrees Chancel) are often required for sulphurs used in agriculture.

Moisture. The powdered sample, weighing 50 grains, is spread out on a watch-glass and dried for an hour at 100° C, then cooled in a desiccator and weighed.

Loss of weight in grams multiplied by 2=per cent moisture.

Arsenic. Ten grams of the material are treated with 30 ec. of carbon tetrachloride mixture (3 parts CCl₄+2 parts Br) and after standing for ten minutes 25 ec. strong nitric acid are added in small portions (a watch-glass covering the beaker during the intervals of addition). HNO₃ and Br are expelled by evaporation on the steam bath. Water is added and the evaporation repeated. Arsenic is now determined on the residue by the Gutzeit Method for arsenic.

Note. Arsenic-free reagents should be employed.

Chlorine. One hundred grams of the hrimstone are extracted with hot water, the filtered extracts oxidized with 10 to 15 cc. of nitric acid and a few crystals of ammonium persulphate by hoiling and treated with 5 cc. of 10% solution of silver nitrate. The solution, brought to boiling, is placed in a dark place and the silver chloride allowed to settle. This is now filtered off in a weighed Gooch crucible and chlorine calculated from the AgCl.

$$AgC1 \times 0.2474 = C1$$
 or $= 0.4078 = NaC1$.

Mineral and Organic Impurity. Ash 100 gms. of the sample by igniting a little at a time in a tared porcelain or silica ware dish. Carry on the combustion in plenty of air and without the aid of any external heat except toward the last. In igniting the sample use a small pin flame gas jet such as the petroleum chemist uses in making flash and fire tests. Do not use match or taper or alcohol to ignite the sulphur as a small amount of organic matter is certain to get into the sample from these sources and cause trouble in the combustion. The sulphur once ignited will burn evenly and clean unless organic matter is present. All refined sulphurs should burn completely without the aid of any external heat. With American Gulf Coast brimstone and with oil or asphalt contaminated sulphur the organic matter present in even minute amount will cause trouble in burning unless special precautions are taken. A film of melted asphalt or oily matter forms over the surface of the molten sulphur and shuts off the air so that the flame from the burning sulphur is When this film of dark oily matter is first noticed, touch it lightly with the pin flame and it will usually break or char, allowing the sulphur to burn evenly. Toward the last apply very gentle heat to the dish and thus char the organic matter but keep the temperature well below the red so that this organic material is not ignited. When all the sulphur is burnt off as indicated by no more odor of SO2, cool the dish and weigh; this weight giving the combined organic and mineral matter. Then ignite the residue at low red heat to burn off all organic material; again cool and weigh; this weight

giving the mineral impurity or ash. The difference between the two weights represents the organic impurity.


Acidity. Boil 100 gms. of the pulverized sample with about 500 cc. water. The addition of a little neutral alcohol at the start will aid in wetting the sulphur which sometimes floats and causes trouble. Cool and make up to a standard volume. Pipette or filter off an aliquot and titrate with N/10 alkali, using phenolphthalein. Calculate acidity as H₂SO₄ and express as per cent acidity.

Available Sulphur. Add together moisture, organic matter, ash, arsenic, acidity, chlorine and report available sulphur as the difference.

Amorphous Sulphur (CS2 insoluble). Weigh five to twenty grams of the finely pulverized sample into a tared Extraction Thimble and extract with earbon bisulphide. The rate of extraction is regulated so that one filling of the chamber takes about five minutes. The extraction should be complete in thirty minutes. It is important that the extraction be stopped as soon as tho loss in weight of the thimble and contents becomes constant as longcontinued extraction will carry some of the amorphous sulphur into solution. Note: A Soxhlet type oxtraction apparatus is best as other types where the thimble is not immersed in the liquid give erratic results at times on account of the tendency of the CS2 solution of sulphur to "crawl" to the top of the thimble and there deposit out a hard scale of rhombic sulphur. When the extraction is completed, the thimble and contents are freed from CS₂ by exposure to a rapid current of dry air and then dried for thirty minutes in a water oven through which air circulates. (Finely divided sulphur, CS2, and air is a mixture liable to spontaneous combustion, so get rid of the bulk of the CS₂ in the cold dry air current before exposing to the heat of the oven.) The weight of the contents of the thimble less ash and arsenic and organic matter is taken as the amorphous sulphur. Flowers of sulphur must contain in oxcess of 30% amorphous sulphur. (Flowers are often sophisticated by the addition of ground sulphur when the content of amorphous sulphur is lowered in proportion—this should not be reported as flowers but flowers with so much adulteration.) Refined lump sulphur, roll sulphur and rubber makers sulphur should contain no amorphous sulphur. Powdered sublimed sulphur usually contains some small percentage of amorphous sulphur. Note: Direct sunlight, heat and some chemical fumes cause the amorphous sulphur in flowers to revert to the soluble rhombic modification. Therefore be eareful in the preparation and treatment of samples of flowers of sulphur.

Fineness and Specific Volume of Degree Chancel. Examine the sample under the microscope. Use a recessed slide and wet the specimen with alcohol or preferably with concentrated sulphuric acid. Flowers of sulphur appear as loose agglomerations of opaque yellow spherical droplets. Ground refined sulphur and ground brimstone appear as clear angular fragments almost colorless. High quality flowers consists entirely of minute droplets all of uniform size and barely touching each other. In low quality flowers the droplets are of large and irregular size and are more or less fused together. The smaller and the more uniform the size of the sulphur particles—whether the droplets of the flowers or the grains of a pulverized sulphur—the greater will be the specific volume and the Degree Chancel. This is determined by the

Chancel Sulphurimeter, a tall glass tube, glass-stoppered, graduated into 100 degrees of $\frac{1}{4}$ ec. each. Five grams of the sulphur sample are accurately weighed out and dusted into the tube which is half filled with ether or alcohol. The sulphur and alcohol is strongly shaken and the tube and contents allowed to stand in a vertical position. The reading of the sulphur level is taken as soon as the subsidence ceases or at the end of an hour and this is reported as the degree Chancel. (If a Chancel Sulphurimeter is not obtainable, a tall glass-stoppered graduate of 25 ec. capacity will serve, remembering that each quarter ec. represents a degree in the Chancel scale. Of course this reading will not be as accurate as on the Sulphurimeter where the scale is larger on account of the smaller diameter of the Chancel tube.)



The cylindrical glass tube should have the following dimensions: The cylinder should be 23 cm. long and 15 mm. in diameter, with a scale starting from below, graduated upwards into 100 degrees, each degree being \{ \text{cc.}; the 100 degrees (25 cc.) occupy a length of 100 mm. The cylinder is closed at the lower end, and glass stoppered, as shown in Fig. 66a. The sulphur is first passed through a sieve 1 mm. mesh, in order to break down the lumps formed with storage. As stated, a 5 gram sample is placed in the tube and this half filled with



Fig. 66a. Fig. 66b. Flowers of Sulphur. Sulphurimeter.

Fra. 66c. Rhombie Sulphur.

anhydrous ether, having a temperature of 17.5° C. The sieved sample is shaken and additional ether added until the level stands 1 cc. over the 100° mark and the whole again shaken in an upright position, the sulphur allowed to settle and the degrees Chancel read off.

The procedure for analysis of refined sulphurs was contributed by Chas. A. Newhall.

¹ Lunge, Tech. Methods of Chem. Analy., Vol. 1, p. 265 (1908). Lunge, Sulphuric Acid and Alkali, Vol. 1, Part 1, page 47 (1913).

QUANTITATIVE ESTIMATION OF SMALL QUANTITIES OF SULPHIDE SULPHUR; METHOD OF W. A. DRUSHEL AND C. M. ELSTON¹

The method is a colorimetric method and consists essentially of the comparison of the depth of color of lead sulphide stains obtained from the sulphide sulphur of a given weight of a sample to be analyzed with a standard series of stains prepared from sulphide solutions of known sulphur content. A set of stains varying in depth of color from a faint yellowish brown to black representing from 0.0002% to 0.004% of sulphide sulphur may be prepared and used indefinitely for comparison. With a set of standard stains at hand the method has the advantage that within the range given the sulphide sulphur of a sample may be determined with a fair degree of accuracy in less than ten minutes.

Preparation of Standard Set of Sulphide Stains. The apparatus used for preparing standard stains and for making analyses is very simple. The inner tube of a Liebig condenser with its larger end about 18 num. in internal diameter is cut off 15 cm. in length. The smaller end is drawn down somewhat, rounded and fitted to a sound cork stopper which in turn is fitted to a 100 cc. round-bottom flask. The condenser tube then serves as a sort of reflux condenser. To the upper and larger end of this tube a filter paper moistened with a dilute solution of lead accetate is smoothly fitted and tied, so that the steam passing up through the tube and carrying hydrogen sulphide is required to pass out through the lead accetate paper. A similar tube with the internal diameter of its larger end about 36 mm. is also prepared and used for sulphide sulphur samples containing 0.001% or more of sulphur.

A solution of sodium sulphide is made up with pure distilled water and carefully standardized. The solution is then diluted to contain exactly 0.01% of sulphide sulphur. This solution is used for making up standard solutions containing 0.0002, 0.0004, 0.0006, 0.0008, 0.001, 0.002, 0.003 and 0.004% of sulphide sulphur respectively, taking care to use distilled water free from traces of nitrites in making the dilutions. It is found that the more dilute sulphide solutions when made up with ordinary distilled water lose their sulphide content either wholly or in part on standing for several hours in stoppered bottles. This difficulty is obviated by using nitrite free distilled water in making up the solutions.

Carefully measured portions of 1 cc. to 5 cc. of the standard solutions are pipetted into the 100 cc. flask and 25 cc. of hydrochloric acid of about 0.5% strength is added. The flask is immediately attached to the condenser tube fitted with moistened lead acetate paper as previously described. The mixture is then gently boiled for a few minutes at such a rate that the steam issued not too rapidly from the upper end of the condenser tube. In this way the sulphide sulphur is quantitatively liberated as hydrogen sulphide and evenly deposited as lead sulphide on the moistened lead acetate paper. The undecomposed lead acetate is then washed out, the paper dried and labeled with the amount of sulphide sulphur present as one of the set of standard stains. In the same way complete sets in duplicate are prepared ranging in sulphide sulphur from 0.0002% to 0.004%.

¹ Am. Jour. Sci., Fourth Series, Vol. XLII, No. 248, August, 1916.

In making these estimations the larger condenser tube is used where a preliminary trial indicates that the amount of sulphide sulphur is equal to or greater than 0.001%. In all other cases the smaller tube is used. The maximum error, depending upon the amount of sulphur present, with the larger tube was 0.001% and with the smaller tube 0.0003%. These errors may be reduced by repeating the determination and taking the mean of several values found. In this way in the practical applications of the method the errors may be kept within reasonable limits.

Practical Applications. (1) In gas analysis. Twenty-five liters of nir are slowly drawn through a Geissler bulb of the most modern type containing dilute potassium hydroxide solution. This solution is then washed into a measuring flash and made up to the mark with nitrite free distilled water and aliquot portions of this solution are used for determining the sulphide sulphur as previously described.

- (2) In coke analysis. The simplest method of estimating sulphur in coke given by Fresenius is to boil 5 grams to 10 grams of powdered coke in dilute hydrochloric acid, and to absorb the hydrogen sulphide evolved in dilute potassium hydroxide solution. The sulphur is then oxidized to the sulphate condition by chlorine water or bronnine water and weighed as barium sulphate. This method is used as a control to check up the results obtained by the colorimetric method. In this method the hydrogen sulphide is liberated and absorbed as suggested by Fresenius and aliquot portions of the sulphide containing potassium hydroxide solution are transferred to the distillation flask and the previously described procedure is followed.
- (3) In paper analysis. In order that tissue paper may be used for wrapping polished metal without producing a tarnish the paper must be relatively free from sulphide sulphur. A weighed amount of paper, I gram to 2 grams, is cut into small pieces and transferred to the distilling flask and digested with gently boiling 0.5% hydrochloric acid, collecting the hydrogen sulphide as lead sulphide on lead acetate paper as previously described.

THORIUM

Th, at.wt. 232.15; sp.gr. 11.0-12.2; m.p. 1450°; oxides, ThO₂ (ThO₃ and Th₂O₇ known only in hydrate form)

DETECTION

In the regular analytical procedure thorium is found in the precipitate of the tri- and tetra-valent hydroxides produced by ammonium hydroxide, provided a sufficiently thorough decomposition of the sample has been obtained (see section on preparation and solution of sample). Along with rare earth elements, and a little zirconium, thorium may be obtained as oxalate by dissolving the hydroxide precipitate 2 in hydrochloric acid and adding a slight excess of oxalic acid to the hot, weakly acid (not over 0.5 normal) solution. The precipitate should be allowed to stand six or eight hours before filtration. After having been washed with water containing 2 cc. of 6 normal hydrochloric acid per 100 cc., the precipitate is rinsed into a beaker with pure water, using about 50 cc. To this mixture 5 g. of solid ammonium oxalate are added, and the mixture is heated for half an hour nearly to boiling, and well stirred. Two volumes of water are added, the mixture is allowed to stand half an hour and then filtered. To the filtrate 20 cc. of 6 normal hydrochloric acid are added. A white precipitate indicates the presence of thorium.³ This precipitate can be put into solution by strong heating with cone. sulphuric acid, and taking up with ice-cold water. One of the following characteristic tests may be used as confirmation of thorium.

A sensitive test for thorium 4 consists in the precipitation of thorium iodate in nitric acid solution. Two reagent solutions are necessary: (I) 15 g. of potassium iodate, 50 cc. of conc. nitric acid, and 100 cc. of water. (II) 4 g. of potassium iodate, 50 cc. of conc. nitric acid, and 450 cc. of water. The solution to be tested for thorium, which must contain no hydrochloric acid, is boiled with a little sulphurous acid to reduce any cerium present. To this solution is added twice its volume of reagent (I), which causes precipitation

*11 is shorter to add oxalic acid directly to the filtrate from the hydrogen sulphide group, after boiling out the excess of hydrogen sulphide. This, however, causes complications in the analysis of subsequent groups, and may also contaminate the oxalate precipitate with calcium; so it is better to first precipitate the hydroxides with (carbonate-free) animonium hydroxide as described.

*Thorium oxalate is soluble in ammonium oxalate. Zirconium oxalate, and traces of the oxalates of the yttrium earths also dissolve, but the yttrium earth oxalates are reprecipitated on dilution. The addition of an excess of mineral acid to the ammonium oxalate solution of thorium and zirconium precipitates thorium oxalate, but not zirconium oxalate.

"Meyer and Hauser, "Die Analyze der Seltenen Erden und Erdsaüren," p. 171. Ferdinand Enke, Stuttgart (1912).

Chapter by Paul H. M.-P. Brinton.

of thorium iodate, and more or less rare earth iodates according to their concentration in the solution. By now adding reagent (II) in volume equal to four times the original volume, and boiling, any rare earth iodate is dissolved, while thorium iodate (also any zirconium iodate) remains undissolved. If the absence of zirconium is not known with certainty, the iodate precipitate may be boiled with 50 cc. of 10% oxalic acid solution 1 until iodine vapors are no longer given off. Any precipitate remaining is thorium oxalate.

Sodium pyrophosphate produces in solutions of an acid normality of 0.2-0.3 a white precipitate of thorium pyrophosphate. To make certain that this precipitate is entirely free from rare earths it should be redissolved, any tetravalent cerium reduced with sulphurous acid, and then the thorium reprecipitated as pyrophosphate as described later under Gravimetric Determination. Zirconium and titanium would also be precipitated under these conditions, but they would be separated from thorium on the basis of their non-precipitation by excess of oxalic acid.

Spectrum analysis, and the determination of radioactivity 2 are also useful

in the detection of thorium.

ESTIMATION

The estimation of thorium is required chiefly in connection with the incandescent gas mantle industry. The main source of thorium is monazite sand, of which the greater part comes from Brazil and India. The South Carolina monazite is of poor quality and of very little commercial importance. Monazite is essentially an orthophosphate of the cerium earths, and earries from about 4% to nearly 10% of ThO₂. The highest grade material comes from Travancore, India. Thorite and thorianite, the silicate and the uranate respectively of thorium, are now of limited importance.

Preparation and Solution of the Sample

Thorite. The very finely pulverized sample is digested with cone. hydrochloric acid at a temperature just below boiling. This usually effects complete decomposition, but for safety any insoluble residue should be filtered, after dilution, ignited, and then fused with potassium pyrosulphate. This fusion is taken up with 6 normal hydrochloric acid and added to the main solution. Silica and the hydrogen sulphide group are removed in the conventional way, leaving thorium, rare earths, etc., in the acid solution.

Monazite, Thorianite, Gas Mantle Residues, etc. While fusion with potassium pyrosulphate effects the decomposition, yet it is more convenient to attack larger samples with cone. sulphuric acid. In the case of monazite sand, large samples are necessary to insure uniform and representative samples. Thorianite and Carolina monazite should be finely ground, but Brazilian and Indian monazite are fully decomposable without grinding, and filtration from the insoluble residue is easier if the sample is taken as it comes. A batch of sand should be very carefully mixed before samping, to avoid the tendency toward segregation arising from the different sizes and densities of the constituent grains.

¹ Brinton and James, J. Am. Chem. Soc., 41, 1084 (1919). ² Helmick, J. Am. Chem. Soc., 43, 2003 (1921), gives details for the quantitative, as well as the qualitative, determination of thorium in minerals.

The following method for the decomposition of monazite is recommended by Dr. H. S. Miner, of the Welsbach Co.: 50 g. of the sand are weighed out and placed in a porcelain casserole of about 50 ce. capacity. 75 cc. of cone. sulphurie acid are added, and the mixture is heated for about four hours with frequent stirring, a gentle evolution of fumes being maintained during the course of the operation. When the mass has become pasty, it is allowed to eool, and the sulphates are extracted by the addition of about 400 ee. of ice-cold water, or enough to cool the solution sufficiently so that the sulphates become soluble. This solution is decanted into a liter-graduated flask, and the remaining sulphates are extracted with small portions of cold water and decanted into the flask. A point is reached toward the end of the extraction when, due to the decreasing acidity, the small wash portions show a slight separation of rare carth phosphate. A few more extractions are made beyond this point, but these portions are not added to the graduated flask. They arc temporarily preserved in a separate beaker. To the remaining sand, which has been dried, 10 ec. of cone, sulphuric acid are added, and the digestion is earried out as before, except that a somewhat higher temperature is used, enough to maintain copious evolution of white fumes, and the duration of the digestion need not exceed one and a half hours. After cooling, extraction is started with the last portions of the previous extraction liquor, i.e., those decanting which showed slight precipitates of rare earth phosphates, and which were preserved in the separate beaker. The sand is now thoroughly washed with cold water, and the washings are all decanted into the liter flask. This flask now contains all the thorium and rare earths as soluble sulphates. A little suspended siliea is usually visible at this point, but this will not be mistaken for undissolved sulphates.

After cooling, the sulphate solution is made up exactly to the liter mark, thoroughly mixed, and filtered through a dry filter, discarding the first 25 or 30 ee., and receiving the remainder in a dry flask or bottle. The whole need not be filtered, and, of course, no washing is to be done. Each 100 cc. of this solution represents 5 g. of the sample.

¹ U. S. Bureau of Mines, Bulletin 212, p. 53 (1923).

SEPARATIONS

Thorium is separated from practically all elements excepting the rare earth elements and scandium by precipitation as oxalate in slightly acid solution. Zirconium may be in part precipitated along with thorium and the rare earths, especially in the absence of a sufficient excess of oxalic acid; and if considerable quantities of calcium, and to less extent strontium and barium, are present, there may be contamination unless the mineral acid concentration be kept dangerously high. In the presence of much calcium, it is better to first separate thorium from it by precipitation with freshly distilled ammonium hydroxide, and then to precipitate the thorium as oxalate. The details of the oxalate separation have been given under Detection.

The main problem, then, is the separation of thorium from the rare earth The iodate method has already been given in detail. Two other much used methods will now be described.

The Pyrophosphate Method. An aliquot portion of the sulphate solution, prepared as already described, and usually representing 2.5 g. of monazite sand, is diluted to about 450 cc., and 5 cc. of conc. hydrochloric acid are added. The solution is heated nearly to boiling and the iron and cerium are reduced by adding sulphurous acid solution until the yellow color is discharged. 15 cc. of sodium pyrophosphate solution (50 g. Na₄P₂O₇.10H₂O in 1 liter of water) are slowly added, with constant stirring, and the mixture is then heated to gentle boiling for 5 minutes. After standing 5-10 minutes-not more-the precipitate of thorium phosphate is filtered and washed twice with water containing 1 drop of hydrochloric acid per 100 cc. A slight cloud in the first filtrate, due to atmospheric oxidation of iron (and possibly of cerium), with consequent precipitation of pyrophosphate may be neglected.2 The filter paper and precipitate are freed from excess liquid by wrapping for a moment in cheap filter paper or blotting paper, and then dropped into a dry 250-cc. Kjeldahl flask. 15 cc. of conc. sulphuric acid and a few crystals of ammonium perchlorate are added, a small funnel is placed in the neck of the flask, and the contents are heated until the filter is disintegrated. When a clear brown solution is obtained more perchlorate 3 is added, and the heating is continued until the mixture is pure white (or very slightly yellow if much cerium was carried down in the first precipitate). The flask is placed in

Carney and Campbell, J. Am. Chem. Soc., 36, 1134 (1914).

² V. T. Jackson, U. S. Bureau of Mines, Bulletin 212, p. 65 (1923).

The oxidation of the filter paper requires 10 or 15 minutes, and about 1.5 g. of perchlorate. Heating should not be continued far beyond the point at which the organic matter is fully destroyed, as the perchloric acid may break up and cause considerable foaming. Cartledge (J. Am. Chem. Soc., 41, 49 (1919)) shows that fuming nitric acid may be satisfactorily substituted for ammonium perchlorate. In this case the precipitate and paper are shaken with 15 cc. of conc. sulphuric acid in the Kjeldahl flask for about two minutes, cooling, if necessary, until the flask is just a little too hot to be held comfortably in the hand. To the charred mixture 2-4 ec. of fuming nitric acid (sp.gr. 1.53) are added, and after a minute or two the solution is gradually raised to the boiling point. Occasionally as fumes of sulphur trioxide appear a second charring occurs, in which case 0.5 cc. more nitric acid, poured cantiously down the neck of the flask, will complete the oxidation. (If the nuxture has once been white or slightly yellow, no harm is done if during cooling oxides of nitrogen redissolve in the acid, thereby restoring a yellow color.)

ice-water and then slowly, with shaking, about 100 cc. of ice-cold water are added. Complete solution may at times require several hours. Occasionally a slight cloud of suspended silica persists. This may be neglected as it will

be removed in the next step.

The sulphate solution is riused into a solution of 30 g. of sodium hydroxide in 125 cc. of water, contained in the original beaker in which the pyrophosphate was precipitated, boiled for several minutes, and washed several times with hot water. The paper and precipitate are then placed in the beaker just used, 10 cc. of cone. hydrochloric acid are added, and after a few minutes of stirring, 150 cc. of water are added, and the solution is boiled. The paper shreds are filtered off and washed, and the filtrate is diluted to about 400 cc. 3 cc. of saturated sulphurous acid solution are added, the solution is heated to boiling, and the thorium is again precipitated with sodium pyrophosphate. The precipitate is washed and changed to sulphate and hydroxide in the manner just described. This second sulphate should always be perfectly white, and should dissolve entirely clear. The final hydroxide is free from rare carths, and aside from zirconium and titunium, which are precipitated as pyrophosphate, it should contain only a trace of iron as impurity. These three foreign elements will be separated from the thorium by the final precipitation of the latter as oxalate. The last hydroxide precipitate is dissolved in as little conc. hydrochloric acid as possible (never more than 10 cc.) and filtered free from paper. This chloride solution is now ready for the gravimetric determination of thorium by precipitation as oxalate.

The Thiosulphate Method.² 200 cc. of the sulphate solution prepared as described under Preparation of Sample, and representing 10 g. of monazite sand, are diluted to 1 liter, and poured into 150 cc. of a cold saturated solution of oxalic acid. The sulphate solution should be fed in very slowly, preferably from a separatory funnel, and vigorous stirring should be maintained to convert the gummy precipitate to the crystalline form. Only in this way is it possible to get the oxalate precipitate free from considerable amounts of phosphate. After standing not less than fifteen hours the precipitate is filtered, washed

free from acid, and dried.

The filtrate and first washings are neutralized with ammonia, and hydrochloric acid is then added in an excess of from 10 to 15 cc. This precipitates the remaining rare earths (and any thorium still in solution) as oxalo-phosphates. This precipitate is also allowed to stand fifteen hours, and then it is filtered and washed with weak oxalic acid solution. This precipitate, after drying, is ignited in a porcelain dish, moistened with a little water, and dissolved by warming with cone. hydrochloric acid. The solution so obtained is filtered, largely diluted, and precipitated by the addition of a large excess of oxalic acid, warming to convert the precipitate to a crystalline form. After standing two or three hours, this oxalate precipitate is filtered, washed, and dried.

The oxalate precipitates are ignited together. If "total rare-earth oxides" are wanted, they may be weighed at this point. The oxides are transferred to a 600-ce. beaker, moistened with a little water, and dissolved by warming

¹ Thorium pyrophosphate adheres rather tenneiously to the glass, and this procedure climinates the necessity for the tedious cleansing of the beaker after the first precipitation.

² The details here given are essentially those in use in the laboratories of the Welsbach Co. See H. S. Miner, loo, cit.

with 100 cc. of 6 normal hydrochloric acid. The solution is transferred to a 1500-cc. beaker, diluted to about 700 cc., and ammonia is added until the precipitate formed just ceases to redissolve, leaving the solution neutral or very slightly acid. Conc. hydrochloric acid is now added, a drop at a time, until the precipitate just dissolves, and then 6 to 8 drops more. 100 cc. of a boiling 30 per cent sodium thiosulphate solution are added to the boiling solution, and boiling is continued for 45 minutes. The precipitate is filtered on a $2\frac{1}{4}$ -inch Büchner funnel, and washed with hot water. It is well to fold the filter paper so as to cover the whole of the inside of the funnel.

To the filtrate 10 cc. more of the thiosulphate solution are added, and it is boiled for half an hour longer. The small precipitate thus obtained is filtered, set temporarily aside and designated as "Residue No. 1." The filtrate is

discarded.

The paper containing the first large precipitate is put into the original 1500-cc. benker and boiled over a low flame with 75 cc. of 6 normal hydrochloric acid. When the thorium precipitate has dissolved and the paper is pretty well disintegrated, usually about 5 minutes, without filtering off the filter paper and sulphur, the mixture is diluted to 700 ee., and neutralized with ammonia just as before, finally having an excess of 6 to 8 drops of conc. hydrochloric acid. It is then heated to boiling and 60 cc. of boiling 30 per cent sodium thiosulphate solution are added. After boiling 30 minutes the precipitate is filtered on a Büchner funnel as before and washed. This filtrate is reserved.

The paper and precipitate are dropped into the original beaker and all the operations described in the paragraph immediately preceding are repeated,

the final filtrate, however, being this time discarded.

The paper containing the thorium precipitate is boiled with 40 cc. of 6 normal hydrochloric acid. When the paper is well disintegrated, it is filtered off, well washed, and this residue is designated as "Residue No. 2." The

solution is temporarily set aside.

Residues Nos. 1 and 2 are combined, ignited in a porcelain crueible, and fused with sodium pyrosulphate. The fusion is extracted with dil. hydrochloric acid and this solution is added to the reserved filtrate from the second thiosulphate precipitation. Ammonia is now added in excess, the precipitate is filtered, and dissolved in hydrochloric acid. This solution is diluted to 300 cc. nearly neutralized with ammonia, leaving only a faint acidity, heated to boiling, and precipitated by the addition of 20 cc. of boiling 30 per cent sodium thiosulphate solution. After boiling 20 minutes, the precipitate is filtered on a small Büchner funnel, washed, and dissolved in 50 cc. of 6 normal hydrochloric acid. Without filtering, the solution is diluted to 300 cc., almost neutralized with ammonia, and the thiosulphate precipitation is repeated. The last precipitate is dissolved by boiling in a mixture of 5 cc. of conc. hydrochloric acid and 20 cc. of water, the sulphur is filtered off, and the chloride solution is combined with the solution obtained at the end of the preceding paragraph.

This solution now contains all the thorium from the original sample and it is ready for the Gravimetric Determination of thorium by precipitation

as oxalate.

GRAVIMETRIC DETERMINATION OF THORIUM

Thorium is nearly always precipitated as oxalate and ignited to ThO₂, in which form it is weighed. The solubility of thorium oxalate in very dilute mineral acids is slight, especially in the presence of excess oxalic acid. It is well, however, not to have over 2 ec. of conc. mineral acid per 100 ec. of solution. More strongly acid solutions may be partially neutralized with ammonium hydroxide. Thorium oxalate does not filter readily if precipitated rapidly, or from a cold solution. The solution should be boiling hot and dilute (200–500 ec.); and should be precipitated by adding very slowly a boiling-hot solution of oxalic acid, which has been saturated in the cold; or by stirring in the oxalic acid added in solid form. Both methods insure a slow rate of precipitation, but the first method seems to be the better. The precipitate is allowed to stand not less than 10 or 12 hours before filtration, and it is washed with water containing a few drops of hydrochloric acid.

The thorium exulate is ignited with the filter paper in a porcelain or platinum crucible over the blast to constant weight. If a platinum crucible is used, the full heat of a Mecker burner is sufficient. The ThO₂ finally weighed should be pure white in color. A yellow color shows cerium earths or iron and is an indication of faulty work.

Sn, at.wt. 118.7; sp.gr. 6.56; m.p. 232°; b.p. 2275°; oxides SnO: and SnO.

DETECTION

Tin is separated, together with arsenic, antimony, gold and platimin, from the hydrogen sulphide precipitate of the metals of the second group, by the action of yellow ammonium sulphide. (Normal ammonium sulphide does not readily dissolve the sulphides of tin.) If the ammonium sulphide solution is acidulated with hydrochloric acid and the acid solution reduced with iron, antimony, arsenic, platinum and gold are precipitated in the metallic form. The presence of tin, which is present as stannous chloride, is indicated by the reducing action of the solution on mercuric chloride, a white precipitate of HgCl or a gray precipitate of Hg being thrown down.

Reduce the hydrochloric acid solution of the sample by means of a small piece of iron wire. Treat with an excess of cold potassium hydroxide. Filter if the solution is not clear. Add an ammoniacal solution of silver nitrate. (One part AgNO₁: 16 parts NH₄OH.) A brown precipitate of metallic silver indicates the presence of tim. Antimony, arsenic, platinum and gold are precipitated by the iron, while all of the heavy metals remaining, except lead, tin, aluminum, chro-

mium, and zinc, are removed by the treatment with potassium hydrate.

Welch and Weber 1 recommend the following method for detection of tin: Add 10 cc. concentrated hydrochloric acid to the superficially dried precipitated sulphides from the animonium sulphide separation. Filter off arsenic which does not decompose. Dilute filtrate to 70 cc. volume. Saturate with H₂S. Heat to expel excess H₂S. Add 5 cc. of hydrogen peroxide and heat until precipitate is redissolved. Add 5 to 10 grams of oxalic acid and pass H₂S into the hot solution. Antimony separates as a red sulphide. Filter. Filtrate contains the tin. Reduce with test lead and add mercuric chloride. White or grayish precipitate indicates presence of tin.

ESTIMATION

The estimation of tin is required in connection with the analysis of tin ores, dross, ashes, dust, tin plate, alloys such as solder, canned foods, and general analysis.

Opening Up Tin Ores

As the oxides of tin are not readily soluble in acids the tin can be most easily removed by assay. Ores, slags, dross, and ashes are first subjected to the assay process. The button obtained is then analyzed either volumetrically or gravi-

Chapter contributed by Wilfred W. Scott and B. S. Clark.

¹ Jour. Am. Chem. Soc., 38, 5, 1011, 1916.

metrically by one of the methods given below. Having the weight of the button and the per cent of tin in it, the per cent of tin in the sample as received can be calculated.

There are two general processes of assaying, namely, the Cyanide Process and the Carbonate of Soda Process.

The Cyanide Process

The theory of this method is that the oxides are reduced to the metal by the action of potassium cyanide, the reaction being represented as follows:

$$SnO_2+2KCN = Sn+2KCNO$$
.

Potassium cyanide reduces other metals also so that the button obtained is not pure.

Procedure. Take 100 grams of the sample which has been dried and finely powdered. (For complete analysis the moisture should be determined in the usual way.) Mix thoroughly with four times its weight of powdered potassium cyanide. Place about 1 in. of potassium eyanide in the bottom of a number H (height 5\frac{1}{4} ins., diameter 3\frac{1}{4} ins.) Battersca clay crucible. Place the mixture of sample and cyanide on top of the cyanide in the crucible and cover with enough more cyanide to fill the crucible to within 1 in. of the top.

Flace the crucible in the assay furnace and heat slowly until it has been thoroughly warmed and the cyanido begins to melt. Then increase the heat gradually to a pure white, taking care that the cyanide does not boil over. Grasp the crucible with the tongs and tap it gently on the heatth to assist in settling the metal. Continue the heating until all of the organic matter has disappeared, adding more cyanide from time to time if necessary. Near the end of the process the molten mass becomes clear and transparent and finally pasty and translucent. When this last condition appears, remove the crucible from the furnace and allow it to cool slowly at the temperature of the room.

When cool, break the crucible and slag away from the button. The appearance of the button and the slag immediately surrounding it indicates whether or not the process has been properly manipulated. The button itself should be firm and compact and the slag around it should be white or greenish in color. If the button is spongy or if the slag has a dirty black color, the assay should be discarded and a new determination made, using a fresh sample.

Weight of Button = per cent Metal in Sample.

Weight of Metal
$$\times$$
per cent Sn = per cent Sn in the Sample.

Note. This process should be carried on under a hood in a segregated room, and every precaution should be taken to avoid breathing the poisonous fumes of potassium cyanide.

Lunge advises that the cyanide should not be allowed to boil. He uses a small sample (10 grams). "Technical Methods of Chemical Analysis" 1, Part 1, p. 256. It is our experience that satisfactory results are not obtained unless the extreme heat of the furnace is used.

² See also Mellor, "A Treatise on Chemical Analysis," p. 270, 1913.

The Sodium Carbonate Method

The sample is fused with equal parts of sodium carbonate and sulphur.¹ The fusion is then dissolved in water. The tin goes into solution as a thiostannate of sodium. Iron and copper are then separated by the addition of sodium sulphite, leaving arsenic, antimony and tin in solution.2

Other Methods of Opening Tin Ores

Fusion with Sodium Hydrate. The sample of ore is fused with ten times its weight of sodium hydrate. The process is carried out in an iron erucible and then transferred to nickel. The fused mass is dissolved in water and the tin determined in the usual way.3

Reduction by Means of Hydrogen. The ore may be reduced by strongly igniting in a porcelain tube in a current of hydrogen. The reduced metal is then dissolved in hydroehlorie acid and the tin estimated by a standard method.

Fusion with Sodium Peroxide. J. Darroch and C. Meiklejohn opened ores, slags, etc., by fusing with sodium peroxide in a nickel crucible. They dissolve the fused mass in hot water and acidify with hydroeldorie acid. The sample is then ready for the necessary separations.

SEPARATIONS

Tin is separated from iron, aluminum, chromium, etc., by the insolubility of its sulphide in dilute hydrochloric acid. Tin, together with antimony, arsenie, platinum and gold, is separated from lead, mercury, copper, eadmium and bismuth, by the solubility of its sulphide in yellow ammonium sulphide. Antimony, arsenic, platinum and gold are precipitated as metals from a hydroehlorie acid solution by the action of metallic iron, leaving tin in solution.

A few special separations are of interest.

Tin and Lead. For the analysis of an alloy of lead and tin, it is usually preferable to make the estimations on different samples. In this ease, lead is estimated by Thompson's method and the tin by Baker's modification of the iodine method. Lead can also be separated from tin by the method given below for the separation of tin and eopper.

Tin and Copper. This alloy can be dissolved in concentrated hydrochloric acid by the addition of potassium chlorate. A large excess of ammonium tartrate is added and the solution made alkaline with ammonia. Copper is then precipitated as sulphide by the addition of hydrogen sulphide water until no more precipitate is formed.

Very finely divided carbon is sometimes preferred. Air must not be allowed to enter the crucible. Else decomposition is not complete. Mellor, "A Treatise on Chemical Analysis," 1913, p 270. If carbon is used instead of sulphur the process becomes one of reduction to the metal and is carried out in the assay furnace. The details of operation are similar to the cyanide process. The metal separates as a button details of operation are similar to the eyanide process. The metal separates as a button in the bottom of the crucible. The button contains other metals with the tin and must be analyzed further for exact percentages.
Mellor objects to the method as being tedious and dirty.
Low, "Technical Methods of Ore Analysis," 3d Ed., pp. 208-213, 1908.
Engineering and Mining Journal, 81, 1177, 1906.

Tin and Antimony. Antimony is separated, in the metallic form, from the hydrochloric acid solution of the alloy, by the action of metallic iron placed in the solution. The tin may be determined by the iodine method without the removal of the antimony. If the antimony is desired, it may be filtered off and determined in the usual way.

As in the case of lead, it is usually quicker and more accurate to make these determinations on separate samples. The tin can be determined by the iodine method. The antimony can be determined volumetrically by various methods,

preferably the bromate. (See chapter on Antimony.)

Tin and Phosphorus. One-half gram of the alloy is dissolved in 15 cc. of concentrated hydrochloric acid containing potassium chlorate. This is diluted to 200 cc. with water and warmed. It is then treated for a long time with hydrogen sulphide gas. The tin is all precipitated as sulphide while the phosphorus remains in solution.

Tin and Iron and Aluminum. Tin is separated from iron and aluminum by

precipitation, as sulphide, from the hydroculoric acid solution.

Iron may also be separated from tin with copper, and lead by precipitation

as sulphide from the alkaline ammonium tartrate solution.

Tin and Tungstic Acid. Donath and Mullner 1 separate tin oxide from tungstic acid by mixing the sample with zine dust and strongly igniting in a covered crucible for fifteen minutes—boiling with dilute hydrochloric acid; oxidizing with potassium chlorate to change the blue tungstic oxide to tungstic acid and diluting with water. It is then allowed to stand overnight and filtered. The tin is in solution.

GRAVIMETRIC METHODS FOR THE DETERMINATION OF TIN

Determination of Tin or the Oxides of Tin by Hydrolysis

This method depends upon the precipitation of meta-stannic acid in the presence of ammonium nitrate when the stannic chloride is diluted to considerable volume and heated to boiling. It is especially applicable to the determination of tin oxide in tin paste, but may be extended to all chloride solutions of the higher oxides. The reaction involved proceeds as follows:

$= H_2SnO_2 + 4NH_4Cl + 4HNO_{2,2}$

Stannous tin may be determined by oxidizing the chloride solution to the stannie form. The method gives concordant results and is rapid.

Procedure. For the analysis of tin paste take a catch weight of about 10 grams for a sample. Dissolve this sample by heating it in a No. 6 beaker with 300 cc. of concentrated hydrochloric acid. Transfer the acid solution to a 500-cc. volumetric flask and make up to the mark with dilute (1:1) hydrochloric acid.

 $SnCl_4+4Na_2SO_4+3H_2O=H_2SnO_3+4NaCl+4NaHSO_4$.

¹ J. Chem. Soc. Absts., 54, 531, 1888. ² Fresenius, "Quantitative Chemical Analysis," 1, 406, 1903. Sodium sulphate may be used instead of ammonium nitrate. In that case the reaction is

Take 50 cc. (approximately 1 gram) for a working sample. (If the determination is to be made on tin paste, the sample may be obtained directly by one of the methods described under Opening Tin Ores.) Dilute to 100 cc. with cold water. Nearly neutralize with strong ammonia and finish by adding drop by drop from a burette, dilute ammonia until a slight permanent precipitate is formed. A large amount of ammonia will tend to precipitate iron, if present, as a hydrate and to re-dissolve the meta-stannic acid. Add 50 ec. of a saturated solution of ammonium nitrate. Dilute to 400 ce. with boiling water, stirring constantly. Bring the solution to an incipient boil, remove from the flame and allow the beaker to stand on the steam bath unvil the precipitate has settled.* The solution above the precipitate should be clear. Decant the supernatant liquor through a 12½ cm. S. & S. 590 filter paper and wash the precipitate by decantation six times, using 200 ce. of boiling water and allowing the precipitate to settle thoroughly at each washing. Transfer the precipitate to the filter, "cop" out the beaker and wash down with hot water in the usual way. After the precipitate has been allowed to drain, transfer to a porcelain or a siliea crucible and dry carefully on an asbestos board over a Bunsen flame. When dry, ignite at a low temperature until the filter paper has been consumed. Increase the heat and finally blast to constant weight.

> Weight SnO₂×100×.7877 = per cent Sn. Weight of sample

Determination of Tin as Sulphide

The determination of time as a sulphide involves many difficulties and should be avoided if possible. Better results can be obtained by the volumetric methods and in most cases without the necessity of preliminary separations of interfering metals. If tin must be separated as a sulphide, better results would be obtained if the precipitate were dissolved and the tin content determined by the iodine

Having the hydrochlorie acid solution of tin after the interfering metals have been separated, to precipitate tin sulphide, neutralize with ammonia and then acidify with acetic acid. Pass hydrogen sulphide until the solution is saturated. Allow the precipitate to settle overnight. Pour the supernatant liquor off through a Gooch crucible and wash the precipitate six times by decantation, using a solution of ammonium nitrate * for wash water. Finally transfer to the crueible and wash free from chlorides. Dry the crucible in an oven at 100° C. Heat slowly in a Bunsen flame until all the sulphur has been expelled. Care should be taken at this point to avoid forming fumes of stannic sulphide by heating too rapidly.

¹ Some practice is required to judge accurately the exact point when the necessary amount of ammonia has been added. The precipitate should appear white.

² It the boiling continues more than a few seconds the precipitate will not settle Time will be saved in this case if the sample is discarded and a new deterproperly. mination commenced.

If meta-stannic acid is washed over onto the filter at this point, clogging will result and a great deal of time will be lost,

4 Spattering is likely to occur here, causing loss

Sulphide of tin separates as a slimy mass which tenaciously retains alkaline salts, especially in the absence of ammonium salts. Mellor, "Treatise on Chemical Analysis. p. 308, 1913.
Biohloride of tin, Acker process, page 425.

Remove the lid of the crucible, which should be kept in place during the first p. of the heating, and raise the temperature gradually, finally finishing with t blast. As sulphuric acid is usually present in some quantity, the crucible shou be cooled and a small piece of ammonium carbonate should be placed in it. Repet the ignition to drive out the acid. Cool and weigh as SnO₂.

BICHLORIDE OF TIN

Bichloride of tin is of great importance in some of the industries, especially the textile. It is necessary to have exact analytical control of the processes is which this compound is used in order to insure uniform results and to certify the efficiency and economy of the process. Several methods have been developed for this purpose. The ones given below have had practical application and have proven to be satisfactory.

Stannic Acid Method.—Hot-water Precipitation. In the textile industry where bichloride of tin is used, the efficiency of the process depends directly of the neutrality of the tin liquor. If there is more than enough chlorine present in the bichloride solution to exactly oxidize all the tin to the stannic form, this excess is called "free HCl." If there is not enough chlorine present to do this the deficiency is spoken of as "basic HCl." The difficulty of determining the "free" or "basic" HCl is apparent when it is known that SnCl4 readily decomposes in water, liberating free acid. The following method has been developed especially for this purpose and has given good results.

The important point in this analysis is to determine whether the liquor ha "free" HCl present or whether it is "basic" in nature. It has been found tha hot water precipitates tin from the SnCl₄ solution as stannic hydroxide and at the same time liberates the chlorine as free HCl.

$SnCl_4+4H_2O = Sn(OH)_4+4HCl_2$

The Sn(OH), separates in a colloidal precipitate which may be filtered off an the tin estimated as Sn()₂. The liberated acid may be determined in the filtrate and from this data tho "free" or "basic" HCl can be calculated.

Procedure. For accurate work about 20 grams of the liquor should be weighe out in a tared weighing bottle, but for works control, where time is an importan factor, it is sufficiently accurate to get the specific gravity of the liquor by mean of a hydrometer and take a measured quantity for a sample, calculating the weigh from these data.

Transfer the sample to a 100-cc. volumetric flask. Make up to volume wit cold distilled water. Praw out of this solution 10 cc. (approximately 2 grams and place in a 150-cc. tall beaker. Fill the beaker nearly full with boiling he water, stirring continuously while the water is being poured in. Place the beake on top of the steam bath and allow the precipitate to settle. Decant the liquo

Holleman and Cooper, "Text Book of Inorganic Chemistry," 4th Ed., 1912.
 If the solution is not stirred at this point, the precipitate will not settle an trouble will be experienced during the filtering process.

¹ This method is generally used only when minute traces of tin are present, an then it is considered best to dissolve the sulphide in hydrochloric acid and make th final determination by the iodine method. (See analysis of Canned Foods for "Salt of Tin," page 536.)

through an 11 em. 590 S. & S. filter ¹ and wash the precipitate six times by decantation, using hot water. Now transfer the precipitate to the filter and continue the washing until 1 drop of the filtrate gives no test for chlorine. After most of the water has drained out of the filter, place the paper and precipitate in a tared silica crucible. If there is plenty of time, dry the contents of the crucible on an asbestos board over a low Bunsen flame. In case the analysis must be made in a hurry, cover the crucible ² and heat it very carefully over a low flame until all the water has been driven out and the paper has been charred. Then remove the cover and increase the heat to the full Bunsen flame and finally blast to constant weight. Weigh as SnO₂. Titrate the filtrate with N/1 NaOH, using methyl orange as the indicator.

Calculation:

The difference between these last two figures equals "free" or "basic" HCl. The Acker Process Method. The theory of this method is practically the same as that of the hot-water method, except that in this case the liberated acid is neutralized with ammonia before the stannic hydroxide has been filtered off, the advantage being that any solution of the stannic hydroxide, by either acid or alkali, is prevented. The method is not applicable for the determination of "free" or "basic" HCl.

Procedure. Weigh out 25 cc. of the bichloride of tin solution. Transfer to a 500-cc. flask (volumetric) and make up to volume with cold water. With a standardized pipette, transfer 25 cc. of this solution to a No. 4 beaker. Dilute with hot water to precipitate most of the tin as stannic hydrate. Add 10 drops of phenolacetolin⁴ (1 gram of phenolacetolin dissolved in 200 cc. of water). Titrate very carefully with dilute ammonia until the appearance of a rose-ced color. Boil a few minutes on the hot plate. Allow the tin precipitate to settle. Decant through an 11-cm. filter paper (S. & S. 589, black ribbon brand). Wash rapidly with hot water without allowing the precipitate to cake down in the filter until the washings are free from chlorine. Dry the precipitate in an oven at 100° C. When dry, invert the filter into a tared porcelain crucible and heat on a gauze until the paper has disappeared. Remove the gauze and heat with the full

¹ Time may be saved by using a platinum cone with the filter and applying a gentle vacuum. This can be done with very little danger of breaking the paper.

² This precaution must be taken, else there will be a loss by decrepitation.

³ Kindness of W. F. Dorflinger, chief chemist of Perry-Austin Manufacturing Company.

^{*}Luteol may be used as indicator, giving a yellow color at the end-point. It is slightly more delicate but much more expensive.

Bunsen flame for a few minutes. Finally blast to constant weight. Weigh as SnO₂.

Take the filtrate and washings and dilute them to a volume of 1000 cc. Warm 500 ec. of this solution and saturate it with hydrogen sulphide. If any tin separates, filter and ignite in a tared porcelain crueible. Moisten with a little nitrie acid and heat very slowly to drive out the seid. Ignite to constant weight. Weigh as SnO₂. Add this result to the SnO₂ obtained above when calculating the final result.

Determination of Tin in Bichloride of Tin as Sulphide

This method is given as an alternative for the Acker Process Method and may, be used as a check on that process. Uniform and concordant results have been obtained by the use of the two methods.²

Procedure. Weigh out 25 cc. of bichloride and dilute to 500-cc. volume with cold distilled water. Take 25-cc. portions of this solution for analysis. Dilute the sample to 250 cc. Saturate with hydrogen sulphide. Warm the mixture on a hot plate at a temperature of about 65° C. until the precipitate is coagulated. Test the clear supernatant liquor fer unprecipitated tin by adding a little hydrogen sulphide water. Filter on an ashless filter and wash free from chlorides. Make the filtrate and washings up to 1000 cc. volume for further determinations. Dry the tin sulphide precipitate on the filter in an oven at 100° C. Remove the precipitate from the paper as completely as possible. Ignite the paper in a weighed porcelain crucible. Cool and add a few drops of nitric acid. Repeat the ignition, heating very carefully at first until the acid has nearly all been driven out. Now place the main tin precipitate in the crucible. Cover, heat gently for a few minutes, moisten with funning nitric acid, ignite very carefully for one-half hour and then blast for fifteen minutes. Weigh as SnO₂.

VOLUMETRIC DETERMINATION OF TIN

Volumetric methods for the determination of tin are based upon the reducing power of stannous compounds. They vary according to the oxidizing agent used and the details of manipulation.

Lenssen's Iodine Method as Modified by Baker. This method is a modification of Lenssen's Iodine Method for the determination of tin in alkaline solutions. It is especially applicable to the determination of "salts of tin" in eanned foods and to the estimation of tin coating on tin plate, but is accurate, rapid and very satisfactory for alloys and general analysis.

The method is based on the action of iodine in the presence of stannous chloride in hydrochloric acid solution. The reaction involved is:

$$SnCl_2+I_2+2HCl = SnCl_4+2HI$$
.

A. Jilek reduces tin by means of iron, filtering off precipitated Sb, Cu and excess of Fe, in an atmosphere of CO₂. The reduced tin solution is now titrated with standard iodine.

^{h-1} If there has been any reduction, a few drops of nitric acid may be added and the ignition repeated, heating slowly at first to prevent loss by decrepitation.

Iron, lead and antimony do not interfere with the reaction. Copper in small quantities does not interfere with the determination, but if it is present in large quantities as a salt, it is likely to produce low results. Determinations made by the writer show that results are accurate when less than 10% of copper, as copper chloride, is present. Larger amounts gave consistently low results. The reason for this fact centers around the difficulty of reducing all the copper to the cuprous form. If any CuCl₂ is left in the solution, it reacts with the potassium iodide of the iodine solution, causing the precipitation of CuI and the liberation of free iodine.

$CuCl_2+2KI=CuI+2KCl+I$.

Copper present as the metal is not easily soluble or goes into solution in the reduced form and is not likely to disturb the determination.

Solutions—Standard Tin Solution. Dissolve 5.79 grams of Kahlbaum's C. P. tin in C. P. hydrochlorie acid. The solution of the tin is effected by placing about 150 cc. HCl in an Erlenmeyer flask, together with the tin, and boiling. After the tin has all been dissolved, transfer to a volumetric liter flask and make up to the mark with dilute hydrochloric acid.

1 ee.'=.00579 grain Sn.

Standard Iodine Solution. Dissolve 12.7 grams of C. P. iodine in a water solution of 20 grams of potassium iodide. Make up to one liter and standardize against the standard tin solution. For tin plate analysis, it is convenient to adjust the iodine solution so that 1 cc. equals exactly .00579 gram of tim. Then, if a sample of the plate having a total surface of 8 sq.ins. is taken, 1 cc. of the iodine solution is the equivalent of one-tenth of a pound per base box.

Indicator. Dissolve 5 grams of pure soluble starch in 1 liter of water.

Air-free Water. Dissolve 12 grams of bicarbonate of soda in 1 liter of water. Add 20 cc. HCl and allow the resulting gas to escape. Keep in a stoppered bottle.

Procedure. For practical purposes, take a sample, such that the tin content will be between .2 gram and .5 gram. A larger sample should be taken for extreme accuracy in order to decrease the possible technical error. Place the sample in flask A of the Sellars apparatus, Fig. 68, together with 100 cc. of cone. C. P. HCl. Stopper the flask and connect tubes B and D, as shown in the illustration. Boil until the metal is all dissolved. This point is indicated by the cessation of the hydrogen evolution and the appearance of large well-developed bubbles. If a sufficient amount of metallic iron is present in the sample, complete reduction is assured. If no iron was present in the sample, or if there was not enough to reduce all of the tin, make sure that the tin is all converted to the stannous form by adding aluminum foil (about 1 gram). Replace the stopper and connect as originally. Boil until normal bubbles reappear. Open cock C to allow CO_2 4 gas to enter. Place the flask in cooling bath F without disconnecting the apparatus. After the solution has become thoroughly

² Sulphates must not be present. They tend to have an oxidizing effect and spoil

⁴ Carbon dioxide generated in a Kipp apparatus is likely to contain oxygen. It is much better to use liquid CO₂ such as can be purchased in the open market.

¹ Mr. B. S. Clark.

the results.

There should always be an excess of bicarbonate of soda present in order that carbon dioxide will be generated during the washing process, thus preventing air from entering the flask at any time during the analysis.

cool, disconnect tubes B^1 and D^1 from the splash bulbs. Wash the bulbs with "air free" water, allowing the washings to drain into the bulk of the sample. Remove the stopper and wash down the sides of the flask. About 50 cc. of water should be used in the washing so that the final sample contains about 25% HCl. Add 5 cc. starch solution and titrate with the standard iodine solution.

$$\frac{\text{ce. iodine} \times .00579 \times 100}{\text{Weight of Sample}} = \text{per cent Sn,}$$

or

$$\frac{\text{ec. iodine}}{10}$$
 = pounds per "base box."³

The Sellars Apparatus. This apparatus is a device designed by Mr. W. S. Sellars of this laboratory for the purpose of facilitating the solution of tin samples out of contact with air. Added to this advantage, it is equipped with a water




Fig. 67.—Sellars' Apparatus.


eooler. It is also constructed so that the tubes and scrubbing bottles can be cleaned by flushing with water. The use of this apparatus practically climinates the usual sources of error in connection with the iodine method, and at the same time greatly increases the speed of the determination. Fig. 67 shows the apparatus in operation.

- A. 300-ce, Erlenmeyer flask.
- B.1 Connection with reduced pressure line from liquid carbon dioxide cylinder.
- C.1' Glass manifold.
- D.1 Exit connection to trap.
- E.1 Water trap to prevent escape of IIC1 fumes and to prevent air from backing into the flask,
- F.1 Cooling tank.
- G.1 Low-pressure water wash-out manifold.
- H.1 Perforated feed pipe to water cooler.
- K.1 Outlet for cooler.
- Ly Electric hot plate.
- M.1 Lead drain pipe.

¹See Fig. 68, page 535. ²" Basebox"—112 sheets of tin, 14×20 ins.

Ferric Chloride Method.¹ This method depends upon the reduction of ferric chloride by stannous chloride in hot solution.

SnCl₂+2FeCl₂-SnCl₄+2FeCl₂.



Mene, Dinglers Journal, 117, 230, 1850. K. Pallet and A. Allart, Bul. Soc. Chim. (2) 27, 43, 438, 1877. H. J. B. Rawlins, Chem. News, 107, 53, 1913. H. Nelsmann, Zeit. Anal. Chem., 16, 50, 1877.

Antimony, copper, arsenie, bismuth, mercuric chloride, tungsten and titanium must be absent.

The Standard Solution of Ferric Chloride is made by dissolving pure iron wire in hydrochloric acid. To standardize this solution, dissolve 1 gram of pure tin in 200 cc. of C. P. HCI, preventing air from coming in contact with the solution by means of a trap, or by passing earbon dioxide over it. Titrate this standard sample with the ferric chloride solution. The end-point is indicated by the yellow color, due to a slight excess of the iron solution.

Procedure. Tin is first separated from the interfering metals in the usual way. If lead, copper, arsenic, antimony or bismuth arc present, the sample is first reduced, in the hydrochloric solution, with iron wirc. The solution is then filtered. Lead and tin remain in the filtrate. Neutralize by adding strips of zinc until the action ceases. Tin and lead are precipitated. The clear liquid should show no trace of tin with hydrogen sulphide. Allow the precipitate to settle and wash by decantation, keeping the precipitated metals in the flask. Add 150 ec. of concentrated hydrochloric acid, keeping the contents of the flask protected from the air, and bring to a boil. When everything is dissolved, titrate to a yellow color with the ferric chloride solution.3 This part of the analysis should be dono very quickly to prevent oxidation by the oxygen of the air.

¹ Lunge, "Technical Methods of Chemical Analysis," 2, Part I, p. 267.

The Sellars apparatus can be used with advantage for this purpose.
The end-point can be easily identified by looking at a blue Bunsen flame through the solution. When a small quantity of ferric chloride is present, the flame appears green. Mellor, "A Treatise on Chemical Analysis," p. 310, 1913.

4 H. A. Baker, Eighth International Congress of Applied Chemistry.

TIN 536a

VOLUMETRIC METHOD FOR TIN IN ALLOYS

The titration of stannous solutions by iodine may be represented by the following reaction:

 $SnO + 2I + H_2O = SnO_2 + 2HI.$

Sn is equivalent to O or to 2H, hence a normal solution contains one-half the molecular weight of Sn, or 59.35 grams per liter of solution.

Apparatus. This consists of a 300-cc. Erlenmeyer flask, with a one-hole stopper, through which passes a quarter-inch glass tube, connected with a rubber tube 12 to 15 inches in length, the other end of the rubber tubing is connected with 2-3 inches of glass tubing, which dips in the beaker containing a bicarbonate of sodium solution.

Reagents. 0.1N iodine solution. Standardize against a sodium arsenite (arsenions acid) solution. 1 cc. 0.1N I=0.005935 g. of Sn.

Starch solution. Sulphuric and hydrochlorie acids. Antimony powder.

Procedure. Decomposition of the Sample. Tin alloys generally decompose in hydrochloric acid, but more readily in strong, hot sulphuric acid.

A factor weight 0.5935 gram of the tin alloy is placed in a 300-ce. Erlenmeyer flask and 10 ce. of strong sulphuric acid added. The mixture is heated, preferably over a free flame, until the alloy completely disintegrates. Nearly all of the excess of free acid is expelled, keeping the flask in motion over the flame to lessen the tendency towards bumping, which is apt to occur during the concentration. The moist residue is allowed to cool.

100 cc. of (air-free) water are added followed by 50 cc. of strong hydrochloric acid and the mixture gently warmed until the solution begins to clear. The apparatus is now assembled as shown in the figure, about 15 cc. of 10% (saturated solution) sodium bicarbonate being placed in the test tube (or 50 cc. in the beaker, if this is preferred to a test tube).

About 1 gram of very finely powdered antimony metal is placed in the flask, followed by 10 ce. of saturated sodium bicarbonate solution, the stopper being removed during the addition and then immediately replaced. The air is displaced by the CO₂ generated.




Fig. 68a. Apparatus for Determination of Tin

The apparatus is now placed on a hot plate, or on an inverted sand-bath dish over a flame, and the solution is gently boiled for 10 to 15 minutes. The antimony should be of such fineness as to remain suspended during the ebul-

Ition of the liquid at this stage.

The test tube is now nearly filled with saturated sodium bicarbonate and the apparatus removed to a desk for a few minutes, and then placed in a cold water-bath of running water or under tap water, until the solution cools down to near room temperature. During this cooling carbonate will be sucked back into the flask. "A" to establish pressure equilibrium, CO₂ being generated in the flask. Sufficient solution will remain in the test tube to act as a scal and prevent admission of air, which would spoil results by its oxidation of the tin.

The tube B and the test tube C are disconnected and 5 ec. of starch solution added by means of a pipette passing through the hole in the stopper

(which should be loosened in the throat of the flask).

Standard iodine solution is now added, the tip of the burette passing through the hole of the stopper, agitating the solution by a "swirling" motion of the flask. The end-point is a blue color, which does not fade on stirring the solution.

If a factor weight has been taken, each cc. of the iodine of 0.1N strength is equivalent to 1 per cent of tin.

Notes. In the presence of copper a separation must be effected as over 3 per cent copper interferes in this volumetric method especially when the percentage of the tin is low. High copper alloys do not decompose readily in hydrochloric or sulphuric acids, but easily in dilute nitric acid. The solution obtained is evaporated to dryness, the residue is taken up with strong nitric acid, the oxide of tin (and antimony) remains insoluble, hot water is added and the solution filtered (hot) and the oxide washed once or twice with hot water. The tin (and antimony) is now best dissolved 1 by digesting for 3-5 minutes with 50 cc. of water saturated with SO₂ (at 60-70° C.), then 10 cc. of strong HCl are added to the solution heated to boiling and the SO₂ expelled by boiling. The solution is now ready for reduction with antimony by the method outlined above.

Tin may be reduced by iron wire or nails, the precipitated Cu, Sb and the excess of Fe filtered off, under an atmosphere of CO₂, and tin titrated with iodine.

¹ Earnest Stelling, Ind. and Eng. Chem., 16, 346 (April, 1924).

ESTIMATION OF TIN IN CANNED FOOD PRODUCTS¹

The tin in the canned food products is obtained as a sulphide precipitate from wet combustion, with nitric and sulphuric acids, of 100 grams food product.

The elear sulphuric acid residue is diluted, neutralized with ammonia and then rendered about 2% acid with hydrochloric acid, after which it is thoroughly saturated with hydrogen sulphide gas. This precipitate is then filtered on a Gooch crucible with a false bottom. The precipitate may contain foreign substances, such as lime, phosphorus, and silica, some lead, or even small amounts of iron, but none of these will cause any trouble subsequently in the titration, so that the labor of separating the tin completely from the precipitate is obviated.

After washing the precipitate three or four tunes in a Gooch crucible, it is transferred to a small porcelain dish by simply foreing out the false bottom of the

Gooch crucible and its asbestos pad and rinsing off the crucible.

The precipitate, mixed with asbestos, is now transferred to a 300-cc. Erlenmeyer flask and boiled with strong hydrochloric acid, potassium chlorate being added from time to time to insure the complete breaking up and solution of the tin sulphide, as well as the elimination of the sulphur. This is accomplished in a very few minutes. A tew strips of pure aluminum foil, free from tin, are then added to the flask until all of the chlorine is eliminated. The flask is then attached to the Sellars apparatus and the determination completed, according to the details given under the Iodine Method, using N/100 iodine solution.

Gravimetric Method. The sample is first digested to a colorless or pale

yellow solution as described under Baker's method.

Add 200 cc. water to the digested solution and pour into a 600-cc. beaker. Rinse out the Kjeldahl flask with three portions of boiling water so that the total volume of the solution is about 400 cc. Allow to cool and add 100 cc. concentrated ammonia. This amount of ammonia should render the solution nearly neutral, unless more than 50 cc. sulphuric acid have been used for digestion. The solution should be tested to see that it is still somewhat acid. In case of a large excess acid, add ammonia until just alkaline and then make about 2% acid with hydrochloric or sulphuric acid. Pass in a s'ow stream of hydrogen sulphide for an hour, having the covered beakers on an electric hot plate at about 95° temperature. Allow to digest on the hot plate for an hour or two.

Filter the tin sulphide on an 11-cm. filter. Wash with three portions of wash solution alternated with three portions of hot water. The wash solution is made up of 100 cc. saturated ammonium acetate, 50 cc. glacial acetic acid, and 850 cc. water. The filter papers used in this method are C. S. & S. No. 590, white

ribbon.

Place the filter and precipitate in a 50-cc. beaker and digest with three successive portions of animonium polysulphide, bringing to a boil each time and filtering through a 9-cm. filter. Wush with hot water. Acidify with acetic acid, digest on the hot plate for an hour and filter through a double 11-cm. filter. Wash with two portions of wash solution alternated with hot water and dry thoroughly in a weighed porcelain crucible. Thorough drying is essential to the success of the determination. Ignite very gently at first and later at full heat of Bunsen flame. Finally heat strongly with large burner, or Méker burner, having the crucible partly covered. Stannic sulphide must be gently roasted to the oxide, but the oxide may be heated strongly without loss, due to volatilization.

Weigh the stannie acid and convert to metallic tin by the factor .7877.

H. A. Baker, Eighth International Congress of Applied Chemistry.
 E. L. P. Treuthardt. Association of Official Agricultural Chemists, August 15, 1915.

TITANIUM

Tl, at.wt. 47.9; sp.gr. 4.5 1; m.p. 1795° C. (±15°)1; oxides TlO, Tl₂O₂, TiO₂, TiO₁.

DETECTION

The powdered ore is fused with potassium bisulphate, KHSO4, until effervescence ceases. The cooled mass is dissolved in dilute sulphuric acid by boiling. Hydrogen peroxide, H₂O₂, added to this titanium solution. produces a yellow to orange color, according to the amount of titanium present. Hydrofluoric acid, or fluorides, destroys the color. Vanadium also produces this color with hydrogen peroxide, but the color is not destroyed by HF. The yellow color, according to Weller • is due to TiO, formed.

Morphine produces a crimson color with solutions of titanium in sulphuric acid.

Zinc added to hydrochlorie acid solutions of titanium produces a blue color, tin a fine violet solution.

If sulphur dioxide, SO2, is passed into the solution of titanium to reduce the iron, and the slightly acid solution then boiled, yellowish white metatitanie seid, TiO(OH)2, is precipitated.

Bead Test on Charcoal. A small portion of the powdered mineral heated on charcoal with microscosmic salt and tin produces a violet-colored bead if titanium is present.

OCCURRENCE

The element is widely distributed in minerals, soils, clays and titaniferous iron, FeTiO₂. It is found in granite, gneiss, mica, slate, syenitic rocks, granular limestone, dolomite, quartz, feldspars and a large number of other minerals. The principal commercial minerals are:

Ilmenite, FeTiO₂, containing about 52.7% TiO₂.

Rutile, TiO₂, containing 90 to 100% TiO₂.

Titanite, CaTiSiO₅, containing 34 to 42% TiO₂.

Perovskite, CaTiO₂, containing about 60% TiO₂ and 5 to 6% Yt₂O₃.

Titaniferous ores of variable titanie oxide content.

APPLICATION

Titanie oxide is now extensively used as a white pigment for paint. this purpose the titanic oxide is usually precipitated upon or coalesced with

¹ By Wilfred W. Scott and L. E. Barton.
² Hunter, Eighth Int. Congress Applied Chem., 2, 125.

Burgess and Waltenburg, U. S. Bureau of Standards.

4 J. S. C. I., 1882, 508-508.

Deville, C. N., 4, 241.

Cahen and Wootton, "The Mineralogy of the Rarer Metals."

precipitated barium sulphate, making a product containing about 25% titanic oxide. The white titanium pigments are characterized by their exceptional hiding power, excelling in this respect any other commercial white pigments.

Another important application of titanium is the use of ferrotitanium in the iron and steel industry. The function of the titanium is to deoxidize the steel and consequently to yield a product free from blowholes and segregation of impurities. In a steel thus purified the natural strength and resistant properties of the material are developed in the highest degree.

Titanium has also found application in the textile and leather industries. In the dyeing of leather, titanium potassium oxalate has been found particularly well adapted. The use of titanous chloride and titanous sulphate for bleaching or discharging colors is increasing. Such bleaching agents are particularly applicable for silk and wool, which are injured by the action of those bleaching agents in which chlorine is the active element.

Titanium compounds are also used for electric light filaments, are carbons, ceramies, fine brown glazes, paint for iron and steel, etc.

ESTIMATION

Preparation and Solution of the Sample

A knowledge of the solubility of the element and its oxides is of value in the solution of the sample.

Element. This is feebly soluble in cold dilute hydrochloric or sulphuric acids; more readily so when the acids are heated. It is soluble in cold, concentrated hydrochloric acid; readily soluble in hot, concentrated hydrochloric or sulphuric acids. It is searcely acted upon by nitric acid, but readily dissolves in hydrofluoric acid. It is soluble by fusion with the alkalies.

Oxides. Ti₂O₅, which has a black or blue color, is soluble in concentrated hydrochloric or sulphuric acids; forming, in the latter case, a violet-colored solution. The oxide is insoluble in water and in ammonium hydroxide.

TiO₂ is difficultly soluble in concentrated sulphuric acid, less soluble if strongly ignited. The metatitanic acid, TiO(OH)₂, requires strong hydrochloric or sulphuric acid to effect solution; the orthotitanic acid, Ti(OH)₄, however, is readily soluble in hot or cold, dilute or concentrated acids. From titanic solutions orthotitanic acid is precipitated by ammonia, the precipitation being assisted by warming. Boiling a slightly acid solution precipitates the metatitanic acid, TiO(OH)₂. TiO₂ is soluble upon fusing with alkalics. TiO₂ is soluble in hydrofluoric acid, forming TiF₄, which is volatile, unless an excess of sulphuric acid is present (distinction from silica). The ignited oxide is best dissolved by fusion with KHSO₄ and heating the fused mass with dilute sulphuric acid solution.

Salts. Many titanic salts are decomposed in the presence of water, precipitating titanic acid, the extent of the decomposition depending on the quantity of water used. Titanic sulphate is readily soluble in water and the solution is remarkably stable unless largely diluted with water. Some of the double salts are readily soluble and their solutions stable, i.e., potassium titanium oxalate.

¹ Ebelmen, A. Ch. (3), 20, 392, 1847.

Solution of Steel. The sample may be dissolved in hydrochloric acid (1:2). If a residue remains, it is treated with a mixture of equal parts of hydrofluoric and sulphuric acids and a few drops of nitric acid, in a platinum dish, and the mixture evaporated to sulphuric anhydride funces and to complete expulsion of hydrofluoric acid. The colorimetric procedure is now used for estimating titanium. For determination of titanium in hydrochloric acid solution see page 545.

Note. Titanium in steel treated with ferro earbon-titanium exists in two conditions: (1) Titanium soluble in hydrochloric acid. (2) Titanium insoluble in hydrochloric acid. Of the very small amount of titanium in treated steel the greater part will usually be found in the second form. When the amount of titanium in the steel is exceedingly small, the soluble titanium frequently exceeds the insoluble, and it is then occasionally desirable to determine also that existing in the second form.

Alloys. These are dissolved in concentrated nitric acid, aqua regia or a mixture of the dilute acids. Should nitric acid be used, the excess is expelled by evaporation to dryness with hydrochloric acid. The metals of the hydrogen sulphide group are removed in an acid solution by precipitation with H₂S, and titanium determined colorimetrically in the filtrate.

Ores. One to 5 grams of the ore are treated with 10 to 50 cc. of a mixture of sulphuric and hydrofluoric acids (1 to 5), a few drops HNO₂ added, and the solution evaporated to fumes to expel HF. If a residue remains upon taking up with water containing a little sulphuric acid, it is filtered off and fused with KHSO₄ as directed under the fusion method.

Fusion Method for Ores. The finely powdered sample is fused with four to five times its weight of potassium bisulphate, KHSO₄, and the cooled fusion dissolved with dilute sulphuric or hydrochloric acid. In the presence of silica potassium fluoride is added to assist in the decomposition of the material.

(See Analysis of Titaniferous Orcs, page 551.)

Titaniferous Slags. One-half gram of the finely ground sample is decomposed in a platinum dish by a mixture of 5 cc. water, 5 cc. concentrated sulphuric acid, 2 cc. nitric neid, and 10 cc. of hydrofluoric acid, the reagents being added in the order named. The solution is evaporated rapidly to SO₂ fumes to expel fluorides and the excess sulphuric acid until residue is left nearly dry. After cooling it is taken up with 40 cc. of dilute hydrochloric acid (1:3), which will give a clear solution containing all the constituents of the slag except silica, which has been volatilized as SiF₄. The solution is diluted to 200 cc. with cold water. Iron and titanium are precipitated by ammonia in slight excess and filtered at once without boiling. The precipitate is dissolved in cold dilute hydrochloric acid and reprecipitated with ammonia. Titanium is now separated from iron by reducing iron with SO₂ and precipitating titanium from a boiling acid solution as described on page 542.

SEPARATIONS

Details of the isolation of titanium are given in the methods for its estimation.

Separation of Titanium from the Alkaline Earths, etc. The hydroxide is precipitated when a titanium solution containing ammonium ehloride is treated with ammonium sulphide, whereas barium, strontium, calcium and magnesium remain in solution. Titanium hydroxide may be precipitated by making the solution containing titanium slightly ammoniacal with HN₄OH.

Separation from Copper, Zine, Aluminum Iron, etc. Titanium is precipitated from a slightly acid solution 1 by boiling, passing sulphur dioxide through the solution to keep the iron reduced and prevent its precipitation.

Separation from the Bivalent Metals, Manganese, Niekel, Cobalt, Zine. Titanium is precipitated along with aluminum and iron by hydrolysis of its acetate in a hot, dilute solution, whereas manganese, nickel, cobalt and zinc remain in solution. Details of the basic acetate method are given on page 298.

Separation of Titanium from Aluminum. Small amounts of titanium from large amounts of aluminum. (One part Ti to 50 parts Al.) Cupferron, $C_6H_6(NO)N\cdot ONH_4$ added to a decidedly acid solution containing titanium and aluminum precipitates titanium, but not aluminum. The precipitate is washed by decantation and then on the filter with very dilute hydrochloric acid to remove traces of aluminum. The procedure affords a separation of titanium from ehromium, nickel, cobalt, manganese, etc. Copper and iron, however, precipitate with the titanium, if present in the solution. The yellow titanium salt has the composition $(C_6H_6(NO)NO)\sqrt{T}$.

Separation of Titanium from Iron. See Gravimetric Method for Determination of Titanium, Modified Gooch Method, below.

¹ Acidity exactly 0.5% is best according to Levy, C. N., 56, 209.

² Analyst, 36, 520, 1912, method of J. Bellucci and L. Grassi.

GRAVIMETRIC METHODS

Gravimetric Determination of Titanium. Modified Gooch Method 1

This method is applicable to minerals and metallurgical products that are comparatively high in titanium. The method provides for the separation of titanium from iron and from aluminum and phosphoric acid with which it commonly occurs. The procedure as proposed by F. A. Gooch and modified for non-aluminous rocks by Wm. M. Thornton has been found by the author to give reliable results. The details of the method with a few slight changes found to be advantageous are given below. Iron is separated from titanium by precipitation as a sulphide in presence of tartaric acid, the organic acid is destroyed by oxidation and titanium precipitated from a boiling acetic acid solution. In the presence of alumina and phosphoric acid the impure precipitate is fused with Na₂CO₃ and the impurities leached out with boiling water. In presence of zirconium, titanic acid is incompletely precipitated. Hillebrand's modification for the removal of zirconium is given in the notes.

Procedure. Preparation of the Sample. Ores High in Silica. These may be decomposed by taking to SO₂ furnes with a mixture of 10 to 15 cc. of 50% hydrofluoric acid, HF, and 3 to 4 cc. of concentrated sulphuric acid per gram of sample.

Oxides. Decomposed by fusion with sodium or potassium bisulphate. The fusion is dissolved in 10% sulphuric acid, keeping the volume as small as possible.

The sample should contain not over 0.2 gram titanium.

Precipitation of Iron. To the solution containing titanium, tartaric acid, equal to three times the weight of the oxides to be held in solution, is added. This should not exceed 1 gram of the organic acid, as the subsequent removal of larger amounts would be troublesome. H₂S is passed into the solution to reduce the iron and NH₄OH added to slight alkalinity followed by a further treatment with H₂S to completely precipitate FeS. The solution should be faintly alkaline (litmus) otherwise more anunonia should be added. After filtration and washing of the ferrous sulphide with very dilute and colorless ammonium sulphide, the titanium is entirely in the iron-free filtrate.

Oxidation of Tartaric Acid. Since titanium cannot be precipitated by any reagent in the presence of tartaric acid, the organic acid is oxidized by addition of 15 to 20 cc. of concentrated sulphuric acid to the sample placed in a 500-cc. Kjeldahl flask. The solution is evaporated to incipient charring of the tartaric acid. After cooling slightly, about 10 ec. of funing nitric acid are added cautiously, a few drops at a time, and when the violent reaction has subsided the flask is heated gradually (hood), a vigorous reaction taking place accompanied by much effervescence and foaming with evolution of copious brown fumes. The organic matter gradually disappears, the effervescence becomes steady and finally ceases and white fumes of SO₂ are given off. The solution is cooled and the pale yellow syrup poured into 100 cc. of cold water, the flask washed out, adding the rinsing to the main solution. If cloudy, the solution is filtered.

¹ F. A. Gooch, Proc. Am. Acad. Arts and Sci., New Series, **12**, 435. Wm. M. Thornton, C. N., **107**, 2781, 123, 1913.

² W. W. Scott.

Cupferron precipitates titanium in presence of tartaric acid.

Precipitation. Ammonia is added until the solution is nearly neutral, a point where the solution is slightly turbid, the precipitate dissolving upon vigorous stirring. If a trace of iron is suspected about 1 ec. of 10% ammonium bisulphate is added. Five ee. of glacial acctic acid followed by 15 grams of ammonium acctate or its equivalent in solution is added and the volume of the solution made up to about 350 cc. The solution is brought rapidly to boiling and maintained in ebullition for about three minutes. The titanium will precipitate in white flocculent and readily filterable condition. The precipitate is washed first with water containing acctic acid and finally with pure water. The filter and the precipitate are ignited cautiously over a low flame and finally blasted over a Méker blast for twenty minutes. The residue is weighed as TiO₂.

In the presence of large amounts of alumina and phosphoric acid, the residue above obtained is fused with sodium carbonate in a platinum dish and the fusion leached by boiling with pure water. Alumina and phosphoric acid go into solution as soluble sodium salts and titanium oxide remains insoluble in the residue.

Ignited insoluble residue = TiO₂.

Note. Titanium may be separated from aluminum by fusing the residue with potassium acid sulphate, KHSO₄, and precipitation of titanium in an acid solution by eupferron. Al₂O₃ is in solution.

Determination of Titanium in Ferro Carbon Titanium. Gravimetric Method ¹

Into a 6-in. porcelain evaporating dish, weigh 0.6 gram (factor weight) of alloy.

Dissolve in a mixture of 15 cc. of dilute sulphuric acid (one acid to one water), 5 ec. of nitrie acid, and 10 cc. of hydrochloric acid. Evaporate to fumes of sulphuric anhydride.

Cool and take up by boiling with 50 to 60 ec. of water and 5 to 10 ec. hydrochloric acid. Filter into a 500-ce. beaker and wash the residue with hot water and dilute hydrochloric acid.

In the filtrate precipitate iron and titanium by ammonia in slight excess. Filter without boiling and wash precipitate twice on filter with hot water.

Reject filtrate. Dissolve the precipitate in a very little dilute hydrochlorie acid, washing the filter with hot water and collecting the solution and washings in the original beaker.

Nearly neutralize the solution with amnionia or ammonium carbonate; dilute to 300 cc.; saturate with sulphur dioxide gas, and boil until titanie acid is precipitated and the solution smells faintly of sulphur dioxide.

Filter and wash with hot water and dilute sulphurous acid.

Dry, ignite, and weigh as titanic oxide.

Since the factor weight of sample has been used, one milligram of titanic oxide is equal to 0.1% metallic titanium.

¹ Methods of analysis used in the laboratories of the Titanium Alloy Manufacturing Company.

VOLUMETRIC METHODS

The Determination of Titanium by Reduction, Addition of Ferric Salt and Titration of Reduced Iron with Potassium Permanganate 1

Principle. Titanic acid is reduced by means of zinc, an excess of ferric sulphate is added and the ferrous salt, formed by reduction by titanous salt, is titrated with standard permanganate. The method is more accurate than direct titration of the titanous salt with permanganate.

Reaction. $Ti_2(SO_4)_3 + Fe_2(SO_4)_3 = 2Ti(SO_4)_2 + 2FeSO_4$, or $TiCl_3 + FeCl_3 = TiCl_4 + FeCl_3$.

Preparation of the Sample

Procedure. One to 2 grams of the ore is decomposed by hydrofluoric and sulphuric acids or by fusion with potassium bisulphate or a combination of the two according to the methods already described. Members of the H₂S group, if present, may be removed by H₂S. If iron is present it may be determined by boiling off the H₂S in the filtrate containing Fe, Ti, ctc., and allowance made in the titration for titanium. If other interfering elements are present in this filtrate, titanic acid may be precipitated by boiling the slightly acid solution (sulphurous acid) according to directions given in the gravimetric method. The washed oxide is dissolved in strong H₂SO₄ and diluted as directed below.

Reduction. The solution is washed into a 100-cc. flask and diluted with water so that it will contain 10% of sulphuric acid. This acid holds titanic acid in solution and at the same time is insufficient to oxidize the reduced titanium oxide. Sufficient zinc to cause complete reduction is added and a rubber stopper carrying a Bunsen valve tube and a thistle tube with glass stop-cock is inserted in the neck of the flask. The evolved hydrogen expels the air and reduces the titanic oxide to the titanous form. Iron if present is also reduced. Gentle heat is applied until the excess of zinc dissolves. The solution is cooled and an excess of ferric sulphate added through the thistle tube, followed immediately by cold distilled water until the flask is filled to the neck. The contents of the flask is poured into a No. 6 beaker containing 150 to 200 cc. of cold distilled water and the ferrous iron, formed by the reducing action of titanous salt, is titrated with N/10 KMnO₄ solution.

[&]quot; One cc. N/10 KMnO₄=0.00481 gram Ti, or 0.00801 gram TiO₂.

¹ H. D. Newton, A. J. Sc. (4), 25, 130. A. F. Gooch, "Methods in Chemical Analysis."

² T. R. Ball and G. McP. Smith, Jour. Am. Chem. Soc., 36, 1838, 1914.

The Determination of Titanium by Reduction with Zinc and Titration with Permanganate 1

In a contribution from the U. S. Bureau of Standards, the authors have reported a study of this method, the results of which indicate that:

The reduction of titanium in a Jones reductor proceeds rapidly and is quantitative, provided the reduced solution is caught under a 3-5-fold excess of ferric sulphate.

The reduction is conveniently carried on in solutions containing 3-5% by volume of sulphuric acid and may be done at any temperature between 25°

and 100°.

The determination is carried out as follows:

Using a Jones reductor of 19 mm. internal diameter, with zinc column 43 cm. in length, there is added in order 25-50 cc. dilute sulphuric acid, 3 to 5% by volume; 150 cc. of the titanium solution containing 3 to 5% by volume of sulphuric acid; 100 cc. more of acid and finally 100 cc. of water. The reduction is performed at a speed of about 100 cc. per minute.

The reduced solution is delivered through a tube from the reductor under and into a ferric sulphate solution containing about .02 g. of iron per ce. in 8% by volume sulpharic acid. The ferric sulphate solution should be from 3 to 5 times that theoretically required by the titanium. The reduced solution is titrated with tenth normal potassium permanganate.

The original article suggests means for separating tin, arsenic, antimony, molybdenum, iron, chronium, vanadium, tungsten and uranium, which would interfere with determination of titanium by the method described.

Volumetric Method by Reduction of Titanium and Titration with a Ferric Salt

The following volumetric method recommended by the Titanium Alloy Mfg. Co., is essentially that described by P. W. & E. B. Shimer, Proceedings of Eighth International Congress of Applied Chemistry, the method hereafter described differing principally in the form of reductor and also in a few details of operation.

Reagents. Standard ferric ammonium sulphate solution.

Dissolve 30 grams of ferric ammonium sulphate in 300 cc. water acidified with 10 cc. of sulphuric acid; add potassium permanganate drop by drop as long as the pink color disappears, to oxidize any ferrous to ferric iron; finally dilute the solution to 1 liter.

Standardize this solution in terms of iron. The iron value multiplied by 1.4329 gives the value in titanic oxide (TiO₂); and the iron value multiplied by 0.86046 gives the value of the solution in terms of metallic titanium.

Indicator. Saturated solution of potassium thiocyanate.

Reductor. As a reductor a 500-cc, dispensing burette is used. The internal dimensions of the burette are 1\frac{1}{8} by 22 ins.

The reductor is charged with 1200 grams of 20-mesh amalgamated zine, making a column about 12 ins. high and having an interstice volume of about 135 cc. This form of reductor is connveient, and when used as hereafter described

¹G. E. F. Lundell and H. B. Knowles, Jour. Amer. Chem. Soc., Vol. 45, No. 11, page 2620 (1923).

is adapted to maintaining hot solutions, which facilitates complete reduction of the titanium.

The reductor is connected to a liter flask for receiving the reduced titanium solution, through a three-hole rubber stopper which carries also an inlet tube for carbon dioxide supply, and outlet tube for connecting with the suction pump.

Procedure. Determination of Titanium in Ferro-Carbon Titanium. Onehalf gram of sample is dissolved in a 6-in, porcelain evaporating dish in a mixture of 10 ec. water, 10 cc. sulphuric acid, 5 cc. of hydrochloric acid, 5 cc. of nitric acid.

The solution is evaporated to fumes of sulphuric anhydride; taken up by boiling with 50 cc. water and 10 cc. of hydrochloric acid; filtered and washed with hot water and hydrochloric acid.

The filtrate and washings should be about 100 cc. in volume.

The reductor is prepared for use by first passing through it a little hot dilute sulphuric acid followed by hot water, finally leaving sufficient hot water in the reductor to fill to the upper level of the zinc.

The hot titanic solution prepared as described above is now introduced, about 100 cc. of water being drawn from the reductor into the original beaker to bring the solution to about the upper level of the zinc. The water thus removed will not contain any titanium if the operation has been conducted as described; but it serves as a safeguard and is also convenient to acidify this water with 10 cc. of sulphuric and reserve it on the hot plate to be used as an acid wash after the reduction of the sample solution.

The titanium solution is allowed to remain in the reductor for ten minutes. While the solution is being reduced the receiving flask is connected to the reductor and the air completely displaced by carbon dioxide, conveniently drawn from a cylinder of the liquefied gas.

When the reduction is complete the receiving flask is connected with the suction pump, and while still continuing the flow of carbon dioxide the reduced solution is drawn out, followed by the reserved acid wash and then three or four 100-cc. washes with hot water. The displacement of the sample solution and washing of the zinc is so regulated by means of the stop-coek that the reductor is always filled with solution or water to the upper level of the zinc.

When the washing is complete, gradually release the suction to prevent air

being drawn back into the receiving flask.

Disconnect the flask, add 5 ec. of potassium thiocyanate solution as indicator and titrate immediately with standard ferric ammonium sulphate solution, adding the solution rapidly until a brownish color is produced which will remain for at least one minute.

The method is also well adapted for determining titanium in other titanium products, suitable means being employed for bringing the titanium into sulphuric acid solution.

The brown color developed at the end point indicates that an excess of ferric ammouium sulphate has been added and the depth of color is roughly proportional to such excess. Ordinarily the excess ferric ammonium sulphate amounts to about .05 cc. which is deducted from the burctte reading before calculating the titanium, thus increasing the accuracy of the result. It is desirable for each operator to establish for himself, by running a few blanks, the proper amount to deduct from the burette reading as a correction.

Colorimetric Determination of Titanium with Hydrogen Peroxide

Preliminary Considerations. Hydrogen peroxide added to acid solutions of titanium produces a yellow to orange color, the depth of the color depending upon the amount of titanium present. Upon this fact the method is based. It is of especial value in determining small amounts of titanium, as it is possible to detect less than one part of the metal per hundred thousand parts of solution. Color comparisons can best be made on samples containing 0.05 to 5 milligrams of the element; larger amounts produce too deep a color for accurate comparison.

The following interferences should be made note of, e.g., molybdenum, vanadium and chronium also produce a color that would lead to error. Iron if present to the extent of 4% or over produces a color that must be allowed for; e.g., 0.1 gram Fe₂O₃ in 100 cc. of solution is equivalent to about 0.2 gm. of TiO₂ oxidized by H₂O₂ in 100 cc. of solution. Fluorides destroy the color, hence must be absent.¹ Phosphoric acid and alkali sulphates have a slight fading action, hence must be allowed for by adding equivalent amounts to the standard if they are present in the sample. The addition of an excess of sulphuric acid partly counteracts the action of phosphates or alkali sulphates.³ The color intensity is increased by increase of temperature, hence the standard and the sample

DIRECTIONS FOR THE USE OF A DUBOSCQ TYPE OF COLORIMETER

The mirror is turned so that the two balves of the field appear to be equally illuminated with the caps clean and caupty. The solutions are then poured into the cups. The cup containing the standard solution is then lowered to a definite thickness of the stundard solution between the hottom of the cup and the end of the plunger. With this movement the half of the field corresponding to the standard solution is seen to darken, while the other half remains luminous and colorless. If the cup containing the unknown solution is now moved in its turn, the two halves of the field are brought to the same intensity, after which the height at which the two liquid columns display this equal absorptive power is read by means of this scale. The proportion of coloring matter in two solutions is inversely proportional to the heights of the two columns necessary to obtain the same intensity of illumination, thus if the standard tube is set at 10 mm., and the solution under examination is the same intensity of color at 20 mm., the latter is just one-half the concentration of the standard. This is usually expressed by the formula:

Color of test solution + Color of stand, sol. = Height of stand, sol. + Height of sol, to be tested.

If, therefore, the scale reading is 20 mm, for the standard, and 15 mm, for the solution to be tested, the formula reads: $\S^2_0 = 1.33$.

M, for example, the standard solution contains 4 ml. of coloring matter in 100 ml., the solution under test will be found to contain $4 \times 1.33 = 5.32$ ml. in 100 ml.



By courtesy of Arthur H. Thomas Company, Philadelphia, Pa.

Fig. 68b.—Colorimeter.

¹ W. F. Hillebrand, J. A. C. S., 17, 718, 1895. C. N., 72, 158, 1895.

P. Faber, Zeit. an. Chemie, 46, 277, 1907.
 H. E. Merwin, A. J. S. (4), 28, 119, 1909.

examined should have the same temperature. Since metatitanic acid produces no color with hydrogen peroxide, its formation must be prevented; the presence of 5% of free H₂SO₄ accomplishes this.²

The procedure is very satisfactory for magnetic or other iron ores. It is fully as accurate as the best gravimetric method and very much more rapid.

Solutions Required. Standard Titanium Solution. This may be prepared by precipitations of TiO₂ from K₂TiF₄ according to the gravimetric procedure and purification by solution and reprecipitation, the fluorine being first removed by taking the compound to fumes with H₂SO₄ and then hydrolyzing titanium with NH₄OH. The washed precipitate is ignited over a Méker flame




Fig. 69.—Colorimeter.

for fifteen minutes, cooled in a desiccator and placed in tightly stoppered bottle, since TiO₂ is slightly hydroscopic.

0.5 gram of TiO₂ is fused with about twenty times its weight of KHSO₄ in a platinum dish, keeping at fusion heat until the oxide has dissolved. A high temperature is not advisable. The fusion is dissolved in 5% sulphuric acid by gently heating. The solution washed into a 500-cc. graduated flask is made up to volume with 5% H₂SO₄. One cc. contains 0.001 gram TiO₂, or 0.0006 gram Ti.

Hydrogen Peroxide. Thirty per cent solution. If this is not available sodium peroxide dissolved in dilute sulphuric acid will do.

Apparatus. Colorimeter—Fig. 69. Also see Fig. 43, page 283.

Preparation of the Sample. The solution of the sample having been obtained by one of the procedures given under Preparation and Solution of the Sample, the element may be determined according to the procedure given below. If interfering substances are present, e.g., comparatively large amounts of iron, or if tungsten, vanadium or chromium are present it will be necessary to precipitate titanic acid by adding ammonium hydroxide to the boiling solution as directed under the gravimetric determination of the element. The washed precipitate is dissolved in sulphuric acid.

Procedure. The sulphuric acid solution of titanium should contain 5% of free sulphuric acid. It is poured from the beaker in which solution was effected into a 100-cc. Nessler tube, 2 cc. of hydrogen peroxide, 30% solution are added and the volume made up to 100 cc. with 5% sulphuric acid. The *standard* is prepared by pouring 40 or 50 cc. of 5% sulphuric acid into a second 100-cc. Nessler tube, adding 2 cc. of 30% hydrogen peroxide, H_2O_4 , followed by sufficient

¹ Hillebrand.

² Dunnington, C. N., 64, 302; J. A. C. S., 12, 210, 1891.

standard titanium solution to exactly match the sample and the solution made up to 100 cc. with 5% sulphuric acid. The titanium solution is added from a burette, noting the exact volume required. From this the percentage of titanium in the sample can readily be calculated. If iron is present in the sample, an equivalent amount should be added to the standard. If a colorimeter is used, a standard should be prepared which is deeper in color than the sample examined. The standard is poured into the comparison cylinder and the two tubes compared. By raising or lowering the plunger (see illustration) the standard solution is forced in or drawn out of the comparison tube. When the colors match, the cc. in the comparison tube will indicate the amount of TiO, present in the sample. The solution may be mixed by stirring with a platinum spiral.

Example. One-gram sample required 20 cc. of titanium standard solution, 1 cc. of which contained 0.001 gram TiO2. Then the sample contains

$$\frac{0.001\times20\times100}{1} = 2\% \text{ TiO}_2.$$

If the colorimeter has been used and 150 cc. of standard made by adding 30 cc. of standard titanium solution and it is found that the column of liquor in the standard comparison tube stands at 85 cc., the calculation would be as follows: 150 cc. contains 30×0.001 gram TiO2, therefore 85 cc. are equivalent 85×0.03

to
$$\frac{85 \times 0.03}{150}$$
 = 0.017 gram TiO₂ per gram or 1.7%.

For the practical application of the colorimetric method in determining titanium in steel the following procedure is given.

Note. Separation of Titanium from Iron. J. H. Walton, Jr. 1 separates titanium from iron by fusing the finely powdered substance with three or four times as much sodium peroxide, and extracts the fusion with water. The filtrate contains the sodium pertianate whereas the iron oxide remains on the filter paper. The filtrate is acidified with H₂SO₄ until 5% of free acid is obtained and the color of this solution compared with a standard obtained by fusing a known weight of TiO₂ with Na₂O₂ and extracting and treating with H2SO4 as in case of the sample.

Colorimetric Determination of Titanium in Steel Treated with Ferro-carbon Titanium²

The titanium in steel treated with ferro-carbon titanium exists in two conditions:

- (1) Titanium insoluble in hydrochloric acid.
- (2) Titanium soluble in hydrochloric acid.

Of the very small amount of titanium in treated steel the greater part will usually be found in the first form, and ordinarily the determination of titanium in this form answers every purpose of identifying and judging the quality of titanium-treated steel.

When the amount of titanium in the steel is exceedingly small, the soluble titanium frequently exceeds the insoluble and it then is sometimes desirable to determine also that existing in the second form.

¹ J. Am. Chem. Soc., 29, 481, 1907. ² By L. E. Barton. Method of analysis recommended by the Titanium Alloy Manufacturing Company.


Reagents. Peroxide Solution. Dissolve 4 grams of sodium peroxide in 125 cc. dilute sulphuric acid (1 of acid to 3 of water), and dilute to 500 cc.

Concentrated Standard Titanium Solution. Stock Solution. One-fourth gram of a standard 20% carbonless ferro-titanium is dissolved in 30 cc. dilute sulphuric acid (1 acid to 3 water). When solution is complete it is oxidized by the least possible quantity of concentrated nitric acid, boiled for a few minutes, cooled and diluted to such a volume that 1 cc. will contain 0.0005 gram of titanium.

When using a 5-grain sample 1 cc. is therefore equal to 0.01% titanium.

Dilute Standard Titanium Solution. This solution is made, just before making the determination, by diluting one volume of the concentrated standard titanium solution to ten volumes.

One cc. of this solution contains 0.00005 gram of titanium and is equal to 0.001% of titanium when using a 5-gram sample.



Fra. 70.

Apparatus. Pipettes and Burettes. The pipettes for measuring the concentrated standard solution and burette for delivering the dilute standard solution should be carefully calibrated.

Nessler Jars. These should be graduated with 50-cc. mark. It is convenient to have a set of four.

Colorimeter. The colorimeter or comparator consists of a rectangular block 2½ by 4 by 7 ins. high—the height being about ¾ in. less than the height of Nessler jars—through which two chambers 1¾ ins. diameter and 1¾ ins. between centers are bored lengthwise—the chambers being of such diameter as to just receive the jars.

To one end of the block is fastened the base, which is in. thick and through which two 4-in. holes are bored concentric with the chambers, thus forming a shoulder which supports the jars and also exclude light from the sides of the tubes. To prevent shadows and give better lighting the holes in the base are beveled outward at an

angle of 45°. The construction will be apparent by reference to Fig. 70. The interior of the chamber is painted dead black.

(a) For Determination of Titanium Insoluble in Hydrochloric Acid

Procedure. Dissolve 5 grams of steel in 100 cc. of dilute hydrochloric acid (one of concentrated acid to two of water) by boiling gently. Wash off the cover and wash down the sides of the beaker with water and filter out the slight insoluble residue, washing with hot water and dilute hydrochloric acid until free from iron. For filtration it is advisable to use either a close-grained paper or double rapid-filtering papers such as S. & S. No. 589 white ribbon.

Ignite the residue gently in a platinum crucible to burn off carbonaceous matter. Treat the residue in the crucible with a mixture of 3 cc. dilute sulphuric acid (1:1), 2 or 3 cc. hydrofluoric acid, and a few drops of nitric acid.

¹ Ferro-titanium suitable for the preparation of standard titanium solutions is made and supplied by the Titanium Alloy Manufacturing Company, Niagara Falls, N. Y.

Heat and evaporate to fumes of sulphurie anhydride to complete expulsion of hydrofluoric acid.

Cool, add a few ee. of water and heat until the solution is perfectly clear. The ignited residue may also be rapidly and completely brought into solution by fusion with about 3 grams of potassium bisulphate and dissolving the fusion in water and sulphuric acid.

In either ease wash the contents of the crucible into one of a pair of Nessler jars and dilute with cold water nearly to the 50-cc. mark, and in the other jar place an equal volume of distilled water.

Place the jars in the colorimeter and observe if the sample solution is colorless. If the sample solution is colored slightly yellow by iron, the water in the standard tube should be brought to the same color by addition of a few drops of a ferric solution. For this purpose a solution of ferric ammonium sulphate, 30 grams per liter, is very convenient.

If the work up to this point has been carefully performed, the addition of ferric solution will usually be unnecessary; and if more than a few drops of ferric solution are required the analysis should be rejected and a new sample started. After adjusting the color—if necessary—bring the volume of solution in both jars to the 50-cc. mark.

The volumes now being equal and the solutions practically colorless, add 2 ee. of the peroxide solution to each. If the sample contains titanium even in minute quantity it will be indicated by the immediate development of a yellow color.

Match the colors by running into the standard jar freshly prepared dilute standard titanium solution, keeping the volumes equal by adding an equal quantity of water to the sample, placing the jars in the colorimeter for comparison of colors,

As before stated, each cc. of the dilute standard solution is equal to 0.001% titanium when using a 5-gram sample.

The determination may be made in less than an hour and requires little attention.

(b) For Determination of Titanium Soluble in Hydrochloric Acid

For the determination of soluble titanium the filtrate from the insoluble titanium residue obtained as before described may conveniently be used.

Dilute the solution in which the iron is already in the ferrous state to 180 ee. Add 10 ce. of alum solution made by dissolving 40 grams of crystallized alum in a liter of water.

The aluminum here added is subsequently precipitated as alumina with the titanium and serves to collect quickly the exceedingly small precipitate of titanium hydroxide and facilitate its separation from the solution by filtration.

Heat the solution to about 90° C. and add ammonia or ammonium carbonate solution, stirring constantly until a slight permanent precipitate is produced. Add dilute hydrochloric acid (1 to 1) drop by drop from the wash bottle until the precipitate is just redissolved and the solution perfectly clear; then add 1 cc. more of the dilute hydrochloric acid.

Add 3 ce. of phenylhydrazine dissolved in 10 cc. hot water, which will precipitate the titanium and aluminum. Stir thoroughly and filter immediately

on a 7-cm. filter paper in a Büchner funnel, using suction. Wash thoroughly with hot water.

Calcine the precipitate gently in a platinum crucible to destroy organic matter and dissolve the residue exactly as described under (a), except that 6 cc.

of dilute sulphuric acid is used instead of 3 cc.

The solution, which has a very light yellow, or greenish-yellow color, is transferred to one of a pair of Nessler jars and diluted to the 50-cc. mark. About 40 cc. of water are placed in the other jar and the color of the sample solution exactly matched by addition of ferric ammonium sulphate and copper sulphate solutions, which are conveniently delivered from burettes.

For matching the original color of the solution nearly saturated solutions

of ferric ammonium sulphate and copper sulphate are suitable.

Only a few drops of such solutions are required, but it is frequently necessary to use both blue and yellow to match the greenish-yellow tone of the sample solution.

The standard is finally diluted to the 50-cc. mark. The volumes now being equal and identical in color, add to each 2 cc. peroxide solution to develop the titanium color and finish the determination as before described under (a).

(c) For Determination of Total Titanium

The total titanium is given by the sum of the insoluble and soluble titanium determined as under (a) and (b); but if desired may be determined in one operation.

To determine total titanium, dissolve as before in hydrochloric acid and without filtering proceed as directed under (b) for determination of soluble

titanium.

Determination of Titanium when Interfering Elements are Present

If chromium, vanadium or molybdenum is present in the steel, fuse the residue insoluble in hydrochloric acid or the calcined phenylhydrazine precipitate containing the interfering element with a mixture of sodium carbonate and a little sodium nitrate.

Dissolve the fusion in water and filter. The residue on the filter will contain the titanium, free from interfering element. Bring the residue into sulphuric acid solution by methods before described and determine the titanium as usual.

Colorimetric Determination of Titanium with Thymol 1

Principal and Preliminary Considerations. Titanium dioxide dissolved in sulphuric acid is colored red by addition of thymol, the depth of color being directly proportional to the amount of titanium present. The intensity of the color is claimed by Lenher and Crawford to be twenty-five times that produced by hydrogen peroxide with the same amount of titanium.

∴ As in case of hydrogen peroxide, fluorides destroy the color, hence must be absent. Dilution with water has no effect until the concentration of sulphuric acid falls below 79.4 (e.g., sp.gr. 1.725). The color then fades in direct propor-

¹ Victor Lenher and W. G. Crawford, C. N., 107, 152, March 28th, 1913.

tion to dilution. Warm solutions are lighter in color than cold solutions with the same amount of titanium, hence the standard and the sample compared must have the same temperature. The color fades on heating but returns on cooling. The temperature should be kept below 100° C. Chlorides, phosphates and tin scem to have no effect. Tungsten, WoO_s, interferes, as it intensifies the color of the solution in direct proportion to the amount present; hence it must be removed or allowance made by adding an equivalent amount to the standard or subtracting the equivalent blank.

Special Reagents. Thymol Solution 1%. The thymol is dissolved in a little glacial acetic acid containing 10% ethyl alcohol, and this solution added to concentrated sulphuric acid. Addition of the thymol directly to the acid would produce a colored solution. The reagent should be kept protected from strong light, otherwise it will become colored.

Apparatus. See Colorimetric Determination of Titanium with Hydrogen Peroxide, Figs. 69, 70, also Fig. 43.

Procedure. About 0.3 gram of the material is fused with potassium acid sulphate, KHSO₄, and the melt dissolved in concentrated sulphuric acid. Enough thymol reagent is added so that there is present at least 0.006 gram thymol for every 0.0001 gram TiO₂. Concentrated sulphuric acid is added to bring up the volume to 50 or 100 cc. in a Nessler tube exactly as in the case of the colorimetric determination of titanium with H₂O₂. The depth of color is compared with a standard solution of titanium dissolved in a concentrated sulphuric acid added to 5 cc. of thymol solution made up to a convenient volume with concentrated sulphuric acid. The procedure is the same as described in the H₂O₂ method.

THE ANALYSIS OF TITANIFEROUS ORES 1

Determination of Titanium

Decompose the ore by fusion with potassium bisulphate, dissolving the fusion in water, hydrochloric and sulphuric acids. If an insoluble residue remains, filter it out. Calcine the residue, add a few drops of sulphuric acid and sufficient hydrofluoric acid to dissolve siliea, evaporate to fumes of sulphuric anhydride and then heat to redness.

If a residue now remains, bring it into solution directly in acids or fuse with a little potassium bisulphate, etc., finally adding the solution to the main solution obtained as before described.

If desired, the sample of ore can first be partially dissolved in hydrochloric and sulphuric acids, and the insoluble residue then fused with potassium bisulphate or treated with sulphuric and hydrofluoric acids.

Some ores may be completely decomposed by a mixture of nitric, hydro-fluoric and sulphuric acids, evaporating to fumes of sulphuric anhydride in a platinum dish to free the solution from nitric and hydrofluoric acids.

The complete decomposition of the sample having been accomplished, the titanium in the solution is determined by either the gravimetric or volumetric methods for Determination of Titanium in Ferro-Carbon Titanium. Pages 542 and 547.

¹ Method of Analysis used in the laboratories of The Titanium Alloy Manufacturing Company.

Determination of Iron in Presence of Titanium

The sample is decomposed as directed under the Determination of Titanium. The sulphuric acid solution, which should have a volume of 150 to 200 ec., is saturated with hydrogen sulphide gas to reduce the iron, and filtered to separate any precipitated sulphides and free sulphur. The filtrate is collected in a flask fitted with a rubber stopper through which pass two glass tubes, one reaching nearly to the bottom for conducting gas into the solution, the other a short exit tube. Unless the solution after filtration is still highly charged with hydrogen sulphide, more gas should be passed into the solution to reduce any iron that may have been oxidized by the atmosphere during filtration. The excess hydrogen sulphide is now expelled by boiling the solution while passing a current of carbon dioxide.

When the exit gases cease to darken a piece of filter paper moistened with lead acetate solution, the flask is cooled while still passing the carbon dioxide. When the flask has partially ecoled the carbon dioxide is shut off and the flask quickly cooled in running water and immediately titrated with standard permanganate solution.

Determination of Silica

This determination is conveniently combined with the determination of iron the ore being preferably decomposed by fusion with potassium bisulphate. The fusion is dissolved and evaporated with excess sulphuric acid to fumes of sulphuric anhydride and the silica determination finished as usual—weighing, volatilizing with hydrofluoric acid, etc. If the ore contains quartz or a silicate undecomposable by treatment with potassium bisulphate and hydrofluoric acid, the residue filtered from the sulphuric acid solution should be fused with sodium carbonate and the silica then determined as usual.

Determination of Alumina

After making determination or separation of titanium by gravimetric method use the filtrate for determination of alumina.

Phenylhydrazine Method for Determination of Aluminum in Presence of Iron

The iron and aluminum should be in hydrochlorie or sulphuric acid solution. Nearly neutralize the solution with ammonium carbonate. Pass sulphurous acid gas to complete reduction of the iron. Boil until the excess sulphurous acid is driven off and if titanic acid separates filter it out.

After filtering out titanic acid again nearly neutralize with ammonium carbonate, pass a little sulphurous acid gas and heat for a few minutes to reduce any iron that might have been oxidized during filtration. If titanium has not been detected the second treatment with sulphurous acid may be omitted. In either case the solution still containing a little free sulphurous acid is nearly neutralized with ammonium carbonate, diluted to 300 cc. and 3 ec. of phenol-hydrazine added. Stir thoroughly, let settle and filter out the alumina. If the precipitate is discolored by iron, dissolve in hydrochloric acid, and repeat the reduction, neutralization and precipitation by phenylhydrazine. Ignite and

weigh $Al_2O_3+P_2O_5$. Since the alumina precipitate may be contaminated by phosphorie anhydride (P_2O_5), determine it by analysis and correct the alumina determination accordingly.

Determination of Phosphorus

Phosphoric acid may be separated from titanic acid by repeatedly fusing the ore with alkali carbonate and extraction of alkali phosphate with water.

The determinations of other constituents of the ore are conducted by the usual methods of ore analysis.

ANALYSIS OF MIXED PIGMENTS CONTAINING TITANIC OXIDE

Weigh one gram sample into a 400-cc. Pyrex glass beaker, add 10 grams sodium sulphate and 40 cc. concentrated sulphuric acid (93%). Heat on hot plate for one-half hour and then increase the heat, as by placing the beaker directly over the coils of an electric hot plate and boiling for about 10 minutes. The solution should acquire a temperature of about 335° C.

Cool, dilute the solution to 300 cc., boil 20 minutes, filter while hot and wash residue and precipitate with 5% sulphuric acid. On the filter will be silica and undecomposed silicates and all the lead and barium as sulphates. This residue and precipitates can be analyzed by well-known methods if desired. The filtrate will contain the titanium, iron, aluminum, zine and calcium.

To the filtrate while still hot add an excess of ammonia, filter and wash precipitate with hot water. Re-dissolve precipitate in hydrochloric acid (1 to 1) and again precipitate with ammonia. Filter and wash with hot water, combining filtrate with that from first separation. By this procedure the titanium, iron and aluminum will have been separated from the zine and calcium. The use of an excess of ammonia as described would tend to carry a little aluminum into solution but in the presence of titanium and iron substantially all the aluminum will be found in the precipitate. If desired, the filtrate can be tested for presence of aluminum and then used for determination of calcium and zine.

The precipitate of titanium, iron and aluminum hydroxide is again redissolved in dilute hydrochloric acid and the titanium separated and determined as before described and with all precautions given under the head of "Gravimetric Method for the Determination of Titanic Oxide."

The filtrate after separation of the titunium can be used for determination of iron and aluminum if desired.

In ease it is not desired to determine iron and aluminum separately, the hydroxides obtained after second separation by ammonia can be calcined and weighed as total oxides of titanium, iron and aluminum. The titanium can be determined by the volumetric method before given and deducted from total oxides thus giving the iron and aluminum together by difference.



TUNGSTEN, TANTALUM AND COLUMBIUM¹

TUNGSTEN

W., at.wt. 184.0; sp.gr. 18.77; m.p. 3000° C.; oxides, WO₁ (brown); WO₂ (yellow); acids, H₂WO₄, ortho tungstic; H₂W₄O₁₃, meta tungstic

DETECTION

Minerals. The finely powdered material is decomposed by treating with mixed acids according to the procedure given on page 560. Tungsten is precipitated with einchonine, the precipitate filtered off and dissolved in ammonium hydroxide, then acidified with hydrochloric acid and reprecipitated with cinchonine as described.

Tungsten oxide may be confirmed as follows:

- 1. The residue is suspended in dilute hydrochloric acid and a piece of zinc, aluminum, or tin placed in the solution. In the presence of tungsten a blue-colored solution or precipitate is seen, the color disappearing upon dilution with water.
- 2. A portion of the precipitate is warmed with ammonium hydroxide and the extracts absorbed with strips of filter paper.
- (a) A strip of this treated paper is moistened with dilute hydrochloric acid and warmed. In the presence of tungstie acid a yellow coloration is produced.
- (b) A second strip of paper is moistened with a solution of stannous chloride. A blue color is produced in the presence of tungsten.

(c) A third strip dipped into cold ammonium sulphide remains unchanged until warmed, when the paper turns green or blue if tungsten is present.

Iron, Steel and Alloys. These decomposed with strong hydrochloric acid followed by nitrie acid as directed under Solution of the Sample leave a yellow residue in the presence of tungsten. If this residue is digested with warm ammonium hydroxide and the extract evaporated to dryness a yellow compound, WO₃, will remain if tungsten is present. This oxide may be reduced in the reducing flame to the blue-colored oxide.

¹ Columbium is also known as Niobium.

Chapter by Wilfred W. Scott, A. M. Smoot and J. A. Holladay,

ESTIMATION

Tungsten occurs principally as wolfram, a tungstate of iron and manganese (FeWO₄·MnO₄), as scheelite, a tungstate of calcium (CaWO₄), as ferberite, FeOWO₃ and hubernite, MnO·WO₃. The best concentrate of hand-picked material contains 70 to 74% tungsten in terms of its oxide, WO₃.

The element is met with in alloys—ferro-tungsten, silico-tungsten, tungsten steels containing as much as 10 to 20% of the metal, used for making high-speed, self-hardening cutting tools; tungsten powder; lakali tungstates for mordanting purposes; tungstic oxide, WO₃; tungsten electric light filaments, etc.

Solution of the Sample

For solution of the sample the following facts should be kept in mind regarding solubilities.

The metal is practically insoluble in HCl and in H₂SO₄. It is slowly attacked by HNO₃, aqua regia and by alkalies. It is readily soluble in a mixture of HNO₃ and HF (=WF₄ or WOF₄).

Oxides. WO₂ is soluble in hot IICl and in hot H₂SO₄ (=red sol.), also in KOH (red sol.). The oxide WO₃ is scarcely soluble in acids, but is readily soluble in KOH, K₂CO₃, NH₄OH, (NH₄)₂CO₃, (NH₄)₂S₂. Both the acid and the alkali solutions deposit the blue oxide on standing.

Acids. Ortho tungstates. A few are soluble in water and in acids. The alkali salts only slightly soluble. The meta tungstates are easily soluble in water. Tungstates are precipitated from alkali salts by dilute H₂SO₄, HCl, HNO₃, H₂PO₄ (aqua) as yellow WO₃·H₂O or white WO₃·2H₂O. Meta tungstates are not precipitated by cold acids, but are precipitated by boiling and by long standing.

Solution of Minerals. The material is best decomposed by acid treatment as described on page 560. Use of a fusion as a means of decomposition of tungsten ores preliminary to either the qualitative detection or the quantitative determination of tungsten cannot be recommended. The precipitation of tungsten by boiling with acids in presence of considerable amounts of alkali salts (such as result from acidification of a fusion) is absolutely worthless inasmuch as large amounts of tungsten always remain in solution. Repeated evaporations do not improve matters. In fact, when the amount of tungsten present is small, and especially if the ore contains much phosphorus, there is small likelihood that any of the tungsten will be precipitated. The use of cinchonine is necessary in order completely to precipitate tungsten under these conditions.

TYPICAL ANALYSES

W, 97 to 98.7 71 to 85.5 Fe, .5 to .6+ 14 to 24.5 C, .1 to .3+ .4 to 2.6 Si, .3 to .7+ .1 to .4	EN POWDER	FERRO TUNGSTEN
Fe, .5 to .6+ .4 to 24.5 C, .1 to .3+ .4 to 2.6 Si, .3 to .7+ .1 to .4	0%	%
Fe, .5 to .6+ C, .1 to .3+ Si, .3 to .7+ 14 to 24.5 .4 to 2.6 .1 to .4	7 to 98.7	
Si, .3 to .7+	5 to .6+	
DI, .0 t0 .7 T	1 to .3+	
		.08 to .9+
P, —		
Al, .2 to .5 .001 to .07 0 to .008	2 to .5	
Cu, — — — 0 to .3+		0.00

SEPARATIONS

Separation of Tungsten from Silica. The oxide of tungsten, as ordinarily obtained, is frequently contaminated with silica. The removal of silica is accomplished by heating the mixture in a platinum dish with sulphuric and hydrofluoric acids and volatilizing the silica. After taking to dryness and igniting gently, the last traces of sulphuric acid are expelled by adding ammonium carbonate and again igniting.

In presence of small amounts of silica (0.1 to 0.2%) and large amounts of tungsten (75 to 85%) J. A. Holladay recommends evaporation with sulphuric and phosphoric acids, filtration to remove the bulk of the tungsten, and subsequent ignition and voltailization with sulphuric and hydrofluoric acids.

Separation from Tin. The weighed residue is mixed with six to eight times its weight of animonium chloride (free from non-volatile residue) in a platinum crucible, placed in a larger crucible, both vessels being covered. Heat is applied until no more vapors of ammonium chloride are evolved. Additional ammonium chloride is added and the treatment is repeated three times. The fourth treatment is followed by weighing of the residue and the treatment repeated once more. If no further loss of weight takes place it is assumed that all the stannic oxide has been driven off. The inner crucible is now placed directly over the flame and heated to dull redness for a few minutes and the oxide, WO₅, weighed.

Separation of Tungsten from Tin and Antimony. Talbot's Process.¹ The mixed oxides are fused with twelve times their weight of potassium cyanide in a porcelain crucible. Tin and antimony are thrown out as metals and the soluble alkali tungstate formed. This is leached out with water and the aqueous extract boiled (hood) with an excess of nitric acid to drive off the cyanogen compounds. The tungstate is then precipitated by the usual methods. If phosphorus is present in the sample it will be found in the solution with tungsten and its removal will be necessary.

Separation of Tungsten from Arsenic and Phosphorus. Both arsenic and phosphorus may be precipitated by cold magnesia mixture in an ammoniacal solution, tungsten remaining in solution. The separation of arsenic is difficult, as it is tenaciously retained by tungsten as a complex salt. The following process is outlined by Kehrmann.²

One to 2 grams of the sample are fused with twice as much sodium hydroxide as is required to combine with the arsenic oxide, the resulting cake is dissolved in a little water and boiled in an Erlenmeyer flask for half an hour. After cooling, three times as much ammonium chloride as is needed to form chlorides with the alkalies present is added, and then ammonium hydroxide equal to one-fourth the volume of the solution under investigation, followed by sufficient magnesia mixture, added cold, drop by drop with constant stirring. After settling several hours, the solution is filtered and the residue washed with a weak solution of ammonia and ammonium nitrate. It is advisable to dissolve the residue in dilute acid and repeat the precipitation several times. The filtrates containing the tungsten are combined and concentrated by evaporation if necessary.

¹ J. A. Talbot, J. Sci. (2), **50**, 244, 1870. ³ F. Kehrmann, Ber., **20**, 1813, 1887.

Separation of Tungsten from Molybdenum, Hommel's Process. The moist oxides of tungsten and molybdenum are digested with concentrated sulphuric acid and a few drops of dilute nitric acid, in a porcelain dish over a free flame for about half an hour. About three times its volume of water is added to the eooled solution, the residue, WO3, filtered off and washed with dilute sulphuric acid (1:20) followed by three washings with alcohol. The residue is ignited separately from the paper and weighed with the ash of paper as WO₃.

Molybdenum is in the filtrate and may be precipitated in a pressure flask with H.S.

Volatilization of Molybdenum with Dry Hydrochloric Acid Gas. Pechard's Process.1 The procedure depends upon the fact that molybdenum oxide heated in a current of dry hydrochloric acid gas at 250 to 270° C. is sublimed, whereas tungsten is not affected.

The oxides of the two elements, or their sodium salts, are placed in a porcelain boat and heated in a hard glass tube, one end of which is bent vertically downward and connected with a Péligot tube containing a little water. A current of dry hydrochloric acid gas is conducted over the material, heated to 250 to 270° C. From time to time the sublimate of molybdenum (MoO₂·2HCl) is driven towards the Féligot tube by careful heating with a free flame. This enables the analyst to observe whether any more sublimate is driven out of the sample and to ascertain when the tungsten is freed of molybdenum. From one and a half to two hours are generally sufficient to accomplish the separation. If sodium salt is present it is leached out of the residue, and this is then ignited to WO₃. Molybdenum may be determined in the sublimate.

Separation from Vanadium. Tungstie and vanadic acids are precipitated with HgNO, and HgO, the moist precipitate dissolved in HCl and the solution largely diluted; WO, is precipitated free from vanadium.

Separation from Titanium. The material is heated with K2CO, and KNO, tungsten is dissolved out with water and precipitated as mercurous tungstate.

Separation of Tungsten from Iron. The procedure is given under Solution of the Sample, of Steel and Alloys. The impure oxide WO, is fused with Na₂CO₃ and the mclt extracted with water. Fe(OH), remains on the filter. The filtrate is evaporated to dryness with HNO, and the residue extracted with water. The insoluble WO, is washed with dilute NH,NO, solution, then dissolved in NH4OH and tungsten determined in the solution.

Separation of Tungsten from Uranium.4 The sample is evaporated with nitric acid to near dryness, 5 cc. HNO₃ is added and the uranium is dissolved out by extraction with ether.

```
    E. Peehard, Comp. Rend., 114, 173, 1891.
    Friedheim, C. N., 61, 220.
    Defacqz, C. N., 74, 293.
```

⁴C. A. Pierlé, Jour. Ind. Eng. Chem., 12, 61-63, 1920.

GRAVIMETRIC PROCEDURES FOR DETERMINING TUNGSTEN

Since there is no highly commendable volumetric procedure for determining

tungsten, the gravimetrie methods are preferred.

The element is determined as tungstie oxide, WO₃. It may be isolated preferably by precipitation with einchonine, or in the form of tungstie acid, ammonium tungstate, or as mereurous tungstate, in the usual course of analysis, all of which forms may be readily changed by ignition to the relatively non-volatile oxide, WO₃.

Gravimetric Determination of Tungsten in Steel and Alloys

Tungsten alloys may be decomposed by hydrochlorie (or sulphurie) and nitric acids. Tungsten precipitates, earrying down chromium and a little iron. The bulk of the iron is filtered off and tungsten determined in the residue, by direct or difference methods.

Special Rea gent. Cinchonine Solution. 100 grams of the alkaloid dissolved in dilute (1:3) HCl and made to 1000 ee. with the dilute acid. Wash Solution. 30 ec. of the above solution, with 30 ee. strong HCl diluted to 1000 ee.

Procedure

1. Decomposition of the Sample. Two grams of high tungsten alloys or 5 grams of alloys low in tungsten are dissolved in a 350-ee. beaker by addition of 20 cc. strong HCl, the beaker being placed over an asbestos mat on a hot plate or steam bath. (The temperature should be below the boiling point of HCl, since the acid should remain strong to effect decomposition.) Since the reaction is energetic the beaker is covered by a watch glass. Ten cc. of strong nitric acid are added, pouring small portions at a time through the lip of the beaker. The sample is digested until all the black particles have dissolved and only the fine greenish yellow tungstie oxide is evident. Agitation of the liquor to prevent caking assists the reaction.

2. When the sample is decomposed, the beaker is uncovered and the solution evaporated rapidly to about 20 ee. and then eautiously at low heat to about 5-10 cc. 5 cc. of HCl are added to the moist residue and the solution diluted to about 50 cc. and heated to boiling 2-3 cc. of einehonine reagent are added. Avoid taking to dryness and baking as this will make the tungsten difficult to

dissolve in NH₄OH. See step 4.

3. The mixture is filtered and the ferrie ehloride washed out from the tungstic residue with dilute HCl (1:10), i.e., until the wash solution passes through the filter colorless. The filtrate is tested for tungsten by addition of more cinchonine. (See step 7.) As small amounts of tungsten come down slowly at least an hour should be given for the test.

4. A clean beaker is placed under the filter and tungsten dissolved out from the impure residue by treating this with warm ammonia water (1:5), the filter being half filled with each washing and thoroughly drained. It is advisable to rinse out the beaker in which the decomposition was made, with warm ammonia solution and pour this on the filter. After five washings the filter is cautiously removed and spread out on a watch glass. The residue is washed into a beaker with a stream of ammonia water and digested with about 20-30 ec. of ammonia for about 5 minutes warming to near boiling. The solution is poured through a

fresh filter into the main extract, the filter is drained and then washed twice more with warm ammonia solution (1:5). All the tungsten should now be in the filtrate. If much residue remains as in case of high silica samples, tungsten is apt to be present. This is recovered by acid sulphate fusion. See Notes.

5. The filtrate is boiled to expel the ammonia. When the odor has become faint, HCl is added until the solution is just acid and about 3 cc. excess is added. The total volume will be 75-100 cc., after boiling. Acidification may eause some tungsten to precipitate, but this does no harm. The ammonia is generally expelled by boiling the filtrate down to half its original volume.

6. 10 ee. of einehonine reagent are added to the hot solution and the mixture stirred and allowed to settle until cold. If the supernatant solution is cloudy stirring up the precipitate and allowing it to settle will clear the solution. It is well to test the clear liquor with a few drops more of the reagent to ascertain whether all of the tungsten has precipitated.

7. The solution is filtered and the tungsten residue washed three or four times with dilute cinchonine reagent (washing down from the rim of the filter), and once with 5-10 ec. of water.

NOTE. The filtrate from step 3 may contain some tungsten. If the filtrate treated with einehonine has become cloudy on standing it must be filtered, the residue washed with einehonine reagent as in the procedure above and the filter and residue added to that containing the bulk of the tungsten.

8. The filter (or filters) is ignited in a weighed crucible to destroy the carbon, then cooled and weighed as WO_3 .

$$WO_3 \times 0.7931 = W$$

Note. The oxide WO₃ fused with KHSO₄ and the cooled melt extracted with ammonium carbonate reagent should give a clear solution. If the solution is cloudy SiO₂ is indicated. This should be filtered off, ignited and its weight subtracted from the WO₃ obtained above. See optional method below. The KHSO₄ fusion may be made in a porcelain or platinum crucible.

Optional Method

The impure residue obtained in step 3 of the first procedure is ignited and weighed. The residue is now fused with acid potassium sulphate, KHSO₄ (5-6 grams of salt). The heating is continued until efferveseence ceases and the mass changes to a clear solution. The fusion is cooled by rotating the crucible so that the mass is spread in a layer over the sides. It is now dissolved by placing in about 100 cc. of ammonium carbonate solution (10% sol.) and heating to boiling. Iron, chromium and silica will remain insoluble, tungsten will be in solution. The liquor is filtered and washed 4 or 5 times with water containing a little (NH₄)₂CO₃. The residue is ignited, cooled and weighed. The difference of this weight and that of the impure residue is due to the WO₂.

Note. If the earbonate extract is boiled, acidified and cinehonine reagent added tungsten will precipitate as the cinehonine compound. See Notes.

Notes

The use of sulphuric acid in place of hydrochloric acid in the decomposition of the sample offers no advantages as to speed of decomposition. On the

other hand with sulphuric acid treatment tungsten is invariably found in the filtrate (step 3) while with the HCl method it is seldom found in appreciable amounts.

Hydrofluoric acid assists in the decomposition of alloys high in silicon. A large excess must be avoided as this would attack the glass of the beaker with liberation of silicic acid, and fluosilicic acid. With large amount of HF a platinum dish should be used.

WO₂ does not dissolve readily in ammonia after it has been ignited. The moist residue of tungsten precipitated by acids is easily soluble in ammonia. If an appreciable amount of residue remains from the ammonia extraction, it is fused with KHSO₄, extracted with a 10% solution of (NH₄)₂CO₃, the CO₂ expelled by boiling and the ammoniacal solution filtered from siliea, vanadium, iron, etc., and the tungsten precipitated and determined according to the procedure outlined in steps 5 to 8 inclusive.

SiO₂ is but slightly soluble in dilute ammonia solution. The silica dissolved by 100 ee., 1:1 NH₄OH in a 30 hour treatment on a 47% SiO₂ ore amounted to less than 0.005 g. on a gram sample. With a 30 minute treatment the amount was inappreciable. In case of doubt treat the WO₃ with HF in a platinum crucible and again ignite after expelling the acid by evaporation.

THE ANALYSIS OF TUNGSTEN ORES, CONCENTRATES AND METALLIC PRODUCTS¹

General Considerations

Commercial tungsten minerals are marketed usually in the form of concentrates derived from treatment of lean ores by water concentration, or, sometimes, as specially selected high grade ore which has not been subjected to dressing operations other than hand sorting.

The important commercial minerals are Wolframite—iron-manganese tungstate; Hubnerite—manganese tungstate; Ferberite—iron tungstate; Scheelite—calcium tungstate. The first three grade into each other imperceptibly; commercially, they are all classed as Wolframite although the predominant mineral may, in some cases, be either manganese tungstate or iron tungstate. The determinations usually required are tungstic oxide, manganese, tin, phosphorus, sulphur, copper and arsenic sometimes molybdenum, which occurs more or less frequently in Scheelite, and occasionally bismuth and lead.

The principal minerals associated with tungsten concentrates are pyrite, arsenopyrites, cassiterite, magnetite, columbite, and always more or less quartz and silicates. Scheelite sometimes is associated with baryte.

The following analytical methods have been in practical use for a long time; they have been modified from time to time as experience showed necessary. Many suggestions from Works' chemists and others have been adopted. The descriptions are given in detail where this has been thought to be necessary because much depends upon minor points and upon the experience gained in making many hundreds of determinations.

Methods for the analysis of tungsten powders and ferro-tungsten are also given, since these are the raw materials of manufacturers of special steels.

Gravimetric Determination of Tungsten in Ores and Concentrates

Special Reagents

Cinchonine Solution. Cinchonine solution is made by dissolving 100 grams of the alkaloid in dilute HCl (1 part acid to 3 of water) and diluting to 1000 cc. with HCl of the same strength.

Cinchonine Wash Solution. 30 cc. Cinchonine solution, 30 ec. strong HCl to 1000 cc. of water.

Preparation of the Sample

Ores should be ground in agate to pass a 200-mesh screen; double screening is recommended to insure perfect fineness.

Weigh one gram into a 350 cc. beaker, add 5 cc. of water and shake to spread the ore evenly over the bottom of the beaker. Add 100 cc. of strong HCl, cover the beaker and set it to warm gently for an hour. The temperature should not exceed 60° C.—higher heating expels HCl gas. The ore is slowly decomposed and most of the tungsten is held in solution by the excess of HCl, leaving the undecomposed ore exposed to further attack by the HCl.

Stir the solution with a glass rod once or twice during this digestion to prevent

the formation of crusts or cakes on the bottom. The glass rod may be left in the beaker.

After an hour increase the heat and boil until the solution is evaporated one-half or thereabouts. The cover may be removed after boiling begins, or better, it may be supported over the beaker on three glass hooks. After the liquid is reduced in volume to 50 or 55 cc., scrape the bottom of the beaker thoroughly with a glass rod to detach all caked ore and residue—this is very important, otherwise complete decomposition by the acid treatment is difficult if not impossible to accomplish. Add 40 cc. more strong HCl and 15 cc. HNO₃, replace the cover and boil until all danger of spattering (owing to the rapid expulsion of chlorine) is past, remove the cover and evaporate to a volume of 50 cc., then add 5 cc., more HNO₃, replace cover and continue boiling, finally remove cover and evaporate to a volume of 15 cc. or less. All this boiling and evaporation requires about an hour. Occasional stirring to break up crusts, especially when fresh additions of acid are made, is recommended.

Add 200 cc. of hot water to the concentrated solution, stir well and simmer gently just at the boiling point for half an hour. Nearly all the tungstic acid is separated after the addition of nitric acid, and during the subsequent simmering and boiling after dilution, but a little may remain in solution. Add 6 cc. of cinchonine solution, stir well and let stand for half an hour, or longer if convenient, thus precipitating all tungsten.

This method of attack is preferable to that formerly employed wherein less acid was used and HNO₃ was added earlier in the digestion. Most ores are completely decomposed, so far as tungsten minerals are concerned, but it is unsafe to assume that this is the case unless the residue is pure white silica.

After the tungstic acid residue has settled well and has stood for half an hour, filter the solution through a 9 cm. paper, using a little paper pulp in the filter. Wash the residue well, first by decantation in the beaker and afterward on the paper with a dilute solution of cinchonine and HCl.

It is unnecessary to detach the tungstic acid which adheres to the sides of the beaker, but washing should be thorough to remove all iron, manganese, lime, etc., from the residue and filter paper. Finally wash both beaker and filter once with cold water to displace most of the dilute einchonine washing solution.

Procedure for Isolation of Tungsten

Wash the tungstic acid and residue back from the filter into the original beaker with a fine jet of water from a wash bottle—the residue washes out easily because of the paper pulp which prevents adherence—about 25 cc. of water should be used. Add 6 cc. of strong NH₄OH, cover the beaker and warm it gently for about ten minutes. Tungstic acid dissolves readily, stir well and wash down the sides of the beaker with dilute ammonia, make sure that all the yellow tungstic acid has dissolved, then filter the warm solution through the same filter paper that was used at first, thus dissolving the small amount of tungstic acid that adhered thereto. Collect the filtrate in a 400 cc. beaker, wash the original beaker and the filter paper thoroughly with dilute ammonia (1 part strong NH₄OH—9 parts H₂O). The filtrate should be clear, or at most only slightly cloudy. The addition of about one gram of NH₄Cl to the solution before filtering and the use of a little of the same salt in the wash solution will insure a perfectly clear filtrate; but the use of this salt is not recommended unless the silicious residue tends to pass the filter in large

amount. The residue insoluble in ammonia will usually be free from tungsten; it may consist of tin oxide (cassiterite) silica and undecomposed silicates, titanium minerals or columbite; to make sure, it must be fused as described below.

Cover the 400 cc. beaker and boil it until free ammonia is expelled. The object of boiling off the free ammonia is to minimize ammonium salts since the cinchonine tungsten compound to be precipitated comes down more quickly and completely in solutions free from ammonium salts. Dilute the solution to 200 cc. with hot distilled water, acidulate with 3 cc. HCl and add 6 to 8 cc. of cinchoninc solution. Stir very briskly for half a minute, which will cause the flocculent precipitate to agglomerate. It will then settle rapidly, leaving a clear supernatant liquid. Let it stand until cold, filter on an 11 cm. weightless ash filter (B. & A.—A grade) which has been treated to a rather copious dose of paper pulp. If ammonium chloride is used in the prior operation, the solution should be allowed to stand for several hours, best over night, after adding cinchonine. Wash well with dilute cinchonine solution (wash solution described above) policing the beaker with a rubber tipped rod. Follow the cinchonine wash by one washing with cold water, transfer the filter to a small weighed platinum dish or large crucible, dry by heating on the hot plate, then burn the filter slowly over a bunsen burner or in a muffle followed by strong ignition until all carbon is consumed.

The use of paper pulp in the filter promotes ignition, leaving the ignited precipitate as a porous, friable mass, whereas if paper pulp is not used, the ignited precipitate is dense and it is sometimes difficult to burn the carbon completely.

After the carbon is practically all consumed break down the residue with a glass rod flattened at one end, wipe off the end of the rod with a small piece of moistened filter paper, adding it to the dish. Any remaining carbon and the small piece of filter paper are quickly burned, leaving a pure yellow residue.

Moisten the residuc with three drops of strong H₂SO₄, add 5 cc. of HF and evaporate slowly on the hot plate until the HF is expelled. It is best to continue heating on the hot plate until the II₂SO₄ is expelled also; there is then no danger of spitting. Ignite the dish cautiously at first, finally at full red heat for ten minutes, cool in a desiccator and weigh as WO₃.

The residue left after the ammonia treatment may in some cases contain WO₃, although with Scheelite and most pure ores and concentrates it does not. It is best in all cases to examine it. In the case of impure ores containing much insoluble residue, the residues from duplicate determinations should be examined separately. When the residue is small and light-colored, it suffices to unite the duplicates for this determination.

Ignite the filter containing the residue in a small porcelain crucible. This is necessary because tin may be present, which would be reduced by the filter paper and ruin platinum. Mix the ignited residue with five or six times its weight (in any case at least one gram) of sodium carbonate plus a very little KNO₂. Transfer the mixture to a platinum crucible and fuse for five or ten minutes. Leach the fusion with 50 cc. of hot water in a small beaker, filter, acidulate slightly with HCl and boil to expel CO₂. Add 5 cc. cinchoniue solution. Let the beaker stand for several hours, best over night; long standing is essential because small amounts of tungsten are slowly precipitated by cinchonine in the presence of alkaline chlorides.

If any tungsten precipitate appears, filter it off on a 7 cm. paper and wash it with dilute cinchonine solution, followed by one wash with cold water, dissolve on the filter in warm dilute ammonia, collecting the filtrate in a small beaker, boil out the excess of ammonia, make slightly acid with HCl and reprecipitate the

tungsten with cinchonine. This reprecipitation is done in a very small volume of liquid practically free from salts so the tungsten comes down quickly, let it stand for an hour, filter on a small weightless ash filter containing a little pulp, wash with dilute cinchonine solution followed by one wash with water, ignite, cool, treat with a drop of H_2SO_4 and 1 cc. of HF, evaporate, ignite and weigh. Add the percentage of WO₄ thus found to the principal amount.

Factors: $WO_3 \times 0.7931 = W$, $W \times 2.4739 = PbWO_4$.

Aqua Regia Method of Watts1

One gram of medium grade, or 0.5 gram of high grade, very finely pulverized orc, is treated in a 4-oz. flask with 40-50 ec. aqua regia and kept at moderate heat, below boiling, on a hot plate, until the solution has evaporated to about 15 cc. The solution is shaken frequently to prevent a solid cake forming at the bottom of the flask, which would prevent eomplete action of the acid on the ore.

The solution, removed from the hot plate, is diluted to about 50 ce. with hot distilled water and set aside to settle for half an hour. The clear liquor is decanted through a paper filter and the residue washed in the flask twice by decantation with 25 ce. portions of water slightly acidulated with HCl.

The WO₃ in the flask is dissolved with 20 ee. of 1:5 NH₄OH containing 2-3 drops of HCl. The solution is decanted through the filter and any remaining residue washed by decantation twice with the ammonia reagent.

If the residue is white it is transferred to the filter. If any black particles of undecomposed ore are evident, the residue is again digested with 10-15 ee. of aqua regia and treated as in the first ease, only with relatively smaller portions of solutions. The ammonia extract is added to the filter. And the filter washed down in the customary way to remove all tungsten solution, allowing it to flow into the main extract.

The filtrate containing the tungsten is evaporated to dryness in a platinum dish over a water bath. The ammonia salts expelled by heat. The residue cooled is treated with 1-2 drops of H_2SO_4 and about 2 cc. HF. The silica is expelled (in Hood), together with the neids by gently heating. The residue is now heated to dull redness for 5-10 minutes, then cooled in a desiceator and weighed as WO_3 .

DETERMINATION OF COMMONLY OCCURRING SUB-STANCES IN TUNGSTEN ORES AND CONCENTRATES

Determination of Phosphorus

Treat two grams of ore exactly as in the tungsten determination and evaporate the HCl and HNO₃ solution until only about 10 cc. of liquid remains. Add 5 cc. of strong H₂SO₄ and evaporate to funcs. Cool, take up with 25 cc. H₂O, add about two grams of tartaric acid and heat to boiling. Add 20 cc. of strong NH₄OH thus dissolving the separated WO₃. Filter into a "shaking bottle" (a glass stoppered 250 cc. bottle) and wash the residue with dilute NH₄OH. Reserve the liquid. Ignite the residue and expel SiO2 with HF and H2SO4. In the case of Scheclite this residue may be rather large owing to the insolubility of CaSO4. Add sufficient Na₂CO₃ to make eight or ten times the weight of the residue and fuse thoroughly. Leach the fusion with hot water and filter, washing the residue with dilute Na₂CO₃ solution. Acidulate the filtrate with HCl and boil to eliminate CO2-evaporate the solution if necessary to a volume of 75 cc. and make it slightly alkaline with NH4OH. A precipitate of Al2(OH)6 may appear at this point; if it does, make the liquid slightly acid until the precipitate dissolves, and add it to the main ammoniacal solution in the shaking bottle. The presence of tartaric acid in this solution will prevent the separation of alumina. Add 10 cc. magnesia mixture to the bottle (the whole volume of solution should not exceed 160 ec.) and cool to 5° C. or less. Add five or six glass beads to the bottle and shake in a shaking machine for five or ten minutes. The object of the glass beads and the shaking, is to start the formation of magnesium-ammonium phosphate. After shaking, add 25 cc. of strong NH4OH and let the bottle stand in a refrigerator over night. Filter off the solution and wash the precipitate in the bottle and on the paper with dilute NH4OH but do not attempt to remove the precipitate adhering to the sides of the bottle. The precipitate consists of magnesium ammonium phosphate and arsenate together with silica and other impurities. Tin, tungsten, molybdenum, vanadium and titanium are eliminated by precipitation with magnesia mixture in the presence of tartaric acid. Dissolve the magnesia precipitate in hot dilute HCl and evaporate to small volume, say 7 or 8 cc. Add 10 cc. of strong HCl and 0.5 gram NaBr and evaporate to dryness. Take up with 5 cc. HNO2 and evaporate to dryness again. The NaBr serves to reduce Asv to As". The addition of strong HCl and boiling followed by evaporation to dryness eliminates As and SiO2. Dissolve residue in 60 cc. HNO3, S. G. 1.135, add 40 cc. of NH4OH Sp. Gr. 0.96, cool to 35° C., add 30 cc. molybdate solution (Blair) and finish the determination by the alkalimetric method (Handy) described on page 368.

Determination of Sulphur in Ferberite, Wolframite and Scheelite

Fusion Method. Fuse two grams of pulp mixed intimately with nine grams of Na₂CO₃ and one gram KNO₃. Leach the fusion with water and wash the residue thoroughly with a dilute solution of Na₂CO₃. Acidulate the liquid with HCl and evaporate to dryness. Take up with a little HCl and 150 cc. of water, add 5 cc. of strong einehonine solution and heat until all soluble salts are dissolved, finally boil for about five minutes. Let the solution stand over night, filter and wash with dilute einehonine solution, using paper pulp in the filter. Neutralize the filtrate with Na₂CO₃, make slightly acid with HCl (0.5 cc. for each 100 cc. of liquid) heat to boiling and precipitate BaSO₄ by the slow addition of 10% BaCl₂

solution. Let stand over night; filter, wash and weigh. The cinchonine solutions are the same as those used in the tungsten determinations. Note that the use of cinchonine is essential in this determination because in the presence of a large excess of alkaline chlorides the complete separation of tungsten is only effected by cinchonine. If it is omitted the BaSO₄ precipitate will inevitable contain BaWO₄. Blank determinations on the reagents run parallel with the sample are essential.

Wet Method. In Ferberite and Wolframite only where sulphur is present as associated sulphides. The method is not applicable to Scheelite which may

contain BaSO.

Treat two grams of the 200-mesh pulp with 20 cc. of a mixture of three parts HNO₃ and one part HCl in a 250 cc. beaker, add 0.5 cc. Br and let stand at room temperature for half an hour. Digest on a steam bath, for half an hour, remove cover and evaporate to dryness on the steam bath. Add 5 cc. strong HCl and again evaporate to dryness. Take up with 3 cc. HCl and 10 cc. H₂O, and digest until all soluble salts are dissolved. Add 250 cc. hot water and 2 cc. cinchonine solution and boil. Let the solution stand until it is cold, filter and wash the residue with water containing a few drops of HCl. Heat the liquid to boiling and precipitate S by adding 10 cc. of a 10% solution of BaCl₂·2H₂O. Let stand over night, filter and wash with hot water. Ignite and weigh as BaSO₄. In this method, the tungsten mineral is only partly decomposed, but all sulphides of iron, copper, etc., are oxidized to sulphates. This method is useful for the analysis of impure concentrates containing much associated sulphides. It is not to be relied upon for the accurate determination of small amounts of sulphur.

Determination of Arsenic in Tungsten Ores and Concentrates

Wet Method. The method is based on the assumption that arsenic in tungsten ores and concentrates is wholly present as associated minerals which may be decomposed by acid treatment and not as complex arsenic-tungsten compounds unaffected by acids, since the treatment used does not wholly decompose the

tungsten mineral or associated tin, titanium and niobium minerals.

Treat two grams of the 200-mcsh pulp in a round bottom 300 cc. flask with 10 cc. strong HNO₃. Digest for half an hour over a small flame, add 7 cc. of strong H₂SO₄ and evaporate to fumes by shaking the flask over a naked flame and at the same time blowing a mild air current into it to remove HNO₃. Cool the flask, add 10 cc. of water and again evaporate to fumes of H₂SO₄; this is done to expel HNO₃ completely which is important. Cool the flask and add 3 cc. of water, not more, then add two grams of dry FeSO₄ and connect the flask to an Allihn condenser, set up vertically, by means of a rubber stopper carrying a stoppered funnel tube and a wide exit tube. The exit cud of the condenser is sealed by allowing it to dip slightly below the surface of 300 cc. of cold water contained in a large beaker.

Add 75 cc. of strong HCl through the funnel tube and boil until the volume in the flask is reduced to 25 or 30 cc., then add 25 cc. more strong HCl and repeat the distillation. Usually two distillations serve to volatilize all arsenic which is collected in the beaker. To make sure, substitute another beaker containing water, add 25 cc. more HCl to the flask and distil again. The second distillate is tested by itself; it seldom shows any arsenic. Pass a rapid current of H₂S into the acid distillate, thus precipitating arsenic as As₂S₃. Let the precipitate settle at a temperature of 60° to 70° for an hour or two, filter through a Gooch crucible fitted with a well washed asbestos pad and wash the precipitate thoroughly with hot water, followed by alcohol, ether and finally CS₂. Dry the precipitate at 105° C.

for an hour and weigh, dissolve the As₂S₃ from the filter by passing warm NH₄OH through it, wash again with water followed by alcohol only, dry at 105° C. for an hour and weigh again. Take the weight of As₂S₃ by difference between first and second weighing. This method is preferable to weighing the Gooch crucible before filtering.

The distillation method depends on the reduction of As" to As" by ferrous sulphate and on volatilization as AsCl₃. This can only be done if the HCl employed is *strong*. Dilution of the HCl below a gravity of 1.10 will prevent the formation of AsCl₃, since in that case we have a solution of As₂O₃ in HCl rather than AsCl₃.

See also the procedure given on pages 37-39 of this volume.

Preliminary Fusion. In case the ore or concentrates contains insoluble arsenic compounds not broken up by the simple acid treatment described, it is necessary to fuse two grams of pulp with 15-20 grams of potassium pyrosulphate in a porcelain or fused silica crucible. After the melt is cold, remove it from the crucible which can usually be done easily by inverting and tapping, and break it into small pieces in a porcelain mortar. Transfer the ground melt to the 300 cc. flask, add two grams FeSO₄ and proceed with the distillation as above. The latter modification is unnecessary on most ores, since arsenic is rarely present except as associated arsenical minerals decomposed by acids.

Some trouble may be experienced in distilling owing to the "bumping" caused by separated WO₂ or undecomposed ore. This may be overcome by introducing a few glass beads into the flask.

Tin in Tungsten Ores and Concentrates

Fuse two grams of the finely pulverized ore in a spun iron crucible with ten grams of a mixture of equal parts of finely granulated sodium hydrate and sodium peroxide. The ore should be intimately mixed with the flux, fusion should be continued for one or two minutes after the mass is completely liquid, and a rotary motion should be given to the crucible during this period by holding it in the tongs and turning it in the flame; turning should be continued during cooling to spread the fusion.

Dissolve the fusion in 75 to 100 cc. of hot water. This is best done by placing the crucible in water in a large nickel dish since the strongly alkaline solution attacks glass or porcelain. When the mass is thoroughly disintegrated, remove the crucible and wash it; then pour the liquid into a 300 cc. beaker containing 15 grams of tartaric acid dissolved in 50 cc. of water; forthwith add 40 cc. of strong HCl. The solution will, of course, be quite hot. It should become clear on standing a few minutes except for a small amount of iron scale from the crucible, but it may require further heating to dissolve all iron hydrate. There should be no perceptible residue of undecomposed ore but it does not matter if there is a little, because it will be decomposed by the subsequent treatment. Pass a brisk current of H₂S into the warm solution until ferric iron is reduced and tin is precipitated as stannic sulphide. Filter the solution and wash the precipitate thoroughly with warm water containing H2S. If there is a tendency for the tin sulphide to run through add a little ammonium nitrate to the wash water. It is important to remove chlorides since their presence might entail a loss of tin in the subsequent ignition.

The presence of sufficient tartaric acid prevents the precipitation of tungstic acid when the fusion is acidulated with HCl, but with large amounts of tin or with

the considerable separation of sulphur caused by reduction of ferric iron in the solution some tungsten is likely to be entrained with the precipitate which no reasonable amount of washing will remove; a second fusion is therefore necessary. Ignite the sulphide precipitate in a porcelain crucible and transfer the residue carefully to a small spun iron crucible. The reason for this step is the presence of free sulphur and sulphides which unite with the iron of the crucible, forming iron sulphide when ignition is made in the iron erueible. The film of iron sulphide is vigorously acted upon by peroxide, causing spattering. Mix the ignited residue with about two grams of sodium peroxide and fuse as before. Dissolve the fusion, in the crucible, in 25 cc. of water, transfer to a 250 cc. beaker and boil to decompose peroxide; then add two grams of tartaric acid and 60 cc. of strong HCl. This gives a solution containing 2 vols. of strong HCl to 1 vol. of water. Iron scale from the crucible and iron hydrate dissolve immediately in acid of this strength, leaving a perfectly clear solution, but the object in adding the large excess of HCl is to obtain a solution of such acid strength that arsenic may be precipitated with H₂S while tin sulphide is not formed.

If the foregoing proportions are maintained the separation of arsenic and tin may be accomplished by passing H_2S into the solution, whereby arsenic is separated as sulphide. Pass H_2S into the hot solution for about ten minutes or until practically all ferric iron is reduced. Filter off the arsenie sulphides through a small filter and wash thoroughly with HCl (1.19 sp.gr.) diluted with one half its volume of water. Good quality filter paper will withstand HCl solutions of this strength

although an asbestos filter (Gooch) may be used if preferred.

Dilute the acid filtrate with twice its volume of water, add 25 cc. of strong NH₄OH to neutralize part of the free acid, and pass a little more H₂S thus precipitating tin, antimony, copper, etc. as sulphides. Let the sulphides stand until they have settled well, then filter and wash the precipitate with H₂S water slightly acidulated with HCl. Filter the solution through a 9 cm. filter, or better through a Gooch filter, using very moderate suction. Transfer the filter to a small beaker and heat it with 10 cc. of a 10% solution of sodium monosulphide. The tin sulphide and free sulphur dissolve readily leaving, usually, a very small amount of copper sulphide. Filter the solution through a 7 cm. paper and wash the filter several times with a 1% solution of sodium sulphide. Since copper sulphide is usually exceeding small, a single treatment with sodium sulphide suffices to dissolve all the tin sulphide, but if much copper should be present a second treatment is advisable.

The alkaline filtrate and washings contained in a 450 ec. Erlinmeyer flask should measure approximately 60 cc.; add 70 cc. of strong HCl, or a little more than the volume of the liquid. The sulpho-stannate is decomposed, most of the tin sulphide will dissolve, and there will be a separation of free sulphur. If the liquid is fairly cool at the time of adding the acid, there will be no great rise in temperature; if the temperature does not exceed 50-55° C. the liberated sulphur will not agglomerate and subsequent oxidation is easily accomplished by adding about two grams of KClO₂ a little at a time to the cool solution, shaking after each addition. After the solution begins to clear, heat it to boiling to remove chlorine. A perfectly clear solution without agglomerations of sulphur should result. Continue boiling for about ten minutes to insure complete expulsion of chlorine. Add 70 cc. of water to the flask, making the volume approximately 200 cc. containing between one-quarter and one-third of its volume of free HCl; this proportion of free acid is important. Introduce a coil of nickel foil, 1½" x 7", rolled around a

glass rod until it will just slip into the neck of the flask, heat the solution to boiling and boil gently for about 20 minutes; connect the flask by means of a double perforated rubber stopper with a current of CO₂ gas and continue boiling for a few minutes. Remove from heat and while a brisk stream of CO₂ is continued immerse the flask in cold water. When the solution is cooled to room temperature disconnect from the source of CO₂ and immediately titrate the tin with N/20 iodine solution using a few drops of starch solution as indicator. It is unnecessary to remove the nickel before titration. A "blank" should be made on the titration by boiling a solution of hydrochloric acid with a foil of nickel under the same conditions as the determination. The correction may amount to 0.2 cc. The iodine solution should be standardized against pure tin dissolved in HCl and KClO₂ and reduced with nickel under the same conditions as the determination.

Notes. Antimony does not interfere; it is precipitated as metal by the nickel and

remains as a black precipitate in the bottom of the flask.

Arsenic in minute proportions does not interfere. Where it is known to be present only in small amounts the steps for its elimination may be omitted. Some tungsten ores, however, contain relatively large proportions of arsenic, usually present as arsenopyrite. When a large amount of arsenic is present it should be climinated as described, otherwise serious errors may be made.

In place of the cumbersome CO₂ apparatus mentioned for use at the end of the reduction with nickel and during cooling, the "tin reduction" apparatus devised by A. Craig and described in The Engineering and Mining Journal, Vol. 106, p. 25, may be

used to great advantage.

Copper in Tungsten Ores and Concentrates

Applicable to All Ores Whether Scheelite, Wolframite or Hubnerite

Treat five grams of the fine pulp with 20 cc. of HCl in a 400 cc. beaker and digest with frequent shaking at a low temperature for an hour. Add 5 cc. of HNO₃ and boil down to a volume of, say, 10 cc., cool and add 10 cc. of $\rm H_2SO_4$ and evaporate to fumes. Cool, add 150 cc. of water and boil. Filter off the separated tungstic acid. All copper is in the acid filtrate, but it is well to test the residue also to be perfectly sure.

In the case of Scheelite it is necessary to add a few ec. of HCl to the acid solution before filtering off the WO₂, since the large amount of CaSO₄ which separates in sulphuric acid solution alone is troublesome to wash and renders the examination

of the insoluble residue difficult unless it is removed.

Neutralize the sulphuric acid solution from the WO₂ with NH₄OH, make it just acid with HCl, avoiding any greater excess than is sufficient to dissolve the iron and manganese hydrates. Add 50 ce. of a solution of sodium bisulphite (150 grams per liter) and let stand in a warm place for half an hour with frequent stirring—iron is reduced to the ferrous condition. Add 5 ce. of sodium sulphocyanate (150 grams per liter) and let stand for another hour stirring from time to time. Copper is precipitated as cuprous sulphocyanate free from molybdenum (which frequently occurs in Scheelite), arsenic or other interfering elements. Filter the cuprous sulphocyanate through a double filter, returning the first part of the filtrate to the filter since the precipitate is very fine and is apt to "run through" at first. To prevent this, add a little paper pulp to the filter.

Wash the precipitate with warm water and transfer the wet filter to a porcelain crucible, dry in an oven heated to 250° to 275°. This will char the paper gradually without danger of loss of precipitate. When the paper is thoroughly charred, heat

the crucible in a muffle or over an open burner until all carbon is consumed. Dissolve the mixture of copper sulphide and oxide remaining in the crucible in a few cc. of strong HNO, and finish the determination by the electrolytic or iodide methods. Very small amounts of copper are best estimated colorimetrically by comparing the blue color of the ammoniacal solution with a standard in short color tubes. Since the exact determination of copper is sometimes very important, it is advisable always to take a large initial weight of sample (5 grams) unless copper is present in large amount—say two per cent. This is sometimes the case in scheelites containing cupro-scheelite. In examining the residue left by the acid treatment, dissolve the WO₄ in NH₄OH and wash the filter with dilute NH₄OH. Ignite the filter containing the insoluble matter and undecomposed ore and fuse it with KHSO₄ in a porcelain crucible. Dissolve the fusion in water and make the solution strongly alkaline with NH₄OH. Filter off any iron hydrate and insoluble residue and observe whether or not the filtrate shows a blue color. As little as 0.5 mg. can easily be detected in a volume of 50 cc. If there is no blue color, further examination may be omitted. If the qualitative test indicates copper, dissolve any iron hydrate which may have separated in dilute H₂SO₄. Add this solution to the main liquid and slightly acidulate with HCl. Then add sodium bisulphite and sulpho-cyanate, proceeding as in the main determination.

Manganese in Tungsten Ores and Concentrates

Treat one gram of the pulp exactly as in the tungsten determination omitting the use of cinchonine, but letting the solution stand until it is cold after decomposition has been effected. Filter off the insoluble residue and tungstic acid and wash it thoroughly with dilute HCl (25 cc. per liter). It is quite difficult to remove every trace of iron and manganese from the heavy WO₃ residue which invariably retains a little unless the precipitate and residue is washed back from the filter and agitated with the wash liquid. The filtrate contains all Mn.

Neutralize the solution by means of Na₂CO₃ until there is a slight permanent precipitate. Dissolve this by adding dilute H₂SO₄ (1-5) leaving the solution very slightly acid. Add two or three grams of ZnO, ground to a cream with water, heat to boiling and titrate Mn with standard permanganate by Volhard's method.

See page 304.

METALLIC TUNGSTEN AND TUNGSTEN ALLOYS

Tungsten in Tungsten Metal and Ferro-Tungsten

Treat one gram of the finely ground sample in a large (60 cc.) platinum crucible fitted with a cover with 5 cc. HF.; add HNO3, drop by drop, until the metal dissolves. Add 3-4 cc. H₂SO₄ and evaporate on a steam bath until HNO₃+HF is expelled. Shake gently over a small Bunsen flanic until H2SO4 fumes strongly. Cool, transfer to a 250 cc. beaker with water, finally wiping the crucible with a little filter paper. A little WO3 sticks to the erucible; it cannot be removed by wiping. Reserve the crucible. Dilute the contents of the beaker to about 150 cc. with water, add 3 cc. HCl and boil. Remove from the stove and to the hot solution add 5 ec. cinchonine solution and let stand over night (or at least four or five hours). Filter on "ashless paper" and wash with dilute cinchonine solution. Gently ignite the precipitate in the erucible in which it was originally treated. Heat for five minutes with full Bunsen burner flame, eool and weigh. Add about 5 grams Na₂CO₃ and fuse, running the fusion around the side of the crucible to remove all WO₃. Dissolve the fusion in hot water; filter and wash five or six times with hot water. Place the filter in the crueible and ignite, add a little Na₂CO₂ and fusc again. Dissolve the fusion in water, filter and wash very thoroughly with hot water to remove last traces of Na₂CO₂, ignite in the same dish as at first, cool and weigh. The difference between weight of dish plus residue and weight of dish plus tungstic oxide is WO₃.

Dilute Cinchonine Solution. 30 cc. strong cinchonine solution and 30 cc.

HCl to one liter.

Strong Cinchonine Solution. 100 grams cinchonine dissolved in dilute HCl (1 part acid, 3 parts water) and diluted to one liter with acid of the same strength.

Method for Phosphorus in Ferro-Tungsten and Tungsten Metal

Treat one gram of the finely powdered sample in a platinum dish, fitted with a gold cover, with 15 cc. HNO₃ (1.42 sp.gr.), add 3 ec. HF and warm gently. When action subsides, add 3 cc. more HF. After action subsides, boil, remove cover and if decomposition is not complete, add more HF and boil again. When solution is complete, wash off the cover and evaporate at a low heat to a volume of about 10 cc. then add 3-4 drops of concentrated permanganate solution and continue evaporation until erusts of WO, begin to form at the edges; that is, to a volume of, say, 6 cc. Add 5 cc. H₂SO₄ and evaporate on the stove at a low heat until HF and HNO2 are expelled and H2SO4 fumes are given off. (Strong heat causes spattering and also cause hard, over-baked crusts to form on the bottom of the dish which resist subsequent treatment.) Cool, add 25 cc. H₂O and boil (by agitating over bunsen flame) until all soluble salts are dissolved. Destroy pink color due to excess of permanganate by adding sulphurous acid drop by drop. The pink color may not be very evident but the SO₂ is added anyway to reduce higher oxides of Mn. Boil for a minute or two after adding the SO₂. Add 1.2 grams of pure tartaric acid and when this is dissolved and the solution is cooled to a temperature of about 50° C., add 20 cc. of NH4OH, (0.90 sp.gr.) diluted with an equal volume of water. The precipitated tungstic acid should dissolve completely, giving a clear solution. The solution is hot from the reaction between H₂SO₄ and NH₄OH. While it is

still hot add 10 cc. magnesia mixture and transfer it from the Pt dish to a six-ounce glass stoppered bottle. Set the bottle in ice water and when it is thoroughly cooled, add four or five glass beads, say 6 mm. diameter. Stopper it tightly and shake in an efficient shaking machine for at least ten minutes. The agitation should be violent. The beads aid in starting the formation of the magnesium precipitate; after agitation add 15 cc. of strong NH₂OH and return the bottle to ice water tank or put it in a refrigerator to stand over night. Phosphorus separates as magnesium ammonium phosphate free from tungsten but containing possibly basic magnesium compounds. After standing over night, filter the solution through a 9 cm. paper containing a little paper pulp and wash the bottle and paper thoroughly by small additions of ammonia wash water (1 part NH₄OH, 3 parts H₂O). Do not attempt to remove all the precipitate from the bottle but remove the beads to the filter. Place the bottle under the filter and pour through the filter 60 cc. of HNO₂ of 1.135 sp.gr. (1 part HNO₃, 1.42; 3 parts H₂O) in five successive portions of 12 cc. cach letting the acid fall on the upper cdges of the filter paper. This dissolves any ammonium magnesium phosphate and washes it into the bottle where any that remained adhering to the glass is also dissolved. Add 12 cc. of NH4OH (sp.gr. 0.90) to the liquid, cool to 35° C., add 35 cc. molybdate mixture and proceed according to either of the methods described on pages 368-370 of this volume.

Notes. The usual proportions of HNO₃ and HF are reversed in order to provide a constant excess of HNO₃ to oxidize P. The procedure given takes a little longer than when the sample is treated with HF first and HNO₃ is added a little at a time, but solution is finally complete. It is necessary to keep the platinum dish covered after action begins, as the reaction is somewhat violent.

The platinum dishes recommended are:

8 cm. in diameter at top.
7.8 cm. in diameter at bottom.
4 cm. high.

They have flat bottoms and are wire rimmed at top to give additional stiffness. They weigh 58 to 60 grams each and hold about 175 cc. The covers are made of pure gold (for economy) "dished" like a crucible cover to fit the top of the dishes elosely. The dishes have small lips to aid pouring. The "tongue" of the cover overlaps the lip. Ordinary round bottomed dishes may be used but the manipulation is much more difficult; there is greater tendency to spattering and danger of local baking or overheating in evaporating to fumes of H_2SO_4 . If the separated WO_3 is overheated locally, it does not dissolve readily in NH_4OH . In a flat bottomed dish, the WO_3 is spread in a thin layer and heat is applied evenly all over the bottom.

A good shaking machine should be used. The magnesia precipitate may be started by shaking the bottles by hand, but it is a tiresome job. The solution must be cold—

say 8° or 10° when shaking begins.

Permanganate solution is added to insure complete oxidation of phosphorus, as in steel analysis. The color of the permanganate gradually fades in the hydrofluorie nitric solution, but after evaporating to fumes and adding water, the solution is usually

slightly pink.

The amount of tartarie acid is limited to 1.20 grams since ammonium tartrate retards the formation of the magnesia precipitate. Complete precipitation can only be obtained by brisk agitation and by keeping the solution very cold followed by long standing in a cold place. By this method, determinations started at 3 p.m. may be completed by noon the next day.

Determination of Sulphur and Silicon in Ferro-Tungsten and Tungsten Metal

Fuse two grams of the finely powdered metal, intimately mixed with 8 grams of dry Na₂CO₃ and 2 grams of powdered KNO₃, in a large platinum crucible (40 cc.). The fusion is best made in an electric muffle to avoid contamination with sulphur contained in illuminating gas. Leach the fusion with 100 cc. of distilled water in a 250 cc. beaker. Filter into a 12 cm. porcelain casserole and wash the residue several times with hot distilled water. The solution contains practically all of the sulphur and most of the tungsten and silica. The residue contains some

of each, but not more than traces of sulphur.

Solution. Render the liquid acid with 20 ec. HCl and evaporate to dryness on a steam bath, thus precipitating tungstic acid. After the residue is dry, heat it to 110°-120° C. in an oven to dehydrate silica, take up with 5 cc. HCl and 50 cc. water, add 3 cc. strong einchonine solution (see tungsten determination) and boil, or heat just short of the boiling point, for half an hour. Let the solution stand until it is cold. By means of the cinchonine all WO3 is rendered insoluble. Filter through an 11 cm. filter paper (free from ash) which has been liberally treated with an emulsion of filter paper pulp, and wash the residue with dilute einchonine solution (see tungsten determination). Reserve the residue. The filtrate contains all the sulphur, heat it to boiling and add 10 ce. of barium ehloride solution (100 grams BaCl₂ 2H₂O to 1000 ec.) boil for ten minutes, allow it to stand over night, filter on a 9 cm. filter paper (free from ash) wash repeatedly with hot water, ignite in platinum and weigh as BaSO4. If the work is properly carried out every trace of WO₃ is removed from the solution and there is no danger of including BaWO₄ with the BaSO4. If one suspects that the BaSO4 is not quite pure, 't should be fused with a little Na₂CO₃, leached with water and filtered, the filtrate should be acidulated with HCl, a few drops of cinchonine solution added and the solution evaporated to dryness on a steam bath. The dry residue should be dissolved in a little water, a few drops of HCl added, and any residue filtered off. In the clear filtrate BaSO₄ should be again precipitated as before. The weight of BaSO₄ \times 0.1373=S.

A "blank" on all reagents must be made parallel with the determination; this is important since all sodium carbonate obtainable contains sulphur and there is sometimes more or less of it in the cinchonine. All evaporations should be made over steam and the operations conducted in a place free from sulphur gases.

Silicon. The residue of tungstic oxide from which the solution for the determination of sulphur was filtered contains most of the silica. The residue from

leaching the original fusion contains the rest.

Wash the residue from the Na₂CO₃ fusion from the filter paper with a fine jet of water into a small casserole, add an excess of HCl and evaporate to dryness on a steam bath, heat the dry residue at 110°-120° C. to dehydrate silica and filter on a small filter paper (free from ash). Wash thoroughly with hot dilute HCl (1-10°) and finally with hot water. Reserve the filter.

Wash the residue of tungstic oxide, silica and filter paper pulp from the filter into a small casserole, add 5 cc. of HCl and heat for a few minutes, then filter again through the same paper and wash it thoroughly with hot water. This second washing is necessary to remove sodium salts completely. (The original washing sufficed to remove all of the small amount of sulphur present.) Transfer the well-washed filter and residue to a platinum crucible, add the small filter containing

the little silica recovered from the Na₂CO₃ fusion residue and ignite both to constant weight in a platinum crucible. On account of the presence of filter paper pulp, the ignited residue is porous and friable; if paper pulp had not been used, the WO₃ would be dense and not easily susceptible to the subsequent treatment. Cool the ignited residue of WO₃ and SiO₂ and weigh it. Add two or three drops of H₂SO₄ and 5 or 6 cc. of pure HF. Digest at a gentle heat for some time, and then slowly evaporate off the HF. When H₂SO₄ fumes are evolved, cool and again add HF, digest as before, evaporate off the HF, ignite gently to expel H₂SO₄ and then strongly for ten or fifteen minutes. Cool and weigh. The loss in weight after expulsion is SiO₂ which multiplied by 0.4693 equals silicon.

Determination of Manganese in Tungsten and Ferro-Tungsten

The filtrate from the tungstic acid obtained by digesting the residue after evaporation to fumes of H2SO4 and digestion with dilute HCl (see tungsten determination) contains all the manganese. Separate iron from this solution by means of a basic acetate precipitation and wash the precipitate thoroughly with a hot dilute solution of sodium acetate, reject the precipitate, and to the filtrate, which contains all the manganese, add 5 cc. of strong NH4OH, add about two grams of (NH₄)₂S₂O₈. Digest on a steam bath for 45 to 60 minutes, manganese separates as hydrated peroxide. Filter and wash with hot water. Dissolve the precipitate through the filter with ten or fifteen cubic centimeters of H₂SO₃ containing a few drops of H₂SO₄ and wash the filter paper several times with hot dilute H₂SO₄ (10%). Again filter through the same paper into a 500 cc. flask and wash with hot water. Dilute the liquid to a volume of about 200 ec. and boil it for fifteen or twenty minutes until all SO₂ is expelled. Nearly neutralize the solution with a solution of NaOH but still leave it slightly acid, complete the neutralization by adding 5 grams of zinc oxide cmulsified by grinding with water, heat again to boiling and titrate manganese in the hot solution with a N/10 solution of KMnO₄ (Volhard's Method).

Acknowledgement is made to Mr. J. A. Holladay, Electrometallurgical Co., for cooperation in the preparation of these methods.

TANTALUM AND COLUMBIUM

Cb, at.wt. 93.5; sp.gr. 7.06; m.p. 1950°; oxides CbO, CbO₂, Cb₂O₄. Ta, at.wt. 181.5; sp.gr.14.49; m.p. 2900°; oxides TaO₂, Ta₂O₄, Ta₇O₄.

DETECTION

The finely powdered mineral is digested with strong hydrochlorie acid, followed by concentrated nitric acid and the mixture taken to dryness. The residue is treated with hydrochloric acid, diluted with water, boiled and filtered. The residue is digested with warm ammonium hydroxide to remove tungsten and the solution filtered from the insoluble material, in which tantalum and columbium will be found, if present in the sample.

Decomposition of the material may be effected according to the procedure

described for the detection of tungsten, page 554.

The residue obtained is digested, in a platinum erucible, with hydrofluorie acid and a saturated solution of potassium fluoride added. The mixture is evaporated to small volume and allowed to cool slowly. Tantalum will separate in acicular rhombic crystals (solubility—1 part of the salt in 200 parts of water) as potassium fluotantalate $2KF \cdot TaF_{4}$; columbium separates in plates as the double fluoride, $2KF \cdot CbF_{5}$, if HF is in excess, or as a double oxy-fluoride $2KF \cdot CbOF_{5}$, if HF is not in excess; the columbium salt being much more soluble (1 part of the salt in 12 parts of water) crystallizes after the crystals of tantalum have formed.

The crystals may be examined under a lens and then treated as follows: The needle-like crystals are heated in a shallow platinum dish or crueible cover with strong sulphuric acid to fumes, the cooled mixture is transferred to a test-tube with water and boiled to precipitate the tantalic acid. An opalescent solution is obtained when this precipitate is treated with an excess of hydrochloric acid. Metallic zine added to this solution produces no color. A light-brown precipitate is obtained with tannic acid in the presence of tantalum. If the crystals of columbium salt are treated in the same way, metallic zine added to the acid solution will give a blue coloration, and tannic acid an orange-red coloration. Tantalic acid fused with sodium meta-phosphate gives a colorless bead (distinction from silica). The bead moistened with FeSO₄ and heated in the inner flame is not colored red. Columbic acid fused in the same way gives a blue bead in the reducing flame, and a red bead by addition of FeSO₄, and heating in the flame.

ESTIMATION

Tantalum and columbium occur commonly with tungsten in nature. In the following minerals, however, tantalum and columbium form the more important constituents:

Columbite, $(Ta \cdot Cb)_1(Fe \cdot Mn)O_6$; pyrochlore, $RCb_1O_4R(Ti \cdot Th)_1$; hatchettolite, $2R(Cb \cdot Ta)_1O_6$ or $R_1(Cb \cdot Ta)_2O_7$; fergusonite, $R(Cb \cdot Ta)O_4$; yttrotan-

talite, RR(Cb·Ta),O13·4H2O; samarskite, R1R2(Cb·Ta),O21.

Tantalum is used in electric light filaments; it is also used for hardening steel for drills, files, cutting edges, watch springs, and pen points. It is used in rectifiers for alternating currents.

Solution of the Sample

The statements made for solution of the sample in determinations of tungsten apply here also. It is well to keep the following facts in mind: Tantalum is insoluble in the common mineral acids—hydrochloric, nitric and sulphuric acids, but dissolves in hydrochloric acid. Columbium is insoluble in hydrochloric, nitric and in nitro-hydrochloric acid, but dissolves in hot concentrated sulphuric acid. The oxides Ta₂O₅ and Cb₂O₅ fused with KOH form soluble salts. Cb₂O₅ (not strongly ignited) is soluble in acids, from which (NH₄)₂S and NH₄OH precipitate columbic acid (containing ammonia). Freshly precipitated tantalic acid is soluble in acids, and reprecipitated by NH₄OH. The acid dissolves readily in HF.

Tantaliferous Minerals. Although decomposition may be effected by fusion with potassium acid sulphate, fusion with potassium hydroxide is recommended as being the best flux for opening the uninerals. Simpson's process is as follows:

Three grams of pure potassium hydroxide are fused in a nickel or silver crucible and the finely powdered mineral (0.5 gram) added, the contents mixed by gently rotating the erucible and fusion kept at a dull red heat for ten minutes longer. The crucible placed in a hole in an asbestos board, Fig. 65, is heated over a free flame for half an hour, the sample being covered. The lid is removed and allowed to cool reversed, if any material clings to this. The cooled crucible, placed in a beaker, is two-thirds filled with distilled water, and a clock-glass immediately placed over the beaker. After the violent reaction has subsided the contents of the crucible are poured into about 10 cc. of dilute hydrochloric acid (sp.gr. 1.08) in a 300-ee. beaker, and the crucible, basin and the lid washed with water, followed by about 20 cc. of the dilute acid, and again with water, adding the washings to the remaining solution. The total volume of the solution should occupy from 80 to 100 cc. A drop or two of alcohol are added to destroy any potassium manganate formed.

Separations

Isolation of Columbium and Tantalum Oxides. Separation from iron, manganese, copper, cobalt, niekel, calcium, magnesium, titanium, and tin. The solution obtained above is boiled with 5 to 10 ee. of hydroehloric acid (sp.gr. 1.16) (less acid may be used if titanium is absent). Columbium and tantalum hydroxides are precipitated. The solution is now diluted to 200 ce. and boiled for fifteen minutes longer to make sure that the precipitation is complete. After settling, the clear solution is decanted through a close-grained filter and the residue, having been transferred to the filter, is washed with dilute hydrochloric acid (sp.gr. 1.08) until the washings give no indication of iron. The residue may contain tantalum, columbium, tungsten, silica, antimony and tin. The greater part of the tin, titanium, and all of the iron, manganese, cobalt, nickel, copper, calcium and magnesium are removed in the filtrate.

NOTES. If the filtrate becomes turbid, it is advisable to dilute the solution and repeat the boiling to recover the columbium and tantalum that may still be in solution.

In the presence of appreciable amounts of titanium a soluble double chloride of columbium and titanium is formed, so that the precipitation of columbium

¹ E. S. Simpson, Chem. News, 99, 243, 1909.

is not complete. (See L. Weiss and Landecker, Chem. News, 101, 2, 13, 26, 1910.) The formation of this compound is hindered by the addition of an oxidizing agent—sodium nitrate—to the alkali.

Removal of Tin, Antimony, Tungsten and Silica. Tungsten is removed by digesting the moist precipitate with ammonium hydroxide or sulphide, tungsten being soluble in these reagents. Antimony and Tin are also removed.

Silica is volatilized by heating the residue with sulphurie and hydrofluorie

acids according to the standard procedure.

Tin. The oxide may be reduced with hydrogen passed over the heated residue within a boat placed in a combustion tube. The tin may now be dissolved out with hydrochloric acid.

Determination of Columbium and Tantalum

The insoluble residue obtained, freed from other elements by the procedures outlined, is ignited at a red heat for fifteen or twenty minutes and the residue weighed as Cb₂O₅+Ta₂O₅.

Separation of Columbium and Tantalum, Selenium Oxychloride Method.1

The method depends on the solubility of columbium oxide and the comparative insolubility of tantalum oxide in a mixture of sulphuric acid and selenium oxychloride as found by Victor Lenher.²

The method worked out by H. B. Merrill is as follows:-

The oxides are separated together with titanium dioxide from the other elements by the usual methods and the total percentage of titanium and columbium pentoxides (with titanium) is determined.

A weighed sample (0.2-0.3 g.) of the ignited oxides is boiled with 50 ec. of a 1:1 mixture of selenium oxychloride and strong sulphuric acid (sp. gr. 1.34) in an Erlenmeyer flask, on a sand bath for half an hour, avoiding heating to voluminous fumes. After cooling the solution is earefully decanted from the residue, with suction, through asbestos in a Gooch crucible that has been weighed. The filtrate is poured into a large volume of water and the solution boiled. A white precipitate indicates the presence of columbium. The residue in the flask is again extracted with 20 ec. of the reagent for fifteen minutes, the extract being poured through the asbestos filter and the filtrate tested as before for columbium. The process is repeated until the filtrate upon hydrolysis gives only a faint precipitate, due to traces of dissolved tantalum pentoxide. Three or four extractions are usually sufficient.

The undissolved tantalum pentoxide is transferred to the erucible with a jet of water from a wash bottle, washing unnecessary. The crucible is ignited and weighed, the gain in weight representing tantalum pentoxide.

Columbium (with titanium) is determined by difference. If titanium is present it is determined colorimetrically in a separate sample and its amount deducted from columbium.

¹ Henry Baldwin Merrill, Jour. Am. Chem. Soc. 43, 2378 (Nov. 1921).

² Victor Lenher, Jour. Am. Chem. Soc. 43, 21 (1921).

URANIUM

U, at.wt. 238.17; sp.gr. 18.7; m.p. $<1850^{\circ}$ C.; oxides UO_2 , UO_3 , (oxide U_3O_3 , formed by ignition = UO_2+2UO_3)

DETECTION

The mineral is warmed with a slight excess of nitric acid (1:1) until decomposition is complete. The solution is diluted with water and then an excess of sodium carbonate added and the mixture boiled and filtered. Sufficient nitric acid is added to neutralize the carbonate, and after expelling the CO₂ by boiling, sodium hydroxide is added to the filtrate. A yellow precipitate is formed in presence of uranium. The precipitate is insoluble in an excess of the reagent, but dissolves in ammonium carbonate.

Uranous salts are green or blue and form green or bluish-green solutions, from which alkalies precipitate uranous hydroxide, reddish brown, insoluble in excess, but readily dissolved by ammonium earbonate. Uranous salts are strong reducing agents.

Uranyl salts (${\rm UO_2 \cdot R_2}$) are yellow. Alkali carbonates give a yellow precipitate, soluble in excess. UO₂ is regarded as a basic radical, known as "uranyl." The radical migrates to the cathode, upon electrolysis of a uranyl solution. Uranyl salts are more stable than uranous and are better known.

Potassium ferrocyanide, K₄Fe(CN)₆, added to uranous or uranyl solutions gives a reddish brown precipitate (or a red color in dilute solutions). The precipitate dissolves in a large excess of HCl. If sufficient ferrocyanide is present the color changes to green on boiling. Addition of sodium hydroxide to the ferrocyanide precipitate of uranium changes the color to yellow. (Distinction from cupric ferrocyanide. Ferrocyanide gives a green precipitate with vanadium, the color deepens on addition of nitric acid. A blue color is produced with ferric iron. No color change with chromates. Distinction from vanadium, chromium and iron.)

Barium carbonate precipitates the uranic ion completely (distinction from the ions of nickel, cobalt, manganese, zinc).

Disodium hydrogen phosphate added to uranyl solutions, in presence of alkali acetates or free acetic acid gives a yellowish white precipitate, $UO_2HPO_4 \cdot x H_2O$, soluble in mineral acids. Warming promotes precipitation.

Tartarie acid, certain organic compounds, hydroxylamine hydrochloride, ammonium earbonate, prevent precipitation of uranium by alkalies and ammonia.

u Oxides UO₂, brown or black; UO₃, brick red; UO₂(OH)₂, yellow. All oxides are converted to U₃O₈ on ignition with free access of air.

Chapter by Wilfred W. Scott and Albert H. Low.

ESTIMATION

The element occurs in the following minerals: *

Pitchblende, or uraninite, containing 40 to 90% U₂O₃.

Autunite, Ca(UO₂)₂P₂O₃·8H₂O, contains 55 to 62% UO₃.

Torbernite, Cu(UO₂)₂·P₂O₃·8H₂O, contains 57 to 62% UO₃.

Carnotite, a vanadate of potassium and uranium, V₂O₃·U₂O₃·K₂O·3H₂O.

Samarskite, a urano-tantalate of iron and yttrium, etc., 10 to 13% UO₃.

Fergusonite, a columbate of cerium, uranium, yttrium, calcium and iron.

Nearly all the silicates, phosphates and zirconates of the rare earths contain uranium.

The element is used in the ceramic industry for producing yellow, brown, gray, and velvety-black tints. It produces canary-yellow glass. It is used as a mordant in dyeing of silk and wool. It also finds use in photography. The metal is used in cigarette-lighters and self-lighting burners.

Preparation and Solution of the Sample

The element dissolves in hydrochloric and in sulphuric acids; less readily in nitric acid. It is insoluble in alkaline solutions.

The oxide, UO2, dissolves in nitric acid and in concentrated sulphuric acid.

U₃O₈ is readily soluble in nitric acid, but dissolves with difficulty in hydrochloric acid. V₂O₅ dissolves with difficulty in nitric acid but easily in hydrochloric (red colored solution); U₂O₈ is readily soluble in a mixture of glacial acetic-nitric acids (100:5), V₂O₅ and Fc₂O₃ (ignited) are practically insoluble in this reagent.

The salts, UF4 and UO2(HPO4)2. 4H2O, are insoluble in water, but dissolve in

strong mineral acids.

Solution of Ores. One gram or more of the ore is dissolved with 15 to 20 cc. of aqua regia, by placing the mixture first on the steam bath for ten to fifteen minutes and then gently boiling over a low flame or on the hot plate. The solution is taken to dryness, silica dehydrated as usual, the residue treated with 10 cc. of hot dilute hydrochloric acid and diluted to about 50 cc. with hot water and the silica filtered off. Uranium passes into the filtrate. The solution is now treated as directed under Separations. If much silica or acid-insoluble matter is present, this should be treated in a platinum dish with strong hydrofluoric acid, and evaporated twice on the steam bath with hydrochloric acid to expal HF. The residue, dissolved with hydrochloric acid and water, is added to the first portion of solution obtained.

Carnotite. Solution of the ore is readily effected by boiling with nitric acid to which a little hydrofluoric acid is added. One gram of ore with 20 cc. nitric acid and 5 cc. hydrofluoric acid at boiling temperature will be completely decomposed in five minutes. Some authorities recommend addition of sulphuric acid with ores containing barium to break up the combination of barium and uranium. If the lead acctate separation of vanadium is used, the sulphuric acid should be expelled previously to this separation. Consult the gravimetric

procedures following the section on "Separations."

SEPARATIONS

Separation of Uranium from Copper, Lead, Bismuth, Arsenic, Antimony and the Other Members of the Hydrogen Sulphide Group. The solution containing uranium, etc., having an acidity of about 5 cc. strong HCl per 100 ec. of solution, is saturated with hydrogen sulphide and allowed to settle and again saturated with H_2S . The sulphides are filtered off and washed. The filtrate

and washings contain the uranium that was present in the sample.

Separation of Uranium from Iron and from Elements Having Water-insoluble Carbonates. The filtrate from the hydrogen sulphide group is concentrated to about 150 cc., and 15 cc. of hydrogen peroxide added. The solution is now neutralized with sodium earbonate and about 3 grams added in excess. After boiling for about twenty minutes, renewing the water evaporated, the hydroxide of iron, insoluble earbonates, etc., are filtered off, washed with hot water and the filtrate set aside for the determination of uranium. To recover any occluded uranium the precipitate is dissolved in just sufficient nitric acid to effect solution, and iron again precipitated by addition of hydrogen peroxide and sodium earbonate and boiling as directed above. The combined filtrates from this precipitate are concentrated to about 250 ec.

Separation of Uranium from Vanadium. Procedure 1. To be Used in the Gravimetric Determination of Uranium. The solution obtained as directed, under the previous separation, is acidified with nitric acid, adding a slight excess, and CO_2 expelled by boiling. The acid is now neutralized with ammonia in slight excess, then re-acidified with nitric acid in slight excess, finally adding about 4 cc. of the strong acid additional. Vanadium is now precipitated as lead vanadate by adding 10 cc. of a 10% solution of lead acetate, followed by sufficient strong ammonium acetate solution (1 vol. strong NH₄OH) to neutralize the free nitric acid (ubout 20 cc.). The precipitated lead vanadate is allowed to settle for a couple of hours on the steam bath, and is then filtered off (returning the first portions if not perfectly clear) and washed well with hot

water. The uranium passes into the filtrate.

The excess of lead remaining in the filtrate is next removed. A marked excess of ammonia is added to the hot filtrate, which is then boiled for about a minute and filtered. No washing required. The precipitate contains all the uranium as ammonium uranate, perhaps some ferrie and aluminum hydroxides and a portion of the lead. Most of the lead passes into the filtrate, which is discarded. The precipitate is now treated on the filter with a strong hot solution of ammonium carbonate containing a little free ammonia until all the uranium is dissolved and then washed with the same solution diluted. Most of the admixed lead and other impurities remain on the filter, the lead as carbonate. Sufficient strong hydrogen sulphide water is now added to the filtrate, or the gas is passed to precipitate all the lead remaining. The mixture is heated to boiling and then allowed to stand until clear. Any iron present is precipitated with the lead. Finally, the uranium solution is filtered off and the precipitate washed with hydrogen sulphide water containing a little ammonium earbonate. The filtrate is boiled to expel the hydrogen sulphide and ammonium earbonate and concentrated to 200-250 ce. Uranium is now precipitated and determined by the gravimetric procedure given on page 581a.

Procedure 2. To be Used in the Volumetric Determination of Uranium. The separation of vanadium from uranium may be effected by precipitation of the latter as a phosphate according to the following procedure. The solution is heated and allowed to run in a small stream through a funnel with constricted stem, into a boiling solution of 15 grams of ammonium acetate, 5 grams of microcosmic salt dissolved in 100 cc. of water containing about 5 cc. of glacial acetic acid. A rod, with a cup-shaped tip, placed in the solution prevents bumping. The mixture is allowed to boil for a few minutes, the beaker is then removed from the heat and the precipitate allowed to settle. This is now transferred to a filter after first decanting off the clear solution. It is washed once with hot water, then washed back into the beaker and dissolved in a small amount of hot dilute nitric acid, the precipitate clinging to the filter being dissolved off by the acid, which is allowed to run through the filter into the beaker. This nitric acid solution containing the vanadium is diluted to about 75 ec. and the uranium (together with aluminum if present) again precipitated as the phosphate according to the procedure described. The precipitate is again transferred to the filter previously used, and washed off with hot water four or five times. Vanadium passes into the filtrate. The phosphate is now dissolved off the filter with 15 cc. of hot dilute sulphuric acid (1:3), and uranium determined by titration with permanganate according to the directions given under the volumetric method described later.

Glacial Acetic Method for Separating Uranium from Vanadium.* Uranium nitrate or oxide dissolves readily in a mixture of glacial acetic acid and nitric acid, 20 parts of the former to 1 part of the latter. The nitrate and oxide of vanadium are insoluble in the reagent. Addition of water causes vanadium to dissolve. See method for determining uranium in Carnotite under the "Gravimetric" methods.

Separation of Uranium from Molybdenum, Tungsten and Vanadium.* The residue obtained by evaporating a mixture of uranyl nitrate and nitric acid with ammonium molybdate, or sodium tungstate, or sodium vanadate to dryness, is slightly moistened with nitric acid (5 cc. HNO₃-1.42) and extracted with ether; uranium dissolves completely while molybdenum, tungsten and vanadium remain insoluble. The evaporation is conveniently conducted in a glass bout of a size that may be placed in the paper thimble of a Soxhlet extraction apparatus, commonly used with volatile solvents. The extraction is generally complete after the ether has siphoned over five or six times.

^{*} Peligot, Ann. Chem. Phys., (3) 5 (1842). C. A. Pierlé, Jour. Ind. Eng. Chem. 21, 60 (1920).

GRAVIMETRIC DETERMINATION OF URANIUM AS THE OXIDE, U₃O₈

Procedure. The filtrate containing the uranium, as obtained according to the method given, under "Separations," is made slightly acid with nitric acid and boiled for a short time to ensure the absence of CO₂, then ammonia is added in marked excess, the mixture boiled for about a minute more and filtered. No washing necessary. Either paper or a weighed Gooch crucible may be used for the filtration. The precipitate is dried and ignited to the oxide U₂O₂, in which form it is weighed.

$$U_aO_8 \times 0.8482 = U_a$$

Notes. The purity of the oxide may be ascertained by dissolving in HNO₁ and testing for vanadium with H_1O_2 and for Al_2O_3 by adding $(NH_4)_2CO_3$.

Treadwell recommonds that the oxide be reduced by hydrogen passed over the red-hot residue, the brown UO₂ being formed. The oxide is cooled in a current of hydrogen.

GRAVIMETRIC METHOD FOR URANIUM IN ORES*

Take 0.5 gram of the finely ground ore, or more, according to richness. Treat by heating gently in an 8-oz. "copper flask" with nitric or hydrochloric acid, or both, together with about 1-2 cc. of hydrofluoric acid, to effect complete solution of the uranium. Sometimes galena is present, in which case it is best to start with 10 cc. or more of hydrochloric acid and heat until the galena is decomposed. Whenever hydrochloric acid is used, boil almost to dryness to expel most of it before continuing. To this residue, or to the original ore, if hydrochloric acid appeared unnecessary, add 10 cc. of nitric acid and 1-2 cc. of hydrofluoric acid. Boil very gently to effect complete decomposition, and finally to approximate dryness. Allow to cool, add 3 cc. of nitric acid and 50 cc. of hot water, and see that everything soluble is dissolved.

Now make slightly alkaline with ammonia, then just acid with nitric acid, and again alkaline with a little solid ammonium carbonate, followed by about 5 cc. of strong ammonia and 3-4 grams more of ammonium carbonate.

Boil for about a minute and then filter, having a wetted wad of absorbent cotton in the apex of the filter. Wash twice with hot water. Boil and concentrate the filtrate in a covered beaker during the next step.

Dissolve the precipitate on the filter with a little hot dilute nitric acid, receiving the filtrate in the original flask. Again neutralize and precipitate as before, washing this second precipitate well with hot water. Add the filtrate to the first one and continue the concentration to 150-200 cc. Now acidify with nitric acid, and then, in case of doubt, add about 1 cc. of hydrogen peroxide. A reddish brown color indicates vanadium.

A. Vanadium Present.—Boil to expel any remaining CO₂, make just alkaline with ammonia, then just acid with nitric acid, finally adding about 4 cc. of the latter in excess. The appearance of the liquid is usually a sufficient indication of the neutralization points. Now add 1 gram of lead acetate crystals and then sufficient ammonium acetate solution (about 20 cc.) to neutralize the nitric acid and precipitate the lead vanadate. Boil for about 10 minutes and then filter through a double filter, returning the first portions if not perfectly

* By Albert H. Low.

Wash with hot water. Receive the filtrate in a large beaker. bulky, boil down to perhaps 200-250 cc. Now add ammonia in marked excess and boil for a minute to expel any CO₂. Filter hot, paying no attention to a turbid filtrate unless it is yellowish (in which case wash the precipitate once with hot water, re-acidify the filtrate with nitric acid, heat to boiling and again precipitate with ammonia, filtering through the previous precipitate). No washing required. Place the last beaker under the funnel and fill the latter with a strong hot solution of ammonium carbonate, to which some free ammonia has been added. Usually one filling is sufficient to dissolve all the uranium and leave a white residue of lead carbonate, perhaps slightly discolored by a trace of iron. Wash with hot water, using a little more of the ammonium carbonate solution, if apparently necessary. Add to the filtrate sufficient strong hydrogen sulphide water to precipitate all the remaining lead (ordinarily 25 cc. of strong hydrogen sulphide water), or pass the gas for a short time. This also removes traces of iron. Heat to boiling, then allow to stand and settle. Filter, washing with hydrogen sulphide water containing some ammonium carbonate. Boil to expel the sulphide, then acidify with nitric ncid and boil off all CO2. Continue according to C.

B. Vanadium Absent.—Boil the nitric acid solution sufficiently to expel all CO₂, then add ammonia in marked excess and boil a little longer to expel any CO₂ in the ammonia. Filter the hot mixture, returning the first portions if not perfectly clear. No washing required. Dissolve the uranium on the filter with hot ammonium carbonate solution, as described in the last paragraph, and continue from this point as in the same situation above. Do not omit the hydrogen sulphide treatment, for, even in the absence of lead, there will usually be traces of iron to be removed. Continue according to C.

C. Add ammonia in marked excess, boil well for one minute and then filter through an ashless filter, returning the first portions if not clear. No washing required. Ignite filter and precipitate thoroughly in a porcelain crueible and weigh, after cooling, as U₃O₈. Impurities are usually present.

Dissolve the residue in the crueible by warming with a little nitric acid. Dilute and test for vanadium with hydrogen peroxide. A faint brownish tinge may be neglected. Rinse the solution into a small beaker, add solid ammonium carbonate in excess, boil a minute or two and then filter through a small filter, washing with hot water. The residue on the filter may consist of alumina and other insoluble matter. Ignite filter and residue in the original crueible, weigh and deduct the weight from that of the impure U₃O₈ previously found.

Ammonium Acetate Solution .- Eighty cc. of strong ammonia, 100 cc. of

water and 70 cc. of 90 per cent. glacial acetic acid.

Note.—A yellow filtrate from the ammonium uranate indicates incomplete precipitation. This may be due to a deficiency in ammonium nitrate, as ammonium uranate is perceptibly soluble in pure water. Add a gram or so of ammonium nitrate to the filtrate, boil and refilter. Or, better, dissolve the precipitate on the filter with dilute nitric acid, so that the mixed filtrates will be markedly acid, and repeat the precipitation with ammonia. The filtrate should be colorless.

GLACIAL ACETIC ACID METHOD FOR DETERMINING URANIUM IN CARNOTITE*

The following method depends upon the fact that uranium nitrate or oxide is soluble in a mixture of glacial acetic and nitrie acids in the proportion of 20 parts by volume of the former to 1 part of the latter, while vanadic nitrate and oxide (V_2O_5) are not.¹

Procedure

Half a gram or more of carnotite ore according to its richness (ground to pass 100-mesh sieve) is taken for analysis and digested at boiling temperature with 25 cc. dilute $\rm HNO_3$ (1:1) and 1-2 cc. HF. (An amount that will fill a small crucible lid.) The solution is rapidly evaporated to dryness and baked

gently to expel water, but not ignited.

Fifteen to 20 ee. of glacial acetic-nitric reagent (20:1) are added, rinsing down the sides of the heaker to remove any adhering material, using a policeman if necessary. (The reagent may be conveniently handled in a small wash bottle, the transferring of precipitates and washing with the reagent being necessary, no water being used at this stage.) The residue transferred to a filter is washed with the reagent five or six times, using small portions of the mixture.

The filtrate and glacial washings are rapidly evaporated to dryness and the residue again extracted with glacial-nitric acids.² This extract, free from vanadium,³ is evaporated to dryness, and gently heated over a free flame until the residue turns dark.⁴ Ten ec. of nitric acid and 40 ec. of water are added and the mixture heated to dissolve the uranium.

The greater part of the free nitric acid is neutralized by addition of ammonia (no permanent precipitate should form). Solid ammonium carbonate is added (covering the beaker during the intervals between additions of the carbonate as loss will occur through effervescence in an uncovered beaker) until a precipitate forms that remains undissolved on stirring. 2-3 grams additional ammonium carbonate and 5 cc. of ammonium hydroxide are now added and the solution warmed to coagulate the hydroxides of iron and aluminum. Uranium passes into solution.

The precipitate is filtered off and washed with hot water. The filtrate and washings (concentrated by boiling to about 150 ec.-200 ec. if the volume is large) is acidified with nitric acid (uranium precipitates andre dissolves). Carbon dioxide is expelled by boiling and a decided excess of ammonium hydroxide added. The boiling is now continued until uranium precipitates completely. If the supernatant solution is yellow, it is again acidified with nitric acid, followed by an excess of ammonium hydroxide and the boiling repeated. This generally effects complete precipitation.

The precipitated uranium is filtered off, washing being unnecessary. The filter and precipitate are placed in a crucible, the greater part of the water expelled by drying and the material then ignited. The greenish black residue

is weighed as U₃O₈.

This residue should be soluble when boiled with nitric acid. If it is not, contamination by iron and aluminum is indicated. Any residue remaining should be filtered off, then washed free of uranium with hot water, and ignited. Its weight is subtracted from the uranium oxide to obtain the true value of U_2O_3 .

Notes. 1. C. A. Pierlé, Jour. Ind. Eng. Chem. 12, 61, 1920.

^{*} Method by Wilfred W. Scott.

2. Uranium dissolves completely in the glacial-acetic mixture. A small amount of the vanadium may dissolve, hence the extract is evaporated and the residuc again extracted. A smaller quantity of the reagent may be used in this second extraction. 25 cc. of the reagent will dissolve, at boiling temperature, about 4.5 grams of U₂O₈ in five minutes and about 0.003 gram of V2O5. The proportion of glacial acetic acid to nitric acid should not fall below 10:1, otherwise vanadium will dissolve in appreciable amount. The author uses a round bottom flask filled with cold water, placing this over the beaker to act as a condenser to prevent loss of acetic acid.

3. The acetic acid extract filters rapidly. The red colored residue contains

the vanadium and practically all of the silica, iron and alumina.

4. The residue is ignited to destroy organic matter which would prevent precipitation of uranium by ammonia.

5. Uranium carbonate precipitates and then dissolves in the acid when present in excess. CO2 must, be expelled as this prevents precipitation of uranium by ammonium hydroxide.

6. A colored solution indicates the presence of uranium. The nitrate formed by acidification with IINO3 and making alkaline with ammonia with additional boiling insures complete precipitation of uranium.

7. Nitric acid dissolves uranium oxide very easily. The oxide of iron is

practically insoluble. Vanadic oxide difficultly soluble.

8. Hydrogen peroxide added to the nitric extract will produce a reddish brown color if vanadium is present.

Wash water used in transferring the uranium precipitate should contain ammonium nitrate to prevent solution of uranium.

DETERMINATION OF URANIUM IN CARNOTITE

The following method, worked out by C. E. Scholl,1 is adapted for eliminating the difficulties in an accurate determination of uranium, caused by the presence of iron, alumina and vanadium, which commonly occur in carnotite.

Procedure. To the sample of material containing about 0.2 gram uranium oxide, are added 25 to 50 cc. 1:1 nitric acid and heat applied until all the uranium is in solution. If necessary, allow to stand on the water bath to keep warm overnight. After diluting with warm water to 250 cc. the solution is filtered. Ferric chloride, equivalent to about three times the weight of vanadium present, is added. To the cold or slightly warm solution solid sodium carbonate is now added in small portions until all the acid is neutralized and then an excess of 1 gram added, the beaker being kept covered during the intervals between the additions. The sample is placed on a hot plate and heated to about 90° C., but not to boiling. After keeping hot for 15 minutes, the solution is filtered and washed. The residue contains all the iron and vanadium and the greater part of the aluminum. The filtrate is neutralized cautiously with nitric acid until uranium begins to precipitate. The greater part of the CO2 is removed by boiling. Sodium hydroxide is now added in excess and after boiling 15 minutes the solution is filtered. The filtrate contains the remainder of the aluminum and the vanadium not previously precipitated. The precipitate containing the uranium is dissolved in dilute nitric acid and heated to 90° C. and an excess of NH4OH added and the solution boiled. The precipitate is filtered off, ignited and weighed as uranium oxide, U₃O₄.

The oxide is tested for its purity with nitric acid as in the previous method.

¹Jour. Ind. Eng. Chem., Vol. 11, No. 9, p. 842, Sept., 1919.

VOLUMETRIC DETERMINATION OF URANIUM BY REDUCTION AND OXIDATION

Introduction. The determination of uranium by oxidation of the lower oxide UO₂ to UO₃ may be accomplished by means of potassium permanganate in precisely the same manner as in the determination of iron, the Jones reductor being used for the reduction of the uranic salt to the uranous form. The metal must be in solution either as a sulphate, a chloride or an acetate, but not as a nitrate. If present as a chloride the usual preventative solution of phosphorie acid and manganous sulphate solution must be present as in case of the titration of a chloride of iron, hence a sulphate solution is to be preferred. Although the degree of reduction varies with conditions, it is found that with brief contact with the oxygen of the air the oxide UO2 is formed.1

Procedure. Solution. The method for preparation of the sample, isolation of the uranium, has been given under Preparation and Solution of the Sample and Separations. The solution from the ammonium earbonate precipitate is acidified with sulphurie acid and boiled to expel the CO2.

Reduction. The uranium sulphate solution, diluted to a volume of 100 to 150 ec., containing one-sixth of its volume of sulphuric acid, is heated nearly to boiling and the organic matter that may be present oxidized by addition of just sufficient potassium permanganate solution to produce a faint pink color. Fifteen to 20 ee. of dilute sulphuric acid are passed through the 18-in. column of zine in the Jones reductor, followed by the hot uranium sulphate solution, flowing very slowly, fifteen to twenty-five minutes being required for 0.2 gram uranic oxide, thirty to forty minutes for 0.3 gram of the oxide, care being taken that the liquid in the reductor always covers the zine.2 The uranic solution is followed by 10 to 15 ce. of dilute 1: 6 solution of sulphuric acid.

Titration. The olive-green solution is poured into a beaker or casserole. The lower oxides are immediately oxidized to UO2 by the air, as seen by the slight change of color to sea green. The hot solution is now titrated with tenth normal permanganate. The solution during titration gradually becomes more and more yellowish green, as the highest oxidation is approached, until a faint pink color is obtained. With large amounts of uranium the color appears a yellowish pink.

One ec. N/10 KMnO₄=0.11925 gram U.

Note. 55.85 grams Fe is equivalent to 119.25 grams U.—Sutton.

C. A. Pierlé claims that high results are obtained by this method.

Oxidation of lower oxides by air to UO2". O. S. Pulman, Jr. Am. Jour. Sc. (4), 16, 229.

Hydrogen dioxide formed by nascent hydrogen in contact with air would vitiate

Determination of Uranium in Alloy Steels and Ferro-Uranium¹

The following method provides for the analysis of steels containing Cr, Mo, V, W, Co, Ni, C, Mn, Si, Al and Ti.

A 2 g. sample is dissolved in 75 cc. of 1:1 hydrochloric acid. After solution is complete the solution is oxidized by the dropwise addition of nitric acid. In the case of samples where tungsten is present an easily filterable product is obtained by diluting to 300 cc. and boiling for 15 min. The tungstic oxide is then filtered out and washed, the filtrate and wash waters being returned to the original beaker for evaporation to dryness, followed by baking at a moderate temperature. On dissolving the residue with 50 ce. of 1:1 hydroehloric acid and diluting with hot water, a solution is obtained from which the balance of the silica and the last traces of tungsten can be separated by filtering. The two precipitates after washing are available for the determination of tungsten and silicon by the usual methods. Filtrates and wash waters from these precipitates are combined and evaporated to a syrupy consistency in preparation for the extraction of most of the iron with ether. In the absence of tungsten the original solution is evaporated to dryness and baked with the object of removing silica. After the extraction of the iron, the aqueous layer is evaporated to a small volume to free it from the excess of acid. It is then diluted to a volume of 150 cc. with hot water, and an excess of sodium carbonate in the form of a saturated solution is added. This solution is boiled and, after settling, filtered, the precipitate being washed with hot water. The precipitate consists of the hydroxides of chromium, iron, manganese, cobalt, nickel, copper, and aluminum, if all of these elements are present, together with traces of silica, titanic oxide, phosphorus, and vanadium compounds. The filtrate contains uranium, molybdenum, vanadium, and traces of the elements which occur chiefly in the precipitates.

Bulky precipitates should be dissolved in hydrochloric acid and reprecipitated one or more times with sodium carbonate solution to insure a complete

separation of the uranium.

All filtrates from the precipitate are cautiously acidified with sulphuric acid and boiled long enough to insure the complete removal of all earbon Ammonia free from carbonate is then added in slight excess. Boiling precipitates the uranium, much of the vanadium, and traces of impurities. The molybdcnum is left in the filtrate. Steels contain only small amounts of phosphorus and the contamination of the uranium from this source is usually negligible. If the amount of phosphorus is large, it may be necessary to dissolve the precipitate in nitric acid, and after suitable oxidation, precipitate the phosphoric acid with ammonium molybdate. The phosphorus can then be removed as ammonium phosphomolybdate. The uranium and vanadium may be reprecipitated from this filtrate along with the manganese, if permanganate is used to oxidize the phosphorus, by adding a few drops of sulphuric acid, a small amount of ammonium persulphate, and enough carbonatefree ammonium hydroxide to give an excess. The precipitate obtained by boiling the solution is in the condition corresponding to the first uranium precipitate mentioned above.

The impure uranium precipitate containing phosphorus in negligible

¹ By G. L. Kelley, F. B. Myers and C. B. Illingworth, Jour. Ind. & Eng. Chem., Apr., 1919.

amounts, or free from it, is transferred to a beaker with a little water and solid ammonium earbonate added. On heating this solution under conditions and for a time calculated to result in only a partial decomposition of the ammonium carbonate, the uranium and vanadium go into solution leaving the manganese, iron, and other impurities undissolved. The filtrate is acidified with sulphuric acid and boiled until free from CO₂, when a slight excess of carbonate-free ammonium hydroxide is added. This precipitates only the uranium and vanadium.

The combined precipitates of uranium and vanadium are ignited at dull redness in a platinum crucible, allowing free access of air to reoxidize any reduced material. The ignited residue is weighted as U₃O₈+V₃O₆. In general, only a small part of the vanadium is present in this precipitate, thus making it unavailable for the vanadium determination. It is necessary, however, to determine the vanadium to correct the weight of uranium oxide. This may be done by almost any of the several known methods for determining vanadium. To this end we determine the vanuadium after reduction with hydrochloric acid by permanganate titration, and by oxidation with ammonium persulphate and silver nitrate, followed by electrometric titration. The latter method is the more certain and convenient, but the former gives entirely satisfactory For the purpose of either method the precipitate is dissolved in 50 cc. of concentrated hydrochloric acid and evaporated with 30 cc. of sulphuric acid (sp. gr. 1.58) until fumes appear. When the titration is to be completed with permanganate, the sulphuric acid solution is diluted to 250 ee. with hot water and titrated at 80° C, to the first pink color. At the same time like quantities of sulphuric and hydrochloric acids are evaporated, diluted, and titrated in similar fashion to obtain a blank correction for the vanadium. When the titration is to be made electrometrically, the sulphuric acid solution is diluted to 250 cc. with hot water, exidized with silver nitrate and ammonium persulphate and titrated with ferrous sulphate. The weight of vanadium so found is multiplied by 1.784 to convert it into the corresponding weight of the oxide V₂O₅. This weight is subtracted from the weight of the residue U₃O₈+V₂O₅. The corrected weight of the oxide U₃O₅ is converted into the corresponding weight of uranium by multiplying by 0.8483 from which the percentage of uranium can be calculated.

VANADIUM

V, at.wt. 50.96; sp.gr. 6.025; m.p. 1720° C.; oxides V₁O₁, V₁O₂, V₁O₃, V₁O₄, V₂O₄, pyro Na₄V₂O₁, tetra Na₂H₁V₆O₁, hexa Na₂H₁V₆O₁.

DETECTION

Ammonium Sulphide or Hydrogen Sulphide passed into an ammoniacal solution of vanadium precipitates brown V₂S₄, soluble in an excess of alkali sulphide and in alkalies, forming the brownish-red thio-solution, from which the sulphide may be reprecipitated by acids.

Reducing Agents. Metallic zinc, sulphites (SO₂), oxalic acid, tartarie acid, sugar, alcohol, hydrogen sulphide, hydrochloric acid, hydrobromic and hydriodic acids (KI) reduce the acid solutions of vanadates with formation of a blue-colored liquid. (See Volumetric Methods.) Reduction is hastened by heating.

Hydrogen Peroxide added to a cold acid solution of vanadium produces a

brown color, changing to blue upon application of heat.

Solid Ammonium Chloride added to a neutral or slightly alkaline solution of a vanadate precipitates the colorless, crystalline s.lt, NH₄VO₄, insoluble in ammonium chloride. The ammonium metavanadate ignited is decomposed, ammonia volatilizing and the red pentoxide of vanadium remaining as a residue.

The colorless ammonium vanadate solution becomes yellow when slightly

acidified. Acids produce a rcd color when added to the solid salt.

The oxide, V_2O_5 , is distinguished from Fe_2O_3 by the fact that it fuses very readily with the heat of Bunsen burner, whereas the oxide of iron, Fe_2O_5 , is infusible in

the heat of a blast lamp. M.p. $V_2O_6 = 658^{\circ}$ C.; m.p. $Fe_2O_4 = 1548^{\circ}$ C.

Comparison of Vanadium and Chromium Salts. Vanadium, like Chromium, forms a soluble salt upon fusion with sodium carbonate and potassium nitrate or with sodium peroxide. The solution of vanadates and of chromates are yellow or orange; the color of the chromate becomes more intense when strongly aeidified, whereas that of the vanadate is reduced. The yellow color of the vanadate solution is destroyed by boiling with an excess of alkali, but may be restored by neutralizing the alkali with acid. The chromate color is not destroyed. (Yellow with alkalies, orange in aeid solution.) Silver nitrate produces a dark-maroon precipitate with a soluble chromate and an orange-colored precipitate with a vanadate; mercurous nitrate produces a red-colored precipitate with ehromates and a yellow with vanadates. Vanadates are also distinguished from chromates by the reduction test; reducing agents such as a soluble sulphite, or sulphurous acid added to aeid solutions, form a blue-colored liquid with vanadates and a green color with chromates. Ammonium hydroxide added in excess to the cold reduced solutions

 1 Reduction with zinc is rapid with vanadates, much less vigorous with chromates. V_2O_5 reduced to V_2O_2 , color changes to blue, green, lavender and finally violet. ${\rm SO_2}$ or ${\rm H_2S}$ reduces V_2O_5 to V_2O_4 . V_2O_2 forms vanadyl salts.

gives a brown color, or a brown to dirty green precipitate with vanadium, and violet or lavender color or a light green-colored precipitate with chromium, depending upon the concentration of the solutions. Hydrogen peroxide added to the reduced cold acid solutions changes the vanadium blue to reddish brown; the chromium

green remains unchanged.

Detection of Vanadium in Steel. Five grams of the sample are dissolved in dilute nitric acid, the nitrous fumes boiled off, the solution cooled, and an excess of sodium bismuthate added. After filtering through an asbestos filter an excess of concentrated ferrous sulphate solution is added, and the solution divided into two equal parts in test-tubes. To one portion 10 ec. of hydrogen peroxide are added and to the other 10 ec. of water. If vanadium is present the peroxide solution will show a deeper color than the untreated solution. A deep red color is produced with high vanadium steels and a brownish-red with low. Since titanium also causes this color, it would interfere, if it were not for the fact that the color produced with titanium is destroyed by hydrofluoric acid and fluorides, whereas that of vanadium is not. In presence of titanium, 5 ec. of hydrofluoric acid are added to the treated sample.

The brown color produced by hydrogen peroxide, with vanadium solutions, will remain in the water portion when shaken with ether. The ether layer is

colored a transient blue in presence of chromium.

ESTIMATION

The materials in which the estimation of vanadium is desired may be surmised from the following facts: Industrial application. Vanadium is used in special iron and steel alloys. It increases the strength of steel as well as the compression power, without loss of hardness, and increases the resistance to abrasion; hence vanadium steels are used in locomotive and automobile cylinders, pistons, bushings and in all parts of machines subject to jar. It is used in high-speed tools, vanadium bronzes for gears, trolley wheels, etc. It is used in indelible inks, and in the form of alkali vanadates and hypovanadates it serves as a mordant for aniline black on silk, for calico printing and like uses. Vanadium salts are used in ceramics where a golden glaze is desired.

The element occurs widely distributed in minute quantities. It is found in iron ores, hence occurs in blast-furnace slags as the oxide, V_2O_5 . The principal

ores are:

Patronite, a sulphide of vanadium containing 28 to 34% V₂O₅, associated with pyrites and carbonaceous matter; the principal source of vanadium.

Vanadinite, (PbCl)Pb₄(VO₄)₃, containing 8 to 21% V₂O₅. Carnotite, K₂O·2UO₂·V₂O₅·3H₂O, contains 19 to 20% V₂O₅.

Descloizite, (PbZn)₂NVO₅, contains 20 to 22% V₂O₅.

Roscoelite, a vanadium mica with variable composition.

Eusynchite, contains 17 to 24% V2Os.

Cuprodescloizite, (PbZnCu)₂(OH)VO₄, contains 17 to 22% V₂O₅. Calciovolborthite, (CuCa)₂(OH)VO₄, contains 37 to 39% V₂O₄.

Vanadium occurs in ores of copper and lead, it is present in certain clays and basalts, in soda ash, phosphate soda, and in some hard coals.

Preparation and Solution of the Sample

In decomposition of the material for analysis the following facts regarding the solubility of the metal, its oxides and principal salts, will be helpful:

Element. The inetal is not attacked by aqueous alkalies, but is soluble by fusion with potassium or sodium hydroxide, and sodium earbonate containing potassium nitrate. It is insoluble in dilute hydrochloric and sulphuric acids. It dissolves in concentrated sulphuric acid and in dilute and concentrated nitric acid forming blue solutions.

Oxides. V₂O₂ is easily soluble in dilute acids, giving a lavender-colored solution.

V₂O₃ is insoluble in hydrochloric and sulphuric acids, and in alkali solutions. It dissolves in hydrofluoric acid, and in nitric acid.

V₂O₄ is easily soluble in acids, forming blue-colored solutions. It dissolves in alkali solutions.

 V_2O_5 is soluble in acids, alkali hydroxide and carbonate solutions. Insoluble in alcohol and acetic acid.

Salts. Animonium meta vanadate, NH₄VO₃, is slightly soluble in cold water, readily soluble in hot water. The presence of animonium chloride renders the salt less soluble. The vanadates of lead, mercury and silver are difficultly soluble in water. These are dissolved, or are transposed by mineral acids, the vanadium going into solution; i.e., lead vanadate treated with sulphuric acid precipitates lead sulphate and vanadic acid passes into solution.

General Procedure for Decomposition of Ores. One gram (or more) of the finely divided material is placed in a large platinum crucible together with five times its weight of a mixture of sodium carbonate and potassium nitrate (Na₂CO₃=10, KNO₃=1). The product is heated to fusion over a blast lamp and, when molten, about 0.5 to 1 gram more of the nitrate added in small portions. (Caution—platinum is attacked by KNO₃. A large excess of Na₂CO₃ tends to prevent this.) The material should be kept in quiet fusion for ten to fifteen minutes, when most of the ores will be completely decomposed. The cooled fusion is extracted with boiling water, whereby the vanadium goes into solution. Arsenic, antimony, phosphorus, molybdenum, tungsten and chromium pass into solution with the vanadium. These must be removed in the gravimetric determination of this element. (Iron remains insoluble in the water extract.)

Should there be any undecomposed ore, the residue from the water extract will be gritty. If this is the ease, a second fusion with the above fusion mixture should be made.

Small amounts of oecluded vanadium may be recovered from the water-insoluble residue by dissolving this in nitrie acid and pouring the solution into a boiling solution of sodium hydroxide. Vanadium remains in solution.

Vanadium may be determined volumetrically after removal of the hydrogen sulphide group, by titration with potassium permanganato according to the procedure given later. The isolation and determination of vanadium by the gravimetric procedures are given in detail later.

Ores and Material High in Silica. The sample is treated in a platinum dish with about ten times its weight of hydrofluoric acid (10 to 50 cc.) and 2 to 5 cc. of strong sulphuric acid. The silica is expelled as SiF4 and the hydrofluoric acid driven off by taking the solution to SO4 fumes. The residue is extracted with hot water containing a little sulphuric acid. Any undissolved residue may be brought

into solution by fusion with potassium acid sulphate, KHSO4, and extraction with hot water containing a little sulphuric acid. By this treatment the iron passes

into solution with vanadium.

Products Low in Silica. Decomposition may be effected by fusion in a nickel crucible with sodium peroxide and extraction with water. The water should be added eautiously, as the reaction is vigorous. One gram of the finely divided ore is intimately mixed with 3 to 4 grams of Na₂O₂ and 1 gram of the peroxide placed on the charge. The material is then fused as stated.¹

Iron and Steel. The solution of the sample, isolation of vanadium and its

volumetric determination are given at the close of the ehapter.

Alloys. These may be decomposed with nitric acid, or aqua regia. The isolation of vanadium with mercurous nitrate or lead acetate are given under the gravimetric methods.

SEPARATIONS

Fusion with sodium earbonate and potassium nitrate and extraction of the melt with water effect a separation of vanadium from most of the metals, which remain insoluble as earbonates or oxides. Arsenic, molybdenum, tungsten, ehronium and phosphorus, however, pass into the filtrate with vanadium.

Removal of Arsenie. This element generally occurs in vanadium ores. It may be removed when desired, by acidifying the water extract of the fusion with sulphurie acid, and after reducing arsenic with SO₂, precipitating the sulphide,

As₂S₄ with H₂S gas. Vanadium passes into the filtrate.

Removal of Molybdenum. The procedure is similar to that used for arsenie, with the exception that the sulphide of molybdenum is best precipitated under pressure. The solution in a pressure flusk is treated with H₂S. The flask is stoppered and heated in the steam bath. It is advisable to resaturate the solu-

tion with II2S before filtering off the sulphide.

Separation from Phosphorie Acid. In the gravimetric procedure phosphorus and vanadium are precipitated together as mercuric vanadate and phosphate. The mercury is expelled by heat and the oxides V_2O_5 and P_2O_5 weighed. (V_2O_5 in presence of P_2O_5 does not melt as it does in pure form, but only sinters.) The oxides are fused with an equal weight of sodium earbonate, the nelt dissolved in water, then acidified with sulphuric acid and vanadium reduced to the vanadyl condition by SO_2 gas. The excess of SO_2 is expelled by boiling and passing in CO_2 . Phosphoric acid is now precipitated with ammonium molybdate (50 ec. of a solution containing 75 grams ammonium molybdate dissolved in 500 ec. of water affd poured into 500 cc. nitric acid—sp. gr. 1.2) in presence of a large amount of ammonium nitrate and a little free nitric acid. It is advisable to dissolve the precipitate in ammonia and reprecipitate in presence of additional ammonium molybdate and nitrate by acidifying with nitric acid. The equivalent P_2O_5 is deducted from the weight of the combined oxides, the difference being due to V_2O_5 .

Note. Vanadium must be completely reduced to the vanadyl form, as vanadic acid will precipitate with phosphoric acid.

¹ Direct reduction and titration of vanadium in presence of a large accumulation of salts leads to erroneous results. The vanadium should be separated by precipitation with lead acetate.

Separation of Vanadium and Chromium. A volumetric procedure for determining vanadium and chromium in the presence of one another is given. If a separation is desired the following procedures may be used:

- A. The solution is acidified with nitric acid. If hydrochloric acid is present it is expelled by taking to near dryness twice with nitric acid, the residue is taken up with water and SO₂ gas passed in to completely reduce the vanadium. This solution is poured into a boiling solution of 10% sodium hydroxide. After boiling a few minutes, the solution is filtered and the residue washed. The filtrate contains vanadium, the residue chromium. It is advisable to pour the filtrate into additional caustic to remove the small amount of chromium that passes into the solution.
- B. One hundred cc. of the neutral solution is made acid with about 15 ee, of glaeial acetic acid and hydrogen peroxide added. The solution is boiled for a few minutes. Chromium is thereby reduced to (r_2O_3) , whereas vanadium appears as V_2O_5 . Lead acetate will now precipitate lead vanadate, the reduced chromium remaining in solution. The lead vanadate now treated with strong sulphuric acid is decomposed upon heating. Addition of water precipitates PbSO₄, the vanadium remaining in solution.

GRAVIMETRIC METHODS

The following procedures presuppose that vanadium is present in the solution as an alkali vanadate, the form in which it occurs in the water extract from a fusion with sodium carbonate and potassium nitrate, as is described in the method of solution of ores containing vanadium. Chrominn, arsenic, phosphorus, molybdenum and tungsten, if present in the ore will be found in this solution.

Mercurous Nitrate Method for Determination of Vanadium— Gravimetric ¹

Principle. A nearly neutral solution of mercurons mitrate precipitates vanadium completely from its solution. The dried precipitate ignited forms the oxide, V_2O_4 , mercury being volatilized.

Procedure. To the alkaline solution or an aliquot portion of the water extract from the sodium carbonate potassium nitrate fusion nearly neutralized with nitrie acid ² (the solution should remain slightly alkaline) is added drop by drop, a nearly neutral solution of mercurous nitrate in slight excess of that necessary to precipitate completely the vanadium present, as may be determined by allowing the precipitate to settle and adding a few drops more of the reagent. The mixture is heated to boiling and then placed on the water bath or steam plate and the grayeolored precipitate allowed to settle. The precipitate is washed several times

¹ Method of Rose. J. W. Mellor, "A Treatise on Quantitative Inorganie Analysis."

² Should the alkaline solution of the vanadate be made acid, nitrous acid, from the nitrate fusion, will be liberated and cause reduction of the vanadate to the vanadyl salt, in which form it is not precipitated by mercurous nitrate; hence great care should be used in neutralizing the alkaline solution to avoid making it acid. It is a good practice to measure the acid added, having determined on an aliquot portion the aurount necessary to add to neutralize the solution. This is readily accomplished when a comparatively large sample has been prepared for analysis and an aliquot portion taken for analysis, several determinations being made on the same fusion.

with water containing a few drops of mereurous nitrate, washing onee or twice by decantation and finally on the filter paper. The precipitate is dried, then ignited in a porcelain crucible in a hood over a Bunsen burner to a red heat. The fused red residue is V₂O₄.

 $V_2O_5 \times 0.5604 = V$.

Gravimetric Method of Determining Vanadium by Precipitation with Lead Acetate 1

Principle. From a weakly acetic acid solution, vanadium is quantitatively precipitated by lead acetate. The precipitate is dissolved in nitric acid, lead removed as a sulphate, and vanadium determined in the filtrate by taking to

dryness and igniting to the oxide, V2O6.

Procedure. To the alkaline solution or an aliquot portion obtained by extraction of the carbonate fusion of the ore with water, just sufficient amount of nitrie acid is added to nearly neutralize the alkali present, as in the case of the method described for precipitation of vanadium by mercurous nitrate, and then a 10% solution of lead acetate is added in slight excess with continuous stirring. The precipitate is allowed to settle on the steam bath. The vanadate, first appearing orange colored, will fade to white upon standing. The lead vanadate is filtered and washed free of the excess of lead acetate with water containing acetie acid. The precipitate is washed into a porcelain dish with a little dilute nitric acid, and brought into solution by warming the lead salt with nitric acid. To this, the ash of the incinerated filter is added. Sufficient sulphurie acid is added to precipitate completely the lead, and the solution taken to small volume on the water bath and then to SO₄ fumes, but not to dryness. About 100 ec. of water are added and the mixture filtered; lead sulphate will remain upon the filter and the vanadium will be in solution. The lead sulphate is washed free of vanadium (i.e., until the washings no longer give a brown color with hydrogen peroxide).

The filtrate containing all the vanadium is evaporated to small volume in the porcelain dish, then transferred to a weighed platinum crueible and evaporated to dryness on the water bath and finally the residue (V₂O₅) heated to a dull redness over a Bunsen flame.

 $V_2O_5 \times 0.5604 = V$.

Notes. Lead may be separated from the vanadium by passing H_2S through the nitric acid solution, the oxcess of H_2S volatilized by boiling and the liberated sulphur filtered off. The filtrate is evaporated to dryness and the vanadium ignited with a few drops of nitric acid to the oxide V_1O_6 .

Lead may also be separated as lead chloride in the presence of alcohol, the solution taken to dryness and vanadium exidized by addition of nitric acid and ignited

to VOs.

¹ Mcthod by Roscoe, Ann. Chem. Pharm., Supplement 8, 102, 1872. Treadwell and Hall, "Analytical Chemistry," p. 305.

VOLUMETRIC PROCEDURES FOR THE DETERMINATION OF VANADIUM

Reduction of the Vanadate, V₂O₅, to Vanadyl Condition, V₂O₄, and Reoxidation with Potassium Permanganate

Principle. Vanadium in solution as a vanadate is reduced to the vanadyl salt by H₂S or SO₂, the excess of the reducing agent expelled and the solution titrated with standard KMnO₄, vanadium being oxidized to its highest form, V₂O₄.

Reactions. a. $V_2O_5 + SO_2 = V_2O_4 + SO_3$. b. $V_2O_4 + O = V_2O_5$. Hence

$$N/10$$
 sol. = $\frac{At. wt. V}{10}$ grams to the liter.

Procedure. An aliquot portion of the solution containing vanadium, as obtained by one of the procedures given for the solution of the sample, is taken for analysis; dilute sulphuric acid (1:1) is added to acid reaction and 5 cc. of acid per 100 ec. of solution added in excess. The vanadium content should be not over 0.5 gram V when a tenth normal permanganate is used for the titration. If arsenic or molybdenum is present these may be removed from the solution by passing in H₂S. The insoluble sulphides are filtered off and washed with H₂S water. The filtrate is boiled down to two-thirds of its volume and the sulphur filtered off. In the absence of members of the H₂S group, this portion of the procedure is omitted.

Oxidation with KMnO₄. The solution containing the vanadium is oxidized by adding, from a burette, tenth normal potassium permanganate to a faint permanent pink. If the solution has been treated with H₂S, the vanadium is in the vanadyl condition, and the amount of permanganate required to oxidize the solution completely will give a close approximate value for the vanadium present, each cc. of N/10 KMnO₄ being equivalent to 0.0051 gram vanadium.

Reduction. The vanadite is now reduced to vanadyl salt by passing through the acid solution, containing approximately 5% free sulphuric acid, a steady stream of SO₂ gas. Reduction may also be accomplished by adding sodium metabisulphite, or sodium sulphite, to the acid solution. The excess SO₂ is now removed by boiling (a current of CO₂ passed into the hot solution will assist in the complete expulsion of the SO₂).

NOTE. KMnO4 is reduced by SO2.

Test for Iron. A drop test with potassium ferricyanide, $K_1Fe(CN)_6$, on a white tile will give a blue color in the presence of ferrous iron. Since ferrous iron will titrate with potassium permanganate, its oxidation is necessary. This is accomplished by adding tenth normal potassium dichromate solution cautiously to the cold liquid until no blue color is produced by the spot test with $K_1Fe(CN)_6$ outside indicator. If the sample is sufficiently dilute, the blue color of the vanadyl solution will not interfere in getting the point where the iron is completely oxidized. Care must be taken not to pass this end-point, otherwise Va_2O_4 will also be oxidized and the results will be low.

Note. The action of the dichromate is selective to the extent that iron is first oxidized and then V_2O_4 . If the amount of iron present is large a separation must be effected. In case a sodium carbonate potassium nitrate fusion has been made and

vanadium has been extracted by water, iron will not be present. A special procedure for determination of vanadium in steel is given.

Potassium Permanganate Titration. N/10 KMnO₄ is now eautiously added until a pink color, persisting for one minute, is obtained. During the titration the solution changes from a blue color to a green, then a yellow and finally a faint pink. The reaction towards the end is apt to be slow if made in a cold solution.

Nores. In absence of chromium, it is better to make the titration in a hot solution, 60 to 80° C., the end-point being improved by heat. In case an excess of pernanganate has been added, the excess may be determined by a back titration with tenth normal thiosulphate. The solution may be rerun, if desired, by repeating the reduction with SO_2 and the titration with $K_2Cr_2O_7$ and $KMnO_4$.

One cc. N/10 KMnO₄=0.0051 grain V, or =0.00912 gram V_2O_5 .

For solutions containing less than 0.5% vanadium a weaker permanganate reagent should be used. A fiftieth normal permanganate solution will be found to be useful

for materials low in vanadium.

The author obtained excellent results by the above procedure on materials containing small amounts of iron and chromium; with amounts equal to that of vanadium persent in the solution no interference was experienced. The titration with potassium permanganate is made in cold solutions if chromium is present, as the permanganate will oxidize chromium in hot solutions. Potassium permanganate added to samples containing chromie salts, and the mixture boiled, will oxidize these quantitatively to chromates. This reaction does not take place in cold solutions to any appreciable extent during a titration and only slowly in warm solutions.

Volumetric Determination of Vanadium by Reduction with Zinc to V_2O_2

The procedure proposed by Gooch and Edgar is to reduce vanadic acid, in presence of sulphuric acid, by zine to the oxide, V_2O_2 ; oxidation of the unstable V_2O_2 by the air is anticipated by means of ferric chloride or sulphate, in the receiver of the Jones reductor, the highest degree of reduction being registered by the ferrous salt formed by the reaction of the reduced vanadate on the ferric salt, i.e., $V_2O_2+3Fe_2O_3=6FeO+V_2O_5$. Compounds reduced by zine and oxidized by KMnO₄ must be absent or allowed for.

Procedure. The Jones reductor is set up as directed in the procedure for the determination of iron by zine reduction. The receiver attached to the tube containing the column of zine is charged with a solution of ferric alum in considerable excess of that required for the oxidation of the reduced vanadium. (The amalgamated zine is cleaned by passing through the column, a dilute solution of warm sulphuric acid. The final acid washings should show no further reducing action on permanganate when the reductor is clean.) Gentle suction is applied, and through the column of clean amalgamated zine are passed in succession—100 ec. of hot water, 100 ec. of 2.5% sulphuric acid, and then the solution of vanadic acid diluted to 25 cc. in a 2.5% sulphuric acid solution, and finally 100 ec. of hot

¹ Corrections should be made for the action of zine upon the reagents without the vanadic acids, as it is almost impossible to get a condition where no blank is obtained with permanganate. The reductor is cleaned first by passing about 500 cc. of dilute 2.5% sulphuric acid through the column of zine. A blank is now obtained with the same quantity of reagents as is used in the regular determination, only omitting the vanadium, and this is deducted from the titration obtained for each sample reduced.

water. To the receiver is added a volume of 4 cc. of syrupy phosphoric acid to decolorize the solution. The reduced iron salt is now titrated with N/10 KMnO4.

One cc. N/10 KMnO₄=0.0017 gram V, or =0.00304 gram V₂O₄.

Determination of Vanadium in Steel

The following method is used in analyzing the Bureau's vanadium and chromevanadium steels. The procedure was worked out by J. R. Cain and L. F. Witmer of the U. S. Bureau of Standards.

Five to 10 grams of drillings are dissolved in hydrochloric acid (1:1), a few drops of hydrofluoric are added, and the solution is boiled for a few minutes. The insoluble matter is filtered off, ignited, fused with a little sodium earbonate, the fusion dissolved in water and added to the main filtrate. This is then oxidized with the minimum amount of nitrie acid needed, and boiled till free from fumes. The iron is extracted with ether and the excess of ether removed from the aqueous layer by evaporation on the steam bath. After concentration on the bath, strong nitrie acid is added to the solution and it is evaporated to dryness. The residue is dissolved in strong nitric acid, the solution is diluted with water and nearly neutralized with strong sodium hydroxide solution. It is then poured slowly into 150 to 200 cc. of a 10% sodium hydroxide solution, stirring vigorously. The solution is filtered, and the series of operations are repeated with the precipitate until it is free from vanadium, as shown by dissolving it in nitric acid and testing with hydrogen peroxide. In the latter treatments the amount of sodium hydroxide solution used may be smaller. From the combined filtrates the vanadium is precipitated with mercurous nitrate solution, after making nearly but not quite neutral with dilute nitric acid. After settling, the precipitate is collected on paper and washed with dilute mercurous nitrate solution. The filter is burned off in a platinum erucible and the precipitate ignited till all the mercury is expelled. The impure vanadium pentoxide left is fused with a little sodium carbonate, the fusion is dissolved in water and filtered (on asbestos) from insoluble matter. A second precipitation with mercurous nitrate is then made. Sometimes a further fusion and precipitation may be necessary in order to get a product sufficiently pure for the next step, which is a final fusion with sodium carbonate. The fusion is dissolved in dilute sulphuric acid and the vanadium is reduced by sulphur dioxide gas and titrated against N/50 permanganate after complete expulsion of the excess of reducing agent.

Volumetric Determination of Molybdenum and Vanadium in Presence of One Another

Sulphur dioxide reduces V₂O₄ to V₂O₄, but does not reduce molybdic acid provided the sample contains 1 ec. of free sulphurie acid per 50 ec. of solution and not more than 0.2 gram of molybdic acid. By means of amalgamated zine V₂O₄ is reduced to V₂O₂ and MoO₃ to Mo₂O₃. Upon these two reactions the determination is based according to the procedure worked out by Edgar. Details of the method are given in the chapter on Molybdenum, page 321.

¹ Graham, Edgar, Am. Jour. Sci. (4), 25, 332. Gooch, "Methods in Chemical Analysis," John Wiley & Sons.

Volumetric Determination of Vanadium, Arsenic or Antimony in Presence of One Another. Edgar's Method 1

Tartaric or oxalic acid reduces V2O5 to V2O4, but does not act upon arsenic or antimony. On the other hand SO2 causes the reduction of all three. Therefore if aliquot portions of the solution are taken, one portion being treated with tartaric acid and vanadium determined by titration with iodine, and another portion reduced with SO2 and again titrated with iodine, the difference between the two titrations is due to the cc. of reagent required for the oxidation of the reduced arsenie or antimony.2

Reactions.
$$V_2O_4+I_2+H_2O=V_2O_5+2HI$$
.
 $As_2O_3+V_2O_4+3I_2+3H_2O=As_2O_5+V_2O_5+6HI$.
 $Sb_2O_2+V_2O_4+3I_2+3H_2O=Sb_2O_5+V_2O_5+6HI$.

Vanadium. One portion is boiled with about 2 grams of tartaric or oxalic acid, until the solution turns the characteristic blue of vanadium tetroxide. After cooling, the solution is nearly neutralized with potassium bicarbonate, and an exeess of standard iodine solution added. Neutralization is now completed, an excess of bicarbonate added, and after fifteen to thirty minutes the excess iodine titrated with standard arsenious acid, stareh being used as an indicator. This titration measures the vanadium present.

Arsenic or Antimony. A second portion of the solution is placed in a pressure flask and acidified with sulphurie acid. A strong solution of sulphurous acid is added, the flask closed and heated for an hour on the steam bath. After cooling, the flask is opened and the solution transferred to an Erlenmeyer flask and the excess of SO₂ removed by boiling, a current of CO₂ being passed through the liquid. The cooled solution is treated with bicarbonate, iodine added and the titration conducted exactly as described for determination of vanadium in the first portion. The difference between the first titration and the second is a measure of the cc. required for oxidation of arsenic or antimony.

Determination of Vanadium and Iron in Presence of Each Other

The solution slightly acidified with sulphuric acid is treated with sulphurous acid, the excess expelled and the reduced vanadium and iron titrated with standard potassium permanganate.4

$$10\text{FeO} + 5\text{V}_2\text{O}_4 + 6\text{H}_2\text{SO}_4 + 4\text{KM}_1\text{O}_4 = 5\text{Fe}_2\text{O}_5 + 5\text{V}_2\text{O}_5 + 2\text{K}_2\text{SO}_4 + 4\text{M}_1\text{SO}_4 + 6\text{H}_2\text{O}_5$$

The solution is now reduced with zinc in the Jones reductor and again titrated with permanganate.2 V2Os is reduced by zine to V2O2, the sample being caught

¹ G. Edgar, Am. Jour. Sci. (4), 27, 299.
¹ Gooch, "Methods of Chemical Analysis."

¹ Graham, Edgar, Am. Jour. Sci., (4), 26, 79.
See Am. Jour. Sci., (4), 27, 174, also Gooch, "Methods in Chemical Analysis," p. 510, for procedure determining iron, chronium and vanadium, in presence of one another.
¹ When the color has changed from a bluish-green to greenish-yellow the solution is heated to 70 to 80° C., and the permanganate titration completed in a hot solution

in ferric alum solution (details for determining of vanadium by reduction with zinc are given under the volumetric methods for this element).

 $10\text{FeO} + 5\text{V}_2\text{O}_2 + 12\text{H}_2\text{SO}_4 + 8\text{KMnO}_4 = 5\text{Fe}_2\text{O}_3 + 5\text{V}_2\text{O}_5 + 4\text{K}_2\text{SO}_4 + 8\text{MnSO}_4 + 12\text{H}_2\text{O}_5$

The difference between the two titrations multiplied by 0.00456 = vanadic acid (V2O6) originally present.

Iodometric Method for Estimation of Chromic and Vanadic Acids in Presence of One Another

The following procedure developed by Edgar, is given by Gooch ("Methods of Chemical Analysis").

In carrying out the operation, the alkali salts of the chromic and vanadic acid are put into the Voit flask of the distillation apparatus shown in the cut, Fig. 71. One or 2 grams of potassium bromide are added, the flask is connected with

the absorption apparatus containing a solution of potassium iodide made alkaline with sodium carbonate or sodium hydroxide, and the whole apparatus is filled with hydrogen gas. Fifteen to 20 cc. of concentrated hydrochloric acid are added through the separatory funnel and the solution is boiled for ten minutes, an interval of time found to be enough for the completion of the reduction. A slow current of hydrogen is maintained to avoid back suction of the liquid from the Drexel bottle. The apparatus is disconnected, the Voit flask placed in a beaker containing cold water, and the alkaline solution in the absorption




Fig. 71.

apparatus cooled by running water. The contents of the trap are washed into the Drexel bottle and the solution therein is made slightly acid with hydrochloric acid. The liberated iodinc is titrated with approximately N/10 sodium thiosulphate and the color is brought back by a drop or two of N/10 iodine solution, after the addition of starch.

Alkaline potassium iodide is again placed in the absorption apparatus and the latter connected with the Voit flask. The current of hydrogen is turned on and, after the air has been expelled, the apparatus is disconnected momentarily, 1 or 2 grams of potassium iodide are added to the solution in the Voit flask, and connections made again. Through the separatory funnel 10 cc. to 15 cc. of concentrated hydrochloric acid and 3 cc. of syrupy phosphoric acid are added and the solution in the reduction flask is boiled to a volume of 10 cc. to 12 cc. The absorption apparatus is removed and cooled, hydrochloric acid is added and the liberated iodine titrated with approximately N/10 sodium thiosulphate.

¹ Graham Edgar, Am. Jour. Sci. (4), 26, 333.

The iodine determined in the first titration corresponds to a reduction of the chromic and vanadic acids according to the equation

$$V_2O_3 + 2CrO_3 + 8HBr = V_2O_4 + Cr_2O_3 + 4Br_2 + 4H_2O_3$$

while in the second case the iodine corresponds to a reduction of the vanadium tetroxide to trioxide as indicated in the equation

$$V_2O_4 + 2HI = V_2O_2 + I_2 + H_2O_4$$

The second titration, therefore, determines the vanadic acid present, and the difference between the first and second furnishes the necessary data for the calculation of the chromium.

DETERMINATION OF VANADIUM IN FERRO=VANADIUM

Standard Methods of the American Vanadium Company¹

Dissolve 0.510 gram of the alloy (100 mesh) in a 250-cc. beaker with 50 cc. dilute sulphuric acid (1:2) and 10 cc. (concentrated) nitric acid. If the alloy does not decompose, when heated, add a few cc. of hydrofluoric acid. Take down to copious white fumes. Cool, add 50 cc. dilute sulphuric acid (1:2) and water. Heat until all salts are in solution and transfer to a white casscrole containing 100 cc. dilute sulphuric acid (1:2). Dilute the solution to 400 cc. with H₂O and heat to 60° C. The solution is ready to titrate.

Add potassium permanganate until a deep red is obtained. Just discharge the

red color with ferrous ammonium sulphate. Get the neutral point by alternating the permanganate and ferrous ammonium sulphate until one drop of the ferrous sulphate just discharges the pink color.

Now add N/10 ferrous ammonium sulphate from a burette until the vanadium

is reduced and then 3 cc. in excess.

Titrate the excess of ferrous ammonium sulphate with N/10 potassium bichro-mate, using potassium ferricyanide as an indicator.

· From the cc. of ferrous ammonium sulphate used, subtract the cc. of bichromate used. The number of cc. used gives the per cent of vanadium in the alloy.

The relation between ferrous annuonium sulphato and bichromate is established by adding 150 cc. sulphuric acid (1:2) to a casserole, diluting to 400 cc.

Find the neutral point and then add 25 cc. ferrous ammonium sulphate and titrate with bichromate until the blue spot is just discharged. TYAMDI D

Blank.	EXAMPLE
Ferrous ammo	nium sulphate used
Potassium bich	romate used 24 g (6
20020010111 0.01	25.00
	24.60
	21.00
	$.40 \div 25 = -0.016$ factor.
Alloy.	.40 720 0.010 factor,
Horrous ammo	nium guluhata ugad 40.00
Determine high	nium sulphate used
10tassium bici	romate used
40 co. x -0.010	64 cc.
40.00-0.64	=39.36 **
Correction on ferr	ous ammonium sulphate:
$39.36 - 2.4 \dots$	=36.96% V.
Solutions used:	
N/10 potassium	n bielromate.
N/10 ferrous a	mmonium sulphate.
	nide, a crystal the size of a pea in 50 cc. of water.
	ganate, 5 grams per liter.

¹ Methods developed in the Bridgeville Laboratory. By courtesy of the American Vanadium Company.

Determination of Vanadium in Vanadium Ores

Weigh 0.51 gram of the finely powdered ore in a 1½-in. diameter iron crucible filled three-fourths full of sodium peroxide. Fuse. Dissolve the fusion in water and add 100 cc. $\rm H_2SO_4$ (1:2) in excess and evaporate until white fumes come off. Cool and dilute and filter. Gas the filtrate, which should be about 400 cc., until all $\rm H_2S$ metals are precipitated. Boil and filter. Boil the filtrate until all $\rm H_2S$ is off. Transfer to a 500-cc. casserole and add 50 cc. $\rm H_2SO_4$ (1:2) and heat to above 60° C. Titrate as in the determination of vanadium in ferro-vanadium.

Determination of Vanadium by Precipitation with Phosphomolybdate

The alloy or steel is dissolved in nitrie acid and treated, dropwise, with strong potassium permanganate until a precipitate of MnO₂ is obtained on boiling. Ammonium bisulphite solution is now added drop by drop until the manganese dissolves. The solution is boiled until the nitrogen oxides are expelled. 10 ee. of a 5 per cent ammonium phosphate solution and 10 grams of animonium nitrate are added, the solution heated to boiling, and 50 ec. of ammonium molybdate solution added. The solution is shaken for 3–5 minutes to precipitate all of the vanadium and phosphorus. The precipitate is separated by decanting onto an asbestos filter. The precipitate is dissolved in conc. H₂SO₄, the iron oxidized by HNO₃, the nitric expelled by fuming off and the vanadium now reduced by adding hydrogen peroxide and heating. The addition of peroxide and heating is repeated. The green or blue solution is heated to 80° and titrated with 0.1N KMnO₄ as usual.

Vanadium in Steel—A. S. T. M. Method

SOLUTIONS REQUIRED

"Dilute Hydrochloric Acid (2:1).—Mix two parts of HCl (sp.gr. 1.19) with one part of water.

part of water.
"Dilute Nitric Acid (sp.gr. 1.20).—Mix 380 cc. of HNO₃ (sp.gr. 1.42) and 620 cc. of distilled water.

"Dilute Hydrochloric Acid (1:9).—Mix 100 ec. of HCl (sp.gr. 1.19) and 900 cc. of distilled water.

Метнор

"(a) (When Cobalt does not exceed 1 per cent.)

"Treat 2 g. of the steel in a porcelain dish with 70 ee. of dilute HCl (2:1) and heat until all action ceases. Cantiously add 10 ee. of dilute HNO₂ (sp.gr. 1.20) and evaporate the solution to dryness or to low bulk. Treat the residue with 45 ee. of dilute HCl (2:1) and heat until the soluble portion dissolves. Add an equal volume of water, boil for three minutes, filter and wash the residue thoroughly with dilute HCl (1:9) until free from iron. Evaporate the solution to small volume and destroy hydrochloric acid by small additions of nitric acid (sp.gr. 1.42) followed by boiling. If a residue appears, filter the solution. From this point proceed for chromium as in the Determination of Chromium in Chrome-Nickel Steel by the Persulphate Oxidation Method and for Vanadium as in the Determination of Vanadium in Chrome-Vanadium Steel by Reduction with Ferrous Sulphate and Titration with Permanganate.

"(b) (When Cobalt exceeds 1 per cent.)
"See the Determination of Vanadium in Chrome-Vanadium Steel by the Elec-

trolytic Separation Method.

"Proceed as described in this method until the bicarbonate precipitate has been when with hot water. Return the paper and precipitate to the flask and add 60 cc. of dilute HCl (2:1). Heat the solution, add 10 cc. of HNO₃ (sp.gr. 1.20) and evaporate the solution to dryness or to a small volume. Treat the residue with 45 cc. of dilute HCl (2:1) and proceed as described above.

Notes

"Tungsten interferes with the determination of vanadium by the above method and must be removed. While chromium can be determined in the presence of tungsten, it is conveniently determined in the same sample as is vanadium and the end point is easier to get when tungsten has been removed.

"In case hydrochloric acid is present when silver nitrate is added, enough of the latter must be added to take care of this before the regular addition is made.

"The pink color of cobalt interferes with the end point readings. If under 1 per cent, the color does not seriously affect the results, if over this, it should be removed."

Determination of Vanadium in Steel (When Chromium is present)

Dissolve 5.1 grams of steel in a covered 400-cc. beaker with 60 cc. of HCl (concentrated). After total solution, add concentrated HNO₃ sufficient for complete oxidation. Evaporate to a syrupy consistency, add 40 cc. HCl (concentrated) and evaporate to about 20 cc. Cool and transfer contents to a separatory funnel, washing with dilute HCl (2 HCl: 1 H2O). Add 100 cc. ether, cork and shake for some time, cooling funnel under tap water while shaking. Removo cork, place funnel in stand and allow it to stand for at least five minutes. Run out the lower layer of the separation into the original 400-cc. beaker.

Evaporate the ether off. Add 5 cc. HNO₃ (concentrated) and just bring to a boil, Stir out all nitrous fumes, make alkaline with NaOH (saturated solution). Make just acid with HNO, (concentrated) cool solution.

Add above solution to a solution containing 300 cc. cold water and 5 cc. of NaOH (saturated solution). Boil and filter, washing with hot water thoroughly. Make filtrate just acid with HNO; (concentrated). Add 40 cc. of a saturated solution of lead acetate. (If lead precipitate forms just clear solution by adding HNO; drop by drop and bring to a boil.) Add 60 cc. of ammonium acetate. Boil for twenty minutes.

The vanadium is precipitated as lead vanadate.

Filter the lead vanadate onto a Munktell paper, washing with hot water. Put filter containing lead vanadate in a small porcelain dish and burn off paper at a low heat. Add a little HNO₃ and evaporate on the hot plate, then put the dish in the cold end of a muffle to drive off the remaining HNO₃. Avoid baking. Dissolve in HCl (concentrated) and transfer the solution to a 400-cc. beaker. Add 60 cc. dilute H₂SO₄ (1:2). Oxidize thoroughly with KMnO₄ (5 grams to a liter.) Add 40 cc. HCl (concentrated) and evaporate to dense white fumes. Cool, add 40 cc. or water and again take to white fumes. Cool, add 150 cc. of water, cool, and titrate with N / 50 KMnO₄. Each co. of paragraphs a used is equal to 0.00102 gram of with N/50 KMnO. Each ce. of permanganate used is equal to 0.00102 gram of vanadium, or in this case, having used a ten-factor weight, each ce. represents 0.02% vanadium.

NOTES.

Vanadium is used chiefly in steel for purposes requiring great toughness and vanadium is used emery in steel for purposes requiring great foughness and torsional strength, common applications being in automobile parts, gears, piston rods, tubes, boiler plates, transmission shafts, gun barrels, and forgings that have to withstand great stresses and wear. The vanadium content in steel usually ranges from 0.1 to 0.4%. Vanadium is also used occasionally in certain tungsten alloy steels for making high-speed steel. Introduced in small proportions, it reduces considerably the amount of tungsten required in steel for a given hardness and toughness. Vanadium differs from tungsten in that it has a good effect not only on troughter but on structural steel from tungsten in that it has a good effect not only on tool steel, but on structural steel as well.

Chrome-vanadium steels and chrome-vanadium-molybdenum steels are the latest developments in structural alloy steels that have gained an extensive market. Almost all these steels are made in the open-hearth furnace, chromium and vanadium alloys being added shortly before easting. In their physical properties these steels are much like chrome-nickel steels, but they have a greater contraction of area. Most of the chromium-vanadium steels made go into automobiles. Some manufacturers prefer them because of their greater freedom from the surface imperfections—notably seams

which the steels containing nickel are likely to have.

¹ Machinery, June, 1924.

Determination of Vanadium in Ores, Mine and Crude Mill Samples¹

Reagents Indicator. K₃Fe(CN)₆. Make up just before using in a drop bottle which has been washed out with NaOH and then with water. Place a small crystal of the salt in the bottle and wash several times to remove the oxidized coat, pouring out the washings, then add about 30 ec. of distilled water and dissolve for use.

Ferrous ammonium sulphate, FeSO₄(NII₄)₂SO_{.5}H₂O. 135 grains of the sult are

dissolved in a mixture of 333 sulphuric acid and 3000 cc. of water.

Standardize the solution as follows: Take 25 cc. of the solution and add 25 cc.

H₂SO₄. Dilute to 400 cc. and titrate with standard K₂Cr₂O₇ reagent using K₃Fe(CN)₆ indicator according to the procedure used in the determination of iron.

Potassium permanganate,— $KMnO_4$. 3.162 grains per liter. Potassium dichromate, $K_2Cr_4O_7$. 4.903 grains per liter. Standardize with 1/2 grain of iron wire. (I cc. = .056 g. Fe.)

PROCEDURE. Solution of the Sample.

Take 2.04 grams of the ore, ground to pass through a 60-mesh screen. Fuse with (about 20 times its volume), sodium peroxide in a 25 cc. iron crucible. (If the mixture can be thoroughly eintered, it is better than a complete fusion.) Take up the mass with water in a 600 cc. beaker. Add a solution of 50 cc. strong sulphuric acid diluted with 100 cc. of water. Then dilute to 400 cc. with water.

Titration. Heat to about 80° F, and add just sufficient of the permanganate reagent

to make the solution pink. Titrate back with a few drops of ferrous ammonium sulphate reagent until the color of the permanganate just disappears. The solution will now appear a green or blue color. Now add the "ferrous" solution until the ferric cyanide spot test shows a faint blue color. Then 2 ce, excess of the "ferrous" solution. Titrate back the excess with the standard potassium dichronate reagent until a drop of the

indicator shows no color on the spot plate, with a drop of the solution.

Calculate the ratio of the ferrous solution and the dichromate to a common basis.

Deduct the cc. dichromate from the cc. "ferrous" added to the bluish green solution above, and divide the result by 4. With an exactly N/10 solution the result will be the

percent vanadium in the sample.

Lead Acetate Method. The solution obtained from the fusion of the ore (see Solution of the sample) is acidified with acetic acid. Then sufficient lead acetate is added to completely precipitate the vanadium (usually 2 or 3 grams, according to the amount of vanadium in the sample), the solution is stirred, allowed to settle and the lead vanadate filtered off and treated as follows.

Take the residue on the filter (this at first appears yellow) and dissorve in a very dilute solution of nitrie acid. The acid should be hot. Transfer to an 800 cc. beaker. Add about 10 cc. of concentrated sulphuric acid and evaporate to fumes of SO₁.

All traces of nitrous oxide must be expelled. Dilute to 600 cc. with distilled water, add 25 cc. of concentrated sulphuric acid, hat and titrate with standard permanganate according to the first of the volumetric procedures.

Determination of Vanadium in Cupro-vanadium, Brasses and Bronzes

Dissolve 1.020 grams of cupro-vanadium in aqua regia. Evaporate to small bulk and add excess of peroxide of hydrogen. Dilute to 600 ce. and add ammonia until all copper goes into solution. Heat to boiling and add sufficient barium chloride solution to precipitate all the vanadium. Boil and filter. Wash all copper out of filter with hot ammonia water. Transfer the filter to a beaker, add 100 cc. 1:2 sulphuric acid, boil and filter on close filter paper. Titrate the filtrate with N/10 ferrous ammonium sulphate and N/10 potassium hichronate the same as in the case of the ferro alloy, except that this being a two-factor weight, the result must be divided by 2.

Vanadium copper, brasses and bronzes are treated in the same manner except that a ten-factor weight is used and the titration carried out with N/50 solution instead

of N/10.

¹ Communicated to the author by Theodore Marvin, Dupont Powder Company.

VOLUMETRIC-PHOSPHOMOLYBDATE METHOD FOR DETERMINATION OF VANADIUM

Reagents

Ammonium Molybdate. See page 1363 for phosphorus in steel.

Ammonium Phosphate. 50 g. salt per liter of water.

Acid Ammonium Sulphate. 50 cc. strong H₂SO₄, 950 cc. water and 15 cc. strong ammonium hydroxide. Use hot, 80° C.

Nitric Acid. 100 cc. strong HNO, and 1200 cc. water.

Nitric Acid for Washing. 20 cc. strong HNO₃ per liter.

Potassium Permanganate, Standard. 0.35 g. salt per liter of solution. Standardized against sodium oxalate. Adjust so that 1 cc. will equal 0.0005 g. vanadium, or 0.02 per cent on a 2.5-g. sample. 1 g. Na₂C₂O₄=0.7612 g. V. Potassium Permanganate, for oxidation. 25 g. salt per liter of solution.

Sodium Bisulphite, for reduction. 30 g. salt per liter of solution.

Procedure for Steel

A sample of 2.5 g. of steel in a 300-cc. beaker or Erlenmeyer flask are dissolved in 50 cc. of the nitric acid, and to the boiling solution are added 6 cc. of the permanganate oxidation solution, the boiling being continued until MnO2 precipitates. The precipitate is now dissolved by cautious additions of sodium bisulphite solution and the boiling continued until no brown fumes are evident. Now 5 cc. of ammonium phosphate solution are added and 10 g. ammonium nitrate. The solution is removed from the heat and 50 cc. of ammonium molybdate reagent immediately added. After standing for 1 minute, the solution is agitated for 3 minutes, then allowed to settle and the clear solution decanted through an asbestos filter, the residue is washed three times with hot acid ammonium sulphate reagent, decanting each time through the filter. The flask containing the bulk of the residue is placed under the filter. (The washings are best conducted with suction, using a bell jar filter.) The precipitate on the filter is dissolved by successive portions of hot strong H₂SO₄, catching the solution in the vessel containing the bulk of the precipitate. The precipitate is now dissolved by heating and to the solution a few drops of the nitric acid are added and the heating continued to strong fumes.

The solution is cooled and hydrogen peroxide added in small quantities with vigorous shaking after each addition, until the solution takes on a deep brown color. The solution is again heated for 4 or 5 minutes, then cooled and 100 cc. of water added, the solution again heated to about 80° C. and titrated to a permanent pink color with standard potassium permanganate.

NOTE. If the peroxide treatment followed by heating does not result in a clear green or blue color, the solution should be evaporated to strong sulphuric acid fumes and the peroxide treatment repeated. The presence of nitric acid interferes with the reduction of vanadium.

VANADIUM IN STEEL—ETHER EXTRACTION—HYDRO-CHLORIC ACID REDUCTION METHOD

Reagents

Hydrochloric Acid. 600 ee. strong HCl and 400 ee. water.

Sulphuric Acid. Equal volumes of strong H₂SO₄ and water.

Other Reagents. See Phosphomolybdate Precipitation Method for Vanadium.

Procedure

A sample of 2.5 g. of steel in a 250-cc. beaker is dissolved in 50 ee. of the HCl, and then small portions of HNO3 added to oxidize the iron. After expelling the brown fumes by heating, the solution is cooled and transferred to an 8-oz. separatory funnel, together with the rinsings (small portions of HCl) of the beaker. Now 50 cc. of ether are added and the mixture shaken for 5 minutes. After settling for 1 minute the clear lower layer is drawn into another separatory funnel. The first funnel is treated with 10 cc. of strong HCl, again shaken vigorously and the settling repeated, the lower layer being added to the solution in the second separatory funnel. The combined solutions in the second separatory funnel are treated with 50 ec. of ether and shaken for 5 minutes, allowed to settle 1 minute and the clear lower layer drawn into a 150-ec. beaker. This aqueous solution is warmed gently to expel the ether, 25 ec. of the H2SO4 (1:1) added and the mixture concentrated to strong fumes. After cooling, 25 cc. of water are added followed by a slight excess of potassium permanganate solution and the sample heated to boiling. 15 ee. of strong HCl are added and heat applied until the solution again fumes. The heating is continued for 10 minutes. After cooling, 100 cc. of water are added, the solution heated to 80° C. and titrated with standard potassium permanganate reagent to a permanent pink color.

Notes. In heating the solution to expel the brown fumes of oxides of nitrogen, the solution should not be boiled.

In presence of chronium, the pink color will fade on standing owing to the oxidation of chromium. The oxidation of chromium is reduced by titrating the solution cold, but only ten seconds are allowed for the pink color to remain. A blank must be run with the same amount of chromium and allowance made for its oxidation. The blank is conveniently made by putting a suitable amount of chrome steel or chrome-nickel steel through the recommended procedure. By varying the amounts of steel and hence the amount of chromium in solution, data for a charted curve may be obtained that will be convenient for a blank deduction.

Preparation of a Gooch Crucible

Asbestos Fibre.—The asbestos for use in Gooch crucibles should be carefully selected. The fibres should be moderately stiff, not the "cottony" type. Cut the fibre into pieces about ½ inch long. Ignite the asbestos in a platinum dish at low red heat. Cool and transfer to a clean porcelain mortar and mascerate to a pulp with strong hydrochloric acid. Dilute with water and transfer to a large beaker containing 600-800 ec. of water. Stir thoroughly, allow to settle and pour off the milky water. Repeat the washing with water until the milkiness, due to powdered fibres, is scarcely evident. Now filter off the asbestos onto a Buechner funnel. Again wash with water until free of acid. Transfer to a wide mouth bottle, add water in sufficient amount to form with the stirred up fibre a thin suspension of asbestos. This is now ready for use. If preferred the asbestos may be dried and kept in this form until desired.

Preparation of the Filter. The erucible, either of platinum or porcelain, having a perforated bottom, is placed in a funnel tube and the apparatus set up as is shown in Fig. 71a. The suction bottle holding the Gooch is attached to a second bottle, if a water filter pump is used to obtain the vacuum, as there is danger of water being sucked into the apparatus from the tap. Suction is now applied and a small amount of the finely suspended asbestos is poured into the crucible, in amount sufficient to form a thin pad of the material about $\frac{1}{16}$ inch thick over the bottom of the Gooch. The felt is washed with distilled water, the asbestos drawn down hard. It is possible to see light through the bottom of a properly made filter. The crucible is placed in an




Fig. 71a. Filtering Through a Gooch Crucible.

oven and the filter dried to constant weight at 110° C. For BaSO₄ and AgCl determinations it is advisable to make the filter about twice the above thickness to prevent the precipitate from passing through. Whenever the Gooch crucible is used, suction should be applied before pouring material into the crucible and the suction continued during the washing of the precipitate.

Zn. at. wt. 65.38; sp.gr. 6.48 to 7.19; m.p. 419°; b.p. 920°; ZnO oxide.

DETECTION

The finely powdered material, when heated on charcoal in the reducing flame of a blowpipe, gives an incrustation, yellow when hot—white when cold. On moistening with cobalt nitrate solution and re-igniting, the mass is greenish-yellow. Materials containing above 5% Zn will give positive tests. With experience, less can be detected, but for smaller amounts the regular procedure as given under Titration in Acid Solution, Separating Zn as ZnS, should be followed, using samples as follows: For material containing 0.01-0.05%, 10 to 20 grams; 0.05-0.10%, 5 to 10 grams; 0.10-0.5%, 5 grams; 0.5% on up, 2 grams to 0.5

gram, depending on per cent of zinc present.

In case the material is of interest, only if it carries higher than several per cent of zinc, a shorter and easier wet test is to bring the material into solution by means of hydrochloric or nitric acid, add bromine water and then precipitate iron, aluminum and manganese with ammonia, as given under heading of Determination of Zinc in Acid Solution, Separating Iron, Aluminum and Manganese with Ammonia and Bromine, filter, wash and make the filtrate acid with hydrochloric acid, 10 cc. excess added for each 100 cc. of solution, and potassium ferrocyanide added. Zinc, if present, gives the characteristic precipitate. Copper interferes and if present must be separated with hydrogen sulphide, as given under heading Procedure for Copper-bearing Ores.

In case manganese and copper are known to be absent, a still shorter test may be used: To the solution of the zinciferous material add 2 or 3 grams of citric acid per 200 cc. solution, then make ammoniacal, add ferrocyanide—a white

precipitate indicates zine.

ESTIMATION

The determination of zinc is called for in the buying and selling of ores for smelters, refuse material, e.g., from galvanizing plants, foundrics, brass mills, and blast furnaces, in manufacture of brass, white metals, and alloys in-general, paints and pigments, zinc chloride for preservation purposes, and in the control work in smelting of zinc and lead ores.

Preliminary. The method to be followed in the estimation of zinc will depend largely on the nature of the material in which it occurs, the quantity present, and the experience of the analyst. Each of the methods outlined will give correct results only on the materials for which they are indicated, there being but one method recommended which is applicable to all zinciferous mate-

rials. It cannot be emphasized too strongly that each step has a definite purpose (which may not be at once apparent to the analyst making only an occasional zinc determination), and no part of the procedure should be varied or omitted, excepting after abundant experience.

Preparation of Sample

The representative sample should be ground to pass a 100-mesh screen or finer. If the material contains shot metal, it should be screened out and the percentage present calculated. It is then treated as given under heading Material Containing Metallics, page 602.

Moisture Determination in the Pulp

One of the commonest causes of differences in zinc ore analysis is the failure

to take moisture determinations on the pulp sample.

In order that analyses made on the same pulp at different times and in different laboratories may be compared it is absolutely necessary that all determinations be corrected to a dry basis. It is not sufficient that the sample be dried before or after having been pulped, but a sample for moisture must be weighed out at the same time as the sample for analysis, and the analytical result corrected for the per cent of moisture found at the time of weighing. This is especially true on roasted zinc ores which contain sulphates of zinc, iron and lime and which take up moisture quite rapidly under ordinary atmospheric conditions.

The usual temperature for drying should be 110° C., but on special ores, e.g., those containing sulphates, it is necessary to dry at 250° C. unless it is first shown

that there is no loss of water above 110° C.

The determination is best made by weighing approximately two grams in a small glass-stoppered weighing tube and drying to constant weight, the weighing tube being closed with the glass stopper as soon as the tube is taken from the drying oven.

SEPARATIONS

Silica. Evaporate with hydrochloric acid or take to fumes of sulphuric acid. The dehydration with sulphuric acid is complete and gives silica that is easily filtered and washed.

Cadmium, Lead, Arsenic, Antimony, Bismuth and Copper. Aluminum may be used to separate all the metals, except cadmium, the latter being only

partially separated. The procedure is as given in the standard method.

The separation may also be made as follows: Evaporate the solution of the sinciferous material to fumes with 7 cc. of 1: 2 sulphuric acid. Cool, take up in about 50 cc. of water and warm, add 10 cc. of 10% sodium thiosulphate, boil until evolution of sulphur dioxide ceases, then filter. Cadmium if present is not precipitated. It should be separated by the procedure given under Titration in Acid Solution Separating Zinc as Sulphide.

Iron, Aluminum and Manganese. This separation may be effected by precipitation with ammonia and bromine, providing the quantities present are small. When large amounts are present the basic acetate procedure is followed, or. better, the sinc separated as sulphide in dilute sulphuric acid solution, page 605.

Nickel and Cobalt. When nickel or cobalt are present, the only safe procedure is to separate the zinc as zinc sulphide in dilute sulphuric acid solution, as described under the standard method. Weiss has shown conclusively that zinc can be precipitated free from either cobalt or nickel under the conditions there outlined.

METHODS OF ANALYSIS

- I. Gravimetric methods.
- II. Electrolytic methods.
- III. Titration with standard solution of K4Fe(CN).
 - (a) In acid solution.
 - (b) In alkaline solution.
 - (c) In acid solution, separating Zn as ZnS. (Standard method.)

GRAVIMETRIC METHODS

Weighing as Zinc Oxide

In this case the procedure is the same as in the volumetric method, in which zine is separated as zine sulphide up to point where the zine sulphide is filtered off and washed. It is now ignited in a weighed crucible and heated to 800 to 900° C. in a muffle for one hour and weighed as ZnO. Factor $\text{ZnO} \times 0.8034 = \text{Zn}$.

The precipitate of zinc sulphide may also be filtered on a Gooch crucible, and ignited as above.

Weighing as Sulphate

The zine sulphide is dissolved in hydrochloric acid. Sulphuric acid is added and the solution evaporated in a weighed crucible, all excess acid funcd off and the resulting zine sulphate finally ignited at a dull red heat and weighed. $ZnSO_4 \times .405 = Zn$.

Electrolytic Methods

The determination is best made from an alkaline electrolyte or one slightly acid with acetic acid and containing a considerable amount of sodium acetate. The alkaline electrolyte tends to give high results, due to the presence of zinc oxide or hydroxide in the deposit. The best results are obtained with a solution weakly acid with one of the weaker organic acids. The procedure for the acetate electrolyte is as follows:

The zinc is separated from other elements by precipitating with hydrogen sulphide in dilute sulphuric acid solution, as given under the standard method. The precipitate is filtered and washed, dissolved in hot hydrochloric acid—5 cc. 1: 1 sulphuric acid added and the whole evaporated to fumes to expel hydrochloric acid. Cool and dilute, neutralize with sodium hydrate solution, make slightly alkaline, then acidify with acetic acid, and add about 5 grams of sodium acetate. The volume of solution should now be about 100 to 125 cc. Electrolyze with a platinum gauze electrode with 0.5 ampere at 5 volts.

The electrolytic methods, on account of the special apparatus needed, the experience and earc necessary to get reliable results, and the unavoidable errors involved in their use, are less desirable than the gravimetric oxide method and still less desirable than the ferrocyanide method.

VOLUMETRIC METHODS

Titration in Acid Solution, Separating Iron, Aluminum, and Manganese with Ammonia and Bromine

General. This method is especially adapted to material low in silica, alumina. iron, and manganese. When the operator gains experience in manipulation, it is, possible to obtain good results on samples higher in these elements, but its haphazard use with materials high in those impurities is one of the chief causes of the common inaccuracy of zinc work. If copper or cadmium are present in quantities, the titration in acid solution, separating Zn as ZnS, is to be preferred for accurate work.

Procedure for Ores. One-half or 1 gram (depending on the per cent of zinc present) is weighed in a 250-cc. beaker. Fifteen cc. of hydrochloric 1 acid (sp.gr. 1.2) are added, a cover-glass put on, and the ore agitated to prevent caking. Boil down to a volume of about 5 cc.2 cool, wash down cover-glass and sides of beaker with a jet of water. Add 10 cc. of saturated bromine water, 5 grams of ammonium chloride and 15 cc. of ammonia water (sp.gr. 0.90) and boil vigorously for a minute or two. Filter off the precipitated hydroxides, and wash four times with hot water, containing 50 grams ammonium chloride and 25 cc. ammonia per liter. The precipitate is now washed from the filter into the beaker in which the original precipitation was made, and the precipitate dissolved in strong hydrochloric acid. Ten cc. of ammonia (sp.gr. 0.9) are added, the solution boiled, filtered and washed as before, the filtrate being combined with the first filtrate.3 The solution is then diluted to 250 cc., heated to boiling, and 4 drops of ammonium sulphide solution added to destroy oxidizing agents and precipitate small amounts of copper and cadmium. The solution is neutralized with hydrochloric acid, the resolution of the precipitated zinc sulphide serving in lieu of an indicator. Ten cc. excess of concentrated hydrochloric acid are added and the solution titrated, not below 75° C., with standard ferrocyanide, using uranium nitrate (10% solution) as an external indicator.

Standardization of the Ferrocyanide Solution

The potassium ferrocyanide is standardized by weighing out portions of C.P. zinc that will give a titration of approximately the same number of cc. as the sample. Dissolve in 15 to 20 cc. of hydrochloric acid and dilute to about 225 cc.

1 Nitric acid should be added in case of sulphide ores.

In case of siliceous ore, it is advisable to evaporate to dryness, and on unknown material to evaporate slowly, in order to make sure of complete solution of the zinc. Certain siliceous and oxide ores are difficultly soluble in hydrochloric acid, and frequently cause low results, where rapid decomposition is the routine.

³ In case of high silica, alumina, iron, and manganese materials, three precipitations are necessary.

It is necessary to destroy all oxidizing agents, as they will react with the ferrocyanide. ⁵ The excess of hydrochloric acid should be carefully measured. A burette is very

*useful in neutralizing the solution.

The strength of the uranium nitrate is a matter of personal preference, some using a saturated solution. On the other hand some prefer ammonium molybdate. The strength or solution given above, however, is recommended as the first choice of a large number of experienced zinc chemists.

*In presence of manganese 10 cc. of saturated bromine water are added.

Then add 37 cc. strong ammonia, taking care to avoid spattering, heat to boiling, add 4 drops of ammonium sulphide, neutralize and add 10 cc. excess hydrochloric acid and titrate.

General Notes

The precipitate with ammonia carries down zinc. The is especially true with siliceous material or material high in iron and alumina. By working with hot ammoniacal ammonium chloride solution and making two or three precipitations, the amount held can usually be made negligible.

The precautions in regard to adding ferrocyanide and keeping conditions of standardization and titration the same, hold here as in all ferrocyanide titrations.

Titration in Alkaline Solution

General. This procedure is designed for rapid routine work on roasted or oxidized ores, especially those high in silica, alumina, iron, and manganese. It should only be used on unroasted sulphides, copper, or high cadmium-bearing ores, when the operator has had long experience. It is designed to give the zinc content of materials soluble in hydrochloric or nitric acid. For materials containing insoluble zinc, the titration in acid solution, in which zinc is separated as sulphide, is preferred.

Procedure for Common Ores. The following method is recommended: The weight of ore to be taken will depend on the approximate amount of zinc present. For material above 50%, take 1 gram; from 10 to 50%, 2 grams; 5 to 10%, 4 grams; and below 5%, 5 to 10 grams. Weigh the sample into a tall 400-cc. beaker, cover with water and add 25 cc. concentrated hydrochloric acid, rotating the beaker to prevent caking. In case sulphides are present, nitric acid also should be added. Place on a hot plate or steam bath and evaporate to dryness. Now add 40 cc. concentrated nitric acid, cover with a watch crystal and boil off all nitrous fumes. When these have disappeared, add about 3 to 4 grams KClO, and boil until chlorine fumes do not show. Cool, wash off the watch crystal and sides of the beaker, and dilute to about 100 ec. Wash into 500 cc. graduated flask, make up to the mark and shake well. Filter through a close 24-cm. qualitative paper and without waiting for the whole to run through, measure out 250 cc. of the clear filtrate 4 into a 600-cc. beaker. Add ferric nitrate solution, if necessary, so as to bring the iron content up to about 300 to 400 milligrams, i.e., if only a small amount is present, add 10 cc.; if 10 to 15% is present, add 5 cc., and proceed exactly as under Standardization.

Procedure for Copper-Bearing Ores. Either method is recommended: Separation of Copper by Aluminum. The sample is treated as usual up to

ciably volatile at higher temperatures.

¹ The amounts of acid and ammonia used throughout should be carefully measured, so as to keep the amount of ammonium salts approximately the same. This is very important in order to avoid errors, due to varying blanks.

The temperature of the hot plate should not be over 120° C., as ZnCl₂ is appre-

Any oxidizing agent such as chlorine or chlorine oxides acts on the ferrocyanide. The graduated flasks should be standardized against one another, i.e., the 500 cc. should be twice the volume of the 250 cc.

the point where manganese has been separated and 250 cc. of the clear filtrate measured out. Add 25 cc. 1:1 sulphuric acid and evaporate to strong fumes, cool, dilute to 100 cc., add a gram or two of 20-mesh zinc-free aluminum. Heat until all the copper separates, filter, wash and proceed with the filtrate as in the regular method, after oxidizing iron with a few drops of nitric acid.

Separation of Copper by Hydrogen Sulphide. After separation of the manganese with chlorate, sulphuric acid is added and the solution taken to fumes, as in above. Cool, dilute to 100 cc., and add sulphuric acid so that 12% is present. Warm slightly and pass hydrogen sulphide through the solution. Filter off the copper sulphide, wash, boil H₂S out of the filtrate, and titrate as usual, after adding ferric nitrate and citric acid.

Material Containing Cadmium. If the material contains cadmium in quantities sufficient to warrant separation (0.15% or more), it is best to use the titration in acid solution, separating zinc as sulphide.

Material Containing Carbonaceous Matter. If the material under examination contains carbonaceous matter, coal, etc., it must be separated by taking to dryness with hydrochloric acid. Take up in acid and water, filter and wash, and evaporate the filtrate to dryness. Take up in nitric acid and proceed as in the regular method.

If the carbonaceous material is not removed, the manganese does not separate cleanly, due to the reducing action of earbonaceous compounds.

Procedure for Material Containing Metallics. On account of the lack of uniformity in the case of metallic zinciferous material containing lead and iron, it is well to work on large samples. Five or 10 grams of the metallics reduced to as fine a size as possible are weighed out and dissolved in nitric acid. The nitrous fumes are boiled off and the whole made up to 500 cc. or 1000 cc. Fifty or 100 cc. are now pipetted off into a 600-cc. beaker and the zinc titrated as usual. In case the metallic portion contains manganese, which is unusual, it can be separated by the regular procedure. Copper is separated as given under Copper-bearing Orcs. Material containing cadmium should be analyzed by other methods, as given under Standard Procedure.

Solutions

Potassium Ferrocyanide. 34.8 grams pure salt in 1000 cc. water. One cc. = approximately .0075 g. Zn. This solution should be allowed to stand about four weeks before using.

Ferric Nitrate. One part salt in 6 parts water. It is well to add a little nitric acid to prevent hydrolysis.

Citric Acid. One part acid in 3 parts water. One hundred cc. of nitric acid should be added to each liter to prevent mould growth.

Standardization. The factor for the standard solution varies slightly, as would be expected, with the amount of ferrocyanide used, so that it is best to have at least three sets of factors, one at 40 cc., one at 20 cc., and one at 10 cc.

Weigh into 600-cc. beakers at least three portions of C.P. zinc. Dissolve the metal in about 10 cc. nitric acid, first covering with water. Boil off the nitrous

fumes and dilute to 250 cc. with distilled water. Add 10 cc. of ferric nitrate solution, and 15 cc. citric acid solution, make faintly ammoniacal, using a piece of litmus paper as indicator. Then add a measured excess of ammonia, as follows: 40 cc. factor, 20 cc. excess; 20 cc. factor, 10 to 12 cc. excess; and for low titrations make only faintly ammoniacal. Heat the solution to a full boil, and titrate immediately with the standard ferrocyanide, stirring the solution thoroughly and adding ferrocyanide not too rapidly. The titration is completed when a drop of solution gives a bluish-green coloration with a drop of 50% acetic acid on a spot plate. To prevent passing the end-point, or until the operator is experienced, a portion (50 cc.) of the solution may be held back in a small beaker, the end-point passed, and the titration completed after adding the part in the small beaker.

General Notes

A standard zine solution may be used in case the end-point is passed. However, this is not to be recommended as a usual practice. In any case it should be very

dilute, so that 1 ce. =0.001 gram zine.

The ferrocyanide should be added gradually and the solution stirred constantly, to prevent occlusion of ferrocyanide or zine solution by the heavy precipitate.

A moisture sample should be weighed at the same time as the sample for analysis.

The variation of factor with amount of zinc titrated is more marked in this method than in the titration in acid solution. Hence, it is necessary that standards be run covering the whole range of zincs to be titrated. It will be found that the factors from 30 to 50 ee. are almost the same and from 15 to 30 cc. slightly lower, from 5 to 15 cc. still lower.

The zine used as a standard should be carefully examined for foreign particles and oxidized zinc. In case stick zinc is used, the surface should be scraped clean before cutting. Merck's and Kahlbaum's stick zinc, as well as Baker & Adamson's, Limer & Amend's, or J. T. Baker's powdered zinc answer the purpose as regards metallic impurities. It is desirable to check the factor by means of a standard

The standard of the ferrocyanide solution should be frequently checked, at least once every ten days. A solution of such a strength that 1 ec. equals 10 milligrams of zinc has in glass a temperature coefficient sufficient to decrease the factor 0.2 % per 5° C. rise in temperature, so care should be taken that no sharp change of temperature occurs between standardization and titration.

The factors in alkaline and acid solution are not identical. In alkaline solution the precipitate closely approaches the normal ferrocyanide, while in acid solution there is formed a double ferrocyanide of zine and potassium.

Standard Method

Titration in Acid Solution-Separating of Zinc as Sulphide

General. The method of separating zinc as sulphide in a solution slightly acid with sulphuric acid is of almost universal application, and can be used on any class of zinciferous material that has come under the author's observation. The steps fit together, so that copper and cadmium are easily separated and any zinc in the insoluble state, e.g., spinels, ctc., can readily be looked for. The method of decomposing (taking to fumes of sulphuric acid) tends to take into solution material that would be overlooked in the rapid decompositions effected in the preceding methods. Moreover, the use of the internal indicator gives a very sharp end-point, so that this method is fully as accurate as any gravimetric method. The method is more time consuming than the ones already given, but

it is not designed for rapid routine work, but rather as a standard procedure that will give absolutely reliable results on all classes of material. This method is also recommended for routine work in case the analyst is called on to make only occasional zinc analyses.

Standardization of the Ferrocyanide Solution

Note. The standardization of the solution is given first, on account of the method of titration.

Weigh into tall 400-cc. beakers several portions of C.P. zinc, using about 0.35 gram. Cover with water and dissolve in 10 ee. hydrochloric acid (sp.gr. 1.2). Now add 13 cc. ammonia (sp.gr. 0.9), make acid with hydrochloric acid, and add 3 cc. excess. Add 0.03 or 0.04 milligram of ferrous iron in the form of a ferrous sulphate solution and dilute to about 200 cc. with distilled water. Heat to boiling and titrate as follows: About one-quarter of the solution is reserved in a small beaker and the ferrocyanide added to the main solution with vigorous stirring. The solution takes on a blue color, which changes to a creamy white when an excess of ferrocyanide is added. Now add a few cc. more and pour in the reserved portion of zinc solution, excepting about 5 or 10 cc. Add ferrocyanide until the end-point is reached and add about ½ cc. more. The last of the reserved zinc solution is then poured into the main beaker, washing out the small beaker with a portion of the main solution, and the ferrocyanide added drop by drop until the blue color fades sharply to a pea green with one drop of ferrocyanide. This is the end-point. Repeat until satisfactory standards are obtained.

Procedure. Weigh into a tall 150-cc. beaker an amount of sample so that it gives a titration of about 40 cc., i.e., 5 grams for a 10% ore to ½ gram for 60% ore and over. Moisten with water and add 10 cc. of hydrochloric acid (sp.gr. 1.20), cover with a watch-glass. In case of sulphides it is necessary to add nitric acid. Boil moderately on a hot plate for half hour or so. Remove and wash down cover-glass and sides of beaker, add 10 cc. of 1: 1 H₂SO₄ and evaporate to strong fumes of sulphuric acid. In case of very siliceous material, it is well to break up the silica with a glass rod before adding the sulphuric acid. After fuming, the solution is cooled and diluted to 40 to 50 cc. and about a gram of 20-mesh aluminum added. Cover with a watch crystal and boil until water white (about ten to fifteen minutes). This will reduce the iron and precipitate all the hydrogen sulphide metals, except cadmium.² The silica and precipitated metals are filtered off and washed with hot water.

Add 5 ce. of 1:1 sulphurie to the filtrate and dilute to 100 cc. Pass a rapid stream of hydrogen sulphide through the solution for fifteen minutes. Add dilute ammonia, a drop at a time until yellow cadmium sulphide precipitates. Then heat the solution to 70 to 90° C. and continue to pass hydrogen sulphide for a few minutes. Filter at once through a close paper previously packed by washing with a polysulphide, an acid and water. The precipitate is washed with cold 8 to 10% sulphuric acid and finally with hot water. The filtrate is boiled to remove hydrogen sulphide, cooled, neutralized with potassium hydroxide

It is only by adding an excess of terrocyanide that one is assured of a precipitate of normal composition.

^a Cadmium is partially precipitated, but goes back in solution. ^a All the cadmium is separated, except about 0.05%, which does not interfere with the titration at the given acidity.

ZINO, 605

solution, and finally potassium carbonate solution, to within an acidity of a couple of drops of 20% sulphuric acid. Methyl orange is used as an indicator. Add from 2 to 4 cc. of 5% ¹ sulphuric acid per 100 cc. of solution according to the amount of zinc present. Cool thoroughly. A rapid stream of hydrogen sulphide is now passed through the solution for forty minutes. Allow the precipitate to settle ten or fifteen minutes, filter and wash with cold water. A hole is punched in the filter paper and the sulphide washed back into the beaker in which it was precipitated. The filter paper and glass tube are then washed with 10 cc. of hydrochloric acid in hot water, catching the washings in the same beaker. Boil off the hydrogen sulphide, add 13 cc. of ammonia (sp.gr. 0.9), neutralize with hydrochloric acid, add 3 cc. excess and dilute to 200 cc. Heat to boiling and titrate as under Standardization. When cadmium is absent or present in quantities less than 0.05, the procedure is of course shortened considerably.

To Separate Cadmium Electrolytically. After filtering off the silica and precipitated hydrogen sulphide metals, add 1 cc. of 1:1 sulphuric acid, dilute to 125 cc. and electrolyze with 0.8 to 1.0 ampere per 100 sq.cm. of electrode surface for 1½ hours at 2.95 to 3.05 volts. Proceed with the residual solution as above. As in all electrolytic separations the current must be carefully watched.

Procedure with Material Containing Insoluble Zinc

Proceed as usual up to point where the solution is to be reduced. Filter off the silica and insoluble material, wash with hot water and proceed with the filtrate as usual. Burn the insoluble residue in a platinum crucible, taking the usual precautions in case lead is present. Fume off the silica with hydrofluoric and sulphuric acids and fuse with acid potassium sulphate. Dissolve in water and sulphuric acid and proceed as in the regular method. The solution may be added to the main portion or titrated separately.

Discussion on Separating Zinc as Zinc Sulphide and Titrating in Acid Solution

Precipitation. The method of precipitating zinc as sulphide in sulpnuric acid solution was investigated by G. Weiss (Inaugural Dissertation, München, 1906), and the work confirmed by F. G. Breyer. The main points of Weiss' paper are as follows:

- 1. "Sulphate solutions are preferable to chlorides." A N/10 ehloride solution is not completely precipitated by H₂S. Furthermore, the precipitate of sulphide from HCl solution when quantitative is not crystalline and easy to filter like that obtained from sulphate solution.
- 2. "The concentration of a sulphate solution is without influence on the completeness of precipitation from N/10 down. That is for solutions containing at most 400 milligrams ZnO per 100 cc."
- 3. "Sulphate solutions of 400 milligrams ZnO per 100 cc. may be N/100 acid with H_2SO_4 before beginning the precipitation." Even at acidity N/20 before
- ¹ Bear in mind at this point the acid liberated by the action of H₂S in the zinc sulphate. See Discussion below.

In cold solution the precipitate is more granular and easier to filter.

*The hydrogen sulphide should pass through at a rate of at least eight bubbles per second.

606 ZINO

precipitation less than a milligram of zinc remains unprecipitated. According to Weiss, if the solution were diluted to 300 cc. 1.3 grams of H₂SO₄ could be added or 6½ cc. of 20% H₂SO₄, and still have the precipitation complete. Even if as much as 10 cc. of 20% acid were added the loss would still be only a little more than 1 milligram. Precipitating 300 milligrams from 100 cc., however, only 100 milligrams or ½ cc. of 20% acid could be added. This means that when the solution becomes more acid than 550 milligrams of H₂SO₄ per 100 cc. the precipitation of ZnS ceases. Knowing approximately the zinc content of a solution one can easily calculate the H₂SO₄, freed when the ZnSO₄ is converted into ZnS, and the difference between 550 milligrams and this calculated H₂SO₄ is the amount of acid that may be added when precipitating from 100 cc. of solution. For two hundred cc. of course more acid can be added, being the difference between 1.100 grams and the calculated H₂SO₄ freed from the ZnSO₄. One and one-half times the amount of Zn judged to be present is close enough for the H₂SO₄ freed.

4. "The precipitation, under the above given conditions, is incomplete when a slow current of hydrogen sulphide is used (about four bubbles per second). One must work with as fast a stream as possible without causing mechanical losses (at least eight bubbles per second)." Weiss is the first one to discuss this all-important question in the precipitation of ZnS. His explanation of the efficacy

of the rapid stream of H2S is as follows:

The precipitation takes place according to the following equation:

$$ZnSO_4 + H_2S \Longrightarrow ZnS + H_2SO_4$$

Equilibrium is reached, i.e., the velocity becomes equal in both directions, and precipitation ceases when the amount of H₂SO₄ per 100 cc. reaches a certain point, under a given set of conditions. Let these conditions remain exactly the same with the exception of the H₂S and have the active mass of that increased. The equilibrium will be displaced from left to right and as a consequence ZnS will come down in the presence of more acid than before. H₂S is not very soluble in water at room temperature, but if one increases the surface of contact between the two the H₂S is dissolved much more rapidly and consequently the mass of H₂S active at any time greatly increased. This is exactly what is accomplished when the zinc solution is constantly kept full of bubbles of H₂S. One can easily see how greatly increased the mass of H₂S would be in the extreme case, when the solution is all foam.

5. "A strong current of gas, like that called for above, will precipitate the

usual amounts of zinc used in analytical operations in forty minutes."

6. "At temperatures above 50° the precipitation is incomplete; furthermore, at room temperature the ZnS comes down in a form suitable for filtration."

7. "Water only is required for washing the precipitates."

End-point. The change of color from blue to pea green is very sharp. It should be observed by looking down through the solution and not from the side. The change in color may be explained as follows: The ferrocyanide, having stood for three or four weeks, has oxidized slightly to ferricyanide, due to dissolved oxygen in the water. The few tenths of a milligram of ferrous iron added acts with this ferricyanide giving the ferro-ferricyanide blue as long as the ferrocyanide is not in excess. When it is in excess the blue is decomposed and gives the colorless ferro-ferrocyanide.

ZINC 606a

• 1

Rapid Ferrocyanide Method for Determining Zinc in Ores

Outside Indicator

Removal of Interfering Elements

1. 0.5 gram of ore. 8-oz. Erlenmeyer flask. 5 ec. of HCl, 10 ec. HNO₂. Boil gently almost to dryness. Remove from heat. Add 12 ec. HNO₃ and 5 grams (measured) of KClO₃. Boil gently just to dryness, finishing by manipulating flask (in holder) over free flame.

2. Add 35 ce. of Extraction Solution and heat to boiling, boiling very gently until disintegration is complete. Now add 10-25 cc. of saturated bromine water, according as manganese contents appear low or high, as

indicated by brown color of residue.

3. Boil a minute or two longer and then filter through an 11 em. filter containing a small moistened wad of absorbent cotton in the apex. Receive filtrate in a 400 cc. beaker. Wash out the flask with hot water. Remove adhering residue with rubber-tipped glass rod, or dissolve it with a few drops of HCl, then add 5 ee., or an excess, of NH₄OH and rinse into filter, finally washing out flask several times with hot water. Now wash filter and residue 10 times with hot Wash Solution.

Precipitation of H2S Group

4. Add a little litmus solution to filtrate as indicator, stir and cautiously add HCl just to acidity, then 3 ec. in excess. Dilute, if necessary, to 200-250 ec. with hot water and heat nearly to boiling. Now add 50 ec. of saturated H₂S water and then the hot liquid is ready for titration.

Titration of Zinc

5. Pour off about half the liquid as a reserve and titrate the balance until the end-point is passed. Use a spot-plate in which about 2 drops of a 15% solution of uranium nitrate have previously been placed in each depression. Transfer the zine solution to the spot-plate with a glass tube instead of a rod, taking only a drop or two for each test, except for the final tests of the titration, when about do a c. should be taken. After the first end-point is passed add a portion of the reserve and again pass the end-point. Repeat this, each time with more caution, until the reserve is reduced to about 5 cc. Now titrate, 6 drops at a time, until the end is again observed, then pour the entire liquid, or most of it, over the 5 cc. of the remaining reserve and then back into the same beaker again and finish the titration 2 drops at a time until the end-point, or brown tinge, is plainly apparent. Read the burette. Allow a couple of minutes for the tests to fully develop and then deduct from the burette reading for as many tests as show and for 1 drop additional. Multiply the number of cc. of ferroeyanide solution used by the percentage value of 1 cc.

Reagents

6. Extraction Solution. 200 grams of commercial ammonium chloride dissolved in a mixture of 500 ec. of strong ammonia and 750 ec. of water.

Wash Solution. 100 grams of commercial ammonium chloride, 50 ec. of

strong ammonia. Dissolve and dilute to 1 liter.

7. Standard Ferrocyanide. K₄Fe(CN)₆·3H₂O 21.6 grams to the liter. 1 cc. = about 0.005 gram Zn, or 1%. Standardize on about 0.2 gram of pure zinc. Dissolve in 10 cc. of HCl. Dilute somewhat, neutralize as above, complete the dilution, heat and titrate precisely as described above. No filtration or H₂S water necessary.

Notes

Potassium chlorate is added to precipitate the manganese and to dilute the mass with salts fucilitating the subsequent zine extraction. The presence of HCl is undesirable, hence an excess of HNO₂ should be present to expel HCl during evaporation. Bromine water is added to insure complete precipitation of manganese.

The degree of acidity is important as it has a direct influence on thee and point. Two drops (i.e. one drop excess) are necessary to produce a color at the end point,

hence the deduction of one drop is made.

The zine compound formed has approximately the following composition— $K_4ZnFe(CN)_6$, $Zn_4Fe(CN)_6$, the precipitating reagent is $K_4Fe(CN)_6$, $3H_2O$, two molecules of this reagent (422.37 g.×2) precipitate three atoms of zine (65.38×3) hence a reagent containing 21.54 grams is equivalent to 5 grams of zine or to 0.005 g. Zu per ce.

In presence of Fe and M.O. indicator the color is lavender changing to pink at the end point. If phenolphthalein is the indicator, the end point is a pea green (from robin's egg blue) becoming white or gray with an excess of ferroeyanide reagent (H₂S present in large amount interferes).

Determination of Zinc in Alloys. See chapter in volume 2.

False Endpoint. During the titration with potassium ferroeyanide with too rapid addition of the reagent a false endpoint is obtained. This is recognized by the fact that an additional amount of reagent causes no deepening of the brown color with the uranium indicator. With additional reagent, heating and stirring no further brown color is produced. When the true endpoint is reached an addition of more ferrocyanide results in a deeper color of the spot test. The solution stirred and boiled still gives the test.

If considerable copper and lend are present in the ore, it is advisable to remove these from the solution. The addition of paper pulp assists in the settling of the sulphides, enabling a test to be made with the clear supernatant solution. With the dark suspended sulphides a sharp endpoint can not be obtained, so that it is advisable to allow the solution to settle and test using

the clear liquor.

DETERMINATION OF SMALL AMOUNTS OF ZINC

The following method is applicable to samples containing 0.05% Zn or less. Procedure. A large sample, 10 or 20 grams, is brought into solution by the standard procedure, taken to funes of sulphuric acid and the zinc precipitated as sulphide after separating groups 5 and 6 by the procedures given under Standard Method, filtered and dissolved in hydrochloric acid. The sample is now washed into a 100-cc. Nessler tube, 5 ec. of ferrocyanide added and the whole made up to the mark, mixed by pouring into a beaker and then back into the tube. A standard containing the same amount of acid is made up and a standard zinc chloride solution added until the turbidity of standard and unknown are the same. From the amount of zinc added to the standard the percentage can be calculated. The standard zinc solution is made up by dissolving C.P. zinc in hydrochloric acid and diluting so that 1 cc. is equal to 1 milligram of zinc.

SPECIAL METHODS

Determination of Metallic Zinc in Zinc Dust


Discussion. There have been various methods proposed for determining the metallic zinc content of zinc dust. Most of these are based upon its reducing power. The latter may be determined by any one of many ways, although the results from different methods will not be concordant, due to the inaccuracies inherent with most of the methods. Potassium bichromate, iodate, ferric sulphate, and iodine have been used for measuring the reducing power of zinc dust. Fresenius also proposed dissolving the zinc dust in dilute sulphuric acid and after drying passing the hydrogen over heated copper oxide in a combustion tube, absorbing the water formed in a calcium chloride tube and weighing.

There have also been methods devised based on the volume of hydrogen evolved when a sample of zinc dust is dissolved in dilute acid. Several investigators have concluded from comparative investigations that the gasometric determination of the hydrogen evolved gives the most consistently accurate results. The best arrangement of apparatus for earrying out this hydrogen evolution method is shown in Fig. 72. The time required for a determination is about 1½ hours.

Procedure. One gram of zinc dust is weighted and transferred as rapidly as possible to a small Erlenmeyer flask A, of 100 or 200 cc. capacity, in which is placed a piece of sheet platinum about 1.5 cm. square. About 5 g. of clean unoxidized ferrous sulphate crystals are added on top of the zinc dust and the flask nearly filled with distilled water saturated at room temperature with hydrogen gas.

The object of adding the sheet platinum and ferrous sulphate is to increase the rate of hydrogen evolution by catalytic action. A further reason for adding the ferrous sulphate on top of the zinc dust sample is to coagulate the latter as much as possible when it becomes wetted, and thus prevent the floating of more than an unappreciable amount of the sample.

The rubber stopper containing separatory funnel B and connecting tube C is tightly inserted into the neck of the flask. A little distilled water is poured into B



and the three-way stop-cock in C turned to connect the flask with the downward outlet. Enough water is now run in from the separatory funnel to displace all the air in the flask and the connecting tube through the bore in its stopcock. The stopcock in C is now turned so that the downward outlet is in connection with the measuring tube D. By raising the leveling bottle E, containing 10 per cent. sulphuric acid also saturated with hydrogen at room temperature, all the gas in D is displaced. stopcock in C is now turned through 90 deg. so as to connect the decomposing flask A with the measuring tube D. The system is hence completely filled with liquid and ready for the generation of hydrogen. The measuring tube D has a total capacity of 400 cc. and is graduated from 250 to 400 cc. by 0.25 cc.

Thirty cubic centimeters of 1:1 sulphuric acid are now poured into the separatory funnel. A small portion of this acid is allowed to run into the decomposing flask until a brisk but not too rapid evolution of hydrogen takes place. The acid, being much heavier than water, settles to the bottem of the flask and the action commences immediately. The gas evolved, together with some solution and a very small amount of zinc dust passes over into the measuring tube, displacing the acid there. When the action in the decomposing flask has slowed down, more strong acid is introduced until all has been

added. During this time the acid in the measuring tube and flask is shaken so as to wash down the particles of zinc dust from the upper parts of the flask and tube now filled with gas. The particles in the measuring tube on coming in contact with the 10 per cent. sulphuric acid are readily dissolved and generate their portion of hydrogen.

When all the zinc dust has been dissolved, water is run in from the separatory funnel to force the hydrogen over into the measuring tube and to fill the flask and connecting tube with water through to the stopcock which is then closed. After leveling with the leveling bottle the volume of hydrogen generated from the 1-g. sample at the prevailing atmospheric conditions is read from the measuring tube. The percentage of metallic zinc in the sample is then calculated from the following expression:

Per cent. of Metallic Zinc =
$$\frac{V \times (P-p) \times 0.29196}{(1+0.00367t)760}$$
,

in which V=volume of gas in measuring tube at atmospheric conditions, P=: barometric pressure, p=vapor tension of water above 10 per cent. sulphuric acid at room temperature, and t=room temperature.

Necessary Precautions. To obtain results of the highest accuracy, it is necessary when weighing out samples of zinc dust which are very finely divided, to keep the time of exposure as small as possible in order to minimize the oxidation


that takes place with the oxygen of the air. It is also highly important when samples are to be held, that they be kept in ground glass stoppered bottles, completely filled, and sealed with paraffin or wax.

The two variables most likely to affect the results are temperature and barometric pressure. A change in the barometric pressure is practically always ex-

tended over a reasonable length of time. A careful reading of the barometer when the volume of gas in the measuring tube is read will eliminate any error from this source. A temperature change, on the other hand, affects not only the volume of gas, according to Charles' law, but also affects the vapor tension of water and house the actual pressure of the hydrogen when measured.

The rubber connection between the connecting and measuring tubes must be of heavy rubber and should be shellacked.

The vapor tension of water is slightly lower above 10 per cent. sulphuricacid than above purc water, as shown in Fig. 73 and for accurate work should be used in place of the ordinary vapor tension tables.



The result obtained should be corrected for any metallic impurities, as Fe, Al, etc., which coolve hydrogen when dissolved in sulphuric acid.

DETERMINATION OF IMPURITIES IN SPELTER

LEAD

Electrolytic Method

The sample is thoroughly mixed on a sheet of paper and a magnet passed over to remove iron particles. Any pieces showing discolorations are discarded. The pieces of spelter for the weighed sample are removed from the paper by lifting and not pouring. The amount of sample taken is determined by the amount of lead

in the spelter.

For No. 1 or High Grade Spelter a sample of 17.286 grams is weighed into a 600 cc. beaker, 200 cc. of distilled water added, and 60 cc. of concentrated nitric acid added gradually until solution is complete. The solution is boiled down to 200 cc., expelling all nitrons fumes, and then transferred to a 250 cc. beaker, washing out original beaker without unnecessarily increasing volume. Four or five drops of 5% silver nitrate solution are added, to precipitate any traces of chlorine present, and the solution electrolyzed for one and one-half to two hours, with initial temperature of 60-70° C. and current of 1.8 amperes.

For No. 2 or Intermediate grade, a sample of 8.643 grams is weighed into a 250 cc. beaker, 100 cc. of distilled water added, and 40 cc. of concentrated nitric acid added. The solution is boiled until all nitrous fumes have been expelled and diluted to 200 cc. with distilled water, 4 or 5 drops of 5% silver nitrate added and

the solution electrolyzed as given under High Grade Spelter.

For the three lower grades of spelter, Brass Special, Scleeted and Prime western, a sample of 17.286 grams is weighed into a 600 cc. beaker, covered with 200 cc. of water and 60 cc. of concentrated nitric acid added. This solution is boiled down to 200 cc. transferred to a 500 cc. graduated flask and the flask filled to the graduation. After thorough mixing, an aliquot portion of 125 cc. (equivalent to 4.3215 grams) is poured into a 250 cc. beaker, 10 cc. of concentrated nitric acid added, boiled for ten minutes, diluted to 200 cc., with distilled water, silver nitrate added and electrolyzed as given for high grade spelter.

The anode is made of sheet platinum with wire stem and is sand blasted. No gold solder should be used on these cylinders. The surface area is 135 sq. cm. A spiral of platinum wire is used as a cathode. A spiral of aluminum wire may also

be used, although its life is much shorter.

When electrolysis is complete, the anode is removed from the solution as rapidly as possible, washed three times with distilled water, once with alcohol, dried in an air bath at 210°C for thirty minutes, cooled and weighed.

The weight of PbO₂ can be calculated directly to percentage of lead as factor

weights of sample were taken.

Lead Acid Method

Weigh 10 grams of the sample into a 400 cc. beaker and add 120 cc. of "lead acid." When all but about 10% of the zinc is dissolved, filter and wash with lead acid. Retain the filtrate. Wash the metallics back into the beaker and dissolve in nitric acid. Add 40 cc. of "lead acid" and evaporate to strong fumes. Cool and add 35 cc. of water, which is the amount evaporated from the "lead acid," and heat to boiling. Add the filtrate containing most of the zinc and a little lead sulphate, stir and allow to settle over night. Filter on a Gooch crucible, wash with lead acid, a mixture of alcohol and water (1:1), finally with alcohol and ignite inside a porcelain crucible and weigh as lead sulphate.

Lead Acid. Add 1 gram of lead acetate in 300 cc. of water to dilute sulphuric acid (300 cc. acid to 1800 cc. of water). Shake well, allow to cool and settle. Filter off the precipitated lead sulphate. By the use of this sulphuric acid saturated with lead, the solubility of lead sulphate need not be considered, the solution being brought back to the same concentration each time.

Note. The rejection limits for spelter of the American Society for Testing Materials consider five grades as follows:

	Grade	Pb Not Over	Fo Not Over	Cd Not Over	Sum Pb+Fe+Cd Not Over	Al
No. 2.	High GradeIntermediate	.20	0.3% .03	.07% .50	.10% .50	None "
No. 3. No. 4. No. 5.	Brass Special	.60 .80 1.60	.03 .04 .08	.50 .75	1.0 1.25	"

IRON

Hydrogen Sulphide Method

Ten grams or more of the sample of spelter, which has been passed under a magnet to remove any metallic iron particles, is weighed out into a 250 cc. beaker and dissolved with 50 cc. of concentrated hydrochloric acid. After standing several minutes until violent action has ecased, about 1 cc. of potassium chlorate solution (50 grams per liter) is added and boiled until all chloring fumes have been driven off. It is then cooled, 50 cc. of water added, neutralized with ammonia, adding a large excess of the latter, boiled for two or three minutes and then allowed to settle. The solution is filtered, the precipitate on the filter washed with dilute aminonia water and finally with hot water. The precipitate is dissolved into a 500 cc. Erlenmeyer flask, using 10 cc. 1: 4 sulphuric acid. The paper is washed thoroughly with hot water. After diluting to a volume of about 300 cc. hydrogen sulphide is passed through for 5 minutes to reduce the iron. The excess of hydrogen sulphide is boiled off, being careful to exclude the entrance of any air. When no trace of hydrogen sulphide is present, as indicated by no test with lead acctate paper, the solution is cooled rapidly, and titrated with a standard solution of potassium permanganate, 1 cc. of which is equivalent to about 0.00034 grams of iron. A blank determination is also run in order to determine the amount of potassium permanganate required to show the pink color on titration. The permanganate solution is standardized against Bureau of Standards Sodium Oxalate.

Colorimetric Method

Solutions. Ammonium Sulphocyanate. One part salt to 2 parts of water. Potassium Chlorate. One part salt to 20 parts of water.

Standard Iron Solution I. 500 grams of low iron granulated zinc is dissolved in 800 to 1000 cc. of concentrated hydrochlorie acid, sufficient amount of potassium chlorate solution added to oxidize the iron present, boiled several minutes to expel chlorine, cooled and made up to 2500 cc. This solution is standardized by measuring off 50 cc. portions, corresponding to 10 grams of zinc, and determining the iron content by the Hydrogen Sulphide Method.

Standard Iron Solution II. 0.7 grams of ferrous ammonium sulphate is dissolved in water, 10 cc. dilute sulphuric acid added, and the iron oxidized with permanganate. The solution is diluted to 1000 cc. each cc. being equivalent to .0001 gram iron.

Procedure. Ten grams of sample are dissolved and oxidized as given under the Hydrogen Sulphide Method. The solution is cooled and diluted to about 25 cc. and transferred to a comparison tube, 2 cc. of the sulphocyanate solution are added, and the volume brought up to 100 cc. and mixed by pouring into the beaker and back into the tube. The red color is compared with the color produced on adding 2 cc. of sulphocyanate to 50 cc. of standard iron solution I, 2 and diluting to 100 cc. Standard Iron Solution II is added until the colors are the same, and the iron present in the unknown calculated. In case the iron is over 0.030, it should be determined by the Hydrogen Sulphide Method.

CADMIUM

Sulphide Method

The determination of cadmium in spelter is best carried out by either of the two following methods, according as the amount to be determined is low or high.

Cadmium in Spelter (Cd -.001% to .02%)

A sample of 500 grams is taken and placed in a 2000 cc. flask with 500 cc. of water and 100 cc. of 1:1 sulphuric acid. Sulphuric acid (1:1) is added in small quantities from time to time, to maintain solution of the zinc (but never any violent action), until about 90% of the sample has been dissolved. This requires about 750 cc. of 1:1 sulphuric acid. When the evolution of hydrogen has become slow, after the last addition of acid, the solution is filtered off, retaining as much of the undissolved metallics as possible in the flask. The metallics are washed twice with water, decanting and pouring the small amount of metallics on the filter. The metallics on the filter are then washed from the paper into the original flask and all dissolved in nitric acid. The solution is washed into a 600 cc. beaker and sufficient sulphuric acid (1:1) added to convert all the metals present to sulphates, leaving an excess of free acid of 10-15 cc. This requires about 95 to 100 cc. of acid. The solution is evaporated until all nitric acid has been expelled.

After cooling, water is carefully added and the beaker heated until all the soluble salts have been dissolved. The lead sulphate is allowed to settle, filtered off and washed. Enough water must be added to keep all zinc sulphate in solution after cooling. Hydrogen sulphide is passed through the filtrate for 15-20 minutes. No precipitate will appear at first, so that a drop or two of ammonia is added and repeated at intervals until a considerable amount of zinc sulphide has been precipitated. The sulphides are then filtered off and washed with cold water. The film of sulphides on the side of the original beaker and the sulphides on the paper are dissolved in 1:2 hydrochloric acid, washing with water, and catching the solution in a tall 400 cc. beaker. 15 cc. of 1:1 sulphuric acid are added and evaporation carried down to fumes. After cooling, 200 cc. of water is added, hydrogen sulphide passed through and ammonia added as above to produce a pre-

¹ Clear glass test-tubes ³ in. in diameter, and holding 110 cc. make good comparison tubes.

tubes.

The sinc content of the standard and unknown must be approximately the same. (See references, Bureau of Standards Bulletin, No. 1, Vol. 3.)

cipitate of cadmium sulphide. The precipitate is treated as before and a third precipitation made. In the case of very low cadmium, a fourth precipitation is advisable. The last precipitate is filtered at once on a weighed Gooch crucible, washed with cold water, dried at 110° C. and weighed as CdS or the cadmium may be weighed as metallic cadmium, by dissolving the last precipitate and electrolyzing as given by the following method:

The last precipitation of cadmium as CdS is filtered off, washed with cold water, and dissolved in dilute hydrochloric acid as in previous precipitations, catching solution and washings in original beaker. Twenty-five cc. of 1:1 sulphuric acid are added and evaporation carried to dense fumes. After cooling, a small amount of water is added, the solution neutralized with ammonia (using methyl orange as indicator), then made just acid with sulphuric acid (sp.gr. 1.09) and 3 cc. added in excess. The solution is then transferred to a 250 cc. beaker, (washing out the original beaker), diluted to cover the cylinder (beaker $\frac{2}{3}$ full), and electrolyzed over night using a current of one ampere. The cylinder with cadmium deposit is removed, washed with water and alcohol, dried at 110° C., removed from oven as soon as dry, cooled and weighed.

Cadmium in Spelter (Cd -0.2% to 1.0%)

A sample of 10 (or 25) grams is taken and entirely dissolved in a tall 400 cc. beaker with nitric acid, the solution then treated with 25 (or 50) cc. of 1:1 sulphuric acid and evaporated to expel all nitric acid. After cooling, water is carefully added and the beaker heated until all the soluble saits have been dissolved. The lead sulphate is allowed to settle, filtered off and washed. The filtrate is diluted to 200 ec. and hydrogen sulphide gas passed through for 15-20 minutes. No precipitate will appear at first, so that a drop or two of ammonia is added and repeated at intervals until a considerable amount of zinc sulphide has been precipitated. The sulphides are filtered off and washed with cold water. They are then dissolved with 1:2 hydrochloric acid, catching in the original beaker, 15 cc. of 1:1 sulphuric acid added and taken to fumes. This is again diluted to 200 cc. hydrogen sulphide gas passed through, and ammonia added as before to produce a precipitate of cadmium sulphide. This is treated as above and a third precipitation made. The cadmium sulphide from this is filtered at once on a weighed gooth, washed with eold water, dried at 110° C., and weighed as CdS, or the cadmium may be weighed as metallic cadmium, by dissolving the last precipitate and electrolyzing as given under Method for Low Cadmium.

General Remarks

A very retentive filter paper must be used for the cadmium sulphide precipitates. In dissolving the eadmium sulphide precipitates from the filter paper, the funnel should be covered to guard against loss by spraying. The number of treatments with hydrochloric acid depends upon the amount of sulphides on the paper. The paper may be finally washed with water after all sulphides have dissolved, if desired.

It is not absolutely necessary to wash the final precipitate of cadmium sulphide on the gooch, as this has been accomplished in the transfer of the precipitate from the beaker. This has been included in the methods to safeguard against free acid remaining on the Gooch.

ANALYSIS OF ZINC CHLORIDE SOLUTION

The methods to be used for the analysis of zine chloride solution or fused zine chloride are essentially those given under the various chapters for the various elements. It seems advisable, however, to include a set of methods of analysis suitable for the commercial evaluation of zine chloride.

I. Specific Gravity at 15° C.

The specific gravity is determined by means of a picnometer. The volume is brought to the graduation after the solution in the picnometer has been brought to 15° C., using a water bath. The weight of this volume of boiled distilled water is determined at 15° C., and the specific gravity of the zinc chloride solution calculated, compared to water at 15° C.

II. Zinc (Manganese and Copper Absent)

About 25 grams of the well shaken solution is weighed out in a weighing bottle and transferred to a 500 cc. graduated flask. Sufficient nitric acid is added to clarify the solution upon dilution. The flask is filled to the mark with distilled water and thoroughly mixed.

A portion, approximately equivalent to one gram of ZnCl₂ is accurately measured from a pipette or a burette and the zinc determined by titration with a standard potassium ferrocyanide solution as given under procedure for zinc in ores.

Zinc (Manganese or Copper Present)

If manganese or copper is present an aliquot portion is measured out and the manganese or copper separated according to the methods given under procedures for ores, before titration with potassium ferrocyanide.

III. Chlorine

Another portion of this solution, approximately equivalent to .5 grams ZnCl₂ is measured off into a 500 cc. Erlenneyer flask, 15 cc. of distilled water, 100 cc. of standard N/10 silver nitrate solution and 40 cc. of nitric acid are added to the flask and boiled until all nitrous fumes are driven off. After cooling, the excess silver nitrate is titrated with standard N/10 ammonium thiocyanate solution using 5 cc. (1-6) ferric nitrate solution as an indicator. A blank is run at the same time and the amount of chlorine determined from the difference in volumes of ammonium thiocyanate required. The factor for the standard ammonium thiocyanate solution is best determined with C.P. sodium chloride.

IV. Sulphuric Anhydride (SO₃)

Twenty-five cc. of the original well shaken solution of zinc chloride are measured off with a pipette into a 400 cc. beaker, diluted to 300 cc. with hot water and a few drops of hydrochloric acid added. Any insoluble matter is filtered off, five cc. of bromine water are added to the filtrate and the solution boiled until excess bromine is all driven off. The SO, in the filtrate is precipitated with 25 cc. hot 10% barium chloride solution. After standing on the steam plate for 3 hours, the barium sulphate is filtered off, ignited and weighed. The weight of the sample is determined from the specific gravity.

V. Iron (Fe)

A portion of the well shaken solution, equivalent to 10 grams of zinc is evaporated to a syrupy consistency and the iron determined by the colorimetric method as under spelter.

In case the iron is too high to estimate colorimetrically, it is separated with ammonia, filtered off, washed with hot water and dissolved in hot dilute sulphurie acid. This solution is cooled, run through a Jones reductor and titrated with standard potassium permanganate solution, or the iron may be determined by the hydrogen sulphide method as given under analysis of spelter.

VI. Iron and Aluminum (Fe₂O₃+Al₂O₃)

Either 10 or 20 cc. of the original well shaken solution are transferred to a 400 cc. beaker, diluted with 150 cc. of water and hydrochloric acid added to a very faint excess. (2 drops concentrated acid.) A rapid stream of hydrogen sulphide is passed through the solution for 30 to 40 minutes. The precipitate of zinc sulphide is filtered off and washed thoroughly. The filtrate is boiled for about 15 minutes to remove hydrogen sulphide, cooled, sufficient bronnine water added to more than oxidize all the iron, and then boiled to remove the excess bromine. Aminonium hydroxide is now added in slight excess, the precipitate of iron and alumina filtered off and washed with hot water. The precipitate is dissolved from the paper with hot hydrochloric acid (1:4) re-precipitated, filtered off, washed free from chlorides, ignited and weighed.

VII. Manganese (Mn)

Either 10 or 20 cc. of the original well shaken solution are transferred to a 400 cc. beaker, 25 cc. of sulphuric acid (1:1) added and evaporated to practically complete expulsion of all excess sulphuric acid. Nitric acid (1:3) is now added and the manganese determined according to the bismuthate method.

VIII. Lime (CaO)

Twenty-five cc. of the well shaken solution are measured off with a pipette, a few drops of hydrochloric acid added, and the solution diluted to 150 cc. Twenty grams of ammonium chloride and a few drops of bromine water are added. The iron and manganese are precipitated by ammonia and filtered off after bringing to boiling. The filtrate is evaporated to 150 cc., the lime precipitated with 25 cc. ammonium oxalate solution (saturated solution) and allowed to stand for, 3 hours. The calcium oxalate is filtered off and washed four times with hot water. A hole is then punched in the filter paper, the precipitate washed into a 400 cc. beaker, with boiling water, 10 cc. of sulphuric acid (1:1) poured over the paper and the paper washed with boiling water. The solution is diluted to 150 cc. with hot water and titrated with standard potassium permanganate solution.

IX. Magnesia (MgO)

The filtrate and washings from the lime determination is made slightly acid with hydrochloric acid and 15 cc. of a saturated solution of microcosmic salts added. The solution is cooled and the magnesia precipitated by the slow addition of ammonia. Sufficient ammonia must be added to hold all zinc in solution, an excess

of about 50 cc. being required. The precipitate after standing 12 hours is filtered off, and redissolved in hot 1-4 hydrochloric acid. Twenty grams of ammonium chloride are added to this solution, then a few drops of microcosmic solution, and precipitation affected with ammonia as before, the excess of ammonia being only 10 cc. in this case. After standing 12 hours, the precipitate is filtered off, washed six times with 1:10 ammonia water, or until free from chlorides, ignited and weighed as Mg₂P₂O₁.

X. Alkalies (NaCI+KCI)

A sample of about 10 grams is taken and made up to a volume of 500 cc. From this a portion equivalent to approximately 2 grams is measured off, slightly acidified with hydrochloric acid and the zinc precipitated with hydrogen sulphide. After filtering, the filtrate is tested with annuonium sulphide, and any zinc, iron and manganese precipitated is filtered off. The filtrate is boiled for about thirty minutes to drive off the hydrogen sulphide, and cooled. After cooling, the solution is made slightly acid with hydrochloric acid, a few drops of bromine water added and the excess of bromine boiled off. The solution is diluted to about 200 cc. with hot water, and 10 cc. of hot 10% BaCl₂ solution added, to precipitate SO₃. Without filtering off the barium sulphate, the solution is made ammoniaeal, one gram of ammonium carbonate and 5 cc. of ammonium oxalate solution added and the precipitates allowed to settle in a warm place. The precipitate is filtered off, washed with hot water, and the combined filtrate and washings evaporated to dryness in a porcelain dish. The ammonium salts are completely driven off by ignition over a low flame. The residue remaining is dissolved in a small amount of water with two drops of hydrochloric acid, transferred to a weighed platinum dish, the porcelain dish being washed with a minimum amount of water, evaporated to dryness on a hot plate, and after eooling weighed.

Any magnesia which may be present with the alkali chlorides is determined, calculated to MgCl₂ and deducted from the weight of salts in the dish. This difference is expressed as combined alkali chlorides KCl+NaCl.

XI. Copper

Twenty cc. of solution are taken, 5 grams of ammonium chloride and 20 cc. of ammonium hydroxide added, diluted to 100 cc. in a color comparison tube and compared with a zine chloride solution of equal strength, to which a measured amount of standard copper solution is added to give the same depth of color. If iron interferes with the color comparison, it should be filtered off before diluting to volume. When the amount of copper present is over 0.05%, the determination should be carried out by some other method. See chapter on copper.

XII. Barium (Ba)

If sulphuric anhydride (SO₃) is found to be present, it is not worth while to make a determination for barium. If no sulphuric anhydride is present, barium should be looked for and determined by diluting 10-20 ec. to 300 ec. with water, adding slight excess of hydrochloric acid heating to boiling and precipitating the barium with ammonium sulphate solution (10 per cent.).

ANALYSIS OF FUSED ZINC CHLORIDE

The analysis of fused zinc chloride for zinc, etc., is carried out by the same methods as given under Zinc Chloride Solution, working on a solution of the fused salt in water. This solution is made up by rapidly transfering approximately 20 grams of fused salt to a weighing bottle, weighing, dissolving in water in a 2000 cc. graduated flask to which a few drops of nitric acid has been added to prevent precipitation of basic zinc chloride, and filling to the mark. Aliquot portions are taken from this solution for the various determinations.

Special determinations are sometimes called for with fused zinc chloride which is to be used for some special purpose. It is very essential that such analyses be carried out carefully according to the method prescribed in order that the results, which are largely empirical, may be comparable. One analysis of this sort which is commonly called for is Basicity expressed in some empirical way to give a measure of the relative quantities of the basic zinc chloride, which will settle out upon dissolving fused zinc chloride in water. It may be expressed as the volume of standard hydrochloric acid (usually N/2) required to neutralize 10 cc. of a 40° Baume solution of the fused zinc chloride, diluted with 300 cc. of water, when using Methyl orange as indicator, or the weight of basic chloride obtained by treating 10 grams of the sample, weighed in a weighing bottle, with 400 cc. of water, agitating to complete all possible solution, filtering off insoluble on a gooch crucible and washing with water until combined filtrate and washings total just 1000 cc.

Ammonia (NH₃)

It is often of value to know if ammonium chloride is present. A sample of 5–10 grams is weighed and transferred to a 500 cc. distilling flask, 100 cc. of water, 50 cc. of sodium hydroxide (20 per cent.) and a small quantity of granulated zinci added. The ammonia and water are distilled over into an absorption bottle containing a measured quantity of standard acid. The excess of acid is titrated with standard alkali solution, using methyl orange.

See chapter on nitrogen, page 343, also analysis of paint pigments, volume 2.

¹ The addition of granulated zine aids in the expulsion of the ammonia by hydrogen formed with the sodium hydroxide.

617a ZINC

Determination of Zinc in Pig Lead 1

Solutions Required

Nitric Acid (1:4).—Mix 200 cc. of HNO₃ (sp. gr. 1.42) with 800 cc. of distilled water.

Sulphuric Acid (1:1).—Carefully pour, with stirring, 500 cc. of H₂SO₄ (sp. gr. 1.84) into 500 cc. of distilled water.

Acidulated Hydrogen Sulphide Water.—Add 20 cc. of HCl (sp. gr. 1.19) to 1000 cc. of distilled water and saturate with hydrogen sulphide.

Ammonium Thiocyanate Solution (2 per cent).—Dissolve 20 g. of NH4CNS in 1000 cc. of distilled water.

Hydrochloric Acid (1:3).—Mix 100 cc. of HCl (sp. gr. 1.19) and 300 cc. of distilled water.

Standard Zinc Solution (0.1 mg. of zinc per cc.).—Dissolve exactly 0.1 g. of U. S. Bureau of Standards pure zinc in 5 cc. of HCl (sp. gr. 1.19) and diluto to exactly 1000 cc. with distilled water.

Potassium Ferrocyanide Solution.—Dissolve 34.8 g. of K₄Fe(Cu)_{6.3}H₂O in 1000 cc. of distilled water.

Method

Dissolve 222.23 g. of the sample in 1100 cc. of HNO₂ (1:4), using a 1300-cc. beaker. When the lead is dissolved, transfer the solution to a 2000-cc. graduated flask and add slowly 150 cc. of $\rm H_2SO_4$ (1:1). Cool, fill the flask to the mark and then pour the solution into a clean 3000-cc. flask provided with a rubber stopper. Rinse the measuring flask with exactly 50 cc. of water, which is equivalent to the volume of lead sulphate which is present. Mix the solution thoroughly by shaking, allow the precipitate to settle and filter through a dry filter until 1800 cc. of filtrate has been obtained.

Place exactly 1800 cc. of filtrate (equivalent to a 200-g. charge) in a No. 9 porcelain evaporating dish and evaporate the solution to approximately 100 cc. Transfer the solution to a 600-cc. beaker, neutralize with ammonia, and then add 5 cc. of HCl (sp. gr. 1.19) for every 100 cc. of solution. Warm the solution and pass in a rapid current of hydrogen sulphide until it is saturated. Digest for 30 minutes on the steam bath, add an equal volume of water and again saturate with hydrogen sulphide. Filter and wash with acidulated H₂S water.

Discard the precipitate and evaporate the filtrate in glassware containing no zinc (such as Pyrex) until the volume of the solution is approximately 100 cc.

Neutralize the solution with ammonium hydroxide, add 5 g. of citric acid, and warm until the acid is dissolved. Add small portions of calcium carbonate to the hot citric acid solution until about 1 g. of calcium citrate has separated and then pass in a rapid current of II₂S as the solution is allowed to cool. Allow the solution to stand for from 2 to 4 hours, part of the time on a water bath, until the supernatant liquid is clear.

Collect the precipitate on a filter, wash with a 2 per cent solution of ammotium thiocyanate and then dissolve the precipitate in hot dilute hydrochloric acid (1:3). If the solution has a reddish color (due to iron), the zinc must

¹ Standard Method of the A. S. T. M.

ZINC 617b

be reprecipitated as above. If the solution is clear, evaporate it to dryness on the steam bath, take up the residue in 3 cc. of HCl (sp. gr. 1.19), add 20 cc.

of water and filter if not perfectly clear.

Transfer the solution (Note 2) to a 50-cc. Nessler jar and dilute to 45 cc. Prepare other Nessler jars containing 3 cc. of HCl (sp. gr. 1.19), definite volumes of standard zinc solution, and diluted to 45 cc. Add 5 cc. of potassium ferrocyanide solution to each jar, mix quickly, and compare the turbidities by viewing longitudinally as the jars are held over a sheet of fine print. Add more of the standard zinc solution from a burette to the jar which approximates the turbidity of the unknown most closely, until the turbidities match each other, and calculate the percentage of zinc on the basis of a 200-g. sample or the aliquot portion taken.

Notes. 1. All glassware that contains zine must be avoided and in umpire work a blank test should be carried along with the test.

2. The whole solution can be used if the lead contains no more than 0.002 per cent of zine. If more zinc is present, it is best to take such an aliquot portion of the solution as will give approximately 4 mg. of zine and then to add enough HCl to provide 3 cc.
3. For further details concerning the turbidmetric test, consult the "Determination of Small Quantities of Zine" by Mr. Bodansky, in the Journal of Industrial and Engi-

neering Chemistry, Vol. 13, pp. 696-697 (1921).

4. The addition of calcium carbonate with the formation of a precipitate of calcium citrate serves the purpose of giving a clear filtrate, and prevents the loss of colloidal sulphide.

ZIRCONIUM 1

Zr, at.wt. 91.2; sp.gr. 4.1 (amorphous) to 6.2 (coherent); m.p. about 1700; 2 oxides, ZrO2 (Zr2O5 and ZrO2 in hydrated form).

DETECTION

The material to be tested is brought into solution by one of the methods given in the section on the Preparation of the Sample. In the regular course of qualitative analysis the zirconium will be found in the main precipitate formed either by ammonium hydroxide alone or by the combined action of ammonium hydroxide and ammonium sulphide. This precipitate can be dissolved in sulphuric acid, the acidity then adjusted so that 10% of the solution, by volume, is conc. sulphuric acid, 10 ce. of 3% hydrogen peroxide and 1 cc. more of cone, sulphuric acid added, and then a large excess of Na₂HPO₄ or (NH₄)₂HPO₄ solution, to which has also been added 1/10 its volume of conc. sulphuric acid. A white precipitate proves the presence of zirconium, since no other elements (titanium having been peroxidized) have phosphates which are insoluble in such an acid concentration.3 This is the simplest and surest method of detecting zirconium. In the regular course of analysis thorium and the rare earths would probably have been precipitated from the acid solution of the ammonium hydroxide precipitate by an excess of oxalic acid (see "Detection" in chapter on thorium). The filtrate would contain almost all of the zirconium, along with titanium, beryllium and the more common elements of the group. The oxalic acid in this filtrate can be destroyed by evaporation with suphuric acid, and then zirconium, titanium and aluminum precipitated by boiling the weakly acid solution (containing 8 or 10 drops more sulphuric acid than is needed to redissolve the first faint precipitate formed by gradually adding dilute ammonia) with sodium thiosulphate. This precipitate may be brought into solution by fusing with potassium pyrosulphate, and taking up with sulphuric acid. The phosphate test as just outlined may then be applied.

Turmeric paper on drying after having been moistened with a slightly acid (HCl or H2SO4) solution containing zirconium shows a reddish-brown color, similar to that due to boric acid. Titanium gives a like reaction in the tetravalent condition, but if the acidified solution is reduced by adding a piece of zinc, and then promptly tested (before titanium is reoxidized), the test is spécific for zirconium.

¹ Paul H. M.-P. Brinton, Professor of Analytical Chemistry, University of Min-

nesota.

Considerable doubt exists as to the reliability of the physical constants of zirconium. If the contentions of Coster and Hevesy that practically all zirconium contains varying amounts of hafnium (more justly called celtium) is true, it is not surprising that such discordant results have been recorded by different investigators.

Biltz and Mechlenburg, Z. angew. Chem., 25, 2110 (1912); Lundell and Knowles, J. Am. Chem. Soc., 41, 1801 (1919).

Oxalic acid produces a precipitation of zirconium oxalate in dilute mineral acid solution, but the precipitate is soluble in excess of oxalic acid. (It is also soluble in ammonium oxalate; and is not reprecipitated by addition of hydrochloric acid, thus differing from thorium.)

From aluminum zireonium may be differentiated by the solubility of zireonium basic carbonate in excess of a strong, cold solution of ammonium carbonate (on boiling the hydroxide separates out again); and by the insolubility of zireonium oxyiodate, produced by an alkali iodate in a slightly acid solution. (Thorium and tetravalent cerium also give the iodate test.)

ESTIMATION

The main ores of zirconium are baddeleyite, essentially zirconium dioxide; and zircon, essentially zirconium orthosilicate. While zircon is the most widely distributed ore of zirconium, the most important commercially is now the Brazilian baddeleyite, which, mixed with a little zircon, comes under the trade name of zircite, and contains around 75% of ZrO₂. The determination of zirconium in furnace-lining material, high temperature laboratory ware, enamels, and steel is at times called for.

Preparation and Solution of the Sample

Acid treatment will not decompose ordinary zirconium ores. The following fluxes are most commonly used.

Sodium peroxide is used in a nickel crucible which has been lined by fusing some sodium carbonate, and causing it to cool in an even layer on the sides and bottom. This prevents in large measure the attack of the crucible by the peroxide, and avoids the subsequent introduction of large amounts of nickel into the solution. Several grams of sodium peroxide are melted in the crucible, after lining with sodium carbonate, and allowed to solidify on the bottom. This prevents particles of the ore from being eaught in the carbonate lining and remaining unfused. The sample of finely ground ore (0.5 g.) is mixed with 8-10 g. of sodium peroxide in the crucible thus prepared, and fused at low red heat over a small flame, by gently swirling the erueible, held in tongs. 5-10 minutes should suffice. When cool the erucible is placed in a large platinum dish, or porcelain enserole, and covered with warm water, keeping the vessel covered with a watch glass until danger of loss from effervescence is over, the solution is boiled until the carbonate liping has dissolved, and the erueible is then removed. The solution is next made decidedly acid with hydrochloric acid, and boiled until carbon dioxide is expelled. This should give a clear solution containing the zirconium and all the other constituents of the ore. If a very small amount of undecomposed ore is found here, it should be filtered off, ignited, fused with a little potassium pyrosulphate, dissolved in 5% sulphuric acid, filtered if necessary, and added to the main solution.

Potassium hydrogen fluoride is applied by Smith and James ² in the following manner: The finely ground ore is fused with 12 to 15 times its weight of potassium hydrogen fluoride. The latter may be prepared from potassium carbonate or fluoride by treating with a slight excess of hydrofluoric acid, and evaporating over a small flame until a clear fused mass is obtained. When cool the melt may be broken up and preserved for use. The mixture

² Smith and James, J. Am. Chem. Soc., 42, 1764 (1920).

¹ Private communication from J. A. Holladay, Electro Metallurgical Co., Niagara Falls, N. Y.

of ore and fluoride, in a platinum disn, is carefully heated over a small flame. When the mixture has softened it is stirred with a platinum rod, and the size of the flame is gradually increased, finally heating over a Mccker burner until the mass just fuses to a clear liquid. The cooled melt is treated with 50 cc. of 1:1 sulphuric acid, gently heated until nearly all water is expelled, and then more strongly until abundant fumes are evolved. The cold residue is boiled with water. This solution contains all the zirconium. If it is to be used for the selenite method of Smith and James, the zirconium is precipitated (along with many other bases) by ammonium hydroxide, filtered, washed free from sulphates—since sulphates are undesirable for the selenious acid

precipitation—and dissolved in hydrochloric acid.

Borax is strongly recommended by Lundell and Knowles 2 for the decomposition of all ores of zirconium. This flux is particularly suited to the decomposition of samples in which zirconium only is to be determined, and by precipitation with cupferron, since boric acid does not interfere with this reagent. If other elements of the sample are to be determined, the boric acid must be removed by volatilization as methyl borate, so in such cases it is better to employ the sodium peroxide fusion. In using the borax method Lundell and Knowles recommend the following procedure: 4 g: of the flux are melted in a platinum crucible and allowed to cool. About 0.3 g. of the finely ground ore is placed on top of the fused borax, the crucible is covered. and heated over a Meeker burner until thorough fusion has taken place, which does not ordinarily require more than half an hour. During the operation it is well to stir the melt occasionally with a short platinum rod or stiff wire. which is allowed to remain in the crucible, and which may be conveniently handled with the crucible tongs. When the decomposition of the orc is complete, the platinum rod is removed, and it is put into the beaker to be used for the solution of the melt. As the melt cools, the crucible is gently twirled in order to run the fusion up on the sides in a thin layer. The cooled melt is dissolved in 150 cc. of 1:5 hydrochloric acid in a 250-cc. beaker, by filling the crucible with acid, inverting in such a manner that one edge of the crucible rests on the crucible cover, which has been placed on the bottom of the beaker-thus allowing free circulation of the solvent-and then gently warming on the steam bath. The solution is transferred to a platinum dish or porcelain casserole, 20 cc. of 1:1 sulphuric acid are added, and the mixture is evaporated until heavy fumes escape.3 The cooled solution is next diluted to about 100 cc., the impure silica is filtered off and washed with hot water. This solution is allowed to stand warm over night. If the ore contained interfering amounts of phosphorus, it will be thrown down as zirconium phosphate by this digestion. If a precipitate appears, it is filtered and washed with 5% ammonium nitrate solution. This precipitate will contain zirconium,

¹ Experiments in the writer's (Brinton's) laboratory by Mr. Tohru Kameda indicate that there is no loss of zirconium by volatilization if the process is carried out as here described. Continuing the heating for 5 minutes after clear fusion has been attained may cause a loss of as much as 2 mg. of ZrO₂.

¹ Lundell and Knowles, J. Am. Chem. Soc., 42, 1439 (1920).

¹ Lundell and Knowles, J. Am. Chem. Soc., 42, 1439 (1920).
² During the evaporation boric acid will separate and form a crystal skin over the surface, thus retarding evaporation. Occasional stirring during this period will hasten the evaporation. As the sulphuric acid becomes more concentrated by evaporation, the boric acid eventually dissolves again.

and there is still apt to be a little zirconium in the impure silica first filtered off. Also there may be some phosphoric acid in the filtrate; so to this filtrate 5 g. of ammonium chloride, and then ammonium hydroxide in slight excess are added, and after boiling for several minutes, the precipitated hydroxides are filtered and washed with 2% ammonium nitrate solution. This filtrate is disearded. The precipitate and paper are digested in 100 cc. of hot 5% sulphurie acid solution, and the filter shreds and any insoluble residue are filtered and well washed with hot water. This solution, containing most of the zirconium of the sample, is temporarily set aside. The last residue filtered, the impure siliea, and any zirconium phosphate obtained by the over-night digestion are all ignited in the original platinum crueible. The ignition residue is moistened with water, 1 ce. of 1:1 sulphurie acid, and 5 cc. of hydrofluoric acid are added, and the mixture is heated until all sulphurie acid has been expelled. The residue in the crucible is fused with a little sodium carbonate, digested in water, and filtered, washing with hot water. The filtrate is disearded. The insoluble residue is again ignited in the platinum crucible, fused with potassium pyrosulphate; and, after cooling, the melt is dissolved in hot 5% sulphuric acid. This solution is added to the main solution, thus giving one solution in which is contained all the zirconium originally present in the sample.

SEPARATIONS

From Members of the Copper and Tin Groups. The members of these groups are precipitated free from zirconium by hydrogen sulphide in slightly acid solution.

From Iron, Nickel, Cobalt, Manganese, and Zinc. The iron, in acid solution, is reduced by hydrogen sulphide gas, tartaric acid equal to 5 times the approximate weight of the oxides present is added, the solution is made ammoniacal, and then hydrogen sulphide is passed into the solution until the sulphide precipitate has coagulated. The precipitate is filtered on closegrained paper, care being taken to keep the funnel well filled, so that oxidation of the sulphides and consequent "running through" is avoided. The sulphides are promptly washed, using the same precaution, with water containing a little ammonium ehloride and ammonium sulphide. If the cupferron precipitation of zireonium is to be used, the tartrate need not be destroyed, and it is sufficient to acidify to a total acidity of 10% of conc. sulphuric acid (by volume), and to boil out the hydrogen sulphide. If for further work it should be necessary to remove the tartrate, the solution is acidified with 10 ee. of conc. sulphuric acid, evaporated to a volume of about 50 ec., 10 cc. of conc. nitrie acid added, and the solution evaporated to fumes of sulphur trioxide. After cooling, 10 ee. of cone. nitric acid are again added, and the mixture once more evaporated to fumes. At times a third addition of nitric acid and evaporation may be necessary to completely destroy the tartaric acid.

From Titanium. Zirconium may be separated from titanium by precipitating the zirconium with Na₂HPO₄ or (NH₄)₂HPO₄ in a 10% (by volume) sulphurie acid solution, in presence of hydrogen peroxide. See Gravimetric Determination as phosphate.

From Thorium and Rare Earth Elements. These elements may be precipitated with an excess of oxalic acid, leaving the zirconium in the filtrate. (See "Detection" in chapter on thorium.) For complete separation the rare earth oxalates should be boiled with cone. sulphuric acid until decomposed, diluted, nearly neutralized with ammonia, and again precipitated with an excess of oxalic acid. The combined filtrates contain all the zirconium. (A method adapted to the determination of small amounts of rare earth oxides in the cupferron precipitate is given later.)

From Aluminum, Chromium, and Uranium. Zirconium is quantitatively separated from these three elements by precipitation with cupferron in 10% (by volume) sulphuric acid solution. The uranium must be in the hexavalent condition or it will contaminate the zirconium precipitate. (Nitric acid should not be used to oxidize uranium, as it decomposes cupferron. Uranium will practically always be in the hexavalent condition without special oxidation. If in doubt, the 10% sulphuric acid solution may be boiled with a little hydrogen

peroxide.)

From Molybdenum. By precipitation of molybdenum sulphide in acid solution. (See chapter on molybdenum.)

From Tungsten. By precipitation of tungsten in acid solution by cinchonine hydrochloride. (See chapter on tungsten.)

From Vanadium. By fusion of the mixed oxides with sodium peroxide or sodium carbonate, and leaching out the soluble sodium vanadate with water.

GRAVIMETRIC DETERMINATION OF ZIRCONIUM

By Precipitation with Cupferron. The solution, which has a volume of 300-400 cc., and contains 10% (by volume) of conc. sulphuric acid (any tartaric acid present does not interfere), is cooled to about 10° C., and then an excess of cupferron solution (6 g. dissolved in 100 cc. of cold water and filtered) is added. The formation of a fine white precipitate (nitrosophenylhydroxylamine) which redissolves shows that an excess of the reagent has been added. The zirconium precipitate is white and curdy, but any titanium present is also quantitatively precipitated, and it will impart a yellow color to the precipitate. A brownish color indicates that the previous separation from iron has been faulty. The precipitate is filtered and washed with cold 1:10 hydrochlorie acid solution. The precipitate and paper are carefully ignited in a weighed platinum crucible, very slowly until the rush of gases from decomposition of the organic matter has ceased; and then to constant weight over a blast or over a large Mecker burner. The weight thus found represents all the zirconium and titanium dioxides, and some rare earth oxides, if these elements have not previously been completely removed.

To correct for titanium and rare earths the ignited oxides are fused with potassium pyrosulphate, dissolved in 1:10 sulphuric acid, and diluted to exactly 100 cc. in a graduated flask. By means of a dry 50-cc. pipette exactly one-half of the solution is taken for the determination of titanium, and the pipette and the 100-cc. flask are completely rinsed into another vessel, thus

e giving the other half for the determination of rare earths.

Small amounts of titanium are determined by the colorimetric method; while for larger amounts the zine reductor—permanganate titration method—is used. For details of these see chapter on titanium.

Rare earths may be determined according to Hillebrand's method 1 as follows: "Precipitate the hydroxides with an excess of potassium hydroxide, decant the liquid, wash by decantation with water once or twice and then slightly on the filter. Wash the precipitate from the paper into a small platinum dish, treat with hydrofluoric acid, and evaporate nearly to dryness. Take up in 5 cc. of 5% (by volume) hydrofluoric acid. If no precipitate is visible, rare earths are absent. If a precipitate is present, collect it on a small filter held by a perforated platinum or rubber cone and wash it with from 5 to 10 cc. of the same acid. Wash the erude rare earth finorides into a small platinum dish, burn the paper in platinum, add the ash to the fluorides and evaporate to dryness with a little sulphuric acid. Dissolve the sulphates in dil. hydrochloric acid, precipitate the rare carths by ammonia, filter, redissolve in hydrochloric acid, ovaporate the solution to dryness, and treat the residue with 5 ce. of boiling hot 5% oxalic acid. Filter after fifteen minutes, collect the oxalates on a small filter, wash with not more than 20 ec. of cold 5% oxalic acid, ignite and weigh as rare earth oxides which are to be deducted from the weight of the enpferron precipitate."

While the recovery of the rare earths by this method is not absolutely

complete, the error is negligible for the amounts ordinarily found.

The sum of the weights of rare earth oxides and titanium dioxide found are subtracted from the weight of the ignited cupferron precipitate to obtain the

true weight of ZrO2.

By Precipitation with Selenious Acid.² The zirconium and other bases should be in about 5% (by volume) hydrochloric acid solution, free from sulphuric and nitric acids, and should be in a volume of about 750 cc. The solution is heated to boiling, and an excess of 12½% selenious acid solution (usually 20-40 cc.) is added. After the precipitate of zirconium selenite has settled it is filtered, washed with 3% hydrochloric acid solution (Smith and James directions; the writer prefers a wash liquid containing 40 cc. of 12½% selenious acid reagent in 750 cc. of 3% hydrochloric acid), ignited to constant weight over a strong Meeker burner or blast, and weighed as ZrO₂. For a discussion of the possible interference of large amounts of iron, of titanium, and of phosphoric acid, the original paper of Smith and James should be consulted.

By Precipitation with Ammonium Phosphate. This method is suitable for separations, and for the determination of small amounts of zirconium such as are encountered in rock analysis. In view of the probability that almost all minerals of zirconium contain appreciable amounts of celtium ("hafnium"), which gives practically all the reactions of zirconium, but which has a very much higher atomic weight, an uncertainty as to the factor ZrO₂/ZrP₂O₇ exists, so the pyrophosphate can hardly be recommended as a weighing form for large amounts of zirconium. The following details are recommended for observance in using this method.³

A. Volume of Solution. From 25 ce. for small amounts (i.e., 0.0005 g. ZrO₂) to 200 ee. for amounts ranging around 0.1 g. ZrO₂.

¹ W. F. Hillebrand, The Analysis of Silicate and Carbonate Rocks, U. S. Geol. Survey Bulletin 700, p. 176; Lundell and Knowles, loc. cit., p. 1446.

² Smith and James, loc. cit.

³ Lundell and Knowles, J. Am. Chem. Soc., 41, 1806 (1919); Hillebrand, op. cit., p. 173; Nicolardot and Reglade, Compt. rend., 168, 349 (1919).

B. Acidity. Twenty per cent sulphurie acid by weight.

C. Hydrogen Peroxide. Sufficient to keep titanium peroxidized; 10 ec. will do no harm.

D. Precipitant. Secondary animonium phosphate in excess. From 10 to 100 times the theoretical requirement, as expressed by the ratio $Zr: P_2O_6$, should be used here. The large excess is desirable when small amounts of zirconium are determined.

E. Precipitation Conditions. (1) Temperature: Cold or tepid, preferably 40-50° C. (2) Time: Two hours for amounts of ZrO₂ in excess of 0.005 g. Six hours, or longer, for smaller amounts.

P. Filtration. Warm solution, decant as far as possible to avoid clogging the filter.

G. Washing. This should be done with cold 5% ammonium nitrate, since

the phosphate is appreciably soluble in pure water.

H. Ignition. Ignite very carefully in a partially covered platinum crucible over a low flame until carbon is destroyed, then blast or heat over a Meeker burner for 15 minutes.

RECOMMENDED METHOD FOR THE DETERMINATION OF ZIRCONIUM IN COMMERCIAL ZIRCONIUM ORES

The following combination gives a method essentially as recommended by the U. S. Bureau of Standards. Details will be found in the respective sections of this chapter.

Decomposition by fusion of 0.3 g. sample with borax, following the procedure under "Preparation and Solution of the Sample" until the sulphuric acid solution containing all the zirconium originally present in the sample is obtained.

Separation from members of the copper and tin groups by precipitation with hydrogen sulphide in an approximately 1% sulphuric acid solution; and then, without intervening filtration, separation from iron, manganese, etc., by treatment with tartaric acid, ammonia, and hydrogen sulphide, as detailed under "Separations," finally obtaining the zirconium in 10% (by volume) sulphuric acid solution. (Removal of tartaric acid is not necessary.)

Precipitation with cupferron, with subsequent corrections for any titanium and rare earths present, just as outlined in the "Gravimetric Determination."

Determination of Zirconium in Steel. See chapter on iron.

Determination as Zirconium Oxide

With pure salts the zirconium may be precipitated completely as the hydroxide by the addition of ammonia, settling and finally igniting and weighing as the oxide, ZrO₂.

VOL. I PART II QUALITATIVE TESTS OF SUBSTANCES

QUALITATIVE TESTS OF SUBSTANCES

BLOWPIPE AND FLAME TESTS OF SOLIDS

Blowpipe Tests on Charcoal

Heat a small portion of the material on charcoal in the reducing flame, using a blowpipe. Scoop out a round hole in the charcoal, place a little of the substance in the cavity, and direct the inner flame of the blowpipe against it at an angle of thirty degrees.

RESULT OF TEST.

Melts and runs into the charcoal

An alkaline residue on charcoal

A residue which, when moistened with a drop of Co(NO₃)₃ and heated in O. F., produces a color which is blue

Produces a color which is green Produces a color which is red

Produces a color which is pink or rose-red

Deflagrates

Leaves an incrustation which is white near flame

White, garlic odor

Dark red

Red to orange

Lemon yellow (hot), light yellow (cold)

Orange yellow (hot), light yellow (cold)

Yellow (hot), white (cold)

INVERENCE.

Alkalies. K, Na, etc. Ca, Sr, Ba, Mg.

Aluminum, silicon.

Zinc, tin, antonony. Barium.

Manganese.

Nitrates, chlorates.

Antimonv.

Arsenic.

Silver.

Cadmium.

Lead.

Bismuth.

Zinc or tin, latter nonvola-

tile.

Blowpipe Tests. - Substance fused with Na₂CO₂ on Charcoal. Place a small amount of the substance on charcoal with a little sodium carbonate, and fuse, using reducing flame.

RESULT OF TEST.

Metallic globules, without incrustation

Vellow flakes

Red flakes

White globule, moderately soft Metallic globules, with incrustation

White, moderately soft beads

White, brittle beads

Yellow in O. F.

Green in O. F.

A substance (in R. F.) which, when moistened and placed on a silver coin, leaves a brown or black stain

INFERENCE.

Gold.

Copper.

Silver.

Lead or tin (volatilized lead leaves vellow coat).

Bismuth or antimony (yellowish).

Chromium.

Manganese.

Sulphur compounds.

Test.	Inference.
Dark gray magnetic powder which, when moistened on a filter paper with a drop of dil. HCl and HNO ₁ , and gently dried over a flame, leaves a stain which	•
is faint pink, turning blue	Cobalt.
Green stain, turning yellow	Nickel.
A stain turned blue by K ₄ Fe(CN) ₆	Iron.

In place of using charcoal the above tests may be made with a splinter of wood covered with a coating of fused Na₂CO₃. The test is made by dipping the heated splinter into a mixture of the powdered substance with fused sodium carbonate and plunging for a moment in the reducing flame. Examine the material on the splinter, scrape off on a piece of glazed paper and examine.

Blowpipe Test. Substance moistened with cobalt nitrate solution and ignited.

Color of Residue or Incrustation.	Inference.
Brick red	BaO
Pink	MgO
Gray	SrÖ, CaO.
Yellowish green	ZnO
Dark muddy green	Sb ₂ O ₅
Bluish green	SnO
Blue	Al ₂ O ₃ , SiO ₂

Flame Test

Flame Test. Moisten a platinum wire in conc. HCl, dip into the powdered substance and insert into a Bunsen flame. If sodium is prominent, examine through a blue glass. (Test the cobalt glass to see if it is effective in cutting out the yellow sodium light by examining a sodium flame through it.)

FLAME COLOR.	Color through Blue Glass.	ELEMENT.
Carmine red	Purple	Lithium
Dull red	Olive green	Calcium
Crimson	Purple	Strontium
Golden yellow	Absorbed	Sodium
Greenish yellow	Bluish green	Barium, molybdenum
Green	· ·	C_{11} , $-PO_4$, $-B_2O_2$,
Blue		Cu, Bi, Pb, Cd, Zn, Sb, As
Violet	Violet red	Potassium

The platinum wire should be cleaned before making the test. This can be accomplished by dipping it into conc. HCl and holding it in the Bunsen, or, better, a flame of a blast lamp, until the flame is no longer colored. Repeatedly dipping into the HCl may be necessary.

Examine the flame through a spectroscope, if available, and compare the spectra with a spectra chart. Mere traces of the alkali and alkaline earth metals can be detected in this way by their characteristic spectral lines.

Behavior of Substances fused with Microcosmic Salt and Borax Beads

timales goodlered substance

Coloriess (a. c.) Fe. M. (b. c.); Fe. M. Cr. Ce. M. M. (c. c.) M.	r bead i. o be exulter most	ar bead is formed by fusing the flux on a to be exumined, and heat again—first in are mostly changed to oxides. In the Testronoly saturated; h. c., hot and cold.	A clear bead is formed by fusing the flux on a loop of platingm wire. Dip the bead in the finely powdered substitute to be exumined, and heat again—first in the oxidizing frame; second in the reducing or inner flame. Metallic salls are mostly changed to oxides. In the Table—k. signifies hot; c., cold; sups., supersaturated with oxide; s. s., strongly saturated; h. c., hot and cold.	e. Dip the bead in the f econd in the reducing or in: ; c., cold; sups., supersat	inely powarted superince ner flame. Metallic salls urated with oxide; 5. 5.,	
At we are the correducing Flame. In outer or oxidizing Flame. In outer or oxidizing Flame. Si (swims undissolved). Si (swims undissolved). Si (swims undissolved). At we are the correducing Flame. At we a	C-Gran	With Microcosmic Salt,	um Ammonium hate.	With Sodium Tetri	aborate (Borax).	Q
Si (swims undissolved) Si (swims undissolved) Al (s. s.) (swims undissolved) h. c.: Si, Al, Sn (sups. paque) Al, Sn (sups. paque) h. c.: Si, Al, Sn (sups. paque) Al, Sn (sup	Bead.	In outer or oxidizing Flame.		In outer or oxidizing Flame.	In inner or reducing Flame.	UA:
A. (8. 8.): Fe. U, Ce. A.: Fe, Tl. A., sups.: Fe. U. A.: Tl. Mo. A. (8. 8.): Fe. Nd. Cr. Ce. C.: Cl. A.: Tl. Mo. C.: Cl. A.: Tl. Mo. C.: Tl. A.: Tl. Mo. C.: Tl. A.: Tl. Mo. C.: Tl. A.: Cl. Mo. A.: Cl. A. A.:	Colorless.			90 A	Si, Al, Sn (s. s. opque). Maine earths and earths. h. c.: Mn, Ge. h.: Cu.	LITATIV
h. (s. s.): Fe, Nd. Cr. Ce. c.: Cu. h.: Fe, Ce. c.: Cu (sups. opages). c.: Cu (sups. opages). h. c.: Mn. c.: Ti. h. c.: Mn. c.: Ti. c.: Ti. h. c.: Go. h. c.: Co. h. c.: Co. h. c.: Co. c.: Cu. c.: Cu. c.: Cr. c.: Cr. h. Cu. Mo. c.: Cr. c.: Cr. c.: Cr. h.: Cu. Mo. c.: Cr. c.: Cr. c.: Cr. h.: Cu. Mo. c.: Cr. c.: Cr. c.: Cr. c.: Cr. h.: Cu. Mo. c.: Cr. c.: Cr. c.: Cr. h.: Cu. Mo. c.: Cr. c.: Cr. c.: Cr. h.: Cu. Mo. c.: Cr. c.: Cr. c.: Cr. h.: Cu. Mo. c.: Cr. c.: Cr. c.: Cr. h.: Ch. Mo. c.: Cr. c.: Cr. c.: Cr. h.: Ch. Mo. c.: Cr. c.: Cr. c.: Cr. h.: Ch. Mo. c.: Cr. c.: Cr. c.: Cr. h.: Ch. Mo. c.: Cr. c.: Cr.	1		h.: Fe, Ti. c.: Ni.	h., not sat.: Fe. U. h., sups.: Pb, Bl, Sb.	h.: Ti, Mo.	Е ТЕ
h. c.: Mn. c.: Ti. h. c.: Mn. c.: Ti. h. c.: Go. c.: Go. h. c.: Go. h. c.: Go. c.: Gu. c.: Gu. c.: Gr. c.: Gr. h.: U. Mo. c.: Gr. h. c.: Gr. h.: Gu, Mo. c.: Gr. h.: Gr. Fe with Go. c.: Gr. h.: Gr. Fe with Go. rups.: Fe. c.: Gr. h.: Gr. Fe. with Go. rups.: Fe.	Red.	1	c.: Cu. h.: Ni, Ti with Fc.	h.: Fe, Ce. c.: Ni.	c.: Cu (sups. opaque).	STS
h. c.: Co. h. c.: Co. h. c.: Co. h. c.: Co. c.: Cu. c.: Cu. c.: Ct. c.: Ct. c.: Ct. c.: Ct. h.: Cu, Mo. d U, Mo. d Cu, Mo. d Cu, Mo. d Cu. d Cu. c.: Ct. d Cu, Mo. d Cu, Mo. d Cu, Mo. d Cu. d Cu. Ag. Pb, Sb, Cd, Bl, Zn, Ml. d Cu. d Cu. d Cu. The same as with microcosmic salt.	Violet	h. c.: Mn.	c.: Ti.	h. c.: Mn. h.: Ni with Co.	a.: T1.	
A.: Cu, Mo; Fe with Co or c.: Cr. h.: Cu, Fe with Co. sups.: Fe. h.: U, Mo. c.: Cr. h.: Cu, Fe with Co. The same as with microcosmic sail.	nethyst. Blue.	h. e.: Co.	h. c.: Co.	h. r.: Co. c.: Cu.	h. c.: Co.	
Ag. Pb. Sb. Cd. Bi, Zn. Ni.	Green.	h.: Cu, Mo; Fe with Go or	6: Cr.	c.: Cr. h.: Cu, Fe with Go.	Cr. sups.: Fo.	
	Gay and		Ag. Pb. Sb, Cd, Bi, Zn, Mi.		The same as with micro-cosmic salt.	627

	PPV Y	Add hydrochloric acid.	c arid.		Precipitate
	Pass hydrosulphuric acid gas into the	rric acid gas	warm sol	ution. In and Copper Group.	B
Sohu	Solution.		1	pitate.	bCl (gCl gCl
Crn becomes Cr'', Fe''' becomes Fe'' and Mar's becomes Mar'. Bell to expel H.S., add HWO, and boil to oxidize ferrosum; and semonium chloride and ammonium hydroxide.	"becomes Fe" and Ma'" becomes Ma". HRO, and boil to oxidize ferrorum; and add annonium hydroxide.	n Ma". n; and add	HgS (bk) PbS (bk) His; (br) Cu; (bk) CuS (bk) CuS (y)	As,S, (y) As,S, (y) As,S, (o) Sb,S, (o) SaS, (o) SaS, (y) SaS (br) As,S, (br) PtS, (bk) MoS, (br)	(M) Ser
		(3) Iron Group.	Add yellor Copper Group.	Add yellow ammonium sulphide. er Group.	3
Solution. Solution. Solution. Solution. Solution. MgCL, UKE, ZaO, and MgCL, IKE, CI are formed; also soluble double compounds of Co and Ni with ammonium hydroxide. With ammonium hydroxide.	ounds of Co and Ni	Al(OH); (w) Al(OH); (g) Cr(OH); (g) Fe(OH); (r)	HgS PbS PbS Cus Cus Cus Cds	(NH ₄),As-S ₄ (NH ₄);SbS ₄ S (NH ₄);SbS ₅ S (NH ₄);SbS ₅ Solution. Solution. (NH ₄);MoS ₄	IgCl Add NH
Aun nyarempanen erra er ere	(4) Zine Group.	Boil with	Digest in hot dilute HNO.	Add dilute hydrochloric acid. Preripitation of Tin Group.	OH (F
Solution. Add NE,OE and (NE,),CO. (6) Calcinon Group.	CoS (bk) Signature NiS (bk) E MnS (pk) L ZnS (w)	{ g NaAlO ₃ A g Cr(OH); g Fe(OH);	HgS Diss Pb(NO ₃) ₂ Bi(NO ₃) ₂ Cu(NO ₃) ₃ Cd(NO ₃) ₃	As-S, As-S, Sb-S, Sa-S, Au ₁ S ₁ PtS, MoS,	
Solution. Add Ma, HPO, 10 a portion, and 10 a portion, and 10 a portion, and 10 a portion, and 10 a portion and 11 a portion and 11 b panelye in 12 and 12 and 12 and 12 and 12 and 13 and 13 and 15	Digest with cold dilute HCt. So. So. Soc. Soc.	Fuse on platinum foll KNO; and Na;CO;. Extract with water.	polye in nitrohydrochlosi Body 2 PbSO, Comb Bi(NO ₂); Cu(NO ₂)	H,AsO, March Pick Pick Pick Pick Pick Pick Pick Pick	(b) +H ₁ 8=Pb8 black. [gCl+Hg black.) ₂ (AgCl) ₂ } acidify with 33

```
F THE METALS. ANALYSIS OF THE SOLUTION.
```

c) +KcCrO;=PbCrO; yellow. (d) +EI=PbI; yellow.

```
-AgCl white.
    AsH, gas
```

SbH, gas+8b

Conduct egas into H,AsO, Remove AgNO, with CaCle and add H,S { As,S, Lemon yellow. Gützeit Test—AsH₂ colors HgCl₂ paper a deep marcon See method on page 40. SbAg: Dissolve in hot HCl, dilute, filter and add H.S Sb.S. Orange.

Sa | Sc. | S | Sect with mgcut. | August with mg of any stray. | Sect. reject or test in Marsh apparatus. | Sect. reject or test in Marsh apparatus. | Sect. reject or test in Marsh apparatus. | AuCl. NH.Cl Evaporate and sect. | AuCl. NH.Cl Evaporate and sect. | PtCl. | Ignite to Pt°, Gray.

Blue to green-brown Evaporate to dryness with excess of HNO. Dissolve res. in NH₄OH and add to an or black solution. Texcess of HCl. Test this sol. with Na₂PHO Ammonium phosphomolybdate, Yellow.

id and test with (a) SnCla = White HgCl or Gray to Black Hg. (b) Au wire = Hg on wire.

by formation of PbIs or PbCrOs. See Pb above.

g Bi(OH), Add hot K,SnO, pouring over ppt. on filter Bi Black. Cu(OH), 2NH, OH. 2NH, NO, Deep blue solution evidence of copper.

For traces add HC, H,O, and test with K,Fe(CN), Cu,Fe(CN), Red-brown. Cd(OH),2NH,OH.2NH,NO. Add KCN till blue color disappears, then HeS CdS Lemon-yellow.

th HCl and precipitate with (NH_c)₂CO₂ Al(OH)₂ White, gelatinous.

Res. Fe(OH):

ith | Sol. | KaCrO, and | Acidify with HCHO, and add Pb(C,HaO,); | PbCrO, Lemon-yellow. Dissolve in HCl and add ECNS Fe(CNS), Blood red. Test original solution (acid) with ECNS for Fe" and with EFe(CN), for Fe" Fe, Fe(CN), Blue.

CoCL NiCL

a. Test with borax bead. Blue bead. c. b. Add NaHCO, and H₂O₂, Green solution. a. Test with borax bead. Brown bead. c. b. Heat with Br { Ni(OH)₄} add KI. and NaOH { Ni(OH)₄} c. Or ovaporate +HeSO, and add nitrose-6-naphthes. co—Red precipitate. Test with borax beast c. Or make sol. ammoniacal and add 1% alcoholio sol. nitrosobetanaphthol = [(CH_i)₁C₁N₂O₃H_bNi Red.

Mn(OH): { Boil with PbO2 and HNO2 HMnO4 , Purple.

Na,ZnO, { Add H.S } ZnS White. Ppt. is insoluble in dilute scetic scid.

BaCrO Sr(C,H,O,)

Ca(CaH,Oa)a

Dissolve in HCl and add H.SO. BaSO. White.

SrCO₃
SrCO₄
SrCO₅
SrCC₂
SrCC₂
SrCC₃
SrCC₄
SrCC₄
SrCC₄
SrCC₄
SrCC₅
SrCC₄
SrCC₅
SrCC₄
SrCC₅
SrCC₄
SrCC₅
SrCC₄
SrCC₅
SrCC₅
SrCC₄
SrCC₅
SrCC₅
SrCC₄
SrCC₅

Precipitate MgNH,PO, White.

K-Apply flame test using cobalt glass. Violet. Ra-After removal of Mg apply flame test, yellow.

To the original solution add EOH in strong excess, warm (note odor) and test with moist Etan paper; pass gas into Nessler's reagent K.HgL sol. [NHg.I, Brown.

(r) = red; (g) = green; (pk) = pink. Ppt. = precipitate. Res. = residue. Sol. = solution.

GENERAL SUMMARY OF TESTS FOR ACIDS

Acids.	DETECTING REAGENTS.	REACTIONS RESULTING FROM TEST.
Acetates	H ₂ SO ₄ (conc.)	Odor of vinegar
Arsenates	(a) $(N\dot{H}_4)_2MoO_4 + HNO_3$	Yellow precipitate
	(b) Magnesia mixturc	White granular precipitate
	(c) Reduced on C+Na ₂ CO ₃	Garlic odor, arsenic mirror
Arsenites	(a) Magnesia mixture	No reaction
	(b) H₂S+HCl	Yellow precipitate
Bromides	(a) H ₂ SO ₄ (conc.)	Red Br vapor
	(b) Chlorine water + CS.	Reddish color, due to Br
Borates	H ₂ SO ₄ (conc.) +alcohol	Green flame
Carbonates	Dilute acids	CO2 evolved. Limewater test
Chlorates	(a) H ₂ SO ₄ (conc.)	Explosive liberation of CI + CIC
	(b) Heated alone	O given off
Chlorides	AgNO ₈ +HNO ₃	White precipitate, sol. in NH40
Chromates	(a) H ₂ SO ₄ (conc.)	O liberated (sol. yellow to green
	(b) HCl	Chlorine of HCl liberated
	(a) Alcohol + NaOH	Reduced and Cr(OH)3 precip
Cyanides	H₂SO₄ (conc.)	tated HCN (POISON). Odor, bitte almonds
Ferricyanides	FeSO ₄ +HCl	Turnbull's blue precipitate
Ferrocyanides	FeCl ₃ +HCl	Prussian blue precipitate
Fluorides	H ₂ SO ₄ (conc.)	HF gas liberates silicic acid from glass rod with drop of H ₂ O
Hypochlerites	Dilute acids	Cl liberated, yellow gas
lodides	(a) H ₂ SO ₄ (conc.)	Violet vapor of iodine
Iouides	(b) Chlorine water+CS ₂	Violet color to CS₂
Nitrates	FeSO ₄ + H ₂ SO ₄ (conc.)	Brown ring
Nitrites 1	Dilute acids	N ₂ O ₈ brown evolved
Oxalates	H ₂ SO ₄ (conc.)	CO+CO2 evolved
Permanganates	Reducing agents	Decolorized
Phosphates	HNO8+(NH4)2MOO4 at 40°	Yellow precipitate
Silicates	(a) Fused with Na ₂ CO ₈ and HCl added	Silicic acid precipitated
•	(b) HF	SiF4 gas liberated
Sulphates	HCl+BaCl ₂	White precipitate of BaSO4
Sulphides	Dil. acids	H ₂ S gas blackens Pb(C ₂ H ₈ O ₂)
Sulphites	Dilute acids	SO ₂ gas
Sulphocyanides	FeCla	Deep red color
Thiosulphates	Dilute acids	SO ₂ gas + free S
Tartrates	Ignited	Char. Odor of burnt sugar
Organic acids	Heated	Generally char.
O'Same acids	1	

¹ Nitrites + KI + CS₁ = violet color in CS₂ due to free I.

TABLES OF REACTIONS BASES AND ACIDS

REACTIONS OF THE BASES

TABLES OF REACTIONS OF THE BASES.

HYDROGEN CHLORIDE GROUP.

			•
Present.	LEAD, Pb(NO ₂) ₂ .	Mercury, HgNO ₂ .	Silver, Agnor
	Lead chloride, PbCl, white ppt. Slightly sol. in cold water. Solubility in 100 c.c. H ₂ O,0° = 673 mg. 100° = 3340 mg. Converted into the insol. basic salt by N4,0H.	Lead chloride, PbCl, white ppt. Mercurous chloride, HgCl, white Slightly sol. in cold water. ppt. Sol. in hot HNO; and in aqual Solubility in 100 c.c. H ₂ O ₂ = 673 regia. NH ₂ OH converts it to HgCl. solubility in 100 c.c. H ₂ O ₃ = 673 regia. NH ₂ H + Hg.black. 100 c.c. H ₂ O disrinto the insol. basic salt by solves 0.31 mg. (cold), 10 mg. (bot). H ₄ OH.	Mercurous chloride, HgCl, white Silver chloride, AgCl, white ppt. Sol. in hot HNO; and in aqua regia. NH4OH converts it to HgCl. KCN, and Na ₂ S ₂ O ₃ . AgCl darkens regia. NH4OH converts it to HgCl. in the light. Solubility in 100 c.c. NH4+ Hg. black. 100 c.c. H ₂ O dispenses o.31 mg. (cold), 10 mg. (hot).
Ammonium hydroxide, NH ₄ OH.	(PbO), Pb(NO;), Basic salt, white ppt. Insol. in excess. Only slightly sol. in water.	Mercuric ammonium salt and mercury, HgNH ₃ NO ₃ + Hg, black ppt. Insol. in excess.	Mercuric ammonium salt and mercury, HgNH ₃ NO ₃ + Hg, black ppt. Sol. in excess Sol. in KCN. 4.3 ³⁵⁰ mg. in roo c.c. H ₂ O. Sol. in KCN. Insol. in excess.
Hydrogen sulphide, H ₂ S.	Lead sulphide. PbS. black ppt Insol in (NH ₄): Sx. Sol. in HNO ₃ . Cold water dissolves o.1 mg. Hot water, insol.	Mercuric sulphide. HgS + Hg. black ppt. Slightly sol. in HNO3. Sol. in aqua regia. Insol. in water.	Mercuric sulphide, HgS + Hg. Insol in (NH4,1,5x. Sol. in hot black ppt. Slightly sol. in HNO3. HNO3. o. o. 2 mg. in cold water. Sol. in aqua regia. Insol. in water. in conc. HySO4.
Potassium chro- mate, K ₂ CrO ₄ .	Lead chromate, PbCrO,, yellow ppt, Slightly sol, in HNO; Sol, in NH,OH. Solubility o 02 ¹⁸⁰ Insol, in hot water and in acetic acid.	Mercurous chromate. Hg,CrO,, brick red. Slightly sol in HNO,. Sol. in aqua regia. Sol. in hot water and in KCN.	Potassium chro- Lead chromate, PbCrO, yellow Mercurous chromate. Hg2CrO, brick ppt. Sol. in HNO; Sol. in HNO; Sol. in HNO; Sol. in hot water and in acetic in KCN. Recurous chromate. Hg2CrO, brick Silver chromate, Ag2CrO, dark red state. Sol. in HNO. Sol. in HNO; and in Accordance in HNO. Sol. in hot water and in acetic in KCN. Recurous chromate. Hg2CrO, brick Sol. in HNO; and in Insol. in HNO; acetic in KCN.

Potassium ferro- cyanide, K.Fe(CN)s.	Lead ferrocyanide, Pb,Fe(CN), Mercurous ferrocyanide, white ppt. Insol. in cold water. Hg,Fe(CN), white ppt.	Mercurous ferrocyanide, Hg,Fe(CN)s, white ppt.	Silver ferrocyanide, Agree(CN)s, yellowish white ppt. Insol. in acids and in NH ₄ OH. Sol. in KCN.
Sodium carbon- ate, Na ₄ CO ₃ .	Basic lead carbonate, 2 PbCO ₃ · Pb(OH) ₃ , white ppt "white lead." Insol. in hot and cold water.	Basic salt, yellow ppt, becoming black.	Silver carbonate, Ag ₂ CO ₃ , white ppt. Sol. in NH ₄ OH, 3·116°, 50 mg. at 100° in H ₂ O. Sol. in Na ₅ S ₂ O ₅ .
Sodium hydrox- ide, NaOH.	Lead hydroxide, Pb(OH), white ppt. Sol. in excess. Sol. in HNOs. Insol. in NH,OH. Sol. in KOH. Slightly sol. in water.	Lead hydroxide, Pb(OH), white Mercurous oxide, Hg,O, black ppt. ppt. Sol. in excess. Sol. in Sol. in HNO,. Insol. in NH,OH. Sol. and alkalies. Sol. in glacial acetic in KOH. Slightly sol. in water.	Silver oxide, Ag ₂ O, brown ppt. Sol. in NH ₂ OH and in HNO ₃ . 43 mg. at 20° in H ₂ O. Sol. in KCN.
Stannous chloride, SnCl ₂ .	Stannous chloride, Lead chloride, PbCl., Sol. in SnCl	Sol. in Mercury. Hg. dark gray ppt. Sol. Silver chloride, AgCl, white ppt. in HNOs, conc. H;SO4. Insol. in (See above.)	Silver chloride, AgCl, white ppt. (See above.)
Suphuric acid, H ₂ SO ₄ .	Lead sulphate, PbSO ₄ , white ppt. Insol. in excess. Slightly sol. in HNO ₅ . Sol. in NaOH, NH ₄ C ₂ H ₅ O ₇ . 4.2 at 20°.	Mercurous sulphate, Hg.SO ₄ , white Silver sulphate, Ag.SO ₄ , white ppt. ppt. Slightly sol. in water, 200 mg. Formed only in conc. solutions. Sol. in H ₂ SO ₄ , HNO ₃ . Insol. in alkalies. Sol in H ₂ SO ₄ and in HNO ₃ . 580 mg. in H ₂ SO ₄	Silver sulphate, Ag.SO, white ppt. Formed only in conc. solutions. Insol. in alkalies. Sol in H ₂ SO ₄ and in HNO ₃ . 580 mg. in H ₂ O.
Miscellany.	Zn ppts. Pb in crystalline form. Pb sol. in HNOs. Hot conc. H ₂ SO ₄ .	Pptd. in acid solutions by Cu, Zn, Insoluble salts, AgBr, AgI. Ag is from its salts as metallic Hg. SO, displaced from its salts in crystalline reduces mercurous salts to Hg, form by Zn, Cu, Hg, and in gray which collects as globules on boiling form by SO, SnCl, FeSO, etc. solution. Hg sol. in HNO ₃ . Insol. Ag sol. in HNO ₃ . Insol. in alkalies, in HCI.	Insoluble salts, AgBr, AgI. Ag is displaced from its salts in crystalline form by Zh, Cu, Hg, and in gray form by SO, SnCl, FeSO, etc. Ag sol. in HNO ₂ . Insol. in alkalies.
The numerals indicate	ate milligrams of the substance that will dis	isolve in 100 c.c. of water at stated tempera	The numerals indicate miligrams of the substance that will dissolve in 100 c.c. of water at stated temperature. Reference to Van Nostrand's Chemi

cal Annual, edited by Olsen,

THE HYDROGEN SULPHIDE GROUP.

Insoluble Subgroup.

Sol. = Soluble. Insol. = Insoluble.

REAGENT.	BISMUTH, BICL.	CADMIUM, CdSO ₄ .	COPPER, CuSO.	Mercury (= ic), HgCls.
Hydrogen sulphide, H ₂ S.	Bismuth sulphide, Bi ₂ S ₃ , brown ppt. Sol. in HNOs. Insol. in (NH ₄) ₂ S ₄ and in KCN. Cold water roc.c. dissolves 0.018 mg.	Cadmium sulphide, CdS, yellow ppt. Sol. in HNOs, yellow ppt. Sol. in HNOs, H.SO, (hot dil.). Insol. in (NH ₁). SS, KCN. Cold H ₂ O, o.13 mg. Hot H ₂ O forms coloidal solution.	Copper sulphide, CuS. black ppt. Sol. in HNOs, v KCN. Slightly sol. in (NH4,),5x. Insol. in H;SO4 (hot dil.). Cold H;O, 0.033 mg.	Mercuric sulphide, HgS, white → yellow → red → brown → black. Insol. in HNOs, (NH4),5x. Sol. in Br + KClOs or aqua regia, Na ₂ S. Cold H ₂ O, 2.5 mg.
Ammonium hydroxide, NH ₆ OH.	Bismuth hydroxide, Bi(OH)s, white ppt. In- sol. in excess. Changed by boiling to Bi ₂ O ₃ . Insol. in H ₂ O. Insol. in alkalies.	Cadmium hydroxide, Cd(OH)2, white ppt. Sol. in excess. Insol. in water, s.g. o.26 ²²⁰ mg. Sol. in NH, salts.	Basic copper, Ammonium sulphate. Sol. in excess = a deep blue. Cu(NHJ,TSQ,".H-Q, characteristic test.	Amido mercuric chloride, HgNH ₂ Cl, white ppt.
Potassium chromate, K ₂ CrO ₄ .	Bismuth chromate, (BiO) ₂ CrO ₄ , yellow ppt. Sol. in HNO ₅ . Insol. in KOH. (See Pb.)	Basic chromate, Cd ₂ (OH) ₂ CrO ₄ , yellow. Insol. in NaOH.	Copper chromate, CuCrO ₄ , reddish brown ppt. Sol. in NH ₄ OH, forming a green solution.	Mercuric chromate, HgCrO ₄ , reddish yellow ppt. Sol in HNO ₃ . Slightly sol. in water.
Potassium cyanide, KCN.		Cadmium cyanide, Cd(CN)s, white ppt. Sol. in excess, = Cd(CN)s(KCN)s, From this H ₂ S ppts. Cd3, yellow.	Copper cyanide, Cu(CN) ₂ , greenish yellow ppt. Sol. in excess = Cu(CN) ₂ (HCN) ₂ . No pptn. by H ₂ S.	Hg(CN), Sol. in water.

Fotassium ferrocyanide, K ₄ Fe(CN) _b .	Jismuth ferrocyanide. Bi.(Fe(CN) ₈), white ppt. Insol. in HCl.	Cadmium ferrocyanide, CdyFe(CN)6, yellowish white ppt. Sol. in HCI. Insol. in H ₂ O.	Copper ferrocyanide, Cust'e(CN)s, reddish brown pp. Slightly sol. in NH ₄ OH. Insol. in acids.	zn	
Sodium carbonate, Na _z CO _z .	Basic bismuth carbon- ate, (BiO) ₂ CO ₃ , white ppt. Insol. in water. Sol. in acids. Insol. in Na ₂ CO ₃ .	Cadmium carbonate, CdCO ₁ , white ppt. Insol. in excess. Sol. in NH ₄ OH. Sol. in acids.	Basic copper carbonate, Cu ₂ (OH) ₂ CO ₁ , blue. Changed to black CuO on boiling.	Mercuric basic carbonate, HgCO ₃ (HgO), reddish abrown ppt. Changed to yellow HgO on boiling. Insol. in H ₂ O.	, 1012
Sodium hydroxide, NaOH.	Bismuth hydroxide, Bi(OH)s, white ppt. See above.	Cadmium hydroxide, Cd(OH), white ppt. Insol. in excess. (See above.)	Copper hydroxide, Cu(OH)s, light blue. Insol. in excess. Changed to black CuO on boiling.	Mercuric hydroxide, Hg(OH): Easily changed to HgO, yellow. Insol. in excess. In presence of NH ₄ Cl = HgNH ₂ Cl,	MOTIONS OF
Sulphuric acid, H ₂ SO ₄ .	* No precipitate.	No precipitate.	No precipitate.	No precipitate.	1111
Stannous chloride, SnCl ₂ .	Darkens. Precipitate of BiOOH changes to Bi ₂ O ₅ .		Cuprous chloride, CuCl, white ppt. Sol. in HCl, NH, aq., NH ₄ Cl. Insol. in H ₄ O.	Murcurous chloride, HgCl, white ppt. In excess = gray, Hg.	DAGE
Miscellany.	In water Bi salt precipitates as BiOCl, white. Reduced by Na ₂ SnO ₂ to metallic Bi, black. Bi sol. in HNO ₃ , conc. H ₂ SO ₄ .	Na, HPO, ppts. Cds (PO,) b. white. Sol. in NH,OH and in dilute acids. Cd sol. in acids. Sol. in NH,NOs.	Na,HPO, precipitates Cu ₁ (PO ₁), greenish blue. Sol. in NH,OH. KI ppts. Cu ₂ I ₂ , white+I=brown. Cu ₂ I ₃ , white+I=brown. conc. H ₂ SO ₄ .	Precipitated by Cu. KI ppts. Hgl., red. Sol. in excess. Hg sol. in HNO, conc. H5SO, Insol. in HCi.	A)
		A A			

· A precipitate forms on long standing.

The Soluble HeS

	ARSENIC,	As, As	ANTIMONY,	Sb, Sb
	(ous) K _S As() _S ,	(ic) KH ₂ AsO ₆ .	(ous) SbCl ₈ .	(ic) KSbO ₂ .
Hydrogen sulphide, H₂S.	Arsenic trisul- phide, As ₂ S ₋ , yellow ppt. Sol. in alkalies, (NH ₁) ₂ S ₋ , (NH ₄) ₂ S. Insol. in conc. HCl.	Arsenic trisul- phide+S. As ₂ S ₃ +S ₂ , yel- low. The ppt. forms slowly by heat.	Antimony trisul- phide, Sb ₂ S ₃ , orange ppt. Sol. in alkalies, (NH ₄) ₂ S ₃ , (NH ₄) ₂ S, HCl (conc.). 0.17 mg.	Antimony penta- sulphide, Sb ₂ S ₅ , orange ppt. Sol. in alkalies, (NH ₄) ₂ S ₅ , (NH ₄) ₂ S, HCl (conc.).
Ammonium hydroxide, NH ₄ OH.			Antimonious hydroxide, Sb(OH) ₃ , white ppt. Sol. in excess.	Ammonium metantimonate, NH ₄ SbO ₃ . Very slightly sol. in excess.
Copper sulphate, CuSO ₄ .	Copper arsenite, CuHAsO ₈ , yel- lowish green ppt. Sol. in NH ₄ OH, NaOH, HNO ₈ .	Copper arsenate, Cu ₃ (AsO ₄) ₂ , greenish blue ppt Sol. in NH ₄ OH and in HNO ₃ .	Antimony oxy- chloride, white, SbOCl, caused by dilution. Insol. alk. Sol. HCl, CS ₂ .	Copper antimo- nate, brown ppt.
Mercuric chloride, HgCl ₂ .	Mercuric arse- nite,Hg ₈ (AsO ₁) ₂ , white ppt. Sol. in acids.		Antimony oxy- chloride, caused by dilution. Sol. in conc. HCl.	
Silver ni- trate, AgNO ₈ .	Silver arsenite, Ag,AsO ₃ , yellow ppt. Sol. in HNO ₃ , NH ₄ OH, HC ₂ H ₈ O ₂ .	Silver arsenate, Ag ₃ AsO ₄ , red- dish brown ppt. Sol. in HNO ₃ and NH ₄ OH.	Silver chloride and antimony trioxide, AgCl + Sb ₂ O ₃ , white ppts.	Silver antimo- nate. Ag ₂ SbO ₃ , white ppt. Sol. in NH ₄ OH.
Miscellany.	Magnesia mix- ture. No ppt. Arsenic sol. in HNO ₂ , Cl ₂ , H ₃ O, aq. reg., hot alkalies.	Magnesia mix- ture ppts. MgNH ₄ AsO ₄ , white crys. ppt. Sol. in acetic acid.	KOH ppts. Sb(OH)s. Na ₂ CO ₃ ppts. Sb(OH) ₈ .	Sb. sol. in hot conc. H ₂ SO ₄ and in aq. reg.
	Marsh test (Zn + HCl, etc.)	AsH ₃ flame deposits arsenic. Sol. in NaOCl. Sol. in (NH ₄) ₂ S. Residue insol. in HCl (conc.).	Marsh test (Zn+HCl).	SbH ₈ in flame deposits anti- mony. Insol. in NaOCI.

See Van Nostrand's Chemical Annual for solubility of saits.

REACTIONS OF THE BASES

Subgroup.

			· · · · · · · · · · · · · · · · · · ·
Tin, Sn	", Sa''".	PLATINUM, Pt'''.	Gold, Au ,
(ous) SnCl ₂ .	(ic) SnCl4.	PtCl ₄ ,	AuCla
Stannous sulphide, SnS, dark brown. Sol. in alkalies. Difficultly sol. in (NH ₄) ₂ S _x . Sol. in HCl (conc.). 100 c.c. H ₂ O diss. 0.002 mg.	Stannic sulphide, SnS_2 , yellow ppt. Sol. in alkalies, $(NH_4)_2S_x$, $(NH_4)_2S$ and alkali carbon- ates. HCl (conc.). $H_2O=0.02$ mg.	Platinic sulphide, PtS ₂ , dark brown ppt. Difficultly sol. in alkali sul- phides. Sol. in aqua regia. Insol. in HCl (conc.).	Gold sulphide, Au ₂ S ₁ , black ppt. Sol. in alkali sul- phides, aqua regia. Insol. in HCl (conc.).
Stannous hydroxide, SnO(OH) ₂ Insol. in excess. Darkens on cooling. Insol. in H ₂ O. Sol. in dilute acids, alk.	Stannic hydroxide, Sn(OH)4. Slightly sol. in excess.	Ammonium chlo- roplatinate, (N114) ₂ PtCl ₆ , yel- low ppt. Sol. in large excess. 679 ^{20,5} mg.	Fulminating gold, Au ₂ O ₈ . 2 NH ₈ , yellow ppt., Insol. in excess.
Cuprous chloride, 2 CuCl, white ppt. Sol. in acids. Reduction by SuCl ₂ .			
Mercurous chloride, HgCl, white ppt. Insol. in cold HCl (conc.). Reduction by SnCl ₂ .			
Silver chloride and silver, AgCl + Ag. Reduction by SnCl ₂ .	Silver chloride, AgCl.	Silver chloride and platinum oxide, AgCl + PtO, brown ppt.	Silver chloride and gold oxide. AgCl+Au ₂ O ₈ , brown ppt.
KOH ppts. Sn(OH) ₂ , Na ₂ CO ₁ ppts. Sn(OH) ₂ . Insol. in excess.	KOH ppts. Sn(OH) ₂ . NaCO ₃ ppts. Sn(OH) ₂ . Insol. in excess.	KOH ppts. K_PtCl ₈ . Na ₂ CO ₈ gives no ppt. Pt sol. in aq. r., fused alk.	SnCl ₂ solution ppts. "Purple of Cassius," eed ppt. Au sol. in KCN, aq. reg.
Metallic Sn deposited by Zn in Marsh test.	Stannic salts reduced by H, gen- erated by Sn.	Zn ppts. Pt, black, from its salts. Also see Electro- motive Series, p. 10.	Zn ppts. Au from its salts.

The Ammonium Sulphide Group.

	Агриний, А!	Сивомичи, Ст	IRON, Fe".	Fe
KRAGENT.	A4K,(SO4)4.	Cr,K,(SO,),	FERROUS, PeSO.	FERRIC, FeCla-
Ammouium sulphide, (NH ₄) _z S.	Aluminum hydroxide, Al(OH)s, white flocculent ppt. Sol. in acids. H ₂ S gas liberated.	Chromium hydroxide, Cr(OH)s, grayish green, ppt. H ₂ S liberated. Sol. in acids and alkalies.	Iron sulphide, FeS, black ppt. sol. in acids. Oxidizes in the air to FeSO, and finally to a brown basic ferric sulphate. 0.89 mg.	Iron sulphide, FeS(+S), black ppt. Sol. in acids. S remains undissolved.
Ammonium hvdroxide, NH4OH.	Aluminum hydroxide, Al(OH)s, white. Very slightly sol. in excess of reagent.	Chromium hydroxide, Cr(OH), grayish green. Slightly sol. in excess, forming a reddish solu- tion when cold and concentrated.	Ferrous hydroxide, white ppt becoming green, then reddish brown, in the air and in presence of NH ₄ Cl. Fe(OH) ₃ slowly forms. Sol. in NH ₄ Cl. 6.7 mgs.	Ferric hydroxide, Fc(OH)s, reddish brown ppt. Insol. in excess of reagent.
Ammonium carbonate, (NH ₄) ₂ CO ₃ .	Aluminum hydroxide, Al(OH)3, white ppt. CO ₂ gas.	Chromium hydroxide, Cr(OH)s, grayish green. Sol. in excess of reagent CO ₂ liberated.	Ferrous carbonate, FeCO ₃ , white ppt. sol. in excess. Slowly changed to hydroxide.	Basic salt changing to Fe(OH)s, reddish brown ppt.
Barium carbonate, BaCO ₃ .	Aluminum hydroxide, Al(OH)s, white.	Basic salt, CO ₂ , liberated, and Cr(OH) ₃ formed.	Iron not pptd. in ferrous form by BaCOst	Same as above.
Borax bead, Na ₂ B ₄ O ₇ . 10 H ₂ O.		OF, yellowish green when hot changing to emerald- green, cold.	OF, yellow. RF, green.	OF, yellow. RF, green.
Hydrogen sulphide, H ₂ S.			In presence of sodium acetate, FeS pptd.	Ferr reduced to Ferwith liberation of free S. (Also reduced by SnCl ₂ .)

Potasslum ferricyanide, KaFe(CN)		(All Cr compounds of oxidized to compounds of chromic acid; c.g. 2 Na ₂ CO ₃ + 3 KNO ₃ + 2 Cr(OH) ₃ = 2 Na ₂ CrO ₄ + etc.)	Ferrous ferricyanide (Tumbull's blue), Fes(FeCaNo), dark blue ppt. Insol. in HCl. De- composed by NaOH to Fe(OH);.	Reddish brown color produced.
Potassium ferrocyanide, K ₄ Fe(CN)•	White ppt. forms slowly.		Potassium ferrous ferrocyanide. K ₂ Fe ₅ (FeC ₆ N ₈) ₂ , bluish white, oxidized in air to blue.	Ferric ferrocyanide, Fe ₄ (FeC ₆ N ₆), (Prussian blue). dark blue. Insol. in mineral acid. NaOH forms Fe(OH) ₂ +.
Sodium hydroxide, NaOH.	* Aluminum hydroxide, Al(OH)3, white. Sol. in exes. forming Navs. Alowing Repptd. by NH ₄ Cl.	*Chromium hydroxide, Cr(OH)*, greenish ppt. Sol. in excess, forming green solution, NaCrO., Repptd. by boiling or by addition of NH,Cl.	* Ferrous hydroxide. Fe(OH)s, white becoming Fe(OH)s, Insol, in excess. Non-volatile organic substance prevents pption.	Ferric hydroxide, Fe(OH)s, reddish brown ppt. Insol. in excess. Sol. in mineral acids.
Sodium phosphate, Na ₂ HPO ₄ .	AlPO, white. Sol. in NaOH. Insol. in HC,H4O2.	CrFO ₄ , green ppt. Sol. in mineral acids and in NaOH.	Fe ₈ (PO ₄) ₂ , white ppt. becoming blue in the air.	FePO ₄ , yellowish white, scl. in excess. Insol. in HC ₂ H ₃ O ₂ .
Miscellany.	Sodium acetate in excess boiled with Al salt ppts. basic Al(OH); (C ₂ H ₃ O ₂) in nettral solutions.	NaC ₂ H ₃ O ₂ forms no ppt. unless Fe and Al are present, in which case Cr partially pptd. by boiling.	KCNS, no color. KCN ppts. Fe(CN), brown. Sol. in excess.	KCNS = red Fe(SCN) ₃ . Boiling with NaC,H ₄ O ₂ in neutral solutions a red brown ppt. formed of Fe(OH) ₂ (C ₂ H ₂ O ₂).
	* Presence of non-volatile org	* Presence of non-volatile organic substances, tartrates, citrates, and sugar prevents predpitation.	ates, and sugar prevents pred	pitation.

The Ammonium Sulphide Group — Continued

REAGENT.	COBALT, CoCl.	NICKEL, NICI,	MANGANESE, MESO4.	ZINC, ZnSO.
(NH ₄) ₂ S.	Cobalt sulphide, CoS, black ppt. Insol. in HC ₂ H ₃ O ₂ . Very slightly sol. in HCl. Sol. in aqua regia and warm HNO ₃ .	Nickel sulphide, Man NiS, black ppt. Slightly MnS and in excess, forming a Sol. in excess, forming a Sol. in solution. Very Oxightly sol. in HCl. Sol. in aqua regia. 0.36 mg.	Manganese sulphide, MnS, buff-colored ppt. Sol. in HCl, HC,H,Ot. Oxidizes in the air. o.6 mg.	Zinc sulphide, ZnS, white ppt. Insol. in HC2HsO2. Sol. in HCI. Presence of NH ₄ Cl aids pption.
.но'ни	Blue basic salt, sol. in excess, forming red solution. No ppt. formed in presence of NH ₄ Cl. Solution becomes red.	Nickel hydroxide, Ni(OH), green ppt. Sol. in excess, forming a blue solution. No ppt. formed in presence of NH,Cl.	Manganese hydroxide, Mn(OH) ₂ , white ppt. turning brown. In presence of NH,Cl a dark brown ppt. slowly forms by oxidation, Mn(OH) ₃ .	Zinc hydroxide, Zn(OH)s, white ppt. Sol. in excess, ZnSol(NH3)s, formed. In presence of NH4Cl no ppt. forms.
(NH ₄) ₅ CO ₅ .	Basic carbonate, red. illac, or pink ppt. Sol. in excess, forming red solu- tion, becoming brown by air oxidation.	Basic carbonate of variable compositions, green ppt. Sol. in excess.	Manganese carbonate, MnCO ₃ , white ppt. Sol. in excess. Bolling aids pption.	Basic zinc carbonate, usually Zn ₂ (OH) ₂ CO ₂ , white ppt. Sol. in excess. (Acid carbonate ppts. ZnCO ₃ white.)
BaC O 3.	No ppt. in cold.	No ppt. in cold.	No ppt. in cold.	No pption. in cold. (Na ₂ CO ₃ ppts. above aided by boiling.)
Borax bead.	Blue	Violet, hot. Yellowish brown, cold.	OF, violet-red, hot. Amethyst-red, cold. RF, colorless.	
H,S.	From neutral or alkaline solutions, CoS, black. No ppt. in acid solutions.	From neutral or alkaline solutions, NiS. No ppt. in acid solutions.	MnS forms slowly from alkaline solutions. No ppt. in acid solutions.	From neutral or alkaline solutions, or in solutions acidified with HC ₂ H ₃ O ₃ , ZnS is pptd.

	REACT	TIONS OF T	THE BASES		641
Zinc ferricyanide, Zn ₃ (FeC ₆ N ₄) ₂ , yellowish brown ppt. Sol. in HCl and in NH ₄ OH.	Zinc ferrocyanide. ZnzFe(CN) _{er} white ppt. Insol. in dilute acids and in NH4OH.	Zinc hydroxide, Zn(OH), white ppt. Sol. in excess, forming NasZnO ₂ . Repptd. by boiling.	Zn ₃ (PO ₄) ₃ , white ppt. Sol. in excess and in dil. acids and in NH ₄ OH.	KCN ppts. Zn(CN), white. Sol. in excess. From this solution (NH4), S ppts. ZnS, white.	
Manganese ferricyanide, Mn:(FeCeNe)s, brown ppt. Insol. in HCl.	Manganese ferrocyanide, Mnrfe(CN), faint red ppt. Diff. sol. in HCI. Easily sol. in H ₂ SO ₄ , HNO ₃ .	Manganese hydroxide, Mn(OH) ₂ , white ppt. turning brown. Insol. in excess. Sol. in NH ₄ CI.	Mn;(PO ₁), white ppt. Sol. in NH,OH, mineral acids, and HC;H;O ₂ . Boiled with NH,OH + NH,CI = MnNH,PO ₄ , rose colored.	PbO ₂ + HNO ₃ + Mn salt warmed = red HMnO ₄ . Na ₄ CO ₃ + KNO ₃ , fused on Pt = green, Na ₂ MnO ₄ .	For solubility of salts, see tables in D. Van Nostrand's Chemical Annual, edited by Olsen.
Nickel ferricyanide Ni ₁ (FeC ₆ N ₆) _{5, yellowish green ppt. Insol. in HCl.}	Nickel ferrocyanide, Ni ₂ Fe(CN)s. light green ppt. Insol. in HCl.	Nickel hydroxide, Ni(OH), apple green ppt. Insol. in excess. Sol. in Hc,H-0, HCl. NH4OH. Oxidized by Br to Ni (OH),	Ni,(PO,);, green ppt. Sol. in NH,OH. Sol. in dil. acids.	HCN ppts. greenish yellow, Ni(CN);. Sol in. excess. Repptd. by HCl. Pptd. by Br + NaOH as Ni(OH)s, black + CNBr (poison gas).	re tables in D. Van Nostrand's C
Cobalt ferricyanide, Co.(FeCeNs), dark brown ppt. Insol. in HCI.	Cobalt ferrocyanide, Cost e(CN)e, green ppt. becoming greenish blue. Insol. in HCI. Sol. in KCN.	Basic salt, blue. Boiled with excess = red. Insol. in excess. Sol. in HC;H;O ₂ , HCi, NH ₂ OH.	Co.(PO ₄), blue ppt. Sol. in NH ₄ OH. Sol. in dil. acids. Sol. in H ₄ PO ₄ .	HCN ppts. reddish brown. Co(CN) ₂ - Sol. in excess. Addition of Br+NaOH = K.Co(CN) ₈ - Co not pptd. •(Ni is pptd.)	For solubility of salts, se
K ₆ Fe(CN) ₆ .	K,Fe (CN)6.	NaOH.	Na _t HPO ₄ .	Miscellany.	

The Ammonium Carbonate Group

And Allinonium Carbonate Croup Solubility in miligrams per 100 c.c. of water cold, "c", and hot, "h",

REAGENT.	BARIUM, BaCL.	CALCIUM, CACL	STRONTIUM, STCl.	SOLUBLE IN PRESENCE OF NHA
Ammonium carbonate, (NH ₄) ₂ CO ₅ .	Barium carbonate, BaCO ₃ , white ppt. Sol. in acids. Slightly sol. in NH ₂ Cl. Precipitation aided by excess of NH ₂ OH and by boiling. "c" 2.2 mg.; "h" 6.5 mg.	Calcium carbonate. CaCO ₃ , Strontium white ppt. Sol. in acids. SrCO ₃ , wh Slightly sol. in NH ₄ Cl. acids. S Rendered less sol. by boil. NH ₄ Cl. ing with NH ₄ OH. "c" 1.3 sol. by mg.; "h" 88 mg. eess of NH mg.	white ppt. Sol. in acids. Sightly sol. in NH,Cl. Slightly sol. in NH,Cl. Sightly sol. in NH,Cl. Slightly sol. in NH,Cl. Slightly sol. in NH,Cl. Slightly sol. in NH,Cl. Slightly sol. in NH,Cl. Rendered less. ppt. formed if NH, salts cess of NH,OH and by ing with NH,OH. "c" 1.3 sol. by boiling "c" 2.2 mg.; "h" 88 mg. mg.	Basic magnesium carbon- ate MgCO ₄ + Mg(OH) ₄ , wnite ppt. on warming. No ppt. formed if NH ₄ salts are present. But if absent, solubility only 10.6 mgs.
Ammonium hydroxide, NH ₄ OH.				Magnesium hydroxide, Mg(OH) ₂ , Sol. in NH ₄ Cl.
Ammonium oxalate, (NH ₄);C ₂ O ₄ .	Barium oxalate, BaC ₂ O ₄ , white ppt. Sol. in HCl. Slightly sol. in HC ₂ H ₄ O ₂ and water. "c" 93; "h" 22.8.	Calcium oxalate, CaC ₂ O ₁ , white ppt. Sol. in HCl. Almost insol. in HC ₂ H ₃ O ₂ or in H ₂ C ₂ O ₄ . "c" o.68 mg.; ⁴ h" 1.4 mg.	Barium oxalate, BaC ₂ O ₄ , Calcium oxalate, CaC ₂ O ₄ Strontium oxalate, SrC ₂ O ₄ , white ppt. Sol. in HCl. white ppt. Sol. in HCl. Slightly sol. in HC ₂ H ₃ O ₂ Almost insol. in HC ₂ H ₃ O ₂ Slightly sol. in HC ₂ H ₃ O ₃ and water. "c" 9.3; "h" or in H ₂ C ₂ O ₄ . "c" o.68 and water. "c" 5.1 mg. 22.8.	
Ammonium sul- phate, (NH4), SO4, or sulphuric acid, H ₂ SO ₄ .	Barium sulphate, BaSO, white ppt. Insol. in H ₂ O and in acids. "c" 0.17 mg.; "h" 0.3 mg.	Barium sulphate, BaSO ₄ , Calcium sulphate, white pt. Insol. in H ₂ O pt. Somewhat sol. in white ppt. Silghtly sol. and in acids. "c" 0.17 H ₂ O. Sol. in (NH ₄) ₂ SO ₄ , in H ₂ O and in (NH ₄) ₂ SO ₄ , in (Strontium sulphate, SrSO ₄ , white ppt. Slightly solin H ₂ O and in (NH ₄) ₂ SO ₄ . "c". 11.4 mg.; "h" 10.4 mg.	·
Potassium chromate, K ₂ CrO ₄ .	Barium chromate, BaCrO, yellow ppt. Insol. in HC ₂ H ₃ O ₂ in presence of K ₂ CrO ₄ . Sol. in HCl, HNO. "c" o.38 mg.; "h" 43 mg.			

	REACTIONS O	F THE	BASES	643
Maguesium hyd rozide, Mg(OH),, white ppt. Sol. in NH,Cl.	Magnesium hydrogen phosphate, MgHPOto white ppt. Boiled Mg.(POto): In presence of NH,CI and NH,OH a white crystalline ppt. of MgNH,PO, slowly forms. Sol. in acetic acid.	White.	:	No ppt. by H,SiF. Boiled with Na ₂ CO ₂ = white Mg ₁ (OH) ₁ (CO ₂) ₂ . No ppt. if NH ₄ Cl present.
Strontium hydroxide, Sr(OH)s, white ppt. Slightly sol. in water; c. 410 mg.; "h" very soluble.	Strontium hydrogen phosphate. SrHPO ₄ , white ppt. Sol. in acids. See BaHPO ₄ . Insol. in H ₂ O.	Crimson.	Several orange and red lines. Brilliant blue line.	No ppt. by H ₂ SiF ₆ .
Calcium hydroxide, Strontium hydroxide, Ca(OH)s, white ppt. Sr(OH)s, white ppt. Slightly sol. in water; Sol. in NH ₄ Cl. "c" 410 mg.; "h" 80 mg. soluble.	Calcium hydrogen phosphate, Carl POt, white ppt. "c" = 28 mg. Sol. in acids. In presence of NH4OH, Cas(POt); pptd. "c" 3 mg. to 8 mg.	Yellowish red.	Sharp orange line α and Several orange and red bluish line β .	No ppt. by H ₂ SiF ₆ .
Barlum hydroxide, Ba(OH), while ppt. formed only in conc. solu- tions. "c" 5560 mg.; "h" very soluble.	Barium hydrogen: phosphare, BaHPO,, white ppt. 19 acids. If NH,OH present, BaNH,PO, formed.	Yellowish green.	Green α and β bands. Fainter yellow and red bands.	H.SiF, ppts. BaSiF, Insol. in alcohol and dilute acids. "c" 26 mg.: "h" 90 mg.
Sodium hydrox- ide, NaOH.	Sodium phos- phate, Na ₂ HPO.	Flame.	Spectra.	Miscellany.

REACTIONS OF THE BASES

The Soluble Metal Group.

KEAGENT.	ARMORIUM, NH,CI.	LTHUM, LICE.	Potassium, KCl.	Sodium, NaCl.
Hydrofluosilicic acid, H ₂ SiF ₆ .			Potassium fluosilicate, K.SiF ₆ . Transparent ppt. Slightly sol. in water. " c = 120 mg.; "h" 955 mg.	Sodium fluosilicate, Na ₂ SiF _g , white ppt. Somewhat sol. in water. "c" = 650 mg.; "h" 2460 mg.
Nessler's reagents, Hg1 ₄ (K1) ₂ . KOH.	Reddish brown or yellow, according to amount of ammonia. Test very delicate.			
Platinic chloride, PtCl., H ₂ PtCl _g .	Ammonium chloro- platinate, (NH ₄) ₂ PtCl ₁ , yellow ppt. Slightly sol. in water. Insol. in alcohol. "c" 670.0 mg. Very sol. in hot water.		Potassium chloroplatinate, K ₂ PtCl ₆ , yellow ppt. Slightly sol. in water. Insol. in atcohol or ether. "c", 480 mg.; "h" 5180 mg.	
Potassium pyroantimonate, H ₂ K ₂ Sb ₂ O ₇ .				Sodium pyroantimonate, Na ₂ H ₂ Sb ₂ O ₇ , white cryst. ppt. Best formed in slightly alkaline solutions. NaSbO ₃ + aqua. "c" = 31 mg.
Sodium carbonate, Na ₂ CO ₃ .	Ammonia gas evolved on boiling.	Lithium carbonate, Li ₂ CO ₃ , white ppt. Slightly sol. in water. Less sol. in hot than in cold. "c" = 1539 mg.; "h" 728 mg.		

	REACTION	S OF THE	BASES	6
No ppt. in acetic acid solutions of sodium salts.		·		Yellow flame. Single yellow line.
Forassum coont intrue, KaCo(NO ₂), yellow, or KaNaCo(NO ₂), yellow, or Go an excess of sodium. Insol. in acetic acid. Sol. in inorganic acids. Hastened by warming. Solution should have acetic acid present.	•		Monopotassium tartrate, KHC,H40g, white cryst. ppt. Hastened by stirring. Somewhat sol. in H2O. "c" 370 mg.	Violet flame. A red and blue line.
		Lithium phosphate, Li,PO,, white ppt. Slightly sol. in water. Sol. in HCl. "c" = 40 mg.		Red flame. Bright crimson line with feeble orange line.
In acetic acid solutions (see Na), Co(NO),3+3 NH ₄ NO, yellow ppt. Sol. in inorganic acids.	Ammonia gas evolved when salt is warmed with NaOH or KOH.		Monoammonium tarrate. NH,HC,H,O,, white cryst. pp. Haste cred by shaking. Slightly sol. in H ₂ O.	
Sodium cobaltic nitrite, Co(NO ₂)s-	Sodium or potassium hydrox- ide, NaOH or KOH.	Sodium phosphate, Na ₄ HPO ₄ .	Tartaric acid, HrC4H4Os.	Flame and spectrum.

REACTIONS OF THE ACIDS. Inorganic Acids.

ACEDS:	Selver Nitrate. Agno _p	BARIUM CHLORIDE, BeCl.	CALCIUM CHLORIDE, CACL	Lead Acetals, Pb(C,H,O,);	CHARACTERISTIC REACTIONS.
Arsenic, H,AsO ₄ , arsenates.	Reddish brown ppt., Ag,AsO ₄ . Sol. in NH,OH, HNO ₃ .	White ppt., Ba ₃ (AsO ₄) ₂ . Sol. Ca ₄ (AsO ₄) ₂ . in acids.		Lead acetate ppts. white salt. Insol. in acetic acid. Sol. in HNOs.	(NHJ),MoO, produces a yellow ppt. MgSO, + NH,Cl + NH,OH = white ppt.
Arsenious, HaAsOs, arsenites.	Yellow ppt., Agasoj. Sol. in NH,OH, HNOs.	White ppt., Ba ₃ (AsO ₄) ₃ . Sol. in acids.	White ppt. Sol. Leadacetate ppts.) in C ₂ H ₄ O ₂ . white arsenious salt. Sol. in acetic acid, HNO ₃ .	Lead acetate ppts.) white arsenious salt. Sol. in acetic acid, HNOs.	Marsh's test with both forms—ous and ic—gives arsenic mirror. Sol. in NaOCl. H ₂ S produces yellow As ₂ S ₃ and As ₂ S ₃ . Gutzeit test.
Boric, H ₁ BO ₁ , (H ₂ B ₂ O ₇), borates.	White ppt. Sol. in NH,OH, HNOs.	Sol. White ppt. Not readily sol. in water. Sol. in acids.	White ppt. Sol. White ppt. Caused in acids. by lead acetate. Sol. in excess.	White ppt. Caused by lead acetate. Sol. in excess.	H,SO4 + C2H,OH colors flame green. Turmeric paper dipped in boric acid salt acidified with HCl, dried, turns red.
Carbonic, H ₂ CO ₃ , carbonates.	Grayish white ppt., AgrCO ₃ . Sol. in HNO ₃ . 3.1 ¹²⁵ mg.	White ppt., BacO ₃ . Sol. in acids. 2 2 mg.	White ppt CaCO ₁ . Sol. in acids. 2.2 mg.	Lead acetate ppts. white lead. Sol. in HNOs.	Effervesces with dilute inorganic acids, HCl, H ₂ SO ₄ , HNO ₃ , etc., CO ₃ gas being evolved. Limewater clouded by CO ₃ , CaCO ₃ being formed.

Chloric, HClO, chlorates.			H ₂ SO ₄ , conc. warmed with salt causes explosion.	Heated on charcoal deflagrates. H ₂ SO ₄ evolves yellow gas, ClO ₂ .
Chromic, H ₂ CrO ₄ , chromates.	Dark red ppt., Ag.SrOt. Sol. in HNOs. 2.818° mg.	Yellow ppt. BaCrO ₄ . Sol. in HCl. HNO ₃ . lnsol. in acetic acid. 0.38 mg.	Pb(C,H,O ₂), ppts. yellow PbCrO ₄ . Sol. in NaOH. o.o.2 ^{68°} mg.	Pb(C ₂ H ₂ O ₂) ₂ ppts. Reduced to green CrCl ₁ by warm-yellow PbCrO ₄ . Solin NaOH.
Hydroiodic, HI, iodides.	Yellow ppt., Agl.: Very difficultly sol. in NH ₀ OH.		Soluble lead salt ppts. Pbl _x yellow. Sol. in hot water. 39,000 mg.	Liberated from its salts by HNO, or Cl water. Imparts in free form violet color to CS, blue to starch.
Hydrobromic, HBr, bromides.	Light yellow ppt., AgBr. Difficultly sol. in NH,OH.		Pb(C ₂ H ₃ O ₂) ₂ ppts. PbBr ₂ , white. Sol. in hot water. 455 mg.	Liberated from its salts by Cl, colors CS ₂ reddish yellow.

REACTIONS OF INORGANIC ACIDS.

	CHARACTERISTIC REACTIONS,	K ₂ Cr ₂ O ₇ + H ₂ SO ₄ , (conc.), gives CrO ₂ Cl ₂ . MnO ₃ + H ₂ SO ₄ gives Cl gas. KMnO ₄ + HCl evolves Cl.	Warmed with NaOH+FeSO ₄ +FeCl ₈ and acidi- fied with HCl, "Prussian Blue" formed. Warmed with (NH ₄) ₂ S _x =NH ₄ CNS, which pro- duces a blood-red color with FeCl ₈ .	On warming, PbO ₂ Dark blue, Turnbull's blue, is pptd.	Prussian Blue with FeCl ₃ (Fe). Red ppt. with copper salts (Cu).	White ppt., CaF., white salt. Sol. in HCl. Insol. white salt. Sol. in HCl. Insol. HNOs. 1.6 mg.
	Pb(C ₂ H ₃ O ₂) ₂ .	PbCl ₂ , white, is pptd. Sol. in hot water. Insol. in alcohol. 673 mg.	White ppt. with sol. Pb salt, Pb(CN);. Sol. in HNO3.	On warming, PbO ₂ is pptd.	White ppt. Sol. in HNOs.	Pb(C ₂ H ₃ O ₂), ppts. white salt. Sol. in HNO ₃ .
Inorganic Acids.	cacl _s .					White ppt, CaF ₂ . Sol. in HCl. Insol. in actic acid. 1.6 mg.
	BaCl.	"				White ppt., BaF ₂ Sol. in HCl. 163 ¹³ mg.
	AgN@3.	White ppt., AgCl. Insol. in HNOs. Sol. in NH,OH. KCN. 0.152 mg.	White ppt., AgCN. Sol. in NH,OH, KCN. 0.021 mg.	Orange ppt., AgsFeCys. Sol. in NH,OH, KCN. Insol. in HNOs.	White ppt. Sol. in KCN. Insol. in HNOs.	
	Acros.	Hydrochloric, HCl, chlorides.	Hydrocyanic, HCN, cyanides.	Hydroferri- cyanic, HaFe(CN), ferricyanides.	Hydroferro- cyanic, H,Fe(CN),	Hydrofluoric, HF, fluorides.

	*ILEACTIONS	or inor	GANIU ACI	DS 6
Decomposed by H ₂ SO ₄ into HF and SiF ₄ . Ppts. K in concentrated solution, as K ₂ SiF ₆ , white.	Most sulphides decomposed by strong inorganic acids, with odor of rotten eggs (see AgNO ₃ and Pb(NO ₃), tests). Colors sodium nitro prussiate, violet.	Cl evolved when salt is treated with HCl and many other acids. Ppts. MnO ₂ black from solution of MnSO ₄ .	With acetic acid and KI, free iodine formed. CS ₂ colored violet. Starch colored blue.	Coagulates albumen. Boiled with HNO ₂ =H ₂ PO ₄ .
	Black ppt., PbS. Sol. in hot HNO ₃ . o.1 mg.	White ppt., becomes brown on boiling.	White ppt. Sol. in HNO3.	White ppt. Sol. in HNO3.
				White ppt. Sol. in dil. acids.
White ppt., BaSiF ₆ . Insol. in HCl. 26 ¹⁷⁰ mg.		(White ppt., Ba(10 ₃) ₂ . Sol. in HCl. 8 mgs.	White ppt. Sol. in excess of meta- phosphate.
	Black ppt., Ag.S. Sol. in hot HNOs. o.o2 mg.	White ppt, AgClO. Sol. in HNO3-	White ppt., AglO ₃ . White ppt., Sol. in NH ₄ OH. Ba(1O ₃)z. Sol. Reduced by SO ₂ in HCl. 8 mgs. to Agl. 4.4 mg.	White ppt. Sol. in NH ₄ OH, HNO ₃ .
Hydroftuo- silicic, H ₂ SiF ₆ , ftuosilicates.	Hydrosul- phuric, H ₂ S, sulphides.	Hypochlorous, HCiO, hypochlorites.	lodic, HIOs, iodides.	Metaphos- phoric, HPOs, metaphos- phates.

Inorganic Acids.

REACTIONS OF INORGANIC ACIDS, ...

-			ا م		··
CHARACTERISTIC 'REACTIONS.	H ₂ SO ₄ (conc.) poured into a mixture of a nitrate salt with FeSO ₄ produces a brown ring at upper surface of heavier H ₂ SO ₄ .	With an iodide, when acidified with HCl, liberates iodine, which will color CS ₂ violet.	White ppt. with Pb (NH ₄) ₂ MoO ₄ + HNO ₂ ppts. at 40°, salt. Sol. in NaOH yellow phospho ammonium Insol. in NH ₄ OH. molybdate. Magnesia mixture Insol. in HC ₂ H ₄ O ₂ . produces a white ppt., MgNH ₄ PO ₄ . oco 4 mg.	Reducing action. Very concentrated solutions heated evolve PH ₃ .	Does not coagulate albumen as does the metaphospheric acid. Boiled with HNO ₂ changes to H ₂ PO ₄ .
Pb(C,H,O ₂),			White ppt. with Pb salt. Sol. in NaOH Insol. in NH ₄ OH. Insol. in HC ₂ H ₃ O ₂ .	White ppt. Insol. in HC ₂ H ₃ O ₂ . Sol. in HNO ₃ .	Pb salt same as Ca salt.
- ದಾರು			White ppt. Sol. in inorganic and in acetic acids.	White ppt. Sol. in NH ₄ Cl.	White ppt. Sol. in excess of the pyrophos-phate.
BeCl.			White ppt., Ba,(PO,), Sol. in acids.	White ppt. Sol. in acids, acetic acid.	White ppt. Sol. in HCI. 10 mg.
AgNÔ,		White ppt., AgNO ₂ . Sol. in hot water. 330 mg.	Yellow ppt., Ag-PO _t . Sol. in NH,OH and HNO _b . 1.93 mg.	White ppt. On warming, causes reduction of silver salt to Ag.	White ppt. Sol. in NH,OH, HNOs.
Actol.	Nitric, HNOs, nitrates.	Nitrous, HNO,, nitrites.	Phosphoric, HaPO, phosphates.	Phosphorus, H ₂ PO ₃ , phosphites.	Pyrophos- phoric, H.P.O., pyro- phosphates.

***************************************	TURNOTTO	MS OF IM	JAGANIC AC	JIDS .	00
Heated with Na ₂ CO ₃ , evolves CO ₂ . SiO ₂ skeleton with Na ₂ PO ₃ bead. Decomposes when evaporated to dryness, SiO ₂ separating.	FeCl, produces a blood-red color, which is destroyed by HgCl,.	Sulphates heated with Na ₂ CO ₂ on charcoal in reducing flame from Na ₂ S, which blacken a silver coin when it is moistened.	Reducing agent. Reduces KI (starch sol. test). Decolorizes KMnO, SO, evolved when salt is acidified with HCI.	Decomposed by HCl to SO ₂ + S. Na ₂ S ₂ O ₃ dissolves AgCl.	
White ppt. Insol. in HNO ₃ .	White ppt.	White ppt. Sol. in NaOH, NH,C ₂ H,O ₂ , (NH,);C ₄ H,O ₆	White ppt.	White ppt. On boiling becomes gray. PbSO ₄ + PbS.	
White ppt.		White ppt. Sol. in water and acids.	White ppt. Sol. in HCL		
White ppt.		White ppe BaSO4. Insol. in acids. 0.172 mg.		Conc. solution produces white ppt.	
Yellow ppt. Sol. in HNOs.	White ppt., AgCNS. Difficulty sol. in NH,OH.	Conc. AgNOs produces white ppt., Ag. SO4. Sol. in water. 580 mg.	White ppt., Ag. SO ₂ . White ppt. Decomposed by Sol. in HCl. Ag + Ag. SO ₄ + SO ₂ .	AgsStO ₁ , white ppt. Sol. in NasstO ₂ . Decomposed by boiling, forming H ₈ SO ₄ + AgsS.	
Silicic, H.SiO _B , silicates.	Sulphocyanic, HCNS, thiocyanates or sulpho	Sulphuric, H ₂ SO ₄ , sulphates.	Sulphurous, H ₅ SO,, sulphites.	Thiosulphuric, H ₂ S,O ₃ , thiosulphates.	

Organic Acids.

SP_CIAL Trets,	H_2SO_4 + alcohol = ethyl acetate, recognized by characteristic odor.	Pb(C ₂ H ₂ O ₂) ₂ ppts. white compound. m.p. 121°, sublimes when heated. H ₂ SO ₄ + C ₂ H ₅ OH heated = ethyl benzoate.	Bromine water, even in very dilute solutions, gives a white ppt. sol. in NaOH, KOH. CeH,50H + 1 c.c. H;SO ₄ + NaNO; warned = deep green or blue color.	White ppt. with lead acetate. Sol. in ammonium citrate. Prevents pption. of Fe(OH ₃ by alkalies. CdCl ₃ ppts. Cd(C ₆ H ₈ O ₇) ₂ . Insol. in hot water. Sol. in acetic acid. (Cd salts, no ppt. with tartrates.)	H ₂ SO ₄ (conc.) + ethyl alcohol= ethyl formate, pleasant char- acteristic odor.
Н ₂ SO ₄ Сомс.	Heated, gives odor of vinegar.	Dissolves without charring or evolution of gas.			With reducing agent heated, gives CO, which burns with blue flame.
FeCly	Reddish brown solution. Pots. on boiling of ferricacetate = Fe ₂ (OH) ₂ A ₄ . Sol. in HCl.	Buff-colored ppt. (CH ₅ COO)FeOH. Sol. in HCl.	Deep violet. Color destroyed by acetic acid (not destroyed in case of salicylic acid).		Red ppt. Color destroyed by HCl.
CaCl.				White ppt. Less sol. in hot than cold water. Sol. in NH ₄ Cl. Insol. in NaOH. Crystalline form insol. in NH ₄ Cl.	
Agno _b .	White ppt. Sol. in hot water.	White ppt. C ₄ H ₄ COOAg. Sol. in hot water.		White ppt. Sol. in NH,OH. No reduction on heating.	White ppt. in conc. solutions. Becomes dark from reduced silver salt.
Across	Acetic, H · C ₂ H ₃ O ₂ .	Benzoic, CeHcOOH.	Carbolic, C.H.OH.	Ciric, White ppt. Cs.4,04(COOH), in NH,OH. reduction on heating.	Formic, HCOOH.

ne solu- ter or ppt.	with	alt.	ives MnO, gent in	salt. oduces	e acid	of tion. of
The alkali Limewa	nO4 and kes place, iyde.	s. white s Prevents Ikalies.	MnO, g color of K n that rea H,SO,.	s. a white th salt pre	s a yellouste. The glue.	ed. Odor es. Silver
Melts at 200°. The alkaline solutions absorbs O. Limewater or Ba(OH), produces a blue ppt.	Decolorizes KMnO, and efferverscence takes place, with odor of acetaldehyde.	Lead acetate ppts. white salt. Sol. in hot water. Prevents pption. of Fe(OH), by alkalies.	H ₂ SO ₄ (dilute) + MnO ₂ gives CO ₂ . Destroys color of KMnO ₄ when heated with that reagent in presence of dilute H ₂ SO ₄ .	Lead acetate ppts. a white salt. Acid m.p. 156. HNO, heated with salt produces yellow picric acid. Color is intensified by caustic soda.	Lead acetate gives a yellow ppt., with astringent taste. The acid ppts. a solution of glue. Limewater produces a gray ppt.	Chars when heated. Odor of burnt sugar. Prevents pption. of Fe(OH), by alkalies. Silver. Nitrate test, page 104.
Melts tions a Ba(OF		Lead a Sol. in of Fe(H,SO, CO;. when h present	Lead a Acid m HNO ₃ yellow Color is	Lead a with as ppts. a water n	Chars burnt s Fe(OH) Nitrate
	Charring on heating with evolution of CO.		Heated. CO ₂ and CO evolved.	Dissolves. Pro- longed heating darkens solution and gas is evolved.		
Blue-black ppt. Sol. in excess == green.				Deep violet color. Destroyed by mineral acids.	Blue-black color (ink).	
		White ppt. only in presence of strong alcohol (distinction from citric).	White ppt. Insol. in acetic acid. Sol. in HCl, HNO ₃ .			White crystalline ppt. Action similar to magnesium precipitation.
Metallic Ag from reduction.	Reduction results. Ag formed (no action on Fehling's sol.).	White ppt.	White ppt. Sol. in HNO,, NH,OH.	White ppt. Sol. in hot water, CeH4OHCOOAg.	White ppt.	White ppt. Sol. in excess of tartrate, HCl, NH,OH! Reduction on hearing
Gallic, Metallic / C4H(OH)COOH. reduction.	Lactic, Carentooon.	Malic, C ₂ H ₃ OH(COOH) ₂ .	Ozalic, H ₂ · C ₂ O ₄ .	Salicylic, Сыңонссон.	Tannic, C14H10Op.	Tartaric. H ₂ ·C ₄ H ₄ O ₆ .

SOLUBILITY TABLE

Since no salt is absolutely insoluble, the term "insoluble" is only relative. For solubility of the salts formed, see Van Nostrand's Chemical Annual, edited by Professor John C. Olsen.

																	. —			
CATION.	Ť.	ά	Br'	Ι'	CN,	NO,	CIO ₃ ′	C2H3O2	S''	,,eOO	SiO3"	"tos	CrO*"	BOs''' BOs'	PO4""	AsO4""	AsO ₃ ""	Fe(CN)6"	Fe(CN),""	,,o;
K.	w	w	,,,	w	w	w	w	w	w	w	w	w	w	w	w	w	w	w	w	w
Na.	W	W	W W	W	W	W	W	w	W	W	W	w	w	w	w	w	w	w	w	w
	W	W	w W	w	W	W	W	w	w	w	W	w	w	w	w	w	w	w	w	w
Li'		W	W	w	wA		W	w	W	A	A	ĭ	A	A	A	A	A	I	wA	_
Ba"	wa			w	WA	W	W	w	W	A	A	I	wA	A	A	Α	A	_	w	
Sr"	wa	W	W	W	W	W	W	w	W	A	A	wa	wA	A	A	A	A	w	w	_
Ca"	wa	W	W	w	W	W	W	wA	w	A	A	W	W	wA	A	A	A	w	w	
Mg.	wa W	w w	W	W	W	W	W	W	W	v		W	**	A	A	A	_			
Al	١.,		W	W	_	W	W	wA	_ A	A	wa A	W	w	A	A	A	Α	I	A	
Mn"	A	W	W	W	A	W	W	WA	A	A	A	W	w	A	A	A	_	Â	wa	
Zn··	wA		W	W	A	W	w	wA	A	V	A	W	A	A	A	A	_	<u></u>		
Cr	W	W	W	w	A	W	W	WA	A	A	A	W	w	wA	A	_			_	
Cd	wA	W	W	W	1	ı	w	W				W		A	A	A	A	_ I	I	
Fe"	wA		W	W	wa	W	W	ı	A	A	A	W	w	A	A	A	A	w	I	
Fe"	WA	W	W	-	_	W	w W	A W	_	_	A	W	A	A	A	A	A	ï	i	\Box'
Con	, -		W	W	wa	W	W	ł	A	A	A	W	A	A	A	A	A	ī	1	
Ni	wA		W	W	wa	W		W	1	A	A			A	A	^	Λ	I	Ī	
Sn"	W	W	_	W	-	W	W	A	A			W	A	A	A	A	A	٠,	I	
Sn	W	W	_	W W	-	[w		A		7	ī	I	— А	A	A	A	wA	A	
Pb	A	W	W	1	A	W		W	A	A	A	W	w		A	A	A	WA.	I	
Cu	A	W	W	I.	I	W	W	W	A	A	_	1		A	A	A	А	_	1	_
Sb	W	A	A	wA	-	-	-	A	A	-	-	A	A	_	A	A	_		_	-
Bi	W	A	A	A		A	W	A	A	A	A	A	A	A		l	_	-	_	-
Hg.	-	I	I	I	-	W	W	Ą	-	A	-	wA	A	_	A	A	A	-	_	-
Hg"	wA	1	W	A	W	W	W	A	A	A	1	W	wA	_	A	A	A	A	ı	
Ag.	W	I	I	I	I	W	W	A	A	A	A	wA	A	A	A	A		A	ı	
Pt	-	W	W	111	W	W	-	-	A		-	W	-	-	_		A		_	
Au.	-	W	W	A	W	1-	1	-	A	-	-	-	-	-	_		_	-		-

ABBREVIATIONS. — W = soluble in water; A = soluble in acids; wA = slightly soluble in water, readily soluble in acids; wa = difficultly soluble in water and in acids; 1 = insoluble in water and acids.

The metals are arranged in order of their electromotive series.

VOL. I

PART III FACTORS, ACID AND ALKALI TABLES AND OTHER USEFUL DATA



I.-MELTING-POINTS OF THE CHEMICAL ELEMENTS 1

Reproduced from Circular No. 35 (2d edition) of U. S. Bureau of Standards.

otanuarus.					
Element.	C.	F.	Element.	C.	F.
Helium	<-271	< -456	Neodymium	840?	1544
Hydrogen	-259	-434	Arsenic	850?	1562
Neon	-253?	-423	Barium	850	1562
Fluorine	-223	-369	Praseodymiur	n 940?	1724
Oxygen	-218	-360	Germanium	958	1756
Nitrogen	-210	-346	SILVER	960.5	1761
Argon	-188	-306	GOLD	1063.0	1945.5
Krypton	-169	-272	COPPER	1083.0	1981.5
Xenon	-140	-220	Manganeso	1260	2300
Chlorine	-101.5	-150.7	Samarium	1300-1400	2370-2550
Mercury	- 38.9	-38.0	Beryllium		
Bromine	- 7.3	+18.9	(glueinum)	1350?	2462
Caesium	+ 26	79	Scandium	?	
Gallium	30	86	Silicon	1420	2588
Rubidium	38	100	NICKEL	1452	2646
Phosphorus	44	111.2	Cobalt	1480	2696
Potassium	62.3	144	Yttrium	1490	2714
Sodium	97.5	207.5	Chromium	1520	2768
Iodine	113.5	236.3	Iron	1530	2786
	(8, 112.8	235.0	1'ALLADIUM	1549	2820
Sulphur	$\{S_{11}, 119.2\}$	246.6	Zirconium	1700?	3090
	Sm 106.8	224.2	Columbium		
Indium	155	311	(Niobium)	1700?	3090
Lithium	186	367	Thorium	(>1700	>3090
Selenium	217-220	422-428	1 nonum	\ <pt< td=""><td><pt< td=""></pt<></td></pt<>	<pt< td=""></pt<>
TIN	231.9	449.4	Vanadium	1720	3128
Bismuth	271	520	· PLATINUM	1755	3191
Thallium	302	576	Ytterbium	?	
CADMIUM	320.9	609.6	Titanium	1800	3272
LEAD	327.4	621.3	Uranium	<1850	<3362
ZINC	419.4	786.9	Rhodium	1950	3542
Tellurium	452	846	Boron	2200-2500? 4	1000-4500
ANTIMONY	630.0	1166	Iridium	2350?	4262
Cerium	640	1184	Ruthenium	2450?	4442
Magnesium	651	1204	Molybdenum	2500?	4500
ALUMINUM	658.7	1217.7	Osmium	2700?	4900
Radium	700	1292	Tantalum	2850	5160
Calcium	810	1490	TUNGSTEN	3000	5430
Lanthanum	810?	1490	Carbon	>3600 {	>6500
Strontium	>Ca <ba?< td=""><td></td><td>1 Carbon</td><td>$\{for p. = 1 at. \}$</td><td>for $p. = 1$ at.</td></ba?<>		1 Carbon	$\{for p. = 1 at. \}$	for $p. = 1$ at.

II. OTHER TEMPERATURE STANDARDS

Temperatures of Flames.	
	Cent. Deg. of Accuracy.
Bunsen, open	1100 Within 100° C.3
Meker	1500 ¹
Petrol blow lamp	1600 ¹
Oxyhydrogen with H ₂ +0	2420 Within 100° C.
Oxyacetylene	
Thermat	2500
Electric arc	
Sun	6000 Within 500° C.
1 Metallurgical and Chemical Engineering, Vol. XIII	. No. 5. May. 1915.
* Measurement of High Temperatures, G. K. Burgess	and H. Le Chatelier
Pyrometer tests of the open Bunsen flame gave ten	
to 1100° C.	whereas a resource man and
W 1100 C.	

III. OTHER TEMPERATURE STANDARDS

Approximate Temperatures by Colors.	Cent.	Fahr.
d	525	977
	700	1292

	Cent.	PADI.
First visible red.	525	977
Dull red	700	1292
Cherry red		1652
Dull orange	1100	2012
White	1300	2372
Dazzling white	1500	2732
Dazzing witte	1900	2132

Substance.	Phenomenon.	c.	F.	Variation with pressure (pressure in mm. of Hg.)
Oxygen	Boiling	-183.0	-297.4	C. °-183.0+0.01258 (p. 760) -0.0000079 (p. 760)
Carbon dioxide	Sublimation in inert liquid	- 78.5	-109.3	C. $\circ = -78.5 + 0.017$ (p. 760)
Sodium sulphate		32.384	90.291	
$Na_2SO_4+10H_2$				
Water		100	212	C. °-100+0.03670 (p. 760) -0.00002046 (p. 760)
Naphthalene	Boiling	217.96	423.73	C. $^{\circ}=217.96+0.058$ (p. 760)
Benzophenono		305.9	582.6	C. °-305.9+0.063 (p. 760)
Sulphur		444.6		C. °=444.6+0.0908 (p. 760) -0.000047 (p. 760)
Ag ₂ Cu ₂	Eutectic Freezing	779	1434	(p. 100)
Sodium ehloride.	Freezing	801	1472	

IV.—ELECTROMOTIVE ARRANGEMENT OF THE ELEMENTS

Each element is positive to the element placed after it and negative to the element placed above.

1. Cs	14. Al	27. Ge	40. Os	53. Mo
2. Rb	15. Zr	28. In	41. Au	54. V
3. K	16. Th	29. Ga	42. H	55. Cr
4. Na	17. Ce	30. Bi	43. Sn	56, As
5. Li	18. Di	31. U	44. Si	57. P
6. Ba	19. La	32. Cu	45. Ti	58. Se
7. Sr	20. Mn	33. Ag	46. Cb	59. 1
8. Ca	21. Zn	34. Hg	47. Ta	60. Br
9. Mg	22. Fe	35. Pd	48. Te	61. Cl
10. Be	23. Ni	36. Ru	49. Sb	62. F
11. Yt	24. Co	37. Rh	50. C	63. N
12. Er	25. Cd	38. Pt	51. Bo	64. 8
13. Sc	26. Pb	39. Ir	52. W	65. O

ACID AND ALKALI TABLES

V.-HYDROCHLORIC ACID

BY W. C. FERGUSON

Degrees Baumo.	Sp. Gr.	Degrees Twadaeil.	Per Cent HCl.	Degrees Baumé.	Sp. Gr.	Degrees Twiddell.	Per Cent HCl.
1.00	1.0069	1.38	1.40	14.25	1.1090	21.80	21.68
2.00	1.0140	2.80	2.82	14.50	1.1111	22.22	22.09
3.00	1.0211	4.22	4.25	14.75	1.1132	22.64	22.50
4.00	1.0284	5.68	5.69	15.00	1.1154	23.08	22.92
5.00	1.0357	7.14	7.15	15.25	1.1176	23.52	23.33
5.25	1.0375	7.50	7.52	15.50	1.1197	23.94	23.75
5.50	1.0394	7.88	7.89	15.75	1.1219	24.38	24.16
5.75	1.0413	8.26	8.26	16.0	1.1240	24.80	24.57
6.00	1.0432	8.64	8.64	10.1	1.1248	24.90	24.73
6.25	1.0450	9.00	9.02	16.2	1.1256	25.12	24.90
6.50	1.0469	9.38	9.40	16.3	1.1265	25.30	25.06
6.75	1.0488	9.76	9.78	16.4	1.1274	25.48	25.23
7.00	1.0507	10.14	10.17	16.5	1.1283	25.66	25.39
7.25	1.0520	10.52	10.55	16.6	1.1292	25.84	25.56
7.50	1.0545	10.90	10.94	16.7	1.1301	26.02	25.72
7.75	1.0564	11.28	11.32	16.8	1.1310	26.20	25.89
8.00	1.0584	11.68	11.71	16.9	1.1319	26.38	26.05
8.25	1.0603	12.06	12.09	17.0	1.1328	26.56	26.22
8.50	1.0623	12.46	12.48	17.1	1.1336	26.72	26.39
8.75	1.0642	12.84	12.87	17.2	1.1345	20.90	26.56
9.00	1.0662	13.24	13.26	17.3	1.1354	27.08	26.73
9.25	1.0081	13.62	13.65	17.4	1.1363	27.26	26.90
9.50	1.0701	14.02	14.04	17.5	1.1372	27.44	27.07
9.75	1.0721	14.42	14.43	17.6	1.1381	27.62	27.24
10.CO	1.0741	14.82	14.83	17.7	1.1390	27.80	27.41
10.25	1.0761	15.22	15.22	17.8	1.1399	27.98	27.58
10.50	1.0781	15.62	15.02	17.9	1.1408	28.16	27.75
10.75	1.0801	10.02	16.01	18.0	1.1417	28.34	27.92
11.00	1.0821	16.42	16.41	18.1	1.1426	28.52	28.09
11.25	1.0841	10.82	16.81	18.2	1.1435	28.70	28.26
11.50	1.0861	17.22	17.21	18.3	1.1444	28.88	28.44
11.75	1.0881	17.62	17.61	18.4	1.1453	29.06	28.61
12.00	1.0902	18.04	18.01	18.5	1.1462	29.24	28.78
12.25	1.0922	18.44	18.41	18.0	1.1471	29.42	28.95
12.50	1.0943	18.86	18.82	18.7	1.1480	29.60	29.13
12.75	1.0964	19.28	19.22	18.8	1.1489	29.78	29.30
13.00	1.0985	19.70	19.63	18.9	1.1498	29.96	29.48
13.25	1.1006	20.12	20.04	19.0	1.1508	30.16	29.65
13.50	1.1027	20.54	20.45	19.1	1.1517	30.34	29.83
13.75	1.1048	20.96	20.86	19.2	1.1526	30.52	30.00
14.00	1.1069	21.38	21.27	19.3	1.1535	30.70	30.18

V.—HYDROCHLORIC ACID (Continued)

Degrece Baumé.	Sp. Gr.	Degrees Twaddell.	Per Cent HCl.	Degrees Baumé.	Sp. Gr.	Degrees Twaddell.	Per Cent HC1.
19.4	1.1544	30.88	30.35	22.5	1.1836	36.72	36.16
19.5	1.1554	31.08	30.53	22.6	1.1846	36.92	36.35
19.6	1.1563	31.26	30.71	22.7	1.1856	37.12	36.54
19.7	1.1572	31.44	30.90	22.8	1.1866	37.32	36.73
19.8	1.1581	31.62	31.08	22.9	1.1875	37.50	36.93
19.9	1.1590	31.80	31.27	23.0	1.1885	37.70	37.14
20.0	1.1600	32.00	31.45	23.1	1.1895	37.90	37.36
20.1	1.1609	32.18	31.64	23.2	1.1904	38.08	37.58
20.2	1.1619	32.38	31.82	23.3	1.1914	38.28	37.80
20.3	1.1628	32.56	32.01	23.4	1.1924	38.48	38.03
20.4	1.1637	32.74	32.19	23.5	1.1934	38.68	38.26
20.5	1.1647	32.94	32.38	23.6	1.1944	38.88	38.49
20.6	1.1656	33.12	32.56	23.7	1.1953	39.06	38.72
20.7	1.1666	33.32	32.75	23.8	1.1963	39.26	38.95
20.8	1.1675	33.50	32.93	23.9	1.1973	39.46	39.18
20.9	1.1684	33.68	33.12	24.0	1.1983	39.66	39.41
21.0	1.1694	33.88	33.31	24.1	1.1993	39.86	39.64
. 21.1	1.1703	34.06	33.50	24.2	1.2003	40.06	39.86
21.2	1.1713	34.26	33.69	24.3	1.2013	40.26	40.09
21.3	1.1722	34.44	33.88	24.4	1.2023	40.46	40.32
21.4	1.1732	34.64	34.07	24.5	1.2033	40.66	40.55
21.5	1.1741	34.82	34.26	24.6	1.2043	40.86	40.78
21.6	1.1751	35.02	34.45	24.7	1.2053	41.06	41.01
21.7	1.1760	35.20	34.64	24.8	1.2063	41.26	41.24
21.8	1.1770	35.40	34.83	24.9	1.2073	41.46	41.48
21.9	1.1779	35.58	35.02	25.0	1.2083	41.66	41.72
22.0	1.1789	35.78	35.21	25.1	1.2093	41.86	41.99
22.1	1.1798	35.96	35.40	25.2	1.2103	42.06	42.30
22.2	1.1808	36.16	35.59	25.3	1.2114	42.28	42.64
22.3	1.1817	36.34	35.78	25.4	1.2124	42.48	43.01
22.4	1.1827	36.54	35.97	25.5	1.2134	42.68	43.40

Sp. Gr. determinations were made at 60° F., compared with water at 60° F. From the Specific Gravities, the corresponding degrees Baumé were calculated by the following formula: Baumé = 145 - 145/Sp. Gr.

Atomic weights from F. W. Clarke's table of 1901. O = 16.

ALLOWANCE FOR TEMPERATURE:

10-15° Bé. - 1/40° Bé. or .0002 Sp. Gr. for 1° F. 15-22° Bé. - 1/30° Bé. or .0003 " " " 1° F. 22-25° Bé. - 1/28° Bé. or .00035 " " " 1° F.

AUTHORITY - W. C. FERGUSON.

This table has been approved and adopted as a Standard by the Manufacturing Chemists' Association of the United States.

W. H. BOWER, JAS. L. MORGAN, ARTHUR WYMAN, HENRY HOWARD, A. G. ROSENGARTEN,

New York, May 14, 1903.

Executive Committee

VI.—HYDROCHLORIC ACID

LUNGE AND MARCHLEWSKI

Specific Gravity, 15° in Vacuo.	Per Cent HC1 by Weight.	r Liter con- tains Grams HCl.	Specific Gravity 15° 4° in Vacuo.	Per Cent HCl by Weight.	z Liter con- talns Grams HCl.	Specific Gravity 15° 4° In Vacuo.	Per Cent HCl by Weight.	I Liter con- tains Grams HCl.
1.000	0.16	1.6	1.075	15.16	163	1.145	28.61	328
1.005	1.15	12	1.080	16.15	174	1.150	29.57	340
1.010	2.14	22	1.085	17.13	186	1.152	29.95	345
1.015	3.12	32	1.090	18.11	197	1.155	30.55	353
1.020	4.13	42	1.095	19.06	209	1.160	31.52	366
1.025	5.15	53	1.100	20.01	220	1.163	32.10	373
1.030	6.15	64	1.105	20.97	232	1.165	32.49	379
1.035	7.15	7.1	1.110	21.92	243	1.170	33.46	392
1.040	8.16	85	1.115	22.86	255	1.171	33.65	394
1.045	9.16	96	1.120	23.82	267	1.175	34.42	404
1.050	10.17	107	1.125	24.78	278	1.180	35.39	418
1.055	11.18	118	1.130	25.75	291	1.185	36.31	430
1.060	12.19	129	1.135	26.70	303	1.190	37.23	443
1.065	13.19	141	1.140	27.66	315	1.195	38.16	456
1.070	14.17	152	1.1425	28.14	322	1.200	39.11	469

COMPOSITION OF CONSTANT BOILING HYDROCHLORIC ACID*

Pressure mm. of Mercury.	Per Cent of HCl.	Grams constant boiling distillate for 1 mol. HCl,
770	20.218	180.390
760	20.242	180.170
750	20.266	179.960
740	20.290	179.745
730	20.314	179.530

Temperature of constant boiling hydrochloric acid is 108.54° at 763 mm. Specific gravity 1.09620¹⁶.

^{*} Hulett and Bonner, Jour. Am. Chem. Soc. xxxi, 390.

VII.—NITRIC ACID By W. C. Ferguson

=====							
Degrees Baumė.	8p. Gr. 60° F.	Degrees Twaddell.	Per Cent HNO,.	Degrees Baumė.	8p. Gr. 60° F.	Degrees Twaddell,	Per Cent HNO.
10.00	1.0741	14.82	12.86	21.25	1.1718	34.36	28.02
10.25	1.0761	15.22	13.18	21.50	1.1741	34.82	28.36
10.50	1.0781	15.62	13.49	21.75	1.1765	35.30	28.72
10.75	1.0801	16.02	13.81	22.00	1.1789	35.78	29.07
11.00	1.0821	16.42	14.13	22.25	1.1813	36.26	29.43
11.25	1.0841	16.82	14.44	22.50	1.1837	36.74	29.78
11.50	1.0861	17.22	14.76	22.75	1.1861	37.22	30.14
11.75	1.0881	17.62	15.07	23.00	1.1885	37.70	30.49
12.00	1.0902	18.04	15.41	23.25	1.1910	38.20	30.86
12.25	1.0922	18.44	15.72	23.50	1.1934	38.68	31.21
12.50	1.0943	18.86	16.05	23.75	1.1959	39.18	31.58
12.75	1.0964	19.28	16.39	24.00	1.1983	39.66	31.94
13.00	1.0985	19.70	16.72	24.25	1.2008	40.16	32.31
13.25	1.1006	20.12	17.05	24.50	1.2033	40.66	32.68
13.50	1.1027	20.54	17.38	24.75	1.2058	41.16	33.05
13.75	1.1048	20.96	17.71	25.00	1.2083	41.66	33.42
14.00	1.1069	21.38	18.04	25.25	1.2109	42.18	33.80
14.25	1.1090	21.80	18.37	25.50	1.2134	42.68	34.17
14.50	1.1111	22.22	18.70	25.75	1.2160	43.20	34.56
14.75	1.1132	22.61	19.02	26.00	1.2185	43.70	34.94
15.00	1.1154	23.08	19.36	26.25	1.2211	44.22	35.33
15.25	1.1176	23.52	19.70	26.50	1.2236	44.72	35.70
15.50	1.1197	23.94	20.02	26.75	1.2262	45.24	36.09
15.75	1.1219	24.38	20.36	27.00	1.2288	45.76	36.48
16.00	1.1240	21.80	20.69	27.25	1.2314	46.28	36.87
16.25	1.1262	25.24	21.03	27.50	1.2310	46.80	37.26
16.50	1.1284	25.68	21.36	27.75	1.2367	47.34	37.67
16.75	1.1306	26.12	21.70	28.00	1.2393	47.86	38.06
17.00	1.1328	26.56	22.04	28.25	1.2420	48.40	38.46
17.25	1.1350	27.00	22.38	28.50	1.2446	48.92	38.85
17.50	1.1373	27.46	22.74	28.75	1.2473	49.46	39.25
17.75	1.1395	27.90	23.08	29.00	1.2500	50.00	39.66
18.00	1.1417	28.34	23.42	29.25	1.2527	50.54	40.06
18.25	1.1440	28.80	23.77	29.50	1.2554	51.08	40.47
18.50	1.1462	29.24	24.11	29.75	1.2582	51.64	40.89
18.75	1.1485	29.70	24.47	30.00	1.2609	52.18	41.30
19.00	1.1405	30.16	24.82	30.25	1.2637	52.74	41.72
19.25	1.1531	30.62	25.18	30.50	1.2664	53.28	42.14
		31.08	25.53	30.75	1.2692	53.84	42.58
19.50	1.1554	31.54	25.88	31.00	1.2719	54.38	43.00
19.75	1.1577	_	26.24	31.25	1.2747	54.94	43.44
20.00	1.160	32.00	26.61	31.50	1.2775	55.50	43.49
20.25	1.1624	32.48	26.96	31.75	1.2804	56.08	44.34
20.50	1.1647	32.94	27.33	32.00	1.2832	56.64	44.78
20.75	1.1671	33.42		32.25	1.2861	57.22	
21.00	1.1694	33.88	27.67	32.40	1.2801	01.22	45.24

VII.-NITRIC ACID (Continued)

	8p. Gr.			,	Sp. Gr.		
Degrees Baumé.	60° F.	Degrees Twaddell.	Per Cent HNO ₃ .	Degrees Baumé.	50° P.	Degrees Twaddell.	Per Cent HNO.
32.50	1.2889	57.78	45.68	40.75	1.3909	78.18	63.48
32.75	1.2918	58.36	46.14	41.00	1.3942	78.84	64.20
33.00	1.2946	58.92	46.58	41.25	1.3976	79.52	64.93
33.25	1.2975	59.50	47.04	41.50	1.4010	80.20	65.67
33.50	1.3004	60.08	47.49	41.75	1.4044	80.88	66.42
33.75	1.3034	60.68	47.95	42.00	1.4078	81.56	67.18
34.00	1.3063	61.26	48.42	+42.25	1.4112	82.24	67.95
34.25	1.3093	61.86	48.90	42.50	1.4146	82.92	68.73
34.50	1.3122	62.44	49.35	42.75	1.4181	83.62	69.52
34.75	1.3152	63.04	49.83	43.00	1.4216	84.32	70.33
35.00	1.3182	63.64	50.32	43.25	1.4251	85.02	71.15
35.25	1.3212	64.24	50.81	43.50	1.4286	85.72	71.98
35.50	1.3242	64.84	51.30	43.75	1.4321	86.42	72.82
35.75	1.3273	65.46	51.80	44.00	1.4356	87.12	73.67
36.00	1.3303	66.06	52.30	44.25	1.4392	87.84	74.53
36.25	1.3334	66.68	52.81	44.50	1.4428	88.56	75.40
36.50	1.3364	67.28	53.32	44.75	1.4464	89.28	76.28
36.75	1.3395	67.90	53.84	45.00	1.4500	90.00	77.17
37.00	1.3426	68.52	54.36	45.25	1.4536	90.72	78.07
37.25	1.3457	69.14	54.89	45.50	1.4573	91.46	79.03
37.50	1.3488	69.76	55.43	45.75	1.4610	92.20	80.04
37.75	1.3520	70.40	55.97	46.00	1.4646	92.92	81.08
38.00	1.3551	71.02	56.52	46.25	1.4684	93.68	82.18
38.25	1.3583	71.66	57.08	46.50	1.4721	94.42	83.33
38.50	1.3615	72.30	57.65	46.75	1.4758	95.16	84.48
38.75	1.3647	72.94	58.23	47.00	1.4796	95.92	85.70
39.00	1.3679	73.58	58.82	47.25	1.4834	96.68	86.98
89.25	1.3712	74.24	59.43	47.50	1.4872	97.44	88.32
39.50	1.3744	74.88	60.06	47.75	1.4910	98.20	89.76
39.75	1.3777	75.54	60.71	48.00	1.4948	98.96	91.35
40.00	1.3810	76.20	61.38	48.25	1.4987	99.74	93.13
40.25	1.3843	76.86	62.07	48.50	1.5026	100.52	95.11
40.50	1.3876	77.52	62.77			1	

Specific Gravity determinations were made at 60° F., compared with water at 60° F.
From the Specific Gravities, the corresponding degrees Baumé were calculated by the following formula:

Baumá=145_145_...

following formula: $Baum = 145 - \frac{145}{8p. Gr.} .$ Baum = Hydrometers for use with this table must be graduated by the above formula, which formula should always be printed on the scale. A tomic weights from F. W. Ciarke's table of 1901. <math>O = 16.

ALLOWANCE FOR TEMPERATURE:

At 10° - 20° B6. - 1/30° B6. or .00028 Sp. Gr. = 1° F.
20° - 30° B6. - 1/22° B6. or .00044 " " = 1° F.
30° - 40° B6. - 1/20° B6. or .00080 " " = 1° F.
40° - 48.5° B6. - 1/17° B6. or .00084 " " = 1° F.

AUTHORITY - W. C. FERGUSON.

This table has been approved and adopted as a Standard by the Manufacturing Chemists' Association of the United States.

W. H. BOWER, JAS. L. MORGAN,
HENRY HOWARD, ARTHUR WYMAN,
A. G. ROSENGARTEN, Executive Committee New York, May 14, 1903.

TABLES AND USEFUL DATA

VIII.—NITRIC ACID

LUNGE AND REY

Specific Gravity 15°	100 parts by weight contain		z liter con- tains grams		Specific Gravity	100 parts by weight contain		z liter con- tains grams	
in vacuo	₩,O,	HNO,	N ₂ O ₂	HNO,	15° 4° in vacuo	% N,O,	HNO,	N _s O _s	HNO ₃
1.000	0.08	0.10	1	1	1.195	27.10	31.62	324	378
1.005	0.85	1.00	8	10	1.200	27.74	32.36	333	388
1.010	1.62	1.90	16	19	1.205	28.36	33.09	342	399
1.015	2.39	2.80	24	28	1.210	28.99	33.82	351	409
1.020	3.17	3.70	33	38	1.215	29.61	34.55	360	420
1.025	3.94	4.60	40	47	1.220	30.24	35.28	369	430
1.030	4.71	5.50	49	57	1.225	30.88	36.03	378	441
1.035	5.47	6.38	57	66	1.230	31.53	36.78	387	452
1.040	6.22	7.26	64	75	1.235	32.17	37.53	397	463
1.045	6.97	8.13	73	85	1.240	32.82	38.29	407	475
1.050	7.71	8.99	81	94	1.245	33.47	39.05	417	486
1.055	8.43	9.84	89	104	1.250	34.13	39.82	427	498
1.060	9.15	10.68	97	113	1.255	34.78	40.58	437	509
1.065	9.87	11.51	105	123	1.260	35.44	41.34	447	521
1.070	10.57	12.33	113	132	1.265	36.09	42.10	457	533
1.075	11.27	13.15	121	141	1.270	36.75	42.87	467	544
1.080	11.96	13.95	129	151	1.275	37.41	43.64	477	556
1.085	12.64	14.74	137	160	1.280	38.07	44.41	487	568
1.090	13.31	15.53	145	169	1.285	38.73	45.18	498	581
1.095	13.99	16.32	153	179	1.290	39.39	45.95	508	593
1.100	14.67	17.11	161	188	1.295	40.05	46.72	519	605
1.105	15.34	17.89	170	198	1.300	40.71	47.49	529	617
1.110	16.00	18.67	177	207	1.305	41.37	48.26	540	630
1.115	16.67	19.45	186	217	1.310	42.06	49.07	551	643
1.120	17.34	20.23	195	227	1.315	42.76	49.89	562	656
1.125	18.00	21.00	202	236	1.320	43.47	50.71	573	669
1.130	18.66	21.77	211	246	1.325	44.17	51.53	585	683
1.135	19.32	22.54	219	256	1.330	44.89	52.37	597	697
1.140	19.98	23.31	228	266	1.3325	45.26	52.80	603	704
1.145	20.64	24.08	237	276	1.335	45.62	53.22	609	710
1.150	21.29	24.84	245	286	1.340	46.35	54.07	621	725
1.155	21.94	25.60	254	296	1.345	47.08	54.93	633	739
1.160	22.60	26.36	262	306	1.350	47.82	55.79	645	753
1.165	23.25	27.12	271	316	1.355	48.57	56.66	658	768
1.170	23.90	27.88	279	326	1.360	49.35	57.57	671	783
1.175	24.54	28.63	288	336	1.365	50.13	58.48	684	798
1.180	25.18	29.38	297	347	1.370	50.91	59.39	698	814
1.185	25.83	30.13	306	357	1.375	51.69	60.30	711	829
1.190	26.47	30.88	315	367	1.380	52.52	61.27	725	846

VIII.—NITRIC ACID (Continued)

Specific Gravity 15°	100 parts by weight contain		r liter con- tains grams		Specific Gravity 150	100 parts hy weight contain		ı liter con- tains grams	
in vacuo	% N ₂ O ₅	HNO ₃	N,O5	HNO,	150 4° in vacuo	% N ₁ O ₅	HNO ₃	N ₁ O ₃	HNO,
1.3833	53.08	61.92	735	857	1.495	78.52	91.60	1174	1369
1.385	53.35	62.24	739	862	1.500	80.65	94.09	1210	
1.390	54.20	63.23	753	879 896	1.501	81.09	94.60	1217	1420
1.395	55.07 55.97	64.25 65.30	768 783	914	1.502	81.50 81.91	95.08 95.55	$\frac{1224}{1231}$	1428 1436
1.405	56.92	68.40	800	933	1.504	82.29	96.00	1238	1430
1.410	57.86	67.50	816	952	1.505	82.63	96.39	1244	1451
1.415	58.83	68.63	832	971	1.506	82.94	96.76	1249	1457
1.420	59.83	69.80	849	991	1.507	83.26	97.13	1255	1464
1.425	60.84	70.98	867	1011	1.508	83.58	97.50	1260	1470
1.430	61.86	72.17	885	1032		83.87	97.84	1265	
1.435	62.91	73.39	903	1053		84.09	98.10	1270	1481
1.440	64.01	74.68	921	1075	1.511	84.28	98.32	1274	1486
1.445	65.13	75.98	941	1098	1.512	84.46	98.53	1277	1490
1.450	66.24	77.28	961	1121	1.513	84.63	98.73	1280	1494
1.455	67.38	78.60	981	1144	1.514	84.78	98.90	1283	1497
1.460	68.56	79.98	1001	1168		84.92	99.07	1287	1501
1.465	69.79	81.42	1023			85.04	99.21	1289	1504
1.470	71.06	82.90	1045	1219	1.517	85.15	99.34	1292	1507
1.475	72.39	84.45	1068	1246		85.26	99.46	1294	1510
1.480	73.76	86.05	1092	1274	1.519	85.35	99.57	1296	1512
1.485	75.18	87.70	1116	1302	1.520	85.44	99.67	1299	1515
1.490	76.80	89.60	1144	1335					

IX.-PHOSPHORIC ACID AT. 17.5°

Specific Gravity.	Per Cent. P ₂ O ₅ .	Per Cent. H ₃ PO ₄ .	Specific Gravity.	Per Cent. P ₁ O ₁ .	Per Cent. H ₃ PO ₄ .	Specific Gravity.	Per Cent. P ₂ O ₂ .	Per Cent.
1.809	68.0	93.67	1.462	46.0	63.37	1.208	24.0	33.06
1.800	67.5	92.99	1.455	45.5	62.68	1.203	23.5	32.37
1.792	67.0	92.30	1.448	45.0	61.99	1.198	23.0	31.68
1.783	66.5	91.61	1.441	44.5	61.30	1.193	22.5	30.99
1.775	66.0	90.92	1.435	44.0	60.61	1.188	22.0	30.31
1.766	65.5	90.23	1.428	43.5	59.92	1.183	21.5	29.62
1.758	65.0	89.54	1.422	43.0	59.23	1.178	21.0	28.93
1.750	64.5	88.85	1.415	42.5	58.55	1.174	20.5	28.24
1.741	64.0	88.16	1.409	42.0	57.86	1.169	20.0	27.55
1.733	63.5	87.48	1.402	41.5	57.17	1.164	19.5	26.86
1.725	63.0	86.79	1.396	41.0	56.48	1.159	19.0	26.17
1.717	62.5	86.10	1.389	40.5	55.79	1.155	18.5	25.48
1.709	62.0	85.41	1.383	40.0	55.10	1.150	18.0	24.80
1.701	61.5	84.72	1.377	39.5	54.41	1.145	17.5	24.11
1.693	61.0	84.03	1.371	39.0	53.72	1.140	17.0	23.42
1.685	60.5	83.34	1.365	38.5	53.04	1.135	16.5	22.73
1.677	60.0	82.65	1.359	38.0	52.35	1.130	16.0	22.04
1.669	59.5	81.97	1.354	37.5	51.66	1.126	15.5	21.35
1.661	59.0	81.28	1.348	37.0	50.97	1.122	15.0	20.66
1.653	58.5	80.59	1.342	36.5	50.28	1.118	14.5	19.97
1.645	58.0	79.90	1.336	36.0	49.59	1.113	14.0	19.28
1.637	57.5	79.21	1.330	35.5	48.90	1.109	13.5	18.60
1.629	57.0	78.52	1.325	35.0	48.21	1.104	13.0	17.91
1.621	56.5	77.83	1.319	34.5	47.52	1.100	12.5	17.22
1.613	56.0	77.14	1.314	34.0	46.84	1.096	12.0	16.53
1.605	55.5	76.45	1.308	33.5	46.15	1.091	11.5	15.84
1.597	55.0	75.77	1.303	33.0	45.46	1.087	11.0	15.15
1.589	54.5	75.08	1.298	32.5	44.77	1.083	10.5	14.46
1.581	54.0	74.39	1.292	32.0	44.08	1.079	10.0	13.77
1.574	53.5	73.70	1.287	31.5	43.39	1.074	9.5	13.09
1.566	53.0	73.01	1.281	31.0	42.70	1.070	9.0	12.40 11.71
1.559	52.5	72.32	1.276	30.5	42.01	1.066	8.5	
1.551	52.0	71.63	1.271	30.0	41.33	1.062	8.0	11.02
1.543	51.5	70.94	1.265	29.5	40.64	1.058	7.5	10.33
1.536	51.0	70.26	1.260	29.0	39.95	1.053	7.0 6.5	9.64 8.95
1.528	50.5	69.57	1.255	28.5	39.26 38.57	1.049		8. 26
1.521	50.0	68.88	1.249	28.0	1	1.045	6.0	7.57
1.513	49.5	68.19	1.244	27.5 27.0	37.88 37.19	1.041	5.5 5.0	36.89°
1.505	49.0	67.50	1.239	26.5	36.50	1.037	4.5	6.20
1.498 1.491	48.5	66.81	1.233	26.0	35.82	1.029	4.0	5.51
1.484	48.0	66.12	1.228	25.5	35.13	1.025	3.5	4.82
	47.5	65.43 64.75	1.218	25.0	34.44	1.023	3.0	4.13
1 · 476 1 · 469	47.0 46.5	64.75	1.218	24.5	33.75	1.021	2.5	3.44
4.408	10.0	U1.00	1.210	47.0	30.10	1.017	2.0	0.78

X.-SULPHURIC ACID

By W. C. FERGUSON AND H. P. TALBOT

Degrees Baumó.	Specific Gravity 60° F.	Degrees Twaddell.	Per Cent H ₂ SO ₄ .	Weight of t Cu. Ft. in Lbs. Av.	Per Cent O. V.*	Pounds O. V. 112 2 Cubic Poot.
0	1.0000	0.0	0.00	62.37	0.00	0.00
1	1.0069	1.4	1.02	62.80	1.09	0.68
2	1.0140	2.8	2.08	63.24	2.23	1.41
3	1.0211	4.2	3.13	63.69	3.36	2.14
. 4	1.0284	5.7	4.21	64.14	4.52	2.90
- 5	1.0357	7.1	5.28	64.60	5.67	3.66
6	1.0432	8.6	6.37	65.06	6.84	4.45
7	1.0507	10.1	7.45	65.53	7.99	5.24
8	1.0584	11.7	8.55	66.01	9.17	6.06
9	1.0662	13.2	9.66	66.50	10.37	6.89
10	1.0741	14.8	10.77	66.99	11.56	7.74
11	1.0821	16.4	11.89	67.49	12.76	8.61
12	1.0902	18.0	13.01	68.00	13. 96	9.49
13	1.0985	19.7	14.13	68.51	15.16	10.39
14	1.1069	21.4	15.25	69.04	16.36	11.30
15	1.1154	23.1	16.38	69.57	17.58	12.23
16	1.1240	24.8	17.53	70.10	18.81	13.19
17	1.1328	26.6	18.71	70.65	20.08	14.18
18	1.1417	28.3	19.89	71.21	21.34	15.20
19	1.1508	30.2	21.07	71.78	22.61	16.23
20	1.1600	32.0	22.25	72.35	23.87	17.27
21	1.1694	33.9	23.43	72.94	25.14	18.34
22	1.1789	35.8	24.61	73.53	26.41	19.42
23	1.1885	37.7	25.81	74.13	27.69	20.53
24	1.1983	39.7	27.03	74.74	29.00	21.68

Sp. Gr. determinations were made at 60° F., compared with water at 60° F. From the Sp. Grs., the corresponding degrees Baumé were calculated by the following formula: Baumé = 145-145/Sp. Gr.

Baumé Hydrometers for use with this table must be graduated by the

above formula, which formula should always be printed on the scale.

* 66° Baumé = Sp. Gr. 1.8354 = Oil of Vitriol (O. V.). 1 cu. ft. water at 60° F. weighs 62.37 lbs. av. Atomic weights from F. W. Clarke's table of 1901. O = 16. $H_2SO_4 = 100$ per cent.

% H,SO. % o. v. %60° 0. V. = 93.19100.00 = 119.9883.35 = 100.00 66.72 = 80.06 = 77.67 = $50^{\circ} = 62.18 =$

X.-SULPHURIC ACID (Continued)

Degrees Baumé.	* Freezing (Melting) Point.	APPRO	XIMATE	BO1LING	POINTS
]	F.		50° B.	295° F.	
			60° ''	386° "	
0	32.0		61° "	400° "	
1	31.2		62° "	415° "	
2	30.5		63° "	4320 "	
3	29.8		640 "	451° "	
4	28.9		65° "	485° "	
5	28.1		66° "	538° "	
6	27.2		FIXED	POINTS	
7	26.3		FIRM	1 0114119	
8	25.1				
9	24.0	Specific Gravity.	Per Cent	Specific Gravity.	Per Cent H ₁ SO ₄ .
10	22.8				-1
11	21.5	1.0000	.00	1.5281	62.34
12	20.0	1.0048	.71	1.5440	63.79
13	18.3	1.0347	5.14	1.5748	66.51
14	16.6	1.0649	9.48	1.6272	71.00
		1.0049	14.22	1.6679	74.46
15	14.7	1.1353	19.04	1.7044	77.54
16	12.6	1.1736	23.94	1.7258	79.40
17	10.2	1.2105	28.55	1.7472	79.40 81.32
18	7.7	1.2513	33.49	1.7700	83.47
19	4.8	1.2951	38.64	1.7959	86.36
20	+ 1.6	1.3441	44.15	1.7959	80.30 88.53
21	- 1.8	1.3947	49.52	1.8194	89.75
22	- 6.0	1.4307	53.17	1.8275	91.32
23	-11	1.4667	56.68	1.8354	93.19
23	-11 -16	1.4822	58.14	1.0004	vo.19
24	-10	1.4822	08.14		

Acids stronger than 66° B6, should have their percentage compositions determined by chemical analysis.

* Calculated from Pickering's results, Jour. of Lon. Ch. Soc., vol. 57, p. 363.

AUTHORITIES - W. C. FERGUSON; H. P. TALBOT.

This table has been approved and adopted as a standard by the Manufacturing Chemists' Association of the United States.

W. H. BOWER,
HENRY HOWARD,
JAS. L. MORGAN,
ARTHUR WYMAN,
A. G. ROSENGARTEN,
Executive Committee

New York, June 23, 1904.

X.—SULPHURIC ACID (Continued)

Degrees Banmé.	Specific Gravity 60° F.	Degrees Twaddell.	Per Cent H ₃ SO ₄ .	Weight of t Cu. Ft. in Lbs. Av.	Per Cent O. V.	Ponnds O. V. in cubic Foot.
25	1.2083	41.7	28.28	75.33	30.34	22.87
26	1.2185	43.7	29.53	76.00	31.69	24.08
27	1.2288	45.8	30.79	76.64	33.04	25.32
28	1.2393	47.9	32.05	77.30	34.39	26.58
29	1.2500	50.0	33.33	77.96	35.76	27.88
30	1.2609	52.2	34.63	78.64	37.16	29.22
31	1.2719	54.4	35.93	79.33	38.55	30.58
32	1.2832	56.6	37.26	80.03	39.98	32.00
33	1.2946	58.9	38.58	80.74	41.40	33.42
34	1.3063	61.3	39.92	81.47	42.83	34.90
35	1.3182	63.6	41.27	82.22	44.28	36.41
36	1.3303	66.1	42.63	82.97	45.74	37.95
37	1.3426	68.5	43.99	83.74	47.20	39.53
38	1.3551	71.0	45.35	84.52	48.66	41.13
39	1.3679	73.6	46.72	85.32	50.13	42.77
40	1.3810	76.2	48.10	86.13	51.61	44.45
41	1.3942	78.8	49.47	86.96	53.08	46.16
42	1.4078	81.6	50.87	87.80	54.58	47.92
43	1.4216	84.3	52.26	88.67	56.07	49.72
44	1.4356	87.1	53.66	89.54	57.58	51.56
45	1.4500	90.0	55.07	90.44	59. 0 9	53.44
46	1.4646	92.9	56.48	91.35	60.60	55.36
47	1.4796	95.9	57.90	92.28	62.13	57.33
48	1.4948	99.0	59.32	• 93.23	63.65	59.34
49	1.5104	102.1	60.75	94.20	65.18	61.40
50	1.5263	105.3	62.18	95.20	66.72	63.52
51	1.5426	108.5	63.66	96.21	68.31	65.72
52	1.5591	111.8	65.13	97.24	69.89	67.96
53	1.5761	115.2	66.63	98.30	71.50	70.28
54	1.5934	118.7	68.13	99.38	73.11	72.66
55 '	1.6111	122.2	69.65	100.48	74.74	75.10
56	1.6292	125.8	71.17	101.61	76.37	77.60
57	1.6477	129.5	72.75	102.77	78.07	80.23
58	1.6667	133.3	74.36	103.95	79.79	82.95
59	1.6860	137.2	75.99	105.16	81.54	85.75

X.—SULPHURIC ACID (Continued)

Dogrees Baumé.	* Freezing (Melting) Point. °F.	4.7	LOWLNCE	EOD mes	IDIN A MUND	
25	-23	AL	LOWANCE	FOR TEN	IPERATURE	
26	-23 -30	4	D			_
27	-30 -39	At 10°	Bé029° Be		$3 \operatorname{Sp. Gr.} = 1^{\circ} \operatorname{F}$	•
28	- 39 - 49	20	.000	.0003		
29	-49 -61	00	.030	.0003		
~~	-01	" 40° " 50°	.001	.0004		
30	-74	" 60°	.020	.0004	<i>→</i> = 1···	
31	-82	" 63°	" .026° " .026°	.0000	·) = 1 · · ·	
32	-96	" 66°	" .0235°	.บบบอ	, = 1 · · ·	
33	-97	ω.	.0200	.0005	4 " = 10"	•
34	-91					
35	-81					
36	-7 0		1	×		_
37	-60	Per Cent	Pounds 60° Baumé	Per Cent	Pounds 50° Baumé	
38	-53	60° Baumé,	in	50° Baumė.	in (
39	-47		t Cubic Foot.		1 Cubic Foot.	
40	-41	61.93	53.34	77.36	66.63	
41	-35	63.69	55.39	79.56	69.19	
42	-31	65.50	57.50	81.81	71.83	
43	-27	67.28	59.66	84.05	74.53	
44	-23	69.09	61.86	86.30	77.27	
45	-20	70.90	64.12	88.56	80.10	
46	-14	72.72	66.43	90.83	82.98	
47	-15	74.55	68.79	93.12	85.93	
48	-18	76.37	71.20	95.40	88.94	
49	-22	78.22	73.68	97.70	92.03	
50	-27	80.06	76.21	100.00	95.20	
51	-33	81.96	78.85	102.38	98.50	
52	-39	83.86	81.54	104.74	101.85	
53	-49	85.79	84.33	107.15	105.33	
54	-59	87.72	87.17	109.57	108.89	
55	}	89.67	90.10	112.01	112.55	
56	3	91.63	93.11	114.46	116.30	
57	Below	93.67	96.26	117.00	120.24	
58	·_]#	95.74	99.52	119.59	124.31	
59	- 7'	97.84	102.89	122.21	128.52	

X.—SULPHURIC ACID (Continued)

Degrees Baumé.	Specific Gravity 60° F.	Degrees Twaddell.	Per Cent H ₂ SO ₆ ,	Weight of 1 Cu. Ft. in Lbs. Av.	Per Cent O. V.	Pounds O. V. in 1 Cubic Foot.
60	1.7059	141.2	77.67	106.40	83.35	88.68
61	1.7262	145.2	79.43	107.66	85.23	91.76
62	1.7470	149.4	81.30	108.96	87.24	95.06
63	1.7683	153.7	83.34	110.29	89.43	98.63
64	1.7901	158.0	85.66	111.65	91.92	102.63
641	1.7957	159.1	86.33	112.00	92.64	103.75
641	1.8012	160.2	87.04	112.34	93.40	104.93
641	1.8068	161.4	87.81	112.69	94.23	106.19
65	1.8125	162.5	88.65	113.05	95.13	107.54
651	1.8182	163.6	89.55	113.40	96.10	108.97
651	1.8239	164.8	90.60	113.76	97.22	110.60
651	1.8297	165.9	91.80	114.12	98.51	112.42
66	1.8354	167.1	93.19	114.47	100.00	114.47
Degrees Baunié.	Freesing (Melting) Point.	Per Cent 60° Baumé.	Pounds 60° Baumé in Cubic Foot.	Per Cent 50° Baumé.	Pounds 50° Baumé in Cubic Foot.	
60	+12.6	100.00	106.40	124.91	132.91	
61	27.3	102.27	110.10	127.74	137.52	Ì
62	39.1	104.67	114.05	130.75	142+47	İ
63	46.1	107.30	118.34	134.03	147.82	
64	46.4	110.29	123.14	137.76	153.81	
641	43.6	111.15	124.49	138.84	155.50	
64	41.1	112.06	125.89	139.98	157.25	
641	37.9	113.05	127.40	141.22	159.14	1
65	33.1	114.14	129.03	142.57	161.17	
651	24.6	115.30	130.75	144.02	163.32	
651	13.4	116.65	132.70	145.71	165.76	
651	- 1	118.19	134.88	147.63	168.48	}
66	-29	119.98	137.34	149.87	171.56	l .

XI.—SULPHURIC ACID TABLE 94-100% H₂SO₄ By H. B. Bishop

Bé.	Sp. Gr. at 60° F.	Per Cent.	Wt. 1 Cu. Ft.	Allowance for Temperature.
66	1.8354	93.19	114.47	At 94% .00054 sp.gr. = 1° F
66.12	1.8381	94.00	114.64	" 96 .0053 " =1° F
66.23	1.8407	95.00	114.80	" 97.5 .00052 " =1° F
66.31	1.8427	96.00	114.93	" 100 .00052 " =1° F
66.36	1.8437	97.00	114.99	
66.36	1.8439	97.50	114.99	
66.36	1.8437	98.00	114.99	l .
66.30	1.8424	99.00	114.91	
66.16	1.8391	100.00	114.70	

FUMING SULPHURIC ACID EQUIVALENTS

Total 80:	Equivalent H ₂ SO ₄	Per Cent H ₂ SO ₄	Per Cent Free 80:	Total SO:	Equivalent H ₂ SO ₄	Per Cent HaSO4	Per Cen Free 80.
81.63	100.00	100	0	90.82	111.25	50	50
81.82	100.23	99	li	91.00	111.48	49	51
82.00	100.45	98	2	91.18	111.70	48	52
82.18	100.67	97	3	91.37	111.93	47	53
82.37	100.90	96	4	91.55	112.15	46	54
82.55	101.13	95	5	91.73	112.37	45	55
82.73	101.35	94	6	91.92			
82.92	101.58	93	7		112.60	44	56
83.10	101.80	92	8	92.10	112.82	43	57
83.29				92.29	113.05	42	58
	102.03	91	9	92.47	113.28	41	59
83.47	102.25	90	•l	92.65	113.50	40	60
83.65	102.47	89	11	92.84	113.73	39	61
83.84	102.70	88	12	93.02	113.95	38	62
84.02	102.92	87	13	93.20	114.17	37	63
84.20	103.15	86	14	93.39	114.40	36	64
84.39	103.38	85	15	93.57	114.62	35	65
84.57	103.60	84	16	93.76	114.85	34	66
84.75	103.82	83	17	93.94	115.08	33	67
84.94	104.05	82	18	94.12	115.30	32	68
85.12	104.27	81	19	94.31	115.53	31	69
85.31	104.50	80	20	94.49	115.75	30	70
85.49	104.73	79	21	94.67	115.97	29	71
85.67	104.95	78	22	94.86	116.20	28	72
85.86	105.18	77	23	95.04	116.42	27	73
86.04	105.40	76	24	95.22	116.65	26	74
86.22	105.62	75	25	95.41	116.88	25	
86.41	105.02	74	26	95.59	117.10		75
86.59	106.07	73				24	76
		72	27	95.78	117.33	23	77
86.78	106.30		28	95.96	117.55	22	78
86.96	106.53	71	29	96.14	117.77	21	79
87.14	106.75	70	30	96.33	118.00	20	80
87.33	106.98	69	31	96.51	118.22	19	81
87.51	107.20	68	32	96.69	118.45	18	82
87.69	107.42	67	33	96.88	118.68	17	83
87.88	107.65	66	34	97.06	118.90	16	84
88.06	107.87	65	35	97.25	119.13	15	85
88.24	108.10	64	36	97.43	119.35	14	86
88.43	108.33	63	37	97.61	119.57	13 i	87
88.61	108.55	62	38	97.80	119.80	12	88
88.80	108.78	61	39	97.98	120.03	11	89
88.98	109.00	60	40	98.16	120.25	10	. 90
89.16	109.22	59	41	98.35	120.48	9	91
89.35	109.45	58	42	98.53	120.70	š •	92
89.53	109.67	57	43	98.71	120.92	8 •	93
89.71	109.90	56	44	98.90	121.15	6	94
89.90	110.13	55	45	99.08	121.37	5	95
90.08	110.35	54	46	99.27	121.60	4	96
90.00	110.58	53	47	99.45	121.83	*	
	110.80	52				3 2	97
90.45			48	99.63	122.05	2	98
90.63	111.02	51	49	99.82	122.28	1	99
	1			100.00	122.50	0	100

Compiled from the table by H. B. Bishop, Van Nostrand's Chemical Annual, 1913.

XII.-ACETIC ACID AT 15°

OUDEMANS

			0000	TANIS			
Specific Gravity,	Per Cent H.C, H,O,.	Specific Gravity.	Per Cent H.C,H ₃ O ₂ .	Specific Gravity.	Per Cent H.C,HsO,.	Specific Gravity.	Per Cent H.C,H,O,.
0.9992	0	1.0363	26	1.0623	51	1.0747	76
1.0007	ĭ	1.0375	27	1.0631	52	1.0748	77
1.0022		1.0388	28	1.0638	53	1.0748	78
1.0037	2 3	1.0400	29	1.0646	54	1.0748	79
1.0052	4	1.0412	30	1.0653	55	1.0748	80
1.0067	5	1.0424	31	1.0660	56	1.0747	81
1.0083	6	1.0436	32	1.0666	57	1.0746	82
1.0098	7	1.0417	33	1.0673	58	1.0744	83
1.0113	8	1.0459	34	1.0679	59	1.0742	84
1.0127	9	1.0470	35	1.0685	60	1.0739	85
1.0142	10	1.0481	36	1.0691	61	1.0736	86
1.0157	11	1.0492	37	1.0697	62	1.0731	87
1.0171	12	1.0502	38	1.0702	63	1.0726	88
1.0185	13	1.0513	39	1.0707	64	1.0720	89
1.0200	14	1.0523	40	1.0712	65	1.0713	90
1.0214	15	1.0533	41	1.0717	66	1.0705	91
1.0228	16	1.0543	42	1.0721	67	1.0696	92
1.0242	17	1.0552	43	1.0725	68	1.0686	93
1.0256	18	1.0562	44	1.0729	69	1.0674	94
1.0270	19	1.0571	45	1.0733	70	1.0660	95
1.0284	20	1.0580	46	1.0737	71	1.0644	96
1.0298	21	1.0589	47	1.0740	72	1.0625	97
1.0311	22	1.0598	48	1.0742	73	1.0604	98
1.0324	23	1.0607	49	1.0744	74	1.0580	99
1.0337	24	1.0615	50	1.0746	75	1.0553	100
1.0350	25	11	1	<u> </u>	1		1

XIII.-MELTING POINTS OF ACETIC ACID

RUDORFF, Ber. 3, 390.

H.C ₂ H ₄ O ₂ mixed with gr. water.	by weight con- tain parte water.	Melting (eolidi- fying) point C.	H.C ₂ H ₈ O ₂ mixed with gr. water	by weight con- tain parts water.	Melting (solidifying) point °C.
0.0	0.0	16.7°	8.0	7.407	6.25°
0.5	0.497	15.65	9.0	8.257	5.3
1.0	0.990	14.8	10.0	9.090	4.3
1.5	1.477	14.0	11.0	9.910	3.6
2.0	1.961	13.25	12.0	10.774	2.7
3.0	2.912	11.95	15.0	13.043	-0.2
4.0	3.846	10.5	18.0	15.324	-2.6
5.0	4.761	9.4	21.0	17.355	-5.1
6.0	5.660	8.2	24.0	19.354	-7.4
7.0	6.542	7.1	1		

Boiling point 100% acid 117 8°.

XIV.—AQUA AMMONIA According to W. C. Ferguson

Degrees Baumé.	8p. Gr. 60° F.	Per Cent	Degrees Baumé.	8p. Gr. 60° F.	Per Cent	Degrees Baumé.	8p. Gr. 60° F.	Per Cent
10.00	1.0000	.00	16.50	.9556	11.18	23.00	.9150	23.52
10.25	.9982	.40	16.75	.9540	11.61	23.25	.9135	24.01
10.50	.9964	.80	17.00	.9524	12.10	23.50	.9121	24.50
10.75	.9947	1.21	17.25	.9508	12.56	23.75	.9106	24.99
11.00	.9929	1.62	17.50	.9492	13.02	24.00	.9091	25.48
11.25	.9912	2.01	17.75	.9475	13.49	24.25	.9076	25.97
11.50	.9894	2.46	18.00	.9159	13.96	24.50	.9061	26.46
11.75	.9876	2.88	18.25	.9444	14.43	24.75	.9047	26.05
12.00	.9859	3.30	18.50	.0128	14.00	25.00	.0032	27.44
12.25	.9842	3.73	18.75	.9412	15.37	25.25	.9018	27.03
12.50	.9825	4.16	19.00	.9396	15.84	25.50	.9003	28.42
12.75	.9807	4.59	19.25	.9380	16.32	25.75	.8089	28.91
13.00	.9790	5.02	19.50	.9365	16.80	26.00	.8974	29.40
13.25	.9773	5.45	19.75	.9349	17.28	26.25	.8960	29.89
13.50	.9756	5.88	20.00	.9333	17.76	26.50	.8046	30.38
13.75	.9730	6.31	20.25	.9318	18.24	26.75	.8931	30.87
14.00	.9722	6.74	20.50	.9302	18.72	27.00	.8917	31.36
14.25	.9705	7.17	20.75	.9287	19.20	27.25	.8903	31.85
14.50	.9689	7.61	21.00	.9272	19.68	27.50	.8880	32.34
14.75	.9672	8.05	21.25	.9256	20.16	27.75	.8875	32.83
15.00	.9655	8.49	21.50	.9241	20.64	28.00	.8861	33.32
15.25	.9639	8.93	21.75	.9226	21.12	28.25	.8847	33.81
15.50	.9622	0.38	22.00	.9211	21.60	28.50	.8833	34.30
15.75	.9605	9.83	22.25	.9195	22.08	28.75	.8819	34.79
16.00	.9589	10.28	22.50	.9180	22.56	29.00	.8805	35.28
16.25	.9573	10.73	22.75	.0165	23.04			

ALLOWANCE FOR TEMPERATURE

The coefficient of expansion for ammonia solutions, varying with the temperature, correction must be applied according to the following table:

Corrections to be Added for Each Degree Below 60° F.					Corrections to be Subtracted for Each Degree Above 50° F.							
Degrees Baumé.			•	70° F.		80° F.		90° F.		100° F.		
14° Bé	.015°	Bé	.017°	Bé	.020°	Bé	.022°	Bé	.024•	Bé	.026•	Bé
16°	.021	"	.023	"	.026	"	.028	"	.030	"	.032	44
18°	.027	"	.029	"	031	"	.033	"	.035	44	.037	"
20°	.033	"	.036	"	.037	"	.038	"	.040	"	.042	"
22°	.039	"	.042	"	.043	"	.045	"	.047	"		
26°	.053	"	.057	· ·	.057	"	.059	"	}			

XV.—SODIUM HYDROXIDE SOLUTION AT 15° Lunge

Specific	Degrees	Degrees	Per Cent	Per Cent	r Liter Gre	
Gravity.	Baume.	Twaddell.	Na ₂ O.	NaOH.	Na ₂ O.	NaOH
1.007	1.0	1.4	0.47	0.61	4	6
1.014	2.0	2.8	0.93	1.20	g .	12
1.022	3.1	4.4	1.55	2.00	16	21
1.029	4.1	5.8	2.10	2.70	22	28
1.036	5.1	7.2	2.60	3.35	27	35
1.045	6.2	9.0	3.10	4.00	32	42
1.052	7.2	10.4	3.60	4.64	38	49
1.060	8.2	12.0	4.10	5.29	43	56
1.067	9.1	13.4	4.55	5.87	49	63
1.075	10.1	15.0	5.08	6.55	55	70
1.083	11.1	16.6	5.67	7.31	61	79
1.091	12.1	18.2	6.20	8.00	68	87
1.100	13.2	20.0	6.73	8.68	74	95
1.108	14.1	21.6	7.30	9.42	81	104
1.116	15.1	23.2	7.80	10.06	87	112
1.123	16.1	25.0	8.50	10.97	96	123
1.134	17.1	26.8	9.18	11.84	104	134
1.142	18.0	28.4	9.80	12.64	112	144
1.152	19.1	30.4	10.50	13.55	121	156
1.162	20.2	32.4	11.14	14.37	129	167
1.171	21.2	34.2	11.73	15.13	137	177
1.180	22.1	36.0	12.33	15.91	146	183
1.190	23.1	38.0	13.00	16.77	155	200
1.200	24.2	40.0	13.70	17.67	164	212
1.210	25.2	42.0	14.40	18.58	174	225
1.220	26.1	44.0	15.18	19.58	185	239
1.231	27.2	46.2	15.96	20.59	196	253
1.241	28.2	48.2	16.76	21.42	208	266
1.252	29.2	50.4	17.55	22.64	220	283
1.263	30.2	52.6	18.35	23.67	232	299
1.274	31.2	54.8	19.23	24.81	245	316
1.285	32.2	57.0	20.00	25.80	257	332
1.297	33.2	59.4	20.80	26.83	270	348
1.308	34.1	61.6	21.55	27.80	282	364
1.320	35.2	64.0	22.35	28.83	295	381
1.332	36.1	66.4	23.20	29.93	309	399
1.345	37.2	69.0	24.20	31.22	326	420

677

XV.—SODIUM HYDROXIDE SOLUTION AT 15° (Continued)

Specific	Degrees	Degrees	Per Cent	Per Cent	I Liter contains Grams	
Gravity.	Baumć.	Twaddell.	Na ₃ O.	NaOH.	Na ₂ O.	NaOH
1.357	38.1	71.4	25.17	32.47	342	441
1.370	39.2	74.0	26.12	33.69	359	462
1.383	40.2	76.6	27.10	34.96	375	483
1.397	41.2	79.4	28.10	36.25	392	506
1.410	42.2	82.0	29.05	37.47	410	528
1.424	43.2	84.8	30.08	38.80	428	553
1.438	44.2	87.6	31.00	39.99	446	575
1.453	45.2	90.6	32.10	41.41	466	602
1.468	46.2	93.6	33.20	42.83	487	629
1.483	47.2	96.6	34.40	44.38	510	658
1.498	48.2	99.6	35.70	46.15	535	691
1.514	49.2	102.8	36.90	47.60	559	721
1.530	50.2	106.0	38.00	49.02	581	750

XVI.—VAPOR TENSION OF WATER IN MILLIMETERS OF MERCURY -2° TO : 36° C.

According to Regnault, Broch, and Weibe

c.	0	.1	.2	.3	.4	.5	.6	.7	.8	.9
_	mm.	mm.	mm.	mm.	mm,	mm.	mm.	mm.	mm.	mm.
2	3.958	3.929	3.900	3.872	3.844			3.760	3.732	3.705
1	4.258	4.227	4.197	4.166	4.136				4.016	3.987
0	4.579	4.546	4.513	4.481	4.448			4.352	4.321	4.289
9	4.579	4.612	4.646	4.679				4.816	4.851	4.886
1	4.921	4.957	4.992	5.028		5.101	5.137	5.174	5.211	5.24
2	5.286	5.324			5.438				5.595	
3		5.715	5.755			4.3		5.961	6.003	
4		6.131	6.174		6.261	6.305			6.438	
5	6.528	6.574	6.620		6.712		6.806		6.901	6.94
6	6.997	7.045	7.094				7.292		7.392	7.44
7	7.494	7.546							7.914	7.96
8	8.023		8.132						8.469	8.52
9	8.584	8.642	8.700					8.997	9.057	9.11
10									9.680	9.74
l1		9.875		10.006						
			10.617							
			11.333							
			12.091							
			12.892							
			13.738							
			14.632							
			15.575							
			16.571							
10	17.406	17.513	17.620	17.728	17.837	17.947	18.057	18.167	18.278	18.39
11	18.503	18.616	18.729	18.844	18.959	19.071	19.190	19.307	19.424	19.54
12	19.661	19.780	19.900	20.021	20.142	20.264	20.386	20.510	20.634	20.75
13	20.883	21.010	21.137	21.261	21.393	21.522	21.652	21.782	21.913	22.04
			22.446							
			23.828							
16	24.987	25.135	25.284	25.434	25.584	25.736	25.888	26.041	26.195	26.34
17	26.505	26 . 661	26.818	26.976	27.134	27.294	27.454	27.615	27.777	27.93
			28.432							
19	29.785	29.958	30.132	30.307	30.482	30.659	30.836	31.015	31.194	31.37
30	31.555	31.737	31 . 9 19	32.103	32.288	32.473	32.660	32.847	33.036	33.22
			33.799							
12	35:372	35.573	35.775	35.978	36.182	36.387	36.593	36.800	37 008	37.21
13	37.427	37.638	37.851	38.064	38.278	38.493	38.710	38.927	39.146	39.36
14	39.586	39.807	40.030	40.254	40.479	40.705	40.933	41.161	41.390	41.62
			42.319							

XVII.—USEFUL DATA OF THE MORE IMPORTANT INORGANIC COMPOUNDS *

Substance.	Formula.	Molecular or Atomic Weight.	Normal Coefficient 1 c.c. = gm.	Solubility in 100 Gms. Water.	Indi- cator
Acctic acid	HC ₂ H ₃ O ₂	60.04	.06004		
anhydride	(CH ₂ CO) ₂ O	102.07	.051035	1	1
Aluminium		27.10	.009033		1
chloride	Al ₂ Cl ₆	266.96	.04449	69.87140	n
chloride	Al ₂ Cl ₃ ·12H ₄ O	483.15	08053	40	P. P.
oxide	Al ₂ O ₂	102.20	.01703		P.
phosphate	AlPO	122.14	.04071	insol.	
sulphate		342.38		36.1200	-
sulphate		666.67	.05706		P.
Ammonia	N11		.11111	87	P.
Ammonium	NH	17.03	.01703		M.
ahlasida	NIII4	18.04	.01804		M.
ehloride		53.50	.05350	29.400	M.
hydroxide		35.05	.03505		М.
nitrate		80.05	.08005	11800	M.
oxalate	(NH ₄) ₂ C ₂ O ₄ ·H ₂ O	142.11	.0710513		1
sulphate		132.14	.06607	71°°	M.
Antimony		120.20	.06010		
chloride (tri)	SbCla	226.58	.113293		
ehloride (penta)	SbCl	297.50	. 148753		
oxide (tri)	Sb_2O_3	288.40	.072102		
oxide (penta)	Sb_2O_5	320.40	.080103		
Arsenic	As	74.96	.03748		
oxide	As ₂ O ₅	229.92	.03832 1	150	
oxide	As ₂ O ₅	229.92	.05748 1		
Arsenious oxide	As ₂ O ₃	197.92	.03299	1.7160	
Arsenious oxide	As ₂ O ₃	197.92	.04948	1.7130	
Barium	Ba	137.37	.068685		
earbonate		197.37	.098685	.0022200	M.
ehloride		208.29	. 104145	30.900	4444
ehloride	BaCl ₂ 2H ₂ O	244.32	.12216	33.200	
hydroxide	Ba(OH),	171.38	.08569	00.2	
hydroxide	Ba(OH) ₂ 8H ₂ O	315.51	.15775	5.15150	
oxalate	BaC ₂ O ₄ ·H ₂ O	243.40	12170	0.10	
oxide	BaO	153.37	.076685	1.5°°	
sulphate	BaSO ₄	233.43	.11672	.00017200	
sulphite	BaSO ₂	217.43	10872	.000172	
peroxide	BaO ₂	169.37	.08469 *	insol.	
Porie acid	H ₂ BO ₂	61.92	.06192	111801.	
Bromine	Br	79.92	.00192	4 1700	
Cadmium carbonate.	CdCO:	172.405		4.1700	
chloride		183.32	.08620 .09166	insol.	
	CdCl ₂			140200	
chloride	CdCl ₂ 2H ₂ O	219.35	.109675	16820°	
sulphide	CdS	144.46	07223	insol.	
Calcium	Ca	40.07	.020035	f	
acetate	Ca(C ₂ H ₂ O ₂) ₃	158.14	.07907		
bicarbonate	Ca (HCO ₂) ₂	162.10	.08105		
carbonate	CaCO ₂	100.075	.050037	.0013	М.
chloride	CaCl ₂	110.99	.055495	59.5°°	
chloride	CaCl ₂ 6H ₂ O	219.09	.109543	117.4°°	
fluoride	CaF,	78.07	.039035		
hydroxide	Ca(OH) ₂	74.09	.037045	.17°°	
oxalate	CaC ₂ O ₄ ·H ₂ O	146.10	. 07305	1	

Precipitation reagents.
M. Methyl orange.

³ Oxidizing and reducing agents.

² Acids and bases. ³ Oxidising.
e. P. Phenolphtbalein.

Temp. C.

^{*} Compiled and arranged by R. M. Meiklejohn.

XVII.—USEFUL DATA OF THE MORE IMPORTANT INORGANIC COMPOUNDS (Continued)

Substance.	Formula.	Mclecular or Atomic Weight.	Normal Coefficient 1 c.c. = gm.	Solubility in 100 Gms. Water.	Indi- cator.
Calcium oxide	CaO	56.07	.028035	.1300	
sulphate	CaSO ₄	136.13	.06807	. 179°°	
sulphide	CaS	72.13	.03607	.15100	
Carbon	C	12.005	.003001	insol.	
dioxide	CO ₂	44.005	.0220031	179.67 cc.º°	
dioxide	CO ₂	44.005	.0440053	"	P.
Chlorine	Cl	35.46	.03546	150 cc.0°	
Chromic anhydride	CrO ₂	100.00	.0333333	163.40°°	
oxide	Cr ₂ O ₂	152.00	.025333 1	insol.	
Citric acid	H ₄ C ₄ H ₄ O ₇	192.09	.06403	133.	
Cobalt	Co ·	58.97	.029485		
Copper	Cu	63.57	.031785	i i	
oxide	CuO	79.57	.07957		
sulphate	ČuSO₄	159.63	15963	2000	
sulphate	CuSO ₄₅ H ₂ O	249.71	.24971	31.6100	
sulphide	CuS	95.63	.047815	.000033	
Cyanogen	CN	26.013	.026013	.000000	
Ferric oxide	Fe ₂ O ₂	159.68	.07984		
phosphate	FePO4·4H ₂ O	222.94	.07431	1	
	FeO	71.84	.07184	ingal	
Ferrous oxide	FeSO ₄	151.90		insol.	
	FeSO ₄ 7H ₂ O		.15190 2	00.000	
sulphate		278.01	.27801 2	32.8°°	
ammon'm sulphate.		392.14	.39214	180°	
Formic acid	нсоон	46.02	.04602		
Hydrobromic acid	HBr	80.93	.08093	221.2°°	
Hydrochloric acid	HCl	36.47	.03647	82.510°	
Hydrocyanic acid	HCN	27.02	.02702		
Hydrofluoric acid	1IF	20.01	.02001	264	
Hydrofluosilicie acid.	H ₂ SiF ₆	144.32	.02405	i i	
Hydroiodic acid	HI	127.93	.12793	1	
Hydrogen peroxide	H ₂ O ₂	34.016	.017008	l	
Hydrogen sulphide	H₂S	34.076	.017038	437 cc. °°	
Iodine	Ï	126.92	.12692	.0182110	
Iron	Fe	55.84	.05584	1	
Lead	Pb	207.20	. 10360	j i	
carbonate	PbCO ₃	267.205	. 13360	.00198	M.
chromate	PbCrO ₄	323.20	.16160	.00002 ¹⁸ °	
oxide	PbO	223.20	.11160]	
peroxide	PbO ₂	239.20	.11960		
sulphate	PbSO ₄	303.26	.15163	1	
sulphide	PbS	239.26	.11963	.0001	
sulphite		287.26	.14363 1	j į	
Magnesium	Mg	24.32	.01216		
carbonate	MgCO ₃	84.32	. 04216	.0106	
chloride	MgCl ₂	95.24	.04762	52.2°°	M.
chloride	MgCl₂6H₂O	203.34	.10167	167	M.
oxide	MgO	40.32	.02016	.00062	M.
sulphate	MgSO ₄	120.38	.06019	26.9°°	M.
sulphate	MgSO ₄ 7H ₂ O	246.49	.123245	76.9°°	M.
Malie acid	H ₂ C ₄ H ₄ O ₃	134.07	.06703	''''	
Manganese	Mn	54.93	.027465		
chloride	MnCl.	125.85	.062925	62.16100	
peroxide		86.93	.043465	insol.	

² Precipitation reagents.

² Acids and bases.

³ Oxidizing and reducing agents.

M. Methyl orange.

P. Phenolphthalein.

Temp. C.

XVII.—USEFUL DATA OF THE MORE IMPORTANT INORGANIC COMPOUNDS (Continued)

Substance.	Formula.	Molecular or Atomic Weight.	Normal Coefficient 1 c.c. = gm.	Solubility in 100 Gms. Water.	Indi- cator.
Manganese sulphate.	MnSO ₄	150.99	.075495	53.200	
Mercuric chloride	HgCl:	271.52	.13576	5.73°°	ĺ
Mercurous chloride	HgCl	236.06	.23606	0.70	
Mercury	Hg	200.6	.2006		İ
Nickel	Ni	58 68	.02934		
Nitric acid	HNO.	63.02	.06302		
Nitric acid	HNO.	63.02	.021006 3		
Nitrogen trioxide	N ₂ O ₂	76.02	.019005*		
pentoxide	N ₂ O ₂	108.02	.05401		
pentoxide	N ₂ O ₅	108.02			
Nitrous acid			.018033*		
Ntinous acid	HNO ₂	47.02	.04702		
Ntirogen	N	14.008	.01401		
Oxalic acid	H ₂ C ₂ O ₄	90.03	.04501		
Oxalic acid	H ₂ C ₁ O ₄ 2H ₂ O	126.06	.06303	4.900	
Phosphoric acid		98.06	.09806 2	v. sol.	M.
Phosphoric acid	H.PO.	98.06	.04903 *	v. sol. 0	P.
Phosphoric acid Phosphorous acid	H ₂ PO ₄	98.06	.03268	v. sol.	
(ortho)	H ₃ PO ₂	82.06	.02735		
pentoxide	P_2O_b	142.08	.02368		
Potassium	K	39.10	.03910		
bicarbonate	KHCO,	100.11	.10011	22.40°	M.
bitartrate	KHC,H,O,	188.16	.18816	.3700	P.
bromate	KBrO.	167.02	. 16702	.01	1.
biodate		389.95	.38995 2		
	KH(IO ₃) ₃	389.95	.03249		
biodate	KH(IO ₂) ₂			PO 4000	
bromide	KBr	119.02	.11902	53.48°°	
carbonate	K ₂ CO ₃	138.20	.06910	89.4°°	Μ.
carbonate	K ₂ CO ₃	138.20	.06910 2		
chlorate	KClO.	122.56	.020427	3.300	
Potassium chloride	KC!	74.56	.07456	28.500	
chromate	K ₂ CrO ₄	194.20	.06473 *	61.5°°	
cyanide	KCN	65.11	.06511 1	v. sol.	
dichromate	K ₂ Cr ₂ O ₇	294.20	. 07355 1	000	
dichromate	K ₂ Cr ₂ O ₇	294.20	. 14710 *	4.900	P.
dichromate	K ₂ Cr ₂ O ₇	294.20	.04903	4.9°°	
ferrocyanide	K ₄ Fe(CN) ₆	368.32	.36832 *		
ferrocyanide	K₄Fe(CN) _s 3H ₂ O	422.37	.422.37	27.8120	
fluoride	KF	58.10	.05810		
hydroxide	KOH	56.11	.05611	107130	
iodate	KIO.	214.02	.03567	4.7400	
iodide	KI .	166.02	.16602	126.1°°	
manganate	K ₂ MnO ₄	197.13	.049283*		
nitrate	KNO.	101.11	.033703	13.3°°	
nitrite	KNO	85.11	.08511	30013.40	
	KNO:	184.23	.09211	000	
oxalate	K ₁ C ₂ O ₄ ·H ₂ O	94.20	.04710	eol	
oxide	K ₂ O			v. sol.	
perchlorate	KClO ₄	138.56	.01732	0.0000	
permanganate	KMnO ₄ ,	158.03	.031606	2.83°°	
sulphide	K ₂ S	110.26	.05513	sol.	
sulphocyanate	KCNS	97.17	.09717	177.2°°	
tartrate	K ₁ C ₄ H ₄ O ₆	226.25	.11312	sol.	
Silver	Ag	107.88	. 10788		

¹ Precipitation reagents. 8'Acids and bases. ² Oxidising and reducing agents.
M. Methyl orange. P. Phenolphthalein. Temp. C.

XVII.—USEFUL DATA OF THE MORE IMPORTANT INORGANIC COMPOUNDS (Continued)

Substance.	Formula.	Molecular or Atomic Weight.	Normal Coefficient 1 c.c. = gm.	Solubility in 100 Gms. Water.	Indi cator
Silver bromide	AgBr	187.80	. 18780		
chloride	AgCl	143.34	. 14334		l
nitrate	AgNO ₂	169.89	. 16989	122°°	ļ
Sodium	Na	23.00	.02800		
bromide	NaBr	102.92	. 10292	79.5°°	l
bicarbonate	NaHCO _a	84.01	. 08401	6.90°°	M
carbonate	Na ₂ CO ₂	106.005	.053002	7.10°	M
chlorate	NaClO ₂	106.46	.017743		
chloride	NaCl	58.46	.05846	35.7°°	ŀ
cyanide	NaCN	49.01	.04901	sol.	l
hydroxide	NaOH	40.01	.04001	133.3180	
iodide	NaI	149.92	.14992 1	158.7°°	i
nitrate	NaNO.	85.01	.02834	72.900	1
nitrite	NaNO ₂	69.01	.06901	83.3200	l
oxalate	Na ₁ C ₂ O ₄	134.01	.06700	3.2215.80	
oxide		62.00	.03100	decomp.	ł
phosphate (mono).		120.06 2	.12006	v. sol.	М
phosphate (disod)		142.05 2	.14205		P.or
phosphate (disod)	Na ₂ HPO ₄ 12H ₂ O	358.24 2	.35824	6.300	P.or
phosphate (trisod).		164.04 2	.16404	1	P
	Na ₃ PO ₄ ·12H ₂ O	380.24	.380243		P
phosphate		78.06	.03903	15.4100	r
sulphide	Na ₂ S	126.06		15.4.	1
sulphite	Na ₂ SO ₃		.06303	74 700	i
thiosulphate	Na ₂ S ₂ O ₃ 5H ₃ O	248.20	.24820	74.7°°	1
thiosulphate	Na ₂ S ₂ O ₃ 5H ₂ O	248.20	.248203		
Stannic oxide	SnO ₂	150.70	.15070	00.000	1
Stannous chloride	SnCl ₂	189.62	.09481	83.900	
chloride	SnCl₂2H₂O	225.65	.112825	118.700	
oxide	SnO	134.70	.06735	insol.	
Sulphur dioxide	80,	64.06	.03203	7979 cc. °°	1
trioxide	SO ₂	80.06	.04003		l
Sulphuric acid	H ₂ SO ₄	98.076	.049038		1
Sulphurous acid	H ₂ SO ₃	82.076	.04104 2		1
Tartaric acid	H ₂ C ₄ H ₄ O ₆	150.07	.075035	115°°	1
Tin	Sn	118.70	. 05935		1
Titanium chloride	TiCl.	154.48	.15448 *		1
Zinc	Zn	65.37	.037685		ļ
carbonate	ZnCO ₃	125.37	.062685	.001160	1
chloride	ZnCl:	136.29	.008145	209°°	1
oxide	ZnO	81.37	. 040685	.001	1
sulphate		161.43	.080715	43.02°°	
aulphate		287.54	.14377	115.2°	Į .
sulphide	ZnS	97.43	.048715	.00069	

XVIII.—CONVERSION FACTORS •

		1					
Α'	A	В	B'	A'	A	В	B'
1.7408	Ag	AgBr	0.5744	0.3055	AgNO ₁	HNO2	8.2729
2.1857	Ag	AgBrO ₂	0.4575	0.2470	AgNO ₁	N ₂ O ₂	4.0487
1.3287	Ag	AgCl	0.7526		AgNO	HNO	2.6959
1.2411	Ag	AgCN	0.8057		AgNO	NaCl	2.9061
2.1765	Ag	AgI	0.4595	0.7970	AlCl	C1	1.2547
1.4265	Ag	AgNO ₂	0.7010		AlCl	H.SO	0.9072
1.5748	Ag	AgNO ₃	0.6350		AlF	CaF	0.7182
1.0742	Ag	Ag ₂ O	0.9310		Al ₂ O ₁	Al	1.8856
1.2935	Ag	Ag ₃ PO ₄	0.7731	2.6121	Al ₂ O ₂	AlCl	0.3828
1.4034	Ag	Ag ₄ P ₂ O ₇	0.7126	2.2336	Al ₂ O ₂	Al ₂ P ₂ O ₇	0.4477
0.2316	Ag	As	4.3175	2.3902	Al₂O₃	Al ₂ P ₂ O ₃	0.4184
0.7408	Ag	Br	1.3498	3.3501	Al ₂ O ₂	$Al_2(SO_4)_1$	0.2985
0.7502	Ag	HBr	1.3330	6.5232	Al ₂ O ₂	Al ₂ (SO ₄) ₂	
0.3287	Ag	C1	3.0423			18H ₂ O	0.1533
0.3380	Ag	HC1	2.9582	2.1088	Al ₂ O ₂	FeO	0.4742
1.1859	Ağ	HI	0.8433	1.5625	Al ₂ O ₂ ,	Fe ₂ O ₂	0.6400
1.1765	Ag	I	0.8500	2.8792	Al ₂ O ₂	H.SO	0.3473
1.1033	Ağ	KBr	0.9064		Al ₂ O ₃	K2Al2(SO4)4	
0.6911	Ag	KCl	1.4469	9.2859		24H,O	0.1077
1.1361	Ag	KClO ₃	0.8802	1.6067	Al ₂ O ₂	Na ₂ Al ₂ O ₄	0.6224
1.2844	Ag	KClO	0.7786	8.8738	Al ₂ O ₂	(NH ₄) ₂ Al ₂	
0.6036	Ag	KCN	1.6568			(SO ₄) ₄ · 24H ₂ O	0.1127
1.5390	Ag	KI	0.6498	1.8804	Al ₂ O ₂	(80.)	0.5318
0.9540	Ag	NaBr	1.0482	2.3501	Al ₂ O ₂	(SO ₂) ₂	0.4255
0.5419	Ag	NaCl	1.8453		AlPO4	Al	4.5070
1.3897	Ag	NaI	0.7196		AlPO ₄	AlgO ₁	2.3902
0.4256	AgBr	Br		0.5816	AlPO	P ₁ O ₁	1.7198
0.6811	AgBr	BrO ₃	1.4681	0.6224	AlsPsO7	P.O	1.6067
0.4311	AgBr	HBr		0.5816	Al ₂ P ₂ O ₃	P ₃ O ₃	1.7198
0.6337	AgBr	KBr		2.0453	Al ₂ (8O ₄) ₃	BaSO ₄	0.4889
0.8893	AgBr	KBrO ₃		0.8594	Al ₂ (SO ₄) ₂	H ₂ SO ₄ NaHCO ₄	1.1636 0.6792
1.2556	AgBr	AgBrO ₁	1.8247	1.4723 0.7015	$Al_2(SO_4)_1$ $Al_2(SO_4)_2$	SO	1.4255
0.5480	AgBr	NaBr		0.7506		Al	1.3322
0.7526	AgCl	Ag	1.3287 0.8437	1.4154	Al ₄ C ₃ Al ₄ C ₂	Al ₂ O ₂	0.7065
1.1852	AgCl	AgNO	4.0423	1.4104	Auci	AljO ₃	0.7000
0.2474	AgCl	HCl	3 9305	4.3175	As	Ag	0.2316
0.2545 0.5202	AgCl	KCI	1.9225	1 6403	As	A8O2	0.6096
0.8550	AgCl AgCl	KClO ₂	1.1695	1.8538	As	AsO4	0.5394
0.4078	AgCl	NaCl	2.4519	1.3201	As.	As ₂ O ₂	0.7575
0.3732	AgCl	NH.Cl	2.6793		As	As ₂ O ₂	0.6521
0.3754	AgCl	ZnCl ₂	2.1034	1.6417	As	As-S	0.6091
0.4863	AgCN	KCN	2.0564	2.0692	As	As-S	0.4888
0.2020	AgCN	HCN	4.9551	3 3862	As	2I	0.2958
0.6174	AgI	NH.I	1.6197	2.5391	As	MgNH ₄ AsO ₄	
0.5448	AgI	HI	1.8354			· H.O	0.3938
0.5406	AgI	I	1.8500	2.0715	As	Mg.As.O1	0.4827
0.7450	AgI	IO	1.3423	2.1875	As	NaH ₁ AsO ₄	0.4571
0.6428	AgI	I ₂ O ₂	1.5558	2.4809	As	Na ₂ HAnO ₄	0.4081
0.7790	AgI	I ₂ O ₇	1.2836	1.9233	As ₂ O ₂	MgNH,AsO,	
0.7071	AgI	KI	1.4143			H.O	0.5199
0.9115	AgI	KIO	1.0971	1.5691	As ₂ O ₁	Mg ₂ As ₂ O ₇	0.6373
0.6385	AgI	NaI	1.5661	1.1253	A52O1	Mg ₁ P ₂ O ₁	0.8886
						1	

 $A \times A' = B$ $B \times B' = A$

[•] Compiled by Wilfred W. Scott and R. M. Meiklejohn. See page 698.

$\textbf{XVIII.--CONVERSION}_{\bullet}\textbf{FACTORS} \hspace{0.1cm} \textbf{(Continued)}$

							
A'	A	В	B'	A'	A	В	B'
1.1616	As ₂ O ₄	A82O5	0.8609	0.8111	BaO ₁	Ba	1.2329
1.2435	As ₂ O ₄	As ₂ S ₄	0.8042	0.4912	BaSiF	Ba	2.0359
1.5674	As ₂ O ₁	As ₂ S ₆		0.7448	BaSiF	BaCl	1.3427
2.5652	As ₂ O ₄	4I	0.3898	0.6271	BaSiF ₄	BaF	1.5948
1.8493	As _i O ₁	As ₂ S ₂	0.7411	0.5484	BaSiF ₆	BaO	1.8235
1.3507	A82O4	Mg.As ₁ O ₇	0.7403	0.4078	BaSiF	F	2.4533
1.6556	At ₂ O ₆	MgNH ₄ AsO ₄	0 0040	0.4292	BaSiF ₆	HF	2.3297
1.4264	As ₂ O ₄	· H ₂ O NaH ₂ AsO ₄	0.6040	0.5160	BaSiF	H ₂ SiF ₄	1.9379
1.6177	As ₂ O ₄	Na ₂ HA ₅ O ₄	0.7011 0.6182	0.3729 0.2156	BaSiF ₄	SiF ₄	2.6814 4.6380
2.2081	As ₂ O ₄	4I	0.4529	0.8108	BaS	Ba	1.2334
	220304	T	0.1020	1.2833	BaS	BaSO	0.7792
1.5394	Au	AuCl	0.6496	1.3777	BaS	BaSO	0.7258
2.0898	Au	HAuCL		1.4725	BaS	BaS ₂ O ₄	0.6791
		·4H ₂ O	0.4785	0.6318	BaSO	Ba	1.5828
1.8172	Au			1.0736	BaSO	BaSO	0.9315
		·H _• O	0.5503	1.1475	BaSO ₄	BaS ₂ O ₂	0.8715
3.2018	В	D.O.	0.0100	0.4889	BaSO4	Al ₂ (SO ₄) ₁	2.0453
11.5596	В	B ₁ O ₂ KBF ₄	0.3123 0.0865	0.5885 0.8923	BaSO ₄	Ba BaCl	1.6993
1.2292	B ₁ O ₁	BO.	0.8135	1.0466	BaSO ₄	BaCla 2H ₂ O	1.1207 0.9554
1.6877	B.O	BO ₁	0.5925	0.8455	BaSO ₄	BaCO	1.1827
1.1146	B ₂ O ₂	B ₄ O ₇	0.8972	1.0854	BaSO	BaCrO ₄	0.9213
1.7743	B ₂ O ₂	H ₂ BO ₂	0.5636	1.1197	BaSO	Ba(NOs)s	0.8931
3.6103	B ₁ O ₄	KBF ₄	0.2770	0.6571	BaSO	BaO	1.5219
2.7347	B ₂ O ₄	Na ₂ B ₄ O ₇		0.7256	BaSO ₄	BaO2	1.3782
0.4015	\$210 TO	·10H _i O	0.3657	0.8599	BaSO ₄	Ba4(PO4)4	1.1629
0.4915 0.7575	KBF ₄	H ₁ BO ₁	2.0347	0.7258	BaSO4	BaS	1.3778
0.7070	KBF4	Na ₂ B ₄ O ₇ 10H ₂ O	1.3202	1.0688 0.5147	BaSO ₄	BaS ₂ O ₁ CaSO ₄	0.9356
1.8594	Ва	Ba(C ₂ H ₂ O ₄) ₂		0.5832	BaSO ₄	CaSO ₄	1.9429
1.8444	Ba	BaCrO	0.5420		BaSO ₄	FeS	2.6554
1.6993	Ва	BaSO ₄	0.5885		BaSO	H.S	6.8503
1.4368	Ba	BaCO:	0.6960	0.3517	BaSO	H-SO	2.8441
1.8162	Ba	BaS ₁ O ₁	0.5506		BaSO ₄	H ₂ SO ₄	2.3801
0.7002	Ba	<u> </u>	1.4283		BaSO ₄	K2SO4	1.3395
0.9335 1.1207	Ba BaCla	S ₄		1.0164	BaSO ₄	K,Al,(SO,),	0.0000
0.4709	BaCl _t	BaSO ₄	0.8923 2.1238	0.5834	BogO.	24H ₂ O KHSO ₄	0.9839
1.2887	BaCO ₂	BaCrO ₄		0.5834	BaSO ₄	MgO	1.7141 5.7894
0.7770	BaCO.	BaO		1.0560	BaSO ₄	MgSO ₄ ·7H ₄ O	0.9469
0.0608	BaCO,	C	16.4411	0.6469	BaSO4	MnSO	1.5458
0.2229	BaCO ₃	CO	4.4853	0.4541	BaSO	Na ₂ CO ₃	2.2022
8.1696	C(in BaCO ₆)	H ₂ SO ₄		0.4458	BaSO4	NaHSO	2.2432
0.5420 0.6053	BaCrO ₄	Ba		0.2656	·BaSO ₄	Na ₂ O	3.7651
0.9213	BaCrO ₄	BaSO		0.3344	BaSO4	Na ₂ S	2.9904
0.2052	BaCrO ₄	Cr	1.0854 4.8725	0.5401 0.3387	BaSO ₄	Na SO	1.8515 2.9524
0.8947	BaCrO ₄	CrO ₁		0.6086	BaSO ₄	NasSo	1.6431
0.3000	BaCrO	Cr ₂ O ₁	3.3338	1.3804	BaSO ₄	Na SO	1
0.3000 1.4138	BaCrO	$Cr_2(SO_4)_4$				10H	0.7244
		·18H ₂ O	0.7073	0.5661	BaSO	(NH ₄),804*	1.7665
Q. 76 66	BaCrO ₄	K,CrO,	1.3046	1.2991	BaSO	Pb804	0.7697
0.5807	BaCrO _t	K ₁ Cr ₂ O ₇	1.7224	0.1373	BaSO ₄	8	7.2812
0.5728	Ba(OH) ₈	H ₂ SO ₄	1.7473	0.2744	BaSO ₄	80	3.6439
<u> </u>	<u> </u>		<u> </u>		<u> </u>		

A'	A	В	B'	A'	A	В	В'
0.3430	BaSO ₄	SO ₂	2.9155	0.5133	CaF ₁	Ca	1.948
0.4115	BaSO4	SO4	2.4301	0.7182	CaF ₂	I CaO	1.392
0.4174	BaSO ₄	ZnS	2.3957	1.7438	CaF ₂	CaSO	0.573
1.2318	BaSO ₄	ZnSO ₄ ·7H ₂ O	0.8118	1.7438 0.4867	CaF ₁	F	2.054
G (1)	D.			10.5128	CaF _i	HF	1.950
See Gl.	Be			1.8485 1.0760	CaF ₁	H ₂ SiF ₂ NaF	0.541
1.6681	Bi	BiAsO ₄	0.5995	0.3459	Ca(HCO ₂) ₂	CaO	2.890
1.1154	Bi	Bi ₂ O ₂	0.8965	0.5429	Ca(HCO ₃) ₂ .	CO2	1.841
0.5994	BiAsO ₄	Bi	1.6683	0.4119	CaHPO	CaO	2.427
0.8017	BiOCl	Bi	1.2474	0.9338	CaHPO	Ca ₂ P ₂ O ₇	1.070
1.8658	BiOCl	Bi(NO ₂) ₂		0.5219	CaHPO	P ₂ O ₄	1.916
		5H ₂ O	0.5359	0.7175	$Ca(H_2PO_4)_2$	NaHCO ₁	1.393
0.8942	BiOCl	Bi ₂ O ₂	1.1184	0.6067	$Ca(H_2PO_4)_2$	P ₂ O ₃	1.648
1.1024	BiOCl	BiONO ₂	0.9072	1.0833	CaH ₂ P ₂ O ₇	Ca(H ₂ PO ₄) ₂	0.923
0.8965	Bi ₂ O ₂	Bi	1.1154	0.2594	CaH ₂ P ₂ O ₇	CaO	3.855
1.4955	Bi_2O_2	BiAsO ₄	0.6687	0.7773	CaH ₂ P ₂ O ₇ *	NaHCO ₂	1.286
1.2328	Bi ₂ O ₄	BiONO ₂	0.8112	0.6573	CaH ₂ P ₂ O ₇	$P_2O_1 \dots$	1.521
2.0867	Bi ₂ O ₂	Bi(NO ₂) ₂		$0.2773 \\ 0.6336$	Ca(HSO ₂) ₂	CaO .	3.606
	71.0	•5H ₂ O	0.4792	0.6336	Ca(HSO ₂) ₂	SO ₂	1.578
1.0691	Bi ₂ O ₂	Bi ₂ SO ₂	0.9354	0.6582	Ca(NO ₂) ₂	N ₂ O ₃	1.519
0.8122	Bi ₂ S ₂	Bi	1.2313	0.7146	CaO	Ca (CH ₂ CO ₂)	1.399
0.9059	Bi ₂ S ₄	Bi ₈ O ₈	1.1039	2.8204	CaO	Ca(CH ₂ CO ₂)	0.354
1.0400	n.	A	0.7400	1.9795 1.7847	CaO	CaCl ₂	0.505
1.3498	Br	Ag	0.7408	1.7047	CaO	CaCO ₂	0.560
1.7935	Br	AgCl	0.5576 0.4256	1.3924 2.8908	CaO CaO	CaF_1 $Ca(HCO_1)_1$	0.716
2.3498	Br	AgBr HBr	0.4230	4.1766	CaO	Ca(H ₂ PO ₄) ₂	0.239
1.0126	Br	0	9.9900	3.8553	CaO	CaH ₂ P ₂ O ₇	0.259
0.1001 0.8433	Br BrO ₂	Ασ	1.1858	3 6063	CaO	Ca(HSO ₂) ₂	0.277
1.4681	BrO ₂	AgBr	0.6811	3.6063 1.8446	CaO	Ca ₂ P ₂ O ₂	0.542
1.4001	DIO1	Agin	0.0011	2.1427	CaO	CaSO ₂	0.466
2.7699	Ca	CaCl	0.3610	2.1427 2.4280	ČaO	CaSO4	0.411
1.3993	Ča	CaO	0.7146	3.0707	CaO	CaSO · 2H ₂ O	0.325
1.7690	Ča	Čla	0.5653	2.1417	CaO	CH ₂ CO ₂ H	0.467
3.3973	Ca	CaSO ₄	0.2944	0.7848 1.7494	CaO	CO2	1.274
0.7800	Ca ₂ (AsO ₄) ₂	Mg2As2O7	1.2820	1.7494	CaO	[H ₂ SO ₄	0.571
0.3546	Ca(CH2CO2)2	CaO	2.8203	2.0852	CaO	NaCl	0.479
0.7594	Ca(CH ₂ CO ₂)	CH ₂ CO ₂ H	1.3169	1.8905	CaO	Na ₂ CO ₂	0.522
0.6202	Ca(CH ₂ CO ₂)	H ₂ SO ₄	1.6124	2.5336	CaO	Na ₂ SO ₄	0.394
0.9016	CaCl ₂	CaCO ₂	1.000	0.5718	CaO	<u>S.</u>	1.748
0.5052	CaCl ₂	CaO	1.9795	1.4280	CaO	SO ₂	0.700
1.2265	CaCl ₂	CaSO ₄	0.8153 1.5650	0.5421 0.7178	Ca ₂ P ₂ O ₈	CaOMg ₂ P ₂ O ₇	1.844
0.6390	CaCl	Cl2	1.5650		Ca.P.O	Mg ₂ P ₂ O ₇	1.393
0.4004	CaCO ₂	Ca	2.4975	12.0994	Ca ₂ P ₂ O ₈	(NH ₄),PO ₄	
1.1091	CaCO ₂	CaCl ₂	0.90161	A 4 7 8 A	a no	12MoO ₂	0.082
1.6197	CaCO ₂	Ca(HCO ₂) ₂	0.6174	0.4579	C84P2O2	P ₂ O ₂	2.183
0.5603	CaCO ₂	CaO	1.7847	3.2362 1.9429 0.4667	CaS	BaSO	0.309
0.4397	CaCO ₁	CO ₂	2.2743 0.7351	0 44429	CaSO ₂	BaSO ₄ CaO	0.514 2.142
1.3604	CaCO ₁	CaSO	0.7351	U.4007	CaSO ₂		
1.7204	CaCO ₁	CaSO 2H2O.	0.5813	1.7147	CaSO ₄	BaSO ₄	0.588
1.3810	CaCO ₂	K.CO	0.7241 0.9441	0 9159	CaSO ₄	CaCl ₂	1.226
1.0593	CaCO ₂	Na ₂ CO ₁	1.3720	0.8153 0.5735	CaSO ₄	CaF ₁	1.748
	1:01:11	HCl		V-07-00	UBDU4	Oarl	1.770
0.7288 0.7182	CaF ₂	AlF ₂	1.3925	0.4119	CaSO4	CaO	2.428

 $A \times A' = B$ $B \times B' = A$

	-					-	
A'	_A	В	В'	A'	A	В	B'
0.2791	Ca8O4	F	3.5824	0.2607	C.H.O.HK	H.SO	3.8370
0.2939	CaSO4	HF	8.4021	- 0.00			
0.7205 0.5881	CaSO	H,80,	1.3880	3.0423	Çl	Ag	0.3287
0.3257	CaSO ₄ 2H ₂ O	80 ₁	1.7003	4.0423	C1	AgClAgNO ₁	0.2474
0.8088	CaWO	WO ₂	1.2364	1.2547	Či	AICL	0.7970
				3.5726	Či	BaCrO4.	0.2799
1.4298	Сь	Cb ₂ O ₅	0.6995	2.6645 0.5653	Cl	CH ₂ ClCO ₃ H Ca	0.3753
1.6810	Çd	CdCl ₂	0.6131	1.5650	Čl ₂	CaCl.	0.6390
2.1083	Çd	Cd(NO ₂) ₃	0.4754	4.7454	Cl	I CaCl	0.2107
1.1423 1.2853	Cd	CdO	0.8754	0.5358	<u>Cl</u>	F	1.8663
1.8547	Cd	CdS	0.7780 0.5392	1.0284	<u>C</u> 1	HC1	0.9724
0.2853	Čď	CdSO ₄	3.5059	1.3831 3.5792	C1 C1	H-SO	0.7230
1.4277	CdO	CdCl ₂	0.7004	1.1027	ci	I K	0.2794
1.1251	I CdO	CdS	0.8888	2.1027	Či	KCI	0.4756
1.6235	CdO	CdSO₄	0.6159	3.4563	C1	IKCIO	0.2893
1.2690	CdS	CdCl ₂	0.7880	3.9075	<u>C</u> 1	KC104	0.2559
1.6365 1.4430	CdS	Cd(NO ₂) ₂	0.6110	0.1957	<u>C</u> 1	La	5.1095
0.2359	CdS	CdSO ₄ H ₂ S	0.6930 4.2393	0.3429 1.3429	C1	Mg MgCl ₂	2.9162
0.2220	CdS	8	4.5059	2.8672	Či	MgCl ₂ ·6H ₂ O.	0.7447 0.3488
-				0.5685	Či	MgO in	0.0400
2.1340	Ce	$Ce_2(C_1O_4)_2$ $3H_1O$	0 4000	1 0057	C)	MgCl _a	1.7590
2.7685	Ce	Ce(NO ₂) ₄	0.4686 0.3612	1.2257 0.6486	C1 C1	MnO ₂	0.8158 1.5417
4.0385	Če	Ce(NO ₂)	0.0012	1.6486	Ci	Na NaCl	0.6066
		(NH4NO2)2		3.0023	Ci	NaClO	0.3331
	_	O _r H·	0.2476	3.4535	<u>C</u> 1	NaClO4	0.2896
1.1711 1.2282	Ce	Ce ₂ O ₂	0.8539	0.5088	ÇI	NH.	1.9656
8.0648	Če	Ce(SO ₄) ₁	0.8142 0.3274	1.5088 0.2256	C1	NH Cl	0.6628 4.4325
2.2542	CeO ₁	Ce(NO ₁) ₄	0.4436	2.4098	Ci	Rb	0.4150
1.0487	Ce ₁ O ₂	CeO ₂	0.9536	3.4098	Či	RbCl	0.2933
2.3640	Ce ₁ O ₁	Ce(NO ₂) ₄	0.4230	0.8368	C1	Sn in SnCl	1.1949
0.9750	OTT CICO TT	<u> </u>	0.0045	1.8369	Cl	SnCl	0.5444
0.8758 0.5446	CH ₁ ClCO ₁ H . CH ₁ CHOH	C1	2.6645	3.9216 4.5572	C1	PbCl ₁	0.2550
J. UZZU	COH	H ₁ SO ₄	1.8366	2.6737	Ci	SnCl ₄	0.2194 0.3740
1.3169	CH.CO.H	$Ca(CH_1CO_2)_3$	0.7594	1.9217	Či	ZnCla	0.5204
1.8668	CH-CO-H	CH ₂ CO ₂ Na	0.7319	0.8934	ClO ₂	KCl	1.1194
0.8499	сн.сон	(CH ₂ CO) ₂ O	1.1766	1.7175	CIO	AgCl	0.5823
0.8167 0.8828	CH,CO,H	H ₂ SO ₄ Na ₂ CO ₂	1.2244	0.7005		NaCl	1.4276
0.5164	CH.CO.H	Na ₂ O	1.1327	1.4412 0.7496		AgCl	0.6939 1.3339
1.7255	CH.CO.H	Pb	0.5798	0.5878	ClO4	NaCl	1.7013
0.5979	CH ₂ CO ₂ Na	H-SO4	1.6729				
0.8779	CH ₂ CO ₂ Na	Na ₂ O	2.6463	4.1472	CN	AgAgCN	0.2411
0.8860	CH.CO.Na	Na ₃ SO ₄	1.1547	5.1472	CN	AgCN	0.1943
0.9609 1.0897	(CH ₁ CO) ₁ O	H ₂ SO ₄	1.0407 0.9177	2.8577 0.7240	CNS	AgCNS	0.3499
0.7782	CHO 2HO	H.SO4	1.2851	4.9361	Co	(ČN) _s S Co(NO _s) _s ·	1.3818
0.6537	C.H.O.	H.SO4	1.5298	210007		6H.0	0.2026
1,1197	C.H.O	NaHCO:	0.8931	7.6706	Co	Co(NO ₁)	
			<u> </u>			(KNO ₂) ₂	0.1304
							_

	<u> </u>		ï	i			
Α'	Λ	В	B'	Λ'	Λ	· B	В' ·
1.2714	Co	C ₀ O	0.7866	3.8476	CrO₂	PbCrO4	0.2599
1.3618	Co	Co ₂ O ₄	0.7343		CrO ₃	BaCrO	0.3947
2.6290	Co	CoSO4	0.3804	1.9420	CrO,	K ₂ CrO ₄	0.5149
4.7677	Co	CoSO4.7H2O	0.2097	1.4710	CrO ₂		0.6798
1.0711	C ₀ O	Co ₂ O ₄	0.9336	3.2320	CrO,	PbCrO	0.3094
6.0332	C ₀ O	Co(NO _s),		4.2526	Cr ₂ U ₂	PbCrO	0.2351
	}	(KNO ₂) ₂	0.1657	1.3158	Cr ₂ O ₂	CrO	0.7600
2.0679	C ₀ O	CoSO	0.4836	0.0070		CI .	0.7450
4.4853	CO ₂	BaCO ₂	0.2229	0.2670 1.2670	Cs	Cl CsCl	3.7453 0.7898
3.4853	CO2	BaO	0.2869	1.0602	Cs	Cs ₂ O	0.9432
2.9473	CO2	Ba(HCO ₂) ₂	0.3393		Cs	Cs ₂ CO ₂	0.8157
0.2727	CO2	C	3.6656		Cs	Cs ₁ SO ₄	0.7344
2.2743	CO2	CaCO ₁	0.4397	0.3945	Cs.PtCl	Cs	2.5359
1.8419	CO	Ca(HCO ₂).	0.5429	0.4182	Cs.PtCl	Cs ₂ O	2.3918
1.2743	ČO ₂	CaO	0.7847	1.1950	Cs ₁ O	CsCl	0.8368
0.6364	CO2	co	1.5713	1.2843	Cs ₂ O	Cs ₂ SO ₄	0.7786
8.9178	CO	CdCO ₂	0.2552	0.4998	Cs.PtCl	ČsČl	2.0015
1.3636	CO2	CO2	0.7333	0.4834	Cs ₂ PtCl ₅	C82CO2	2.0686
7.3997	CO2	C82CO2	0.1351	0.9305	Cs ₂ SO ₄	CsCl	1.0747
2.6327	CO ₁	FeCO ₂	0.3798	0.9003	Cs ₂ SO ₄	Cs ₂ CO ₂	1.1107
2.0220	CO2	Fe(HCO ₂) ₂	0.4951				
2.2287	CO2	H ₂ SO ₄	0.4487	1.2517	Cu	CuO	0.7989
3.1409	CO2	K ₂ CO ₃	0.3184	1.1258	Cu	Cu _z O	0.8882
2.1409	CO ₂	K₂O	0.4671	1.2522	Cu	Cu ₂ S	0.7986
1.6790	CO ₂	Li ₂ CO ₂	0.5956	2.5112	C u	CuSO	0.3982
1.5442	ÇO ₂	LiHCO	0.6476	3.9283	Cu	CuSO ₄ 5H ₂ O	0.2546
0.6790	CO	Li ₂ O	1.4727	0.5228	CuCNS	Cu	1.9137
1.9164	<u>C</u> O ₂	MgCO ₂	0.5218	0.6541	CuCNS	CuO	1.5286
1.6629	Ç0	$Mg(HCO_2)_2$	0.6013	2.0062	C uO	CuSO4	0.4985
0.9164	CO ₂	MgO	1.0913	1.2327	CuO	H.SO.	0.8112
2.6121	C O₂	MnCO ₁	0.3828 0.4973	3.1383 0.3353	CuO CuS	CuSO ₄ ·5H ₂ O	0.3186 2.9828
2.0108	CO ₃	Mn(HCO ₂) ₂ MnO	0.6203	0.9996	Cus	S CuO	1.0004
1.6119	CO ₂	Na ₂ CO ₂	0.0203	0.8991	Cu ₂ S	Cu ₂ O	1.1122
2.4089 1.9093	CO ₁	NaHCO,	0.5238	3.1371	Cu ₂ S	CuSO. 5H.O.	0.8188
8.2283	ČO,	Na ₂ SO ₄	0.3098	0.1011	Ougo		0.0100
1.4091	ČÖ,	Na ₂ O	0.7097	0.8746	Er ₂ O ₂	Er	1.1433
2.1836	čŏ	(NH ₄) ₂ CO ₂	0.4579				
6.0720	čŏ	PbCO	0.1647	2.4533	F	BaSiF	0.4076
5.2472	ČÖ,	Rb,CO,	0.1908	2.0545	F	CaF2	0.4868
8.3283	CO	RbHCO ₁	0.3006	3.5827	F	CaSO ₄	0.2791
4.2472	CO ₂	Rb ₂ O	0.2354	1.0531	F	HF	0.9496
8.3551	CO ₁	8rCO ₂	0.2981	1.2660	F	H ₂ SiF ₄	0.7899
2.3823	CO2	Sr(HCO ₂) ₂	0.4198	1.9342	F	K ₂ SiF ₄	0.5170
2.3550	CO ₂	SrO	0.4246	2.2105	F	NaF	0.4524
2.8493	CO ₂	ZnCO ₂	0.3510	1.6518	F	Na ₂ SiF ₄	0.6054
4.8725	Cr	BaCrO4	0.2052	2.2701	Fe	FeCl ₂	0.4405
1.4615	Čr	Cr.O	0.6842	2,9051	Fe	FeCl	0.8442
6.2154	Cr	PbCrO ₄	0.1609	4.8410	Fe	FeCl. 6H.O.	0.2066
8.7346	Cr	K ₁ CrO ₄	0.2678	3.1851	Fe	Fe(HCO ₂) ₂	0.8140
2.8288	Cr	K ₂ Cr ₂ O ₇	0.3535	1.2865	Fe	FeO	0.7778
3.0163	CrO ₂	BaCrO ₄	0.3315	1.4298	Fe	Fe ₂ O ₂	0.6094
1.1905	CrO ₂	CrO2	0.8400	1.3820	Fe	Fe ₂ O ₄	0.7236
		<u> </u>				·	

2.7020	A'	A	В	B'	A'	A	В	В'
1.6743 Fe	2.7020	Fe	FePO.	0.3701	0 8038	GoO.	Co	1 4414
2. 1483 Fe. FeS., 0. 44955 Fe. FeSO, 71140 0. 2008 3 .1881 GiO. GiCl. 0. 3137 3.8907 Fe. FeSO, 71140 0. 2008 3 .1881 GiO. GiCl. 0. 3137 3.8907 Fe. FeSO, (M.) 0. 2793 7 .0807 GiO. GiSO, 44140 0. 1416 Fe. FeSO, (M.) 0. 2793 7 .0807 GiO. GiSO, 44140 0. 1416 S. 2008 1.881 GiO. GiCl. 0. 3137 7.0225 Fe. FeSO, (M.) 1. 2793 7 .0807 GiO. GiSO, 44140 0. 1416 Fe. MacCro. 1. 2788 2. 3206 H.B. MacCro. 1. 2788 2. 3206 H.B. MacCro. 1. 2788 2. 3206 H.B. AgBr. 0. 4300 0. 3798 Fe. CO. CO. 2. 6327 3. 9305 H.C. AgCr. 0. 2.544 1. 6125 Fe. MacCro. 1. 2788 0. 9724 H.C. CaCO. 0. 7282 1. 6125 Fe. Fe(HCO). 1. CO. 2. 0220 1. 2893 H.C. H.NO. 0. 7762 1. 1114 Fe. Fe. Fe(HCO). 0. 4098 1. 7280 H.C. H.NO. 0. 7782 1. 1114 Fe. Fe. Fe(H.CO). 0. 4098 1. 1255 H.C. H.NO. 0. 5787 1. 1114 Fe. Fe. Fe(H.CO). 0. 4098 1. 1255 H.C. H.S.O. 0. 8885 Fe. Fe. Fe. Fe. O. 4761 1. 3448 H.C. H.S.O. 0. 8885 Fe. Fe. Fe. Fe. O. 4761 1. 3448 H.C. H.S.O. 0. 8885 Fe. Fe. Fe. Fe. O. 4761 1. 3448 H.C. H.S.O. 0. 6881 1. 2837 Fe. Fe. Fe. S. 0. 5989 1. 2915 H.C. K.C. 0. 4891 1. 1146 Fe. Fe. Fe. S. 0. 5989 1. 2915 H.C. K.C. 0. 4891 1. 1146 Fe. Fe. Fe. S. 0. 5989 1. 2915 H.C. K.C. 0. 4891 1. 1146 Fe. Fe. Fe. Fe. S. 0. 5989 1. 2915 H.C. K.C. 0. 4891 1. 1146 Fe. Fe. Fe. Fe. Fe. Fe. Fe. Fe. Fe. Fe.		Fe.	FeS			K.C.F.		
2.7205 Fe. FeSO, 0.3676 0.3626 GlO Gl. 2.7582 4.9789 Fe. FeSO, 71I,(1) 0.2008 3.1881 GlO GlCl, 0.3137 3.5807 Fe. FeSO, (NH,1); 7.0225 Fe. FeSO, (NH,1); 8.0,0H,0 0.1244 0.5638 H,BO, B,O, 1.7743 0.5643 Fe(titr. equiv.) HNO, 1.7721 1.3330 HBr. Ag. 0.7502 0.7820 Fe. Na _A Cr ₃ O. 1.2788 2.3206 HBr. AgBr. 0.4309 0.3798 FeCO, CO ₁ 2.6327 3.3935 HCl AgBr. 0.4309 0.4742 FeO Al ₂ O. 2.1088 0.9724 HCl CaCO, 0.7284 1.6125 FeO Fe(CO, 0.6202 1.2893 HCl HNO, 0.7786 1.1114 FeO Fe(O, 0.4701 1.3488 HCl HNO, 0.7786 1.1114 FeO Fe(O, 0.4701 1.3448 HCl HNO, 0.7877 1.1114 FeO Fe(O, 0.4701 1.3448 HCl HSO, 0.7838 1.1098 FeO FeSS, 0.5989 1.2255 HCl K,O 0.7438 1.1098 FeO FeSS, 0.5989 1.2015 HCl K,O 0.7733 1.1146 FeO FeSO, 0.4721 1.3030 HCl K,O 0.7733 1.3653 FeO H ₂ SS, 0.8172 2.0445 HCl K,O 0.6831 1.3653 FeO H ₂ SO, 0.4792 1.6030 HCl Na ₂ CO, 0.6881 1.3653 FeO, FeCO, 0.6892 1.3255 HCl Na ₂ CO, 0.6891 1.3653 FeO, FeCO, 0.6892 1.3255 HCl Na ₂ CO, 0.6891 1.3653 FeO, FeCO, 0.6892 1.3255 HCl Na ₂ CO, 0.6891 1.3653 FeO, FeCO, 0.6992 1.3016 HCl Na ₂ CO, 0.6891 1.3653 FeO, FeSSO, 0.5999 1.2015 HCl Na ₂ CO, 0.6891 1.3653 FeO, FeCO, 0.6892 1.3869 HCl Na ₂ CO, 0.6891 1.3653 FeO, FeCO, 0.6892 1.3869 HCl Na ₂ CO, 0.6891 1.3653 FeO, FeCO, 0.6892 1.3869 HCl Na ₂ CO, 0.6891 1.3653 FeO, FeCO, 0.6892 1.3869 HCl Na ₂ CO, 0.6891 1.3653 FeO, FeCO, 0.6892 1.3869 HCl Na ₂ CO, 0.6891 1.3653 FeO, FeCO, 0.6892 1.3869 HCl Na ₂ CO, 0.6891 1.3653 FeO, FeCO, 0.6892 1.3869 HCl Na ₂ CO, 0.6891 1.3653 FeO, FeCO, 0.6892 1.3869 HCl Na ₂ CO, 0.6891 1.3654 FeO, FeSO, 0.6686 HCl Na ₂ CO, 0.6891 1.3658 FeO, FeCO, 0.6893 1.3869 HCl H ₂ CO, 1.6891 1.3658 FeO, FeSO, 0.6893 1.3869 HCl H ₂ CO, 1.6891 1.3658 FeO, FeSO, 0.6893 1.3869 HCl H ₂ CO, 1.6891 1.3658 FeO, FeSO, 0.6893 1.3869 HCl H ₂ CO, 1.3861 1.3658 FeO, FeSO, 1.5056 1.9869 HCl Na ₂ CO, 0.9893 1.3659 HCl H ₂ CO, 1.6891 1.3869 HCl H ₂ CO, 1.3891 1.3653 FeO, 1.3860 HCl H ₂ CO, 1.3891 1.3653 HCl H ₂ CO, 1.3860 HCl H ₂ CO, 1.3891 1.3653 HCl H ₂ CO, 1.3860 HCl H ₂ CO, 1.3891 1.3653 HCl H ₂ CO, 1.3891 1.3653 HCl H ₂ CO, 1.3891		Fe	FeS.		0.2100	INCOME	<u> </u>	0.0010
1.00		Fe	FeS().		0 3838	CIO	CI	2 7500
3.8807 Fe. Fe,(SO ₄) 0.2793 7.0807 GiO. GiSO ₄ ·4H ₄ O. 0.1416 7.0225 Fe. FeSO ₄ (NH ₄). 0.1424 8.9363 H.B.O. B ₁ O ₁ 1.7743 0.5636 H ₁ B ₁ O ₂ 1.7743 0.3798 FeC.). 1.2788 2.3206 H ₁ B ₁ O ₂ 1.7743 H ₁ D ₂ 0.3798 FeC.). CO ₂ . 2.6327 3.9305 HCl. AgCl. 0.2544 0.4948 Fe(HCO ₂) CO ₃ . 2.6327 3.9305 HCl. AgCl. 0.2544 0.4948 Fe(HCO ₂) CO ₃ . 2.6327 3.9305 HCl. CaCO ₄ . 0.7288 0.4742 FeO. Al ₂ O ₁ . 2.1088 0.9724 HCl. Cl. 0.10294 1.114 FeO. FeCO ₁ . 0.6202 1.2893 HCl. HNO ₅ . 0.7788 2.4787 FeO. Fe(HCO ₃) 0.4039 1.7280 HCl. HNO ₅ . 0.7788 2.1002 FeO. FePO ₄ . 0.4761 1.3448 HCl. H ₃ SO ₄ . 0.5787 Hcl. 1.114 FeO. Fe ₂ O ₃ . 0.8989 1.1255 HCl. HNO ₅ . 0.8898 1.1255 HCl. H ₃ SO ₄ . 0.4891 1.6968 FeO. FeSO ₄ . 0.4729 1.6030 HCl. Na ₂ Cl. 0.4891 1.6968 FeO. FeSO ₄ . 0.4729 1.6030 HCl. Na ₂ Cl. 0.4891 1.6968 FeO. FeSO ₄ . 0.4729 1.6030 HCl. Na ₂ Cl. 0.4891 1.8853 FeO. H ₃ SO ₄ . 0.4729 1.6030 HCl. Na ₂ Cl. 0.6817 1.1146 FeO. SO ₄ . 0.4729 1.6030 HCl. Na ₂ Cl. 0.6817 1.1146 FeO. SO ₄ . 0.4729 1.6030 HCl. Na ₂ Cl. 0.6817 1.1146 FeO. SO ₄ . 0.8922 1.7861 HCl. SnCl ₄ . 0.5599 0.6400 FeO ₄ . FeCO ₄ . 0.4892 2.0588 HCNS AgCNS 0.3560 0.6817 1.4609 FeO ₄ . FeCO ₄ . 0.4892 2.0588 HCNS AgCNS 0.3560 1.8898 FeO ₄ . FeCO ₄ . 0.4891 1.6058 HCO ₃ . H ₃ SO ₄ . 0.5292 1.5028 FeO ₄ . FeCO ₄ . 0.6832 3.9510 HCNS AgCNS 0.3560 1.8898 FeO ₄ . FeCO ₄ . 0.6832 3.9510 HCNS AgCNS 0.2531 1.5028 FeO ₄ . FeCO ₄ . 0.6832 3.9510 HCNS AgCNS 0.2531 1.5028 FeO ₄ . FeSO ₄ . 0.5292 2.0589 HCNS AgCNS 0.03560 1.8898 FeO ₄ . FeSO ₄ . FeSO ₄ . 0.5292 1.5028 FeO ₄ . FeSO ₄ . 0.6648 FeS ₃ . 0.9661 1.8804 HCl. H ₃ SO ₄ . 0.2393 3.4822 FeO ₄ . FeSO ₄ . 0.6638 HCO ₃ . 0.4897 HF. CaF ₄ . 0.5126 HeO ₄ . H ₅ SO ₄ . 0.5292 1.5028 FeO ₄ . FeSO ₄ . 0.5292 1.5028 HCO ₃ . 0.6645 FeS ₃ . 0.6655 1.8908 HF. K ₃ SF ₄ . 0.5448 FeO ₄ . FeSO ₄ . 0.5292 1.5028 HGC. H ₃ SO ₄ . 0.5041 H ₃			FeSO. 711.0				CICI	
7.0225 Fe. FeSO ₄ (NH ₄) ₂ 0.5648 Fe(titr. SO ₄ 6H ₄ O) 0.1424 So ₄ 8 0.5636 H.Bo ₄ Bo ₄ O 0.7820 Fe. Na ₂ Cr ₄ O. 1 2788 2 3206 HBr Ag 0.7502 Ag 0.7820 Fe. Na ₂ Cr ₄ O. 1 2788 2 3206 HBr Ag 0.7502 O.3798 FeCO ₅ CO ₂ 2 6327 3 3905 HCI AgCI 0.2544 Ag 0.4448 Fe(HCO ₄) ₂ O. 2 0.220 1 3720 HCI CaCO ₃ 0.2544 0.4542 FeO 1.6125 FeO 1.6125 FeO 1.6125 FeO 1.6125 FeO 1.6125 FeO 1.6125 FeO 1.6125 FeO 1.6125 FeO 1.6125 FeO 1.6125 FeO 1.6125 FeO 1.6125 FeO 1.6125 FeO 1.6125 FeO 1.6125 FeO 1.6125 FeO 1.6125 FeO 1.6126 F			Fo.(S().)				CICI:	
0.5848 Fe(titr. equiv.)			For COUNTY	0.2180	7.0007	GIO	G1004.41120.	0.1410
0.5843		20		0 1494	8 0262	ш	шо	0 1110
0.7820	0 5842	Fe(titz	50401120	0.1424		11 BO		
0.7820 Fe. Na ₂ Cr ₁ O. 1 2788 2.3206 HBr. AgBr. 0.4309 0.3798 FeCO ₁ . CO ₂ . 2.6327 3.9305 HCl. AgCl. 0.2544 0.4948 Fe(HCO ₁) ₁ . CO ₁ . 2.0220 1.3720 HCl. CaCO ₄ . 0.7288 0.4742 FeO. Al ₁ O ₂ . 0.6020 1.2893 HCl. HCl. Cl. 1.0234 1.6125 FeO. FeCO ₁ . 0.6020 1.2893 HCl. HNO ₁ . 0.7786 2.4757 FeO. Fe(HCO ₁) ₂ . 0.4039 1.7280 HCl. HNO ₂ . 0.5785 2.1002 FeO. FeO ₂ . 0.8988 1.1255 HCl. HSO ₄ . 0.8875 2.1002 FeO. FePO ₄ . 0.4761 1.3448 HCl. HSO ₄ . 0.5885 2.1002 FeO. FeS ₂ . 0.5989 1.2015 HCl. KCl. 0.4981 1.2227 FeO. FeS ₃ . 0.5989 1.2015 HCl. KCl. 0.4981 1.2237 FeO. FeS ₃ . 0.5989 1.2015 HCl. KCl. 0.4981 1.2237 FeO. FeS ₃ . 0.5989 1.2015 HCl. KCl. 0.4981 1.2238 FeO. FeS ₃ . 0.5989 1.2015 HCl. KCl. 0.4891 1.233 S700 FeO. FeS ₃ . 0.5989 1.2015 HCl. KCl. 0.6239 1.3653 FeO. H ₈ SO ₄ . 0.7324 1.4869 HCl. Na ₂ Cl. 0.6239 1.3653 FeO. H ₈ SO ₄ . 0.7324 1.4869 HCl. Na ₂ Cl. 0.6831 1.3653 FeO. H ₈ SO ₄ . 0.7324 1.4869 HCl. Nh ₄ Cl. 0.6817 1.1146 FeO. SO ₄ . 0.8972 1.7861 HCl. SnCl ₄ . 0.5999 0.4400 Fe ₉ O ₄ . Al ₁ O ₂ . 1.5625 2.8089 HCNS. AgCNS. 0.3560 0.4400 Fe ₉ O ₄ . FeCO ₄ . 0.6892 2.0589 HCNS. AgCNS. 0.3560 2.0318 FeO ₇ . FeCO ₄ . 0.6892 3.9510 HCNS. BaSO ₄ . 0.2531 2.2277 FeO ₇ . FeCO ₄ . 0.5292 1.1011 Fe ₉ O ₇ . FeSO ₄ . 0.5292 1.1011 Fe ₉ O ₇ . FeSO ₄ . 0.5292 1.1011 Fe ₉ O ₇ . FeSO ₄ . 0.5292 1.1011 Fe ₉ O ₇ . FeSO ₄ . 0.5292 1.1011 Fe ₉ O ₇ . FeSO ₄ . 0.5292 1.1011 Fe ₉ O ₇ . FeSO ₄ . 0.5292 1.1011 Fe ₉ O ₇ . FeSO ₄ . 0.5293 1.4822 Fe ₉ O ₇ . FeSO ₄ . 0.5293 1.5028 Fe ₉ O ₇ . FeSO ₄ . 0.5293 1.5028 Fe ₉ O ₇ . FeSO ₄ . 0.5293 1.5028 Fe ₉ O ₇ . FeSO ₄ . 0.5293 1.5028 Fe ₉ O ₇ . FeSO ₄ . 0.5295 1.1015 Fe ₉ O ₇ . FeSO ₄ . 0.5295 1.1015 Fe ₉ O ₇ . FeSO ₄ . 0.5295 1.1016 Fe ₉ O ₇ . H ₈ SO ₄ . 0.5291 HF H ₈ Cl. H ₈ Cl. 0.8383 1.8664 FeS ₇ . BaSO ₄ . 0.5291 HF H ₈ Cl. H ₈ Cl. 0.8498 1.8676 FeO ₇ . FeSO ₄ . 1.5025 0.8863 HF H ₈ Cl. H ₈ Cl. 0.8498 1.8676 FeSO ₄ . H ₈ SO ₄ . 0.5295 1.1599 HI ₈ Cl. H ₈ Cl. 0.8498 1.1155 HeSO ₄ . H ₈ SO ₄ . 1.5487 1.1161 H ₈ SO ₄ . 1.1600 H ₈ Cl. H ₈ SO ₄ . 0.1890 1.1155 H ₈ Cl. H ₈ SO ₄ .	0.0020		HNO.	1 7791		HD.		
0. 3798 FeCO ₁ CO ₂ 2. 6327 3. 9305 HCl AgCl 0. 2544 0. 4948 Fe(HCO ₂) ₁ , CO ₂ 2. 0220 1.3720 HCl CaCO ₂ 0. 7248 1. 6125 FeO FeCO ₃ 0. 6202 1.2893 HCl HNO ₂ 0. 7756 0. 7758 1. 1125 FeO Fe(HCO ₂) ₂ 0. 4039 1.7280 HCl HNO ₂ 0. 5787 1. 1114 FeO Fe ₂ O ₃ 0. 8998 1. 1255 HCl HSO ₄ 0. 8835 1. 2237 FeO FePO ₄ 0. 4761 1. 3448 HCl H ₂ SO ₄ 0. 8835 1. 2237 FeO FeSO ₄ 0. 4761 1. 3448 HCl H ₂ SO ₄ 0. 4891 1. 6698 FeO FeS 0. 8172 2. 0445 HCl K ₂ O 0. 4781 1. 6698 FeO FeS 0. 8172 2. 0445 HCl K ₂ O 0. 7743 1. 3653 FeO FeSO ₄ 0. 4729 1. 6030 HCl NaCl 0. 6239 3. 8700 FeO FeSO ₄ 0. 7324 1. 4669 HCl Na ₂ CO ₄ 0. 6881 1. 3653 FeO H ₂ SO ₄ 0. 7324 1. 4669 HCl Na ₂ CO ₄ 0. 6881 1. 1146 FeO SO ₄ 0. 8972 1. 7861 HCl SnCl ₄ 0. 6817 1. 1146 FeO SO ₄ 0. 8972 1. 7861 HCl SnCl ₄ 0. 6519 0. 6400 Fe ₂ O ₄ Al ₂ O ₄ 1. 5625 2. 8089 HCNS AgCNS 0. 3500 0. 6400 Fe ₂ O ₄ Al ₂ O ₄ 1. 5625 2. 8089 HCNS AgCNS 0. 3500 0. 6400 Fe ₂ O ₄ Fe ₂ O	0.7820	Re	No.Cr.O.					
0.4948 Fe(HCO ₁) ₁ CO ₂ 2.0220 1.3720 HCl CaCO ₂ 0.7288 0.4742 FeO Al ₂ O ₁ 2.1088 0.9724 HCl Cl 1.0284 1.6125 FeO FeCO ₂ 0.6202 1.2893 HCl HNO ₂ 0.7756 0.7756 0.24757 FeO Fe(HCO ₂) ₂ 0.4039 1.7280 HCl HNO ₂ 0.5787 1.1114 FeO Fe ₂ O ₂ 0.8998 1.255 HCl H ₂ SO ₄ 0.5885 0.5272 1.2287 FeO FeS 0.4761 1.3448 HCl H ₂ SO ₄ 0.7436 1.2287 FeO FeS 0.8172 2.0445 HCl KCl 0.4891 1.225 HCl KCl 0.4891 1.3653 FeO FeSO ₄ 0.4729 1.6030 HCl Na ₂ CO ₄ 0.6831 1.3433 FeO H ₂ SO ₄ 0.7324 1.4669 HCl Na ₄ CO ₄ 0.6831 1.1146 FeO SO ₄ 0.5292 1.7861 HCl SnCl ₄ 0.5599 1.2016 HCl SnCl ₄ 0.5599 1.2016 HCl SnCl ₄ 0.5590 1.2016 HCl SnCl ₄ 0.5591 1.4509 FeO ₄ FeCl ₄ 0.4892 2.0589 HCNS CuCNS 0.4857 0.9666 FeO ₄ FeO ₄ 1.0346 1.0658 HCNS CuCNS 0.4857 0.9666 FeO ₄ FeSO ₄ 0.5292 1.5028 FeO ₄ FeSO ₄ 0.5292 1.5028 FeO ₄ FeSO ₄ 0.5292 1.5028 FeO ₄ FeSO ₄ FeSO ₄ 0.5263 4.9118 FeO ₄ FeSO ₄ 0.5263 0.9082 2.3297 HF BaSiF ₅ 0.4292 1.5028 FeO ₄ FeSO ₄ FeSO ₄ 0.5263 1.5908 HF Fe FeO ₄ FeSO ₄ 0.5264 HF H ₂ SO ₄ 0.2301 HF H ₂ SO ₄ 0.2301 HF H ₂ SO ₄ 0.4080 0.3993 3.6065 HF H ₂ SO ₄ 0.4292 1.5034 HF H ₂ SO ₄ 0.5318 HF H ₂ SO ₄ 0.4080 0.4080 1.5041 H ₂ SO ₄ 0.5262 1.3026 HF H ₂ SO ₄ 0.4080 0.3083 1.5091 H ₂ FeO ₄ FeSO ₄ H ₂ SO ₄ 0.2361 H ₂ FeO ₄ H ₂ SO ₄ 0.4080 0.3933 1.6065 HF H ₂ SO ₄ 0.4080 0.3933 1.6065 HF H ₂ SO ₄ 0.4080 0.3083 1.5091 H ₂ FeO ₄ H ₂ SO ₄ 0.4080 0.4080 1.1165 H ₂ SO ₄ H ₂ SO ₄ 0.4080 0.4080 H ₂ SO ₄								
0.4742 FeO		Fa(HCO.)	CO.	2.0021			Agol	
1. 6125 FeO FeCO ₁ 0. 6202 1. 2893 HCI HNO ₁ 0. 7758 2. 4757 FeO Fe(HCO ₂) ₂ 0. 4039 1. 7280 HCI HNO ₄ 0. 5787 1. 1114 FeO Fe ₂ O ₂ 0. 8998 1. 1255 HCI H ₂ SO ₄ 0. 8898 2. 1002 FeO Fe ₂ O ₂ 0. 4761 1. 3448 HCI H ₂ SO ₄ 0. 7438 1. 2227 FeO FeS ₃ 0. 5989 1. 2215 HCI KCI 0. 4891 1. 2227 FeO FeS ₄ 0. 5989 1. 2215 HCI K ₂ O 0. 7743 2. 1146 FeO FeSO ₄ 0. 4729 1. 6030 HCI NaCI 0. 6239 3. 8700 FeO FeSO ₄ 0. 4729 1. 6030 HCI NaCI 0. 6239 1. 3653 FeO H ₂ SO ₄ 0. 2584 1. 4669 HCI N ₄ CO ₄ 0. 6881 1. 3653 FeO H ₂ SO ₄ 0. 0. 8972 1. 7861 HCI SnCl ₄ 0. 5599 1. 1146 FeO SO ₄ 0. 0. 8972 1. 7861 HCI SnCl ₄ 0. 5599 1. 1460 Fe ₂ O ₄ 1. 15625 2. 8089 HCNS AgCNS 0. 3560 2. 0318 Fe ₂ O ₄ FeCO ₄ 0. 6892 2. 0318 Fe ₂ O ₄ FeCO ₄ 0. 6892 2. 2277 Fe ₃ O ₄ Fe ₄ O ₄ 0. 6892 2. 2277 Fe ₄ O ₄ Fe ₅ O ₄ 0. 1.0346 2. 9086 Fe ₂ O ₄ Fe ₅ O ₄ 0. 1.0346 2. 9086 Fe ₂ O ₄ Fe ₅ O ₄ 0. 1.0346 2. 9086 Fe ₂ O ₄ Fe ₅ O ₄ 0. 1.0346 2. 9086 Fe ₂ O ₄ Fe ₅ O ₄ 0. 1.0346 2. 9096 Fe ₅ O ₄ Fe ₅ O ₄ 0. 5252 3. 4822 Fe ₅ O ₄ Fe ₅ O ₄ 0. 5253 3. 4822 Fe ₅ O ₄ Fe ₅ O ₄ 1. 0. 5256 3. 4021 3. 4911 Fe ₅ O ₅ FeS ₅ 0. 9082 2. 5041 Fe ₅ O ₄ FeSO ₄ 7H ₅ O 0. 2872 3. 4822 Fe ₅ O ₄ FeSO ₄ 7H ₅ O 0. 2872 3. 4822 Fe ₅ O ₄ FeSO ₄ 7H ₅ O 0. 2872 3. 4822 Fe ₅ O ₄ FeSO ₄ 7H ₅ O 0. 2872 3. 4822 Fe ₅ O ₄ FeSO ₄ 7H ₅ O 0. 2872 3. 4822 Fe ₅ O ₄ FeSO ₄ 7H ₅ O 0. 2872 3. 4822 Fe ₅ O ₄ FeSO ₄ 7H ₅ O 0. 2872 3. 4822 Fe ₅ O ₄ FeSO ₄ 7H ₅ O 0. 2872 3. 4822 Fe ₅ O ₄ FeSO ₄ 7H ₅ O 0. 2872 3. 4822 Fe ₅ O ₄ FeSO ₄ 7H ₅ O 0. 2872 3. 4823 FeSO ₄ 7H ₅ O 0. 11 ₃ SO ₄ 0. 5256 3. 4021 HF CaSO ₄ 7H ₅ O 0. 2872 3. 4822 Fe ₅ O ₄ FeSO ₄ 7H ₅ O 0. 2872 3. 4823 Fe ₅ O ₄ FeSO ₄ 7H ₅ O 0. 2872 3. 4824 FeS 1. 185O ₄ 0. 3898 3. 4825 Fe ₅ O ₄ FeSO ₄ 7H ₅ O 0. 2872 3. 4826 FeSO ₄ 7H ₅ O 0. 11 ₃ SO ₄ 0. 5256 3. 4021 HF CaSO ₄ 7H ₅ O 0. 2883 3. 4827 Fe ₅ O ₄ FeSO ₄ 7H ₅ O 0. 2883 3. 4828 FeSO ₄ 7H ₅ O 0. 11 ₃ SO ₄ 0. 5487 3. 1160 HR FeSO ₄ 7H ₅ O 0. 1185O ₄ 0. 2026 3. 3448 FeS 1. 185O ₄ 0. 3896 3. 1160 HR FeSO ₄ 7H ₅ O 0. 1185O ₄			ALÓ.				Cl	
2.4757 FeO Fe(HCO) ₂ : 0.4039 1.7280 HCl HNO ₃ : 0.5787 1.1114 FeO FeO, 0.4761 1.3448 HCl H ₃ SO, 0.8885 1.2227 FeO FeS 0.8172 2.0445 HCl K ₅ Cl 0.4891 1.2265 HCl H ₃ SO, 0.7436 1.2227 FeO FeS 0.8172 2.0445 HCl K ₅ Cl 0.4891 1.6698 FeO FeS, 0.5989 1.2915 HCl K ₅ Cl 0.4891 1.6698 FeO FeS, 0.5989 1.2915 HCl K ₅ Cl 0.4891 1.6698 FeO FeSO, 0.4729 1.6030 HCl Na ₅ CO, 0.6881 1.3653 FeO H ₃ SO, 0.7324 1.4533 HCl Na ₅ CO, 0.6881 1.1166 FeO SO ₄ 0.7824 1.4533 HCl Na ₅ CO, 0.6881 1.1166 FeO SO ₄ 0.8972 1.7861 HCl Nh ₄ Cl 0.6817 1.11146 FeO SO ₄ 0.8972 1.7861 HCl Nh ₄ Cl 0.6817 1.11146 FeO SO ₄ 0.4922 2.0818 Fe ₃ O ₄ Fe ₅ O ₄ 1.5625 2.8089 HCNS AgCNS 0.3560 0.4600 Fe ₅ O ₄ A ₅ Co ₄ 1.00 1.5925 2.8089 HCNS CuCNS 0.4857 1.4509 Fe ₅ O ₄ Fe ₅ O ₄ 1.00 4922 2.0589 HCNS CuCNS 0.4857 1.4509 Fe ₅ O ₄ Fe ₅ O ₄ 1.0346 1.0346 1.0358 HCO ₂ H H ₃ SO ₄ 0.2531 1.5018 Fe ₅ O ₄ Fe ₅ O ₄ 1.6940 0.5922 1.1011 Fe ₅ O ₅ Fe ₅ O ₄ Fe ₅ O ₄ 0.4489 1.8988 Fe ₅ O ₄ Fe ₅ O ₄ Fe ₅ O ₄ 0.5922 1.1011 Fe ₅ O ₅ FeS ₅ 0.6655 1.9508 HCO ₂ H H ₃ SO ₄ 0.2939 1.5028 Fe ₅ O ₄ Fe ₅ O ₄ FeS ₅ 0.6655 1.9508 HF CaF ₇ 0.5126 1.9027 Fe ₅ O ₄ FeS ₅ 0.6655 1.9508 HF CaF ₇ 0.5126 1.9027 Fe ₅ O ₄ FeS ₅ O ₄ 0.2872 0.4946 HF F CaSO ₄ 0.2939 Fe ₅ O ₄ Fe ₅ O ₄ FeS ₅ O ₄ 0.2872 0.4946 HF F CaSO ₄ 0.2939 Fe ₅ O ₄ Fe ₅ O ₄ FeS ₅ O ₄ 0.2872 0.4946 HF F CaSO ₄ 0.2939 Fe ₅ O ₄ Fe ₅ O ₄ FeS ₅ O ₄ 0.2872 0.4946 HF F CaSO ₄ 0.2939 Fe ₅ O ₄ Fe ₅ O ₄ 1.1 ₅ SO ₄ 0.3993 0.665 HF(2HF) H ₅ SiF ₄ 0.5444 FeS ₆ 1.1 ₅ SO ₄ 0.3993 0.665 HF(2HF) H ₅ SiF ₄ 0.5444 FeS ₆ 1.1 ₅ SO ₄ 0.3993 0.665 HF(2HF) H ₅ SiF ₄ 0.5444 FeS ₆ 1.1 ₅ SO ₄ 0.3993 1.1599 Hg Hg HgO ₄ 0.9281 1.155 FeS ₆ H ₅ SO ₄ 0.3968 1.1599 Hg HgC 1.1600 0.8837 FeS ₆ 1.15SO ₄ 0.3968 Hg HgO ₄ 0.9281 1.1670 0.3688 FeS ₆ 1.18SO ₄ 1.15025 0.9856 HgC 1.18G ₆ 1.1670 0.3688 FeS ₆ 1.18SO ₄ 1.18SO ₄ 1.18SO ₄ 1.18DO ₄			F _e CO.					
1.1114 FeO FeO, 0.8998 1.1255 HCI. II.SO, 0.8885 1.2237 FeO FeB, 0.4761 1.3448 HCI. II.SO, 0.7436 1.2237 FeO FeB, 0.8172 2.0445 HCI. K.C. 0.4891 1.6698 FeO FeS, 0.5989 1.2015 HCI. K.C. 0.4891 1.6698 FeO FeS, 0.5989 1.2015 HCI. K.C. 0.4761 1.3468 HCI. II.SO, 0.7743 1.6698 FeO FeSO, 0.4729 1.6630 HCI. NaCI. 0.6239 3.8700 FeO FeSO, 0.4729 1.4533 HCI. NaCI. 0.6239 1.3653 FeO H.SO, 0.8072 1.7861 HCI. NR.CI. 0.6817 1.1146 FeO SO, 0.8072 1.7861 HCI. SnCI. 0.5599 0.6400 FeO, Al.O, 1.5625 2.8089 HCNS. AgCNS. 0.3560 2.2318 FeO, FeCO, 0.6892 3.9510 HCNS CaCNS. 0.3560 2.2277 FeO, FeCO, 0.6892 3.9510 HCNS BaSO, 0.2531 1.8898 FeO, FeCO, 0.6892 3.9510 HCNS BaSO, 0.2531 1.8898 FeO, FeCO, 0.6892 3.9510 HCNS BaSO, 0.2531 1.5028 FeO, FeSO, 0.6655 1.9027 FeO, FeSO, 0.6655 1.9028 HF CAF, 0.5126 1.9027 FeO, FeSO, 0.6655 1.9028 HF CAF, 0.5126 1.9027 FeO, FeSO, 0.6655 1.9028 HF CAF, 0.5126 1.9027 FeO, FeSO, 0.9082 2.3297 HF BASIF, 0.4292 1.5028 FeO, FeSO, 0.9082 2.3297 HF CASO, 0.2939 3.4822 FeO, FeSO, 0.9082 2.3297 HF CASO, 0.2939 3.4822 FeO, FeSO, 0.9082 2.3297 HF CASO, 0.2939 3.4822 FeO, FeSO, 0.9082 1.9086 HF CAF, 0.5126 1.9027 FeO, FeSO, 0.5256 3.4021 HF CASO, 0.2939 3.4822 FeO, FeSO, 0.9082 1.908 HF CASO, 0.2939 HF CASO, 0.2939 FeO, 1.5630 1.5631 FeO, 1.5631 FeO, 1.5631 FeO, 0.8089 FeO, 0.8080 1.8368 Fe O, 1.6648 FeS, 1.6600 1.8364 FeS. BASO, 0.3766 1.3335 HF HGHF, H,SO, 0.4080 0.4708 FeSO, 1.850, 0.3664 FeS. BASO, 0.3766 1.3335 Hg Hg HgO, 0.9261 1.1155 FeS. H,SO, 0.8963 1.1569 Hg Hg HgS 0.9261 1.1155 FeS. H,SO, 0.8963 1.1569 Hg Hg HgS 0.9261 1.1156 FeSO, H,SO, 1.5487 0.5519 HgC HgSO, 1.860 HgC, HgSO, 1.8121 1.502 FeSO, 7H ₁ O, 1.8973 0.8694 HgC, HgC, 1.8121 0.521 FeSO, 1.850, 1.3890 1.0898 HgO HgC, 1.8121 0.9208 FeSO, 7H ₁ O, 1.8973 0.8694 HgC, HgC, 1.8121 0.9208 FeSO, 7H ₁ O, 1.8973 0.8694 HgC, HgC, 0.9176 1.1160 0.1114 FeSO, 1.1160 0.1114 FeSO, 1.1160 0.1114 FeSO, 1.1160 0.1114 FeSO, 1.1160 0.1114 FeSO, 1.1160 0.1114 FeSO, 1.1160 0.1114 FeSO, 1.1160 0.1114 FeSO, 1.1160 0.1114 FeSO, 1.1160 0.1114 FeSO, 1.1160 0.1114 FeSO, 1.11			Fe(HCO.).			HCI		
2 1002 FeO FePO			Fe ₀ () ₂					
1. 2237 FeO. FeS. 0. 8172 2. 0445 HCl. KCl. 0. 4891 1. 6698 FeO. FeS. 0. 5989 1. 2915 HCl. K ₂ O. 0. 7743 2. 1146 FeO. FeSO. 0. 4729 1. 6630 HCl. NaCl. 0. 6239 3. 8700 FeO. FeSO. 71k ₂ O. 0. 2524 1. 4533 HCl. Na ₂ CO. 0. 6881 1. 3653 FeO. H ₃ SO. 0. 7324 1. 4669 HCl. Nh ₄ Cl. 0. 6817 1. 1146 FeO. SO. 0. 8972 1. 78811 HCl. SnCl. 0. 5599 0. 6400 Fe ₃ O. Al ₂ O. FeCl. 0. 4922 2. 0589 HCNS. AgCNS. 0. 3560 2. 0318 Fe ₃ O. FeCl. 0. 4922 2. 0589 HCNS. AgCNS. 0. 3560 2. 2277 Fe ₃ O. FeCl. 0. 4922 2. 0589 HCNS. CuCNS. 0. 44857 0. 9666 Fe ₃ O. Fe ₄ O. Fe ₄ Cl. 0. 4499 1. 0652 1. 0658 Fe ₅ O. Fe ₅ O. Fe ₇ O. 0. 6449 1. 0346 1. 0658 Fe ₇ O. Fe ₇ O. Fe ₇ O. 0. 0. 6891 1. 0658 Fe ₇ O. Fe ₇ O. Fe ₇ O. 0. 0. 0. 0. 0. 0. 0. 0. 0. 0. 0. 0. 0.			FePO.		1 2449			
1 6698 FeO FeS, 0 5989 1 2915 HCl K ₂ O 0 7743 2 1146 FeO FeSO, 0 4729 1 6030 HCl NaCl 0 6239 3 8700 FeO FeSO, 711 ₂ O 0 2584 1 4583 HCl Na ₂ CO, 0 6881 1 3653 FeO H ₂ SO, 0 7324 1 4669 HCl NH ₂ Cl 0 6881 1 1146 FeO SO ₁ 0 8972 1 7861 HCl SnCl ₄ 0 5599 0 6400 Fe ₃ O ₁ Al ₂ O ₁ 1 5625 2 8089 HCNS AgCNS 0 3560 2 0318 Fe ₃ O ₁ FeCl ₁ 0 4922 2 0.689 HCNS AgCNS 0 3560 2 0318 Fe ₃ O ₁ FeCl ₁ 0 6892 3 9510 HCNS BaSO ₄ 0 2531 2 2277 Fe ₃ O ₁ Fe ₄ O ₁ 1 6030 HCNS BaSO ₄ 0 2531 2 2277 Fe ₅ O ₁ Fe ₄ O ₁ 1 6030 HCNS BaSO ₄ 0 2531 2 2277 Fe ₅ O ₁ Fe ₅ O ₄ 1 6030 HCNS BaSO ₄ 0 2531 1 1011 Fe ₃ O ₁ Fe ₅ O ₄ 0 5292 1 1011 Fe ₃ O ₁ FeSS 0 9082 2 3297 HF BaSiF ₆ 0 4292 1 1011 Fe ₃ O ₁ FeSS 0 9082 2 3297 HF BaSiF ₆ 0 4292 1 1011 Fe ₃ O ₁ FeSO ₄ 1 6035 1 9508 HF CaF ₂ 0 5126 1 9027 Fe ₃ O ₁ FeSO ₄ 0 5292 1 1012 Fe ₃ O ₁ FeSO ₄ 1 6030 HF FeSO ₄ 1 10531 4 9118 Fe ₃ O ₁ FeSO ₄ 1 18SO ₆ 0 5272 0 9496 HF F CaF ₂ 0 5126 1 9027 Fe ₃ O ₁ FeSO ₄ 1 18SO ₆ 0 5427 1 15041 Fe ₃ O ₁ FeSO ₄ 1 18SO ₆ 0 5427 2 25041 Fe ₃ O ₁ Fe ₅ O ₁ 1 18SO ₆ 0 5427 1 15041 Fe ₃ O ₁ FeSO ₄ 1 18SO ₆ 0 3993 3 6065 HF (2HF) H ₂ SiF ₆ 0 2773 1 15041 Fe ₅ O ₁ SO ₁ 0 6648 2 2 6554 FeS BaSO ₄ 0 3766 1 3335 HF (2HF) H ₂ SiF ₆ 0 2492 2 6554 FeS BaSO ₄ 0 3766 1 3335 Hg Hg HgO 0 9261 1 1155 FeS H ₃ S 1 1590 Hg Hg HgO 0 9261 1 1155 FeS H ₃ S 2 5795 1 0798 Hg Hg HgO 0 9261 1 1155 FeS H ₃ S 2 5795 1 0798 Hg HgCl ₂ HgS 0 8622 0 3648 FeS S 2 7417 1 1125 HgCl HgS 10146 0 5346 FeS ₃ Fe ₆ O ₄ H ₅ SO ₄ 1 5487 0 5519 HgCl HgS 1 1046 0 5346 FeS ₃ S 1.8709 0 4017 HgCl SnCl ₂ 2 4898 0 6654 FeS ₃ Fe ₆ O ₄ H ₅ SO ₄ 1 5487 0 5519 HgCl HgS 1 1670 0 7388 Fe ₆ SO ₄ H ₅ SO ₄ 1 5487 0 5519 HgCl HgS 1 1690 0 7388 Fe ₆ SO ₄ H ₅ SO ₄ 1 5890 1 1890 1 HgCl HgS 1 1690 0 7389 Fe ₆ SO ₄ H ₅ SO ₄ 1 1590 1 10898 HgO HgCl ₃ 1 1670 0 7388 Fe ₆ SO ₄ H ₅ SO ₄ 1 1590 1 10898 HgO HgCl ₃ 1 1670 0 7388 Fe ₆ SO ₄ H ₅ SO ₄ 1 1590 1 10898 HgO HgCl ₃ 1 1670 0 7389 Fe ₆ SO ₄ H ₅ SO ₄ 1 1580 1 1380 1 1380 1 1380 1 1380 1 1380 1 1380 1 1380 1			FeS					
2.1146 Fe0. FeSO. 0.4729 1.6030 HCl. NaCl. 0.6330 3.8700 FeO. FeSO. 1.400 0.2584 1.4533 HCl. Na ₂ CO ₁ 0.6881 1.3653 FeO. H ₃ SO ₄ 0.7324 1.4569 HCl. NH ₄ Cl. 0.6817 1.1146 FeO. SO ₁ 0.8972 1.7861 HCl. SnCl ₄ 0.5599 0.6400 Fe ₃ O ₅ FeCl ₄ 0.40 ₂ 2.0589 HCNS AgCNS 0.3560 0.6401 Fe ₄ O ₄ FeCl ₄ 0.4922 2.0589 HCNS AgCNS 0.3560 0.6402 Fe ₄ O ₅ FeCl ₄ 0.4922 2.0589 HCNS CuCNS 0.4857 1.4509 Fe ₄ O ₄ Fe ₆ O ₅ Fe ₆ O ₄ 1.3466 HCl. SnCl ₄ 0.2531 2.2277 Fe ₇ O ₄ Fe ₆ O ₄ 1.0346 1.0658 1.8898 Fe ₇ O ₅ Fe ₇ O ₄ Fe ₇ O ₄ 0.5292 1.1011 Fe ₇ O ₅ FeS 0.9082 2.3297 HF BaSiF ₆ 0.4292 1.5028 Fe ₆ O ₅ FeSS 0.6655 1.9508 HF CaF ₇ 0.5126 1.9027 Fe ₇ O ₄ FeSO ₄ 0.5256 3.4021 HF CaSO ₄ 0.2939 3.4822 Fe ₇ O ₅ FeSO ₄ 0.5256 3.4021 HF CaSO ₄ 0.2939 3.4822 Fe ₇ O ₅ FeSO ₄ 0.5266 3.4021 HF CaSO ₄ 0.2939 3.4822 Fe ₇ O ₅ FeSO ₄ 0.5267 1.2022 HF H ₅ SO ₄ 0.4800 2.5041 Fe ₇ O ₅ FeSO ₄ 0.5267 1.2022 HF H ₅ SiF ₆ 0.5444 2.5041 Fe ₇ O ₅ FeSO ₄ 0.3993 3.6065 HF H ₅ CHF H ₅ SiF ₆ 0.5444 2.5041 Fe ₇ O ₅ FeSO ₄ 0.5271 1.2022 HF(6HF) H ₅ SiF ₆ 0.5444 2.5041 Fe ₇ O ₅ FeSO ₆ 0.5271 1.2022 HF(6HF) H ₅ SiF ₆ 0.5444 1.5041 Fe ₇ O ₅ FeSO ₆ 0.5267 1.2022 HF(6HF) H ₅ SiF ₆ 0.5444 1.5041 Fe ₇ O ₅ H ₅ SO ₆ 0.5427 1.2022 HF(6HF) H ₅ SiF ₆ 0.5444 1.5041 Fe ₇ O ₅ H ₅ SO ₆ 0.5427 1.2022 HF(6HF) H ₅ SiF ₆ 0.5444 1.5041 Fe ₇ O ₅ H ₅ SO ₆ 0.5427 1.2022 HF(6HF) H ₅ SiF ₆ 0.5498 1.5041 Fe ₇ O ₅ H ₅ SO ₆ 0.5427 1.2022 HF(6HF) H ₅ SiF ₆ 0.5498 1.5041 Fe ₇ O ₅ H ₅ SO ₆ 0.5427 1.2022 HF(6HF) H ₅ SiF ₆ 0.5498 1.5041 Fe ₇ O ₅ H ₅ SO ₆ 0.5427 1.2022 HF(6HF) H ₅ SiF ₆ 0.5498 1.5041 Fe ₇ O ₆ H ₅ SO ₆ 0.5427 1.2022 HF(6HF) H ₅ SiF ₆ 0.5498 1.5041 Fe ₇ O ₆ H ₅ SO ₆ 0.5427 1.2022 HF(6HF) H ₅ SiF ₆ 0.5498 1.5041 Fe ₇ O ₆ H ₅ SO ₆ 0.5427 1.2022 HF(6HF) H ₅ SiF ₆ 0.5498 1.5041 Fe ₇ O ₆ H ₅ SO ₆ 0.5427 1.2022 HF(6HF) H ₅ SiF ₆ 0.5498 1.5041 Fe ₇ O ₆ H ₇ SO ₆ 0.5428 H ₇ SO ₆ 0.5428 H ₇ SO ₆ 0.5428 H ₇ SO ₆ 0.5426 H ₇ SO ₆ 0.5426 H ₇ SO ₆ 0.5426 H ₇ SO ₆ 0.5426 H ₇ SO ₆ 0.5426 H ₇ SO ₆ 0.5426 H ₇ S							K-O	
1.3653 FeO			FeSO.			HCi	NaCl	
1.3653 FeO			FeSO 7H.O.			HCi	Na CO.	
1 1146 FeO	1.3653		H.SO				NHCI	
0.6400 Fe ₂ O ₁ Al ₂ O ₂ 0.4922 2.0589 HCNS AgCNS 0.3560 0.4957 4509 Fe ₂ O ₃ Fe _C O ₄ 0.6892 3.9510 HCNS BaSO ₄ 0.2531 0.9666 Fe ₂ O ₃ Fe ₂ O ₄ 0.5292 0.5256 0.4021 0.5256 0.5256 0.5256 0.4021 0.5256	1.1146	FeO	SO					
2.0318 Fe ₃ O ₁ FeCU ₁ 0.4922 2.0589 HCNS CuCNS 0.4857 1.4509 Fe ₃ O ₁ Fe(HCO ₃) ₂ 0.4849 0.2531 HCNS BaSO ₄ 0.2531 1.898 Fe ₅ O ₁ Fe ₅ O ₄ 1.0346 1.0658 HCO ₂ H H ₂ SO ₄ 0.9383 1.898 Fe ₅ O ₁ FeSO ₄ 0.5292 0.3292 1.1011 Fe ₅ O ₃ FeS 0.0655 1.9508 HF CaF ₂ 0.5126 1.9027 Fe ₅ O ₁ FeSO ₄ 0.5256 3.4021 HF CaSO ₄ 0.2939 3.4822 Fe ₅ O ₁ FeSO ₄ 7H ₅ O 0.2872 0.9496 HF F 1.0531 Fe ₅ O ₄ Fe ₅ O ₄ Fe ₅ O ₄ Fe ₅ O ₄ 0.2036 1.8368 HF H ₂ SO ₄ 0.4080 1.5044 Fe ₅ O ₄ H ₂ SO ₄ 0.5427 1.2022 HF(6HF) H ₂ SiF ₆ 0.2773 1.8428 Fe ₅ O ₄ H ₂ SO ₄ 0.5427 1.2022 HF(6HF) H ₂ SiF ₆ 0.8318 1.5041 Fe ₅ O ₄ P ₄ O ₄ 2.1239 1.768 Hg HgCl ₂ 0.7388 0.3877 FeS H ₂ SO ₄ 0.3766 1.3535 Hg HgCl ₂ 0.7388 0.3877 FeS H ₂ SO ₄ 0.3963 1.15041 FeSO ₄ 0.3963 1.15041 Hg HgCl ₂ 0.7388 0.3648 FeS S H ₂ SO ₄ 0.3963 1.1509 Hg HgCl ₂ 0.9861 HgS 0.5271 1.5025 0.9856 HgCl ₂ HgS 0.8622 0.3648 FeS S 1.5025 0.9856 HgCl ₂ HgS 1.0146 0.5271 FeSO ₄ H ₂ SO ₄ 1.5487 0.5519 HgCl ₂ HgS 1.1502 0.3528 Fe ₅ O ₄ H ₂ SO ₄ 1.3590 1.8973 0.8694 HgCl ₂ HgS 1.1502 0.7388 0.1114 FeSO ₄ H ₂ SO ₄ 1.3590 1.0880 HgCl ₂ HgS 1.1670 0.7358 0.1114 FeSO ₄ H ₂ SO ₄ 1.3590 1.0880 HgCl ₂ HgCl ₂ 0.9208 HgCl ₂	0.6400					HCNS	ArCNS	
1.4509 Fe ₀ O ₁ Fe _C O ₁ O.4892 3.9510 HCNS BaSO ₄ 0.2531 0.9666 Fe ₀ O ₂ Fe ₀ O ₄ 0.4898 1.0658 HCO ₂ H H ₂ SO ₄ 0.9383 1.8898 Fe ₅ O ₃ Fe _F O ₄ 0.5292 1.1011 Fe ₀ O ₃ Fe _S 0.6655 1.9508 HF BaSiF ₆ 0.4292 1.5028 Fe ₉ O ₃ Fe _S O ₄ 0.6655 1.9508 HF CaF ₂ 0.5126 1.9027 Fe ₉ O ₃ Fe _S O ₄ 0.5256 3.4021 HF CaSO ₄ 0.2939 3.4822 Fe ₉ O ₃ Fe _S O ₄ 7H ₂ O 0.2872 0.9496 HF F 1.0531 4.9118 Fe ₇ O ₄ Fe _S O ₄ O.2036 1.8368 HF H ₂ SO ₄ 0.4080 2.5041 Fe ₇ O ₅ Fe _S O ₄ 0.2036 1.8368 HF H ₂ SO ₄ 0.4080 2.5041 Fe ₇ O ₅ Fe _S O ₄ 0.5427 1.2022 HF(6HF) H ₂ SiF ₆ 0.5444 5O ₄ Fe ₇ O ₄ O.6648 0.4708 Fe ₇ O ₄ P ₁ O ₄ 2.1239 1.1768 Hg HgCl ₂ 0.7388 0.4877 Fe _S H ₂ SO ₄ 0.3766 1.3535 Hg HgCl ₂ 0.7388 0.3877 Fe _S H ₂ SO ₄ 0.8963 1.1509 Hg HgCl ₂ 0.7388 0.3877 Fe _S H ₂ SO ₄ 0.8963 1.1509 Hg HgCl ₂ 0.7388 0.3877 Fe _S H ₂ SO ₄ 0.8963 1.1509 Hg HgCl ₂ 0.9261 1.1155 Fe _S H ₂ SO ₄ 0.8963 1.1509 Hg HgCl ₂ 0.9261 1.1155 Fe _S H ₂ SO ₄ 0.8963 1.1509 Hg HgCl ₂ 0.9261 1.1157 Fe _S O ₄ H ₂ SO ₄ 0.8963 1.1509 Hg HgCl ₂ 0.8989 0.8648 Fe _S S 2.7417 1.125 HgNO ₂ 0.8989 0.6654 Fe _S S 1.8709 0.4017 HgCl SnCl ₄ 1.8121 0.5271 Fe _S O ₄ H ₂ SO ₄ 1.5487 0.5519 HgCl HgS 1.1670 0.7358 Fe _S O ₄ H ₂ SO ₄ 1.3590 1.8989 HgCl ₃ HgCl ₃ 0.9176 0.7358 Fe _S O ₄ H ₂ SO ₄ 1.3590 1.0898 HgCl ₃ HgCl ₃ 0.9176 0.7358 Fe _S O ₄ H ₂ SO ₄ 1.3690 1.0890 HgCl ₃ HgCl ₃ 0.9176 0.7450 Ga ₄ O ₁ Ga 1.3424 1.3952 HgS Hg(NO ₃) 0.8860 0.7450 Ga ₄ O ₁ Ga 1.3424 1.3952 HgS Hg(NO ₃) 0.8860			FeCh				CuCNS	
2.2277 Fe ₁ O ₁ Fe ₁ HCO ₂) ₂ 0.4489 1.0658 HCO ₂ H H ₂ SO ₄ 0.9383 1.8988 Fe ₂ O ₂ Fe ₂ O ₄ 1.0346 1.0658 HCO ₂ H H ₂ SO ₄ 0.9383 1.1011 Fe ₃ O ₃ Fe ₈ S 0.9082 2.3297 HF BaSiF ₆ 0.4292 1.5028 Fe ₉ O ₁ Fe ₈ S 0.6655 1.9508 HF CaF ₂ 0.5126 1.9027 Fe ₉ O ₁ Fe ₈ SO ₄ 0.5256 3.4021 HF CaSO ₄ 0.2939 1.918 Fe ₇ O ₁ Fe ₈ O ₄ 0.2872 0.9496 HF F 1.0531 1.0531 1.8428 Fe ₇ O ₁ Fe ₈ SO ₄ 0.2036 1.8368 HF H ₂ SO ₄ 0.4080 1.8428 Fe ₇ O ₁ H ₂ SO ₄ 0.5427 1.2022 HF(6HF) H ₂ SiF ₆ 0.5444 1.5041 Fe ₇ O ₄ SO ₄ 0.6648 1.768 HF H ₂ SiF ₆ 0.8318 1.5041 Fe ₇ O ₄ SO ₄ 0.6648 1.768 Hg HgCl ₂ 0.8318 1.5041 Fe ₇ O ₄ SO ₄ 0.6648 1.768 Hg HgCl ₂ 0.7388 1.15041 Fe ₇ O ₄ P ₇ O ₄ 2.1239 1.1768 Hg HgCl ₂ 0.7388 1.15041 Fe ₈ O ₄ P ₇ O ₄ 2.1239 1.1768 Hg HgCl ₂ 0.7388 1.15041 Fe ₈ O ₄ P ₇ O ₄ 0.3766 1.3535 Hg HgCl ₂ 0.7388 1.1505 Fe ₈ H ₃ SiO ₄ 0.8963 1.1599 Hg HgS 0.8622 0.3648 Fe ₈ H ₃ SiO ₄ 0.8963 1.1599 Hg HgS 0.8622 0.3648 Fe ₈ Fe ₇ O ₄ 1.5025 0.9856 HgCl HgS 1.0146 0.5271 Fe ₈ O ₄ H ₃ SO ₄ 1.5487 0.5519 HgCl SnCl ₄ 1.8121 0.7358 Fe ₈ O ₄ H ₃ SO ₄ 1.5487 0.5519 HgCl SnCl ₄ 1.8121 0.7358 Fe ₈ O ₄ H ₃ SO ₄ 1.3690 1.0898 HgCl ₃ HgCl ₃ 0.9176 0.7358 Fe ₈ O ₄ H ₃ SO ₄ 1.3690 1.0898 HgCl ₃ HgCl ₃ 0.9266 0.7450 H ₃ SO ₄ 1.3690 HgS HgCl ₃ 0.9176 0.7358 Fe ₈ O ₄ H ₃ SO ₄ 1.3690 1.0898 HgCl ₃ HgCl ₃ 0.9176 0.7450 0.7450 Ga ₄ O ₄ H ₃ SO ₄ 1.3424 1.3952 HgS HgCl ₃ 0.9286 HgCl ₃ 0.9866 HgS HgCl ₃ 0.9286 HgS HgCl ₃ 0.9286 HgS HgCl ₃ 0.9286 HgS 0.7167 0.7167 0.7167 0.7167 0.7167 0.7167 0.7167 0.	1.4509		FeCO ₂ i					
0.9866 Fe ₃ O ₁ Fe ₅ O ₄ 0.5292 0.5292 HF BaSiF ₆ 0.4292 1.5012 Fe ₆ O ₃ FeS 0.9682 2.3297 HF BaSiF ₆ 0.4292 1.5028 Fe ₆ O ₄ FeS ₂ 0.6655 1.9508 HF CaF ₂ 0.5126 1.9027 Fe ₆ O ₄ FeSO ₄ 0.5256 3.4021 HF CaSO ₄ 0.2939 3.4822 Fe ₆ O ₄ FeSO ₄ 0.6255 1.9508 HF CaSO ₄ 0.2939 3.4822 Fe ₆ O ₄ FeSO ₄ 0.2872 0.9496 HF F 1.0531 4.9118 Fe ₇ O ₄ FeSO ₄ 0.2036 1.8368 HF K ₂ SiF ₆ 0.5444 1.850 ₄ 0.3993 3.6065 HF(2HF) H ₂ SiF ₆ 0.5444 1.850 ₄ 0.3993 3.6065 HF(2HF) H ₂ SiF ₆ 0.2773 1.8428 Fe ₇ O ₄ SO ₄ 0.6648 1.5041 Fe ₇ O ₄ SO ₄ 0.6648 1.5041 Fe ₇ O ₄ SO ₄ 0.6648 1.5041 Fe ₇ O ₄ SO ₄ 0.6648 1.3535 Hg HgCl ₂ 0.3818 1.1504 Fe ₈ O ₄ P ₇ O ₄ 2.1239 1.768 Hg HgCl ₂ 0.7388 0.3877 FeS H ₂ S 1.5045 FeS 1.3535 Hg HgCl ₂ 0.7388 0.3877 FeS 1.3545 H ₂ S 1.5079 Hg HgCl ₂ 0.9261 1.1155 FeS 1.3545 H ₂ S 1.5079 Hg HgS 1.8622 0.3648 FeS 1.5024 H ₂ S 0.8963 1.1599 Hg HgS 0.8622 0.3648 FeS 1.5024 H ₂ S 0.5963 1.1599 Hg HgS 0.8622 0.3648 FeS 1.5025 0.9856 HgCl HgS 1.0146 0.5271 FeSO ₄ H ₂ SO ₄ 1.5487 0.5519 HgCl SnCl ₂ 1.8989 0.6654 FeS ₃ S 1.8709 0.4017 HgCl SnCl ₂ 1.8929 0.6521 FeSO ₄ H ₂ SO ₄ 1.5487 0.5519 HgCl SnCl ₂ 1.1502 0.3528 FeSO ₄ 7H ₂ O H ₂ SO ₄ 1.3590 1.0898 HgCl ₂ HgCl ₂ 1.1502 0.3528 FeSO ₄ 7H ₂ O H ₂ SO ₄ 1.3590 1.0898 HgCl ₂ HgCl ₂ 1.1502 0.3528 FeSO ₄ 7H ₂ O H ₂ SO ₄ 1.3590 1.0898 HgCl ₂ HgS 1.1670 0.7358 Fe ₆ (SO ₄) H ₂ SO ₄ 1.3590 1.0898 HgCl ₂ HgS 1.1670 0.7358 Fe ₆ (SO ₄) H ₂ SO ₄ 1.3590 1.0898 HgCl ₂ HgCl ₂ 0.9856 HgCl 0.916 0	2.2277	Fe ₂ O ₂	Fe(HCO ₂) ₂					0.2001
1.898 Fe ₂ O ₁ FePO ₄ 0.5292 2.3297 HF BaSiF ₆ 0.4292 1.5028 Fe ₂ O ₁ FeS 0.6655 1.9508 HF CaF ₂ 0.5126 1.9027 Fe ₂ O ₁ FeSO ₄ 0.5256 3.4021 HF CaSO ₄ 0.2939 3.4822 Fe ₂ O ₁ FeSO ₄ 7H ₂ O 0.2872 0.9496 HF F 1.0531 FeSO ₄ 1.04292 2.4510 HF H ₂ SO ₄ 0.4080 1.8368 HF H ₂ SO ₄ 0.4080 1.8368 HF H ₂ SO ₄ 0.4080 1.8048 HF H ₂ SO ₄ 0.5424 1.2022 HF(6HF) H ₂ SiF ₆ 0.8318 1.5041 Fe ₂ O ₁ SO ₁ 0.6648 H ₂ SO ₄ 0.3766 1.3535 Hg HgCl ₂ 0.7388 0.3877 FeS H ₂ SO ₄ 0.3963 1.1559 Hg HgCl ₂ 0.7388 0.3877 FeS H ₂ SO ₄ 0.8963 1.1559 Hg HgS 0.8622 0.3648 FeS S 2.7417 1.125 HgCl HgNO ₂ 0.8989 0.6654 FeS ₃ S S 2.7417 1.125 HgCl HgNO ₂ 0.8989 0.6654 FeS ₃ S S 2.7417 1.125 HgCl HgNO ₂ 0.8989 0.6457 FeSO ₄ H ₂ SO ₄ 1.5487 0.5519 HgCl SnCl ₄ 2.4898 0.5271 FeSO ₄ H ₂ SO ₄ 1.5487 0.5519 HgCl SnCl ₄ 1.8121 0.5271 FeSO ₄ H ₂ SO ₄ 1.3590 1.8973 0.8694 HgCl ₂ HgS 1.1670 0.7388 Fe ₃ SO ₄ H ₂ SO ₄ 1.3590 1.0898 HgCl ₄ HgS 1.1670 0.7388 Fe ₃ SO ₄ H ₂ SO ₄ 1.3590 1.0898 HgCl ₄ HgS 1.1670 0.7388 Fe ₃ SO ₄ H ₂ SO ₄ 1.3590 1.0898 HgCl ₄ HgS 1.1670 0.7388 Fe ₃ SO ₄ H ₂ SO ₄ 1.3590 1.0898 HgCl ₄ HgS 1.1670 0.7388 Fe ₃ SO ₄ H ₃ SO ₄ 1.3590 1.0898 HgCl ₄ HgS 1.1670 0.7388 HgCl ₄ HgS 1.1670 0.7480 HgS HgCl ₄ 0.9286	0.9666		$Fe_{\bullet}O_{\bullet}\dots$		1.0658	HCO ₂ H	H ₂ SO ₄	0.9383
1.1011 FesO ₃ FesS 0.9082 2.3297 HF BaSiF ₆ 0.4292 1.5028 Fe ₉ O ₁ FeS ₂ 0.6655 1.9508 HF CaF ₂ 0.5126 1.9027 Fe ₉ O ₁ FeSO ₄ 7H ₂ O 0.2872 0.9496 HF F 1.0531 4.9118 Fe ₇ O ₁ FeSO ₄ 7H ₂ O 0.2872 0.9496 HF F 1.0531 2.5041 Fe ₇ O ₁ Fe ₈ O ₄ 0.2036 1.8368 HF H ₂ SO ₄ 0.4080 2.5041 Fe ₇ O ₁ Fe ₈ O ₄ 0.3993 3.6065 HF(2HF) H ₂ SiF ₆ 0.5444 1.8428 Fe ₉ O ₁ H ₂ SO ₄ 0.5427 1.2022 HF(6HF) H ₂ SiF ₆ 0.2773 1.8428 Fe ₇ O ₁ Fe ₇ O ₁ O.6648 0.4708 Fe ₇ O ₁ SO ₁ 0.6648 0.4708 Fe ₇ O ₄ P ₁ O ₄ 2.1239 1.768 Hg HgCl ₂ 0.8318 0.4708 Fe ₇ O ₄ P ₁ O ₄ 2.1239 1.1768 Hg HgCl ₂ 0.7388 0.3877 FeS BaSO ₄ 0.3766 1.3535 Hg HgCl ₂ 0.7388 0.3877 FeS H ₂ S 0.8663 1.1599 Hg HgC 0.9261 1.1155 FeS H ₂ S 0.8963 1.1599 Hg HgS 0.8622 0.3648 FeS S 2.7417 1.125 HgNO ₁ 0.8989 0.6654 FeS ₁ SS 1.5025 0.9856 HgCl HgS 1.0146 0.5346 FeS ₂ SS 1.8709 0.4017 HgCl SnCl ₂ 2.4898 0.6457 FeSO ₄ H ₂ SO ₄ 1.5487 0.5519 HgCl SnCl ₂ 1.1670 0.5735 Fe ₈ (SO ₄) H ₂ SO ₄ 1.3590 1.0898 HgO HgCl 0.9176 0.7358 Fe ₈ (SO ₄) H ₂ SO ₄ 1.3590 1.0898 HgO HgCl 0.9176 0.7358 Fe ₈ (SO ₄) H ₂ SO ₄ 1.3590 1.0898 HgO HgCl 0.9176 0.7358 Fe ₈ (SO ₄) H ₂ SO ₄ 1.3590 1.0898 HgO HgCl 0.9176 0.7358 Fe ₈ (SO ₄) H ₂ SO ₄ 1.3590 1.0898 HgO HgCl 0.9176 0.7358 Fe ₈ (SO ₄) H ₂ SO ₄ 1.3590 1.0898 HgO HgCl 0.9876 0.7450 Ga ₄ O ₁ Ga 1.3424 1.3962 HgS Hg(NO ₂) 0.9208 0.7450 Ga ₄ O ₁ Ga 1.3424 1.3962 HgS Hg(NO ₂) 0.7167			FePO4	0.5292				
1. 5028			FeS	0.9082	2.3297	HF	BaSiFa	0.4292
1.9027 Fe ₉ O ₁ FeSO ₄ . 7H ₂ O 0.5256 3.4021 HF CaSO ₄ 0.2939 4.9118 Fe ₇ O ₁ FeSO ₄ . 7H ₂ O 0.2872 0.9496 HF H ₂ SO ₄ 0.4080 2.5041 Fe ₇ O ₁ Fe ₂ (SO ₄) ₁ 0.3993 3.6065 HF(2HF) H ₂ SiF ₄ 0.5444 1.5041 Fe ₇ O ₁ SO ₄ 0.5427 1.2022 HF(6HF) H ₂ SiF ₄ 0.2773 1.8428 Fe ₃ O ₄ H ₂ SO ₄ 0.5427 1.2022 HF(6HF) H ₂ SiF ₄ 0.2773 1.5041 Fe ₇ O ₁ SO ₁ 0.6648 0.4708 FePO ₄ P ₁ O ₁ 2.1239 1.768 Hg HgCl 0.8498 0.4654 FeS BaSO ₄ 0.3766 1.3535 Hg HgCl 0.7388 1.1155 FeS H ₂ SO ₄ 0.8963 1.1599 Hg HgC 0.9261 1.1155 FeS H ₂ SO ₄ 0.8963 1.1599 Hg HgS 0.8622 0.3648 FeS S 2.7417 1.1125 HgCl HgS 1.0146 0.5346 FeS ₄ Fe ₇ O ₄ 1.5025 0.9856 HgCl HgS 1.0146 0.5346 FeS ₄ Fe ₇ O ₄ 1.5487 0.5519 HgCl SnCl ₂ 2.4898 0.6654 FeS ₄ Fe ₇ O ₄ 1.5487 0.5519 HgCl SnCl ₂ 2.4898 0.6457 FeSO ₄ H ₂ SO ₄ 1.5487 0.5519 HgCl SnCl ₂ 1.8121 0.5271 FeSO ₄ H ₂ SO ₄ 1.5873 0.8694 HgCl ₂ HgCl 1.1502 0.3528 FeSO ₄ H ₂ SO ₄ 1.3590 1.0898 HgCl HgS 1.1670 0.7358 Fe ₈ (SO ₄) H ₂ SO ₄ 1.3590 1.0898 HgCl HgS 1.1670 0.7358 Fe ₈ (SO ₄) H ₂ SO ₄ 1.3590 1.0898 HgCl HgS 1.1670 0.7358 Fe ₈ (SO ₄) H ₂ SO ₄ 1.3590 1.0898 HgCl HgCl 0.9876 0.7450 Ga ₄ O ₁ Ga 1.3424 1.3952 HgS Hg(N) ₂) 0.7167			FeS ₂	0.6655	1.9508	HF	CaF ₂	
3. 4.9118			IFeSO4		3.4021	HF	CaSO ₄	0.2939
$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$			FeSO ₄ 7H ₂ O.	0.2872	0.9496	HF	F	1.0531
2.5041 Fe ₉ O ₁ Fe ₉ (SO ₄) ₂ 0.3993 3.6065 HF(2HF) H ₂ SiF ₄ 0.2773 1.8428 Fe ₉ O ₁ H ₂ SO ₄ 0.5427 1.2022 HF(6HF) H ₂ SiF ₄ 0.8318 1.5041 Fe ₉ O ₁ SO ₁ 0.6648 0.4708 FePO ₄ P ₄ O ₄ 2.1239 1.1768 Hg HgCl 0.8498 2.6554 FeS BaSO ₄ 0.3766 1.3535 Hg HgCl 0.7388 0.3877 FeS H ₂ S 2.5795 1.0798 Hg HgCl 0.9261 1.1155 FeS H ₂ S 2.5795 1.0798 Hg HgCl 0.9261 1.1155 FeS H ₂ S 2.5795 1.0798 Hg HgCl HgS 0.8622 0.3648 FeS S 2.7417 1.1125 HgCl HgS 0.8622 0.3648 FeS S 2.7417 1.1125 HgCl HgNO ₄ 0.8989 0.6654 FeS ₂ S 1.5025 0.9856 HgCl HgS 1.0146 0.5346 FeS ₂ S 1.8709 0.4017 HgCl SnCl ₂ 2.4898 0.6457 FeSO ₄ H ₂ SO ₄ 1.5487 0.5519 HgCl SnCl ₄ 1.8121 0.5271 FeSO ₄ SO ₅ 1.8973 0.8694 HgCl ₅ HgCl HgS 1.1502 0.3528 FeSO ₄ ·7H ₂ O H ₂ SO ₄ 2.8345 0.8569 HgCl ₄ HgCl 1.1502 0.3528 FeSO ₄ ·7H ₂ O H ₂ SO ₄ 1.3590 1.0898 HgC HgCl ₂ HgS 1.1670 0.7358 Fe ₃ (SO ₄) H ₂ SO ₄ 1.3590 1.0898 HgC HgCl ₂ 0.9856 HgCl 0.9176 0.1114 FeSO ₄ 1.3500 1.0898 HgC HgCl ₂ 0.9268 HgCl ₂ 0.9268 HgCl ₃ 0.640 HgCl 0.8837 0.7450 Ga ₄ O ₁ Ga 1.3424 1.3952 HgS Hg(NO ₃) 0.7467	4.9118	Fe ₂ O ₂				HF		0.4080
1.8428		, n	SO ₄ ·6H₂O					
1.5041 Fe ₂ O ₁ SO ₁ 0.6648 1.1768 Hg HgCl 0.8498 2.6554 FeS BaSO ₄ 0.3766 1.3535 Hg HgCl 0.9261 1.1155 FeS H ₂ S 2.5795 1.0798 Hg HgCl 0.9261 1.1155 FeS H ₂ S 0.8963 1.1599 Hg HgS 0.8622 0.3648 FeS S 2.7417 1.1125 HgCl HgNO ₁ 0.8989 0.6654 FeS ₂ Fe ₂ O ₁ 1.5025 0.9856 HgCl HgS 1.0146 0.5346 FeS ₂ S 1.8709 0.4017 HgCl SnCl ₂ 2.4898 0.6457 FeSO ₄ H ₂ SO ₄ 1.5487 0.5519 HgCl SnCl ₂ 1.8121 0.5271 FeSO ₄ H ₂ SO ₄ 1.8973 0.8694 HgCl ₂ HgCl 1.1502 0.3528 FeSO ₄ TH ₂ O ₄ 2.8345 0.8569 HgCl HgS 1.1670 0.7358 Fe ₃ (SO ₄) H ₂ SO ₄ 1.3590 1.0898 HgC HgCl 0.9176 0.1114 FeSO ₄ (NH ₂) ₁ SO ₄ 1.3590 1.0898 HgC HgCl 0.9837 0.1114 FeSO ₄ (NH ₂) ₂ So ₃ 1.3590 1.0898 HgC HgCl 0.9838 0.7450 Ga ₄ O ₁ Ga 1.3424 1.3952 HgS Hg(NO ₂) ₂ 0.8860 0.7450 Ga ₄ O ₁ Ga 1.3424 1.3952 HgS Hg(NO ₂) ₂ 0.7167			$Fe_2(SO_4)_2$					
0.4708 FePO ₄ P ₁ O ₄ 2.1239 1.1768 Hg HgCl 0.8498 2.6554 FeS BaSO ₄ 0.3766 1.3535 Hg HgCl 0.7388 1.1155 FeS H ₂ S 2.5795 1.0798 Hg HgO 0.9261 1.1155 FeS H ₂ SO ₄ 0.8963 1.1599 Hg HgS 0.8622 0.3648 FeS S 2.7417 1.1125 HgCl HgNO ₄ 0.8989 0.6654 FeS ₄ Fe ₂ O ₄ 1.5025 0.9856 HgCl HgS 1.0146 0.5346 FeS ₅ S 1.8709 0.4017 HgCl SnCl ₂ 2.4898 0.6457 FeSO ₄ H ₂ SO ₄ 1.5487 0.5519 HgCl SnCl ₄ 1.8121 0.5271 FeSO ₄ H ₂ SO ₄ 1.8973 0.8694 HgCl ₂ HgCl 1.1502 0.3528 Fe ₃ C ₄ ·7H ₂ O H ₂ SO ₄ 2.8345 0.8569 HgCl ₂ HgS 1.1670 0.7358 Fe ₄ (SO ₄) H ₂ SO ₄ 1.3590 1.0898 HgC HgCl 0.9176 0.1114 FeSO ₄ (NH ₄) ₂ SO ₄ ·6H ₄ O So ₄ 1.3424 1.3952 HgS Hg(N) ₁ 0.9208 0.7450 Ga ₄ O ₁ Ga 1.3424 1.3952 HgS Hg(N) ₂) 0.7867 0.7167					1.2022	HF(6HF)	H_2SiF_6	0.8318
2.6554 FeS					4 4 7 2 2			
0.8877 FeS			P. 90					
1.1155 FeS			DBSU(0.3766	1.3535			
0.8848 FeS			11.60					
0.6854 FeS ₂ . Fe ₃ O ₄ 1.5025 0.9856 HgCl HgS 1.0146 0.6457 FeSO ₄ H ₂ SO ₄ 1.5487 0.5519 HgCl SnCl ₄ 2.4898 0.5271 FeSO ₄ H ₂ SO ₄ 1.5897 0.5519 HgCl SnCl ₄ 1.8121 0.3528 Fe ₃ O ₄ ·7H ₃ O H ₃ SO ₄ 2.8345 0.8569 HgCl ₂ HgCl 1.1502 0.7358 Fe ₄ (SO ₄) H ₂ SO ₄ 1.3590 1.0898 HgO HgCl 0.9176 0.1114 FeSO ₄ (NH ₄) ₁ SO ₄ ·6H ₃ O Na ₄ Cr ₂ O ₇ 8.9802 1.0860 HgS Hg(CN) ₁ 0.9208 0.7450 Ga ₄ O ₁ Ga 1.3424 1.3952 HgS Hg(NO ₃) ₂ 0.7860 0.7650 HgCl 0.8860 HgCl 0.9860 0.77650 HgCl 0.98860 HgCl 0.98860 0.77670 HgCl 0.98860 HgCl 0.9767 0.77670 HgCl 0.98860 HgCl 0.9208 0.77670 HgCl 0.98860 HgCl HgCl 0.9208 0.77670 HgCl 0.98860 HgCl HgCl 0.98860 0.77670 HgCl 0.98860 HgCl 0.98860 HgCl 0.98860 0.77670 HgCl 0.98860			Q Q				ngs	
0.5346 FeS ₂ , S. 1.8709 0.4017 HgCl. SnCl ₂ 2.4898 0.5519 FeSO ₄ 1.5487 0.5519 HgCl. SnCl ₄ 1.8121 0.5271 FeSO ₄ SO ₅ 1.8973 0.8694 HgCl ₂ HgCl 1.1502 0.3528 FeSO ₄ -7H ₂ O. H ₂ SO ₄ 2.8345 0.8569 HgCl ₂ HgS 1.1670 0.7358 Fe ₂ (SO ₄), H ₂ SO ₄ 1.3590 1.0898 HgO HgCl 0.9176 0.1114 FeSO ₄ (NH ₂) ₁ SO ₄ -6H ₂ O Na ₂ Cr ₂ O ₇ 8.9802 1.1316 Hg ₂ O HgCl 0.8837 HgCl 0.7450 Ga ₄ O ₁ Ga 1.3424 1.3952 HgS HgO ₂ 0.8860			Fa.O	1 5005			ngNO1	
0.6457 FeSO ₄ H ₂ SO ₄ 1.5487 0.5519 HgCl SnCl 1.8121 0.5271 FeSO ₄ SO ₃ 1.8973 0.8694 HgCl HgCl 1.1502 0.3528 FeSO ₄ ·7H ₂ O H ₂ SO ₄ 2.8345 0.8569 HgCl HgCl 1.1502 0.7358 Fe ₃ (SO ₄) H ₂ SO ₄ 1.3590 1.0898 HgO HgCl 0.9176 0.1114 FeSO ₄ (NH ₂) SO ₄ ·6H ₃ O Na ₃ Cr ₂ O ₇ 8.9802 1.0890 HgS HgC HgCl 0.8837 0.9208 HgC HgS Hg(N) ₁ 0.9208 0.7450 Ga ₄ O ₁ Ga 1.3424 1.3952 HgS Hg(NO ₂) 0.7867 HgC 1.0898 Hg(NO ₂) 0.8860			g	1.0020				
0.5271 FeSO ₄ . SO ₃ . 1.8973 0.8694 HgCl ₅ . HgCl 1.1502 0.3528 FeSO ₄ ·7H ₂ O. H ₂ SO ₄ . 2.8345 0.8569 HgCl HgCl 1.670 0.7358 Fe ₃ (SO ₄). H ₂ SO ₄ . 1.3590 1.0898 HgO HgCl 0.9176 0.1114 FeSO ₄ (NH ₄): SO ₄ ·6H ₃ O Na ₃ Cr ₂ O ₇ . 8.9802 1.0860 HgS Hg(ON): 0.9208 1.1287 HgS Hg(ON): 0.9208 0.7450 Ga ₄ O ₁ . Ga 1.3424 1.3952 HgS Hg(NO ₂): 0.7467				1 5497		Ingol		
0.3528 FeSO ₄ ·7H ₂ O. H ₂ SO ₄ . 2.8345 0.8569 HgCl ₁ . HgS 1.1670 0.7358 Fe ₆ (SO ₄). H ₂ SO ₄ . 1.3590 1.0898 HgO. HgCl. 0.9176 1.1316 Hg ₂ O. HgCl. 0.8837 SO ₄ ·6H ₂ O. Na ₄ Cr ₂ O ₇ . 8.9802 1.0860 HgS. Hg(CN) ₁ . 0.9208 0.7450 Ga ₂ O ₁ . Ga. 1.3424 1.3952 HgS. Hg(NO ₂) ₂ . 0.7167				1 9072		HgCl.		
0.7358 Fe ₃ (SO ₄) H ₂ SO ₄ 1.3590 1.0898 HgO HgCl 0.9176 0.1114 FeSO ₄ (NH ₄) ₁ SO ₄ ·6H ₂ O Na ₂ Cr ₂ O ₇ 8.9802 1.0860 HgC HgCl 0.8837 HgC O.7450 Ga ₄ O ₁ Ga 1.3424 1.3952 HgS Hg(NO ₂) ₂ 0.8860 0.7450 Ga ₂ O ₁ Ga 1.3424 1.3952 HgS Hg(NO ₂) ₂ 0.7167								
0.1114 FeSO ₄ (NH ₂): SO ₄ ·6H ₄ O Na ₄ Cr ₂ O ₇ 8.9802 1.1316 HgC HgC 1.0820 HgC 1.287 HgC 0.9208 0.7450 Ga ₄ O ₁ Ga 1.3424 1.3952 HgS Hg(NO ₃): 0.7167	0.7358		H.SO.					
SO ₄ ·6H ₄ O Na ₄ Cr ₂ O ₇ 8.9802 1.0860 HgS Hg(CN) ₁ 0.9208 1.1287 HgS Hg(NO ₄) 0.8860 0.7450 Ga ₄ O ₁ Ga 1.3424 1.3952 HgS Hg(NO ₄) ₂ 0.7167				1.0000			HeCl	
0.7450 Ga ₂ O ₁ Ga 1.3424 1.3952 HgS HgNO ₁ 0.8860 Hg(NO ₂) ₂ 0.7167	31		Na Cr.O.	8.9802		'HøS		
0.7450 Ga ₂ O ₂ Ga 1.3424 1.3952 HgS Hg(NO ₂) ₂ 0.7167						HeS	HeNO.	
	0.7450	Ga ₂ O ₂	Ga	1.3424				
	0.5931	Ga ₂ S ₁					Hg.O.	

XVIII.—CONVERSION FACTORS (Continued)

Α'	A	В	B'	A'	Α	B	B'
0.9310	HgS	HgO		2.0391 1.5279	H ₂ SiF ₄	H₂SO₄ K₂SiF₄	0.4904 0.6545
1.2751	HgS	HgSO ₄	0.7848	0.7227	H ₂ SiF ₄	SiF4	1.3837
0.8433	HI	Ag		0.9860	H-SiF ₁	SiF ₆	1.0141 1.2988
1.8354	<u>HI</u>	AgI	0.5448 2.3979	0.7699	H ₂ SiO ₂	SiO ₂	
0.4170 1.4092	HI	Pd PdI₂	0.7097	2.8441	H ₂ SO ₂	BaSO ₄	0.8517
2.5868	HI	ти	0.3866	0.8885	H ₂ SO ₃	HCl H ₂ SO ₄	1.1255 0.8369
0.0700	HNO2	AgNO ₂	0.3055	1.1949 0.7805	H ₂ SO ₃ H ₂ SO ₃	SO ₂	1.2812
3.2729 0.7756	HNO ₂	HCl	1.2893			AIG!	1.1023
1.0431	HNO2	H ₂ SO ₄	0.9587	0.9072 0.3473	H ₂ SO ₄	AlCla Al ₂ O ₃	2.8789
0.6382 0.3623	HNO	NO NH	1.5667 2.7605		H ₂ SO ₄	Al ₂ (SO ₄) ₃	0.8594
0.5627	HNO	Cl	1.7772	1.7473	H ₂ SO ₄	Ba(OH) ₁	0.5723 0.4202
0.5787	HNO	HCl	1.7280 1.2850		H ₂ SO ₄ H ₂ SO ₄	$C(\text{in BaCO}_1)$.	8.1696
0.7782 1.6045	HNO ₃	KNO.	0.6233		H ₂ SO ₄	Ca(CH ₃ CO ₃) ₃	0.6203
0.2223	HNO.	N	4.4986	0.5716	H ₂ SO ₄	CaO	1.7494 0.7205
1.3490	HNO ₃	NaNO ₃	0.7413 3.7000		H ₂ SO ₄ H ₂ SO ₄	CaSO ₄ CH ₄ CHOH	0.7200
0.2702 0.8489	HNO ₃	NH _s	1.1780			CO ₂ H	0.5446
3.5232	HNO.	(NH ₄) ₂ PtCl ₆	0.2838	1.2244	H ₂ SO ₄	CH.CO.H CH.CO.Na	0.8169
0.4762	HNO	NO	2.0999 1.6579		H ₂ SO ₄	(CH,CO ₂),O	0.9609
0.6032 0.7301	HNO ₁	N ₂ O ₃ N ₂ O ₄	1.3697		H ₂ SO ₄	C ₂ H ₂ O ₄	1.0894
0.8571	HNO1	N_2O_4	1.1668		H ₂ SO ₄	C ₄ H ₄ O ₄ ·2H ₄ O	0.7782 0.6537
1.5488	HNO ₁	Pt	0.6457	1.5298 - 0.7230	H ₂ SO ₄	Cla	1.3831
0.8163	H,PO,	HPO3	1.2251	0.4487	H_2SO_4	CO	2.2287
0.9081	H.PO	H.P.O	1.1012		H ₂ SO ₄ H ₂ SO ₄	CuSO ₄ Fe	0.6144 1.7564
1.0002	H ₂ PO ₄ H ₂ PO ₄		0.8806		H ₂ SO ₄	FeO	1.3653
1.1356 0.3165	H.PO.	P	3.1593	0.5427	H_2SO_4	FeS	1.8428 1.1155
0.7244	H,PO	P ₃ O ₅	1.3804	0.8963 1.5487	H ₂ SO ₄	FeSO.	0.6457
0.3767	H ₂ PtCl ₆ ·6H ₂ C	Pt	2.654	2.8345	H ₂ SO ₄	FeSO. 7H ₂ O.	0.3528
			0 415	- 1.3590	H ₂ SO ₄ H ₂ SO ₄	$Fe_2(SO_4)$ H_1AsO_4	0.7358 1.0362
2.4074	H,S	As ₂ S ₃	0.415	4 0.9651) 0.7438	H ₂ SO ₄	HCl	1.3448
1.3495 6.8506	H ₂ S		0.146	0.9177	H ₂ SO ₄	H ₁ C ₂ O ₄	1.0894
4.2393	H ₂ S	[CdS	0.236		H ₂ SO ₄		1.0658 2.4510
2.5795	H.S	FeS			H ₂ SO ₄	HNO	1.0436
2.8782 0.9408		. [S	1.062	9 1.2850	H ₂ SO ₄	HNO H.PO.	0.7782 1.0002
1.8799	H.S		0.531	9 0.9998 8 0.3474	H ₂ SO ₄ *	H.S.	
2.3495	H ₂ S	SO ₁		- 0.8369	H ₂ SO ₄ *	. I H ₂ SO ₂	1.1949
0.6129	H ₂ SeO ₃	. Se	1.631	5 0.4904 - 2.4293	H ₂ SO ₄	. K,Al,(804)4	
1.9379	H ₂ SiF ₄	. BaSiF	0.516	0		24H,C	
0.5410	H ₂ SiF ₄	. CaF	1.848				
0.7899					H.80	. Ko	1.0418
0.2773 0.8318						. кон	0.8740
	1	1	1		T A	1	1

 $A \times A' = B$ $B \times B' = A$

^{*} Phenolphthalein indicator.

XVIII.—CONVERSION FACTORS (Continued)

***************************************		r—					
A'	A	В	B'	A'	A	B	B'
1.1241 1.7767	H.SO4	K ₂ SiF ₆		2.6074	I	T1	0.6222
0.4111	H.SO4	K ₂ SO ₄ MgO	0.5628 2.4325	1.2090	In	In ₂ O ₂	0.8271
1.2274	H.SO.	MgSO	0.8147		In	In ₂ O ₂	0.7047
1.1920	H.SO.	NaCl	0.8389	1.2101	111	IIIgos	0.1021
1.0808	H.SO.†	Na ₂ CO ₃	0.9252	1.1243	Ir	Ir ₂ O ₃	0.8895
1.8661	H-SO4	Na ₂ C ₂ O ₄	0.7320	1.1220	***************************************	21303	0.0000
2.6711	H,SO4	Na ₂ Cr ₂ O ₇		3.5437	K	KClO4	0.2822
1.7132	H-80.†	NaHCO		1.2046	K	IKO	0.8302
2.4583	H.SO.	NaH ₂ PO ₄		6.2169	K	K.PtCl	0.1609
2.8964	H ₂ SO ₄ †	Na ₂ HPO ₄	0.3453	2.2285	K	K.SO	0.4487
2.1222	H ₂ SO ₄	NaHSO ₃	0.4712	0 .0571	K2Al2(SO4)4		
1.7334	H-80	NaNO ₂	0.5769		24H ₂ O	Al	17.51
0.6821	H-804	Na ₂ O	1.5820	0.1077	ditto	Al ₂ O ₄	9.2859
0.8158	H.SO	NaOH	1.2258 0.8968	0.4556	ditto	H ₂ O	2.1949
1.1151	H,80,	Na ₂ PO ₄	0.8968	0.4116	ditto *	H ₂ SO ₄	2.4293
0.7959	H,SO	Na ₂ S		0.4134	ditto(total)	$H_2SO_4(+Al)$	
0.9598	H.SO	Na ₂ SiF ₆	1.0418		1***	+K)	2.4190
2.5706	H ₂ SO ₄	Na ₂ SO ₂	0.3890		ditto	8	7.4004
1.4485	H ₂ SO ₄	Na ₂ SO ₄	0.6904		ditto	SO ₂	2.9635
0.8473	H,80,	NH ₂	2.8792		ditto	K	12.136
1.0909	H ₂ SO ₄	NH.Cl		0.0993	ditto	K₁O NaHCO₁	10.075
0.5310 0.6948	H ₂ SO ₄	(NH ₄) ₂ O	1.8850 1.4392		$K_2Al_2(SO_4)_4$	Na ₂ B ₄ O ₇	1.0251
1.3473	H ₂ SO ₄	(NH ₄) ₂ S (NH ₄) ₂ SO ₄	0.7422	0.7575	KBF ₄	10H ₂ O	1 2202
2.8268	H.SO.	(NH ₄) ₂ S ₂ O ₃	0.4298	0.0004	17D-		1.3202
0.7750	H.SO.	N_2O_2	1.2903		KBr	Ag AgBr	0.6338
0.9382	H.SO.	N ₂ O ₄		0.6715	KBr	Br	1.4892
1.1013	H.SO.	N ₂ O ₄	0.9080		KBr	K	3.0440
0.0275	H.SO.	11303	0.0000	1.4469	KCI	Ag	0.6911
0.02.0	(Y ppt.)	P	36.336	1.9225	KČI	AgCl	0.5202
0.4829	H.SO	P ₂ O ₃		0.4756	KCl	cî	2.1027
0.0629	H-SO.t		1	0.4891	KCl	HCl	2.0445
	(Y ppt.)	P ₂ O ₃	15.878	1.6438	KCl	KClO ₁	0.6084
0.3267	H.SO	8	3.0590	1.8584	KCl	KClO ₄	0.5381
0.6532	I H.SO. #	80.	1.5309	2.5233	KCl	KClO ₄ KHC ₄ H ₄ O ₆	0.3963
1.3064	H.SO.	80	0.7655		KCl	K ₂ PtCl ₅	0.3069
0.8163	H ₂ SO ₄	80	1.2250		KCl	K ₂ SO ₄	0.8557
1.0912	H ₂ SO ₄			1.3090	KCl	Pt	0.7639
1.1881	H-80	SO HCl	0.8417	1.1696	KClO ₁	AgCl	0.8550
0,4084	H.SO	TiO ₃	2.4488	0.2893	KClO,	[CI	3.4563
0.6665 0.8296	H ₂ SO ₄		1.5004		KClO ₁	K.O	2.6021
1.6459	H.SO		1.2054	0.3399 1.6568	KCIO	K₄O	2.9418 0.6036
1.0208	11,504	ZnSO ₄	0.0070	2.0564	KCN	Ag AgCN	0.4863
0.8500	ĭ	Āg	1.1765	2.2014	KCN	AgCl	0.4543
1 8500	Î	AgI		0.3184	K,CO,	CO ₂	3.1409
1.8500 0.2794		ıĉî		0.8120	K,ČO,	кон	1.2315
1.0079	Î	HI	0.9921	1.2610	K ₂ CO ₂	K.SO	0.7930
1.3081	I I	l Kt		1.3046	K.CrO	BaCrO	0.7666
1.6863	I	KIO: NaIO:	0.5930	0.5149	K,ČrO	CrO	1.9420
1.5594	I	NaIO	0.6413	1.7224	K ₂ Cr ₂ O ₇	BaCrO ₄	0.5807
0,4967 0:4203	1	Na ₂ SO ₃	2.0135	0.6800	K ₂ Cr ₂ O ₇	CrO:	1.4708
0:4203	I	Pd	2.3790	1.1388	K ₂ Cr ₂ O ₇	Fe	0.8782
1.4204	I	PdL	0.7040	0.3200	K ₂ Cr ₂ O ₇	K ₂ O	3.1231
	<u> </u>						L,
		AX	A'-B	BYB	'-A		-

 $A \times A' = B$ $B \times B' = A$

^{*} Phenolphthalein

[†] Methyl orange ‡ Titration of yellow ppt.

-							
A'	A	В	B'	Α'	A	В'	B'
0.4395	KHCO1	CO	2.2752	0.8896	K.SiF	H ₂ SO ₄	1.1241
0.8703	KHCO	K ₂ SO ₄		0.5270	K ₂ SiF ₆	KF	1.8976
1.7141	KHSO4	BaSO	0.5834		K ₂ SiF ₄	SiF ₄	2 1141
0.6399	KHSO	K ₂ SO ₄	1.5628		K ₂ SiF ₄	SiO ₂	8 6567
0.7845	KI	I	1.3081	0.3903	K ₂ SiO ₂	SiO ₂	2.5622
0.2355	K1	I K	4.2460		K-SO	H ₂ SO ₄	1.7767
0.4995	KMnO	Mn ₂ O ₂	2.0022	0.4487	K,SO	K	2.2285
0.4826	KMnO4	Mn_1O_4	2.0721	0.8557	K.SO	KCl	1.1686
0.8981	KMnO4	l NaMnO ₄	1.1134	0.7930	K ₂ SO ₄	K ₂ CO ₂	1.2610
0.4850	KNO	H ₂ SO ₄	2.0617	0.5405	K ₂ SO ₄	K ₁ O	1.8500
2,4041	KNO	K₁PtCl₃	0.4159	2.7897	K ₂ SO ₄	K ₂ PtCl ₂	0.3585
0.8408	KNO ₂	NaNO	1.1894	0.6327	K ₂ SO ₄	K ₂ S	1.5804
0.2968	KNO ₃	[NO	3.3694	0.4595	K ₂ SO ₄	SO ₂	2.1765
0.5342	KNO ₃	N ₂ O ₃	1.8721	0.6059	K ₂ AsO ₄	$Mg_2As_2O_1$	1.6503
0.8741	KOH	H ₂ SO ₄	1.1440				
1.2315	KOH	K ₂ CO ₃	0.8120	1.1727	La	La ₂ O ₃	0.8528
0.8394	KOH	K ₂ O	[1.1913]			· · · · · · · · · · · · · · · · · · ·	
0.7131	KOH	NaOH	1.4024	6.1096	Li	LiCl	0.1637
0.4004	K ₂ MnO ₄	Mn ₂ O ₃	2.4975	5.3231	Li	Li ₂ CO ₂	0.1879
0.7117	K ₂ HAsO ₄	Mg ₂ As ₂ O ₇	1.4050	2.1527	Li	Li ₂ O	0.4645
0.7529	K.O	Cl	1.3282	5.5648	Li	Li ₂ PO ₄	0.1798
0.4671	K₃O	CO2	2.1409	1.2965	LiCl	1.i2SO4	0.7713
0.7743	K ₂ O	HCl	1.2915	0.3523	LiCl	Li ₂ O	2.8381
1.0413	K ₂ O	H ₂ SO ₄	0.9604	0.5956	Li ₂ CO ₂	CO ₂	1.6790
0.8302	K ₂ O	<u>K.</u>	1.2046	2.4727	Li ₂ O	Li ₂ CO ₄	0.4044
2.5270	K₁0	KBr	0.3957	3.6794	Li ₂ O	Li ₂ SO ₄	0.2718
1.5830	K₁O	KCl	0.6317	2.5850	Li ₂ O	LisPO4	0.3870
2.1255	<u>K</u> ₂O	KHCO,	0.4705	0.9569	Li ₂ PO ₄	Li ₂ CO ₃	1.0451
1.4671	K ₁ O	K ₁ CO ₁	0.6816	1.7595	Li ₂ PO ₄	LiHCO	0.5682
3.9949	K₁O	KHC,H,O	0.2504	1.4234	Li ₂ PO ₄	Li ₂ SO ₄	0.7023
3.1231	K ₁ 0	K ₂ Cr ₂ O ₇	0.3200 0.2837	0.1262	Li ₂ SO ₄	LiCl	7.9207
3.5248	K₂O	K1 KOH		0.7712	Li ₂ SO ₄ Li ₂ SO ₄		
1.1913	K₁O	KNO	0.8394 0.4658	0.7282	1419504	SO ₂	1.3732
2.1466	K.O	K ₂ CrO ₄	0.4851	2.9162	Mg	Cl	0.3429
2.0616 5.1609	K ₁ O	K₂PtCl₅	0.1938	1.6579	Mg	MgO	0.6032
1.8500	K ₂ O	K ₂ SO ₄	0.5406	4.5789	Mg	Mg ₂ P ₂ O ₇	0.2184
0.6582	K.O	Na ₂ O	1.5194	4.9498	Mg	MgSO ₄	0.2020
0.8500	K.O	SO	1.1765	0.7447	MgCl	Cl	1.3429
0.1609	K, PtCl	K	6.2169	0.3488	MgCl ₂ ·6H ₂ O.	či	2.8672
0.3068	K PtCl	KCI	3.2602	0.5218	MgCO	ČO ₁	1.9164
0.2844	K.PtCl	K2CO1	3.5177	0.6013	Mg(HCO ₂) ₂	ČO	1.6629
0.4159	K,PtCl	KNO.	2.4041	5.7894	MgO	BaSO4	0.1727
0.1938	K,PtCl	K ₂ O	5.1609	1.7590	MgO	Cl	0.5685
0.3585	K,PtCl	K,804	2.7897	1.0913	MgO	CO ₂	0.9164
1.9521	K ₂ PtCl ₄	K2Al2(SO4)4		2.4325	MgO	H ₂ SO ₄	0.4111
3,00-2		24H ₂ O	0.5120	2.3621	MgO	MgCl ₂	0.4234
2.0545	K.PtCl	K,Cr,(SO,),	1	2.0914	MgO	MgCO ₂	0.4782
3,000		24H ₂ O	0.4964	3.6294	MgO	Mg(HCO ₂) ₂	0.2755
0.4013	K.PtCl	Pt	2.4906	2.7619	MgO	$Mg_2P_2O_7$	0.3621
0.6931	K ₂ PtCl ₂	PtCl ₄	1.4427	2.9859	MgO	MgSO4	0.3349
0.8785	K ₂ PtCl ₄	PtCL.5H.O.	1.1383	3.5236	MgO	Na.804	0.2838
0.5170	K-SiF	F	1.9342	0.7951	MgO	8	1.2578
0.5444	K.SiF.	HF	1.8368	1.9859	MgO	SO	0.5036
0.6545	K.SiF.	H-SiF	1.5279	1.3932	$Mg_1P_2O_7$	Ca ₄ (PO ₄₎₂	0.7178

A'	A	В	В'	Α'	A	В	B'
0.8806	Mg ₂ P ₃ O ₇	H,PO,	1.1356	0.5303	MnSO ₄	SO ₂	1.8858
0.2184	Mg.P.O	Mg	4.5789	0.0000	MIII304	503	1.0000
1.2784	Mg ₂ P ₃ O ₇	Mg(CH ₂ CO ₂) ₂	0.7822	1.5000	Mo	MoO ₃	0.6867
0.8552	Mg ₂ P ₂ O ₇	MgCl ₂	1 1692	2.0022	Mo	MoS.	0.4995
1.8260	Mg ₂ P ₂ O ₇	MgCl ₂ ·6H ₂ O	0.5477	3.8250	Mo	PbMoO ₄	0.2615
0.7572	Mg ₂ P ₂ O ₇	MgCO	1.3206	1.3348	MoO ₂	MoS ₃	0.7492
1.3141	Mg ₂ P ₁ O ₇	Mg(HCO ₃) ₂	0.7610		MoO ₃	(NH ₄) ₂ MoO ₄ .	0.7344
0.3621	Mg.P.O.	MgO	2.7619	1.0863	MoO ₃	(NH ₄) ₄ PO ₄	0.101
1.0811	Mg ₂ P ₂ O ₇	MgSO4	0.9250	1.0000	141003	(MoO ₃) ₁₂	0.9205
2.2135	Mg ₂ P ₂ O ₇	MgSO ₄ ·7H ₂ O	0.4516	2.5500	MoO ₃	PbMoO ₄	0.3923
1.0781	Mg.P.O.	NaH ₂ PO	0.9276		MoO4 (NH4)2	PbMoO ₄	0.5342
1.4731	Mg ₂ P ₂ O ₇	Na PO	0.6789	1.0121	141004 (14114)2	101/1004	0.0012
8.2170	Mg ₂ P ₂ O ₇	Na ₂ HPO ₄	0.0700	3.3564	N	HNO2	0.2979
	112 g21 10 1	12H ₂ O	0.3109	4.4986	N	HNO.	0.2223
3.4144	Mg ₂ P ₂ O ₇	Na PO	0.0100	6.0757	N	KNO ₂	0.1646
0.222	112812 101	12H ₂ O	0.2929		N	KNO.	0.1385
1.2755	Mg ₂ P ₄ O ₇	Na ₂ HPO ₄		4.9263	N	NaNO ₂	0.1380
1.2758	Mg ₂ P ₂ O ₇	Na ₂ SO ₄	0.7838	3.2841	N	NO ₃	0.3045
1.0336	Mg ₂ P ₂ O ₇	(NH ₄)H ₂ PO ₄ .		2.7131	N	N ₂ O ₃	0.3686
1.1865	Mg ₂ P ₂ O ₇	(NH ₄) ₂ HPO ₄ .		3.2841	N	N ₂ O ₄	0.3045
0.2787	Mg ₂ P ₂ O ₇	P		3.8551	N	N ₂ O ₅	0.2594
0.6379	Mg ₂ P ₂ O ₇	P ₂ O ₅		6.0685	N	NaNO ₃	0.1648
1.9389	MgSO4	BaSO		1.2159	N	NH	0.8227
0.8147	MgSO	H,SO	1.2274		N	Pt	0.1435
2.0478	MgSO	MgSO ₄ ·7H ₂ O	0.4884	2.8576	N	SO ₃	0.3499
0.6651	MgSO	SO ₁	1.5036				0.0100
0.3248	MgSO ₄ ·7H ₂ O	SO	3.0786	3.4748	Na	Br	0.2878
0.9469	MgSO.7H,O	BaSO4	1.0560		Na	Ci	0.6486
				5.5182	Na	I	0.1812
2.0923	Mn	MnCO3	0.4779	4.4747	Na	NaBr	0.2235
1.2913	Mn	MnO	0.7744	2.5417	Na	NaCl	0.3934
1.5826	Mn	MnO2	0.6319	2.3044	Na	Na ₂ CO ₃	0.4340
1.4369	Mn	Mn₂O₃	0.6959	1.8261	Na	NaF	0.5476
1.3884	Mn	Mn₃O₄	0.7203	3.6525	Na	NaHCO	0.2740
2.5846	Mn	Mn ₂ P ₂ O ₇	0.3869	6.5183	Na	NaI	0.1534
1.5838	Mn	MnS		1.3478	Na	Na ₂ O	0.7419
0.3828	MnCO ₃	CO2	2.6121	1.7395	Na	NaOH	0.5750
1.2352	MnCO ₃	Mn ₂ P ₃ O ₇	0.8096	2.7404	Na	Na ₂ SO ₃	0.3649
0.4973	Mn(HCO ₃) ₃	CO3	2.0108	3.0885	Na	Na ₂ SO ₄	0.3238
0.6204	MnO	CO₂	1.6119	0.6224	Na ₂ Al ₂ O ₄	Al ₂ O ₁	1.6067
1.6203	MnO	MnCO ₃	0.6172	0.1399	Na ₂ Al ₂ (SO ₄) ₄		
1.2256	MnO	MnO_2	0.8159		- 24H₂O	8	7.1493
2.1287	MnO	MnSO ₄	0.4698	0.6925	Na ₇ B ₄ O ₇	B ₂ O ₃	1.4441
2.0016	MnO	Mn ₂ P ₂ O ₇		1.2287	Na ₂ B ₄ O ₇	H ₂ BO ₂	0.8139
1.1128	MnO	Mn ₂ O ₃	0.8987	0.3657	Na ₂ B ₄ O ₇		
1.2266	MnO	MnS	0.8153		·10H ₂ O	B_3O_3	2.7347
1.1289	MnO	SO	0.8859	0.6488	ditto	H ₂ BO ₂	1.5412
2.0022	Mn ₂ O ₂	KMnO	0.4995	1.3202	ditto	KBF4	0.7575
0.9662	Mn ₃ O ₃	Mn ₃ O ₄		1.0482	NaBr	Ag	0.9540
1.9130	Mn ₂ O ₃	MnSO ₄		1.8247	NaBr	AgBr	0.5480
0.4062	Mn ₂ O ₂	8	2.4619		NaBr	Br	1.2878
1.1014	Mn ₃ O ₄	MnO2	0.9080		NaCl	Ag	0.5419
7.5949	Mn_3O_4	K₂MnO₄	0.3869	2.4519	NaCl	AgCl	0.4078
MOTO	360						
2,5848 1.7357 1.5458	MnSO	MnSO ₄ BaSO ₄	0.5761 0.6469	2.9061	NaCl	AgNO₃ CaO	0.3441 2.0852

XVIII.—CONVERSION FACTORS (Continued)

A'	_ A	В	B'	A'	A	В	B!
0.6066	NaCl	C1	1.6486	1.6003	NaH.PO.	NaH ₂ PO ₄	
0.6239	NaCl	HCl	1.6030			·4H ₂ O	0.6249
0.8389	NaCl	H ₂ SO ₄	1.1920	0.2582	NaH ₂ PO ₄ *	Na ₂ O	3.8728
1.8211	NaCl	NaClO	0.5491	0.2585	NaH.PO.*	P	3.8678
2.1632	NaCl	NaClO ₄	0.4623	0.5917	NaH.PO.	P.O	1.6900
0.9066	NaCl	Na ₂ CO ₂	1.1030	0.3453	NaH,PO,t	H ₂ SO ₄	2.8964
1.4370	NaCl	NaHCO4	0.6959	2.5220	Na ₂ HPO ₄	Na ₂ HPO ₄	
1.2149	NaCl	Na ₂ HPO ₄	0.8231			·12H₂O	0.3965
1.7803	NaCl	NaHSO:	0.5617	0.4365	Na ₂ HPO ₄	Na ₂ O	2.2911
0.5303	NaCl	Na ₂ O	1.8858	0.9366	Na ₂ HPO ₄	Na P.O	1.0677
1.2151	NaCl	Na ₂ SO ₄	0.8230	0.5001	Na ₂ HPO ₄	P ₂ O ₅	1.9995
1.1656	NaCl	ZnCl ₂	0.8579	0.7565	Na ₂ H ₂ P ₂ O ₇	NaHCO:	1.3219
0.3331	NaClO ₃	<u>Cl</u>	3.0023	0.2792	Na ₂ H ₂ P ₂ O ₇	Na ₂ O	3.5822
0.2896	NaClO ₄	C1	3.4535	0.6397	Na ₂ H ₂ P ₂ O ₇	P ₂ O ₄	1.5632
2.2022	Na ₂ CO ₄	BaSO ₄	0.4541	0.3395	Na(NH ₄)	n o	0.0444
0.9441	Na ₂ CO ₃	CaCO	1.0593	0.0000	HPO4·4H ₂ O	P ₂ O ₃	2.9441
0.5290	Na ₂ CO ₃	CaO	1.8905	0.8968	Na ₃ PO ₄	H ₂ SO ₄ Mg ₂ P ₂ O ₇	1.1151 1.4731
1.1327	Na ₂ CO ₃	CH₃CO₂H	0.8828	0.6789	Na ₃ PO ₄ Na ₃ PO ₄	Na ₂ O	1.7639
0.4151	Na ₂ CO ₃	CO ₂	2.4091 1.4533	0.5669 1.2991	Na ₄ PO ₄	Na ₂ SO ₄	0.7698
0.6881	Na ₂ CO ₃	HCl	1.0807	2.3179	Na ₁ PO ₄	Na ₄ PO ₄	0.1000
0.9253	Na ₂ CO ₃	H ₂ SO ₄ K ₄ CO ₄	0.7670	4.0110	Hapt Of	12H ₂ O	0.4314
1.3038	Na ₂ CO ₃ Na ₂ CO ₂	Na	2.3044	0.4321	Na ₁ PO ₄	P ₂ O ₃	2.3091
0.4340 1.1030	Na ₂ CO ₁	NaCl	0.9066	0.4331 2.2432	NaHSO	BaSO ₄	0.4458
1.5850	Na ₂ CO ₂	NaHCO.	0.6309	0.4712	NaHSO	$H_2\widetilde{SO}_4$	2.1222
1.9637	Na ₂ CO ₂	NaHSO3	0.5092	0.5617	NaHSO4	NaCl	1.7803
0.7549	Na ₂ CO ₃	NaOH	1.3247		NaHSO	Na ₂ O	3.3570
0.5849	Na ₂ CO ₃	Na ₂ O	1.7097	0.2979 0.9134	NaHSO:	Na ₂ S ₂ O ₅	1.0948
0.7320	Na ₂ C ₂ O ₄	H ₂ SO ₄	1.3661	0.3081	NaHSO3	8	3.2460
1.9951	Na ₂ CrO ₄	PbCrO ₄	0.5014	0.6156	NaHSO:	SO ₂	1.6244
1.2788	Na ₂ Cr ₂ O ₇	Fe	0.7820	1.5662 0.8466	NaI	AgI	0.6385
0.3744	$Na_2Cr_2O_7$	H ₂ SO ₄	2.6711	0.8466	NaI	<u>I.</u>	1.1812
1.2367	Na ₂ Cr ₂ O ₇	Na ₂ CrO ₄	0.8086	0.1534	NaI	Na	6.5183
0.9294	NaF	CaF ₁	1.0760	0.2068	NaI	Na ₂ O	4.8361
0.9135	Na ₂ HAsO ₃	Mg ₂ As ₂ O ₇	1.0947	0.6413	NaIO	I	1.5594
0.4031	Na ₂ HA ₈ O ₄	As	2.4809	0.7413	NaNO ₃	HNO4 H ₂ SO4	1.3490 1.7334
0.6182	Na ₂ HAsO ₄	As ₁ O ₄	1.6177	0.5769	NaNO	KNO.	0.8408
0.8349	Na ₂ HA ₈ O ₄	Mg ₂ As ₂ O ₇	1.1978 1.4721	1.1894 0.8117	NaNO ₄	NaNO.	1.2319
0.6793	NaHCO	$Al_2(SO_4)_3$ $Ca(H_2PO_4)_4$	0.7175	0.3647	NaNO	Na ₂ O	2.7423
1.3938	NaHCO.* NaHCO.*	CaH ₂ P ₂ O ₇	0.7773	0.2004	NaNO:	NH.	4.9911
1.2866	NaHCO:	CaH ₆ O ₆	1.1197	0.3530	NaNO ₃	NO	2.8327
0.8931 0.5238	NaHCO:	CO2	1.9092	0 6353	NaNO	N ₂ O ₅	1.5740
0.5838	NaHCO	H ₂ SO ₄	1.7129	1.2258	NaOH	H ₂ SO ₄	0.8158
1.0251	NaHCO4	K ₂ Al ₂ (SO ₄) ₄ .	0.9756	0.7748	NaOH	Na ₂ O	1.2906
2.2395	NaHCO	KHC.H.O	0.4465	1.1766	NaOH	Na ₂ SiF ₆	0.8499
0.9284	NaHCO	KMnO ₄	1.0760	2.0400	NaOH	(NH ₄),PO ₄	
0.2740	NaHCO	Na	3.6525			(MoO ₄) ₁₃	0.4902
0.6309	NaHCO:	Na ₂ CO ₂	1.5851	3.7651	Na ₂ O	BaSO ₄	0.2656
1.4291	NaHCO.*	NaH ₂ PO ₄	0.6997	$1.9365 \\ 2.6463$	Na ₂ O	CH.CO.H	0.5164
1.3219	NaHCO.*	Na ₂ H ₂ P ₂ O ₇	0.7565	2.6463	Na ₂ O	CH,CO,Na	0.3779
0.3690	NaHCO ₁	Na ₂ O	2.7099	1.5820	Na ₂ O	H.SO4	0.6321
0.4085	NaH.PO.*	H ₂ SO ₄	2.4482	0.7419	Na ₂ O	Na	1.3478
0.6997	NaH ₂ PO ₄ *	NaHCO	1.4291	1.8858 1.7097	Na ₂ O	NaCl Na ₂ CO ₂	0.5849
	•	1		1.7097	Na ₂ O	Tragoog	U.002F
		<u> </u>	1				

 $A \times A' = B$

B×B'=A

† Methyl orange.

^{*}Phenolphthalein

XVIII.—CONVERSION FACTORS (Continued)

A' A B B' A' B B' A' B B' A' C C C C C C C C C					-			
2.7919 Na ₂ O Na ₂ H ₂ O 0. 3485 8.6929 NH ₃ H ₃ O 0. 2704 3.8728 Na ₂ O Na ₂ H ₂ PO 0. 2792 4.9969 NH ₃ H ₅ O 0. 0. 3473 3.8728 Na ₂ O Na ₂ H ₂ PO 0. 2792 4.9969 NH ₃ H ₅ O 0. 0. 3473 3.8720 Na ₂ O Na ₂ O Na ₂ H ₂ PO 0. 2792 4.9969 NH ₃ K ₃ O 0. 0. 2001 3.8570 Na ₂ O Na ₂ O Na ₂ O 0. 0. 3474 0.8227 3.7422 Na ₂ O Na ₂ O Na ₂ O 0. 0. 3474 0.8227 3.916 Na ₂ O Na ₂ O Na ₂ O 0. 0. 3484 3.2916 Na ₂ O Na ₂ O Na ₂ O 0. 0. 3484 3.2916 Na ₂ O Na ₂ O 0. 0. 3484 3.2916 Na ₂ O Na ₂ O 0. 0. 3484 3.2916 Na ₂ O Na ₂ O 0. 0. 3484 3.2916 Na ₂ O Na ₂ O 0. 0. 3484 3.2916 Na ₂ O Na ₂ O 0. 3885 0. 0.942 3.6922 Na ₂ O 0. Na ₂ O 0. 0. 3686 3.2916 Na ₂ O Na ₂ O 0. 3885 0. 0. 4911 3.2922 Na ₂ O Na ₂ O 0. 3826 3.795 3.29215 Na ₂ O Na ₂ O 0. 3826 3.795 3.0665 Na ₂ O Na ₂ O 0. 3826 3.795 3.0665 Na ₂ O Na ₂ O 0. 3826 3.795 3.0665 Na ₂ O Na ₂ O 0. 3826 3.795 3.0665 Na ₂ O Na ₂ O 0. 3826 3.795 3.1458 Na ₂ O Na ₂ O 0. 3626 3.795 3.1468 Na ₂ O Na ₂ O 0. 3626 3.795 3.1468 Na ₂ O Na ₂ O Na ₂ O 0. 3626 3.795 3.1468 Na ₂ O Na ₂ O Na ₂ O 0. 3626 3.795 3.1468 Na ₂ O Na ₂ O Na ₂ O 0. 3	A'	A	B	B'_	A'	A _	<u>B</u>	B'
2.7099 Na ₂ O Na ₁ HOO ₁ 0.3805 8.6909 NH ₃ H ₁ NO ₁ 0.2704 3.8728 Na ₂ O Na ₂ H ₂ PO ₁ 0.2582 2.8702 NH ₃ H ₄ SO ₁ 0.2013 3.8520 Na ₂ O Na ₂ H ₂ PO ₁ 0.2704 4.9969 NH ₃ H ₅ O ₁ 0.2013 3.8520 Na ₂ O Na ₂ H ₃ PO ₁ 0.2704 4.9969 NH ₃ K _N O ₁ 0.2013 3.8520 Na ₂ O Na ₂ O Na ₂ H ₃ O 0.2979 5.9364 NH ₃ K _N O ₁ 0.2011 1.2159 Na ₂ O Na ₂ O Na ₂ O Na ₂ O 0.2974 4.0617 NH ₃ N ₃ N ₁ N ₁ 1.2159 1.2006 Na ₂ O Na ₂ O Na ₂ O 0.0014 0.2748 4.0617 NH ₃ Na ₃ O ₁ 0.2603 Na ₂ O Na ₂ O Na ₂ O 0.0014 0.0014 NH ₃ N ₃ O 0.0014 0.0014 1.7639 Na ₂ O Na ₂ O Na ₂ O 0.0014 0.0014 NH ₃ N ₃ O 0.0014 0.0014 1.7639 Na ₂ O Na ₂ O 0.0014 0.0014 1.7639 NH ₃ O 0.0014 1.2992 Na ₂ O 0.0014 Na ₂ O 0.0014 0.0014 NH ₃ O 0.0014 1.2992 Na ₂ O 0.0014 Na ₂ O 0.0014 0.0014 1.2014 Nh ₃ O 0.0014 1.2014 Nh ₃ O 0.0014 1.2014 Nh ₃ O 0.0014 1.2014 Nh ₃ O 0.0014 1.2014 Nh ₃ O 0.0014 1.2014 Nh ₃ O 0.0014 1.2014 Nh ₃ O 0.0014 1.2014 Nh ₃ O 0.0014 1.2014 Nh ₃ O 0.0014 1.2014 Nh ₃ O 0.0014 1.2014 Nh ₃ O 0.0014 1.2014 Nh ₃ O 0.0014 1.2014 Nh ₃ O 0.0014 1.2014 Nh ₃ O 0.0014 1.2014 Nh ₃ O 0.0014 1.2014 Nh ₃ O 0.0014 Nh ₃ O 0.0014 1.2014 Nh ₃ O 0.0014 Nh ₃ O 0.0014 1.2014 Nh ₃ O 0.0014 Nh ₃ O 0.0014 1.2014 Nh ₃ O 0.0014 1.2014 Nh ₃ O 0.0014 Nh ₃ O 0.0014 1.2014 Nh ₃ O 0.0014 Nh ₃ O	1.3548	Na ₂ O	NaF		1.1663	Nd	Nd ₂ O ₃	0.8574
3.8728 NagO NalHpO. 0.2582 2.8792 NH. H,SO. 0.3478 3.6822 NagO NalHpO. 0.2797 5.9384 NH. KNO. 0.2001 3.8570 NagO NalHpO. 0.2979 5.9384 NH. KNO. 0.2001 3.8570 NagO NalNo. 0.3847 0.8227 NH. N 1.2159 1.2906 NagO NalO. 0.3047 0.8227 NH. N 1.2159 1.2906 NagO NalO. 0.3038 4.9911 NH. NaNO. 0.2488 3.2916 NagO NalPO. 0.5089 2.8207 NH. NaNO. 0.2488 3.2916 NagO NalPO. 0.5089 2.8207 NH. NaNO. 0.2048 1.7639 NagO NalPO. 0.5089 2.8207 NH. NANO. 0.2048 1.2562 NagO NalSO. 0.4918 3.8785 NH. (NH.),HPO. 0.3345 1.2562 NagO NalSO. 0.4918 3.8785 NH. (NH.),HPO. 0.1480 3.0915 NagO NalSO. 0.4918 3.8785 NH. (NH.),HPO. 0.1480 3.0965 NagO NalSO. 0.3921 2.0577 NH. NH.OH. 0.4860 3.0965 NagO NalSO. 0.3261 13.035 NH. (NH.),HPO. 0.1480 3.0965 NagO NalSO. 0.3261 3.8790 NH. NH.OH. 0.4860 3.0965 NagO NalSO. 0.3234 NH. (NH.),HPO. 0.3518 1.2915 NagO NalSO. 0.3234 NH. (NH.),HPO. 0.3184 1.2904 NalS. BaSO. 0.3344 NH. NH.OH. NAO. 0.3163 1.2915 NagO SO. 0.0743 0.1134 NH. NH.OH. 0.4860 NalS. CdS. 0.6404 0.376 ditto NH., NAO. 0.3163 1.2916 NasS BaSO. 0.3344 NH. NH.OH. NAO. 0.3163 1.2916 NasS BaSO. 0.3344 NH. NH.OH. NAO. 0.3163 1.2916 NasS BaSO. 0.3344 NH. NH.OH. NH.OH. NAO. 0.3163 1.2916 NasS BaSO. 0.3344 NH. NH.OH. NH.			NaHCO ₁					
3.8522							HNO ₃	
1.2560								
1.2900								
1,2006								
3.2916			Nanu				NaNO.	
1.7899							NaNO.	
1.2592 NaiO								
2.0834 Na ₁ C			Na ₂ S				NH.Cl	
2 29015 Na ₂ O Na ₈ SO Na ₉ O Na ₈ SO O 0 3921 2 0577 NH _H NH ₄ OH O 4860 2 5503 Na ₇ O Na ₈ SO O Na ₈ SO O 0 3921 2 0577 NH _H NH ₄ OH O 4860 Na ₇ O Na ₈ SO Na ₈ O O 0 3261 13.035 NH _H NH ₄ O N Nh ₄ O O 0.7673 NH ₄ NH ₄ O N Nh ₄ O O 0.7673 NH ₄ NH ₄ O N Nh ₄ O O 0.3153 Nh ₈ O Na ₈ O Na ₈ O Na ₈ O O 0 3344 (SO ₄) 24H ₄ O (SO ₄ O O 0 3153 Nh ₈ O Na ₈ S Nh ₈ O Na ₈ S O Na ₈ O O 0 1.2598 Nh ₄ O O 0.3153 Nh ₄ O O 0.3153 Nh ₈ O Nh ₈ S Nh ₈ O Na ₈ S Nh ₈ O Nh ₈			Na ₂ SO ₂				(NH ₄),HPO ₄ .	0.2578
2.5503 Na ₂ O Na ₂ SO ₁ 0.3921 2.0577 NH ₁ NH ₁ OH ₁ 0.4860 3.0665 Na ₂ O Na ₂ P ₁ O ₁ 0.3261 13.035 NH ₁ (NH ₁) ₂ P ₁ Cl ₁ 0.0767 1.1458 Na ₂ O P ₁ O ₁ 0.4660 3.8790 NH ₁ NH ₁ (NH ₁) ₂ SO ₄ 0.2578 NH ₁ 1.2915 Na ₂ O SO ₁ 0.7743 0.1127 (NH ₁) ₁ Al ₁ (SO ₂) ₁ 24H ₀ O Na ₂ S BaSO ₄ 0.3344 (SO ₂) ₂ 24H ₀ O Na ₂ S (Na ₂ S H ₃ S 0.5404 0.0376 ditto Na ₂ S 1.2564 Na ₂ S H ₃ S 0.5404 0.0376 ditto SO ₂ 7.70719 1.2564 Na ₂ S H ₃ S 0.22998 0.1414 ditto SO ₂ 2.2908 0.1414 1.2564 Na ₂ S Na ₂ S 0.4004 1.2592 2.6793 NH ₂ C 1.6 Cl 1.5088 1.8515 Na ₂ SO ₁ BaSO ₄ 0.5401 0.6817 Na ₂ SO ₁ BaSO ₄ 0.5401 0.6817 NA ₂ C 1.508 Na ₂ S 1.8515 Na ₂ SO ₁ BaSO ₄ 0.5401 0.6817 NA ₂ C 1.1 1.2508 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2			Na ₂ SO ₄	0.4364		NH		
2,1458	2.5503	Na ₂ O		0.3921			NH _O H	
1. 1458 Na ₄ O P ₁ O ₁ 0.8727 3.1714 NH ₁ N ₁ O ₁ 0.3153 1. 2915 Na ₄ O SO ₁ 0.7743 0.1127 1. 2804 Na ₄ S BaSO ₄ 0.5404 0.0376 ditto NH ₁ 26.6235 0.4365 Na ₄ S H ₅ S 2.2908 0.1414 ditto SO ₁ 2.8320 0.7942 Na ₄ S H ₅ SO ₂ 0.7959 0.3531 ditto SO ₁ 2.8320 0.4108 Na ₄ S Na ₄ O 1.2592 2.6793 NH ₄ Cl AgCl 0.3732 0.4108 Na ₄ S S 2.4348 0.6628 NH ₄ Cl Cl 1.6088 1.8515 Na ₄ SO ₁ BaSO ₄ 0.5401 0.6817 NH ₄ Cl HCl 1.4669 0.3890 Na ₄ SO ₁ H ₅ SO ₂ 2.5706 0.9675 NH ₄ Cl H ₅ SO ₄ 1.0336 0.4918 Na ₄ SO ₃ Na ₄ SO 2.0334 0.4288 NH ₄ Cl H ₅ SO ₄ 1.0336 0.4918 Na ₄ SO ₃ Na ₄ SO ₄ 1.9677 0.2578 0.2541 Na ₄ SO ₄ BaSO ₄ 0.3387 0.1065 NH ₄)HPO ₄ NH ₄ 0.67576 0.2541 Na ₄ SO ₄ BaSO ₄ 0.3387 0.1065 NH ₄ O ₄ NH ₄ D ₄ NH ₄ 0.67576 0.2541 Na ₄ SO ₄ BaSO ₄ 0.3387 0.1065 NH ₄ D ₄ D ₄ D ₄ D ₄ D ₄ D ₄ D ₄ D ₄ D ₄ D		Na ₂ O	$Na_2S_2O_3$				(NH4),PtC4.	
1.2915		Na ₂ O	Na ₄ P ₂ O ₇			NH4		
2.9904 Na.S. BaSO. 0.3344 1.8506 Na.S. CdS. 0.5404 0.0376 0.4365 Na.S. H.S. 0.5904 0.0376 0.4365 Na.S. H.S. 0.7959 0.3531 0.7942 Na.S. Na.O. 1.2592 2.6793 0.4108 Na.S. Na.O. 1.2592 2.6793 0.4108 Na.S. S. Na.O. 1.2592 2.6793 0.4108 Na.S. S. 0.24348 0.6628 1.8515 Na.SO. H.SO. 0.5401 0.6817 NH.Cl. Cl. 1.5088 1.8515 Na.SO. H.SO. 1.5359 0.9167 0.6511 Na.SO. H.SO. 2.5706 0.9675 0.4918 Na.SO. Na.SO. 1. 0.4966 0.1480 0.4918 Na.SO. Na.SO. 1. 0.4966 0.1480 0.4918 Na.SO. Na.SO. 1. 9677 0.2578 0.2541 Na.SO. 7160 0.3850 Na.SO. Na.SO. 0.3387 0.0165 0.5082 Na.SO. Na.SO. 0.3387 0.0165 1.5696 Na.SO. BaSO. 0.3387 0.0165 1.5696 Na.SO. CaO 2.5338 0.4393 0.3947 Na.SO. CaO 2.5338 0.4393 0.3947 Na.SO. CaO 2.5338 0.4393 0.3947 Na.SO. CaO 2.5338 0.4393 0.3947 Na.SO. Ma.O. 2.000 0.3880 Na.SO. Ma.SO. 1.4484 1.4392 (NH.).PtCl. H.SO. 0.6944 1.2267 Na.SO. MgO 3.5236 0.7422 0.3947 Na.SO. MgO 3.5236 0.7422 0.3949 Na.SO. MgO 3.5236 0.7422 0.3949 Na.SO. MgO 3.5236 0.7422 0.3949 Na.SO. N	1.1458	Na ₂ O*	P ₂ O ₁			NHI	N ₂ O ₁	0.0100
1.8506			Dogo.		0.1127	(SO) 24HO	ALO.	8 8738
0.4365					0.0376			
1.2564 Na ₂ S.								
0.7942 Na ₂ S Na ₃ C 1.2592 2.6793 NH ₁ Cl AgCl 0.3732 0.4108 Na ₂ S S 2.4348 0.6628 NH ₁ Cl 1.5088 1.8515 Na ₂ SO ₁ BaSO ₄ 0.5401 0.6817 NH ₁ Cl HCl 1.4669 0.6511 Na ₂ SO ₁ H ₂ SO ₄ 2.5706 0.9675 NH ₁ Cl H ₂ SO ₄ 1.0909 0.3890 Na ₂ SO ₁ H ₂ SO ₄ 2.5706 0.9675 (NH ₁)H ₂ PO ₄ NH ₁ Cl H ₂ SO ₄ 1.0938 0.4918 Na ₂ SO ₁ Na ₂ SO ₂ 1.9677 0.2578 (NH ₁)H ₂ PO ₄ NH ₁ 6.7576 0.4918 Na ₂ SO ₁ Na ₂ SO ₂ 1.9677 0.2578 (NH ₁)H ₂ PO ₄ NH ₁ 3.8785 0.2541 Na ₂ SO ₄ BaSO ₄ 0.3387 0.0165 (NH ₁) ₁ PO ₄ NH ₁ 3.8785 1.5696 Na ₂ SO ₂ BaSO ₄ 0.3387 0.0165 (NH ₁) ₁ PO ₄ NH ₂ Cl 1.5696 1.5696 Na ₂ SO ₄ BaSO ₄ 0.6371 0.0378 (MO ₂) ₁₂ 1.6431 Na ₂ SO ₄ BaSO ₄ 0.6086 0.2838 (NH ₁) ₁ PCl ₄ HNO ₄ 3.5232 1.1547 Na ₂ SO ₄ BaSO ₄ 0.6086 0.2838 (NH ₁) ₁ PCl ₄ HNO ₄ 3.5232 1.1547 Na ₂ SO ₄ CaO 2.5338 0.4932 (NH ₁) ₁ PCl ₄ PtCl ₄ 1.0884 1.2267 Na ₂ SO ₄ H ₂ SO ₄ 0.8660 0.9183 (NH ₁) ₁ PCl ₄ PtCl ₄ 1.0884 1.2267 Na ₂ SO ₄ H ₂ SO ₄ 0.8660 0.9183 (NH ₁) ₁ PCl ₄ PtCl ₄ 1.3844 1.2267 Na ₂ SO ₄ H ₂ SO ₄ 0.8152 1.7665 (NH ₁) ₂ SO ₄ H ₂ SO ₄ 0.6948 1.2267 Na ₂ SO ₄ M ₂ SO ₄ 0.8152 1.7665 (NH ₁) ₂ SO ₄ H ₂ SO ₄ 0.6948 1.2267 Na ₂ SO ₄ Na ₂ SO ₄ Na ₂ SO ₄ 1.2753 0.2120 (NH ₁) ₂ SO ₄ H ₂ SO ₄ 0.6948 1.2267 Na ₂ SO ₄ Na ₂ SO ₄ Na ₂ SO ₄ 1.2439 (NH ₁) ₂ SO ₄ H ₂ SO ₄ 0.2032 1.6904 Na ₂ SO ₄ Na ₂ SO ₄ Na ₂ SO ₄ 1.2498 (NH ₁) ₂ SO ₄ H ₂ SO ₄ 0.2032 1.6904 Na ₂ SO ₄ Na ₂								
0.4108		Na S.					AgCl	0.3732
1.8515 Na ₈ SO ₁		Na ₂ S		2.4348	0.6628	NH Cl	C[
0.8890	1.8515					NH ₄ Cl	HCl	
2.0135 Na ₂ SO ₁ I 0.4966 0.1480 (NH ₄) ₁ HPO ₄ NH ₁ 6.7576 0.4918 Na ₂ SO ₁ Na ₄ O ₂ 2.0334 0.8428 NH ₄ ₂ HPO ₄ NH ₁ 3.8785 0.2541 Na ₂ SO ₄ Na ₂ SO ₄ SO ₂ 3.9356 0.4896 (NH ₄) ₁ HPO ₄ NH ₁ 3.8785 0.2541 Na ₂ SO ₄ Na ₂ SO ₄ Na ₂ SO ₄ 0.3387 0.0165 (NH ₄) ₁ HPO ₄ NH ₁ 3.8785 0.2541 Na ₂ SO ₄ Na ₂ SO ₄ Na ₂ SO ₄ 0.6371 0.0378 (MO ₂) ₁₂ (MO ₂) ₁₂ P ₂ O ₄ 0.60476 (NH ₄) ₂ PO ₄ (MO ₂) ₁₂ P ₂ O ₄ 0.60476 (NH ₄) ₂ PO ₄ (MO ₂) ₁₂ P ₂ O ₄ 0.60476 (NH ₄) ₂ PO ₄ (MO ₂) ₁₂ P ₂ O ₄ 0.60476 (NH ₄) ₂ PO ₄ (MO ₂) ₁₂ P ₂ O ₄ 0.60476 P ₂ O ₄ 0.60476 (NH ₄) ₂ PO ₄ (MO ₂) ₁₂ P ₂ O ₄ 0.60476 (NH ₄) ₂ PO ₄ (MO ₂) ₁₂ P ₂ O ₄ 0.60476 (NH ₄) ₂ PO ₄ (MO ₂) ₁₂ P ₂ O ₄ 0.60476 (NH ₄) ₂ PO ₄ (MO ₂) ₁₂ P ₂ O ₄ 0.60476 (NH ₄) ₂ PO ₄ (MO ₂) ₁₂ P ₂ O ₄ 0.60476 (NH ₄) ₂ PO ₄ (MO ₂) ₁₂ P ₂ O ₄ 0.60476 (NH ₄) ₂ PO ₄ (MO ₂) ₁₂ P ₂ O ₄ 0.60476 (NH ₄) ₂ PO ₄ (MO ₂) ₁₂ P ₂ O ₄ 0.60476 (NH ₄) ₂ PO ₄ (MO ₂) ₁₂ P ₂ O ₄ 0.60476 (NH ₄) ₂ PO ₄ (MO ₂) ₁₂ P ₂ O ₄ 0.60476 (NH ₄) ₂ PO ₄ (MO ₂) ₁₂ P ₂ O ₄ 0.60476 (NH ₄) ₂ PO ₄ (MO ₂) ₁₂ P ₂ O ₄ 0.60476 (NH ₄) ₂ PO ₄ (MO ₂ O ₄) ₁₂ P ₂ O ₄ 0.60476 (NH ₄) ₂ PO ₄ (MO ₂ O ₄) ₁₂ P ₂ O ₄ 0.60476 (NH ₄) ₂ PO ₄ P ₂ O ₄ 0.60476 (NH ₄) ₂ PO ₄ P ₂ O ₄ 0.60476 (NH ₄) ₂ PO ₄ P ₂ O ₄ 0.60476 (NH ₄) ₂ PO ₄ P ₂ O ₄ 0.60476 (NH ₄) ₂ PO ₄ P ₂ O ₄ 0.60476 (NH ₄) ₂ PO ₄ (NH ₄) ₂ PO ₄ 0.60476 (NH ₄	0.6511					NH ₄ Cl	H ₂ SO ₄	
0.4918 Na ₂ SO ₃ . Na ₄ O. 2.0334 0.8428 (NH ₄) ₃ HPO ₄ . Mg ₂ P ₂ O ₇ . 1.1856 0.2541 Na ₂ SO ₃ . SO ₃ . 3.9356 0.4896 (NH ₄) ₄ MO ₄ . Mo. 2.0425 Na ₂ SO ₃ . Na ₂ SO ₃ . BaSO ₄ . 0.3387 0.0165 (NH ₄) ₂ MO ₄ . Mo. 2.0425 1.5696 Na ₂ S ₂ O ₃ . Na ₂ S ₂ O ₃ . Na ₂ S ₂ O ₃ . O.66371 0.0378 (NH ₄) ₂ PO ₄ (MoO ₂) ₁₂ 26.424 1.5696 Na ₂ SO ₄ . CaO. 2.5338 0.4393 (NH ₄) ₂ PCI ₆ . HNO ₂ . 3.5232 0.3947 Na ₂ SO ₄ . CaO. 2.5338 0.4393 (NH ₄) ₂ PCI ₆ . HNO ₂ . 3.5232 0.3947 Na ₂ SO ₄ . CaO. 2.5338 0.4393 (NH ₄) ₂ PCI ₆ . HNO ₂ . 3.5232 0.3947 Na ₂ SO ₄ . Ch ₄ CO ₄ Na. 0.8660 0.9188 (NH ₄) ₂ PCI ₆ . PtCI ₆ . 1.0884 0.6904 Na ₂ SO ₄ . MgO. 3.5236 0.7422 (NH ₄) ₂ SO ₄ . H ₂ SO ₄ . 0.6948 (NH ₄) ₂ SO ₄ . Na ₂ SO ₄ . MgO. 3.5236 0.7422 (NH ₄) ₂ SO ₄ . H ₂ SO ₄ . 0.5661 0.2838 Na ₂ SO ₄ . MgO. 3.5236 0.7422 (NH ₄) ₂ SO ₄ . H ₂ SO ₄ . 0.5661 0.2838 Na ₂ SO ₄ . Na ₂ CO ₂ . 1.2758 0.2120 (NH ₄) ₂ SO ₄ . H ₂ SO ₄ . Na ₂ CO ₂ . 1.3403 0.4298 (NH ₄) ₂ SO ₄ . Nh ₄ SO ₄ . Na ₂ CO ₂ . 1.3403 0.4298 (NH ₄) ₂ SO ₄ . Nh ₄ SO ₄ . Na ₂ CO ₂ . 1.3403 0.4298 (NH ₄) ₂ SO ₄ . Nh ₄ SO ₄ . Na ₂ SO ₄ . Na ₂ CO ₂ . 1.4839 4.9225 Ni. Na ₂ SO ₄ . Na ₂			H ₂ SO ₄			(NH ₄)H ₄ PO ₄ .	Mg ₁ P ₂ O ₇	
0.5082			I			(NH4)H2PO4.	Ma PO	
0.2541			Na ₂ U			(NH) HPO		
2.9524 Na ₂ SO ₂ BaSO ₄ 0.3387 0.0165 (MH ₄) ₂ PO ₄ (MoO ₂) ₁₂ P. 60.476 (MoO ₂) ₁₃ O.3347 Na ₂ SO ₄ BaSO ₄ 0.6086 0.2838 (MH ₄) ₂ PtCl ₆ HNO ₄ 3.5232 0.3047 Na ₂ SO ₄ CaO 2.5338 0.4393 (MH ₄) ₂ PtCl ₆ Pt 2.2748 0.6004 Na ₂ SO ₄ H ₂ SO ₄ 0.6086 0.2838 (NH ₄) ₂ PtCl ₆ Pt 2.2748 1.1547 Na ₂ SO ₄ H ₂ SO ₄ 0.8660 0.9188 Na ₂ SO ₄ MgO 3.5236 0.7422 (NH ₄) ₂ SO ₄ H ₂ SO ₄ 0.6948 1.2267 Na ₂ SO ₄ MgO 3.5236 0.7422 (NH ₄) ₂ SO ₄ H ₂ SO ₄ 0.6948 0.2338 Na ₂ SO ₄ MgO 3.5236 0.7422 (NH ₄) ₂ SO ₄ H ₂ SO ₄ 0.5661 0.2838 Na ₂ SO ₄ MgO 3.5236 0.7422 (NH ₄) ₂ SO ₄ H ₂ SO ₄ 0.5661 0.3338 Na ₂ SO ₄ Ng 3.383 0.2578 (NH ₄) ₂ SO ₄ Nh ₄ 3.3879 0.8230 Na ₂ SO ₄ Na ₄ Cl 1.2151 0.5753 (NH ₄) ₂ SO ₄ NH ₄ 3.3879 0.8230 Na ₂ SO ₄ Na ₄ CO ₅ 1.3403 0.4298 (NH ₄) ₂ SO ₄ N ₄ C ₁ 1.7383 0.7461 Na ₂ SO ₄ Na ₄ CO ₅ 1.4839 4.9225 Ni Nh ₂ SO ₄ Na ₄ CO ₅ 1.4839 4.9225 Ni Nh ₄ SO ₄ Na ₄ CO ₅ 1.3403 0.4298 (NH ₄) ₂ SO ₆ H ₂ SO ₄ Na ₄ CO ₅ 1.4839 1.6912 Na ₂ SO ₄ Na ₄ SO ₄ Na ₄ SO ₄ Na ₄ SO ₄ 1.2925 Ni Ni Ni(NO ₂) ₂ 6H ₄ CO 0.2032 1.9894 Na ₂ SO ₄ Na ₂ SO ₄ Na ₄ SO ₄ 1.2691 1.2727 Ni Ni Ni(NO ₂) ₂ 6H ₄ CO 0.2032 1.3877 Na ₂ SO ₄ Na ₂ SO ₄ Na ₂ SO ₅ 1.1269 2.6371 Ni NiSO ₄ 0.3792 1.3877 Na ₂ SO ₄ Na ₂ SO ₄ Na ₂ SO ₅ 1.1269 2.6371 Ni NiSO ₄ Ni ₂ SO ₄ Na ₂ SO ₄			SO.			NH. MOO.		
1.5696			BaSO ₄			(NH.) PO.		
1.6431			Na ₂ S ₂ O ₂	1	0.0100	(MoO ₂)12	P	60.476
0.3847 Na ₂ SO ₄ CaO 2.5338 0.4393 (NH ₁) ₁ PtCl ₄ Pt 2.2748 0.6904 Na ₂ SO ₄ CH ₃ CO ₃ Na 0.8660 0.9188 (NH ₁) ₁ PtCl ₄ PtCl ₄ 1.0884 1.2267 Na ₂ SO ₄ K ₃ SO ₄ 0.8152 1.7665 (NH ₄) ₂ SO ₄ BaSO ₄ 0.5661 0.2838 Na ₂ SO ₄ MgO 3.5236 0.7422 (NH ₂) ₂ SO ₄ H ₃ SO ₄ 1.3473 0.7838 Na ₂ SO ₄ Na 3.8083 0.2578 0.2120 (NH ₂) ₂ SO ₄ Nh ₂ SO ₄ Na 3.8790 0.8230 Na ₂ SO ₄ Na Cl 1.2151 0.5753 (NH ₂) ₂ SO ₄ Nh ₄ 3.8790 0.8230 Na ₂ SO ₄ Na ₂ CO ₅ 1.3403 0.4298 (NH ₄) ₂ SO ₄ Nh ₂ SO ₄ Na ₂ CO ₅ 1.4839 4.9225 Ni Nh ₂ SO ₄ Na ₂ SO ₄ Na ₂ SO ₄ Na ₂ SO ₄ Na ₂ SO ₄ Na ₂ SO ₄ Na ₂ SO ₄ Na ₂ SO ₄ Na ₂ SO ₄ Na ₂ SO ₅ 1.1269 2.6371 Na ₂ SO ₄ Na ₂ SO ₄ Na ₂ SO ₅ 1.1269 2.6371 Na ₂ SO ₄ Na ₂ SO ₄ Na ₂ SO ₅ 1.1269 2.6371 Ni NiSO ₄ 0.2039 Na ₂ SO ₄ Na ₂ SO ₄ Na ₂ SO ₅ 1.1269 2.6371 Ni NiSO ₄ 0.3792 1.8877 Na ₂ SO ₄ Na ₂ SO ₄ Na ₂ SO ₄ 0.4409 2.0720 Ni NiSO ₄ 7H ₂ O 0.3263 Na ₂ SO ₄ Na ₂			•5H.O	0.6371	0.0378	ditto	P ₂ O ₃	26.424
0.3847 Na ₂ SO ₄ CaO 2.5338 0.4393 (NH ₁) ₁ PtCl ₄ Pt 2.2748 0.6904 Na ₂ SO ₄ CH ₃ CO ₃ Na 0.8660 0.9188 (NH ₁) ₁ PtCl ₄ PtCl ₄ 1.0884 1.2267 Na ₂ SO ₄ K ₃ SO ₄ 0.8152 1.7665 (NH ₄) ₂ SO ₄ BaSO ₄ 0.5661 0.2838 Na ₂ SO ₄ MgO 3.5236 0.7422 (NH ₂) ₂ SO ₄ H ₃ SO ₄ 1.3473 0.7838 Na ₂ SO ₄ Na 3.8083 0.2578 0.2120 (NH ₂) ₂ SO ₄ Nh ₂ SO ₄ Na 3.8790 0.8230 Na ₂ SO ₄ Na Cl 1.2151 0.5753 (NH ₂) ₂ SO ₄ Nh ₄ 3.8790 0.8230 Na ₂ SO ₄ Na ₂ CO ₅ 1.3403 0.4298 (NH ₄) ₂ SO ₄ Nh ₂ SO ₄ Na ₂ CO ₅ 1.4839 4.9225 Ni Nh ₂ SO ₄ Na ₂ SO ₄ Na ₂ SO ₄ Na ₂ SO ₄ Na ₂ SO ₄ Na ₂ SO ₄ Na ₂ SO ₄ Na ₂ SO ₄ Na ₂ SO ₄ Na ₂ SO ₅ 1.1269 2.6371 Na ₂ SO ₄ Na ₂ SO ₄ Na ₂ SO ₅ 1.1269 2.6371 Na ₂ SO ₄ Na ₂ SO ₄ Na ₂ SO ₅ 1.1269 2.6371 Ni NiSO ₄ 0.2039 Na ₂ SO ₄ Na ₂ SO ₄ Na ₂ SO ₅ 1.1269 2.6371 Ni NiSO ₄ 0.3792 1.8877 Na ₂ SO ₄ Na ₂ SO ₄ Na ₂ SO ₄ 0.4409 2.0720 Ni NiSO ₄ 7H ₂ O 0.3263 Na ₂ SO ₄ Na ₂			BaSO ₄			(NH ₄),PtCl ₆		
0.6904 Na ₂ SO ₄ H ₂ SO ₄ 1.4484 1.4392 (NH ₄) ₂ SO ₄ BaSO ₄ 0.6948 1.2267 Na ₂ SO ₄ MgO 3.5236 0.7422 (NH ₄) ₂ SO ₄ BaSO ₄ 0.5661 0.2238 Na ₂ SO ₄ MgDP ₂ O ₇ 1.2758 0.2120 (NH ₄) ₂ SO ₄ N.604 1.3473 0.8238 Na ₂ SO ₄ Na ₂ 1.2758 0.2120 (NH ₄) ₂ SO ₄ N. 4.7168 0.8230 Na ₂ SO ₄ Na ₂ CO ₂ 1.2310 0.5753 (NH ₄) ₂ SO ₄ NP ₄ 1.7383 0.7461 Na ₂ SO ₄ Na ₂ CO ₂ 1.3403 0.4298 (NH ₄) ₂ SO ₄ NP ₂ CO ₂ 1.7383 0.6918 Na ₂ SO ₄ Na ₂ CO ₂ 1.3403 0.4298 (NH ₄) ₂ SO ₄ NP ₂ CO ₂ 2.3268 0.6918 Na ₂ SO ₄ Na ₂ CO ₂ 1.4839 4.9225 Ni NiC ₂ H ₁₄ N ₄ O ₄ 0.2032 1.6912 Na ₂ SO ₄ Na ₂ SO ₄ Na ₂ SO ₄ Na ₂ SO ₂ Ni Ni Ni(NO ₂) ₂ 0.2032 1.6912 Na ₂ SO ₄ Na ₂ SO ₄ Na ₂ SO ₂			CaO			(NH ₄),PtCl ₄ .		
1.2267 Na ₂ SO ₄ K ₂ SO ₄ 0. 8152 1.7665 (NH ₄) ₂ SO ₄ BaSO ₄ 0. 5661 0.2238 Na ₂ SO ₄ MgO 3.5236 0.7422 (NH ₄) ₂ SO ₄ H ₂ SO ₄ 1. 3473 0.7838 Na ₂ SO ₄ Ng ₂ P ₄ O ₇ 1.2758 0.2120 (NH ₄) ₂ SO ₄ NH ₄ 3. 8790 0.8230 Na ₂ SO ₄ Na ₂ CI 1. 2151 0.5753 (NH ₄) ₂ SO ₄ NH ₄ 3. 8790 0.8230 Na ₂ SO ₄ Na ₂ CI 1. 2151 0.5753 (NH ₄) ₂ SO ₄ Nr ₀ C ₁ 1.7383 0.7461 Na ₂ SO ₄ Na ₂ C ₁ 1. 6912 0.6739 Na ₂ SO ₄ Na ₂ C ₁ 1. 6912 Na ₂ SO ₄ Na ₂ SO ₄ Na ₂ C ₁ Na ₂ SO ₄ Na ₂ SO ₅ 1. 1269 2.6371 Ni Ni(NO ₂) ₂ 6H ₃ O 0.7592 1.8877 Na ₂ SO ₄ Na ₂ SO ₅ 1. 1269 2.6371 Ni NiSO ₄ 0. 3792 1.8877 Na ₂ SO ₄ Na ₂ SO ₄ Na ₂ SO ₅ 1. 1269 2.6371 Ni NiSO ₄ 0. 3792 1.8877 Na ₂ SO ₄ Na ₂ SO ₄ Na ₂ SO ₅ 0. 5297 4.7863 Ni NiSO ₄ 7H ₃ O 0. 2089 1. 3883 Na ₂ SO ₄ Na ₂ SO			CHICOINA			(NH ₄) ₂ PtCl ₆ .	PtC4	
0.2838 Na ₂ SO ₄ MgO 3.5236 0.7422 (NH ₁) ₂ SO ₄ H ₂ SO ₄ 1.3473 0.7838 Na ₂ SO ₄ Na 3.0883 0.2578 (NH ₂) ₂ SO ₄ N 4.7166 0.8230 Na ₂ SO ₄ NaCl 1.2151 0.5753 (NH ₂) ₂ SO ₄ N ₂ O ₁ 1.7383 0.7461 Na ₂ SO ₄ Na ₂ CO ₂ 1.3403 0.4298 (NH ₂) ₂ SO ₂ H ₂ SO ₄ 1.7383 0.6730 Na ₂ SO ₄ Na ₂ F 1.6912 N ₂ SO ₂ H ₂ SO ₄ 0.2032 1.6912 Na ₂ SO ₄ Na ₂ SO ₂ 1.4839 4.9225 Ni Ni(NO ₂) ₂ 0.2032 1.6942 Na ₂ SO ₄ Na ₂ SO ₄ 0.5916 4.9656 Ni Ni(NO ₂) ₂ 0.2032 0.4364 Na ₂ SO ₄ Na ₂ SO ₂ 1.2727 Ni Ni Ni(NO ₂) ₂ 0.8495 Na ₂ SO ₄ Na ₂ SO ₂ 1.1269 2.6371 Ni NiSO ₄ . 0.3792 1.8877 Na ₂ SO ₄ Na ₂ SO ₄			H,8004				Roso.	
0.7888 0.3238 Na ₈ SO ₄ . Mg ₂ P ₂ O ₇ . 1.2758 3.0883 0.2120 0.8230 NH ₄) ₈ SO ₄ . N. 0.8230 Na ₈ SO ₄ . Na ₈ CO ₈ . 1.2758 3.0883 0.2578 0.8450 NH ₄) ₈ SO ₄ . NH ₄ . 3.8790 0.1738 NH ₄) ₈ SO ₄ . NH ₄ . 3.8790 0.1738 NH ₄) ₈ SO ₄ . NH ₄ . 3.8790 0.1738 NH ₄) ₈ SO ₄ . NH ₄ . 3.8790 0.1738 NH ₄ . 1.7383 0.1738 NH ₄ . 2.3268 0.1738 NH ₄ . 2.3268 0.1738 NH ₄ . 2.3268 0.5916 NH ₄ . 2.3268 0.5916 NH ₄ . 2.3268 0.5916 NH ₄ . NH ₄ . 0.2032 0.2032 NH ₄ . 0.2032 NH ₄ . NH ₄ . 0.2032 0.2032 NH ₄ . 0.2032 NH ₄ . NH ₄ . 0.2032 0.2032 NH ₄ . NH ₄ . 0.2032 NH ₄ . <th></th> <th></th> <th></th> <th></th> <th></th> <th>NH JSO</th> <th>H-SO.</th> <th></th>						NH JSO	H-SO.	
0.8238 Na ₈ SO ₄ Na 3 .0883 0.2578 (NH ₄) ₈ SO ₄ NH ₅ 3 .8790 0.8230 Na ₈ SO ₄ Na ₆ CO ₅ 1.3403 0.4298 (NH ₄) ₈ SO ₄ N ₂ SO ₄ 1.7383 0.5918 Na ₈ SO ₄ Na ₆ F 1.6912 0.6739 Na ₈ SO ₄ Na ₆ F 0.5916 4.9856 Ni NiC ₆ H ₁₄ N ₄ O ₄ 0.2032 Na ₈ SO ₄ Na ₈						NH. SO.		
0.8230 Na ₂ SO ₄ Na ₂ CI ₂ 1.2151 0.5753 (NH ₄) ₂ SO ₄ Ni ₂ O ₃ 1.7383 0.4298 Na ₂ SO ₄ Na ₂ SO ₅ 1.269 2.4871 Ni NiSO ₄ NiSO ₄ 0.2018 Na ₂ SO ₄ Na ₂ SO ₅ 1.269 2.4871 Ni NiSO ₄ 0.3792 1.8877 Na ₂ SO ₄ Ni ₂ SO ₄		Na SO4	Na			(NH.) SO	NH	
0.7461 Na ₂ SO ₄ Na ₂ CO ₈ 1.3403 0.4298 (NH ₄) ₂ S ₂ O ₃ H ₂ SO ₄ 2.3268 0.6739 Na ₂ SO ₄ Na ₂ SO ₄ 1.4839 4.9225 Ni. NiC ₂ H ₁₄ N ₄ O ₄ 0.2032 1.6904 Na ₂ SO ₄ Na ₂ SO ₄ 0.5916 4.9556 Ni. Ni(NO ₃) ₂ 0.4364 Na ₂ SO ₄ Na ₂ SO ₄ 1.8198 1.2727 Ni. NiO 0.7858 0.8874 Na ₂ SO ₄ Na ₂ SO ₃ 1.1269 2.6871 Ni. NiSO ₄ 0.3792 1.8877 Na ₂ SO ₄ Na ₂ SO ₄ 0.5297 4.7863 Ni. NiSO ₄ 0.2089 2.2681 Na ₂ SO ₄ Na ₂ SO ₄ 0.4409 2.0720 NiO NiSO ₄ 0.4826 1.3883 Na ₂ SO ₄ Na ₂ SO ₂ 0.7472 1.8150 NiSO ₄ NiSO ₄ 0.5510 Na ₂ SO ₄ Na ₂ SO ₂ 1.7743 NiSO ₄ NiSO ₄ 0.5510	0.8230	Na ₂ SO ₄	NaCl	1.2151	0.5753	(NH ₄) ₂ SO ₄	N ₂ O ₂	1.7383
0.6739 Na _p SO ₄ Na _p SO ₄ 1,4839 4.9225 Ni NiC ₂ H ₁₄ N ₄ O ₄ 0.2032 1.6904 Na _p SO ₄ Na _p SO ₄ 0.5916 4.9656 Ni Ni(No ₂) ₂ 6H ₄ O 0.2018 0.5495 Na _p SO ₄ Na _p SO ₄ 1.8198 1.2727 Ni NiO 0.7858 1.8879 Na _p SO ₄ Na _p SO ₄ 1.1269 2.6371 Ni NiSO ₄ 0.3792 1.8879 Na _p SO ₄ Na _p SO ₄ 0.5297 4.7863 Ni NiSO ₄ ·7H ₄ O 0.2089 1.7880 Na _p SO ₄ Na _p SO ₄ 3.0643 NiO NiC ₄ H ₁₄ N ₄ O ₄ 0.3263 1.3883 Na _p SO ₄ Na _p SO ₂ 0.7472 1.8150 NiSO ₄ ·7H ₄ O 0.5510 Na _p SO ₄ SO ₂ 1.7743 NiSO ₄ ·7H ₄ O 0.5510	0.7461		Na ₂ CO ₂	1.3403	0.4298	$(NH_4)_2S_2O_3$	H ₂ SO ₄	2.3268
1.6904 Na ₂ SO ₄ Na ₂ SO ₄ 0.5916 4.9656 Ni Ni(NO ₃) ₂ 0.2018 0.4364 Na ₂ SO ₄ Na ₂ SO ₄ 1.8198 1.2727 Ni NiO 0.7858 0.8874 Na ₂ SO ₄ Na ₂ SO ₅ 1.1269 2.6871 Ni NiSO ₄ 0.3792 1.8877 Na ₂ SO ₄ Na ₂ SO ₄ Na ₂ SO ₄ NiSO ₄ NiSO ₄ 0.2089 1.0H ₂ O Na ₂ SO ₄ Na ₂ SO ₄ NiSO ₄ NiO NiSO ₄ 0.3263 1.3383 Na ₂ SO ₄ Na ₂ SO ₅ 0.7472 1.8150 NiSO ₄ NiSO ₄ NiSO ₄ 0.5510 Na ₂ SO ₄ SO ₆ 1.7743 NiSO ₄ NiSO ₄ NiSO ₄ 0.5510		Na ₂ SO ₄	NaF				200 57 22 0	0.0000
0.4364 Na ₂ SO ₄ Na ₂ SO ₄ Na ₂ SO ₅ 1.8198 1.2727 Ni NiSO ₄ 0.7858 0.8874 Na ₂ SO ₄ Na ₂ SO ₅ 1.1269 2.6371 Ni NiSO ₄ 0.3792 1.8877 Na ₂ SO ₄ Na ₂ SO ₅ Na ₂ SO ₆ Na		Na ₂ S ₁ O ₁	80,			Ni	NiCeriaNaOa.	0.2032
0.5495 Na ₂ SO ₄ Na ₂ S 1.8198 1.2727 Ni NiO 0.7858 0.8874 Na ₂ SO ₄ Na ₂ SO ₅ 1.1269 2.6371 Ni NiSO ₄ 0.3792 1.8877 Na ₂ SO ₄ Na ₂ SO ₄ 0.5297 4.7863 Ni NiSO ₄ ·7H ₂ O 0.2089 Na ₂ SO ₄ Na ₂ SO ₄ 0.4409 2.0720 NiO NiSO ₄ ·7H ₂ O 0.4826 Na ₂ SO ₄ Na ₂ SO ₃ 0.7472 1.8150 NiSO ₄ ·7H ₂ O 0.5510 0.5636 Na ₂ SO ₄ SO ₄ 1.7743 NiSO ₄ ·7H ₂ O 0.5510		Na ₂ SU ₄	Nansu			N1	NI(NUs)	0 2019
0.8874 Na ₂ SO ₄ Na ₂ SO ₅ 1.1269 2.8371 Ni. NiSO ₄ 0.3792 1.8877 Na ₂ SO ₄ Na ₂ SO ₄ 0.5297 4.7863 Ni. NiSO ₄ 0.2089 2.2681 Na ₂ SO ₄ Na ₂ SO ₄ 3.0643 NiO NiC ₂ H ₁₄ N ₄ O ₄ 0.3263 1.3883 Na ₂ SO ₄ Na ₂ SO ₃ 0.4409 2.0720 NiSO ₄ NiSO ₄ 0.4826 Na ₂ SO ₄ Na ₂ SO ₃ 0.7472 1.8150 NiSO ₄ NiSO ₄ 0.5510		Ne.SO.	Ne-S	1 2100	1 9797	N;		
1.8877 Na ₂ SO ₄			Na-SO	1.1269	2.6871	Ni	NiSO	
2.2681 Na ₂ SO ₄ Na ₂ SO ₄ 8.0643 NiO NiC ₂ H ₁₄ N ₄ O ₄ 0.3268 NiC ₂ 1.0H ₂ O 0.4409 2.0720 NiO NiSO ₄						Ni		
1.3383 Na ₂ SO ₄ Na ₂ S _{O₅ Na₂S_{O₅ Na₂S_{O₄ Na₂S_{O₄ Na₂S_{O₄ Na₂S_{O₄ Na₂S_{O₅ Na₂S_{O₆ /sub>}}}}}}}}</sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub></sub>			NasO.	1		I NiO	NiC.H.AN.O.	
1.3383 Na ₂ SO ₄ Na ₂ S ₂ O ₃ 0.7472 1.8150 NiSO ₄ NiSO ₄ .7H ₄ O. 0.5510 Na ₂ SO ₄ SO ₃ 1.7743	že.		·10H ₂ O		2.0720	NiO	Ni80	0.4826
				0.7472	1.8150	NiSO4	NiSO ₄ ·7H ₄ O.	0,.5510
	0.5686	Na ₂ SO ₄	SO ₃	1.7748				
	-			<u> </u>			<u> </u>	<u></u>

 $A \times A' = B$ $B \times B' = A$

Phenolphthalein.

A'	A	В	B'	A'	A	В	B'
1.5667	NO	HNO.	0.6382	1.6900	P ₂ O ₂	NaH,PO	0.5917
2.0999 2.8362	NO	HNO ₂	0.4762	1.5632	P ₂ O ₃	Na ₂ H ₂ P ₂ O ₇	0.6897
3.3694	NO	KNO	0.3526 0.2968	2.9441	P ₂ O ₂	Na(NH ₄)	
2.2997	NO	NaNO ₂	0.4348	0.8720	P.O	HPO ₄ ·4H ₂ O Na ₂ O	0.3395 1.1458
2.8327	NO	NaNO	0.3530		P ₂ O ₂	Na ₄ PO ₄	0.4381
				26.424	P ₂ O ₂	(NH ₄) ₂ PO ₄	0.200
4.0487	N ₂ O ₂	AgNO ₂	0.2470			(MoO ₂) ₁₃	0.0378
0.9594	N ₁ O ₂	HCl	1.0423		P ₂ O ₂	Na ₄ P ₂ O ₇	0.5340
1.6579	N ₂ O ₂	HNO:		5.0278	P ₂ O ₃	$U_2P_2O_{11}$	0.1989
L.0798 L. 2903	N ₂ O ₃ N ₂ O ₃	H ₂ SO ₂	0.9261	0 5705	TIL	CIT CO II	4 507
2.2392	N ₂ O ₃	KNO	0.7750 0.4466		Pb Pb	CH ₂ CO ₂ H Pb(C ₂ H ₄ O ₂) ₂ .	1.7258 0.6369
0.3686	N.O	N	2.7131		Pb	PbCl ₂	0.7449
1.8156	N ₂ O ₂	NaNO ₂	0.5508	1 2897	Pb	PbCO ₁	0.7754
0.7895		NO	1.2666		Pb	(PbCO ₂),Pb	0.7701
1.2104	N ₂ O ₂	N ₂ O ₄	0.8262			(OH).	0.8014
7928	N ₂ O ₄	HCl		1.5601	Pb	PbCrO ₄	0.6410
1.8697	N ₂ O ₄	HNO ₃		1.0773	Pb	PbO	0.9283
0.8920	N ₂ O ₄ *	H ₂ SO ₂		1.1545	Pb	PbO ₂	0.8662
1.0659		H ₂ SO ₄		1.1643	Pb	Pb(OH) ₁	0.8589
0. 3045 0.652 3	N ₂ O ₄ N ₂ O ₄	N		1.1549 1.4639	Pb Pb	Pb8 PbSO ₄	0.8659
0.6752	N ₂ O ₂	NO HCl		0.1548	Pb	8	0.6831 6.4629
1.1668	N ₂ O ₂	HNO ₂		0.2551	PbCl ₁	Cl	3.9216
0.7599	N ₂ O ₂ *	H ₂ SO ₂		0.1647	PbCO ₂	ČO ₁	6.0722
0.9080	N ₂ O ₂	H ₂ SO ₄	1.1013	0.1612	PbCrO ₄	Cr	6.2154
1.8721	N ₂ O ₃	KNO ₂		0.2352	PbCrO ₄	Cr ₂ O ₂	4.2526
.5740	N ₂ O ₂	NaNO ₂	0.6353	0.4551	PbCrO ₄	K ₂ Cr ₂ O ₇	2.1971
0.3153	N ₂ O ₅	NH ₃	3 1710	0.5014	PbCrO ₄	Na ₄ CrO ₄	1.9951
).5556).7038	N ₂ O ₃ N ₂ O ₂	NO N ₂ O ₂		0.6410	PhCrO ₄	Pb	1.5600
7.7000	14202	N2O2	1.4208	1.1733	PbCrO ₄	Pb(C ₁ H ₁ O ₁) ₁ 3H ₁ O	0.8523
.3353	Os	OsO4	0.7489	0.7999	PbCrO4	(PbCO ₂),Pl	0.0020
		0.00		0.1000	200101	(OH),	1.2501
3.1593	P	H ₂ PO ₄	0.3165		PbCrO ₄	PbO	1.4482
. 5877	P.,	$Mg_1P_2O_7$	0.2787		PbCrO ₄	Pb ₂ O ₄	1.3512
.8678		NaH ₂ PO ₄	0.2585		PbCrO ₄	Pb804	1.0657
0.476	P	(NH ₄).PO ₄		0.5642	PbMoO ₄	Pb	1.7722
. 2887	P	P_2O_3	0.0165 0.4369	0.2615 0. 3923	PbMoO ₄	Mo	8.8250
.8936	P ₂ O ₂	Ag PO			PbO	MoO ₂	2.5500 1.0772
.7193		AĬPO	0.1697 0.5815	1.2461	PbO	PbCl	0.8025
7193		Al ₂ P ₂ O ₃	0.5816	1.1972	PbO	PbCO	0.8353
.9161	P ₂ O ₂	CaHPO	0.5816 0.5219	1.4842	PbO	Pb(NO ₂) ₁	0.6738
.6483		$Ca(H_2PO_4)_2$	0.6067	1.3589	PbO	Pb804	0.7859
.5214		CaH.P.O	0.6573	0.8659	Pb8	Pb	1.1549
.7893	P ₂ O ₂	Ca ₂ P ₂ O ₇	0.5589		Pb8	Рьо	1.0720
1.1839 1.1239	P ₂ O ₂	Ca ₄ P ₂ O ₂ FePO ₄	0.4579 0.4708		Pb80	BaSO ₄	7.4629
. 1552	P.O	H.PO.	0.8657		Pb804	Pb(C ₁ H ₁ O ₂) ₂	1.2091
3804	P.O.	H.PO.	0.7244		10004	·8H ₂ O	0.7995
.0709	P ₂ O ₁	H.SO	0.4829	0.8525	Pb804	(PbCO ₂),Pb	V.1500
.5676	P ₂ O ₃	MgsP.O.	0.6379		•	(OH),	1.1781
	DA.	NaPO.	0.6962	A 7007 i	PbSO ₄	PbO	1.2679
.4364	P ₂ O ₂	1104 Oz 1	0.5001	0.1001	PbSO	F0O3	1.8272

 $A \times A' = B$ $B \times B' = A$

Phenolphthalein

			l			l ,	1 5,
<u>A'</u>	A .	В	B'	A'	A	В	B'
0.7889 0.2640	PbSO4	Pb8	1.2676	6.4630 1.9981	S	Pb SO	0.1547 0.5005
0.2049	PbSO ₄	SO ₃	3.7879	2.4972	8	80	0.4005
3.7270	Pd	K₂PdCl₄	0.2683	1.7616	S	BaS	0.5677
2.0024 3.3791	Pd Pd	PdCl ₂ ·2H ₂ O . PdI ₂ ······	0.4994 0.2959	1.3212 3.6439	SO ₁	BaSO	0.7569 0.2745
* :1623	Pd	$Pd(NO_3)_2$	0.4625	1.5783	SO ₂	Ca(HSO ₃) ₃	0.6336
2.3979 2.3790	Pd Pd	HI	0.4170 0.4203	1.2812 1.5309	80 ₂ 80 ₂ †	H ₂ SO ₂ H ₂ SO ₄	0.7805 0.6532
0.7096		I HI	1.4092	0.7655	80,	H.SO.	1.3064
0.7041	PdI	<u>.</u> <u>1</u>	1.4204	1.6244	80	NaHSO ₃	0.6156
0.9703	PdI ₃	IO ₃	1.0306	1.9677 3.9356	SO ₂	Na ₂ SO ₂ Na ₂ SO ₂ .7H ₂ O	0.5082 0.2541
2.4903	Pt	K.PtCl	0.4015	1.2498	80	SO ₃	0.8001
2.6541	Pt	H2PtCl6·6H2O	0.3768	0.4255	SO ₃	Al ₂ O ₂	2.3501
2.2748 1.7266	Pt Pt	(NH ₄) ₂ PtCl ₅ . PtCl ₄	0.4396 0.5792	1.4255 2.9155	SO ₃	Al ₂ (SO ₄) ₂ BaSO ₄	0.7015 0.3430
2.1881	Pt	PtCl ₄ ·5H ₂ O	0.4570	0.7003	SO ₃	CaO	1.4280
1.4423	PtCl ₄	K.PtCl	0.6934	1.7003	803	CaSO	0.5881 0.8163
1.3177 1.1383	PtCl ₄ PtCl ₄ .5H ₂ O	(NH ₄) ₂ PtCl ₆ . K ₄ PtCl ₄	0.7589 0.8785	1.2250 2.1765	SO ₂	H ₂ SO ₄ K ₂ SO ₄	0.4595
				0.5036	80	MgO(in	
1.1703	Pr	Pr ₂ O ₃	0.8545	1.5036	SO ₃	MgSO ₄)	1.9859 0.6651
3.7382	Rh	Na ₂ RhCl ₈	0.2675	1.8858	SO	MnSO	0.5303
2.0338	Rh	RhCl ₁	0.4917	0.7743	80	Na ₂ O	1.2915
1.6775	Rb	AgCl	0.5961	1.7743 1.1416	SO ₃	Na ₂ SO ₄ 66° O. V	0.5636 0.8760
0.4150	Rb	CI	2.4098	2.0162	80	ZnSO4	0.4960
1.4150	Rb	RhCl RbCO ₄	0.7067	2.4298	80 ₄ 80 ₄ .HCl	BaSO ₄	0.4116 3.1953
1.3510	Rb	Rb.O.	0.7402 0.9144	0.3130 0.8417	SO _a HCl	H-SO4	1.1881
1.5622	R b	Rb ₂ SO ₄	0.6402	0.4561	8 ₂ O ₄ Cl ₂	H ₂ SO ₄	2.1926
3.3871 1.1855	Rb RbCl	Rb₁PtCl₃ AgCl	0.2952 0.8435	2.7649	Sb	KSbOC,H,O,	
0.2933	RbCl	ĊĪ	3.4098	2.1010	DD	· H ₂ O	0.3617
1.2686	Rb ₂ CO ₃	RbHCO ₂	0.7883	1.8850	Sb	SbCl	0.5305
1.2939 1.4284	Rb ₂ O	RbCl Rb ₂ SO ₄	0.7729 0.7001	1.1997 1.3328	8b	$\begin{bmatrix} \mathrm{Sb_2O_3} & \dots & & \\ \mathrm{Sb_2O_3} & \dots & & & \end{bmatrix}$	0.8336 0.7503
0.4178	Rb.PtCl	RbCl	2.3938	1.4002	8b	Sb ₂ S ₃	0.7142
0.3987	Rb ₂ PtCl ₆ Rb ₂ PtCl ₄	Rb ₁ CO ₃	2.5071 1.9762	1.2662 1.1109	8b	$Sb_2O_4Sb_2O_3$	0.7897 0.9001
0.5060 0. 3229	Rb.PtCl.	Rb ₂ O	3.0972	1.3462	Sb ₂ O ₃ Sb ₂ S ₄	SbCl ₂	0.7428
	<u> </u>	D. 0	0.1000	1 0015			0.4100
5.2848 6.7820	S	BaSO	0.1892 0.1475	1.6315 1.8336	Se Se	H ₂ SeO ₄	0.6129 0.5454
7.2810	8	BaSO4	0.1373	1.4040	Se	SeO ₂	0 7123
6.0334	§	BaS ₁ O ₁	0.1657	1.6060	Se	SeO ₃	0.6227
6.3143 2.2117	8 S	$BaS_iO_i \cdot H_iO$. $BaS_i \cdot H_iO$.	0.2397 0.4521	2.1307	Si	SiO ₂	0.4693
1.0629	8	H.S	0.9408	2.6961	Si	SiO ₃	0.3709
3.0591 24:7417	8 8	H ₂ SO ₄	0.3270 0.3648	3.2615 2.6814	Si	SiO ₄ BaSiF ₄	0.3066
1.8709	8	FeS ₂	0.5346	1.3837	SiF4	H.SiF4	0.7227
3.4392	8	K.S	0.2908	2.1141	SiF ₄		0.4730
2.4348	<u> 18</u>	Na ₂ S	0.4108	1.0141	SiF ₄	H ₂ SiF ₃	0.9860

 $A \times A' = B$ $A \times A' = A$

^{*} Phenolphthalein.

[†] Methyl orange.

	,	(FAOIC	Tus (Continue	•	,
A'	Λ	В	B'	A'	A	В	. B'
4.6380	SiO2	BaSiF ₂	0.2156	0.5000	Tl2PtCl6	T1	1.9999
1.2988	SiO ₂	H ₂ SiO ₂		0.5869	TlaPtCla	TiCi	1.7038
3.6567	SiO ₂	K ₂ SiF ₆		0.5738	Tl.PtCl	Tl ₂ CO ₂	1.7435
2.5622	SiO ₂	K ₂ SiO ₂	0.3903		Tl.PtCl	Tii	1.2329
2.0282	SiO ₂		0.4930		Tl.PtCl.	TINO.	1.5337
1.7296	SiO ₂	SiF.	0.5782	0.5196	Tl ₂ PtCl ₄	TINO.	1.9244
2.6554	ŠiO ₂	SO ₂	0.3766	0.6178	Tl ₂ PtCl ₅	Ti ₂ SO ₄	1.6187
1.5975	SiO ₂	Si(OH)4	0.6259	0.8094	Ti ₂ SO ₄	Ti	1.235
2.3495	SiO	ZnSiO ₂	0.4256	0.0004	112504	*1	1.200%
2.0100	5101	22110103	0.4200	0.8817	UO2	U	1.1342
0.5975	Sn	Cl ₂	1.6737	0.8482	UsOs.	<u> </u>	1.1789
1.5974	Sn	SnCl ₂	0.6261	0.9621	U.O.	ŬO ₂	1.0394
1.9010	Sn	SnCl ₂ ·2H ₂ O.	0.5260	1.7884	11.0	$UO_3(NO_3)_3$	1.055%
2.1949	Sn	SnCl ₄	0.3200	1.100*	U ₂ O ₃	·6H ₂ O	0.5591
1.1348	Sn	SnO	0.4555	0.6668	TIDA	Ogido.	
1.2696	Sn	8 _n O	0.7877		U ₂ P ₂ O ₁₁	U	1.4990
0.3740	SnCl ₂	SnO_2	2.6738	0.7566	$U_2P_2O_{11}$	UO ₃	1.3221
0.3847		Cl	2.6000	1.3137	**	77.0	0.7612
	SnCl ₂	HCl	1 1075	1 4700	V	V ₂ O ₃	
0.8421 1.1899	SnCl ₂	$Fe_2O_3SnCl_2\cdot 2H_2O$	1.1875 0.8404	1.4706	V	V ₂ O ₃	0.6800
	SnCl ₂		0.8404	1.6275	<u>v</u>	V.O	0.6145
0.5444	SnCl ₄	Cl	1.8369	1.7843	¥	V ₂ O ₂	0.5604
0.5599	SnCl ₄	HCI	1.7861	0.5604	V ₂ O ₃	V	1.7843
1.4974	SnO_{2}	SnCl ₂ ·2H ₂ O	0.6678	1.2638	V ₂ O ₂	VO₄	0.7913
1.7288	SnO2	SnCL	0.5784	0.070	*** A	371	1 1000
2.4389	SnO₂	SnCl.		0.8785	Yt ₂ O ₃	Yt	1.1383
		(NH ₄ Cl) ₂	0.4100	0.7882	Y ₂ O ₃	Y	1.2687
0.8938	SnO ₂	SnO	1.1188	0.4700	377	DI TICO	~
1 00/0		2 22	0 5005	2.4739	W	PbWO₄	0.4042
1.6848	Sr	SrCO ₂	0.5935	0.8519	WO ₂	<u>W</u>	1.1739
1.1826	Sr	8r0	0.8456	0.7931	WO3	W	1.2609
2.0963	Sr	SrSO	0.4770	1.9621	WO3	PbWO₄	0.5099
1.5300	SrO	SrCl ₂	0.6536	4 2004	~	77.00	
0.4357	SrSO ₄	SO ₂	2.2943	1.5004	Z n	H ₂ SO ₄	0.6665
	7	T. CI	0.5050	1.2247	Zn	SO ₃	0.8165
1.9767	Та	TaCl		2.0849	Zn	ZnCl ₂	0.4796
1.2204	Ta	Ta ₂ O ₅	0.8194	7.6222	Zn	ZnHg(CNS)4	0.1312
		*** / D	0.0505	1.2448	Zn	ZnO	0.8034
1.5177	Te	H ₂ TeO ₄		2.3315	Z n	Zn ₂ P ₂ O ₇	0.4289
1.8003	Te	H,TeO,2H,O.		1.4906	Zn	ZnS	0.6709
1.2509	Te		0.7994		ZnCl ₂	AgCl	0.4754
1.3765	Те	TeO ₂	0.7265		ZnCl ₂	C1	1.9217
	The C	m.	1 1000	0.8579	ZnCl ₂	NaCl	1.1656
0.8790	ThO ₂	Th	1.1379	1.2054	ZnO	H ₂ SO ₄	0.8296
1.4155	ThO ₂	ThCl4	0.7065		Z nO	SO	1.0162
2.2271	ThO ₂	Th(NO ₃)4		1.6749	ZnO	ZnCl ₂	0.5970
		O _r H ₀ ·	0.4492	1.1541	ZnO	ZnCO ₂	0.6490
	m:	m:0	- 400F	2.9427	ZnO	Zn ₂ P ₂ O ₇	0.3398
1.6652	Ti	TiO ₂	0.6005	1.1975	ZnO	ZnS	0.8351
4.4-00		- CI	0.0510	1.9840	ZnO	ZnSO4	0.5040
1.1738	T1	TICI	0.8519		ZnO	ZnSO ₄ ·7H ₂ O.	0.2830
1.1470	<u>T1</u>	Tl ₂ CO ₂	0.8718		ZnS	BaSO	0.4174
1.6220 1.3040	<u>Tl</u>	TII	0.6165		ZnS	ZnSO4.7H ₂ O.	0.3389
1.3040	<u>T</u> 1	TINO.	0.7669	0.4256	ZnSiO ₁	SiO ₂	2.3495
1.0392	T1	TI.O	0.9623	0.4960	ZnSO ₄	SO ₃	2.0162
0.7786	Tl ₂ CrO ₄	<u>T</u> 1	1.2843				1
0.6775	TIHSO4	T1	1.4759	0.7390	ZrO ₂	Zr	1.3532
0.6165	TII		1.6222				
			/ 5	n n			

 $A \times A' = B$ $B \times B' = A$

Note.—The editor will welcome additional factors not appearing in these tables. Although a large portion of these factors have appeared in previous editions the entire list has received careful revision, using the atomic weights of 1920. Credit for the arrangement of this section is due to R. M. Meiklejohn. The factors have been checked by three men working independently.

Example of Method for Using Factors. Suppose the product weighed is 0.8535 gram AgCl and the equivalent weight of Cl is desired; hunt up the factors AgCl-Cl. This may be found on the first page of the conversion factors, a little below the middle of the page. Using the formula $A \times A' = B$, and substituting the values for A (weight of AgCl) and A' (factor) we have $0.8535 \times 0.2474 = 0.21124$ gram Cl. If, on the other hand, the weight of Cl were known to be, say, 0.2501 gram and the weight of the equivalent AgCl were desired, we would use the formula $B \times B' = A$ and, substituting the values for B and B', we would have $0.2501 \times 4.0423 = 1.01098$ gram AgCl.

VOLUMETRIC FACTORS

1 c.c. N/2 HCl = .018235 gram HCl 1 c.c. N/10 HCl = .003647 gram HCl 1 c.c. N/2 KOH = .028055 gram KOH 1 c.c. N/6 KOH = .04706 gram oleic acid = .008173 gram H₂SO₄ 1 c.c. N/10 KOH = .00561 gram KOH 1 c.c. K₂Cr₂O₇ = 3.8633 gram per liter = .010 gram I 1 c.c. N/10 Na₂S₂O₃5H₂O = .0248 gram Na₂S₂O₃5H₂O = .012692 gram I

1 c.c. NO = 0.0021 gram HNO₂

NO = 0.0021 gram HNO₁ = 0.0028143 gram HNO₂ = 0.0045154 gram KNO₂

=0.003796 gram NaNO₂ =0.00134 gram NO =0.001696 gram N₂O₃ =0.0024119 gram N₂O₃

A'	A	В	B'	A'	A	В	В'
							٠
		<u> </u>				}	
						•	
	<u>,</u>						
	i		1		1	1	- "

XIX.—COMPARISON OF CENTIGRADE AND FAHRENHEIT SCALE	YIY _	COMPARISON	OF	CENTIGRADE	AND FAHRENHEIT	SCALE
--	-------	------------	----	------------	----------------	-------

°C.	-100	-0	+0	+100	+200	+300	+400	+500	+600	+700	+800	+900	°C.
0	°F. -148	F. + 32	F. 32	F. +212	F. 392	F. 572	F. 752	F. 932	F. 1112	F. 1292	F. 1472	F. 1652	0
5	-157	+ 23	41	221	401	581	761	941	1121	1301		1661	5
10	-166		50	230	410	590	770		1130				1ŏ
15	-175		59		419	599	779		1139			1679	15
20	-184		68		428	608	788		1148	1328	1508	1688	20
25	-193		77	257	437	617	797	977	1157	1337	1517	1697	25
30	-202	- 22	86		446	626	806		1166		1526	1706	30
35	-211	- 31	95		455	635			1175			1715	35
40	-220		104		464	644	824					1724	40
45	-229		113			653	833					1733	45
50	-238		122			662			1202		1562		50
55	-247	- 67	131	311	491	671	851	1031	1211	1391	1571	1751	55
60	-256		140		500	680	860		1220	1400	1580	1760	60
65	-265					689	869				1589	1769	65
70	-274						878				1598	1778	70
75	-283									1427	1607	1787	75
80		-112				716 725					1616	1796	80
85	-301		185							1440	1625 1634	1805 1814	85
90		-130									1643	1823	90 95
95		-139									1652	1832	100
100	-328	-148	+212	392	312	132	932	1112	1492	14/2	1002	1002	100
°.C.	-200	-100	+100	+200	+300	+400	+500	+600	+700	+800	+900	+1000	°C.
	1	ļ	l	1	1	l	l	<u> </u>		l			
					4 400			222		4000			
C' F			200 192	1300 2372	1400 2552			600 912	1700 3092	1800 3272			000 332
D	egrees	C.×1.	8+32	= Degr	ees F.			Deg	rees F.	−3 2÷	1.8=1	Degrees	C.
D	egrees	C.X1.	8+32	= Degr	ees F.			Deg	rees F	-32÷	1.8=1	Jegrees	•

Absolute zero, -273° C. = -459° F.

Comparison of Centiorade and Fahrenheit Scale for Every 1° C. from 0° to 100° C.

C.	0	10	20	30	40	50	60	70	80	90	C.
0 1 2 3 4 5 6 7 8 9 C.	F. • 32 33.8 35.6 37.4 39.2 41.0 42.8 44.6 46.4 48.2	F. 50 51.8 53.6 55.4 57.2 59 60.8 62.6 64.4 66.2	F. 68 69.8 71.6 73.4 75.2 77 78.8 80.6 82.4 84.2	F. 86 87.8 89.6 91.4 93.2 95 96.8 98.6 100.4 102.2	F. 104 105.8 107.6 109.4 111.2 113 114.8 116.6 118.4 120.2	125.6	F. 140 141.8 143.6 145.4 147.2 149 150.8 152.6 154.4 156.2	F. 158 159.8 161.6 163.4 165.2 167 168.8 170.6 172.4 174.2	F. 176 177.8 179.6 181.4 183.2 185 186.8 188.6 190.4 192.2	F. 194 195.8 197.6 199.4 201.2 203 204.8 206.6 208.4 210.2	0 1 2 3 4 5 6 7 8 9
14.				<u> </u>							

100° C. =212° F.

KX.—RELATION OF BAUMÉ DEGREES TO SPECIFIC GRAVITY AND THE WEIGHT OF ONE UNITED STATES GALLON AT 60° F.—LIQUIDS LIGHTER THAN WATER

-									· · · · · · · · · · · · · · · · · · ·		
Baumé.	Specific Gravity.	Pounds in Gallon.	Baumé.	Specific Gravity.	Pounds in Gallon.	Baumé.	Specific Gravity.	Pounds in Gallon.	Baumé.	Specific Gravity.	Pounds in Gallon.
10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27	1.0000 0.9929 0.9859 0.9790 0.9722 0.9655 0.9589 0.9523 0.9459 0.9395 0.9333 0.9271 0.9210 0.9150 0.9090	8.33 8.27 8.21 8.16 8.10 8.04 7.99 7.93 7.83 7.78 7.67 7.62 7.57 7.43 7.43 7.34	31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47	0.8695 0.8641 0.8588 0.8536 0.8484 0.8433 0.8383 0.8284 0.8235 0.8187 0.8092 0.8045 0.7954 0.7909 0.7865 0.7777	7.24 7.20 7.15 7.11 7.07 6.98 6.90 6.86 6.82 6.74 6.70 6.63 6.59 6.55 6.55 6.43	52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 70 71	0.7692 0.7650 0.7650 0.7567 0.7526 0.7486 0.7446 0.7407 0.7368 0.7329 0.7290 0.7253 0.7216 0.7179 0.7142 0.7106 0.7070 0.7035 0.7000	6.41 6.37 6.34 6.30 6.27 6.24 6.20 6.17 6.01 6.01 5.98 5.98 5.89 5.89 5.80	73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90	0.6896 0.6863 0.6829 0.6796 0.6763 0.6730 0.6698 0.6604 0.65578 0.6542 0.6541 0.6451 0.6451 0.6451 0.6451 0.6451 0.6451 0.6302 0.6363 0.6363 0.6322	5.75 5.56 5.69 5.68 5.58 5.55 5.55 5.52 5.50 5.48 5.42 5.42 5.40 5.38 5.38 5.30 5.18
0	0.8750	7.29	51	0.7734	6.44	72	0.6930	5.78		• • • • •	•••

CX.—(a) RELATION OF BAUMÉ DEGREES TO SPECIFIC GRAVITY— LIQUIDS HEAVIER THAN WATER

Baumé Degrees.	Specific Gravity.	Baumé Degrees.	Specific Gravity.	Baumé Degrees.	Specific Gravity.	Baumé Degrees.	Specific Gravity.
0.0	1.0000	6.0	1.0432	24.0	1.1983	42.0	1.4078
0.1	1.0007	7.0	1.0507	25.0	1.2083	43.0	1.4216
0.2	1.0014	8.0	1.0584	26.0	1.2185	44.0	1.4356
0.3	1 0021	9.0	1.0662	27.0	1.2288	45.0	1.4500
0.4	1.0028	10.0	1.0741	28.0	1.2393	46.0	1.4648
0.5	1.0035	11.0	1.0821	29.0	1.2500	47.0	1.4793
0.6	1.0042	12.0	1.0902	30.0	1.2609	48.0	1.4948
0.7	1.0049	13.0	1.0985	31.0	1.2719	49.0	1.5104
.0.8	1.0055	14.0	1.1069	32.0	1.2832	50.0	1.5263
0.9	1.0062	15.0	1.1154	33.0	1.2946	51.0	1.5428
1.0	1.0069	16.0	1.1240	34.0	1.3063	52.0	1.5591
1.5	1.0105	17.0	1.1328	35.0	1.3282	53.0	1.5761
2.0,	1.0140	18.0	1.1417	36.0	1.3303	54.0	1.5934
2.5	1.0175	19.0	1.1508	37.0	1.3426	55.0	1.6111
3.0	1:0211	20.0	1.1600	38.0	1.3551	56.0	1.6292
3.5	1.0247	21.0	1.1694	39.0	1.3679	57.0	1.6477
4.0	1.0284	22.0	. 1.1789	40.0	1.3810	58.0	1.6667
5.0	1.0357	23.0	1.1885	41.0	1.3942	59.0	1.6860
- 1				[]		60.0	1.7059

XXI.—COMPARISON OF METRIC AND CUSTOMARY UNITS (U. S.).

Length

1 millimeter, mm. = 0.03937 inch. 1 centimeter, cm. = 0.39371 inch. 1 meter, m. = 3.28083 feet. 1 meter = 1.09361 yards. 1 kilometer = 0.62137 (U. S.) mile.	1 inch = 25.4001 millimeters. 1 inch = 2.54001 centimeters. 1 foot = 0.304801 meter. 1 yard = 0.914402 meter. 1 mile = 1.60935 kilometers.
--	--

Areas

Volumes

1 cubic meter	= 0.000061 in. = 0.06103 cu.in. = 35.314 cu.ft. = 61,028 cu.ins. = 1.3079 cu.yd.	1 cu.in. = 16,387.2 cu.mm. 1 cu.in. = 16.3872 cc. 1 cu.ft. = 0.02832 cu.m. = 28.32 liters.
T origin titofet	- 1.30/9 cu.ya.	1 cu.yd. = 0.7645 cu.m

Capacities

1 cubic centimeter, e 1 cubic centimeter	ec. =0.03381 (U.S.) liquid ounce, =0.2705 (U.S.) apothecaries'	1 ounce = 29.574 cc.
1 cubic centimeter	dram. =0.8115 (U. S.) apothecaries'	1 dram = 3.6967 cc.
1 liter 1 liter 1 liter 1 hectoliter	scruple. =1.05668 (U. S.) liquid quarts. =0.26417 (U. S.) gallon. =0.11351 (U. S.) peck. =2.83774 (U. S.) bushels.	1 scruple = 1.2322 cc, 1 quart = 0.94636 liter. 1 gallon = 3.78543 liters, 1 peck = 8.80982 liters, 1 bushel = 0.35239 hectoliter.

Masses

1 gram = 15.4324 grains. 1 gram = 0.03527 avoirdupois ounce. 1 gram = 0.03215 troy ounce. 1 kilogram = 2.20462 pounds (av.) 1 kilogram = 2.67923 pounds (troy).	1 grain = 0.06480 gram. 1 ounce (av.) = 28.3495 grams. 1 ounce (troy) = 31.10348 grams. 1 pound (av.) = 0.45359 kilogram. 1 pound (troy) = 0.37324 kilogram.
---	--

Table of Equivalents, U. S. Bureau of Standards. 'For British Imperial Weights and Measures see Van Nostrand's Chemical Annual.

Avoirdupois Weight

The system of weights in ordinary use by which common or heavy articles are weighed.

```
16 drams = 1 ounce = 28.35 grams,

16 ounces = 1 pound = 453.59 grams,

25 pounds = 1 quarter = 11.34 kilograms,

4 quarters = 1 hundred weight = 45.359 kilograms,

1 avoirdupois pound contains 7000 grains,

1 avoirdupois ounce contains 437.5 grains,
```

Apothecaries' Weight

The system of weights employed in weighing medicines.

1 grain = 0.0648 gram.
20 grains = 1 scruple = 1.296 grams.
3 scruples = 1 drachm = 3.888 grams.
8 drachms = 1 ounce = 31.103 grams.
12 ounces = 1 pound = 373.236 grams.
1 apothecaries' (or troy) pound contains 5760 grains.
1 apothecaries' (or troy) ounce contains 480 grains.

Fluid Measure

.06161 cubic contimeter. 1 minim 3.696 cubic centimeters. =1 fluid drachm = 60 minims 8 fluid drachms = 1 fluid ounce = 29.573 cubic centimeters. cubic centimeters. 16 fluid ounces =1 pint =473.179liters. = 3.7858 pints = 1 gallon 1 gallon contains 231 cubic inches.

The minim, fluid drachm, fluid ounce and pint are the fluid measures employed by apothecaries.

Other Data

1 cubic foot of water weighs 62.37 pounds.

1 gallon (U.S.) of water weighs 8.33 pounds (the British gallon is 20% more than the U.S.).

1 liter of water weighs approximately 2.2 pounds.

Areas of Plane Figures

Area of any triangle = $\frac{1}{2}$ base multiplied by the altitude.

Rectangle. Area = base multiplied by altitude, i.e., multiply the length of one side by the length of a perpendicular side.

Parallelogram. Area = multiply the length of one side by the vertical distance to the parallel side.

Trapezoid. Area = multiply half the sum of the parallel sides by the perpendicular distance between the two.

Circle. Area = $0.7854d^2$, or πr^2 or $\frac{1}{2}Cr$, or $\frac{1}{4}Cd$.

 $\pi = 3.1416$, r = radius, C = circumference, d = diameter.

Volumes of Solids

Regular Prism. Area = $\frac{1}{2}nrah$, or Bh.

n = number of sides, r = perpendicular from center of base to sides of the base, h = height of prism, B = area of base.

Lateral area = $2\pi rh$.

Right Circular Cylinder. Volume = $\pi r^3 h$ also Bh. Lateral area = $2\pi rh$. Regular Pyramid. Volume = $\frac{1}{3}$ altitude multiplied by area of base.

Right Circular Cone. Volume = $\frac{1}{2}\pi rh$. Lateral area = πrs .

 $r = \text{radius of base}, s = \text{slant height or } \sqrt{r^2 + h^2}.$

Sphere. Volume = $4/3\pi r^2$, or $4.189r^2$. Area = $4r^2$ or $3.1416d^2$.

Barrel or Cask. Approximate gallons = $.0034n^2h$ where n = mean diameter of barrel. h = height, both measurements in inches.

XXII.--A TABLE OF CONSTANTS

All Volumes of Gases and Vapors are given at 60° F. and 30" pressure.

THE UNITED GAS

1.	n,	111.	IV.	v.	VI.	VIL	VIII.	IX.	x.	XI.	X11.
									Heat nf	Combu	stinn.
NAME OF GAS OR VAPOR.	SYMBOL OR FORMULA.	Weight.	ty Gas or t 60° F.	do t	ry Liquid	Eq. Wis. 1.0	t per	Cubie Pounds.	A W	The	tish rmal
•		Molecular Weight.	Sp. Gravity Vapor at Air = 1.0.	Boiing-point	Sp. Gravity at 60° F. Water = 1.	Sp. Heat Eq. v at Const. Pr. Water = 1.0.	Cubic Feet Pound.	Weight 1 (Foot in]	Calories per Molecular in Grams.	Per Cu. Ft.	Per Pound.
Carbon to CO Carbon to CO Carbon to CO Carbon to CO Carbonic Ox Hydrogen Methane Ethane Ethane Propane. Butane Propane. Butane Butane Ethylene Amylene Amylene Anetylene Allylene Crotonylene Butylene Mestaylene Mestaylene Mydrogen Gydrogen Gydrogen Carbon Bil-Bul Methyl Alo Methyl Aloohni Carbonic Acid Water Bulphur Diox. Oxygen	COMPANY ACCURATE ACCUPANT PRESENTA ACCUPANT ACCU	72 86 28 42 56 70 26 40 54 78 92 106	0.8292 0.8292 0.9692 0.0692 0.5529 1.0368 1.5206 2.0045 1.4883 2.9721 0.9676 1.4514 1.9353 2.4191 0.8984 1.8823 1.	- 13° + 33° + 100° + 156° - 102° - 102°	0.6273 0.6640 0.6511 0.8846 0.8720 0.8692 1.1517	0.2450 3.0490 0.5929 0.4040 0.3754 0.2423 0.5083	15.749 13.749 13.5020 13.526 12.594 8.587 6.514 4.393 13.997 6.747 5.386 14.534 4.107 3.565 3.149 2.952 11.095 2.952 11.742 8.907 6.747 1.742 8.907 1.742 1.743 1.744 1.	0C3.70 0C3.50 0C4.00 0O530 0O4230 0O7940 11645 15350 19055 22780 07410 11111 14820 14820 14820 10855 14290 0012 00450 10710	270,440 529,210 847,110 999,20 333,350 492,740 650,620 807,630 310,085 467,550 799,350 955,680 1,282,310 140,900 90,560 158,620 259,620 265,130	3274 . 0 4035 . 6 4759 . 8 1588 . 0 2347 . 2 3099 . 2 3847 . 2 1476 . 7 2227 . 1 	7,549 9,599 10,578 8,989 6,279

.05922 = 28.316 × .0022046 × 30.00 × 492

. The weights of the compound gases are calculated from these data by Avogadro's law.

Column IV. is calculated by the formula: sp.gr = wt. 1 su. ft. gas, and the figures thus obtained agree with the theoretical formula; ap.gr. = mol. wt.

In Column IX. tha figures given in Hempel'a "Gas Analysis," p. 375, were selected for the fundamental weight of Oxygen, Nitrogen, Hydrogen, Carbonie Oxide and Air.

The formula used for the conversion to English units, is—grams per liter at 0° C. and 760 mm.×.05922 — pounds per ou.ft. at 60° F. and 30° pressure. The derivation of the factor employed is

FOR CERTAIN GASES AND VAPORS

IMPROVEMENT COMPANY

The Temperature of Products of Combustion is reduced to 18° C. = 64.4° F.

XIII.	XIV.	XV.	XVI.	XVII.	XVIII	XIX.	XX.	XXI.	XXII.	XXIII.	XXIV.	xxv.	XXVI.
C			Cu. Fi	. of	Pou	ods per	Pound (of Com	bustible,		of Form Const. P		
Req.	bus-		Produc Sombu		Req. Com	bus-	Produ	ota of C	ombustion.	# # # # # # # # # # # # # # # # # # #	В	t.u.	NAME OF GAS OR VAPOR.
Air.	Oxy-	CO1	H ₂ O.		Air	Oxy- gen.	COs	H ₂ O		Calories per Molecular in Grams.	Per Cu. Ft.	Per Pound.	
4. 785 9. 570 2. 393 2. 393 2. 393 16. 748 38. 280 16. 385 38. 280 38. br>380 380 380 380 380 380 380 380 3	12.0 12.0 1.5 0.75 1.25 2.0 3.0 1.6 8.0	6.0 7.0 8.0 9.0 10.0 1.0 2.0 1.0 2.0	1.0 2.0 4.0 5.0 6.0 7.0 2.0 3.0 4.0 6.0 4.0 1.0 6.0 1.0 6.0 3.0 3.0 4.0 1.0 1.0 1.0 1.0 1.0 1.0 1.0 1.0 1.0 1		11. 54! 424 424 17: 312 2. 471 134. 424 17: 312 2. 471 16: 16: 16: 16: 16: 16: 16: 20: 16: 38: 16: 14: 83: 61: 14: 83: 61: 14: 83: 61: 14: 83: 61: 14: 83: 61: 14: 83: 61: 14: 83: 61: 14: 83: 61: 14: 83: 61: 14: 83: 61: 16: 16: 16: 16: 16: 16: 16: 16: 16	671 8 000 4 000 3 733 3 636 3 586 3 586 3 586 3 585 3 428 3 428 3 428 3 428 3 428 3 428 3 428 3 100 3 100 3 100 1 1412 1 1481 1 1			SO ₂ 1.883 N-0.823 N-0.518 N-0.538 SO ₂ -1.684	+21,750 +22,560 +23,560 +42,550 +41,890 -2,710 +3,220 +10,660 +18,970 -47,770 -39,650 -12,510 -3,620 +4,740 +11,890 -27,480 -66,700 +26,700 +58,470	+136.0 +167.2 +202.2 +207.9 +200.9 +16.3 +50.7 -113.7 -227.5 +113.7 -227.5 +16.7 -47.3 +16.7 -131.1 -124.0 +278.6	+2435.6 +1713.6 +1436.3 +1317.3 +1196.2 +1278.4 -174.2 +138.1 +342.6 +514.1 -299.3 -68.8 +7.3 -299.3 -68.8 +250.9 +1259.0 -2273.9 -616.0 +2388.0 +2388.0 +2388.0	Hydrogen Methans Ethane Propans Butans Pentans

ODS OF CALCULATION.

Columns V. and VI. are taken chiefly from Lunge's "Coal Tar and Ammonia."

Column VII, is from Ganot's "Physics," edition 1895, page 446.

Column X. and XXIII. are from Julius Thomsen's "Thermochemical Investigations," and his results are translated into English units in columns XI.—XII. and XXIV.—XXV.

Columns XIII, and XVIII, are calculated on the assumption that

air = 20.9% oxygen + 79.1% nitrogen by Volume.

air = 23.13% oxygen + 75.87% nitrogen by Wolcht.

XXIII.—SPECIFIC GRAVITY OF GASES*

Name.	Formula.	Molecular	Specific	Gravity, Air = 1.	Weight in Grams of 1 Liter at 0°,
Name.	rormus.	Weight.	Calculated.1	Observed.	760 mm, at Sea Level, Lat. 45°.
Acetylene	C ₂ H ₂	26.026	0.8993	0.9056	1.1624
Air			1.0000		1.2926
Ammonia	NH ₂	17.034	0.5856	0.5971	0.7608
Argon	A	39.88	1.3780	1.379	1.7812
Arsine	AsH ₁	77.984	2.6933	2.695	3.4830
Bromine	Br2	159.84	5.5230	5.524(227.9°)	7.1390
Butane	C ₄ H ₁₀	58.10	2.0075	2.01	2.5949
Carbon dioxide	CO ₁	44.005	1.5205	1.52908	1.9654
Carbon monoxide	CO	28.005	0.9677	0.96716	1.2508
Carbon oxysulphide	COS	60.065	2.0754	2.1046	2.6827
Chlorine	Cl	70.92	2.4505	2.4901	3.1675
Cvanogen	C.N	52.03	1.7977	1.8064	2.3338
Ethane	C ₂ H ₆	30.058	1.0386	1.0494	1.3425
Ethylene	C2H4	28.042	0.9689	0.9852	1.2524
Fluorine	F ₂	38.0	1.3130	1.26	1.6972
Helium	He	4.00	0.1382	0.131	0.1786
Hydrobromic acid	HBr	80.928	2.7963	2.71	3.6145
Hydrochloric acid	HCl	36,468	1.2601	1.2681	1.6288
Hydrofluoric acid	HF	20.008	0.6913	0.7126	0.8936
Hydroiodic acid	ĤÎ	127.928	4.4203	4.3757	5.7137
Hydrogen	H	2.016	0.06965	0.06952	0.09004
Hydrogen sclenide	H ₂ Se	81.216	2.8063	2.795	3.6274
Hydrogen sulphide		34.076	1.1774	1.1906	1.5220
Hydrogen telluride		129.516	4.4752	4.489	5.7846
Krypton	Kr	82.92	2.8252	2.868	3.7035
Methane	CH4	16.037	0.5541	0.5545	0.7163
Neon	Ne	20.2	0.6980	0.6963	0.9022
Nitrie oxide	NO	30.01	1.0370	1.0367	1.3404
Nitrous oxide	N ₂ O	44.02	1.5210	1.5298	1.9661
Nitrogen	N ₂	28.02	0.9682	0.96737	1.2515
atmospheric	N ₂ +A etc.	20.02	0.5002	0.97209	1.25718
	NO ₂	46.01	1.5898		2.0550
Nitrogen dioxide			3.1788	1.60(135°)	4.1099
Nitrosyl chloride	NOCI	92.02	2.2622	2.65(26.7°) 2.31	2.9241
		65.47		1.1053	1.4292
Oxygen		32.00	1.1057	1.1829	1.5214
Phosphine	PH3	34.064			1.8787
		42.063	1.4534	1.498	
Silicon fluoride		104.3	3.6039	3.60	4.6584
Sulphur dioxide		64.06	2.2135	2.2638	2.8611
Xenon	X	130.2	4.4988	4.526	5.8152

*D. Van Nostrand Chemical Annual.—Olsen.

¹ Obtained by dividing the weight of one liter of the gas by 1.2926 (i.e., by the weight of one liter of air).

² Obtained by multiplying $\frac{1}{2}$ the molecular weight of the gas by $\frac{1}{16} \times 1.429234$ (i.e., by $\frac{1}{16} \times 429234$ (i.e., by $\frac{1}{16} \times 429234$).

USEFUL MEMORANDA

Gas Calculations

Conversion Formulae for Gas Volumes. Conversion from existing to standard conditions.

$$V = \frac{V' \times 273 \times (P - w)}{273 + t \times 760}.$$

Gas at standard volume to new conditions of temperature and pressure

$$V' = \frac{V \times 273 + t \times 760}{273 \times (P - w)}.$$

V = standard volume, V' = volume under other conditions of temperature and pressure (other than 0° C. and 760 mm. Hg pressure).

t = temperature of the gas, P = barometric pressure in mm. Hg + static pressure of the gas. w = water vapor pressure at temperature and pressure that the gas is measured or to which it is to be converted.

Petot Formulae for Measuring the Velocity of a Gas in a Flue.

- A. Simple formula for fair approximations $V = 42\sqrt{h}$.
- B. More exact formula $V = 1290 \frac{\sqrt{\frac{1}{2}h(1 + .00217t)}}{BM}$
- V= velocity in feet per second. h= gauge reading in terms of water, i.e., the total differential in terms of vertical reading. In a gauge inclined 1:10, with ether in place of water, 10'' differential $=10\times.72+10=.72$. In the formula $B\frac{1}{2}$ the reading is taken as the deflection due to velocity pressure is half the total deflection (proven by repeated tests, suction is producted by the gas flow on the straight petot arm). Allowance is made for this in formula A. t= temperature of the gas measured. B= barometric pressure + plus static pressure of the gas in terms of inches of mercury (air standard 29.92''). M= specific gravity of the gas compared with the hydrogen molecule $H_2=2.016$.

To obtain the specific gravity of a gas, multiply the molecular weight of each constituent by its per cent ratio in the mixture, divide by 100 and finally divide the sum of these results by 2.016.

Examples. The sp.gr. of a gas having the composition 87% nitrogen, 5% oxygen, and 8% sulphur dioxide we would find

$$28.02 (N_2) \times 87 + 100 = 24.38$$

 $32.00 (O_2) \times 5$ " = 1.6

64.06 (80₂) × 8 " = 5.12 total = 31.1 sp.gr. =
$$\frac{31.1}{2.016}$$
 = 15.42.

The sp.gr. of air containing 78% nitrogen, 21% oxygen, 1% argon would be

$$28.02 \times .78 = 21.86$$
, $32.00 \times .21 = 6.72$, $39.88 \times .1 = 0.4$ total = 28.98 sp.gr. = 14.38.

Consult table XXIII.

The gram molecular weight of any gas occupies 22.4 liters.

Definitions

Heat

Calorie is 1/100 of the heat required to raise the temperature of one gram of water from 0° C. to 100° C.

One kilogram calorie = 1000 gram calories or 3.968 B.t.u.

Latent heat of evaporation is the quantity of heat required to convert 1 gram of a liquid into vapor without change of temperature.

Latent heat of fusion is the quantity of heat required to change a gram of the substance from a solid to a liquid state without changing temperature.

Specific heat. The British thermal unit (B.t.u.) = 1/180 part of the heat required to raise the temperature of one pound of water from 32° F. to 212° F.

Specific heat of a body is the quantity of heat required to raise the temperature of a unit weight of that body one degree, C.

Photometry

Lux. This is the practical unit of illumination and is the light received from a source of 1 meter distance.

Foot-candle. This is the illumination received by a standard candle at one foot distance. The candle loses in burning 120 grams per hour.

1 foot-candle = 10.76 lux.

Candle-power. The comparison of the illumination of a light with one standard candle. A simple method for determination is to place the light and the burning candle 60 inches apart (2 meters and 100 inches distance also taken). A screen with a spot of oil is so placed between the lights as to receive a uniform illumination on each side, which is readily seen by the spot. The square of the distance from the screen to the light tested divided by the square of the distance from the screen to the standard candle = the candle-power of the light. When gas is tested the flame is so regulated that it burns 5 cubic fect of gas an hour. The standard candle burns 120 grams per hour as stated above.

Units in Electricity .

Ampere is the unit of current flow. An ampere will deposit from a silver nitratesolution 1.118 milligrams of silver (.001118 g.) per second.

Coulomb is the unit of quantity. One coulomb will deposit .001118 g. Ag (time factor not considered as in case of ampere). 96,494 coulombs will deposit the gram equivalent of an element from a solution of its salt, i.e., $107.88 \text{ grams of silver}, \frac{63.57}{2} \text{ grams of cupric copper Cu}^{++} \frac{55.84}{3} \text{ of ferric}$

iron Fe⁺⁺⁺, 63.57 of cuprous copper Cu⁺, $\frac{55.84}{2}$ gram of ferrous iron Fe⁺⁺, etc. One gram equivalent of an element carries 96,500 (round numbers) coulombs.

Electromotive force—E.M.F.—is the force causing electricity to move. .

Erg. This is the unit of power and is the force which applied to the standard gram body would give that body an acceleration of 1 cm. per second.

Dyne = the force which acting on one gram for one second produces a velocity of one centimeter per second.

Joule. This is the practical unit of electrical energy and is produced when a steady current of one coulomb per second, i.e., one ampere, passes through a resistance of one ohm for one second.

Ohm. This is the resistance that is offered at 0° C. by a column of mercury 106.3 centimeters long, being 1 square millimeter in cross section and weighing 14.4521 grams.

Volt. This is the electromotive force which produces one ampere of current through a conductor having a resistance of one ohm.

If any two of the factors are known the third can be found by the

formula I = E/R; I = ampere current, E = electromotive force (volts) and R =ohms resistance.

Watt. One watt is produced when one ampere of current flows under a pressure of one volt (E.M.F.).

One watt = .00134 horse power, = 44.25 foot pounds, per minute, = 14.33 gram calories per minute, = .057 B.t.u. per minute.

Watt-hour and kilowatt-hour are the units of energy used in commercial electrical work.

Watt-hour = 3600 joules, = 2655.4 ft. lbs., = 859975 gram calories, = 3.412 B.t.u. = .001341 h.p. hr.One kilowatt = 1000 watts.

Other Terms

Foot-pound is the unit of work done in raising a weight of one pound through a distance of one foot. Work = weight multiplied by height, or force multiplied by distance.

Horse power = 550 foot pounds.

Specific gravity of a substance is the ratio of the weight of a given volume of that substance compared with the weight of an equal volume of water.

a. Solid heavier than water. Weight of solid in the air divided by the difference between this weight and its weight in water = sp.gr. of

b. Solid lighter than water. The weight of the solid in the air divided by this weight + the loss of weight of a sinker due to the buoyancy of the solid = sp.gr.

c. Solid soluble in water. Determine gravity in a liquid in which it is insoluble whose specific gravity is known, multiply the gravity in terms of the liquid by the gravity of the liquid = sp.gr. in terms of

d. Liquids. Compare with water by weighing in a specific gravity bottle; the bottle being filled with water is weighed, the bottle, drained and dried, is filled with the liquid and again weighed; the weights are compared on subtracting the weight of the empty bottle.

e. The loss of weight of an insoluble substance immersed in the liquid is divided by the loss of weight of the substance immersed in water

The specific gravity is determined by the hydrometer. See chapter on Acids, Volume 2.

1 lb. av. = 7000 grains ..1 gallon = 58417.87 grains

.: 1 lb. av. =27.679886 cu. in. H.O at 4°C.

∴ 1 cu. in. = 16.387083 cc. = 16.367083 g H, O at 4°C = 39°F.

Values used in constructing table:
 1 inch = 2.540001 cm.

'to .0001428.

. 231 cu. in. -1 gallon -3785.4162 g.

1 lb. av. =453.5926 g. ∴ 1 gal. =8.34541 lb.

VOLUME AND WEIGHT CONVERSION TABLE

					į		N	Multiply by							
Convert	t t	To To To To To To Cu. Ft. Ox.	Ca. Yd.	To Fi. Os.	To Pint.	To Quart.	To Gallon.	To To To To To To To To To To To To To T	To Ox. Troy.	To Oz. Av.	To Lb. Troy.	To Lb. Av.	CC. or G.	To Ltr. or Kg.	Ci. N
d. In.	1.00000	.0,5787	.0,2143	554112	.034632	.017316	.004329	1.00000 0.55787 0.2143 554112 034632 017316 004329 252 891 526857 578037 043905 036127 16 3871 016387 045000 0.55787 0	526857	578037	.043905	.036127	16.3871	016387	0.163
Ye.	1728.00 46656.0	27 0000	1.00000	957.505 25852.6	59.842 1615.79	807.896	201 .974	1728.001.000001.037037 957-505 9	24581.0	26968.9	2048.42	1685.36	764556	764.556	76455
Oz.	1.80469	001044	0,3868	16 0000	062500	500000	125000	1.80469 001044 0,3868 1.00000 062500 031520 007813 456.339 930813 1.04518 00548 00548 25.318 0.0548 0.0548 0.0548 0.0558 0	.950813 15.2130	16.6908	1.26775	1.04318	473.177	473177	0.473
art.	57.7500	033420	.001238	32.0000	20000	1.00000	250000	Cust 157 7500 033420 001238 32 00002 000001 00000 250000 1460 45 30 4260 33 38162 35502 08635 946 354 946354 0	30.4260	33.3816 133.527	2.53550	2.08635 8.34541	946.354 3785.42	3.78542	0,946
llon	231.000 203954	0,2288	0,8475	161200	0,1369	0,6850	0,1712	Gallon 231 .000 .133081 .004951 .125 .000 4.0050 .0.1712 1.00000 .002083 .002386 .0.1736 .0.1428 .0.6479 .0.6479 .0.6679 .0	.002083	002286	0,1736	0,1428	064799	046479	0,647
. Troy	1.89805	860100	.0,4068	1.05173	065733	.032867	008217	437.500	911457	1.0000	075955	062500	28.3495	028350	0,283
Av	22, 7766	013181	0.4882	12.6208	788800	394400	009860	5760.00	12.0000	13.1657	1.00000	.822857	373.242	373242	0.373
Av.	27.6799	.016018	.0,5933	15.3378	.958611	.479306	119826	70000	14.5833	16.0000	1.21528	00000	453.593	405080	066#\$0.
Gram.	.081024	.0,3531	.0,1308	.033814	.002113	.001057	.0,2642	.061024, 043531 .041308 .033814 .062113 .001057 .042642 15.4323 .032151 .035274 .002679 .0022051 .00000 .001000 .000001	.032151	.035274	.002679	.002205	1.00000	001000	<u>8</u>
Lifer or Ker. Cu. M.	61.0237 61023.7	.035315 35.3146	001308	33.8140 33814.0	2.11337 2113.37	1.05669	.264172 264.172	Lifer or 1.0237 035315 001308 33.814 0 211337 1.05669 264.172 15432 332 1507 35 2739 2.67923 2.204621000 001 00000 0010000 0010000 0010000 0010000 0010000 0010000 0010000 0010000 0010000 00100000 0010000 0010000 0010000 0010000 00100000 0010000 0010000 00100000 0010000 0010000 0010000 0010000 0010000 0010000 0010000 00100000 0010000 0010000 0010000 0010000 0010000 0010000 00100000 0010000 0010000 0010000 0010000 0010000 0010000 0010000 00100000 00100000 0010000 0010000 0010000 0010000 0010000 0010000 0010000 00100000 00100000 00100000 00100000 00100000 00100000 001000000	32.1507 32150.7	35.2739 35273.9	2.67923 2679.23	2.20462 2204.62	1000001	100000	000.1
Note.	The su	nall subn	umeral fo	llowing	a zero in	dicates th	hat the z	Note. The small subnumeral following a zero indicates that the zero is to be taken that number of times: thus, .0.1428 is equivalent	be taken	that no	mber of	times: t	hus, .0,1	428 is eq	

ENERGY CONVERSION FACTORS

To convert from B. T. U. F. C. U. Cal. Ft. 1ba. Ft. Tons Ke. M. B. T. U. 1.00000 555556 251996 778.000 389001 107.563 P. C. U. 1.80000 1.00000 453593 1400.40 700202 193.613 Calorice 0.01285 0,7141 0,3239 1.00000 3091.36 1.5458 426.844 Fr. Ions 2.57069 1.42816 647894 2000.00 1.00000 276.511 KE. M. 0.09297 0.05165 0.02347 0.02347 1980000 1277.10 KW Hrs. 3411.57 1895.32 264200 1327.10 366959 Joules 1.4547 0.62566 0.1327.10 366959 O.99477 0.65266 0.1327.62 113157 Fix. Converse 0.69477 0.65266							Multiply by					
U. 1.00000 55556 251996 778.000 389001 U. 1.80000 1.00000 453593 1400.40 700202 to. 1.80000 1.00000 453593 1400.40 700202 to. 2.27462 1.00000 3091.36 1.5368 1.5368 d. 2.57069 1.42816 647804 2000.00 1.00000 d. 2.57069 1.42816 647804 2000.00 1.00000 d. 2.646.99 1.11388 641.327 1.00000 32.11 d. 3.411.57 1896.32 859.702 2654200 1327.10 s. 0.92565 0.2388 737311 0.3587 6.0287 s. 0.92565 0.2388 737311 0.3587 6.0287	To Convert From	B. T. U.	P. C. U.	j S	Ft. Lbs.	Ft. Tons	Kg. M.	HP Hrs.	км на.	Joules	Lbs. C	Lbs. H ₂ O
U. 1.80000 1.00000 453593 1400.40 700202 ise 3.90832 2.20462 1.00000 3091.36 1.5368 ion 2.57069 1.42816 647804 2000.00 1.00000 d. 0.005165 0.02343 1.00000 1.00000 d. 0.005165 0.02343 1.00000 1.00000 d. 1.42816 647804 2000.00 1.00000 d. 2.57069 1.42816 647804 2000.00 1.00000 d. 3.411.57 1896.32 859.702 2654200 1327.10 d. 1.64.4 0.005.06 0.2388 737311 0.3687 d. 0.95265 0.2388 737311 0.3687 d. 0.95265 0.2388 737311 0.3687	D.	00000	.555556	251996	278,000	389001	107.563	0,3929	0.2931	1055.20	0,6876	.001031
ice 3.96832 2.20462 1.00000 3091.36 1.54368 bb. .001285 0,77141 0,3239 1.00000 .000500 conse .2.57669 1.42816 .647804 .2000.00 1.00000 fra. .009297 .005165 .002343 7.23301 .003617 fra. .2544.99 .141388 .641.327 .1980000 .990.004 Hra. .3411.57 .1895.32 .859.702 .2654200 .1327.10 s. .045265 .042388 .73731 .043687 s. .045265 .042388 .73731 .043687	D	.80000	1.00000	.453593	1400.40	700202	193.613	.0,7072	.C.5276	1899.36	.0,1238	.001855
ba. 001285 0,7141 0,3239 1 00000 000500 cons 2.77069 1.42816 647804 2000 00 1 00000 d. 0.09297 0.05165 0.06243 7 23301 0.03617 line 2.544 99 141388 641 37 1390000 99 0.04 Hra. 3411 57 1895 32 859 702 2654200 1327 10 s. 0.05265 0.2388 737311 0.3587 36 365 3	ie	3.96832	2.20462	1.00000	3091.36	1.54368	426.844	.001559	.001163	4187.37	.0,2729	.004089
Conse 2.57069 1.42816 647804 2000.00 1.00000 Ma .008297 .0063165 .002343 .723301 .003617 Hra .2544 .99 .141388 6411 .27 1890000 990 .09 Hra .9411 .57 1895 .32 859 .70 2654200 1327 10 A .95266 .02 .02388 .73731 .93687 .62 .63 .62	De.	001285	.0,7141	0,3239	1.00000	.000200	. 138255	.0,5050	.0,3767	1.35625	0,8840	.0,1325
fine 2544.99 141388 641.327 198000 990.004 Hrs. 3411.57 1895.32 859.702 2654200 1327.10 fine 3411.57 1895.32 859.702 2654200 1327.10 fine 10,5265 0,2388 737311 0,3587 fine 1,444.4 0,0506.00 986.7 12316.0 656.7	One	3.57069	1.42816	647804	2000.00	1.00000	276.511	.001010	0,7535	2712.59	.0,1768	.002649
Hrs. 2544.99 141388 641.327 1980000 990.004 Hrs. 3411.57 1865.32 859.702 2654200 1327.10 s. 19477 165266 16,2388 737.31 1,3388 s. 1,444.4 0,000.00 368.6 112316.0 656.7	3	009297	.005165	.002343	7.23301	.003617	1.00000	.0,3653	0,2725	9.81009	.0,6394	.0.9580
Hrs. 3411.57 1895.32 859.702 2654200 1327.10 8	Line	2544.99	.141388	641.327	1980000	990.004	273747	1.00000	.746000	2685473	.175044	2.62261
6	Hrs.	411.57	1895.32	859.702	2654200	1327.10	366959	1.34041	1.00000	3599889	.234648	3.51562
14544 A GOOD ON 3865 AS 113150		0,9477	.0,5265	.0,2388	.737311	.0,3687	. 101937	.0,3724	.0,2778	1.00000	.0,6518	.0,9766
CONTRACTOR OF TARTER OF TA	0	4544.0	8080.00	3665.03	113150	5657.63	1564396	5.71434	4.26285	153470;	1.00000	14.9876
H,O	H.O.	70.400	539.111	244.537	754971	377.487	104379	.381270	.284424	1023966	.066744	1.00000

"P.C.U." refers to the "pound-centigrade unit." The ton used is 2000 pounds. "Lbs. C" refers to pounds of carbon oxidized, 100 % efficiency, equivalent to the corresponding number of heat units. "Lbs. H₂O" refers to pounds of water evaporated at 100° C. = 212° F. at 100% efficiency. The sub-numeral following a zero indicates that the zero should be taken the number of times indicated. Thus: 0,3653 is · equivalent to .000003653.

INTER-CONVERSION TABLE

					Multi	Multiply by				
To Convert from	Oraline per	Ounces per Cu. Ft.	Pounds per Cu. Ft.	Grams per Cu. Ft.	Grains per Galion	Ounces per Gallon	Pounds per Gallon	Grains per Cu. In.	Ounces per Cu. In.	Grams per Liter
Grains per Cu. Ft	1.00000	.002286	.0,1428	.064799	.133680	.0,3056	0,1910	.0,5787	0,1323	.002288
Lie per Cu. Fr.	7000.00	16.0000	1.00000	28.4954 453.593	58.4848 935.757	2.13885	.133680	4.05090	009258	1.00103 16.0163
C. per Cu. Fr.	15.4324	.035274	.002205	1.00000	2.06302	.004715	.0,2947	.008931	0,2041	.035310
Oranne per Gallon	3272.72	7.48050	.467510	21.2068	437.500	1.00000	062499	1.89392	003429	7.48798
Libe per Gallon	52363.6	119.690	7.48014	3393.09	2000.00	16.0000	1.00000	30.3028	.069261	119.808
Or per Cu. In.	756000	1728.00	108.000	48987.8	101061	231.000	14.4370	437.500	1.00000	1729.73
G. per Liter	437.050	026866	.062432	28.3203	58.4220	.133540	.008346	.252910	.0,5780	1.00000

INTER-CONVERSION TABLE

			Multiply by		
To Convert From	Lbs. per Sq. In.	Tons per Sq. In.	Kg. per Sq. Cm.	M. Tons per Eq. Cm.	Atmospheres
Lbs. per Sq. In Tons per Sq. In	1:00000 2240:00	.000446	.070307 157.488	.047031 .157488	.068041 152.412
Kg. per Sq. Cm Metric Tons per Sq. Cm Atmospheres	14.2233 14223.0 14.6970	6.34969 .906558	1.00000 1000.00 1.03329	1.00000 .001033	.967768 967.768 1.00000

1 gram = 15.43 grams 1 gram = .0468 grams 1 m. = 3.28 ft.

The above tables were obtained by courtesy of du Pont Ne Mours Company through the kindness of Dr. E. C. Lathrop.

-			×		٥	log 12 olog 12								144 = 144 =				0	
141	0	1	2	3	4	5		7	a			PF	OPO	RTIC	NA	L P	ART	5.	
		_	_		•		٠	•	•	•	1	2	3		5	6	7	8	9
10 11 12 15 14	0414 0798 1139	0453 0628 1178	0498 0864 1906		1271	0907 0969 1303	0645 1004 1835	0689 1038 1367	0719 1079 1399	0374 0755 1106 1430 1732	44000	3 7 6	19 11 10 10 9	1 18	81 19 17 16 15	23	29 98 94 23 31	83 80 98 98	37 94 31 98
18 19 19 18	9041 9304 9558	2068 2330 2577	2095 2555 2001	1847 2122 2380 2625 2856	2148 2405 2648	\$175 9430 9679	9433 9433 2693	2227 2480	2253 2504 2749	9014 9279 9599 9763 9989	8 8 9 9 9	6 5 5 5 4	38777	11 11 10 8 2	14 13 19 18	17 16 15 14 18	90 18 17 16 10	99 81 90 19	34 34 31
20 91 98 94	3010 3889 3494 3617	3948 3444 3636		3075 3284 3483 3674 5856	3304 3503 3692	3394 3529 3711	8343 3541 8729		5333 3579 3766	3598 3784			6 6 6 5	3 3 7 7	11 10 10 2 9	18 18 18 11 11	18 14 14 18 18	17 16 18 13 14	10 10 17 17 18
ALC: NO.	4150 4314 4472 4694	4166 4330 4487	4183 4346 4509	4031 4200 4362 4513 4669	4916 4378 4533	4932 4393 4548	4949 4409 4564	4099 4265 4425 4572 4728	4981 4440 4394	4609	2 2 2 2 1	3 3 3 3	8 8 5 5	7 7 6 6 6		10 10 10 8	12 11 11 11 10	14 13 18 19	18 14 14 14
	T	4786 4998 5065 5198 5398	4800 4942 5079 5211 3340	4814 4955 5092 5294 5353	4829 4969 5105 3237 5366	4943	4997	4371 8011	5094	4900 5038 5179 5308 5428	111111		*****	6 6 5 5	77706	0	2 2	11 11	
	71	5894 5809	5468 5537 5705 3821	5478 5599 5717 5838 5044	5490 5611 5799 5848	5693 5740 3855	5635 5732 5866	50%7 5647 5768 5377 5288	5559 5658 5775 5883	5331 5670 5786 5899	111111		444		65865	44444	0	10 10 2 2	11 10 10 10
		6136 6248 6645 6444	6149 6253 6355	6053 6160 6263 6365 6464	6170 6974 6373	6180 6284 6385	6181 6294 6393	6096 6301 6304 6405 6508	6212 6314 6415	6323 6325 6435	111111				5 5 3 5 5	00000	44448	0::::::::::::::::::::::::::::::::::::::	8
				4561 6749 6889 6988	6065 6758 6848	6678 6767 6857	6684 6776 6866	6599 6683 6785 6473- 6964	6709 6794 6884	6718 6803 6893					\$ 5 5 4 4		77000	* 7777	
				7018 7101 7185 7867 7848	7094 7110 7190 7976 7356	7083 5 7988	7042 7296 7210 7206 7206 7273	7056 7135 7916 7300 7300	7069 7148 7896 7806 7806	7067 7133 // 148 7816 7806	-			******	-			77766	
				2					W 120 1		oolo	(3L)	=	X 5 2/2	3				

Communication by H. G. Shaw, Pu.D.

A convenient chart mounted on cardboard may be obtained of the above logarithms and the following antilogarithms from L. E. Knott Apparatus Co., 79-83 Amiliarst Street, Cambridge, Mass.

<u>-</u> -				777 .221		-				og .55 og .55							
							_							TIN	VAL I	ADT	-
108.	0	1	2	3	4	5	6	7	8	9					5 6	12	
55 56 57 58 58	7482 7559 7634	7490 7568 7642	7497 7574 7649	7582 7657	7435 7518 7589 7664 7738	7520 7597 7672	7529 7604 7679	7456 7536 7612 7686 7760	7543 7619 7694	7551 7627 7701		9		3 3 3 5	4 5 4 6		8 8 8 8
60 61 62 63 64	7858 7924 7993	7860 7931 8000	7868 7938 8007	7675 7945 8014	7810 7892 7952 8021 8089	7889 7959 8028	7696 7966 8035	7832 7903 7973 8041 3109	7910 7980 8048	7917 7987 8055	10000	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	П	5 3 5 3	4 4 4 8 4 8 4 8	5 5 5 5 5	6 6 8
55 St 55 St	\$199 \$195 8961 8396 8398	8908 8967 8381	\$209 \$274 \$33\$	8215 8280 8344	8222 8267 8651	8228 8293 8357	8235 8299 8368	8176 8241 8306 8670 8432	6248 8312 8376	8254 8316 8889		1 1 1 1 1 1 1 1 1 1 1 1	Ì	à	3 4	-	
70 11 12 12 14	\$451 \$518 \$575 \$638 \$692	8519 8576 8639	8525 8585 8645	8561 8521 8651	8537 8597 8657	8548 8605 8663	8549 8909 8669	8494 8555 8615 8675 8733	8561 8621 8681	8567 8627 8686	11111			9	8 4 5 4 8 4 8 4		55555
75 11 17 17 17 17 17 17 17 17 17 17 17 17	8465 8981 9976	8871 8927	8876 8982	8768 8825 8882 8938 8998	8887 8943	8837 8898 8946	8848 8899 8954	8721 8848 8904 8900 9015	8854 8910 5965	3859 8915 9971	-						5 4 6
82234	9001 9005 9138 5121 9343	9090 9148 5196	9096 6149 9301	9101 2154 9206	9106 6156 9919	2165 9217 9269	6117 6170 9898 9874	2122 2175								Section 1	
85 87 88	9394 9345 9395 9445 9494	9850 9400 9450	9855 9405 9485	9360 9410 9460	9865 9415 9465		9425 9474 9482	94.79 94.88	9683	93,0 93,0 94,0 94,0 9538	11000	1 2 1 1 1 1 1 1				****	
80 mm mm mm mm mm mm mm mm mm mm mm mm mm	9542 9590 9638 9645 9781	5565 9643 9689	9600 9647 9694	9605 9658 9699	9809 9857 970 8		9571 9612 9666 9715	9671 9717 9763	9628 9675 9788 9764	9633 9680 9787	90000	1 1 1 1 1 1 1 1 1 1 1				\$ \$ \$ \$	4 4 4 4 4 4 4
	9668 S 9613 S 9656 S	41-1 1017 1017	7423 9877 9661 9665	9791 9836 9881 9996	9795 9841 9886 9930 9974	9800 9845 9880 9934 9978	9050 9094 9909 9909	000									4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4
		77			9.70	47		**				130					

Int.	0	1	2	3	4	5	6	7	8	9	L	PR	OPO	RTIC	NAL.	PA	RTS	
											1	2	3	4	5	6	7	8 9
.00 .01 .02 .03	1023 1047 1072	1026 1050 1074	1028 1052 1076	1030 1054 1078	1009 1033 1057 1081 1107	1034 1059 1084	8 1014 5 1038 9 1062 1 1086 9 1112	1040 1064 1089	1042 1067 1091	1045 1069 1094	00000	0	1 1 1 1	1 1 1 1 1	1 1 1	1 1 1 2	2 2 2 2	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2
.05 .08 .07 .08	1146 1175 1302	1151 1178 1905	1153 1180 1208	1156 1183 1211	1138 1159 1186 1213 1242	1161 1139 1216	1138 1164 1191 1219 1247	1167 1194 1222	1169 1197 1225	1172 1199 1227	00000	1 1 1	1 1 1 1	1 1 1 1	1	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	2 2	2 :
.10 .11 .12 .13 .14	1988 1818	1969 1291 1321 1353	1294	1297 1327	1300 1380	1303 1334 1365	1276 1306 1337 1268 1400	1309 1340 1371	1312 1342 1374	1315 1346 1377	00000	i		1 1 1 1	2 2		9	
.18 .16 417 .13	1413 1445 1479 1614 1649	1416 1449 1483 1517	1452 1486 1521	1483 1482 1594	1459 1493 1528	1462 1496 1531	1432 1466 1500 1535 1570	1469 1503 1538	1478 1507 1548	1476 1510 1545	0000	1 1 1 1 1 1 1 1 1		1 1 1	2 2 2 2 2 2 2 2 2 2 2 2 2			3
·20 .51 .55 .54	1585 1622 1660 1698 1738	1696 1663 1709	1629 1667 1706	1633 1671 1710	1637 1675 1714	1641 1679 1718	1607 1644 1683 1722 1763	1648 1687 1726	1652 : 1690 : 1730 :	1656 1694 1734	00000	1 1 1 1 1 1 1 1	ı	2	2 2 2 2 2 2 2 2 2			3 4
.25 .36 .37 .34	1778 1890 1869 1905 1960	1894 1866 1910	1898 1871 1914	1882 1875 1212	1837 1879 - 1923	1841 1884 1928	1808 1845 1888 1932 1977	1849 1892 1936	354 1 397 1 941 1	858 1901 1945	00000	1 1 1 1 1 1 1 1 1 1		2 :	2 3 2 3 2 3 2 3	1 1 1 1	8	4 4 4 4
.30 .31 .33 .34	1995 2043 2062 2186 2186	1048 5 1094 5 1143 5	0051 5 0099 5 148 5	104 104	9061 2109 2158	9065 9118 9163	9083 1 9070 2 9118 5 9188 2 9818 2	198 S	1080 9 1198 9	084 188 183	0 0	1 1 1 1 1 1 1 1 1 1		2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2		2 2 2 2 4	4	44448
.38	2500 1 2001 1 2044 2 2200 1 2446 2	404 S	410 X	360 1 418 9	421	9317	2970 1 2373 1 2377 9 2438 9	1398 9 1399 9 1438 9	338 8 383 8 443 8	339 893 649	1 1	1 2 1 2 1 2 1 2		2 1 2 2 2 2 2 2 2 2 2 2	3	4444	44445	5 2 5 5 2
44	9512 3 9570 2 9690 3 9692 3 9754 3	576 3 536 3 508 3	643 2 643 2 704 3	588 2 849 2 710 2	894 685 718	2641 1 2600 1 2661 1 2793 1 2798 1	1006 S 1007 S 1750 S	613 9 673 9 785 9	612 24 672 24 743 37	194 148	1 1 1 1 1 1 1 1 1	3		2 5 2 3 3 3 3 3	4	44444	***	
45 46 47 48	9018 3: 9884 3: 9881 3: 9880 3:	194 31 191 31 195 31 197 31	131 21 107 21 104 21 104 21		4112	2041 1 2017 2 2042 2 2046 2 2126 3	094 34 093 34 043 34	931 35 999 36 998 36	193 90 106 30 178 30	18 88	1 1 1 1 1 1 1 1	*		1 1 4	44444	5 5 5 5	3 5 3 6 3	

Yantı.	0	1	2	13	4	5	6	 7	8	9		P	ROP	ORTI	DNAL	PAR	Γ5.	
		_	_	- 1	_					•	E	2	3	1	5 (16	. 8	0
.50	\$169	3170	3177	3184	3192	8199	3206	3214	3221	3228	П	1	9	L	4 4	W		r
.50 .51 .52 .68	3236	3243	3251	3258	3266	3273	3281	3286	3296	3304	ш		-	I i	44444	Ш		
.02	3911	3396	3404	3412	8420	3350 3428	3307 3436	3365 3443	3373	3351		2000	3	:		ш	Н	ď
.54	\$467	3475	3483	3184 3253 3334 3412 3461	8499	3509	3516	3524	3532	3540	L	2	2	Ŀ	4	L		Ť
.55 .56 .57	3548	3556	3365	3573	3581	■ -M.I:	3567	3606	3614	3622	Ī	9	3	2	4 (T	7	7
- 2	3631	3724	3733	3741	3750	3758	3531	3690 3776	3666	3707	П	*	***	H	58	Ш	Н	H
.51	3802	8311	3316	8656 3741 3398 3917	3837	3848	3855	3864	3873	3682	ı	****	3	8 5 4 4	44445		77777	×
.59	2890	8899	3908	3917	3926	3636	3945	3654	3963	3679		3	*	Ŀ	5 5	L	7	
.60 .63 .68 .63 .63	3981	3980	3999	4009 4102 4198 4295	4018			4046 4140				3	3 3		5 6 5 6		7	Ę
.68	4166	4178	4188	4198	4207			4236			I	ŝ	3	ш		Ш		K
.68	4266	4276	4285	4295	4805	4315	4625	4335	4345	4355		~~~	8		5 6 6 6	11		9
.64	-			4395		4416	4426	4436	4446	4407			_	L	0 6	L	ш	L
.65 .86 .87	4487	4477	4487	4498 4608 4710 4819 4932	4608			4536 4645				2 2 2	3 9 3	***	5 6 5 6 5 7	7	****	10
.87	4677	4683	4600	4710	4791			4753			i	3		П	5 7	ш	3	10
.69 .69	4786	4797	4808	4819	4831	4842	4653	4664	4675	4337	H	2	8	l t		1	9	10 10
.69	4000	8009	4930	4983	4945	4600	4966	4677	4686	8000			2	L	6 7	L	•	10
.70 .71 .78 .78	5012	5028.	5038	5047 5104 5284 5408	5058			5096 5212			1	3	4	5 5 5 5	6 7	2	40 10 10 10	11
79	5241	5980	5273	5284	5297			5368			н	998	Н	1 6	8 7	l š	10	н
-73	5370	5363	5398	5408 5504	5420			5458 5585			11111				677666	1	10	Щ
						9000	0012		9009	9010		3		Ľ	0 0	-		
.75 .78 .77 .78	5698	5686	5949	5662 5794 5929 6067 6209	5375	144					1	3	4	9	7 .		10 11 11 11 11	10
***	2222	576 B	0751 8618	0784 5929	5949			5848 5684			Н	н	Н		7	L	H	н
Ži.	6026	6089	8058	6067	6081	6095	6109	6124	3138	6159	l i			55588	77777	ļiŏ	ij	Ħ
-10	6168	6180	3194	8208	6223	6287	6259	6266	6281	6295	1	8	4	·	7 9	10	11	13
इंट्रब्रह्म इंट्रब्रह्म	6810	6894	6336	6353 6501 6653 6306	6368	HH						3	•	•	7 9	10	18 18 18 18 18	19
***	****		9310 9437	6433	9968	8683	6699	6561 6714	6730	6745	ì		Н	8	3 9 9	ш	ii	Ť
	111	Ē	ŧ	\cdots	8453	6836	6855	6871	6887	6902			4 2 5 5 4		2.9	1 !!		Ţ,
						9892	7018	7031	7047	7063		_			\$ 10			-
.85	7079	7000	7113	7129 7295 7464 7638 7816	7145			7194 7363			В		ē	44444	10 10 10 10 11 11	12	18 18 14 14	Ų
,87	7413	7450	7447	7484	7439			7584				3	5 2 5	i	9 10	ľü	ï	H
,85 ,89	Ø11	7008	7891	7638	7656			7709			12		5	7	9 11 9 11		1	Ţ
		_	_			1009	1010	7889	1901	1980			<u> </u>		V !!			
.99	7045	100	1980 1188	7996 8185 8375 8570 3770	8017	9035	8054	8072 8980	111	9110	-8	H	R	7	11 11 10 12 10	10 12 12 12 12	15	
ää		8397	8356	3375	1365	8414	8433	8453	8479	8499		ď	ď	H	0 18	134	Ш	Ť
	6710	0551 7780	3750 3750	3770 3770	8590 8780			8650 8851						B	11 11 10 12 10 14	14	Н	ď
	_			=						<u> </u>								
25	9130	2131	3853E	07/4 0103	6095 9304	9936 9441 9661 9886	90 96 9947	9057 9965	9073	9009 9311	8	4	H			1 11		+
27	1111	98.5A	9770	111	418	9441	9462	9494	9006	9534						14	Н	-
	117		iii i	9949	9863	9886	9008	9931	9004	9077	H	Н		图 5	H	1	Ħ	
	1	· .												P				

COMMON MINERALS

		001.		Spec	ifie
				Grav	vity
Alun	ninum	Al			2.60
And	dusite	Al-SiO.	.Silicate of aluminum	3.16-	
Angl	ovita	PISO.	Lead sulphate	6 19_	6 20
Anth	manita	LUCKY	Hard Coal	1.99	1.70
And	mony	.00	Phosphate of line	0.17	6.71
Apat	ite	OCA3P2Us, Car2	Thosphate of line	3.17-	
Arag	onite	CaCO ₃	Carbonate of lime		2.94
Arge	ntite	Λg ₂ δ	.Silver sulphide	7.20-	
Arse	nc	A8	. White arsenic		5.73
Arser	nolite	As ₂ O ₃	. White arsenic	3.70-	
Asph	altum		.Chloride of copper	1.0 ~	
Atac	amite	CuCl ₂ 3Cu(OH) ₂	.Chloride of copper		3.75
Azur	ite	Cu ₂ (OH) ₂ (CO ₂) ₂	. Blue carbonate of copper	3.77-	3.83
Barif	P	BaSO.	Barium sulphate	4.3 -	4.6
Baux	ite	Al ₂ O ₃ 2H ₂ O	. Hydrate oxide of aluminum	•	2.55
Berv	1	BeaAl-SigO18	.Silicate of beryllium	2.63-	2.80
Bioti	te		. Magnesia-iron mica	2.70-	3.10
Riem	orth	Ri	•		9.80
Rism	uthinite	Ri _s S _s	.Sulphide of bismuth	6.4 -	
Ritus	minous Con	1	Soft Coal	1.14-	
Ross	ita	Co.FoS.	Soft Coal	4.90-	
Code		Cdaraba		1.00	8.60
Cula	mung	U 75 S()	.Silicate of zine	3.40-	
			. Carbonate of lime	0.40-	
Carci	te	CitCO3	Dioxide of tin	0.0	2.7
Cassi	iterite	ShO2	. Dioxide of tin	6.8 -	
Cera	rgyrite	AgCl	. Horn silver	0.40	5.55
			.Carbonate of lead		
			. Copper glance		
Chal	copyrite	CuFeS2	.Copper pyrite	4.1 -	4.3
			.Chromic iron		
Chro	mium	.Cr	.,,,,		6.50
Chry	solite	(MgFe)₂SiO₄	Silicate of magnesia and iron	3.27-	
Cinn	abar	HgS	.Sulphide of mercury	8.0 -	
Coba	lt		Sulph-arsenide of cobalt		8.6
Cobs	ltite	CoAsS	.Sulph-arsenide of cobalt	6.0 -	6.30
Conr	ACT.	Co		8.8 -	8.90
Comi	րժատ	Al ₂ O ₂	.Oxide of aluminum	3.95-	4.10
Crvo	lite	Na ₃ AlF ₄	Fluoride of aluminum and sodium		3.00
Cunr	ite	Cu ₂ O	Red copper ore	5.85-	6.15
Cyon	ite	Al-SiO.	. Aluminun silicate	3.56-	
Dian	าดหลั	C			3.50
Dolo	mita	(CaMo)CO.	.Carbonate of lime and magnesia	2.80	
Fnor	rita	Cu AeS.			4.45
Enid	gios	HCo. (AlFo) Si.O.	Silicate of iron alumina and lime Fluor spar	3.25-	
Epid	ote	CoF.	Fluor spar		3.2
Franci	lilimita	Car 2	Oxide of zinc, manganese and iron	5.07-	
Colo	KIIIII OG	DLC	Sulphide of lead	0.01-	7.43
Care	.10	1 InJ	Sulphide of lead.	3.15-	
Cital				0.10T	
Gala	Li.	Au		1- U.U	0.00 8.0
Grap	nite	O-0- 1011 O	Sulphate of lime	2.09-	4.43
Gyps	um	C8504+2H2U	outphase of time	4.0	2.3
Hem	aute	rc ₂ U ₃	. Kea oxide of Iron	4.9 -	0.3
ice		n ₂ ()	. Iodide of silver	- 0	0.916
lody	rite	Agi	Locate of silver	5.6 -	5.7
Iridit	ım	<u> </u>	,	2	2.42
Iron.	• • • • • • • • •				7.86

COMMON MINERALS—Continued

	COMMO	THILLIAM COMMERCIAL	
			Specific
			Gravity
17 11 11	ATT (2.1.1.(2.40°/2)	(12) 4 0 3 1	• .
		.Silicate of alumina	2.6
Lead	. Pb		11.37
Limonite	.2Fe ₂ O ₃ 3H ₂ O	. Brown oxide of iron	3.6 - 4.0
Magnesite	MgCo.	.Carbonate of magnesia	3.0 - 3.12
		. Magnetic oxide of iron	
wagneru	. FCO, FC2O3	. Magnetic oxide of fron	9.10- 9.19
Manaemite	. Qu ₂ (OH) ₂ QO ₃	.Green carbonate of copper	3.9 - 4.0
Mangauere	. Mu	. Hydrated manganese oxide	7.39
Manganite	. M92O3H2O	. Hydrated manganese oxide	4.2 - 4.4
Monazite			48 - 51
Maranata	Wast.	.White iron pyrite	1.95 1.00
Marianice	. FG 12	. winte non pyrite	4.00- 4.00
Mercury	. <u>11g</u>	. Nickel sulphide.	13.0
Millen(e	. N18	. Nickel sulpliide	5.3 - 5.6
Mimetite	.3PBoAsoOuPhClo.	Lead arsenate	7.0 - 7.25
Muscovite	H.KAL(SiO.)	.Potash mica	2.76- 3.0
Numbtha			0.60 0.756
Minorlifo	NI V.	. Nickel arsenide	7 99 7 67
NICCORC	· NIAS	. Niekei arsenide	7.00- 7.07
Nickel	.N1		8.9
Opal	.SiO₂nH₂O		1.9 - 2.3
Ornment.	. AsaSa	Yellow sulphide of arsenic	34 - 35
Orthoclase	KAISi ₂ O ₂	. Po(ash feldspar	2.46-2.6
Ozoonito		Mineral wax	0.85- 0.00
Platinum	.Pt		14.019.0
Proustite	. Ag ₃ AsS ₃	. Light red silver ore	5.57 - 5.64
Pyrargyrite	. AgaSbSa	.Dark red silver ore	5.77 - 5.86
Pyrite	1868.	. Iron sulphide	4 95 5 10
Previousito	Mu()	. Dioxide of manganese	4.82
D	19111172	. Dioxide of manganese	0 7 7 1
Lyromorphice	.3PD ₃ P ₂ O ₈ PDCl ₂	Lead phosphate	0.5 - 7.1
Pyrrho(i(e	. Fe ₁₁ S ₁₂	. Magnetic pyrite	4.58- 4.64
Quartz	$.\mathrm{SiO}_2$. Red sulphide of arsenie	2.65-2.66
Realgar	.AsS	. Red sulphide of arsenie	3.55
Rhodochrosite	MuCo.	Carbonate of manganese	3.45- 3.6
Phodonito	MASIC)	Silicate of manganese	3.40- 3.68
D.All.	- 191 (B/31X / 3	15th and the second state of the second seco	0.40- 0.00
Ruthe	$\cdot 11Q_3 \dots \dots$. Dioxide of titanium	4.2
Serpentine	. 114Mg ₃ S1 ₂ O ₂	.Silicate of magnesia	2.50- 2.65
Siderite	. FeCO₃	.Carbonute of iron	3.8 - 3.9
Silver	. Ag		10.1 -11.1
Smaltite	CoAs _e	. Arsenide of cobalt	6.4 - 6.6
Smithuanita	ZuCo.	.Carbonate of zine	130- 145
C-l-1	#	Saladada of alleanness and an annual salada of alleanness and an another alleanness another alleanness and an another alleanness and an another allean	2.00- 4.10
Sphaierite	· Zhō	.Sulphide of zinc	0.9 - 4.
Spinel	$\operatorname{AMgAl}_{2}O_{4}$. Aluminate of magnesia	3.5 - 4.1
Stephanite	$.\Lambda gsSbS_4$.Brit(le silver	6.2 - 6.3
Stibnite	$.8b_2S_3$.Sulphide of antimony	4.5 - 4.6
Sulphur	8	. Telluride of gold and silver	2.08
Sulvanita	(An AgiTo	Tollyride of gold and silver	79 - 83
Ti-1	If NI QLO	Siliente of magnesia	0.7 0.0
Taic	. [121V1K3014C/12	.Silience of magnesia	4.1 - 4.0
Tephroite	.Mn ₂ SiO ₄	.Silicate of manganese	4.0 - 4.1
Tetrahedrite	.4Cu ₂ S, Sb ₂ S ₃	.Gray eopper	4.4 - 5.1
Tin	.Su		7.29
Tonaz		. Fluo-silicate of alumina	3.4 - 3.6
Tourmaling		.Silicate of alumina, iron and magnesia	2.98- 3.20
Willowite	7. SiO	Silicate of zinc	30 - 419
windmite	(B) M-NVO	The many of Zince and a constraint of	70 75
wonramite	. (re, mn) WO4	.Tungstate of iron and manganese Molybdate of lead	$\frac{1.2}{0.5} - \frac{1.5}{0.5}$
Wulfeni(c	.PbMoO4	. Molybdate of lead	0.7 - 7.0
Zine	. Zn		7.15
Zincite	ZnO	. Zine oxide	5.43- 5.7
Zireon	ZrSiO.	Silicate of zerconium	4.70

HEAT OF COMBUSTION

Compiled by N. F. WILSON, JR.

Lefax

Heat of Combustion of Various Materials

	it of Compustion of	Various .	Material	S
			roduced	
Material	Burned To	Calories	B.T.U.	Authority
		per gm.		, reduction of
Alcohol, Ethyl	CO2+112O liquid	7,183	12,931	Favre & Silberman
Alcohol, Ethyl	C()2+H2() liquid	6,850	12,530	Andrews
Alcohol, Methyl	•	5,322	9,579	Anonymous
Alcohol, Amyl	CO2+H2O liquid	8,933	16,079	Anonymous
Antimony	SbO.	961	1,730	Dulong
Asphalt		9,532	17,159	Slossen & Colburn
Benzol, C ₆ H ₆ Gas	CO ₂ +H ₂ O liquid	10,070	18,126	Berthelot
Benzol, C ₆ H ₆ Gas	CO_2+H_2O liquid	9,650	17,370	Anonymous
Benzol, C ₆ H _c Liquid	CO2+H2O liquid	10,030	18,054	Stohman
Cane Sugar	1	3,964	7,130	Bertbelot
Carbon, Bisulphide	CO ₂	3,401	6,122	Favre & Silberman
Carbon, Crystallized	CO	2,405	4,329	Berthelot
Carbon, Crystallized	CO ₂	7,859	14,146	Bertbelot
Carbon, Amorphous	CO	2,489	4,480	Berthelot
Carbon, Amorphous	(X() ₂	8,137	14,647	Berthelot
Carbon, Amorphous	CO2	8,080	14,544	Berthelot
Carbon, Vapor	CO ₂	11,328	20,390	Berthelot
Carbon, Vapor Diamond	CO ₂	11,134	20,041	Berthelot
Carbonic, Oxide CO	CO2	5,640	10,152	Thomsen
Celinlose	CO2+H2O liquid	4,208	7,574	Berthelot
Charcoal	+ CO	2,173	4,451	Favre & Silberman
Charcoal	Co	2,112	4,396	Berthelot
Charcoal	ČO ₂	8,080	14,544	Favre & Silberman
Charconl	CO ₂	8,137	14,647	Berthelot
Charcoal, Beech	CO2	7,140	12,852	Schwackhöfer
Charcoal, Soft	CO ₂	7,071	12,723	Schwackhöfer
Charcoal, Sugar	CO ₂	8,040	11,472	Favre & Silbernun
Coal, Anthracite	COL	7,800	11,010	Various
Coal, Bituminous		8,500	15,300	Average of Various
Coal, Coke	1	7,000	12,600	
Coal, Lignite		6,900	12,420	Average of Various Average of Various
Cyanogen	CuO	5,195	9,351	Dulong
Coke, Gas	CO ₂	8.047	14,485	Favre & Silberman
Coke, Petroleum	CO ₂	8,017	14,430	
Copper	CuO	590	1,062	Mohler Thomsen
Dynamite, 75%	Cito	1,290	2,322	
Gas, Acetylene C ₂ H ₂	CO2+H2O liquid	12,142	21,855	Roux & Sarran Berthelot
Gas, Acetylene C ₂ H ₂	CO2+112O liquid	11,527	20,749	Thomsen
Gas, Coal	CO3+1120 inquire	4,440	7,990	
Gas, Coal		7,370	12,266	Anonymous
Gas, Ethylene C ₂ II ₄	CO2+H2O liquid	11,858		Anonymous
Gas, Ethylene C ₂ 11 ₄	CO ₂ +H ₂ O liquid	12,072	21,344 21,730	Favre & Silberman
Gas, Ethylene C ₂ H ₄	CO ₂ +11 ₂ O inquiti CO ₂ +11 ₂ O gas	11,293		Berthelot
Gas, Methane CH.	CO2+112O gas CO2+112O liquid		20,327	Berthelot
Gas, Methane CH ₄	CO2+1120 liquid	13,063	23,513	Favre & Silberman
Gas, Methane C114	CO ₂ +H ₂ O gas	13,344	24,019	Berilielot
Gas, Petroleum	002 T1120 gas	12,066	21,719	Berthelot
Gas, Producer		10,800	19,440	Anonymous
Gas, Producer		773	1,391	Anonymous
ten, i rounci	<u> </u>	1,370	2,466	Anonymous

Heat of Combustion of Various Materials

		Heat P	roduced		
Material	Burned To	Calories B.T.U. per gm. per lb.			
Gas, Naphthalene	CO2+H2O liquid	9,793	17,637	Anonymous	
Gas, Naphthalene	CO2+H2O liquid	9,690	17,442	Berthelot	
Gas. Naphthalene	CO2+H2O kas	9,354	16,837	Berthelot	
Gas, Water Gas, Water		2,350	4,230	Anonymous	
Gas, Water	1	3,032	5,458	Anonymous	
Glycerin	CO2+H2O liquid	4,316	7,769	Stohman	
Graphite	CO2	7,901	14,222	Berthelot	
Gunpowder	_	750	1,350	Various	
Hydrogen	II₂O liquid	34,462	62,032	Favre & Silberman	
Hydrogen	H ₂ O liquid	34,180	61,524	Thomsen	
Hydrogen	H ₂ O liquid	34,500	62,100	Berthelot	
Hydrogen	H ₂ () gas	28,800	51,840	Thomsen	
Hydrogen'	H ₂ O gas	29,150	52,470	Berthelot	
Iron	Fe ₃ O ₄	1,702	3,064	Dulong	
lron	Fe ₂ O ₂	1,582	2,848	Anonymous	
Magnesium	MgO	6,077	10,939	Anonymous	
Nickel	NiO	1,006	1,811	Dulong	
Oil, Cotton Seed		9,500	17,100	Anonymous	
Oil, Castor	1	8,848	15,926	Anonymous	
Oil, Coal, Heavy	1	8,900	16,020	St. C. Devillo	
Oil, Olive	1	9,862	17,751	Dulong	
Oil, Linseed	1	9,430	16,974	Anonymous	
Oil, Rape		9,489	17,080	Stohman	
Oil, Schist		9,000	1,620	Anonymous	
Oil, Sperm		10,000	18,000	Gibson	
Paraffin	CO2+H2O liquid	11,140	20,050	Stohman	
Paraffin	CO2+H2O gas	10,340	18,612	Stohman	
Peat	001, 1110 gam	5,940	10,692	Bainbridge	
Petroleum, Crude	!	11,094	19,969	Mohler	
Petroleum, Refined	İ	11,045	19,881	Mohler	
Phosphorus	PO _s	4,509	8,116	Andrews	
Phosphorus	POs	4,394	7,909	Abria	
Pitch	1.00	8,400	15,120	Anonymous	
Bilicon	SiO ₂	7,407	13,333	Berthelot	
Stearic Acid	CO2+H2O liquid	9,374	16,873	Stohman	
Starch	CO2+H2O liquid	4,228	7,610	Berthelot	
Sulphur, Rhombic	801	2,221	3,998	Favre & Silberman	
Sulphur, Rhombie	802	2,166	3,899	Berthelot	
Sulphur, Monoclinic	SO ₂	2,241	4,034	Thomsen	
Tallow		9,500	17,100	Stohman	
r in	SnO ₂	1,233	2,219	Dulong	
Γin	SnO ₂	1,144	2,059	Andrews	
Purpentine		10,852	19,533	Favre & Silberman	
Wood, Beech, 12.9% H ₂ O		4,168	7,502	Gottlieb	
Wood, Birch, 11.8% H ₂ O		4,207	7,572	Gottlieb	
Wood, Oak, 13.3% H-O		3,990	7,182	Gottlieb	
Wood, Oak, 13.3% H.O Wood, Pine, 12.2% H.O		4,422	7,960	Gottlieb	
Zine	ZnO	1,301	2,342	Andrews	
Zinc	ZnŎ	1,298,	2,336	Dulong	

The Calculation of the Heat of Combustion of Mixed Fuels

The heating value of a mixed fuel is calculated from its constituents as found from ultimate analysis and any one of several formulas may be used for the determination. Dulong's formula is probably the most used and is given below along with Mahler's which has the same basic form. Practically every formula used is similar to the two given below.

B.T.U. per lb. of Fuel =
$$14650 C + 62100 (H - \frac{1}{8}O)$$
 Dulong
B.T.U. per lb. of Fuel = $14650 C + 62100 H - 5400 (O + N)$ Mahler

where C = Parts Carbon in Fuel O = Parts Oxygen in Fuel H = Parts Hydrogen in FuelN = Parts Nitrogen in Fuel

Example: It is desired to find how many British Thermal Units will be developed by a pound of eoal the ultimate analysis of which is:

Carbon = .7216 Oxygen = .0785 Hydrogen = .0496 Nitrogen = .0166

B.T.U. =
$$(14650 \times .7216) + 62100 \left(.0496 - \frac{.0785}{8}\right) = 13,043.02$$
 Dulong

B.T.U. =
$$(14650 \times .7216) + (62100 \times .0496) - 5400(.0785 + .0166) = 13,138.06$$
 Mahler

The calorific value of the above coal as determined by tests of U. S. Geological Survey was 12,958 B.T.U.

Heats of Fusion of Chemical Elements and Inorganic Compounds

Physikalisch-Chemische Tabellen, 1912

Landolt-Boernstein

	Melting	Heat of			
Substance	Point	in Kg. Calories		Authority and Date	
Nunbance	Deg. C.	1-kilogram	1-gram- atom	Transcript and 15000	
Bismuth	266.8	12.64 12.4	2.63 2.58	Person, 1849 Mazzotto, 1891	
Bromine	-7.32	16.18	1.293	Regnault, 1849	
Cadmiun	320.7	13.7	1.54	Person, 1848	
Chlorine	-103.5	22.96	0.814	Estreicher & Staniewski 1910	
Copper	10	43.0	2.74	J. W. Richards, 1903	
Gallium	13	19.1	1.33	Berthelot, 1878	
Iron, cast—white	1	32-34 23		Gruner, 1874	
Iron, cast—gray	325	5.86	1.21	Gruner, 1874	
Lead	326.2	5.37	1.11	Rudberg, 1830 Person, 1849	
44	320.2	5.37	1.11	Mazzotto, 1891	
"	322.4	5.32	1.11	Spring, 1886	
"	322.4	6.45	1.34	Robertson, 1903	
		2.84	0.57	Person, 1848	
Mercury	-38.7	2.75	0.55	Pollitzer, 1911	
46	38.7	2.75	0.57	Koref, 1911	
Palladium	1500	36.3	3.86	Violle, 1878	
Phosphorus	27.35	4.74	0.147	Pettersson, 1881	
rnosphorus	29.73	4.74	0.147	Pettersson, 1881	
"	40.05	4.97	0.154	Pettersson, 1881	
"	44.2	5.034	0.156	Person, 1848	
Platinum	1779	27.2	5.3	Violle, 1877	
Potassium	58	15.7	0.61	Joannis, 1887	
1 Outsoldin	00	13.61	0.532	Bernini, 1906	
Silver	999	21.1	2.28	Person, 1848	
Sodium	96.5	31.7	0.73	Joannis, 1887	
"	1	17.75	0.408	Bernini, 1906	
Sulphur	115	9.37	0.300	Person, 1848	
" mono.	119	10.4	0.33	Wiegand, 1908	
Thallium	290	7.2	1.47	Robertson, 1903	
Tin, ordinary, white	228	13.3	1.6	Rudberg, 1830	
111, ordinary, 11110	232.7	14.25	1.70	Person, 1849	
16 16 11	227.3	14.65	1.74	Spring, 1886	
u u u		13.06	1.62	Mazzotto, 1891	
tt tt tt		14.05	1.67	Robertson, 1903	
Zine	415.3	28.1*	1.84	Person, 1849	
- 66		28.0	1.8	Mazzotto, 1891	

^{*} Not entirely reliable.

Inorganic Compounds

0.1	Melting Point Deg. C.		Fusion Calories		
Substance		1-kilo- gram	1-grain- inol.	Authority and Date	
Aluminum bromide, AlBr ₃ Ammonia, NH ₃ Antimony tribromide, SbBr ₃ Antimony tribromide, SbCl ₃ Arsenie tribromide, AsBr ₃ Barium chloride, BaCl ₂ Caesium hydroxide, CsOH Caleium ehloride, CaCl ₂ Caleium elloride, CaCl ₂ Caleium elloride, CaCl ₂ Caleium of CaCl ₂ Caleium of CaCl ₃ Caleium of CaCl ₃ Caleium of CaCl ₄ Caleium of CaCl ₅ CaCl ₅ Caleium of CaCl ₅ Caleium of CaCl ₅ Caleium of CaCl ₅ Caleium of CaCl ₅ Caleium of CaCl ₅ Caleium of CaCl ₅ Caleium of CaCl ₅ Caleium of CaCl ₅ CaC	-75 94.6 73.2 31.0 958.9 272.3 773.9 28.5 42.4 -56.29	10.47 108.1 9.76 13.29 8.93 27.8 10.7 54.6 40.7 33.49 43.8	2.79 1.84 3.51 3.01 2.81 5.8 1.61 6.06 8.9 7.94 1.93	Kablukow, 1908 Massol, 1902 Tolloczko, 1901 Tolloczko, 1901 Tolloczko, 1901 Plato, 1907 v. Hevesy, 1910 Plato, 1907 Person, 1849 Pickering, 1891 Knepen & Robson, 1902	
Hydrogen peroxide, II ₂ O ₂	30.20	2.70	9.18	de Forcrand, 1900	

Notes. For aluminum and iodine the only value available is the heat necessary to bring 1 kg. of the substance from 0° C. to the molten condition. It is, for aluminum, 239.4 kg. calories per kg. and for iodine 11.7 kg. calories per kg. The value given by Smith is 334.21 ± 0.08 joules. He assumes the mean calorie to equal 4.1832 joules.

Heat, Fusion, Chemical Elements, Inorganic Compounds

	Heat of	Fusion		
Substance	1-kilo- gram	1-grain- mol.	Authority and Date	
lce	75.99	1.369	Pettersson, 1881	
41	76.03	1.375	Pettersson, 1881	
et .	75.94	1.368	Pettersson, 1881	
46	76.60	1.380	Pettersson, 1881	
44	77.71	1.400	Pettersson, 1881	
"	78.26	1.411	Zakrzewski, 1892	
tt.	79.25	1.428	Person, 1848	
ii .	79.06	1.424	Regnault, 1844	
u	79.25	1.428	Regnault, 1844	
tt.	80.025	1.442	Bunsen, 1870	
"	79.24	1.428	Desains, 1843	
" (See Note 2)	79.896±	1.440	A. W. Smith, 1903	
(800 1100 2)	0.02		•	
46	79.61	1.435	Bogojawlenski, 1905	
44	79.2	1.427	Ledue, 1906	
sf	79.67	1.436	W. A. Roth, 1908	

Heat, Fusion, Chemical Elements, Inorganic Compounds (Continued)

lital, Publon, Chemical			Composito (Communica)
	Heat of Fusion		
Substance	1-kilo-	1-gram-	Authority and Date
Dinagance		inol.	nathority and Date
	grain	11101.	
Iodine chloride, ICl	14.15	2.30	Berthelot, 1880
" " ICl a	16.42	2.66	Stortenbeker, 1892
" " iČi ā	14.0	2.27	Stortenbeker, 1892
Lead bromide, PbBr ₁	12.34	4.53	Ehrhardt, 1885
" " "	9.9	3.65	Goodwin & Kalmus, 1909
Lead chloride, PbCl ₁	20.90	5.81	Ehrhardt, 1885
" " "	18.5	5.15	Goodwin &Kalmus, 1909
Lend iodide, PbI ₁	11.50	5.30	Ehrhardt, 1885
Lithium nitrate, LiNO ₁	88.5	0.10	Goodwin & Kalmus, 1909
	9.79	4.44	
Mercuric iodide, Hgl ₁	9.54	0.601	Guinchant, 1907
Nitric acid, HNO ₄	76.67	8.28	Berthelot, 1877
Nitrie oxide, N ₂ O ₅ " N ₂ O ₄	32.2-37.2		Berthelot, 1874
Phosphoric acid, hypo. H ₄ P ₂ O ₆	51.23	8.30	Joly, 1886
01 010: 1131 04	25.71	2.521	Thomsen, 1905
Phosphorous acid, hypo. H ₃ PO ₄	35.00	2.31	Thomsen, 1905
OI UIIO, ALIA OI	37.44	3.072	Thomsen, 1905
Potassium chloride, KCl	86.0	6.41	Plato, 1906
dichromate, K ₂ Cr ₂ O ₇	29.8	8.77	Goodwin & Kalmus, 1909
fluoride, KF	108.0	6.27	Plato, 1907
hydroxide, KOH	28.6	1.61	v. Hevesy, 1910
nitrate, KNO ₃	47.37	4.79	Person, 1848
nitrate, KNO ₁	25.5	2.57	Goodwin & Kalmus, 1909
Rubidium hydroxide, RbOH	15.8	1.62	v. Hevesy, 1910
Silver bromide, AgBr	12.6	2.37	Goodwin & Kalmus, 1909
chloride, AgCl	21.3	3.05	Goodwin & Kalmus, 1909
chloride, AgCl	30.7	4.40	Robertson, 1903
nitrate, AgNO ₁	17.6	2.99	Guinehant, 1907
nitrate, AgNO ₁	15.2	2.58	Goodwin & Kalmus, 1909
Sodium chlorate, NaClO ₂	49.6	5.25	Goodwin & Kalmus, 1909
chlorate, NaClO ₁	48.4	5.15	Foote & Levy, 1907
chloride, NaCl	123.5	7.22	Plato, 1906
chromate, Na ₂ CrO ₄ -10H ₂ O	36.0	12.3	Berthelot, 1878
chromate, Na ₂ CrO ₄ -10H ₂ O	39.2	13.4	Berthelot, 1878
fluoride, NaF	186.1	7.82	Plato, 1907
hydroxide, NaOH	40.0	1.60	v. Hevesy, 1910
nitrate, NaNO.	62.97	5.355	Person, 1848
nitrate. NaNO	45.3	3.69	Goodwin & Kalmus, 1909
phosphate, Na ₂ HPO ₄ . 12H ₂ O	66.8	23.9	Person, 1849
sulphate, Na ₂ SO ₄ , 10H ₂ O	51.2	16.5	Cohen, 1894
thiosulphate, Na ₂ S ₂ O ₃ . 5H ₂ O	37.6	9.3	v. Trentinaglia, 1876
Strontium chloride, SrCl ₂	25.6	4.06	Plato, 1906
Sulphuric acid, H ₂ SO ₄	8.77	0.860	Berthelot, 1874
H ₂ SO ₄	24.031	2.358	Pickering, 1891
H ₂ SO ₄	22.82	2.239	Knietsch, 1909
H ₂ SO ₄	25.98	2.559	Broneted, 1910
H ₂ SO ₄ . H ₂ O	31.72	3.68	Berthelot, 1874
H ₂ SO ₄ . H ₂ O	38.97	4.52	Luginin & Dupont, 1911
H ₂ SO ₄ . H ₁ O	39.92	4.63	Pickering, 1891
H ₂ SO ₄ . H ₂ O	34.91	4.05	' Hammerl
H.SO4. H.O	36.08	4.18	Hammerl
H.SO. H.O	38.38	4.45	Bronsted, 1910
Thallium bromide, TlBr	12.7	3.61	Goodwin & Kalmus, 1909
chloride, TICl	16.6	3.98	Goodwin & Kalmus, 1909

Brief Summary of Some Important Chemical Laws and Hypotheses

§ 19. 1. Avogadro's Hypothesis. Equal volumes of all gases at the same pressure and temperature contain an equal number of molecules.

2. Boyle's (or Mariotte's) Law. The volume of all gases at a constant

temperature is inversely proportional to the pressure.

- 3. Common Ion Effect—Repression of Ionization. Ionization is repressed by adding to the solution a salt which has a common ion with that of the solute.
- 4. Complex Ions. These consist of a group of elements, possessing characteristics distinct from the elements of which they are composed. Example K_4 Fe(CN)₆ ionized = K_4 and $Fe(CN)_6$. KClO₃ ionized = K and ClO_3
- 5. Conservation of Mass, Law of. The total weight of matter resulting from a combination or decomposition is always equal to the sum of the weights of the substances taking part in the reaction. In all chemical transformations mass remains constant.
- 6. Constant Proportion, Law of. The elements combine with one another in absolutely fixed relative proportions by weight.
- 7. Dalton's Atomic Theory. All matter consists of an aggregate of minute particles, or atoms, which are chemically indivisible.
- 8. Dalton-Henry's Law. The pressure exerted by a mixture of gases occupying a given volume is equal to the sum of the separate pressures which the different gases would exert if they alone occupied the given volume. Every gas behaves with respect to its own particular properties just as if it alone was present.
- 9. Dulong-Petit's Law. All elements in the solid state have the same atomic heat. That is, elements taken in proportion to their atomic weights require equal quantities of heat in order to be raised to the same temperature.
- 10. Electrolytic Dissociation Theory of Arrhenius. All substances which form solutions capable of conducting an electric current, the electrolytes, exist in solution, in part at least, as dissociated ions, atoms or atomic groups, carrying a definite charge of electricity. Each positive ion (anion) involves the presence of a negative ion (cation) carrying an equivalent amount of electricity.

When two oppositely charged poles are placed in such a solution, the positively charged anode attracts the negative particles in the solution and repels the positive, while the negatively charged enthode attracts the positively charged particles and repels those negatively charged, a flow of electricity thus being produced.

11. Electromotive or Potential Series. Metals placed in solution tend to pass from a free element to the ionic condition, the more positive elements will displace the less positive from their ionic condition. See list of elements given in order of activity, in the table in the latter part of this volume.

12. Faraday's Law. In equal periods of time a current of definite strength separates the ions from the solutions of electrolytes in quantities by weight, which stand in the same ratio to one another as their equivalent weights, i.e., their atomic weight divided by their valence.

The strength of an electric current can be measured by determining the weight of silver or copper deposited at the cathode in a given time from a solution of silver or copper, or by measuring the volume of hydrogen or oxygen produced from water by the action of the current.

- 13. Gay-Lussac's Law (Charle's Law). At constant pressure, volumes of all gases increase on warming in the same proportion for every one degree. The coefficient of expansion is 1/273 (0.003665). That is to say, for 1° C. increase in temperature the gas expands 1/273 of its volume. A volume of 273 ec. of gas at 0° C. would become 274 ec. at 1° C.
- 14. Hesse's Law Thermo Law of Conservation. The evolution of heat which accompanies a chemical process is always the same whether the process takes place in one step or whether it passes through a number of intermediate processes.
- 15. Lavoisier-Leplace's Law. Every compound has a certain heat of formation which is equal to its heat of decomposition.
- 16. Mass Action, Law of (Guldberg-Waage's Law). The speed of reaction between two substances in solution is directly proportional, at any moment, to the molar concentrations of these reacting substances in solution, and to a constant, which is characteristic of the chemical nature of the reacting components, and of the temperature.
- 17. Multiple Proportion, Law of. If two elements combine in more than one proportion, the masses of the one which combine with a given mass of the other bear a simple rational relation to one another, i.e., are always a whole multiple of the lowest.

Example: N2O, N2O2, N2O3, N2O4, N2O5: the five oxides of nitrogen.

- 18. Neuman-Kopp's Law. Molecular heat corresponds to the sum of atomic heats of the elements which constitute the molecule.
- 19. Osmotic Pressure. A substance in solution produces the osmotic pressure, at a given temperature, which it would exert, if it were contained as a gas, at the same temperature, in the volume occupied by the pure solvent of the solution.
- 20. Periodic Law of Mendeleeff. The properties of the elements are periodic functions of their atomic weights.
- 21. Reversible Reaction. Compounds in solution resulting from a chemical reaction in turn react forming the original compounds present. This reversibility is prevented by removal from solution of one of the resulting compounds, by formation of an insoluble compound, which precipitates from solution, or by the formation of a gas which escapes. (See "Common Ion Effect.")
 - 22. Law of Electrostatic Force. Coulomb's Law.

$$F = \frac{1q_1q_2}{Cd_2}.$$

F = force acting between two charged bodies.

 q_1 and q_2 = quantities of electricity.

C = specific inductive capacity or dielectric constant of the medium.

23. Law of Jule.

$$h = rc^2$$

h = amount of heat evolved in a given time.

r = resistance to the passage of the current.

c =strength of the current.

24. Ohm's Law.

$$C = \frac{E}{R}$$

C =strength of current.

E = electromotive force.

R = resistance.

PREPARATION OF REAGENTS

This chapter includes a list of reagents generally used in the analytical laboratory. Certain special reagents having a limited use are given in the body of the text under the subject with which they are concerned. The alphabetical arrangement will be found convenient for reference. The term per cent is used for convenience and does not represent true percent but rather the grams of reagent per 100 cc. of solution. For example, a ten per cent solution of sodium chloride means 10 grams of NaCl dissolved in water and made to 100 cc. A ten per cent of alcohol solution refers to volume and means 10 cc. of alcohol diluted with water to 100 cc.

COMMON LABORATORY DESK OR SHELF REAGENTS

Reagent Name	Per	Vol.	Vol.	Res.	Approx.	Gm.
	Cent	R.	H ₂ ()	sp.gr.	N.	per cc.
Acetic a. glacial Acetic a. dil. Hydrochloric a. cone. Hydrochloric a. dil. Nitric a. cone. Nitric a. comer. Nitric a. dil. Sulphuric a. dil. Ammonium hyd. cone. Ammonium hyd. dil. Sodium hyd. dil.	96 70 23 95 14 28 9 40	1 1 1	1.5 2 2 6 2	1.06 1.07 1.04 1.20 1.08 1.50 1.42 1.14 1.84 1.09 0.90 0.96 1.44 1.07	17 N 15 N 5 N 13 N 5 N 23 N 16 N 5 N 36 N 5 N 15 N 15 N	1.06 g 0.84 g 0.28 g 0.48 g 0.19 g 1.43 g 1.00 g 0.31 g 1.77 g 0.25 g 0.08 g 0.58 g 0.20 g

R=strong reagent. Res.=resulting. N=Normal. Gm. per cc.=grams of 10% reagent.

Reagents Used for Precipitations and Volumetric Determinations

Volumetric reagents should be standardized at 20° C. if possible. The temperature at which the standardization is made should be noted on the container as the strength of the reagent per cc. will vary with a change of temperature, the concentration increasing with contraction at a lower temperature, and expansion causing decrease with a rise in temperature. It is not advisable to attempt to make the reagent exactly a normal equivalent as the strength may change slightly from this factor. It is necessary to establish the exact factor of the solution, however, by careful standardization. The "factor" is the ratio between a given number of cc. of the solution in question and the number of cc. of a theoretically correct solution. For example, if 50 ec. of the reagent were found to be equivalent to 55 ec. of a theoretically normal solution, the normality factor of the reagent in question would be 55+50=1.1 N and all titrations would have to be multiplied by this factor to obtain the cc. in terms of a normal solution.

Normalities are expressed either by a figure before N or after it, thus

0.2 N or N/5=fifth normal. 0.1 N or N/10=tenth normal. 0.5 N or N/2 = half normal. .02 N or N/50=fiftieth normal, etc.

Acetic Acid, Glacial. C.P., 99.5% pure. The determination of its strength should be made by titration and not by specific gravity, as the 98% and 80% acid have the same specific gravity, 1.067. The determination of the meltingpoint gives results equally good with those obtained by titration and requires less time. It is made after the manner of the "titer test" for acids, the tube being half filled, chilled to 10° to 11° C., and further chilled by placing the outside bottle in ice-water; the temperature of the super-cooled acid rises to its melting-point, where it remains stationary for some time. The melting-points of acids of various strengths are as follows:

100%, 16.75° C.; 99.5%, 15.65°; 99%, 14.8°.

Alcohol. Commercial "Cologne Spirits." For the preparation of alcohol free from aldehyde for alcoholic potash, cologne spirits are treated with silver oxide as follows: 1½ grams of silver nitrate are dissolved in 3 cc. of water, added to 1 liter of alcohol and thoroughly shaken; 3 grams of potassium hydrate are dissolved in 15 ec. of warm alcohol and, after cooling, added to the alcoholic silver nitrate and thoroughly shaken again, best in a tall bottle or cylinder. The silver oxide is allowed to settle, the clear liquid siphoned off and distilled, a few bits of pumice, prepared by igniting and immediately quenching under water, being added to prevent bumping. Alcohol for use in the free acid determination is prepared by placing 10 to 15 grams of dry sodium carbonate in the reagent bottle, taking care to filter it before use.

Alcohol, Amyl. C.P.

Alcohol Potash Solution. See Potassium Hydroxide.

Alizarin S Test. The reagent used is a 0.1% filtered solution of commercial alizarin S, the sodium salt of alizarin monosulphonic acid (yellow with acids, purple with alkalies).

Alkaline Tartrate Solution. See Tartrate Solution.

Ammonium Acetate. 70% solution. Use the salt or cautiously add 1000 cc. of ammonium hydroxide to 1200 cc. of glacial acetic acid.

Ammonium Carbonate. 250 grams of the salt per liter. Add 100 cc. of strong ammonium hydroxide. The solution contains approximately 22% of (NH₄)₂CO₃.NH₄CO₂NH₂.

Ammonium Chloride. 10% solution, 100 grams of NH₄Cl per liter.

Ammonium Chloride Solution Standard. Dissolve 3.82 grams of ammonium chloride in 1 liter of distilled water. Dilute 10 cc. of this to 1 liter with ammonia-free water. 1 cc.=0.00001 gram of nitrogen. Used in water analysis. •

Ammonium Molybdate Reagent Standard. 4.75 grams of the salt are dissolved in water and made up to 1 liter. One cc. with a half-gram sample is equal approximately to 1% of Pb. Standard in lead determination.

Ammonium Molybdate. One hundred grams of pure molybdic acid are thoroughly mixed with 400 cc. of cold distilled water and 80 cc. of strong ammonia (sp.gr. 0.90) added. When the solution is complete, it is poured slowly and with constant stirring into a mixture of 400 cc. of strong nitric acid (sp.gr. 1.42) and 600 cc. of distilled water. This order of procedure should be followed, as the nitric acid poured into the ammonium molybdate solution will cause the precipitation of a difficultly soluble oxide of molybdenum and necessitate filtration. Fifty milligrams (.05 gram) of microcosmic salt,

dissolved in a little water, are added to clarify the reagent, the precipitate agitated, then allowed to settle for twenty-four hours and the clear solution decanted through a filter into a large reagent bottle. Sixty ce. of the reagent should be used for every 0.1 gram of P₂O₃ present in the solution analyzed.

Ammonium Nitrate. 20% solution. 200 grams of NH₄NO₂ per liter. Ammonium Oxalate. 4% solution. 40 grams of (NH₄)₂C₂O₄.2H₂O per

Ammonium Phosphate. 10% solution. 100 grams of (NH₄)₂HPO₄ per liter. Sodium ammonium phosphate Microcosmic salt may be used in place of ammonium phosphate.

Ammonium Sulphate. 25% solution. 250 grams of (NH₄)₂SO₄ per liter. Ammonium Sulphide (Colorless). Saturate 750 cc. of strong ammonia with hydrogen sulphide gas and add 500 cc. of strong ammonia and 1000 cc. of water.

Ammonium Polysulphide (Yellow). To a solution of annonium sulphide made according to the directions above add about 75 grams of flowers of sulphur. Shake well.

Ammonium Thiocyanate ("sulphocyanate"). See Thiocyanate.

Arsenic Standard Solution. One gram of resublimed arsenous acid, As₂O₃, is dissolved in 25 cc. of 20% sodium hydroxide solution (arsenie free) and neutralized with dilute sulpharie acid. This is diluted with fresh distilled water, to which 10 cc. of 95% H₂SO₄ has been added, to a volume of 1000 cc. Ten cc. of this solution is again diluted to a liter with distilled water containing acid. Finally 100 cc. of the latter solution is diluted to a liter with distilled water containing acid. One cc. of the final solution contains 0.001 milligram of As₂O₃. Used in arsenic determinations by Gutzeit and Marsh methods.

Arsenite. Tenth Normal Arsenious Acid. As₂O₂ is equivalent to 2I₂, i.e., to 4H, hence ½ the gram molecular weight of arsenious oxide per liter will give a normal solution: 198÷4=49.5.

4.95 grams of pure arsenious oxide is dissolved in a little 20% sodium hydroxide solution and the excess of the alkali is neutralized with dilute sulphuric acid, using phenolphthalein indicator, the solution being just decolorized. Five hundred cc. of distilled water containing about 25 grams of sodium bicarbonate are added. If a pink color develops, this is destroyed with a few drops of weak sulphuric acid. The solution is now made to volume, 1000 cc. The reagent is standardized against a measured amount of pure iodine. The oxide may be dissolved directly in sodium bicarbonate solution. For iodine titrations. A standard reducing agent.

Note. Commercial arsenious oxide is purified by dissolving in hot hydrochloric acid, filtering the hot saturated solution, cooling, decanting off the mother liquor, washing the deposited oxide with water, drying and finally subliming.

Standard Antimony Solution. A stock solution is made up by weighing out 0.553 gm. of KSbOC₄H₄O₆ which is dissolved in distilled water and made up to 2000 cc. which represents 1 cc. = .0001 gm. of Sb.

From the above stock solution take 100 cc. and make up to 1000 cc.; this solution now equals - 1 cc. = .00001 gm. of Sb, which is used for making the standard stains and introducing into checks. For standard antimony stains.

Barium Chloride. A 10% solution. 100 grams of BaCl_{2.2}H₂O per liter.

Barium Chloride, anhydrous, 5% solution; or crystals, 6% solution. Reagent used for sulphur determinations.

Barium Hydroxide. 5% solution. 50 grams of Ba(OH)₂.8H₂O per liter.

Alpha Benzildioxime. This may be prepared by boiling 10 grams of benzil (not necessarily pure) with 8 to 10 grams of hydroxylamine hydrochloride in methyl alcohol solution. After boiling for three hours the precipitate is filtered off and dried, washed with hot water and then with a small amount of 50% alcohol, and dried. This dried precipitate consists of pure benzildioxime (m.p. 237° C.). A further yield may be obtained by boiling the filtrate with hydroxylamine hydrochloride. The reagent is prepared by dissolving 0.2 gram of the salt per liter of alcohol to which is added ammonium hydroxide to make 5% solution, sp.gr. 0.96 (50 cc. per liter). Reagent used in the determination of nickel.

• Benzidine Hydrochloride is prepared by taking 6.7 grams of the free base, or the corresponding amount of the hydrochloride, and mixing into a paste with 20 ec. of water in a mortar. Twenty ce. of hydrochloric acid (sp.gr. 1.12) are added and the mixture diluted to exactly 1000 cc. One cc. of this solution corresponds to 0.00357 gram of H₂SO₄. The solution has a brown color. Brown flakes are likely to separate out on standing, but these do no harm.

Reagent used in the determination of sulphur.

Bromine. The commercial article; also a N/3 solution, made by dissolving 26.6 grams of bromine in 1 liter of carbon tetrachloride.

Bromine—Potassium Bromide Solution. 320 grams of potassium bromide are dissolved in just sufficient water to eause solution and mixed with 200 cc. of bromine, the bromine being poured into the saturated bromide solution. After mixing well the solution is diluted to 2000 cc. Used for sulphur determinations.

Bromine—Carbon Tetrachloride Solution. Carbon tetrachloride saturated with bromine. Used for sulphur determination.

Bismuth Standard Solution. One gram of metallic bismuth is dissolved in the least amount of dilute nitric acid (1:1) that is necessary to keep it in solution and diluted to 1000 cc. in a graduated flask. One hundred cc. of this solution is diluted to 1000 ee. One cc. of this diluted solution contains 0.0001 gram of bismuth.

Calcium Chloride. 10% solution. 100 grams of CaCl₂.6H₂O per liter.

Acid Calcium Chloride Solution. Saturate with calcium chloride a mixture of 90 parts of water and 10 parts of concentrated hydrochloric acid (specific gravity 1.2).

Calcium Hydroxide (Lime Water). A saturated water solution of Ca(OII)₂. Keep tightly stoppered. Decant or filter before use.

Cinchonine Solution. Cinchonine solution is made by dissolving 100 grams of the alkaloid in dilute HCl (1 part acid to 3 of water) and diluting to 1000 cc. with HCl of the same strength.

Clnchonine Wash Solution. 30 cc. of Cinchonine solution, 30 cc. of strong HCl diluted to 1000 cc. Used in tungsten determinations.

Cinchonine Potassium Iodide Solution. Ten grams of cinchonine are dissolved by treating with the least amount of nitric acid that is necessary to form a viscous mass and taking up with about 100 ce. of water. The acid is added a drop at a time, as an excess must be avoided. Twenty grams of potassium iodide are dissolved separately and cinchonine solution added.

The resulting mixture is diluted with water to 1000 ee. After allowing the reagent to stand forty-eight hours, any precipitate formed is filtered off and the clear product is ready for use. The reagent preserved in a glass-stoppered bottle keeps indefinitely. It should be filtered free of suspended matter before use.

Copper Sulphate—Alkaline Tartrate Solution. See Fehling's solution.

Citric Acid. One part of acid of 3 parts in water. One hundred ee. of nitric acid should be added to each liter to prevent mould growth.

Citrate of Ammonia. 25 grams of the salt per 50 ec. of water.

Copper Solution Standard. One gram of purest electrolytic copper is dissolved in 20 ee. of dilute nitric acid, sp.gr. 1.2, and the solution diluted to 1000 ee. For standardizing the thiosulphate to be used with high-grade copper ores, crude copper, blister copper, etc., a copper solution containing ten times the above amount of metallic copper is prepared. Standard in the iodide determination of copper.

Caustic. Standard solution. See Sodium Hydroxide.

Cuprous Chloride, Acid, for Gas Analysis. The directions given in the various text-books being troublesome to execute, the following method, which is simpler, has been found to give equally good results: Cover the bottom of a two-liter bottle with a layer of copper oxide or "scale" \(\frac{3}{3} \) in. deep, place in the bottle a number of pieces of rather stout copper wire reaching from top to bottom, sufficient to make a bundle an inch in diameter, and fill the bottle with common hydrochloric acid of 1.10 sp.gr. The bottle is occasionally shaken, and when the solution is colorless, or nearly so, it is poured into the half-liter reagent bottles, containing copper wire, ready for use. The space left in the stock bottle should be immediately filled with hydrochloric acid (1.10 sp.gr.).

By thus adding acid or copper wire and copper oxide when either is ex-

hausted, a constant supply of this reagent may be kept on hand.

The absorption capacity of the reagent per cc. is, according to Winkler, 15 ec. of CO; according to Hempel 4 cc.

Care should be taken that the copper wire does not become entirely dissolved and that it extend from the top to the bottom of the bottle; furthermore the stopper should be kept thoroughly greased the more effectually to keep

out the air, which turns the solution brown and weakens it.

Cuprous Chloride, Ammoniaeal, for Gas Analysis. The acid cuprous chloride is treated with ammonia until a faint odor of ammonia is perceptible; copper wire should be kept in it similarly to the acid solution. This alkalino solution has the advantage that it can be used when traces of hydrochloric acid vapors might be harmful to the subsequent determinations, as, for example, in the determination of hydrogen by absorption with palladium. It has the further advantage of not soiling mercury as does the acid reagent.

Absorption Capacity, 1 ee. absorbs 1 et. of CO.

Cuprous chloride is at best a poor reagent for the absorption of earbonic oxide; to obtain the greatest accuracy where the reagent has been much used, the gas should be passed into a fresh pipette for final absorption, and the operation continued until two consecutive readings agree exactly. The compound formed by the absorption—possibly Cu₂COCl₂—is very unstable, as earhonic oxide may be freed from the solution by boiling or placing it in vacuo; even if it be shaken up with air, the gas is given off, as shown by the

increase in volume and subsequent diminution when shaken with fresh cuprous chloride.

Devarda's Alloy. Forty-five parts of aluminum, 50 parts of copper and 5 parts of zinc. The aluminum is heated in a Hessian crucible in a furnace until the aluminum begins to melt, copper is now added in small portions until liquefied and zinc now plunged into the molten mass. The mix is heated for a few moments, covered and then stirred with an iron rod, allowed to cool slowly with the cover on and the crystallized mass pulverized.

Dimethylglyoxime. 1% solution. 1 gram of the salt per 100 cc. of

ethyl alcohol. Used in nickel determinations.

Diphenyl Carbazide Reagent. One-tenth of a gram of the compound is dissolved in 10 cc. of glacial acetic acid and diluted to 100 cc. with ethyl alcohol.

Diphenyl carbazide may be made by heating a mixture of 15 grams of urea with 50 grams of phenyl hydrazine four hours, finishing at 155° C. The solid product is crystallized three times with alcohol. A light straw-colored product is obtained. A white product is obtained if the urea is cut down to 5 grams, the yield, however, is only 25 per cent of that obtained by the first method and the compound possesses no advantages. Used in chromium determinations.

Fehling's Solution for Determination of Sugar. (a) Copper sulphate solution. 34.639 g. of crystallized copper sulphate are dissolved in water and made up to 500 cc. (b) Alkaline tartrate solution. Dissolve 173 g. of Rochelle salts and 125 g. of potassium hydroxide in water and dilute to 500 cc.

Ferric Chloride. 10% solution. 100 grams of FeCl₂.6H₂O per liter.

Ferric Chloride Solution Standard. (10 grams of iron dissolved in 200 cc. of HCl, oxidized with HNO₂ and made to one liter.) 1 cc. = 0.01 g. of Fe.

Ferric Indicator. Saturated solution of ferric ammonium alum. Should this not be available, $FeSO_4$ may be oxidized with nitric acid, and the solution evaporated with an excess of H_2SO_4 to expel the nitrous fumes. A 10% solution is desired. Five ec. of either of these reagents are taken for each titration. Used in titrating silver by Volhard's method.

Standard Iron Solution. A ferric solution, the iron content of which has been determined, is diluted and divided so as to obtain 0.0004 gram of Fe. This is made up to 2 liters with water containing 200 cc. of iron-free, C.P. $\rm H_2SO_4$. One hundred cc. of this solution, together with 10 cc. of normal ammonium sulphocyanate solution, is used as a standard. One hundred cc. contains 0.00002 gram of Fe.

Normal sulphocyanate contains 76.1 grams of NH₄CNS per liter. Used in standardization of the reagent for the determination of iron.

Standard Iron Solution. 8.6322 grams of ferric ammonia alum is dissolved in dilute hydrochloric acid and made up to one liter. The iron is determined in 100 cc. portions by the dichromate method. One cc. will contain about 0.001 gram of Fe.

Ferric Nitrate. One part of salt in 6 parts of water. It is well to add a little nitric acid to prevent hydrolysis.

Ferrous Sulphate Standard. Reagent for Nitric Acid Determinations. A. Reagent to be Used in Titration of Nitric Acid in Sulphurio Acid, Oleum, etc. 176.5 grams of FeSO₄.7H₂O are dissolved in about 400 ec. of water, and 500 ec. of about 60% H₂SO₄ (1 vol. of 66° Bé. acid per 1 vol. of H₂O) are added with constant stirring, and the solution (cooled if necessary) made up to 1000 ec. 1 ec. will be equivalent to 0.02 ± gram of HNO₃, the exact value being determined by standardization.

B. Reagent for Titration of Nitric in Phosphoric or Arsenie Acid. Ferrous sulphate to be used should be made up as follows: 264.7 grams of FeSO₄.7H₂O is dissolved in 500 cc. of water, 50 cc. of 66° Bé. H₂SO₄ (93.2%) added and the solution made up to 1000 cc. 1 cc. will be equal to approximately 0.02 gram of HNO₃. The exact strength is ascertained by titrating a known amount of nitric acid in phosphoric or arsenic acid upon warming to 40° or 50° C.

Ferrous Ammonium Sulphate. 0.1 N solution contains 39.214 grams per liter. Dissolve 39.5 grams in water and dilute to 1000 cc. Clear with a few drops of sulphurie acid. Standardize against potassium permanganate. Pipette out exactly 50 cc. of the ferrous solution, add 5 cc. strong sulphuric acid and titrate to a pink color with 0.1 N potassium permanganate. The cc. permanganate required multiplied by the factor of normality of the permanganate solution divided by 50 will give the normality of the ferrous solution. The reagent keeps well if stoppered, but soon loses strength if the bottle is opened frequently.

Hydrochloric Acid, Arsenic-free. The commercial acid is treated with potassium chlorate to oxidize the arsenic to its higher form and the acid distilled. The distilling apparatus may be arranged so that constant distillation takes place, acid from a large container dropping slowly into a retort containing potassium chlorate, fresh hydrochloric acid being supplied as

rapidly as the acid distills. See Fig. 5, page 48.

Hydrochloric Acid. Desk reagent. See beginning of chapter.

Tenth-normal Hydrochloric Acid. This may be standardized by any of the accepted methods, or as follows: Twenty cubic centimeters of the approximately N/10 acid is measured out with a pipette, and the silver chloride precipitated by an excess of silver nitrate solution in a volume of 50 to 60 ec. After digesting at 70 to 80° C., until the supernatant liquid is clear, the chloride is filtered off on a tared Gooch filter and washed with water containing 2 ec. of nitric acid per 100 ec. of water until freed from silver nitrate. After drying to constant weight at 130° C., the increase of weight over the original tare is noted and from this weight, corresponding to the silver chloride, the strength of the hydrochloric acid is calculated, after which it is adjusted to the strength prescribed. The standardization should be based upon several concordant determinations using varying amounts of acid.

Hydrogen Peroxide. Thirty per cent solution. If this is not available,

sodium peroxide dissolved in dilute sulphuric acid will do.

Hydrogen Sulphide. See page 732.

Indicators. See pages 744-745.

Iodine Solution. Standard 0.1 N. Dissolve 20-25 grams of potassium iodide in as little water as possible. To this add 12.7 grams of resublimed iodine (theoretical amount 12.692 grams), and when dissolved make up to a liter, preferably in a dark colored bottle as the light affects the solution.

Standardization. For general use standardize the iodine against 0.1 N

56

sodium thiosulphate, or 0.1 N arsenous acid solution, taking 50 cc. of the reagent, carefully measured from a burette or pipette, adding a solution of starch and then the iodine solution until a blue color is obtained. Establish the factor for the iodine in terms of a true 0.1 solution. Note the temperature of the solution and make record on the bottle.

For tin plate analysis standardize the iodine solution against standard tin




Fig. 74. Hydrogen Sulphide Gas Generating Apparatus

The apparatus is assembled with A empty at any convenient height greater than the desired gas pressure, above E and C. The minimum pressure of gas, in inches of water, desired at F is then decided upon. Six inches is satisfactory for most work. Water is added at E and air is allowed to escape through F until water just reaches the iron sulphide in C. F is then closed and E is filled with water. F is carefully opened and water is allowed to flow from E to C until the difference between the levels in the two bottles equals the desired minimum lead in inches of water. F is then closed; A is filled with dilute acid and the mercury layer in B is adjusted until the pressure of the acid column is just sufficient to overcome the back pressure of the mercury column in B and the air pressure in C. This is best accomplished by adding slightly more mercury than necessary and then carefully raising E until the dilute acid begins to drop on the sulphide. A short rubber tubing insert at E facilitates this operation. After the mercury layer is correctly adjusted, E is opened and the apparatus is ready to function. No further adjustments are necessary and operation is entirely automatic. To obtain hydrogen sulphide open cock E.

ģ

solution. It is convenient to adjust the iodine solution so that 1 cc. equals exactly .00579 gram of tin. Then, if a sample of the plate having a total surface of 8 sq. in. is taken, 1 cc. of the iodine solution is the equivalent of one-tenth of a pound per base box. Use starch as indicator.

Lead Acetate. 10% solution. 100 grams of Pb(C₂H₂O₁)₂.3H₂O per liter.

If cloudy, clear with a few cc. of acctic acid.

Standard Lead Solution. A convenient solution may be made by dissolving 0.1831 gram of lead acetate, $Pb(C_2H_3O_2)_2.3H_2O$, in 100 cc. of water, clearing any cloudiness with a few drops of acetic acid and diluting to 1000 cc. If 10 cc. of this solution are diluted to 1000 cc., each cc. will contain an equivalent of 0.000001 gram Pb.

Harcourt suggests a permanent standard made by mixing ferric, copper and cobalt salts. For example, 12 grams of FeCl₂ together with 8 grams of CuCl₂ and 4 grams of Co(NO₂)₂ are dissolved in water, 400 cc. of hydrochloric acid added and the solution diluted to 4000 cc. 150 cc. of this solution together with 115 cc. of hydrochloric acid (1:2) diluted to 2000 cc. will give a shade comparable to that produced by the standard lead solution above, when treated with the sulphide reagent. The exact value per cc. may be obtained by comparison with the lead standard.

Lead Acetate Test Paper for Removal of H_2S . Large sheets of qualitative filter paper are soaked in a dilute solution of lead acetate and dried. The paper is cut into strips 7+5 cm.

Lead Acetate Cotton. Preparation of. A roll of absorbent cotton is opened and saturated with a 10% solution of lead acetate and surplus drained off, then hung on a line to dry in a warm place away from the influence of hydrogen sulphide. Do not dry in an oven. When dry, place in a stoppered bottle until used.

Magnesium Ammonium Chloride. Magnesia Mixture. For precipitation of ammonium magnesium phosphate, 110 grams of magnesium chloride (MgCl₂.6H₂O) are dissolved in a small amount of water. To this are added 280 grams of ammonium chloride and 700 cc. of ammonium (sp.gr. 0.90); the solution is now diluted to 2000 cc. with distilled water. The solution is allowed to stand several hours and then filtered into a large bottle with glass stopper. Ten ec. of the solution should be used for every 0.1 gram P_2O_5 present in the sample analyzed. As the reagent becomes old it will be necessary to filter off the silica that it gradually accumulates from the reagent bottle.

Magnesia Wash Solution. For washing magnesium ammonium phosphate precipitate. 100 grams of NH₄NO₃ are dissolved in water, 335 cc. of strong NH₄OH added and the solution diluted to 1000 cc.

Manganous Sulphate Solution. 48 grams of manganous sulphate are dissolved in 100 ee. of distilled water.

Mercuric Chloride. Saturated solution of HgCl₂ (60 to 100 grams per liter).

Mercuric Chloride. 5% solution. 50 g. of HgCl₂ per liter.

Sensitized Mercuric Chloride (or Bromide Paper). 20×20 in. Swedish Filter Paper No. 0 is cut into four equal squares. For use in the large Gutzeit apparatus the paper is dipped into a 3.25% solution of mercuric chloride (mercuric bromide may be used in place of the chloride) or if it is to be used in the small Gutzeit apparatus, it is dipped into a 0.35% mercuric chloride

solution. (The weaker the solution, the longer and less intense will be the stain.) The paper should be of uniform thickness, otherwise there will he an irregularity in length of stain for the same amounts of arsenie. See chapter on Arsenie.

Methyl Red Solution. 0.25 gram of methyl red is dissolved in 2000 cc. of 95% alcohol; 2 cc. of the indicator are used for each titration. As the indicator is sensitive to CO₂, all water used must first be boiled to expel earbonic acid.

Nessler's Solution. Dissolve 50 grains of potassium iodide in the smallest possible quantity of cold water. Add a saturated solution of mercuric chloride until a faint show of excess is indicated. Add 400 cc. of 50% solution of potassium hydrate. After same has elarified by sedimentation, make up to 1 liter with water, allow to settle and decant. For determining NH₂ in water.

Nitric Acid. Desk reagents. See beginning of the chapter.

Nitric Acid. Tenth Normal Solution. The acid is standardized against the caustic solution and should be of such strength that 1 cc. of HNO₃ is equal to 1 cc. of NaOH. Phenolphthalein indicator is used. Approximately 6.7 cc. of 95% HNO₃ diluted to 1000 cc. = N/10 HNO₃ solution.

Nitric Acid Standard—Ferrous Sulphate Method for Nitrates. Standardization of the Acid. 11.6 grams of standard potassium nitrate, equivalent to about 9.6 grams of NaNO₃, are dissolved and made to volume in the weighing bottle (100 cc.), and 10 cc. are placed in the Devarda flask, reduced and the ammonia distilled into 100 cc. of the acid. The temperature of the acid is noted and its value in terms of H₂SO₄, KNO₃ and NaNO₃ stated on the container. The acid expands or contracts 0.029 cc. for every degree centigrade above or below the temperature of standardization.

Oxalic Acid. 0.1 N solution. 6.303 grams of H₂C₂O₄.SH₂O per liter.

Standardization. Titrate 50 cc., measured by a burette, of the solution with 0.1 N NaOH in presence of phenolphthalein indicator. Multiply cc. of caustic used by its factor (titration in presence of phenolphthalein) and divide by 50 to get the factor for the oxalic acid.

Titrate the oxalic acid, hot, with 0.1 N KMnO₄ to a faint pink color. Convert cc. of KMnO₄ to exact normality and divide by 50 to obtain the factor for the oxalic acid.

Palladous Chloride. Five grams of palladium wire are dissolved in mixture of 30 cc. of hydrochloric and 2 cc. of nitric acid, this evaporated just to dryness on a water bath, redissolved in 5 cc. of hydrochloric acid and 25 cc. of water, and warmed until solution is complete. It is diluted to 750 cc. and contains about 1% of palladous chloride. It will absorb about two-thirds of its volume of hydrogen.

Paraffin. Dissolve in carbon tetrachloride and use solution for reagent labels.

Peroxide Solution. Dissolve 4 grams of sodium peroxide in 125 cc. of dilute sulphurie acid (1 of acid to 3 of water) and dilute to 500 ec. Used in titanium colorimetric determinations.

Standard Potassium Dichromate. 'The reaction of potassium diehromate with iron may be represented as follows:

 $K_2Cr_2O_7 + 6FeCl_2 + 14HCl = 6FeCl_2 + 2CrCl_3 + 2KCl + 7H_2O$.

When oxygen reacts with ferrous salts, the following reaction takes place:

 $6FeCl_2+6HCl+3O=6FeCl_3+3H_2O$.

Comparing this reaction with that of dichromate, it is evident that a normal solution of dichromate contains one-sixth of the molecular weight of $K_2Cr_2O_7$ per liter, namely, 49.033 grams. For general use it is convenient to have two strengths of this solution, N/5 for ores high in iron and N/10 for products containing smaller amounts. See Introduction, § 25.

Standardization. For N/5 solution 9.807 grams of the recrystallized dehydrated salt are dissolved and made up to one liter; N/10 potassium dichromate contains 4.9033 grams of the pure salt per liter. It is advisable to allow the solution to stand a few hours before standardization. The Sibley iron ore furnished by the U. S. Bureau of Standards, Washington, D. C., is recommended as the ultimate standard. For accurate work it is desirable to use a chamber burette with graduations from 75 to 90 cc. in tenths and from 90 to 100 in twentieths of a ce. A titration of 90 to 100 ce. of the diehromate would require 0.9 to 1.1 grams of iron for a fifth normal solution and half this amount for a tenth normal solution of dichromate. If the ore contains 69 per cent. of iron, 1.4 grams should be taken for a N/5 solution. The ore is best dissolved in strong HCl, adding a few drops of stannous chloride solution and heating just below boiling. In case of an ore or iron ore briquette, containing silica in an appreciable amount, a earbonate fusion of the residue may be necessary. Reduction and titration of the ore is done exactly as prescribed in chapter on Iron.

The equivalent iron in the ore divided by the cc. titration required for complete oxidation gives the value in terms of grams per cc., e.g., 1.4 grams of ore containing 69.2% of Fe required a titration of 95 cc. of K₂Cr₂O₇ solution, then

1 cc. =
$$\frac{(69.2 \times 1.4)}{100} \div 95 = 0.0102$$
 gram of Fe.

Optional Methods for Standardization of Potassium Dichromate

It is not always possible to use the method of standardization with a standard ore, and chamber burettes may not be available. The following methods are reliable.

First. Optional Method. Standardization against Pure Iron. About 0.25 grain of pure iron wire are dissolved in an Erlenmeyer flask with Bunsen valve. Before adding the iron 20 cc. of the dilute sulphuric acid (5 N desk reagent) are added and about 2 grams of sodium bieurbonate. This displaces the air with CO₂. The wire is dropped in and the rubber stopper carrying the valve inserted. When the reaction has ceased and the iron is in complete solution, the dichromate solution is added until the ferrous iron is just oxidized to ferrie state, the end-point being recognized by an outside indicator (1% solution of potassium ferrieyanide being placed in drops on a white tile with depressions). Ferrous iron produces a blue color, ferrie iron only a yellowish color with the indicator.

Second. Optional Method. 50 ee. of the potassium dichromate solution are pipetted or measured out by a burette into a 300-ec. glass-stoppered bottle. 150 ce. of water are added and 5 ec. of cone. sulphurie acid. After ecoling under a tap, 10 ec. of 25% potassium iodide are added, the liberated iodine is

now titrated with 0.1 N thiosu pnate solution, using starch indicator. The potassium dichromate factor is obtained by multiplying the cc. of thiosulphate by its normality factor and dividing by 50. See Introduction, pages 11, 14.

Potassium Dichromate. Four per cent solution. 40 grams of K2Cr2O7

per liter.

Potassium Chromate. Ten per cent solution of neutral potassium chromate.

Potassium Ferricyanide, $K_3Fe(CN)_6$. The salt should be free of ferro-eyanide, as this produces a blue color with ferric salts, which would destroy the end-point. It is advisable to wash off the salt before using. A crystal the size of a pinhead dissolved in 50 cc. of water is sufficient for a series of determinations. The solution should be made up fresh for each set of determinations.

Potassium Ferrocyanide, Standard Solution for Zine Determination. 21.55 grams of the crystallized salt per liter. (1 cc. of 0.5 gram sample is equal to about 1%.)

Standardization. Low's Method. Weigh carefully 0.2 gram of pure zinc, place in an 8-oz. flask and add 10 cc. of conc. hydrochloric acid (sp.gr. 1.2). When the zinc has dissolved, dilute with 25 cc. of water, add a few drops of itmus solution, and make slightly alkaline with ammonia. Again acidify with hydrochloric acid, adding 3 cc. in excess. Dilute to about 250 cc. with hot water, heat to nearly boiling and titrate with the ferrocyanide solution, using a 15% uranium nitrate solution as an outside indicator, making the tests as in case of the dichromate titration of iron. A brown tinge obtained by adding a drop of the titrated solution to a drop of the uranium nitrate on a white tile is the end-point desired. It is advisable to divide the solution titrated, adding the reserve in portions until the entire amount has been titrated. This avoids overrunning the end-point.

Potassium Ferrocyanide for Zinc Determinations. 43.1 grams of pure sait in 1000 cc. of water. One ce. = approximately 0.010 Zn. This solution should be allowed to stand about four weeks before using.

Standardization. New Jersey Zine Co. Method. Weigh into tall 400-cc. beakers several portions of C.P. zinc, using about 0.35 gram. Cover with water and dissolve in 10 cc. of hydrochloric acid (sp.gr. 1.2). Now add 13 cc. of ammonia (sp.gr. 0.9), make acid with hydrochloric acid, and add 3 cc. excess. Add 0.03 or 0.04 milligram of ferrous iron in the form of a ferrous sulphate solution and dilute to about 200 cc. with distilled water. Heat to beiling and titrate as follows: About one-quarter of the solution is reserved in a small beaker and the ferrocyanide added to the main solution with vigorous stirring. The solution takes on a blue color, which changes to a creamy white when an excess of ferrecyanide is added. Now add a few cc. more and pour in the reserved portion of zinc solution, excepting about 5 or 10 cc. Add ferrocyanide until the end-point is reached and add about \(\frac{1}{2} \) cc. more. The last of the reserved zinc solution is then poured into the main beaker, washing out the small beaker with a portion of the main solution, and the ferrocyanide added drop by drop until the blue color fades sharply to a peagreen with one drop of ferrocyanide. This is the end-point. Repeat until satisfactory standards are obtained.

Potassium fluoride solution; made by dissolving 100 grams of potassium fluoride in about 1200 cc. of hot, CO₂-free water, then neutralizing the solution

with hydrofluoric acid or potassium hydroxide as the reagent may require, using 5 cc. of phenolphthalein as indicator. Dilute sulphuric acid may be used in place of hydrofluoric acid in the final acid adjustment to get a neutral product. One cc. of the solution in 10 cc. of CO₂-free water should appear a faint pink. The concentrated mix is filtered if necessary and then diluted to 2000 cc. with CO₂-free water. The gravity will now be approximately 1.32 or about 35° Bé. One cc. contains 0.5 g. of potassium fluoride.

Potassium Hydroxide. (a) For carbon dioxide determination, 500 grams of the commercial hydrate are dissolved in 1 liter of water.

Absorption Capacity. One ee. absorbs 40 ee. of CO2.

(b) For the preparation of potassium pyrogallate for special work, 120 grams of the commercial hydrate are dissolved in 100 cc. of water.

Potassium Iodide Solution. Dissolve 250 grams of potassium iodide free from iodate in distilled water and dilute to 1000 ec.

Potassium Nitrate Standard. The purest nitrate that can be obtained is recrystallized in small crystals, by stirring, during the cooling of the supersaturated concentrated solution, and dried first at 100° C. for several hours and then at 210° C. to constant weight. Chlorides, sulphates, carbonates, lime, magnesium and sodium are tested for and if present are determined and allowance made.

Used as a standard in the Devarda method for nitrate determination.

Potassium Permanganate. For oxidation purposes. Two per cent solution filtered free of dioxide through asbestos is required.

Potassium. Permanganate, Standard Solutions. As in ease of potassium diehromate, it is convenient to have two standard solutions, N/5 and N/10. (0.2 N and 0.1 N.)

Since commercial potassium permanganate is seldom pure, it is necessary to determine its exact value by standardization. This is commonly accomplished by any of the following methods:

(a) By a standard electrolytic iron solution.

 $2KMnO_4+10Fe+9H_2SO_4=2MnSO_4+K_2SO_4+5Fe_2(SO_4)_3+8H_2O+H_2$.

- (b) By ferrous salt solution, e.g., (NH₄)₂SO₄. FeSO₄. 6H₂O.
- (c) By oxalie acid or an oxalate.

Reaction. 2KMnO₄+5Na₂C₂O₄+8H₂SO₄

 $= K_2SO_4 + 2MnSO_4 + 5Na_2SO_4 + 10CO_2 + 8H_2O_4$

From the reactions above it is evident that $2KMnO_4$ will oxidize 10Fe or $5Na_2C_2O_4$. $2KMnO_4=K_2O+2MnO+5O$, hence a normal solution would contain one-fifth of the molecular weight of $KMnO_4=31.6$ grams of the pure salt. Hence a N/5 solution would contain 6.32 grams per liter and a N/10 solution 3.16 grams.

It is advisable to dissolve the potassium permanganate in about 500 ee. of hot water and filter the solution through asbestos to remove any dioxide of manganese that may be present, as MnO₂ aids in the decomposition of KMnO₄ solution. The reagent should be kept tightly sealed in a dark bottle well protected from the light. This solution should stand two or three days before standardization. The solution is diluted to 1000 ee. for a 0.2 N solution or to 2000 ee. for a 0.1 N solution, if 6.32 grams have been taken.

Standardization. (a) Iron Wire in Sulphate Solution. Standard iron wire, as furnished by chemical supply houses, with the percentage of iron given

(usually about 99.8% of Fe), gives results, when properly treated, which are practically identical with those obtained by the use of sodium oxalate.

Samples of 0.2000 gm. are weighed out and the weights multiplied by the factor for iron, giving the true weight of iron. 50 ec. of 20% sulphurie acid are placed in a 250-cc. Erlenmeyer flask, which is fitted with a rubber stopper earrying a Bunsen valve. Into the acid is dropped from one to two grams of sodium bicarhonate in order that the air may be replaced by carbon dioxide and then the sample of wire is introduced and the flask stoppered by the Bunsen valve. The whole is then boiled gently until the iron is completely dissolved, and the boiling continued for a minute or two more. The solution is now cooled, and, after dilution to 150 cc., titrated to the first permanent pink.

$$\frac{\text{Net weight of iron}}{\text{cc. used}} = \text{iron standard.}$$

The atmosphere of CO₂ and the Bunsen valve are employed so that oxygen may be kept out of contact with the hot solution. Under these conditions the iron goes into solution completely as FeSO₄. The boiling after complete solution is necessary in order that all traces of hydroearbons from the earbon present in the iron may be expelled. Hydroearbons reduce permanganate.

The complete reaction is:

$$2KM_{11}O_4 + 10FeSO_4 + 8II_2SO_4 \rightarrow 5Fe_2(SO_4)_3 + K_2SO_4 + 2M_1SO_4 + 8H_2O_5$$

(b) Standardization of KMnO₄ against sodium oxalate is recommended as the most accurate procedure. The salt has no water of erystallization and is not hygroscopic. It can be obtained from the Bureau of Standards with a guarantee of purity. Traces of moisture can be expelled by heating the salt to 120° C. for two hours, then cooling in a desiccator.

The chemistry of the process is as follows:

$$\begin{split} 2KMnO_4 &\rightarrow K_2O + 2MnO + 5O, \\ Na_2C_2O_4 + H_2SO_4 &\rightarrow H_2C_2O_4 + Na_2SO_4, \\ H_2C_2O_4 + O &\rightarrow H_2O + 2CO_2, \\ and so \ 5O + 5H_2C_2O_4 &\rightarrow 5H_2O + 10CO_2. \end{split}$$

From these expressions it is seen that

 $2KMnO_4 \approx 5O \approx 5H_2C_2O_4 \approx 5Na_2C_2O_4$, and the complete reaction is $2KMnO_4 + 5Na_2C_2O_4 + 8H_2SO_4 \rightarrow K_2SO_4 + 2MnSO_4 + 8H_2O + 10CO_2$. Since $2KMnO_4 \approx 10$ Fe, from the reaction $2FeO + O \rightarrow Fe_2O_3$.

$$2Na_2C_2O_4 \Rightarrow 10Fe$$
.

Weigh 0.2 to 0.3 gram of pure sodium oxalate, place in a beaker and add 200 ee. of water and about 5 cc. strong sulphurie acid. Heat to boiling and titrate with the potassium permanganate solution. The reaction starts slowly, but with the progress of the titration the action becomes vigorous. Towards the end of the reaction the pink color fades less rapidly and finally a permanent pink color is obtained with one drop of the reagent.

Calculation of Normality. Since 67 grams of sodium oxulate per 1000 cc. of solution is a normal solution, the cc. equivalent of the amount taken is obtained by dividing by 0.067. This value divided by the titration of the oxalate with the reagent being standardized will give the normality of the reagent.

Example. Suppose 0.268 gram of sodium oxalate required a titration of 50 cc. of the permanganate solution. Since 67 g. is equivalent to 1000 cc. N solution of sodium oxalate, then 0.268 is equivalent to

 0.268×1000 divided by 67 = 4 cc. N sol. 4 divided by 50 = 0.08 N.

Potassium Permanganate.¹ Preparation of N/100 Solution. Dissolve 0.40 g. of pure potassium permanganate crystals in one liter of redistilled water in a thoroughly clean Florence flask which has been rinsed with the same water. Digest at or near the boiling point for 36 hours. A funnel covered with a watch-glass may be used as a reflux condenser. Cool and allow to stand over night. Without disturbing the sediment of imanganese oxides, filter with gentle suction through a 3-in. Büchner funnel lined with ignited asbestos. Both funnel and filter flask should be rinsed with redistilled water. Transfer the permanganate solution to a glass-stoppered bottle free from traces of organic matter. The solution should be kept in the dark when not in use. If the asbestos becomes clogged with oxides, these may be dissolved out with bot concentrated hydrochloric acid, followed by washing with redistilled water without disturbance of the pad.

After standing two or three days, this permanganate solution may be conveniently standardized against N/50 oxalic acid (0.1261 g. of pure crystals to 100 cc.) or sodium oxalate of similar strength. To 10 cc. of the oxalic acid solution add 10 cc. of 10 per cent sulphurie acid which has been treated with just sufficient permanganate solution to give it a faint pink color. Place in a water-bath at 65° C. for a few minutes. Then titrate at once to a definite pink color which persists for at least a minute. Correct for the blank obtained by titrating 10 cc. of the sulphurie acid and the same volume of water to the same end-point. On account of the sensitivity of this reagent it is desirable to check it up rather frequently.

Potassium or Ammonium Thiocyanate (Sulphocyanate) 0.1 N Solution. About 8 grams of ammonium or 10 grams of potassium salt are dissolved in water and diluted to one liter. The solution is adjusted by titration against the N/10 silver nitrate solution. It is advisable to have 1 cc. of the thiocyanate equivalent to 1 cc. of the silver nitrate solution. Owing to the deliquescence of the thiocyanates the exact amount for a N/10 solution cannot be weighed.

Potassium Pyrogallate. Except for use with the Orsat or Hempel apparatus, this solution should be prepared only when wanted. The most convenient method is to weigh out 5 grams of the solid acid upon a paper, pour it into a funnel inserted in the reagent bottle, and pour upon it 100 cc. of potassium hydrate containing 120 grams KOH. The acid dissolves at once, and the solution is ready for use.

Attention is called to the fact that the use of potassium hydroxide purified by alcohol has given rise to erroneous results.

Absorption capacity. One ec. absorbs 2 ec. of O.

Salt Solution Standard. • 16.48 grams of fused C.P. sodium chloride aro dissolved in 1 liter of distilled water. 100 cc. of this solution diluted to 1 liter gives a standard solution, each cc. of which contains .001 gram of chlorine.

Schiff's Fuchsin Bisulphite Reagent. See Index.

1 Jour. of Ind. and Eng. Ch., Feb. 1918.

Silver Nitrate Standard Solution. 4.8 grams of dried silver nitrate crystals are dissolved in one liter of distilled water. Each ce. of this solution is equivalent to approximately .001 gram of chlorine, standardized against the Standard Salt Solution.

Note. N/50 solutions of both sodium chloride and silver nitrate can be used where it is inconvenient to make too many standard solutions, using the proper factors,

Silver Nitrate N/10. This solution contains 10.788 grams of Ag or 16.989 grams of Ag NO₃ per liter. The silver nitrate salt, dried at 120° C., or pure metallic silver may be taken, the required weight of the latter being dissolved in nitric acid and made to volume, or 17.1 grams of the salt dissolved in distilled water and made to 1000 cc. The solution is adjusted to exact decinormal strength by standardizing against a N/10 sodium chloride solution, containing 5.846 grams of pure NaCl per liter.

Silver, Pure, Preparation of. The volumetric methods used for the determination of high percentages of silver employ solutions which should be standardized by metal of the highest purity. For the preparation of this metal, the electrolytic method as described below is preferred by laboratories

which are suitably equipped.

By Knorr's method, a solution of silver nitrate from which excess of nitric acid has been removed by evaporation is freed of metallic impurities by adding enough sodium carbonate to precipitate one-tenth of the silver, boiling and filtering. The silver in the filtrate is precipitated by sodium carbonate and the precipitate decomposed without addition of reducing agent, by melting in a crucible. Excess sodium carbonate carried down with the precipitate of silver carbonate will cover the fusion and such as adheres tightly to the metal is readily removed by hydrochloric acid. The metal should be smelted under charcoal.

For standardizing the decimal solution, 1 gram of standard silver is dissolved in a funuel-closed liter flask by 20 cc. of equal volumes of nitric acid and water. After boiling to decompose nitrous acid the solution is made up to mark with water at room temperature.

When using the standard thiocyanate solution with the object of obtaining very accurate results, it is good practice, instead of using a standard solution of silver, to obtain the standard by titrating, simultaneously with the assays, solutions of known quantities of standard silver approximately equal in amount and dissolved in the same manner as the assays. Volhard's Method for Silver.

Sodium Bismuthate. Prepare as follows: Heat 20 parts of caustic soda nearly to redness in an iron or nickel crucible, and add, in small quantities at a time, 10 parts of basic bismuth nitrate, previously dried in a water oven. Then add 2 parts of sodium peroxide and pour the brownish-yellow fused mass on an iron plate to cool; when cold, break it up in a mortar, extract with water, and collect on an asbestos filter. The residue, after being washed four or five times by decantation, is dried in the water oven, then broken up and passed through a fine sieve.

Sodium Carbonate. 10% solution. 100 grams of Na₂CO₂ per liter. Sodium Hydroxide. Desk reagent. See the beginning of this chapter. Sodium Hydroxide. Normal solution. 1 cc. of the reagent is equivalent

Sodium Hydroxide. Normal solution. 1 cc. of the reagent is equivalent to 0.04904 g. of H₂SO₄. Use rubber stoppers for bottles with sodium compounds.

Preparation of Standard Solution. Make up a stock concentrated solution of sodium hydroxide by dissolving sodium hydroxide in water in the proportion of 200 grams of NaOH to 200 ee. of water. Allow this solution to cool and settle in a stoppered bottle for several days. Decant the clear liquid from the precipitate of sodium carbonate into another clean bottle. Add clear barium hydroxide solution until no further precipitate forms. Again allow to settle until clear. Draw off about 175 ee. and dilute to 10 liters with freshly boiled distilled water. Preserve in a stock bottle with a large guard tube filled with soda lime. Determine the exact strength by titrating against purobenzoic acid (C_0H_6COOH) or against standard sulphuric acid, using phenolphthalein as indicator. This solution will be approximately one-fourth normal, but do not attempt to adjust it to any exact value. Determine its exact strength and make proper corrections in using it. See chapter on Alkalimetry and Acidimetry.

This should be made of such strength that 1 ee. is equal to 1 ee. of the standard acid, 2 ee. of methyl red being used as indicator. Ten ee. of the acid are diluted to 500 ec. and the alkali added until the color of the indicator changes from a red to a straw color.

Sodium Hydroxide. Tenth Normal Solution. For determination of phosphorus by the alkali volumetric method, consult chapter on Phosphorus.

Sodium Hydroxide Solution, Alcoholic. Dissolve pure sodium hydroxido n 95 per cent alcohol in the proportion of about 22 grams per 1000 ce. Let stand in a stoppered bottle. Decant the clear liquid into another bottle, and keep well stoppered. This solution should be colorless or only slightly yellow when used; it will keep colorless longer if the alcohol is previously reated with NaOH (about 80 g. to 1000 ce.), kept at about 50° C. for 15 lays, and then distilled.

N/5 Sodium Oxalate. Na₂C₂O₄ reacts with KMnO₄ as follows:

 $5Na_2C_2O_4 + 2KMnO_4 + 8H_2SO_4 = K_2SO_4 + 2MnSO_4 + 5Na_2SO_4 + 10CO_2 + 8H_2O_4$

Hence $5\text{Na}_2\text{C}_2\text{O}_4$ divided by 10 or 134 divided by 2=67 grams per liter = a normal sodium oxalate solution. A N/5 solution requires 13.4 grams $\text{Na}_2\text{C}_2\text{O}_4$ per liter.

Sodium Sulphide. Ten per cent solution, made from colorless crystals. Sodium sulphide may be made by saturating a strong solution of sodium hydroxide with hydrogen sulphide gas, and then adding an equal volume of the sodium hydroxide. The solution is diluted to required volume, allowed to stand several days, and filtered.

Sodium metabisulphite. Solid salt of Na₂S₂O₅.

Sodium Thiosulphate. Used in copper determinations. 7.5 grams of the salt, Na₂S₂O₄.5H₂O, are dissolved and made to 2 liters with water. The solution is standardized against a copper solution containing 1 gram of pure copper per liter. 1 cc.=0.001 gram of Cu. Approximately the same amount of copper in the same volume of solution is taken as is to be determined by the assay. For high-grade copper ores and crude copper, etc., it is advisable to prepare a standard thiosulphate solution ten times the above strength. The copper solution is made slightly ammoniacal and then acid with acetic acid. Potassium or sodium iodide crystals, free from iodate, are added and the liberated iodine titrated with the standard thiosulphate. (See Procedure under Copper.)

Sodium Thiosulphate, Standard 0.1 N Solution for General Analysis

Sodium thiosulphate reacts with iodine as

follows:

$$I_2+2Na_2S_2O_3=2NaI+Na_2S_2O_6$$
.

I gram molecule of thiosulphate is equivalent to 1 atom of iodine=1 atom of hydrogen, hence a tenth normal solution is equal to one-tenth the molecular weight of the salt per liter, e.g., 24.822 grams of Na₂S₂O₃.5H₂O; generally a slight excess is taken—25 grams of the crystallized salt. It is advisable to make up 5 to 10 liters of the solution, taking 125 to 250 grams of sodium thiosulphate crystals and making up to volume with distilled water, boiled free of earbon dioxide. The solution is allowed to stand a week to ten days, and then standardized against pure, resublimed iodine.

Standardization. About 0.5 gram of the purified iodine is placed in a weighing bottle containing a known amount of saturated potassium iodide solution (2 to 3 grams of KI free from KIO₃ dissolved in about $\frac{1}{2}$ cc. of H₂O), the increased weight of the bottle, due to the iodine, being noted. The bottle and iodine are placed in a beaker containing about 200 cc. of 1% potassium iodide solution (1 gram KI per 200 ec.), the stopper removed with a glass fork and the iodide titrated with the thiosulphate to be standardized.

Calculation. The weight of the indine taken, divided by the cc. of thiosulphate required, gives the value of 1 ec. of the reagent; this result divided by 0.012692 gives the normality factor.

Note. The thiosulphate solution may be standardized against iodine, which has been liberated from potassium iodide in presence of hydrochloric acid by a known amount of standard potassium bi-iodate, a salt which may be obtained exceedingly pure.

$$KIO_3.IIIO_3+10KI+11IICI=11KCI+6H_2O+6I_2.$$

A tenth normal solution contains 3.2496 grams of the pure salt per liter. (One ec. of this will liberate 0.012692 gram of iodine from potassium iodide.) The purity of the salt should be established by standardizing against thiosulphate, which has been freshly tested against pure resultinged iodine.

freshly tested against pure resublined iodine.

About 5 grams of potassium iodide (free from iodate) are dissolved in the least amount of water that is necessary to effect solution, and 10 ec. of dilute hydrochloric acid (1:2) are added, and then 50 ec. of the standard bi-iodate solution. The solution is diluted to about 250 ec. and the liberated iodine titrated with the thiosulphate reagent; 50 ec. will be required if the reagents are exactly tenth normal.

Optional Methods of Standardization. The thiosulphate may be standardized against standard 0.1 N potassium dichromate (4.9033 grams of pure $K_2Cr_2O_7$ per liter of solution) as follows. Place in a beaker 100 cc. of distilled water and 10 cc. of a 25% solution of potassium iodide. Now add from a burette 50 cc. of the standard N/10 potassium dichromate and 10 cc. of conc. HCl, and titrate the liberated iodine with standard N/10 thiosulphate reagent. When the yellow color has almost disappeared, add about 2 cc. of starch solution and continue the titration until the blue changes to a sea-green. The ec. of dichromate taken divided by the cc. of thiosulphate required will give the factor in terms of tenth normal solution.

Tenth normal potassium permanganate may be used to liberate the iodine in place of the dichromate, if desired, and the thiosulphate titration made as usual.

It is best to leave the thiosulphate solution as it is after determining its exact iodine value, rather than to attempt to adjust it to exactly decinormal strength. Preserve in a stock bottle provided with a guard tube filled with soda lime.

Sodium Thiosulphate Solution. N/100 solution is made as needed from the N/10 stock solution.

Sulphuric Acid. Desk reagents. See first part of this chapter.

Sulphuric Acid. Standard. See chapter on Acidimetry and Alkalimetry. Sulphuric Acid Solution, Half Normal. Add about 15 ec. of sulphuric acid (1.84 specific gravity) to distilled water, cool and dilute to 1000 ec. Determine the exact strength by titrating against freshly standardized sodium hydroxide or by any other accurate method. Either adjust to exactly half normal strength or leave as originally made, applying appropriate correction.

Stannous Chloride Solution. The reagent is prepared by dissolving 2 grams of stannous chloride crystals in hot concentrated hydrochloric acid and making up to 1 liter. The solution should be kept in a dark bottle to which the titrating burette is attached in such a way that the liquid may be siphoned out into this, as shown in the illustration, Fig. 83. The air entering the bottle passes through phosphorous or pyrogallic acid to remove the oxygen. In this way, protected from the air, the reagent will keep nearly constant for several weeks. It is advisable, however, to restandardize the solution about every ten to fifteen days. One ce. will be equivalent to about 0.001 gram of Fe.

Stannous Chloride, Strong. Sixty grams of the crystallized salt are dissolved in 600 cc. of strong HCl and made up to one liter. The solution

should be kept well stoppered.

Starch Solution. Five grams of potato or arrowroot starch are rubbed to a paste in cold water, 200 ce. of hot water stirred in, the starch dissolved by boiling, and then poured into about two liters of hot water and boiled for a few minutes.

Preservatives. Various preservatives are used for preserving the starch solution. A few ee. of 5% NaOH solution added to the boiling solution above will preserve the starch.

Salicylic acid, 10 cc. of 1% solution per liter is a good preservative.

Chloroform, a few drops per liter of starch solution.

Zinc chloride solution, a few cc. of 10% solution per liter.

Sodium chloride and acetic acid. The starch solution is prepared by adding to 500 cc. of a saturated sodium chloride solution (filtered) 100 cc. of 80% acetic acid and 3 grams of starch, mixing cold. The solution is now brought to boiling and boiled about two minutes. The solution thus prepared keeps indefinitely.

Tartrate Solution, Alkaline. Twenty-five grams of C.P. sodium potassium tartrate, NaKC₄H₄O₆.4H₂O, is dissolved in 50 cc. of water. A little ammonia is added and then sodium sulphide solution. After settling some time the reagent is filtered. The filtrate is acidified with hydrochloric acid, boiled

free of H₂S and again made ammoniaeal and diluted to 100 cc.

Thymol Solution 1%. The thymol is dissolved in a little glacial acetic acid containing 10% of ethyl alcohol, and this solution added to concentrated sulphuric acid. Addition of the thymol directly to the acid would produce a colored solution. The reagent should be kept protected from strong light, otherwise it will become colored.

Zinc, Amalgamated. This is best prepared by dissolving 5 grams of mercury in 25 ec. of concentrated nitric acid with an equal volume of water, 250 cc. of water are added and the solution poured into 500 grams of shot zinc, 20-mesh. When thoroughly amalgamated, the solution is poured off and the zinc dried.

PREPARATION AND USES OF CHEMICAL INDICATORS

Cochineal. Yellowish red with aeids, violet with alkalies. Cannot be used in presence of iron, alumina, or acetates. Cochineal may be used for the titration of ammonia and for alkali earbonates and bicarbonates in cold solution. Carminic acid is the essential compound in this indicator and is preferable to the indicator made from cochineal.

Preparation. One part of the crushed insect is extracted with 10 parts

of 25% alcohol. The extract when filtered is ready for use.

Lacmoid. Red with acids, blue with alkalies.

Preparation. It is advisable to use the C.P. reagent. 0.2 gram of the purified lacmoid is dissolved in 100 ec. of alcohol. The commercial product may be purified by dissolving in alcohol (96%) and filtering. The filtrate is evaporated over strong sulphuric acid in an evacuated desiccator and the residue used.

The reagent is used in the titration of strong acids and bases and ammonia. It is not suited for titration of weak acids or nitrous acid.

Litmus. Red with acids, blue with alkalies.

Preparation. A solution obtained by extracting the erushed cubes with hot water may be used after allowing the insoluble matter to settle out. With such a solution the color change is not sharp. The best method of preparation is as follows: The unbroken cubes are digested for some time with several portions of warm (85%) alcohol. The alcoholic solution contains undesirable compounds and is thrown away. The residue is boiled with water, allowed to stand several days and the solution siphoned off. This blue solution is made slightly acid with actic acid, evaporated to a syrup, and then mixed with a large amount of 95% alcohol. By this means the desired coloring matter (azolitmin) is precipitated. It is filtered off, washed with hot alcohol and dissolved in sufficient hot water to give a solution 3 or 4 drops of which will impart a distinct blue color to 50 cc. of water. Tincture of litmus should be preserved in a wide-mouthed bottle loosely stoppered with a plug of cotton so as to exclude dust while permitting the access of air. Litmus gives good results with mineral acids, oxalic acid and caustic alkalies; if used in titrating carbonates, the solution must be boiled to expel CO₂ as it affects the indicator.

Methyl Orange. Pink with acids, yellow with alkalies.

Preparation. 0.2 g. is dissolved in 100 ec. of hot water. If not elear after cooling, it should be filtered. Methyl orange is not very sensitive to acids. For this reason it should not be used with organic acids. Because of its low sensitiveness to acids it may be used for the titration of earbonates in cold solution. It gives good results with ammonia.

Phenacetolin. Color with mineral acids is golden yellow. Color with

alkali earbonates and ammonia is pink.

Preparation. Dissolve 0.2 gram in 100 ce. of 50% aleohol.

Phenolphthalein. Colorless with acids, red with alkalies.

Preparation. One-tenth of a gram is dissolved in 100 cc. of 85% aleohol. Phenolphthalein is very sensitive to acids, less sensitive to alkalies. Can be used with mineral acids and with most organic acids. Carbonates give indistinct end-points unless solution is boiled to expel CO₂. Useless with ammonia.

Rosolic Acid. Yellow with acids, violet red with alkalies.

Preparation. Dissolve 0.2 grams in 100 cc. of 85% alcohol. Rosolie acid can be used with mineral acids including sulphurous acid and with oxalic acid, but not with other organic acids. In neutralizing sulphurous acid with ammonia this indicator changes when the normal sulphite is formed. It is somewhat affected by carbonic acid.

Tumeric Paper. Yellow with acids, brown with alkalies.

Preparation. Pieces of the root are first digested with several portions of water to remove undesired matter, and then with alcohol. Paper is moistened with the alcoholic solution and dried in the dark. It is used in titrating highly colored solutions where an inside indicator cannot be used, and for the detection of borates. When moistened with a solution containing free boric acid and then dried, a brown color results which is not destroyed by dilute sulphuric or hydrochloric acids and is changed by alkali hydroxide to a bluish-black color.

Preparation of Compounds

Cupferron. A liter of water, 30 grams of ammonium chloride and 60 grams of nitrobenzine are stirred by means of a mechanical stirrer to an emulsion. While stirring 80 grams of zinc dust are added in small portions, keeping the temperature of the mixture between 15° and 18° C. by addition of shaved ice. When the odor of nitrobenzine has disappeared and the precipitate of zinc hydroxide appears gray sufficient zinc dust has been added, about half an hour reduction usually being required. The cooled solution is filtered and the precipitate washed with ice water. From the filtrate and washings phenylhydroxylamine crystals are now salted out by means of NaCl added to saturation of the solution at 0° C.

The white needle-like crystals are filtered off with suction and dried between filter paper. (Caution: Solutions of phenylhydroxylamine are active skin poisons. Wash off with water and alcohol.)

The crystals are dissolved in about 500 cc. of ether, the solution filtered through a dry filter, then cooled to 0° C. and saturated with dry ammonia gas. A little more than the theoretical amount (one mole) of fresh amyl alcohol is added as quickly as possible. Heat is generated and snow white crystals of cupferron precipitate out. The mother liquor is filtered off and the crystals washed with ether and dried between filter papers. The cupferron should be kept in a closely stoppered bottle containing a small lump of ammonium carbonate.

Cupferron, C₆H₅N₂O₂NH₄ will precipitate copper, iron and titanium from strongly acid solutions. Copper salt is gray, ferrie salt red and the titanium salt is yellow. The separation of iron and titanium in acid solutions from aluminum, ehromium, manganese, cobalt, nickel, zinc and alkali earth metals makes it a valuable laboratory reagent. Zirconium will precipitate with iron and titanium if present. The reagent is not very stable in acid solution. Precipitations are made from cold solutions.

Copper precipitated with iron by means of cupferron may be dissolved out with ammonium hydroxide and reprecipitated by acidifying the filtrate, containing the copper, with acetic acid. The reagent is removed from the copper by washing with a 1% solution of sodium carbonate.

General References

- Allen, A. H., Organic Analysis, v. 1-8, 4th Ed., 1909-1913. P. Blakiston's Son & Co. Arnold and Mandel, Compendium of Chemistry. John Wiley & Sons, New York. 1904.
- Authenrieth, W., and Warren, W. H., Laboratory Manual for the Detection of Poisons. 1921. P. Blakiston's Son & Co., Philadelphia, Pa.
- Baskerville, C., and Curtman, L. J., Quantitative Analysis, 1910. The Macmillan Co. Blair, A. A., The Chemical Analysis of Iron, 7th Ed., 1918. Lippincott & Co., Philadelphia, Pa.
- Brearly, H., and Ibbotson, F., The Analysis of Steel Works Materials, 1902. Longmans, Green & Co., London and New York.
- Browning, P. E., Introduction to the Rarer Elements, 3d Ed., 1919. John Wiley & Sons, New York.
- Cahen, E. and Wootton, W. O., The Mineralogy of Rarer Metals, 1920. J. B. Lippin-cott Co.
- Carins, F. A., Quantitative Chemical Analysis, 3d Ed., 1896. H. Holt & Co., New York.
- Clowes and Coleman, Quantitative Analysis, 5th Ed. P. Blakiston's Son & Co.
- Classen, A., Quantitative Analysis. Translated by N. H. Harriman, 1902. Geo. Wahr, Pub., Ann Arbor, Mich.
- Comey, A. M., Dictionary of Chemical Solubilities. 1921. Macmillan & Co.
- Crookes, W., Sciect Methods in Chemical Analysis, 4th Ed., 1905. Longmans, Green & Co., New York, London. 1905.
- Dennis, L. M., Gas Analysis. Macmillan & Co., New York. 1913.
- Fresenius, K. M., Quantitative Chemical Analysis, 6th Ed. Translated by A. 1. Cohn, 1911. John Wiley & Sons, New York. 1912.
- 1bid., Qualitative Chemical Analysis. Trans. 17 Ed., 1921, by C. A. Mitchell. J. Wiley and Sons.
- Fulton, C. M., Fire Assaying, 2d Ed., 1911. McGraw-Hill Co., New York. 1911. Furman, H. Van F., Practical Assaying, 5th Ed., 1901. John Wiley & Sons, New
- York.

 Gardner, H. A., Paint Technology and Tests, 1911. McGraw-Hill Book Co., New York.
- Gardner, H. A., Paint Technology and Tests, 1911. McGraw-Hill Book Co., New York.
 Gardner, H. A., and Schaeffer, J. A., Analysis of Paints and Painting Materials, 1911.
 McGraw-Hill Book Co., New York.
- Griffin, Technical Methods of Analysis, 1921. McGraw-Hill.
- Gill, A. H., Gas and Fuel Analysis for Engineers, 3d Ed., 1903. J. Wiley & Sons, New York.
- Gill, A. H., A Short Hand-book of Oil Analysis, 6th Ed., 1911. J. B. Lippincott Co., 1919, Philadelphia and London.
- Gooch, F. A., Methods in Chemical Analysis, 1912. John Wilcy & Softs, New York. Hempel, W., Gas Analysis. Macmillan & Co., New York.
- Hillebrand, W. F., The Analysis of Silicate and Carbonate Rocks, Bull. 422, U. S. Geological Survey, 1910. Washington Gov. Print. Office.
- Hopkins, B. Smith, Chemistry of the Rarer Elements, D. C. Heath and Co., New York.
 Johnson, C. M., Rapid Methods for the Chemical Analysis of Special Steels, 2d Ed., 1920, 1914. John Wiley & Sons, New York.
- Julian, F. A., Text Book of Quantitative Analysis, 1902. Ramsey Publishing Co., St. Paul, Minn.
- Langbein, Electro Deposition of Metals, 1920. H. C. Baird & Co.
- 1.each, A. E., Food Inspection and Analysis, 4th Ed., 1920. John Wiley & Sons, New York.

Levy, S. I., The Rare Earths, 1915. Edward Arnold Pub.

Lewkowitsch, J., Chemical Analysis of Oils, Fats, Waxes, 1913-1916. The Macmillan Co.

Liddell, Metallurgists and Chemists' Handbook. 1918.

Low, A. H., Technical Methods of Ore Analysis, 7th Ed., 1919. John Wiley & Sons, New York.

Lunge, G., The Manufacture of Sulphuric Acid and Alkali, 4th Ed., 1913. Van Nostrand Co., New York.

Lunge, G., Technical Methods of Chemical Analysis. Trans. Edited by Chas. A. Keane. Gurney & Jackson, London. D. Van Nostrand Co., New York.

Mahin, E. G., Quantitative Analysis, 1919. McGraw-Hill Book Co.

Marks, L. S., Mechanical Engineers' Handbook, 1916, McGraw-Hill Book Co.

Mead, R. K., Portland Cement, 2d Ed., 1911. The Chemical Puh. Co., Easton, Pa. Ibid., Chemists' Poeket Manual, The Chemical Pub. Co., Easton, Pa.

Mellor, J. W., Treatise on Quantitative Inorganic Analysis, 1913. Chas. Griffin & Co., Ltd., London.

Olsen, J. C., Quantitative Chemical Analysis, 5th Ed., 1921. D. Van Nostrand Company, New York.

Perkin, F. M., Electro Chemistry. Longmans, Green & Co., London and New York.

Prescott, A. B., and Johnson, O. C., Qualitative Chemical Analysis, 7th Ed., 1920. Revised by J. C. Olsen. D. Van Nostrand Co., New York.

Popoff, Stephen, Quantitativo Analysis, 1924. P. Blakiston's Son and Co., Philadelphia,

Rhead, E. L., and Sexton, A. H., Assaying and Metallurgical Analysis, 2d Ed., 1911. Longnians, Green & Co., London and New York.

Rogers, A., Manual of Industrial Chemistry, 3d Ed., 1921. D. Van Nostrand Co.

Roscoc, H. E., and Schorlemmer, C., Treatise on Chemistry, 1911. Maenillan & Co. Schoeller, W. R., and Powell, A. R., The Analysis of Minerals and Ores of the Rarer Elements. Chas. Griffin and Co., London.

Scott, W. W., Qualitativo Analysis, 4th Ed., 1921. D. Van Nostrand Co., New York. Technical Methods of Metallurgical Analysis, D. Van Nostrand Co., New York.

Segerblom, W., Tables of Properties. Exeter Book Puh. Co., Exeter, N. H.

Seidell, A., Solubilities of Inorganic and Organic Substances, Second Ed., 1919. D. Van Nostrand Co., New York.

Smith, E. F., Electro-analysis. P. Blakiston's Son & Co. 1918.

Stillman, T. B., Engineering Chemistry, 5th Ed., 1916. The Chemical Publishing Co., Easton, Pa.

Sutton, F. A., Systematic Handbook of Volumetric Analysis, 10th Ed., 1911. P. Blakiston's Son & Co., Philadelphia.

Talbot, H. P., An Introductory Course in Quantitative Chemical Analysis, 1899. Macmillan & Co., New York.

Thorpe, E., A Dictionary of Applied Chemistry, Five Volumes, 1913. Longmans, Green & Co., London and New York.

Treadwell, E. P., Analytical Chemistry. Translated by W. T. Hall, 6th Ed., 1924. J. Wilcy & Sons, New York.

Van Nostrand's Chemical Annual. Edited by J. C. Olsen, 4th Issue, 1918. D. Van Nostrand Company, New York.

White, C. H., Methods in Mctallurgical Analysis, 1915. D. Van Nostrand-Co., New York.

Wiley, H. W., Principles and Practice of Agricultural Analysis, 1914. The Chemical Pub. Co., Easton, Pa.

NOTE

The lapse of paging between the end of Volume I and the beginning of Volume II, is to allow for the expansion of Volume I, without changing the folios of Volume II.



II FER. 1927

INDEX

SUBJECT INDEX

Abbé refractometer, 1125	Acid, citric, 1549
Abraham, H., bituminous substances,	chlorsulphonie, 1540
1289-1350	fluosilicic, 1507
Abraham's ductility test, 1304	formic, 1542
Absorption bulbs:	hydrochlorie, determination of total
carbon dioxide, Fleming, Geissler, Ger-	acidity, arsenic, barium, chloride,
hardt, Liebig, Vanier, 111, 11-1	chlorine, nitric acid, sulphuric
gas analysis, Friedrich, Hanjkus, No-	acid, silica, total solids, 1501
wicki-Heinz, Varrentrapp, Winkler,	hydrofluoric, determination of acidity,
Wolff, 1237	hydrofluosilicie neid, sulphurie
Absorption spectrum, carbon monoxide in	acid, sulphurous acid, 1506, 1509
air, 1274	nitric, determination of acidity, free
Accuracy in methods of gas analysis, 1251	chlorine, hydrochloric acid, io-
Accuracy, limit of, in alloy analysis, 1041	dine, nitric and nitrous acids,
Acetanilid, 1732	non-volatile solids, sulphurie
Acetate extraction of lead, 273, 279	acid, 1509
Acetates, 1547	procedure for determining, in ar-
Acetic acid, complete analysis of acetone,	senic acid, ferrous sulphate
formic acid, furfurol, hydrochloric	method, 1516
acid, metals, sulphuric acid, sul-	in olemn and mixed acids, 1515
phurous acid, 1545-1547	in phosphoric acid, 1516
method for nitrite, 338	in sulphuric acid, 1514
specific gravity table, 673, 1548	nitrons, permanganate titration of
Acetic anhydride, analysis of, 1544	1510, 1530
Acetin method for det. glycerol, 1755	oleum and mixed acids, complete
Acetone, analysis of, 1759	nnalysis, determination of total
extraction of rubber, 1576, 1585, 1587	acidity, lower oxides, nitric acid
in acetic acid, 1546	sulphuric acid and free SO ₃ , calcu-
Acetyl value for oils, 1135	lations, table, 1530–1540
Acetylene flaine, temperature of, 658	organic, 1542-1551
properties of, 1227g	phosphoric acid, analysis of, 1521
Acid number in soap analysis, 1604	sulphuric acid, analysis of, 1524
Acid, free in soap, 1600	det. lead, iron, arsenic, zinc, selc-
Acidimetric and alkalimetric methods for	ninn, hydrochloric and nitric
metabisulphites, sulphites, sulphurous	acids, 1524-1528
acid, 513	tartarie acid, 1550
phosphorus in steel, 1364	Acids—arsenic in acids, 49
Acidimetry and alkalimetry, 1491-1560	corrections for in calorimetry, 1653
Acid number, Chinese wood oil (Tung oil),	formulæ for diluting or strengthening
1169	of, 1533
linseed oil, 1165	free acids in aluminum salts, estimation
varnish, 1174	of, 12
Acid number, linseed oil, 1105	in aluminum salts, test for, 13
Acidity in explosives, 1394	in presence of iron salts, estimation
in rubber, 1570	of, 1551
in water, 1429	indicators for determination of 1491
Acids, chapter on, 1491	number in oil analysis. See Oils.
analysis of acetic. See subject above.	reactions—tables of, 630, 646-653
carbolie, 1549	standards, preparation of benzoic, hy-
carbonic, 1549	drocblorie, sulphurie, 1493-1495

Aside took for in spirmal and monetable	Albelias managation of the sumple forti
Acids—test for, in animal and vegetable	Alkalies, preparation of the sample, ferti-
oils, 1140	lizers, 404
in burning oils, 1113 in Chinese wood oil, 1169	plants, ashes of, 405 rocks and insoluble mineral products,
in varnish, 1174	404
titration of, 1497	saline residues, soluble salts, brines,
tungstic, solution of, 555	405
strong acids, Blay-Burkhard burette,	soils, 404
bulb tube, Deli tube, Lunge-Ray	reaction—tables of, 644
pipette, snake tube, 1498	separation from aluminum, chromium,
weighing dilute acids, 1498	iron, phosphoric acid, titanium,
Acker process for determination of tin, 531	uranium, 406
Adolph's apparatus for fluorine det., 218	from barium, caleium, strontium, sul-
modification of Offerman's method for	phuric acid, 406
fluorine, 218	from each other, 408
Ahlum's method for free acids in presence	from the hydrogen sulphide group
of iron salts, 1541	and silica, 405
Alr, composition of, 338	from magnesium, 405
oxamination of. See Gus Analysis, 1272	test for iridium, 383
oxygen in hydrogen combustion meth-	for pulladium, 382
od, 1247	Alkalimeter, Mohr's, 147
phosphorus method, 1246	Schroetter's, 147
pyrogaliate method, 1247	Alkalimetric method for determining
pound per cubic foot of coal burned,	phosphorus, 368
calculation of, 1254	for determining strontium, 491
sulphur dioxide in, 1283	Alkaline earths. See Barium.
Air, dry, properties of, 1227f, 1287	separation from one another, 60
saturated, properties of, 1288	silicates in soap analysis, 1604
Albuminold ammonia, determination of, in water, 1413	Alkalinity determination in water, 1429
Alcohol, ethyl, detection of, 1728, 1743	Alkaloids, 1731 Allen, method for traces of iron, 244
determination of distillation and evap-	modification of Devarda's method for
oration methods, 1744	nitrates, 346
specific gravity tables, 1748	and Bishop method for sulphur in
Alcoholic-KOH oxtraction of rubber,	pyrites and sulphur ores, 498
1588	Allihn's method for sugar in soap, 1159
Alcohol-insoluble matter in scap, 1601	Alloy steel. See Iron and Steel.
methyl, det. of, 1728, 1753	Alloys, 1036–1107
Aldehyde, det. of, 1745	determination of aluminum in, 1090,
Alexander's volumetrie method for de-	1106h
termining lead, 277	antimony in, 28, 1074, 1086, 1103
method for rubber, 1568	arsenic in, 1088
Alizarine S for determination of alumi-	bismuth in, 286, 1047
num, 14 test for aluminum, 3	cadmium in, 1087
Alkali arsenates, arsenic determination in,	carbon in, 1102, 1106g, 1106i copper in, 1049, 1053, 1058, 1067,
35	1071, 1076, 1098, 1099, 1106,
standard for, acidimetry and alkalim-	1106j
etry, 1493-1496	iron in, 1055, 1073, 1082, 1092, 1097,
Alkali combined in soap, 1601	1106j
Alkali fluorides, det. of, 224	lead in, 1051, 1052, 1053, 1061, 1062,
Alkalies, analysis of, 1552-1560	1067, 1071, 1080, 1081, 1106,
Alkalies, chapter on, 401, 1552	1067, 1071, 1080, 1081, 1106, 1106a, 1106b
detection of casium, lithium, potassium,	magnesium in, 1106c
rubidium, sodium, 401–403	manganese in, 1056, 1057, 1093, 1100,
estimation in alunite, 417	1101, 1106d, 1107
in Portland coment, 1216	nickel in, 1083, 1094, 1106b
in silicates, hydrofluoric acid method, 417	phosphorus in, 1059, 1063, 1078, 1084
J. Lawrence Smith method, 416	silieon in, 170, 1095, 1103
volumetrie method, 418, 1552	sulphur in, 1075, 1087, 1107 tin in, 1054, 1059, 1060, 1072, 1077,
physical properties, 401	1079, 1105
A P TO STORE TO STORE TO THE	,

Alloys, titanium in, 1006, 1103	Aluminum, by precipitation as aluminum
zinc in, 1063, 1094, 1106c	chloride, 10
Alloys, decomposition of, 71, 101, 167, 183,	as phosphate, 9
186, 272, 1040, 1041-1066, 1072 —detection of bismuth in, 1047	volumetric, determination of com-
of gold in, 228	bined alumina, 11, 15
general, alloys with:	free alununa or free acid, 12
antimony, 20, 21	special procedures: analysis of metallic aluminum for
iridium, 388	silicon and irou, 17a
iron-titanium, 297	in alloys, 1090, 1106h
load, 21, 272	in bronze, 16
manganese, 286. See Alloys.	in bauxite, 17g
molybdenum, 297 nickel, 331, 336. See Alloys.	in iron and steel, 17a, 268-269
nickel, 331, 336. See Alloys. rhodium, 393	in metallic aluminum dust, 17e
silicon, 297, 1368a	in nickel, 336d
tin, 21, 536a	in presence of iron, phenylhydra- zine method, 552
titanium, 540	impurities in metallic aluminum, 17a
tungsten, 297, 554, 556, 558	industrial application, 3
vanadium, 207. See chapter on V.	occurrence, minerals and ores, 3
non-ferrous alloys, 1033-1066	preparation and solution of the sample,
alloys of antinony, copper, lead and	3-5
tin, 1041–1047 aluminum alloys, 17, 1090, 1095–1106	metallic aluminum and its alloys, 5
brass and sand castings, 1067-1075	properties, 3 aluminum phosphate, 10
bronze and bearing metal, 1076-1089	separation from glucinum, iron, munga-
gun metal, 1058-1063	nese, nickel, phosphoric acid, silica,
manganese brouze, 1047-1057	titanium, uranium, zinc, 5, 6
moncl metal, 1106	from chromium, 158, 150
nickel silver and cupro nickel, 1092-	from glucinum, 69a
1094	solubilities, metal and its oxide, 3
phosphorus in alloys, 1063–1066 white metals, 1047–1048	traces, detection and estimation of, with alizarine S, 3
Alpha benzyldioxine method for deter-	Aluminum Company of America, methods
mining nickel, 332	for aluminum, 17a-17l
test for nickel, 311	methods for alloys of Al, 17a-17l
Alumina in bauxite, 15, 17g	Aluminum precipitate of Cu, 184, 193a
in nitrate of soda, 350	Aluminum reduction method for nitrates,
in phosphate, together with iron, 372	1416
in Prussian blue, 1197 in ultramarine blue, 1197	Aluminum hydrate, analysis of, 17h
in sand, 448	Aluminum sulphate, analysis of, 1773 Alumite, alkalies in, 418
in slag, 1612	American Vanadium Company, methods
in silicate of soda, 447	of analysis, 594-596
in titaniferous ores, 552	Amino-nitrosophenyl-hydroxylamine
in water, 1423	method for iron, 250
basic, determination of, in aluminum	Ammonia, albuminoid, in water, estima-
salts, 13 Alumina and iron oxido in composite	tion of, 1413 free in water, estimation of, 1412, 1434
white paint, 1180	gravimetric method for, determining as
in green paint pigments, 1199	platino-chloride, 342
in metallic lead, 290	reagent for etching, 1705
in Portland cement, 1216	total, in ammoniacal liquor, 343
together in phosphate rock, 372	traces, determination of, in gas, 1261
Alumina ores, arsenic determination in,	volatile, in ammoniacal liquor, 343
Aluminum, detection of, 3	volumetric method, 343
estination, general procedures:	Ammonia, aqua, volumetric method for, 1560
gravimetric, by hydrolysis with am-	in fused zine chloride, det. of, 617
monium hydraxide, 7	conversion to HNO, 361c
by hydrolysis with sodium thiosul-	specific gravity table, 675, 1559
phate, 9	Ammonia-dynamite, analysis of, 1379

Ammonium chloride, fusion with per-	Antilogarithms, table of, 715
chlorate (note), 152	Antimonous and antimonic salts, distinc-
test for iridium, 389 test for palladium, 383	Antimony, detection of, by hydrogen sul-
test for platinum, 376	phide test, hydrolysis, in minerals,
test for vanadium, 583	traces, 18
hydroxide method for determining	estimation, general procedures: gravi-
traces of copper, 199	metric, electrolytic as metallic anti-
table, 675, 1559	mony, 25
test for iron, 246 test for palladium, 382	as trisulphide, Sb ₂ S ₂ , 24 volumetric, bromate method, 26
test for rhodium, 389	indirect evolution method, 28a
iridium chloride, determination of	iodide method, 27
iridium as, 382	oxidation with iodine, 28
magnesium phosphate, acid titration of,	permanganate method, 28a
294 properties of, 294	estimation, special procedures: determination in alloys, in breas
nitrate washing solution for aluminum	and bronze, 28b, 1074, 1086,
hydroxide, 8	1105
nitrate-pyridine in, 1309	in ash of rubber, 1592
oxalate reagent for oxygen consumed,	in copper, 202
water analysis, 1417	in hard lead, 25
persulphate method for Mn det., 266, 305	in metallic lead, 289 in nickel, 336e 1591
phosphomolybdate method for phos-	in rubber goods, 21, 1572, 1580,
phorus, 366	in sulphuric acid, 1526
phosphate method for separating mag-	in soft solder, 28
nesium from alkalics, 408	in tartar emetic, 33
method for zirconium, 622a platinochloride method for determining	in tin and lead alloys, 28 in presence of vanadium, 592
ammonia, 342	industrial application of analysis, 18
Ammonium nitrate, pyridine in, 360	occurrence, minerals, ores and alloys, 18
Animonium persuipnate in. for Mili, 200	preparation and solution of the sample:
Ammonium pierate, analysis of, 1393	alloys of antimony, tin, and lead,
Ammonium salts, effect on magnesium precipitation, 293	hard lead, low-grade oxides, mattes, slags, speisses, sulphides,
effect on sulphur determinations, 497	rubber materials, 19–21
determination of ammonia in, 341	properties, antimony trisulphide, 24
mixtures, ammonia in, 343	separation from members of the subse-
sulphate, det. of, in shale, 1350	quent groups, aluminum, chro- mium, cobalt, iron, manganese,
sulphide group, separation of, 168, 292, 405	nickel, zinc, alkaline carths and
sulphide method for mercury, 377	alkalies, 22
test for ruthenium, 387	from bismuth, cadmium, copper, lead
test for vanadium, 583	and mercury, 22
sulphocyanate test for cobalt, 166 test for iron, 246	from arsenic, antimony and tin, 22–23 from tin in alloys, 1041
table, sp. gr., 1559	solubility of the element and its oxides,
Amorphous sulphur, det. of, 519a	19
Ampre, dennition of 703	solution for standard stains, 31
Amyl alcohol. See Fusel Oil.	traces of, in refined copper, 32
Andrew's method for silver, 463 Andrew-Burgarszk's method for analysis	traces, determination of, 29 Antimony and calcium oxides in As ₂ O ₃ , 54
of crude bromide and bromine, 96	Antimony oxide pigment, 1193
Anemometer, 1236	Antwerp blue, analysis of, 1197
Aniline method for det. acetic anhydride,	Apothecaries' weight table, 703
1544 Animal and vegetable oils, 1133, 1140d	Apparatus. See lists following Table of Contents, Vol. 1 and Vol. 2.
analysis of, 1123	standard, calibrated, 1685–1694
test for, 1134	Applebaum, A. F., chromium in steel, 164
Anthraquinone, 1325	Aqua ammonia, 1559–1560
Antifluorescence, tests for, 1135, 1141	Arc, electric, temperature of, 650

5

Areas, formulæ for determining, 703 Arsenic traces, determination of, by modtable of, 702 ified Gutzeit method, 46, 52 triangle, rectangle, parallelogram, trap-ezoid, circle, 703 Marsh test for, 47 in acids, hydrochloric, nitric, sul-Argon in the atmosphere, 358 phuric, 49-50 Arnold-Kjeldahl-Gunning method for baking powders, canned goods, nitrogen, 339 Arsenates, alkali, 35 meat, organic matter, etc., 51 ores, alumina-bearing, bauxite, Arsenates, distinction from arsenites, 34 cinders, pyrites, 50 Arsenic acid, alkali arsenates, 37 in organic matter, 51 in refined copper, 202 commercial As₂O₃, analysis of, 53 Arsenic, detection of, by Gutzcit test, by in salts, sodium chloride, magnesium sulphate, etc., 51 Arsenite reagent 0.1 N, 240 hydrogen sulphide, volatility test, 34, estimation, general procedures: Arsenous acid, determination of, with iogravimetric, determination as arsenic dine, 43 reduction of bromates with, 96 trisulphide, As₂S₃, 41 chloride, volatility of, 34, 38 determination as magnesium pyrooxide in paint pignients, 1185 in zinc oxide, 1185 arsenate, 41 volumetric, oxidation with iodine, Mohr's method, 44 Arsenous method for determining peroxides, 1761 iodate method, 44 silver arsenate method, 45 Asbestinc paint pigment, 1187 special procedures: Ash soda, cauterized ash, 1555 Ash, fusibility, 1630 determination in alloys, brass and bronze, 1088 in black paint pigments, 1197 in brimstone, 519 in coal, determination of, 1630 in explosives. See Explosives. in copper, 55, 202 in gases, det. of, 1505 in linseed oil, 1166 in plants, determining alkalies in, 282 in hydrochloric acid, 1502 of rubber, sulphur in, 1591 in iron, 55 in metallic lead, 287 Asphalt. See Bituminous substances, 1289 Assaying of gold and silver. See Fire Assay of Gold and Silver. in molybdenite and wulfenite, 565 in molybdcnum ores, det. of, 325 Astringency of tannic acid, 1760 in nickel, 336e A.S.T.M. analysis of alloys, 1036-1107 in presence of vanadium, 593 for gypsiun analysis, 108b A.S.T.M. standards for Chinese wood oil, in steel, 37, 55 in sulphuric acid, 1526 in tungsten ores, 565 impurities in "arsenie acid," determi-1171 iron and steel analysis, 1351-1371d nation of moisture, antimony, ar-senic calcium cobalt, copper, iron, for linseed oil, boiled and raw, 1172 turpentine, 1174 lead, nickel and zinc oxides, silica, vanadium in steel, 595 Atomic weights, international, table of. See front cover sulphuric acid, 53-55 industrial application of methods, 34 occurrence, minerals, ores, 34 Atropine, 1735 potassium iodate method, 44 Attack's method for traces of aluminum, 14 Available lime, 108 preparation and solution of the sample, Avoirdupois weight, table of, 702 alkali arsenates, arsenic acid, arsenous oxide, hydrochloric and sul-Babbit metal, copper in, 211 phuric acids, pyrites ore, 35, 49 lead arsenate, zinc arsenite insecti-Bach's test for rapeseed oil, 1144b for rosin oil, 1144b cides, copper, iron, 36, 37 properties, 34 Bacteria, total in water, 1461 Bacteriological exam. of water, 1454-1468 separation from other elements by dis-Bahr's app. for solubility determ., 1476tillation, 38, 39b 1477 from antimony and tin, 40 from tin in alloys, 1193 Bailar's iodide method for CaO, 108a solubility of oxides, sulphides, salts, 34 solution standard, 1360 zinc chloride method for CaO, 1804 Baker's method for tin, 532 stains, preservation of, for Gutzeit method, 47 Baking powder, arsenic determination in,

Baking powder, lead determination in, 281	Barium hydroxide method for separating magnesium from alkalies, 407
phosphate, determination of phos- phoric acid in, 365	sulphate, apparatus for filtering of, 500
Balata, 1371	decomposition for sulphur det., 496
Ball mill, 1617	in blanc fixe, 1188
Bardy and Riche on det. methyl alcohol,	in lithopone, 1186
1753	properties and solubility of, 64
Barium, detection of, with sat. sol. of cal-	Barium ores, analysis of, 66
cium or strontium sulphates, 56	Barker's hydrometer for CO ₂ det. in car-
with soluble chromates, fluosificie	bonates, 125
acid, flame, 56	B. coli, examination of, 1462
spectrum of, 56	Barnitt, formulæ for solutions, 1533
estimation, general procedures:	chapter on sampling, 1003 Barton, methods for titanium in steel, 547
gravimetric, determination as car-	Burton and Scott, chapter on titanium,
bonate, BaCO ₃ , 63b as chromate, BaCrO ₄ , 63a	538
as sulphate, BaSO ₄ , 64	method for nitrogen in steel, 361a
volumetric, acid titration of carbon-	Barytes, analysis of, determining barium
ate, 66	carbonate, barium sulphate, iron and
dichromate method, 65	aluminum oxides, lime, magnesia,
permanganate method, 65	silica, soluble SO ₃ , etc., 66–68
potassium iodido method, 65	water test for magnesium, 291
estimation, special procedures:	Base box, definition (note), 524
determination in insoluble residue, 62	Bases, reactions, tables of, 632-645
in ores, 63	Basic acetate nicthod for precipitating aluminum and iron, 298
in silicates, 63	Basic alumina in aluminum salts, determi-
ore, valuation of. See Barytes. industrial application, 56	nation of, 13
occurrence, ores, commercial products,	"Basic hydrochloric acid" in bichloride
56	of tin, 530
preliminary tests, 59	Basic carbonate of lead det., 278b
preparation and solution of the sample,	Basic nitrate, precip. of bismuth as, 74
carbonates, insoluble residue, sul-	Basicity of aluminum sulphate, 13
phates, sulphides, soluble salts, or-	Baubigny's method, modified, for deter-
ganic matter, 57	mining halogens, 154
properties, barium sulphate, 56, 64	Baudisch's cupferron method for iron, 250
barium chromate, 64	Baudouin's or Camoine's test for sesame
separations, general considerations, 58 from alkalies and magnesium by the	oil, 1139, 1144b Baughmann, W. F., 97
oxalate and sulphate methods,	and Skinner on iodine in water, 245
59, 60	Bauxite, analysis of, determining soluble
from calcium and strontium, 60, 61	and total alumina, soluble and tetal
from molybdenum and from P2O6,	iron, insoluble residue, silica, titanium
62	oxide, 17f-17g
solubilities, barium compounds, 56, 64	arsenic determination in, 50
traces, detection of, by flame and spec-	Bead test for titanium, 538
Barium asstate or chloride test for shre	Beam test for matter susp. in gas, 1763
Barium acetate or chloride test for chro-	Bearing metal, determining bismuth in, 71 Beeswax, constants, 1150
mate, 356 carbonate in rubber, 1595	Bechi's test for cottenseed oil, 1136, 1142
chloride in hydrochloric acid, 1502	Beckstrom, on oil, 1158
-potassium chromate method for sul-	Bekk's method for determination of the
phur determination, 505	halogens, 155
test for bromate, 92	Belasio on aluminum, 17
chromate, determination of chromium	Bellicr's test for oil, 1144a
as, 160	Belt dressings, 1145 Repeler's method for serbon in steel 130
property of, 64 solubility of, 64	Benoker's method for carbon in steel, 130 Bennett's method for determining arsenic,
-thiosulphate method for sulphur, 506	45
hydroxide reagent for C in steel, 1356,	Benzidine acetate test for gold, 229
1357	hydrochloric acid method for deter-
sulphate in rubber, 1591	mining sulphates, 507, 1427

sulphids, 103 in bronze, 1097 Berkeley's app. solubility dd., 1472, 1473 in steel, 267, 1360	
Berthelot's test for alcohol, 1743 in water, 1426 Beryl, 69 Bisulphate fusion See charter "	ъ
Beryl, 69 Beryllium, 68-69b Bisulphate fusion. See chapter " position of Sample," Vol. 2.	Decom-
detection of, 68 Bisulphite. See Metabisulphite.	
estimation, 68, 69a, 69b Bitumen and pitch in rubber, 1570	1
separations, 69 Bituminous substances, asphalt	s, tars.
Betts, nitrometer method, 355 pitches, 1289-1350	-,,
Bicarbonate, determination of, 1549 Alraham's ductility test, 130	4
Bichloride of tin, Acker method for anthroquinone reaction, 1325	
analysis, 530 bit. solvent examin., cements, Bichloride of tin—hot water precipitation varnishes, 1346–1349	paints,
of tin in, 530 variation variables, 1346–1349 carbenes, 1318	
sulphide method for tin in, 532 characteristics of table, 1326-13	27
Bichromate method for det. glycerol, 1758 chem. tests, carbon free in ta	
Bidtel's method for valuation of fluor- oxygen in non-mineral	
spar, 225	
Bishop, funing sulphurie acid table, 673 solid paraffines, 1323	10
Bishop and Allen, method for determining sulphonation residue, 132 sulphur in ores, 498 water, high and low distl	
Bismuth, detection of, general procedure, composition of, 1289–1293	., 1020
reducing agents, blowpipe test, 70 crude, refined, blended, ex	am. of,
estimation, general procedures: 1294	•
gravimetric, determination as basic diazo reaction, 1324	
chloride, 73 distillation test-flask and	retort
as metal by cyanide reduction, 76 method, 1315–1316	
as metal by electrolysis, 76 ductility, Dow test of, 1302 emulsions, 1349	
as sulphide Bi ₂ S ₂ , 75 examination of, 1289-1350	
volumetric, bismuth iodide colori- fabrics, examination of, 1336	
metric method, 78 physical tests of, 1557	
cinchonine potassium iodide colori-	t. cur.,
metric method, 77 hcat, weather, 1338 permanganate titration of oxalate, weight, pliability and s	trength
permanganate titration of oxalate, weight, pliability and s	utengui,
estimation apecial procedures: fubrics separated, examin, of,	1344
in alloys and metals, 1047 nash-point, Fenski-Wartins	closed
in metallic copper, 200 tester, 1314	
in metallic lead, 79, 286 filler and pigment in, 1347 in ores, mattes, 80 fracture of, 1295	
in ores, mattes, 80 in pig lead, 286 in	v needle
industrial application of methods, 70 penetrometer, 1298	,
occurrence, 70 hcat tests, 1305-1309	
preparation and solution of the sample, cube method, 1309	•
alloys, lead bullion, refined lead, ball and ring method, 13	
ores, 70, 71 Kramer-Sarnow method, properties, bismuth, basic nitrate, 74 mineral aggregates, physica	1 tests
properties, bismuth, basic nitrate, 74 mineral aggregates, physica compression and impact	distor-
sulphide, 75 tion under heat, 1328-133	29
separations, aluminum, chromium, iron, mineral matter, examination of	f, 1333-
cobalt, manganese, nickel, zinc, 1335	
magnesium, alkaline earths, alka- physical characteristics, 1295	le met
lies, 72 saponifiable and unsaponifiable from arsenic, antimony, tin, molybdeter, 1323	11114V-
from arsenic, antimony, tin, molybde- num, selenium, tellurium, 72 ter, 1323 separation bitum. from mine	eral ag-
from cadmium and copper, 72 gregate, 1330	-
from lead and mercury, 72 centrifugal method, 1332	^
solubility, metal and salts, 70, 73, 74, 75 Forest's hot extraction, 133	
traces, determination of, 77, 78 sep. bitum. min. and fib. m.,	100)0

Bituminous substances—	Boron, detection of, borax bend test, prop
fabrics—single layer, saturated or	erties, flame test, turmeric test, 81
coated roofings, laminated	Chapin's method, 87
fabrics, etc., 1339-1343	estimation, general procedures:
Smith's ductility machine, 1303	gravimetric, lime fixation method, 8
solubility tests by CS ₂ , 1317	method of Gooch and Jones (note)
test by petroleum naphtha, 1317	85
specific gravity by hydrometer, 1295	volumetric determination, 86
pycnometer, 1296	estimation, special pracedure:
Westphal balance, 1295	determination as horic acid in butter
streak on porcelain, 1295 susceptibility factor, 1302	83
table of, 1290–1292, 1294	Boron distillation and for 88
viscosity, Engler and float tests, 1297	Boron, distillation app. for, 88 estimation, determination, in meat, 83
volatile matter, 1312	in milk, 83
Black pigments, analysis of, 1177, 1199	in silicates, enancels, etc., 82
Black powder, analysis of, 1372	in mineral water, 82
Black oils, 1145	industrial application of methods, 81
Blair, analysis of steel, 128, 301	occurrence, ores, alloys, sundry prnd
Blanc fixe and barytes, analysis of, 67,	neta, 81
1188	preparation and solution of the sample
Blangey's method for chiloric acid, 152	boric acid, boric oxide, boracite
Blast-furnace gas, analysis of, 1255	borocalcite, boronatrocalcite, cal
slag analysis of, 1610	cium borate, enamels, sibeates
Blasting caps, analysis of, 1396	ete., 82
Blattner and Brassner, chlorine in chlo-	earbonates, butter, nicat and canned
rates and perchlorates, 153 method for reduction of chlorates,	goods, 83
152	mineral water, 82 solubility of boron, boric acid, borax, 82
Blay and Burkhard, graduated weighing	traces, detection of, by Robin's test, 87
burette (Fig. 83), 1500	Bosworth and Gooch, method for silver
Bleaching powder, evaluation of, 155	determination, 463
analysis of, in paper-making materials,	Bowman and Scott, ferrous sulphate
1779	method for nitrie acid, 1512
Blister copper, electrolytic determination	Bradbury and Owen, alkali earbonates
of copper, 189	and hydrates present together, 1066
Blood, carben monnxide determination by	Brass and bronze,
means of, 1273	determination of antimony in, 28b
in carbon monoxide, 83	determination of enpper in, 211
"Bloom" in oils, 1135	determination of vanadium in, 598
Blowpipe test for bismuth, 70 test for cadmium, 100	niethod of National Brass and Cop-
Blowpipe and flame tests, table of, 625	per Tube Co., lead and copper, 207
Blue lead, sublimed, analysis of. 1197	Breyer, on analysis of zine, 597
Blue pigments, analysis of, 1177, 1196	manganese determination in spiegel
Blue vitriol, copper determination in,	iron, 306
206	separation of zinc as sulphide, 605
Boiling, prolonged, effect me aluminum	Briggs and Scott, modified Orsat appa-
hydroxide precipitate, 8	ratus (Fig. 131), 1267
effect on glucinum separation from	Brimstone, analysis of, determining mois-
aluminum, 227	ture, ash, arsenie, chlorine and avail-
point chart, sulphuric acid of varying	able sulphur in, 519
concentration, 1524	Brines, preparation of, for alkali determi-
Bond, F. C., on silver, 458	nation, 405
Borax bead, boron test, 81 evaluation of, 86	Briuton, H. M. P., chapter on Thorium,
table of tests, 627	zirconium, 618
Borie acid, Chapin's determination of,	Brinton and James det. of cerium, 135
87	British thermal unit (B.t.u.), calculation
evaluation of, 87	of, 1627, 1639, 1659
in foods, 83	determination of heat value of coal,
in soan, 1604	1622 1634-1640

Brom-thymol blue, titrations with, 1457 Bromine, determination of, in illuminating gas, 1257 Bromate method for determining anti- mony, 26 Bromates, detection of, 92 determination of, hy arsenous reduction, 96 Bromine, detection of, tests with carbon disulphide, carbon tetrachloride, ha- rium chloride, magenta test, silver nitrate, 92 estimation, general procedures: gravimotric, determination as silver hromide, 94 volumetrie, free bromine by potas- sium iodide method, 95 chlorine method for soluble bro-	Bureau of Standards on manganese in steel, 266 phosphorus in steel, 268 silicon in steel, 270 sulphur in steel, 269 titanox pigment analysis, 1192 Burettes, standard, for acidimetry and alkalimetry, 1497 Burges' nitroso-beta-naphthol method for cobalt, 169 Burkhard and Blay, weighing burette, 1500 Burning oils. See Oils, 1109 Burnell, G. A., analysis industrial gas, 1288j B. typhi, examination of, 1467 Butter, boric acid determination in, 83 method of analysis. See Oils, 1142
nines, 95 silver thiocyanate method of Volhard, 95 estimation, special procedures: crude potassium bromide, analysis of, 96 impurities in commercial bromine, chlorine in, 97 in mineral waters, 97 industrial application, 93 occurrence, 93 preparation and solution of the sample, organic matter, salts, etc., 93 properties, 93 separations from chlorine and iodine, 94 heavy metals, cyanides, and silver, 93 soluhility of the element and its salts, 93 traces, determination of, 95 Brondine-ammonia method for separating manganese from zine, 600 precipitating manganese dioxide with, 301	Cadmium, detection of, general procedure, 99 spectrum of cadmium, blowpipetest, 99 estimation, general procedure: gravimetric, determination as cadmium sulplate, 102 as cadmium sulplate, 102 as cadmium sulplate, 101, 612 ns metallic cadmium by electrolysis, 102, 611, 1102 volumetric, iodine titration of cadmium sulphide, 103 estimation, special procedures: determination in alloys and metals: in metallic lead, 290 in ores, det. of, 101 in spelter, 612 industrial application, 99 occurrence, 99 preparation and solution of the sample, alloys, carbonates, ores, sulphides, in presence of lead, 100 separation from members of the am-
Bromine number in oil analysis, 1130 Bronze, analysis of, by A. S. T. M., 1047 aluminum in, 16 Brown pigments, analysis of, 1176, 1190 Browne's heating tests for Chinese wood oil, 1170 Browning-Drushel, separation of mag- nesium from the alkalies, 407 Browning's test for fluorine, 213 test for silica, 431 Brucine, 1734 Buckwheat coal, determination of B.t.u. in, example data, 1628 Budde's method for rubber analysis, 1568 Bulb, weighing acids, 1500 Bullion, assay of, 482, 484 Buovold's gravimetric method for nitrites, 358 Bunsen pump (Fig. 111), 1232 Burcau of Standards method for carbon in steel, 263	monium salphide group, alkaline earths and the alkalies, 100 from arsenie, antimony, and tin in presence and in absence of copper, 100 from copper in alloys, 1089 from bismuth and lead, 101 from mercury, 101 from silica, 100 Cadmium chloride and sulphate reagents for sulphar determination, 501 sulphate, determination of, 102 sulphide, gravimetric determination of cadmium as, 612 volumetric determination of cadmium as, 103 Casium, detection of, 403 separation from lithium and sodium, 408 Calien-Little-Morgan, arsenic determination in organic matter, 36 Caillet, elaidin test for oils, 1128

Cain, J. R., and Cleaves, H. E., on carbon in steel, 118 Cain and Witmer, method for vanadinm in steel, 591 Calcined ore, analysis of, 17; Calcium, availablo, 108 Calcined ore, analysis of, 17; Calcium, availablo, 108 Calcined ore, analysis of, 17; Calcium, availablo, 108 Calcined ore, analysis of, 17; Calcium, availablo, 108 Calcined ore, analysis of, 17; Calcium, availablo, 108 Calcined ore, analysis of, 17; Calcium, availablo, 108 catination, general procedures: gravimetric, oxalate method, 107 other methods, 1084 estimation, special procedures: determination of, in composite white paints, 1190 in green paint pigments, 1193 in orange and yellow paint pignents, 1196 in sand, 448 in water, 1424 in water as calcium sulphate, 1125 industrial application of methods, 104 occurrence, ores, unireals, etc., 104 precipitation from acetic acid solution, 108 proparation and solution of the sample, enements, delomites, limestone, ungenesite, gypsum, plaster of Paris, silicates, sulphates, sulphides, pyrites, salts, decomposition of refractory ores, 105, 100 proparation and solution of the sample, enements, delomites, limestone, ungenesite, gypsum, plaster of Paris, silicates, sulphates, sulphides, pyrites, salts, decomposition of refractory ores, 105, 100 proparation from aluminum, iron, copper, cobalt, nickel, manganese, zinc and members of the hydrogen sulphide group, 105 from alkalies, barium, strontium, magnesium, P.O., 106 from silica, 105 solubilities, 104 traces, detection of, 104 Calcium earbonate, rapid method for determining, in enement, 1220 fluoride, decomposition of, 215 method for fluorine, 216 Calcium oxide det. in presence of CaCO ₂ , 108a, 1804 Calcium phosphate, decomposition, 107 Calorie, definition of, 708 Calorific power of illuminating gas, 1257 of fuel, 1622 Junker's for gas (Figs. 124, 125, 120), 1257, 1258		
Cain and Witmer, method for vanadium in steel, 591 Calcium, availablo, 108 Calcium, availablo, 108 Calcium, availablo, 108 Calcium, detection of, general procedure, 104 falme test, spectrum, 104 estimation, general procedures: gravimetric, coxalate method, 107 other methods, 108d volumetric, permanganate titration of the oxalate, 17d, 108 iodide method for, 108a estimation, special procedures: determination of, in composite white paints, 1100 in green paint pigments, 1196 in orange and yellow paint pignents, 1195 in Portland cements as CaO (lime), 1216 in sand, 448 in water, 1424 in water as calcium sulphate, 1125 industrial application of methods, 104 occurrence, ores, unierals, etc., 104 precipitation from acetic acid solution, 108 preparation and solution of the sample, cements, dolomites, limestone, unignesite, gypsum, plaster of l'aris, silicates, sulphates, sulphides, pyrices, salts, decomposition of refractory ores, 105, 100 rapid iodide method, 108a separation from aluminum, iron, coper, cobalt, nickel, manganese, zinc and members of the hydrogen sulphide group, 105 from silkalies, barium, strontium, magnesium, P ₂ O ₃ , 106 from alkalies, barium, strontium, magnesium, P ₂ O ₃ , 106 from silkalies, barium, strontium, magnesium, P ₂ O ₃ , 106 from silkalies, barium, strontium, magnesium, P ₂ O ₃ , 106 from silkalies, barium, strontium, magnesium, P ₃ O ₃ , 106 from silkalies, barium, strontium, or collection of, 215 method for fluorine, 216 Calcium oxide det. in presence of CaCO ₃ , 108a, 1804 Calcium phosphate, decomposition, 107 Calorie, definition of, 708 Calorific power of illuminating gas, 1257 of fuel, 1622 value of industrial gases, 1227 Calsimeter, Emerson bomb (Fig. 10.5), for coal, B.t.u. det., 1625 Junker's for gas (Figs. 124, 125, 120),	Cain, J. R., and Cleaves, H. E., on carbon	
in steel, 591 Calcium, availablo, 108 Calcium, availablo, 108 Calcium, detection of, general procedures; 104 flame test, spectrum, 104 estimation, general procedures: gravimetric, oxalate method, 107 other methods, 108d volumetric, permanganate titration of the oxalate, 17d, 108 iodide method for, 108a estimation, special procedures: determination of, in composite white paints, 1190 in green paint pigments, 1196 in orange and yellow paint pignents, 1195 in Portland cements as CaO (lime), 1216 in sand, 448 in water, 1424 in water as calcium sulphate, 1125 industrial application of methods, 104 precipitation from acetic acid solution, 108 preparation and solution of the sample, cements, dolomites, limestone, ungnesite, gypsum, plaster of Paris, silicates, sulphates, sulphides, pyrices, salts, decomposition of refractory ores, 105, 100 rapid iodide method, 108a separation from aluminum, iron, coper, cobalt, nickel, manganese, zinc and members of the hydrogen sulphide group, 105 from alkalies, barium, strontium, magnesium, Pros, 100 from silica, 105 solubilities, 104 traces, detection of, 104 Calcium acetate method for fluorine, 215 Calcium coide det. in presence of CaCOs, 108a, 1804 Calcium phesphate, decomposition, 107 Calorie, definition of, 708 Calcinier, Erroson bomb (Fig. 10.5), for coal, B.t.u. det., 1025 yuluce'r s for gas (Figs. 124, 125, 120),		
Calcium, variablo, 108 Calcium, detection of, general procedure, 104 falme test, spectrum, 104 estimation, general procedures: gravimetric, oxalate method, 107 other methods, 108d volumetric, permanganate titration of the oxalate, 17d, 108 iodide method for, 108n estimation, special procedures: determination of, in composite white paints, 1190 in orange and yellow paint pignents, 1196 in orange and yellow paint pignents, 1196 in sand, 448 in water, 1424 in water as calcium sulphate, 1125 industrial application of methods, 104 occurrence, ores, uninerals, etc., 104 precipitation from acetic acid solution, 108 preparation and solution of the example, cements, dolomites, limestone, magneside, gypsum, plaster of l'aris, silicates, sulphates, sulphides, pyrites, salts, decomposition of refractory ores, 105, 100 rapid iodide method, 108a separation from aluminum, irou, copper, cobult, nickel, manganese, zinc and members of the hydrogen sulphide group, 105 from alkalies, barium, strontium, magnesium, PyOs, 100 from silica, 105 solubilities, 104 traces, detection of, 104 Calcium carbonate, rapid method for determining, in cement, 1220 fluoride, decomposition of, 215 method for fluorine, 216 Calcium oxide det. in presence of CaCOs, 108a, 1804 Calcium phosphate, decomposition, 107 Calcium, browers of illuminating gas, 1259 Calcium earbonate, rapid inethod for fluorine, 223 Calcium earbonate, rapid inethod for fluorine, 216 Manuel extemination in, 536 Canolite of silcon, decemposition of, 435 Carbonate indicating oil, 1121 Capometer, 1235 Capacity, unit table of, 702 Carbona, detection of carbon decidention of decidention of methods, 104 carbonates in water, 109 carbonates in water, 109 carbonates of very combustion method, weighing COs, 111, 118 wet oxidation procedures: gravinetric, dry combustion method, weighing COs, 111, 118 wet oxidation procedures: gravinetric, dry combustion of CO2, 111, 120 volumetric, barium hydroxide method, 122 resimation, special procedures: in alloy steel, 1359 in black pigrate, 124, 125, 12		Campbell, A., chapter ou Soan Analysis.
Calcium, availablo, 108 Calcium, abetection of, general procedure, 104 flame test, spectrum, 104 estimation, general procedures: gravimetric, oxalate method, 107 other methods, 108d volumetric, permanganate titration of the oxalate, 17d, 108 iodide method for, 108a estimation, special procedures: determination of, in composite white paints, 1100 in green paint pigments, 1196 in orange and yellow paint pignents, 1195 in Portland cements as CaO (line), 1216 in sand, 448 in water, 1424 in water as calcium sulphate, 1125 industrial application of methods, 104 occurrence, ores, minerals, etc., 104 precipitation from acetic acid solution, 108 preparation and solution of the sample, cements, dolomites, limestone, magnesite, gypsum, plaster of Parts, silicates, sulphates, sulphides, pyrites, salts, decomposition of refractory ores, 105, 100 rapid iodide method, 108a separation from aluminum, iron, copper, cobult, nickel, manganese, zinc and members of the hydrogen sulphide group, 105 from alkalies, barium, atrontiun, magnesium, P ₄ O ₅ , 100 from siliaa, 105 solubilities, 104 traces, detection of, 104 Calcium acetate method for fluorine, 215 Carbonic acid, etc., 104 precipitation from aluminum, iron, copper, cobult, nickel, manganese, zinc and members of the hydrogen sulphide group, 105 from alkalies, barium, strontiun, magnesium, P ₄ O ₅ , 100 from siliaa, 105 solubilities, 104 traces, detection of, 104 Calcium acetate method for fluorine, 215 Carbonic acid, etc. of, 1549 carbonate method, 102, 111, 118 wet oxidation procedures: malloy steels, 1359 in blook pigments, 1196 in coal as "fixed carbon," 1622, 1646 in coal tar pitch, 1358 in load trace, 119, 120 indicators, 1253 Carbonic acid, free, det. of, 1549 carbonate method, 109 earbonic acid, steel, of, 104 carbonate method, 102 carbonate method, 108 reparation from aluminum, iron, copper, orbital procedures: in alloy steels, 1359 in blook pigments, 1196 in coal as "fixed carbon," 1622, 1646 in coal as "fixed carbon," 150 organic arbon, 151 organic substances, 119, 1		
Calcium, detection of, general procedure, 104 flame test, spectrum, 104 estimation, general procedures: gravimetric, oxalate method, 107 other methods, 108d volumetric, permanganate titration of the oxalate, 17d, 108 iodide method for, 108a estimation, special procedures: determination of, in composite white paints, 1190 in orange and yellow paint pignents, 1195 in Portland cements as CaO (lime), 1216 in sand, 448 in water, 1424 in water as calcium sulphate, 1125 industrial application from acetic acid solution, 108 preparation and solution of the sample, cenients, dolomites, linestone, magnesite, gypsum, plaster of Paris, silicates, sulphates, sulphides, pyrites, saltas, decomposition of refractory ores, 105, 100 rapid iodide method, 108a separation from aluminum, iron, copper, cobalt, nickel, manganese, zine and members of the hydrogen sulphide group, 105 from alkalies, barium, strontium, magnesium, PyOs, 100 from silica, 105 solubilities, 104 traces, detection of, 104 Calcium carbonate, rapid method for determining, in ecment, 1220 fluoride, decomposition of, 215 method for fluorine, 216 Calcium oxide det. in presence of CaCOs, 108a, 1804 Calcium phosphate, decomposition, 107 Calcium, oxide det. in presence of CaCOs, 108a, 1804 Calcium carbonate, capid method for fluorine, 216 Calcium oxide det. in presence of CaCOs, 108a, 1804 Carbonate method, 1022 Calcium carbonate, rapid method for fluorine, 216 Calcium oxide det. in presence of CaCOs, 108a, 1804 Carbonate method for barium, strontium, moderation of, 104 Calcium, touch development, 1220 fluoride, decomposition of, 215 carbonate method, 1222 Carbonate method for barium, 223 Carbonate method, 104 Carbonate method, 105 carbonates in oxidation in sas, 109 carbonates in outcome, 109 carbonates in outcome, 1225 in carbonates in oxidation in solution in oxidation procedures: gravinetric, dry combustion of carbonates in oxidation procedures: gravinetric, dry combustion method, 127 measurement of volume of volume of volume of volume of volume of volume of volume		
flame test, spectrum, 104 estimation, general procedures: gravimetric, oxalate method, 107 other methods, 108d volumetric, permanganate titration of the oxalate, 17d, 108 iodide method for, 108a estimation, special procedures: determination of, in composite white paints, 1190 in green paint pigments, 1196 in orange and yellow paint paints, 1195 in Portland cements as CaO (lime), 1216 in sand, 448 in water, 1424 in water as calcium sulphate, 1125 industrial application of methods, 104 occurrence, ores, univerals, etc., 104 precipitation from acetic acid solution, 108 preparation and solution of the sample, cennents, dolomites, limestone, mag- nesite, gypeum, plaster of Paris, silicates, sulphintes, sulphides, py- rites, salts, decomposition of re- fractory ores, 105, 106 rapid iodide method, 108a separation from aluminum, iron, copper, cobalt, nickel, manganese, zinc and members of the hydrogen sulphide group, 105 from silica, 105 solubilities, 104 traces, detection of, 104 Calcium caectate method for fluorine, 223 Calcium eachonate, rapid inethod for method, 108a separation from aluminum, iron, copper, cobalt, nickel, manganese, zinc and members of the hydrogen sulphide group, 105 from silica, 105 solubilities, 104 traces, detection of, 104 Calcium acetate method for fluorine, 223 Calcium carbonate, rapid inethod for method, 108a separation from aluminum, iron, copper, cobalt, nickel, manganese, zinc and members of the hydrogen sulphide group, 105 from silica, 105 solubilities, 104 traces, detection of, 104 Calcium acetate method for fluorine, 223 Calcium cobalt, nickel, manganese, zinc and members of the hydrogen sulphide group, 105 from silica, 105 solubilities, 104 traces, detection of, 104 Calcium phosphate, decomposition, 107 Calcium phosphate, decomposition, 107 Calcium phosphate, decomposition, 107 Calcium phosphate, decomposition, 107 Calcium phosphate, decomposition, 107 Calcium phosphate, decomposition, 107 Calcium code det. in presence of CaCO ₃ , 108a, 1804 Carbonate method for lauvine, 1220 fluorid	Calcium, detection of, general procedure,	708
estimation, general procedures: gravimetric, oxalate method, 107 other methods, 108d volumetric, permanganate titration of the oxalate, 17d, 108 iodide method for, 108a estimation, special procedures: determination of, in composite white paints, 1190 in green paint pigments, 1196 in orange and yellow paint pig- inents, 1195 in Portland cements as CaO (lime), 1216 in sand, 448 in water, 1424 in water as calcium sulphate, 1125 industrial application of methods, 104 occurrence, ores, unirerals, etc., 104 precipitation from acetic acid solution, 108 preparation and solution of the sample, cennents, dolomites, limestone, mag- nesite, gypeum, plaster of Paris, silicates, sulphiates, sulphides, py- rites, salts, decomposition of re- fractory ores, 105, 106 rapid iodide method, 108a separation from aluminum, iron, copper, cobult, inckel, manganese, zinc and members of the hydrogen sulphide group, 105 from alkalies, barium, magnesium, P ₂ O ₃ , 106 from silice, 105 solubilities, 104 traces, detection of, 104 Calcium acetate method for fluorine, 223 Calcium eactate method for fluorine, 226 Calcium cacetate method for fluorine, 222 fluoride, decomposition of, 215 method for fluorine, 216 Calcium oxide det. in presence of CaCO ₃ , 108a, 1804 Calcium phosphate, decomposition, 107 Calorie, definition of, 708 Calcium phosphate, decomposition, 107 Calcium phosphate, decomposition, 107 Calcium conductive process of the composition of, 215 method for fluorine, 216 Calcium conduction of, 215 method for fluorine, 216 Calcium conduction,		
other methods, 108d volumetric, permanganate titration of the oxalate, 174, 108 iodide method for, 108a estimation, special procedures: determination of, in composite white paints, 1190 in green paint pigments, 1196 in orange and yellow paint pigments, 1196 in orange and yellow paint pigments, 1196 in sand, 448 in water, 1424 in water as calcium sulphate, 1125 industrial application of methods, 104 occurrence, ores, minerals, etc., 104 precipitation from acetic acid solution, 108 preparation and solution of the sample, cenients, dolomites, limestone, magnesite, gypsum, plaster of Paris, silicates, sulphates, sulphides, pyrites, salts, decomposition of refractory ores, 105, 100 rapid iodide method, 108a separation from aluminum, iron, copper, cobalt, nickel, manganese, zine and members of the hydrogen sulphide group, 105 from alkalies, barium, strontium, magnesium, P ₂ O ₃ , 106 from silica, 105 solubilities, 104 traces, detection of, 104 Calcium acetate method for fluorine, 223 Calcium cachonate, rapid inethod for ductrine, 216 Calcium oxide det. in presence of CaCO ₃ , 108a, 1804 Calcium phosphate, decomposition, 107 Calorie, definition of, 708 Calcium cacho from calcium, 107 Calorie, definition of, 708 Calcium cacho from calcium, 107 Calorie, fefinition of, 708 Calcium cacho from calcium, 107 Calcium cacho from cacho f		
other methods, 108d volumetric, permanganate titration of the oxalate, 17d, 108 iodide method for, 108a estimation, special procedures: determination of, in composite white paints, 1190 in green paint pigments, 1196 in orange and yellow paint pigments, 1195 in Portland cements as CaO (lime), 1216 in sand, 448 in water, 1424 in water as calcium sulphate, 1125 industrial application of methods, 104 occurrence, ores, minerals, etc., 104 precipitation from acetic acid solution, 108 proparation and solution of the sample, cennents, dolomites, limestone, magnesite, gypsum, plaster of l'aris, silicates, sulphintes, sulphides, pyrites, salls, decomposition of refactory ores, 105, 106 rapid iodide method, 108a separation from aluminum, iron, copper, cobalt, nickel, manganese, zinc and members of the hydrogen sulphide group, 105 from alkalies, barium, atrontimn, magnesium, P ₂ O ₃ , 106 from silica, 105 solubilities, 104 traces, detection of, 104 Calcium acetate method for fluorine, 216 Calcium oxide det. in presence of CaCO ₃ , 108a, 1804 Calcium phosphate, decomposition, 107 Calorie, definition of, 708 Calorine, power of illuminating gas, 1257 of fuel, 1822 value of industrial gases, 1227 Calgrimeter, Emerson bomb (Fig. 105), for coal, B.t.u. det., 1025 Junker's for gas (Figs. 124, 125, 120), for coal, B.t.u. det., 1025 Junker's for gas (Figs. 124, 125, 120).		
volumetric, perinanganate titration of the oxalate, 17d, 108 iodide method for, 108a estimation, special procedures: determination of, in composite white paints, 1190 in green paint pigments, 1190 in orange and yellow paint pignents, 1190 in orange and yellow paint pignents, 1190 in orange and yellow paint pignents, 1250 in Portland cements as CaO (lime), 1210 in sand, 448 in water, 1424 in water as calcium sulphate, 1125 industrial application of methods, 104 occurrence, ores, nuinerals, etc., 104 precipitation from acetic acid solution, 108 preparation and solution of the sample, cements, dolomites, limestone, magnesite, gypsum, plaster of Paris, silicatos, sulphates, sulphides, pyrites, salts, decomposition of refractory ores, 105, 106 rapid iodide method, 108a separation from aluminum, iron, copper, cobalt, nickel, manganese, zinc and members of the hydrogen sulphide group, 105 from alkalies, barium, strontium, magnesium, PyOs, 106 from alkalies, barium, strontium, magnesium, PyOs, 106 from alkalies, barium, strontium, magnesium, PyOs, 106 from alkalies, barium, strontium, magnesium of, 104 Calcium eachonate, rapid method for fluorine, 216 Calcium oxide det. in presence of CaCOs, 108a, 1804 Calcium phosphate, decomposition, 107 Calorie, definition of, 708 Calcium phosphate, decomposition, 107 Calorie, definition of, 708 Calcium phosphate, decomposition, 107 Calorie, definition of, 708 Calcium phosphate, decomposition, 107 Calorie, definition of, 708 Calcium phosphate, decomposition, 107 Calorie, definition of, 708 Calcium phosphate, decomposition, 107 Calorie, definition of, 708 Calcium phosphate, decomposition, 107 Calorie, definition of, 708 Calcium phosphate, decomposition, 107 Calorie, definition of, 708 Calcium phosphate, see from the definition of, 708 Calcium phosphate, decomposition, 107 Calorie, definition of, 708 Calcium phosphate, decomposition, 107 Calorie, definition of, 708 Calcium phosphate, decomposition, 107 Calorie, definition of, 708 Calcium phosphate, decomposition, 107 Calorie, definiti		
of the oxalate, 17d, 108 iodide method for, 108a estimation, special procedures: determination of, in composite white paints, 1190 in green paint pigments, 1196 in orange and yellow paint pigments, 1195 in Portland cements as CaO (lime), 1216 in sand, 448 in water, 1424 in water as calcium sulphate, 1125 industrial application of methods, 104 occurrence, ores, uniperals, etc., 104 precipitation from acetic acid solution, 108 proparation and solution of the sample, cennents, dolomites, limestone, magnesite, gypseum, plaster of Paris, silicates, sulphates, sulphides, pyrites, salts, decomposition of refractory ores, 105, 100 rapid iodide method, 108a separation from alkalies, barium, strontium, magnesium, 190, 100 from alkalies, barium, strontium, magnesium, 190, 100 from alkalies, barium, strontium, magnesium, 190, 100 from alkalies, barium, strontium, magnesium, 190, 100 from deterfining, in cement, 1220 fluoride, decomposition of, 215 method for fluorine, 216 Calcium phosphate, decomposition, 107 Calorie, definition of, 708 Calcium phosphate, decomposition, 107 Calorie, definition of, 708 Calcium phosphate, from silloa, 105 total control of the sumple colories, 109 carbonates, 1		
iodide method for, 108a estimation, special procedures: determination of, in composite white paints, 1190 in green paint pigments, 1190 in orange and yellow paint pignents, 1190 in orange and yellow paint pignents, 1196 in orange and yellow paint pignents, 1196 in orange and yellow paint pignents, 1196 in sand, 448 in water, 1424 in water as calcium sulphate, 1125 industrial application of methods, 104 occurrence, ores, uninerals, etc., 104 precipitation from acetic acid solution, 108 preparation and solution of the sample, cements, dolomites, limestone, magnesite, gypsum, plaster of Paris, silicates, sulphates, sulphides, pyrites, salts, decomposition of refractory ores, 105, 106 repdi iodide method, 108a separation from aluminum, iron, copper, cobalt, nickel, manganese, zinc and members of the hydrogen sulphide group, 105 from alkalies, barium, strontinun, magnesium, PyOs, 106 from silica, 105 solubilities, 104 traces, detection of, 104 Calcium earbonate, rapid method for determining, in cement, 1220 fluoride, decomposition, 107 Calorie, definition of, 708 Calorific power of illuminating gas, 1257 of fuel, 1622 value of industrial gases, 1227 Calerimeter, Emerson bomb (Fig. 105), for coal, B.t.u. det., 1625 Junker's for gas (Figs. 124, 125, 120), and the procedures in ores, 87, 101, 109, 110, 121, 223, 247, 350 determination in soap, 1605 carbon bisulphide. See Carbon Disul-		
estimation, special procedures: determination of, in composite white paints, 1190 in green paint pigments, 1196 in orange and yellow paint pigments, 1195 in Portland cements as Ca() (lime), 1210 in sand, 448 in water, 1424 in water as calcium sulphate, 1125 industrial application of methods, 104 occurrence, ores, uninerals, etc., 104 precipitation from acetic acid solution, 108 preparation and solution of the sample, cennents, dolomites, limestone, ungnesite, gypsum, plaster of Paris, silicates, sulphates, sulphides, pyrites, salts, decomposition of refractory ores, 105, 106 rapid iodide method, 108a separation from aluminum, iron, copper, cobalt, nickel, manganese, zinc and members of the hydrogen sulphide group, 105 from alkalies, barium, strontium, magnesium, PyOs, 106 ferom silica, 105 solubilities, 104 traces, detection of, 104 Calcium acetate method for fluorine, 223 Carbonic acid, feet. of, 1549, 1730 Carbonic acid, det. of, 1549, 1730 carbonates, 109 earbonates, 109 earbonates, 109 earbonates, 109 carbonates, 109 carbonates in oresembned, 109 carbonates in ore cald in water, 109 earbon monoxide in blood, 109 earbonates, 109 carbonates, 109 carbonates, 109 carbonates in ore cald in water, 109 earbon monoxide in blood, 109 catination, general procedures: gravimetric, dry combustion method, weighing CO ₂ , 111, 118 wet oxidation process, weighing CO ₃ , 111, 120 volumetric, barium hydroxide method, 127 measurement of volume of CO ₂ in black pigments, 1196 in coal as "fixed carbon," 1622, 1646 in coal as "fixed carb		Carbenes, 1318
determination of, in composite white paints, 1190 in green paint pigments, 1196 in orange and yellow paint pigments, 1195 in Portland cements as CaO (lime), 1216 in sand, 448 in water, 1424 in water as calcium sulphate, 1125 industrial application of methods, 104 occurrence, ores, minerals, etc., 104 precipitation from acetic acid solution, 108 preparation and solution of the sample, cements, dolomites, limestone, magnesite, gypsum, plaster of Paris, silicates, sulphates, sulphides, pyrites, salts, decomposition of refractory ores, 105, 106 rapid iodide method, 108a separation from aluminum, iron, copper, cobalt, nickel, manganese, zinc and members of the hydrogen sulphide group, 105 from alkalies, barium, strontium, magnesium, P ₂ O ₃ , 106 from silica, 105 solubilities, 104 traces, detection of, 104 Calcium carde det. in presence of CaCO ₃ , 108a, 1804 Calcium oxide det. in presence of CaCO ₃ , 109 carbonate acid, det. of, 1549, 1730 carbonate acid,		Carbide of silicon, decomposition of, 435
in green paint pigments, 1196 in orange and yellow paint pignents, 1195 in Portland cements as CaO (lime), 1216 in sand, 448 in water, 1424 in water as calcium sulphate, 1125 industrial application of methods, 104 occurrence, ores, minerals, etc., 104 precipitation from acetic acid solution, 108 preparation and solution of the sample, cements, dolomites, limestone, magnesite, gypsum, plaster of Parts, silicates, sulphates, sulphides, pyrites, salts, decomposition of refractory ores, 105, 100 rapid iodide method, 108a separation from aluminum, iron, copper, cobalt, nickel, manganese, zinc and members of the hydrogen sulphide group, 105 from silica, 105 solubilities, 104 traces, detection of, 104 Calcium carbonate, rapid method for determining, in cement, 1220 fluoride, decomposition, 107 Calcine, definition of, 708 Calcium oxide det. in presence of CaCO ₃ , 108a, 1804 Calcium phosphate, decomposition, 107 Calorie, definition of, 708 Calorific power of illuminating gos, 1257 of fuel, 1622 value of industrial gases, 1227 Calcrimeter, Emerson bomb (Fig. 10.5), for coal, B.t.u. det., 1825 Junker's for gas (Figs. 124, 125, 120),		Carbonie acid, free, dct. of, 1549
in orange and yellow paint pignents. Incuts, 1195 in Portland cements as Ca() (lime), 1216 in sand, 448 in water, 1424 in water as calcium sulphate, 1125 industrial application of methods, 104 occurrence, ores, minerals, etc., 104 precipitation from acetic acid solution, 108 preparation and solution of the sample, cements, dolomites, limestone, magnesite, gypsum, plaster of Paris, silicates, sulphates, sulphides, pyrites, salts, decomposition of refractory ores, 105, 100 rapid iodide method, 108a separation from aluminum, iron, copper, cobalt, nickel, manganese, zinc and members of the hydrogen sulphide group, 105 from alkalies, barium, strontinn, magnesium, P ₂ O ₃ , 106 from silica, 105 solubilities, 104 traces, detection of, 104 Calcium acetate method for fluorine, 216 Calcium earbonate, rapid inethod for determining, in cement, 1220 fluoride, decomposition of, 215 method for fluorine, 216 Calcium cated the time presence of CaCO ₃ , 108a, 1804 Calcium phosphate, decomposition, 107 Calcrie, definition of, 708 Calorific power of illuminating gas, 1257 of fuel, 1622 value of industrial gases, 1227 Calsrimeter, Emerson bomb (Fig. 105), for coal, B.t.u. det., 1625 Junker's for gas (Figs. 124, 125, 126),	paints, 1190	indicators, 1252
in Portland cements as CaO (lime), 1216 in sand, 448 in water, 1424 in water as calcium sulphate, 1125 industrial application of methods, 104 occurrence, ores, unerals, etc., 104 precipitation from acetic acid solution, 108 preparation and solution of the sample, cements, dolomites, limestone, magnesite, gypsum, plaster of Paris, silicates, sulphates,	in green paint pigments, 1196	Carbonic acid, det. of, 1549, 1730
in Portland cements as CaO (lime), 1216 in sand, 448 in water, 1424 in water as calcium sulphate, 1125 industrial application of methods, 104 occurrence, ores, minerals, etc., 104 precipitation from acetic acid solution, 108 preparation and solution of the sample, cements, dolomites, limestone, magnesite, gypsum, plaster of Paris, silicates, sulphates, sulphates, pyrites, salts, decomposition of refractory ores, 105, 106 rapid iodide method, 108a separation from aluminum, iron, copper, cobult, nickel, manganese, zinc and members of the hydrogen sulphide group, 105 from alkalies, barium, strontium, magnesium, P ₂ O ₃ , 106 from silica, 105 solubilities, 104 traces, detection of, 104 Calcium carbonate, rapid method for determining, in cement, 1220 fluoride, decomposition of, 215 method for fluorine, 216 Calcium oxide det. in presence of CaCO ₃ , 108a, 1804 Calcium phosphate, decomposition, 107 Calorie, definition of, 708 Calorific power of illuminating gas, 1257 of fuel, 1622 value of industrial gases, 1227 Calerimeter, Emerson bomb (Fig. 10.5), for coal, B.t.u. det., 1625 Junker's for gas (Figs. 124, 125, 126),	in orange and yellow paint pig-	
in water, 1424 in water as calcium sulphate, 1125 industrial application of methods, 104 occurrence, ores, uninerals, etc., 104 precipitation from acetic acid solution, 108 preparation and solution of the sample, cements, dolomites, limestone, magnesite, gypsum, plaster of l'aris, silicates, sulphates, sulphides, pyrites, salts, decomposition of refractory ores, 105, 106 rapid iodide method, 108a separation from aluminum, iron, copper, cobalt, nickel, manganese, zinc and members of the hydrogen sulphide group, 105 from alkalies, barium, strontium, magnesium, P ₂ O ₃ , 106 from silica, 105 solubilities, 104 traces, detection of, 104 Calcium acetate method for fluorine, 223 Calcium carbonate, rapid method for determining, in cement, 1220 fluoride, decomposition of, 215 method for fluorine, 216 Calcium phosphate, decomposition, 107 Calcium, phosphate, decomposition, 107 Calcium, definition of, 708 Calcium phosphate, decomposition, 107 Calcium, definition of, 708 Calcium candonate, rapid method, for function, 215 of fuel, 1622 value of industrial gases, 1227 Calsrimeter, Emerson bomb (Fig. 10.5), for coal, B.t.u. det., 1625 Junker's for gas (Figs. 124, 125, 126),		
in sand, 448 in water, 1424 in water as calcium sulphate, 1125 industrial application of methods, 104 occurrence, ores, minerals, etc., 104 precipitation from acetic acid solution, 108 preparation and solution of the sample, cenients, dolomites, limestone, magnesite, gypsum, plaster of l'aris, silicates, sulphates, pyrites, salts, decomposition of refractory ores, 105, 100 rapid iodide method, 108a separation from aluminum, iron, copper, cobult, nickel, manganese, zinc and members of the hydrogen sulphate group, 105 from alkalies, barium, strontium, magnesium, P ₂ O ₃ , 106 from silkia, 105 solubilities, 104 traces, detection of, 104 Calcium acetate method for fluorine, 223 Calcium earbonate, rapid method for determining, in cement, 1220 fluoride, decomposition of, 215 method for fluorine, 216 Calcium oxide det. in presence of CaCO ₃ , 108a, 1804 Calcium phosphate, decomposition, 107 Calorie, definition of, 708 Calorific power of illuminating gas, 1257 of fuel, 1622 value of industrial gases, 1227 Calgrimeter, Emerson bomb (Fig. 10.5), for coal, B.t.u. det., 1625 Junker's for gas (Figs. 124, 125, 126),		
in water, 1424 in water as calcium sulphate, 1125 industrial application of methods, 104 occurrence, ores, uninerals, etc., 104 precipitation from acetic acid solution, 108 preparation and solution of the sample, cennents, dolomites, limestone, magnesite, gypsum, plaster of 1 raris, silicates, sulphates, sulphides, pyrites, salts, decomposition of refractory ores, 105, 106 rapid iodide method, 108a separation from aluminum, iron, copper, cobalt, nickel, manganese, zinc and members of the hydrogen sulphide group, 105 from alkalies, barium, strontium, magnesium, P ₂ O ₃ , 106 from silica, 104 traces, detection of, 104 Calcium acetate method for fluorine, 223 Calcium earbonate, rapid method for determining, in cement, 1220 fluoride, decomposition of, 215 method for fluorine, 216 Calcium oxide det. in presence of CaCO ₃ , 108a, 1804 Calcium phosphate, decomposition, 107 Calcium for fluorine, 216 Calcium for fluorine, 217 of fuel, 1622 value of industrial gases, 1227 Calorineter, Emerson bomb (Fig. 10.5), for coal, B.t.u. det., 1625 Junker's for gas (Figs. 124, 125, 126),		
industrial application of methods, 104 occurrence, ores, minerals, etc., 104 precipitation from acetic acid solution, 108 preparation and solution of the sample, cements, dolomites, limestone, magnesite, gypsum, plaster of Paris, silicates, sulphates, sulphides, pyrites, salts, decomposition of refactory ores, 105, 106 rapid iodide method, 108a separation from aluminum, iron, copper, cobalt, nickel, manganese, zinc and members of the hydrogen sulphide group, 105 from alkalies, barium, strontium, magnesium, P ₄ O ₅ , 106 from silica, 105 solubilities, 104 traces, detection of, 104 Calcium acetate method for fluorine, 216 Calcium earbonate, rapid method for determining in cement, 1220 fluoride, decomposition of, 215 method for fluorine, 216 Calcium oxide det. in presence of CaCO ₃ , 108a, 1804 Calcium phosphate, decomposition, 107 Calorie, definition of, 708 Calorific power of illuminating gas, 1257 of fuel, 1622 value of industrial gases, 1227 Calgrimeter, Emerson bomb (Fig. 105), for coal, B.t.u. det., 1625 Junker's for gas (Figs. 124, 125, 126),		
occurrence, ores, nuinerals, etc., 104 precipitation from acetic acid solution, 108 preparation and solution of the sample, cenients, dolonites, limestone, magnesite, gypsum, plaster of Paris, silicates, sulplates, sulphides, pyrites, salts, decomposition of refractory ores, 105, 106 rapid iodide method, 108a separation from aluminum, iron, copper, cobalt, nickel, manganese, zinc and members of the hydrogen sulphide group, 105 from alkalies, barium, strontinm, magnesium, P ₂ O ₃ , 106 from silica, 105 solubilities, 104 Calcium carbonate, rapid inethod for determining, in cement, 1220 fluoride, decomposition of, 215 method for fluorine, 216 Calcium oxide det. in presence of CaCO ₃ , 108a, 1804 Calcium phosphate, decomposition, 107 Calorie, definition of, 708 Calorific power of illuminating gas, 1257 of fuel, 1622 value of industrial gases, 1227 Calgrimeter, Emerson bomb (Fig. 105), for coal, B.t.u. det., 1625 Junker's for gas (Figs. 124, 125, 126),		gravimetrie, dry combustion method,
precipitation from acetic acid solution, 108 preparation and solution of the sample, cements, dolomites, limestone, magnesite, gypsum, plaster of l'aris, silicates, sulphates, sulphides, pyrites, salta, decomposition of refractory ores, 105, 106 rapid iodide method, 108a separation from aluminum, iron, copper, cobalt, nickel, manganese, zinc and members of the hydrogen sulphide group, 105 from alkalies, barium, strontium, magnesium, P ₂ O ₃ , 106 from silica, 105 solubilities, 104 traces, detection of, 104 Calcium acetate method for fluorine, 223 Calcium carbonate, rapid method for determining, in cement, 1220 fluoride, decomposition of, 215 method for fluorine, 216 Calcium phosphate, decomposition, 107 Calorie, definition of, 708 Calorific power of illuminating gas, 1257 of fuel, 1622 value of industrial gases, 1227 Calciumeter, Emerson bomb (Fig. 105), for coal, B.t.u. det., 1625 Junker's for gas (Figs. 124, 125, 126),		weighing CO ₂ , 111, 118
preparation and solution of the sample, cenients, dolomites, limestone, magnesite, gypsum, plaster of Paris, silicates, sulphates, sulphates, pyrites, salts, decomposition of refractory ores, 105, 106 rapid iodide method, 108a separation from aluminum, iron, copper, cobalt, nickel, manganese, zine and members of the hydrogen sulphide group, 105 from alkalies, barium, strontium, magnesium, Pros, 106 from silica, 105 solubilities, 104 traces, detection of, 104 Calcium acetate method for fluorine, 223 Calcium carbonate, rapid method for determining, in cement, 1220 fluoride, decomposition of, 215 method for fluorine, 216 Calcium phosphate, decomposition, 107 Calorie, definition of, 708 Calorie power of illuminating gas, 1257 of fuel, 1622 value of industrial gases, 1227 Calciumeter, Emerson bomb (Fig. 105), for coal, B.t.u. det., 1625 Junker's for gas (Figs. 124, 125, 126),	occurrence, ores, influerals, etc., 104	wet exidation process, weighing
preparation and solution of the sample, cenients, dolomites, limestone, magnesite, gypsum, plaster of Paris, silicates, sulphates, sulphates, pyrites, salts, decomposition of refractory ores, 105, 106 rapid iodide method, 108a separation from aluminum, iron, copper, cobalt, nickel, manganese, zine and members of the hydrogen sulphide group, 105 from alkalies, barium, strontium, magnesium, Pros, 106 from silica, 105 solubilities, 104 traces, detection of, 104 Calcium acetate method for fluorine, 223 Calcium carbonate, rapid method for determining, in cement, 1220 fluoride, decomposition of, 215 method for fluorine, 216 Calcium phosphate, decomposition, 107 Calorie, definition of, 708 Calorie power of illuminating gas, 1257 of fuel, 1622 value of industrial gases, 1227 Calciumeter, Emerson bomb (Fig. 105), for coal, B.t.u. det., 1625 Junker's for gas (Figs. 124, 125, 126),		volumetrie berum hydroxide meth-
cennents, dolomites, limestone, magnesie, gypsum, plaster of l'aris, silicates, sulplates sulplates, pyrites, salta, decomposition of refractory ores, 105, 106 rapid iodide method, 108a separation from aluminum, iron, copper, cobalt, nickel, manganese, zinc and members of the hydrogen sulphide group, 105 from alkalies, barium, strontinm, magnesium, P ₂ O ₃ , 106 from silica, 105 solubilities, 104 traces, detection of, 104 Calcium acetate method for fluorine, 223 Calcium carbonate, rapid method for determining, in cement, 1220 fluoride, decomposition of, 215 method for fluorine, 216 Calcium phosphate, decomposition, 107 Calorie, definition of, 708 Calorie, definition of, 708 Calorine power of illuminating gas, 1257 of fuel, 1622 value of industrial gases, 1227 Calciumeter, Emerson bomb (Fig. 105), for coal, B.t.u. det., 1625 Junker's for gas (Figs. 124, 125, 126),		od. titration of earbonate formed.
nesite, gypsum, plaster of Paris, silicates, sulphides, pyrites, salta, decomposition of refractory ores, 105, 106 rapid iodide method, 108a separation from aluminum, iron, copper, cobalt, nickel, manganese, zine and members of the hydrogen sulphide group, 105 from alkalies, barium, strontinn, magnesium, P ₂ O ₃ , 106 from silica, 105 solubilities, 104 traces, detection of, 104 Calcium acetate method for fluorine, 223 Calcium carbonate, rapid inethod for determining, in cement, 1220 fluoride, decomposition of, 215 method for fluorine, 216 Calcium phosphate, decomposition, 107 Calorie, definition of, 708 Calorific power of illuminating gas, 1257 of fuel, 1622 value of industrial gases, 1227 Calciumeter, Emerson bomb (Fig. 105), for coal, B.t.u. det., 1625 Junker's for gas (Figs. 124, 125, 126),		
silicates, sulplintes, sulplintes, pyrites, salts, decomposition of refractory ores, 105, 106 rapid iodide method, 108a separation from aluminum, iron, copper, cobalt, nickel, manganese, zine and members of the hydrogen sulphide group, 105 from alkalies, barium, strontium, magnesium, P ₁ O ₃ , 106 from silica, 105 solubilities, 104 traces, detection of, 104 Calcium carbonate, rapid method for determining, in cement, 1220 fluoride, decomposition of, 215 method for fluorine, 216 Calcium oxide det. in presence of CaCO ₃ , 108a, 1804 Calcium phosphate, decomposition, 107 Calorie, definition of, 708 Calorific power of illuminating gas, 1257 of fuel, 1622 value of industrial gases, 1227 Calerimeter, Emerson bomb (Fig. 105), for coal, B.t.u. det., 1625 Junker's for gas (Figs. 124, 125, 126),		measurement of volume of CO2
fractory ores, 105, 106 rapid iodide method, 108a separation from aluminum, iron, copper, cobalt, nickel, manganese, zinc and members of the hydrogen sulphide group, 105 from alkalies, barium, strontium, magnesium, P ₄ O ₃ , 106 from silica, 105 solubilities, 104 traces, detection of, 104 Calcium acetate method for fluorine, 223 Calcium carbonate, rapid inethod for determining, in cement, 1220 fluoride, decomposition of, 215 method for fluorine, 216 Calcium phosphate, decomposition, 107 Calorie, definition of, 708 Calorific power of illuminating gas, 1257 of fuel, 1622 value of industrial gases, 1227 Calciumeter, Emerson bomb (Fig. 105), for coal, B.t.u. det., 1625 Junker's for gas (Figs. 124, 125, 126),	silicates, sulphates, sulphides, py-	
rapid iodide method, 108a separation from aluminum, iron, copper, cobalt, nickel, manganese, zine and members of the hydrogen sulphide group, 105 from alkalies, barium, strontinn, magnesium, P ₂ O ₃ , 106 from silica, 105 solubilities, 104 traces, detection of, 104 Calcium acetate method for fluorine, 223 Calcium carbonate, rapid method for determining, in cement, 1220 fluoride, decomposition of, 215 method for fluorine, 216 Calcium phosphate, decomposition, 107 Calcium phosphate, de		
separation from aluminum, iron, copper, cobalt, nickel, manganese, zinc and members of the hydrogen sulphide group, 105 from alkalies, barium, strontinin, magnesium, PrOs, 106 from silica, 105 solubilities, 104 traces, detection of, 104 Calcium acetate method for fluorine, 223 Calcium carbonate, rapid method for determining, in cement, 1220 fluoride, decomposition of, 215 method for fluorine, 216 Calcium phosphate, decomposition, 107 Calorie, definition of, 708 Calcium phosphate, decomposition, 107 Calorie, definition of, 708 Calorific power of illuminating gas, 1257 of fuel, 1622 value of industrial gases, 1227 Calcium for oad, B.t.u. det., 1625 Junker's for gas (Figs. 124, 125, 126),		
cobalt, nickel, manganese, zine and members of the hydrogen sulphide group, 105 from alkalies, barium, strontinin, magnesium, P ₁ O ₃ , 106 from silica, 105 solubilities, 104 traces, detection of, 104 Calcium carbonate, rapid method for determining, in cement, 1220 fluoride, decomposition of, 215 method for fluorine, 216 Calcium phosphate, decomposition, 107 Calcium phosphate, decomposition of, 215 method for fluorine, 216 Carbonate method for barium, 63b Carbonate method for calcium, 108d Carbonates in orea, 57, 101, 109, 110, 121, 223, 247, 350 determination of, 1549 Carbonates in orea, 57, 101, 109, 110, 121, 223, 247, 350 determination of, in presence of other combined acids, 514 determination in soap, 1605 Carbon bisulphide. See Carbon Disul-		in coal as "fixed carlyon" 1629 1646
members of the hydrogen sulphide group, 105 from alkalies, barium, strontium, magnesium, P ₂ O ₃ , 106 from silica, 105 solubilities, 104 traces, detection of, 104 Calcium acetate method for fluorine, 223 Calcium carbonate, rapid method for determining, in cement, 1220 fluoride, decomposition of, 215 method for fluorine, 216 Calcium phosphate, decomposition, 107 Calorie, definition of, 708 Calorific power of illuminating gas, 1257 of fuel, 1622 value of industrial gases, 1227 Calciumeter, Emerson bomb (Fig. 105), for coal, B.t.u. det., 1625 Junker's for gas (Figs. 124, 125, 126),		in coal tar pitch, 1358
from alkales, barium, strontinin, magnesium, P ₂ O ₃ , 106 from silica, 105 solubilities, 104 traces, detection of, 104 Calcium carbonate, rapid inethod for determining, in cement, 1220 fluoride, decomposition of, 215 method for fluorine, 216 Calcium oxide det. in presence of CaCO ₃ , 108a, 1804 Calcium phosphate, decomposition, 107 Calorie, definition of, 708 Calorific power of illuminating gas, 1257 of fuel, 1622 value of industrial gases, 1227 Calorimeter, Emerson bomb (Fig. 105), for coal, B.t.u. det., 1625 Junker's for gas (Figs. 124, 125, 126),		in iron and steel, 115-117, 128, 130,
from alkales, barium, strontinin, magnesium, P ₂ O ₃ , 106 from silica, 105 solubilities, 104 traces, detection of, 104 Calcium carbonate, rapid inethod for determining, in cement, 1220 fluoride, decomposition of, 215 method for fluorine, 216 Calcium oxide det. in presence of CaCO ₃ , 108a, 1804 Calcium phosphate, decomposition, 107 Calorie, definition of, 708 Calorific power of illuminating gas, 1257 of fuel, 1622 value of industrial gases, 1227 Calorimeter, Emerson bomb (Fig. 105), for coal, B.t.u. det., 1625 Junker's for gas (Figs. 124, 125, 126),		263, 265, 1352, 1354, 1356
from silica, 105 solubilities, 104 traces, detection of, 104 Calcium acetate method for fluorine, 223 Calcium carbonate, rapid method for determining, in cement, 1220 fluoride, decomposition of, 215 method for fluorine, 216 Calcium oxide det. in presence of CaCO ₃ , 108a, 1804 Calcium phosphate, decomposition, 107 Calorie, definition of, 708 Calorific power of illuminating gas, 1257 of fuel, 1622 value of industrial gases, 1227 Calerimeter, Emerson bomb (Fig. 105), for coal, B.t.u. det., 1625 Junker's for gas (Figs. 124, 125, 126),	from alkalies, barium, strontium,	colorimetric method, 128
solubilities, 104 traces, detection of, 104 Calcium acetate method for fluorine, 223 Calcium carbonate, rapid method for determining, in cement, 1220 fluoride, decomposition of, 215 method for fluorine, 216 Calcium oxide det. in presence of CaCO ₃ , 108a, 1804 Calcium phosphate, decomposition, 107 Calorie, definition of, 708 Calorific power of illuminating gas, 1257 of fuel, 1622 value of industrial gases, 1227 Calorimeter, Emerson bomb (Fig. 105), for coal, B.t.u. det., 1625 Junker's for gas (Figs. 124, 125, 126),		
traces, detection of, 104 Calcium acetate method for fluorine, 223 Calcium carbonate, rapid method for determining, in cement, 1220 fluoride, decomposition of, 215 method for fluorine, 216 Calcium oxide det. in presence of CaCO ₃ , 108a, 1804 Calcium phosphate, decomposition, 107 Calorie, definition of, 708 Calorie power of illuminating gas, 1257 of fuel, 1622 value of industrial gases, 1227 Calcrimeter, Emerson bomb (Fig. 105), for coal, B.t.u. det., 1625 Junker's for gas (Figs. 124, 125, 126),		
Calcium acetate method for fluorine, 223 Calcium carbonate, rapid method for determining, in cement, 1220 fluoride, decomposition of, 215 method for fluorine, 216 Calcium oxide det. in presence of CaCO ₃ , 108a, 1804 Calcium phosphate, decomposition, 107 Calorie, definition of, 708 Calorific power of illuminating gas, 1257 of fuel, 1622 value of industrial gases, 1227 Calcrimeter, Emerson bomb (Fig. 105), for coal, B.t.u. det., 1625 Junker's for gas (Figs. 124, 125, 126),		
Calcium carbonate, rapid method for determining, in cement, 1220 fluoride, decomposition of, 215 method for fluorine, 216 calcium oxide det. in presence of CaCO ₃ , 108a, 1804 calcium phosphate, decomposition, 107 calorie, definition of, 708 calorific power of illuminating gas, 1257 of fuel, 1622 value of industrial gases, 1227 calorimeter, Emerson bomb (Fig. 105), for coal, B.t.u. det., 1625 Junker's for gas (Figs. 124, 125, 126),		
determining, in cement, 1220 fluoride, decomposition of, 215 method for fluorine, 216 Calcium oxide det. in presence of CaCO ₃ , 108a, 1804 Calcium phosphate, decomposition, 107 Calorie, definition of, 708 Calorific power of illuminating gas, 1257 of fuel, 1622 value of industrial gases, 1227 Calorimeter, Emerson bomb (Fig. 105), for coal, B.t.u. det., 1625 Junker's for gas (Figs. 124, 125, 126),	Calcium carbonate, rapid method for	
fluoride, decomposition of, 215 method for fluorine, 216 Calcium oxide det. in presence of CaCO ₃ , 108a, 1804 Calcium phosphate, decomposition, 107 Calorie, definition of, 708 Calorific power of illuminating gas, 1257 of fuel, 1622 value of industrial gases, 1227 Calorimeter, Emerson bomb (Fig. 105), for coal, B.t.u. det., 1625 Junker's for gas (Figs. 124, 125, 126),	determining, in cement, 1220	
Calcium oxide dct. in presence of CaCO ₃ , 108a, 1804 Calcium phosphate, decomposition, 107 Calorie, definition of, 708 Calorific power of illuminating gas, 1257 of fuel, 1622 value of industrial gases, 1227 Calorimeter, Emerson bomb (Fig. 105), for coal, B.t.u. dct., 1625 Junker's for gas (Figs. 124, 125, 126),	fluoride, decomposition of, 215	
108a, 1804 Calcium phosphate, decomposition, 107 Calorie, definition of, 708 Calorific power of illuminating gas, 1257 of fuel, 1622 value of industrial gases, 1227 Calcrimeter, Emerson bomb (Fig. 105), for coal, B.t.u. det., 1625 Junker's for gas (Figs. 124, 125, 126),		
Calcium phosphate, decomposition, 107 Calorie, definition of, 708 Calorie, definition of, 708 Carbonate method for calcium, 108d Carbonate, titration of, 1549 Carbonate in orea, 57, 101, 109, 110, 121, 223, 247, 350 determination of, in presence of other combined acids, 514 determination in soap, 1605 Junker's for gas (Figs. 124, 125, 126), Carbonate method for calcium, 108d Carbonate method for calcium, 108d Carbonate method for calcium, 108d Carbonate method for calcium, 108d Carbonate method for calcium, 108d Carbonate method for calcium, 108d Carbonate method for calcium, 108d Carbonate method for calcium, 108d Carbonate method for calcium, 108d Carbonate method for calcium, 108d Carbonate method for calcium, 108d Carbonate, titration of, 1549 Carbonate, itration of, 1549 Carbonate method for calcium, 108d		
Calorie, definition of, 708 Calorific power of illuminating gas, 1257 of fuel, 1622 value of industrial gases, 1227 Calorimeter, Emerson bomb (Fig. 105), for coal, B.t.u. det., 1625 Junker's for gas (Figs. 124, 125, 126),		
Calorific power of illuminating gas, 1257 of fuel, 1622 value of industrial gases, 1227 Calorimeter, Emerson bomb (Fig. 105), for coal, B.t.u. det., 1625 Junker's for gas (Figs. 124, 125, 126),	Calorie, definition of, 708	
of fuel, 1622 value of industrial gases, 1227 Calorimeter, Emerson bomb (Fig. 105), for coal, B.t.u. det., 1625 Junker's for gas (Figs. 124, 125, 126), Carbon bisulphide. See Carbon Disul-	Calorific power of illuminating gas, 1257	Carbonates in ores, 57, 101, 109, 110, 121,
Calerimeter, Emerson bomb (Fig. 105), for coal, B.t.u. det., 1625 Junker's for gas (Figs. 124, 125, 126), Carbon bisulphide. See Carbon Disul-	of fuel, 1622	223, 247, 350
for coal, B.t.u. det., 1625 determination in soap, 1605 Junker's for gas (Figs. 124, 125, 120), Carbon bisulphide. See Carbon Disul-		actermination of, in presence of other
Junker's for gas (Figs. 124, 125, 126), Carbon bisulphide. See Carbon Disul-		
1257, 1258 phide.	Junker's for gas (Figs. 124, 125, 126).	
	1257, 1258	phide.

Carbon dioxide combined as carbonate:	Cement, gang mold (Fig. 105), 1212
	Gilmore needles (Fig. 103), 1211
estimation, general procedures for	
determination, 121	Le Chatelier's specific gravity appa-
gravimetric determination in ear-	ratus (Fig. 93), 1205
bonates, 121	Richlé automatic cement testing ma-
loss of weight method, 124	ehine (Fig. 107), 1215
hydrometric method, 125	Vicat needle (Fig. 94), 1207
	caleium in, 105
volumetric, measuring the gas evolved, 123	carbon dioxide in, 110
estimation, special procedures:	fineness, 1205
in alloys, 1102, 1106g, 1106i	mixing, 1206 normal consistency, determination of,
in ammoniacal gas liquors, 344	normal consistency, determination of,
in baking powder	1206
available CO2, 124	physical testing, 1202
residual CO ₂ , 123	Portland cement, analysis of, 1216
in barium ores, 67	determination of alkalies, alumina,
in blanc fixe, 1189	iron, insoluble residue, lime, loss
in cement, 84	on ignition, magnesia, sinca, sulphir, 1216–1219
in composite white paint, 1190	sulphit, 1210-1219
in corroded white lead, 1181	rapid method of analysis, 1220
in gypsum, 1188	sampling, 1204
in soap, 1605	setting time, 1210
in zine, 1183	specifications, 1202–1214
free in gaseous mixtures, 338, 1242,	specific gravity, 1204
1244, 1248, 1262	tension test, 1212
	Cements in bituminous sub., 1346
properties of, 1227b	Cement, rock, analysis of (limestone, line,
Carbon disalphide, bromine detection	Dogovalala assent ata \ 1992
with, 92	Rosendalc eement, etc.), 1223
iodine determination with, 242	table of composition, 1225
purification of (see Fig. 7), 75	Cerium, detection of, spectroscopic test,
monoxide in air, 1740	133, 133b
in blood, detection of, 109, 1741	estimation, gravimetrie methods, 134, 136
in blood, detection of, 109, 1741 in gaseous mixtures, determination	estimation, gravimetrie methods, 134, 136
in blood, detection of, 109, 1741 in gaseous mixtures, determination of, 1085	estimation, gravimetric methods, 134, 136 volumetric method, 136
in blood, detection of, 109, 1741 in gaseous mixtures, determination of, 1085 in illuminating gas, determination of,	estimation, gravimetrie methods, 134, 136 volumetric method, 136 estimation of cerium, 136
in blood, detection of, 109, 1741 in gaseous mixtures, determination of, 1085 in illuminating gas, determination of, 1248	estimation, gravimetric methods, 134, 136 volumetric method, 136 estimation of cerium, 136 in presence of rare curths, 136, 137
in blood, detection of, 109, 1741 in gaseous mixtures, determination of, 1085 in illuminating gas, determination of, 1248 properties of, 1227d	estimation, gravimetrie methods, 134, 136 volumetric method, 136 estimation of cerium, 136 in presence of rare curths, 136, 137 in thoria, thorium nitrate, etc., 138
in blood, detection of, 109, 1741 in gaseous mixtures, determination of, 1085 in illuminating gas, determination of, 1248 properties of, 1227d tetrachloride, bromine test with, 92	estimation, gravimetric methods, 134, 136 volumetric method, 136 estimation of cerium, 136 in presence of rare eurths, 136, 137 in thoria, thorium nitrate, etc., 138 industrial application, 133
in blood, detection of, 109, 1741 in gaseous mixtures, determination of, 1085 in illuminating gas, determination of, 1248 properties of, 1227d tetrachloride, bromine test with, 92 tubes, for colorimetric determination of	estimation, gravimetrie methods, 134, 136 volumetric method, 136 estimation of cerium, 136 in presence of rare curths, 136, 137 in thoria, thorium nitrate, etc., 138 industrial application, 133 occurrence and properties, 133
in blood, detection of, 109, 1741 in gaseous mixtures, determination of, 1085 in illuminating gas, determination of, 1248 properties of, 1227d tetrachloride, bromine test with, 92 tubes, for colorimetric determination of	estimation, gravimetrie methods, 134, 136 volumetric method, 136 estimation of cerium, 136 in presence of rare earths, 136, 137 in thoria, thorium nitrate, etc., 138 industrial application, 133 accurrence and properties, 133 preparation of the sample, 133
in blood, detection of, 109, 1741 in gaseous mixtures, determination of, 1085 in illuminating gas, determination of, 1248 properties of, 1227d tetrachloride, bromine test with, 92 tubes, for colorimetric determination of	estimation, gravimetrie methods, 134, 136 volumetric method, 136 estimation of cerium, 136 in presence of rare curths, 136, 137 in thoria, thorium nitrate, etc., 138 industrial application, 133 uccurrence and properties, 133 preparation of the sample, 133 fusion method, 136
in blood, detection of, 109, 1741 in gaseous mixtures, determination of, 1085 in illuminating gas, determination of, 1248 properties of, 1227d tetrachloride, bromine test with, 92 tubes, for colorimetric determination of carbon in steel (Fig. 25), 129 Carbonate in hicarbonate, 1553	estimation, gravimetrie methods, 134, 136 volumetric method, 136 estimation of cerium, 136 in presence of rare curths, 136, 137 in thoria, thorium nitrate, etc., 138 industrial application, 133 uccurrence and properties, 133 preparation of the sample, 133 fusion method, 136
in blood, detection of, 109, 1741 in gaseous mixtures, determination of, 1085 in illuminating gas, determination of, 1248 properties of, 1227d tetrachloride, bromine test with, 92 tubes, for colorimetric determination of carbon in steel (Fig. 25), 129 Carbonate in hicarbonate, 1553 Carbon steel, metallography of, 1713	estimation, gravimetrie methods, 134, 136 volumetric method, 136 estimation of cerium, 136 in presence of rare curths, 136, 137 in thoria, thorium nitrate, etc., 138 industrial application, 133 accurrence and properties, 133 preparation of the sample, 133 fusion method, 136 separation of the rare carths from other
in blood, detection of, 109, 1741 in gaseous mixtures, determination of, 1085 in illuminating gas, determination of, 1248 properties of, 1227d tetrachloride, bromine test with, 92 tubes, for colorimetric determination of carbon in steel (Fig. 25), 129 Carbonate in hicarbonate, 1553 Carbon steel, metallography of, 1713 Carborundum, silicon carbide, decompo-	estimation, gravimetrie methods, 134, 136 volumetric method, 136 estimation of cerium, 136 in presence of rare curths, 136, 137 in thoria, thorium nitrate, etc., 138 industrial application, 133 occurrence and properties, 133 preparation of the sample, 133 fusion method, 136 separation of the rare carths from other clements, 134, 135
in blood, detection of, 109, 1741 in gaseous mixtures, determination of, 1085 in illuminating gas, determination of, 1248 properties of, 1227d tetrachloride, bromine test with, 92 tubes, for colorimetric determination of carbon in steel (Fig. 25), 129 Carbonate in hicarbonate, 1553 Carbon steel, metallography of, 1713 Carborundum, silicon carbide, decomposition of, for silica det., 445	estimation, gravimetrie methods, 134, 136 volumetric method, 136 estimation of cerium, 136 in presence of rare curths, 136, 137 in thoria, thorium nitrate, etc., 138 industrial application, 133 occurrence and properties, 133 preparation of the sample, 133 fusion method, 136 separation of the rare earths from other clements, 134, 135 from rare earth metals, 135
in blood, detection of, 109, 1741 in gaseous mixtures, determination of, 1085 in illuminating gas, determination of, 1248 properties of, 1227d tetrachloride, bromine test with, 92 tubes, for colorimetric determination of carbon in steel (Fig. 25), 129 Carbonate in hicarbonate, 1553 Carlon steel, metallography of, 1713 Carborundum, silicon carbide, decomposition of, for silica det., 445 Carins method for halogeus in organic	estimation, gravimetrie methods, 134, 136 volumetric method, 136 estimation of cerium, 136 in presence of rare earths, 136, 137 in thoria, thorium nitrate, etc., 138 industrial application, 133 accurrence and properties, 133 preparation of the sample, 133 fusion method, 136 separation of the rare earths from other elements, 134, 135 from rare earth metals, 135 from thoria, 134
in blood, detection of, 109, 1741 in gaseous mixtures, determination of, 1085 in illuminating gas, determination of, 1248 properties of, 1227d tetrachloride, bromine test with, 92 tubes, for colorimetric determination of carbon in steel (Fig. 25), 129 Carbonate in hicarbonate, 1553 Carlon steel, metallography of, 1713 Carborundum, silicon carbide, decomposition of, for silica det., 445 Cariss method for halogens in organic matter, 145	estimation, gravimetrie methods, 134, 136 volumetric method, 136 estimation of cerium, 136 in presence of rare cerths, 136, 137 in thoria, thorium nitrate, etc., 138 industrial application, 133 occurrence and properties, 133 preparation of the sample, 133 fusion method, 136 separation of the rare carths from other clements, 134, 135 from rare carth metals, 135 from thoria, 134 table of compositions, 1215
in blood, detection of, 109, 1741 in gaseous mixtures, determination of, 1085 in illuminating gas, determination of, 1248 properties of, 1227d tetrachloride, bromine test with, 92 tubes, for colorimetric determination of carbon in steel (Fig. 25), 129 Carbonate in hicarbonate, 1553 Carbon steel, metallography of, 1713 Carborundum, silicon carbide, decomposition of, for silica det., 445 Carins method for halogens in organic matter, 145 Carney and Campbell on thorium, 423	estimation, gravimetrie methods, 134, 136 volumetric method, 136 estimation of cerium, 136 in presence of rare curths, 136, 137 in thoria, thorium nitrate, etc., 138 industrial application, 133 occurrence and properties, 133 preparation of the sample, 133 fusion method, 136 separation of the rare carths from other clements, 134, 135 from rare carth metals, 135 from thoria, 134 table of compositions, 1215 technical methods of analysis, 138
in blood, detection of, 109, 1741 in gaseous mixtures, determination of, 1085 in illuminating gas, determination of, 1248 properties of, 1227d tetrachloride, bromine test with, 92 tubes, for colorimetric determination of carbon in steel (Fig. 25), 129 Carbonate in hicarbonate, 1553 Carbon steel, metallography of, 1713 Carborundum, silicon carbide, decomposition of, for silica det., 445 Carins method for halogens in organic matter, 145 Carney and Campbell on thorium, 423 Carnot's method, modified, for determin-	estimation, gravimetrie methods, 134, 136 volumetric method, 136 estimation of cerium, 136 in presence of rare earths, 136, 137 in thoria, thorium nitrate, etc., 138 industrial application, 133 occurrence and properties, 133 preparation of the sample, 133 fusion method, 136 separation of the rare earths from other clements, 134, 135 from rare carth metals, 135 from thoria, 134 table of compositions, 1215 technical methods of analysis, 138 Clamber hurette (Fig. 79), 1497
in blood, detection of, 109, 1741 in gaseous mixtures, determination of, 1085 in illuminating gas, determination of, 1248 properties of, 1227d tetrachloride, bromine test with, 92 tubes, for colorimetric determination of carbon in steel (Fig. 25), 129 Carbonate in hicarbonate, 1553 Carbon steel, metallography of, 1713 Carborundum, silicon carbide, decomposition of, for silica det., 445 Carins method for halogens in organic matter, 145 Carney and Campbell on thorium, 423	estimation, gravimetrie methods, 134, 136 volumetric method, 136 estimation of cerium, 136 in presence of rare earths, 136, 137 in thoria, thorium nitrate, etc., 138 industrial application, 133 accurrence and properties, 133 preparation of the sample, 133 fusion method, 136 separation of the rare earths from other elements, 134, 135 from rare earth metals, 135 from thoria, 134 table of compositions, 1215 technical methods of analysis, 138 Chamber hurette (Fig. 79), 1497 Chancel's method for determining alu-
in blood, detection of, 109, 1741 in gaseous mixtures, determination of, 1085 in illuminating gas, determination of, 1248 properties of, 1227d tetrachloride, bromine test with, 92 tubes, for colorimetric determination of carbon in steel (Fig. 25), 129 Carbonate in hicarbonate, 1553 Carbon steel, metallography of, 1713 Carborundum, silicon carbide, decomposition of, for silica det., 445 Carius method for halogeus in organic matter, 145 Carney and Campbell on thorium, 423 Carnot's method, modified, for determining gold, 233	estimation, gravimetrie methods, 134, 136 volumetric method, 136 estimation of cerium, 136 in presence of rare carths, 136, 137 in thoria, thorium nitrate, etc., 138 industrial application, 133 uccurrence and properties, 133 preparation of the sample, 133 fusion method, 136 separation of the rare carths from other elements, 134, 135 from rare carth metals, 135 from thoria, 134 table of compositions, 1215 technical methods of analysis, 138 Chancel's method for determining alaminium, 9
in blood, detection of, 109, 1741 in gaseous mixtures, determination of, 1085 in illuminating gas, determination of, 1248 properties of, 1227d tetrachloride, brominc test with, 92 tubes, for colorimetric determination of carbon in steel (Fig. 25), 129 Carlonate in hicarbonate, 1553 Carlon steel, metallography of, 1713 Carborundum, silicon carbide, decomposition of, for silica det., 445 Carnes method for halogens in organic matter, 145 Carney and Campbell on thorium, 423 Carnot's method, modified, for determining gold, 233 method for nickel, 336b	estimation, gravimetrie methods, 134, 136 volumetric method, 136 estimation of cerium, 136 in presence of rare earths, 136, 137 in thoria, thorium nitrate, etc., 138 industrial application, 133 accurrence and properties, 133 preparation of the sample, 133 fusion method, 136 separation of the rare earths from other elements, 134, 135 from rare earth metals, 135 from thoria, 134 table of compositions, 1215 technical methods of analysis, 138 Chamber hurette (Fig. 79), 1497 Chancel's method for determining alu-
in blood, detection of, 109, 1741 in gaseous mixtures, determination of, 1085 in illuminating gas, determination of, 1248 properties of, 1227d tetrachloride, bromine test with, 92 tubes, for colorimetric determination of carbon in steel (Fig. 25), 129 Carbonate in hicarbonate, 1553 Carbon steel, metallography of, 1713 Carborundum, silicon carbide, decomposition of, for silica det., 445 Carnis method for halogens in organic matter, 145 Carney and Campbell on thorium, 423 Carnot's method, modified, for determining gold, 233 method for nickel, 336b Carnotite, uranium in, 582	estimation, gravimetrie methods, 134, 136 volumetric method, 136 estimation of cerium, 136 in presence of rare carths, 136, 137 in thoria, thorium nitrate, etc., 138 industrial application, 133 uccurrence and properties, 133 preparation of the sample, 133 fusion method, 136 separation of the rare carths from other elements, 134, 135 from rare carth metals, 135 from thoria, 134 table of compositions, 1215 technical methods of analysis, 138 Chancel's method for determining alaminium, 9
in blood, detection of, 109, 1741 in gaseous mixtures, determination of, 1085 in illuminating gas, determination of, 1248 properties of, 1227d tetrachloride, bromine test with, 92 tubes, for colorimetric determination of carbon in steel (Fig. 25), 129 Carlonate in hicarbonate, 1553 Carlon steel, metallography of, 1713 Carborundum, silicon carbide, decomposition of, for silica det., 445 Carins method for halogens in organic matter, 145 Carney and Campbell on thorium, 423 Carnot's method, modified, for determining gold, 233 method for nickel, 336b Carnotite, uranium in, 582 Case hardening, steel metallography, 1720	estimation, gravimetrie methods, 134, 136 volumetric method, 136 estimation of cerium, 136 in presence of rare curths, 136, 137 in thoria, thorium nitrate, etc., 138 industrial application, 133 occurrence and properties, 133 preparation of the sample, 133 fusion method, 136 separation of the rare earths from other clements, 134, 135 from rare carth metals, 135 from thoria, 134 table of compositions, 1215 technical methods of analysis, 138 Chamber hurette (Fig. 79), 1497 Chancel's method for determining aluminium, 9 Chaucel degree for specific volume of 8, 519a
in blood, detection of, 109, 1741 in gaseous mixtures, determination of, 1085 in illuminating gas, determination of, 1248 properties of, 1227d tetrachloride, bromine test with, 92 tubes, for colorimetric determination of carbon in steel (Fig. 25), 129 Carbonate in hicarbonate, 1553 Carbon steel, metallography of, 1713 Carborundum, silicon carbide, decomposition of, for silica det., 445 Carins method for halogens in organic matter, 145 Carney and Campbell on thorium, 423 Carnot's method, modified, for determining gold, 233 method for nickel, 336b Carnotite, uranium in, 582 Case hardening, steel metallography, 1720 Castor oil, constants, 1147, 1148	estimation, gravimetrie methods, 134, 136 volumetric method, 136 estimation of cerium, 136 in presence of rare curths, 136, 137 in thoria, thorium nitrate, etc., 138 industrial application, 133 accurrence and properties, 133 preparation of the sample, 133 fusion method, 136 separation of the rare carths from other elements, 134, 135 from rare carth metals, 135 from rare carth metals, 135 from thoria, 134 table of compositions, 1215 technical methods of analysis, 138 Clamber hurette (Fig. 79), 1497 Chancel's method for determining aluminium, 9 Chaucel degree for specific volume of 8, 519a Chapin's method for boric acid det., 87
in blood, detection of, 109, 1741 in gaseous mixtures, determination of, 1085 in illuminating gas, determination of, 1248 properties of, 1227d tetrachloride, bromine test with, 92 tubes, for colorimetric determination of carbon in steel (Fig. 25), 129 Carbonate in hicarbonate, 1553 Carbon steel, metallography of, 1713 Carborundum, silicon carbide, decomposition of, for silica det., 445 Carins method for halogens in organic matter, 145 Carney and Campbell on thorium, 423 Carnot's method, modified, for determining gold, 233 method for nickel, 336b Carnotite, uranium in, 582 Case hardening, steel metallography, 1720 Castor oil, constants, 1147, 1148 Caustic, free in soap, 1601	estimation, gravimetrie methods, 134, 136 volumetric method, 136 estimation of cerium, 136 in presence of rare carths, 136, 137 in thoria, thorium nitrate, etc., 138 industrial application, 133 uccurrence and properties, 133 preparation of the sample, 133 fusion method, 136 separation of the rare carths from other elements, 134, 135 from rare carth metals, 135 from thoria, 134 table of compositions, 1215 technical methods of analysis, 138 Chamber hurette (Fig. 79), 1497 Chancel's method for determining aluminium, 9 Chaucel degree for specific volume of 8, 519a Chapin's method for boric acid det., 87 Chapman and Thornton on iron det., 258
in blood, detection of, 109, 1741 in gaseous mixtures, determination of, 1085 in illuminating gas, determination of, 1248 properties of, 1227d tetrachloride, bromine test with, 92 tubes, for colorimetric determination of carbon in steel (Fig. 25), 129 Carbonate in hicarbonate, 1553 Carbon steel, metallography of, 1713 Carborundum, silicon carbide, decomposition of, for silica det., 445 Carnis method for halogens in organic matter, 145 Carney and Campbell on thorium, 423 Carnot's method, modified, for determining gold, 233 method for nickel, 336b Carnotite, uranium in, 582 Case hardening, steel metallography, 1720 Castor oil, constants, 1147, 1148 Caustic, free in soap, 1601 standard solution, 1496	estimation, gravimetrie methods, 134, 136 volumetric method, 136 estimation of cerium, 136 in presence of rare earths, 136, 137 in thoria, thorium nitrate, etc., 138 industrial application, 133 occurrence and properties, 133 preparation of the sample, 133 fusion method, 136 separation of the rare earths from other elements, 134, 135 from rare earth metals, 135 from thoria, 134 table of compositions, 1215 technical methods of analysis, 138 Chamber hurette (Fig. 79), 1497 Chancel's method for determining aluminium, 9 Chaucel degree for specific volume of 8, 519a Chapin's method for boric acid det., 87 Chapman and Thornton on iron det., 258 Character of copper deposits by electrol-
in blood, detection of, 109, 1741 in gaseous mixtures, determination of, 1085 in illuminating gas, determination of, 1248 properties of, 1227d tetrachloride, bromine test with, 92 tubes, for colorimetric determination of carbon in steel (Fig. 25), 129 Carbonate in hicarbonate, 1553 Carlon steel, metallography of, 1713 Carborundum, silicon carbide, decomposition of, for silica det., 445 Carius method for halogeus in organic matter, 145 Carney and Campbell on thorium, 423 Carnet's method, modified, for determining gold, 233 method for nickel, 336b Carnotite, uranium in, 582 Case hardening, steel metallography, 1720 Castor oil, constants, 1147, 1148 Caustic, free in soap, 1601 standard solution, 1496 Caustic soda, sodium tartrate m. for dis-	estimation, gravimetrie methods, 134, 136 volumetric method, 136 estimation of cerium, 136 in presence of rare curths, 136, 137 in thoria, thorium nitrate, etc., 138 industrial application, 133 occurrence and properties, 133 preparation of the sample, 133 fusion method, 136 separation of the rare earths from other clements, 134, 135 from rare carth metals, 135 from thoria, 134 table of compositions, 1215 technical methods of analysis, 138 Chamber hurette (Fig. 79), 1497 Chancel's method for determining aluminium, 9 Chaucel degree for specific volume of 8, 519a Chapman and Thornton on iron det., 258 Character of copper deposits by electrolysis, 191
in blood, detection of, 109, 1741 in gaseous mixtures, determination of, 1085 in illuminating gas, determination of, 1248 properties of, 1227d tetrachloride, bromine test with, 92 tubes, for colorimetric determination of carbon in steel (Fig. 25), 129 Carbonate in hicarbonate, 1553 Carlon steel, metallography of, 1713 Carborundum, silicon carbide, decomposition of, for silica det., 445 Carins method for halogens in organic matter, 145 Carney and Campbell on thorium, 423 Carnot's method, modified, for determining gold, 233 method for nickel, 336b Carnotite, uranium in, 582 Case hardening, steel metallography, 1720 Castor oil, constants, 1147, 1148 Caustic, free in soap, 1601 standard solution, 1496 Caustic soda, sodium tartrate m. for distinguishing copper compds., 210	estimation, gravimetrie methods, 134, 136 volumetric method, 136 estimation of cerium, 136 in presence of rare curths, 136, 137 in thoria, thorium nitrate, etc., 138 industrial application, 133 uccurrence and properties, 133 preparation of the sample, 133 fusion method, 136 separation of the rare carths from other elements, 134, 135 from rare earth metals, 135 from thoria, 134 table of compositions, 1215 technical methods of analysis, 138 Chamber hurette (Fig. 79), 1497 Chancel's method for determining aluminium, 9 Chaucel degree for specific volume of 8, 519a Chapman and Thornton on iron det., 258 Character of copper deposits by electrolysis, 191 Characteristics of some animal and veg-
in blood, detection of, 109, 1741 in gaseous mixtures, determination of, 1085 in illuminating gas, determination of, 1248 properties of, 1227d tetrachloride, bromine test with, 92 tubes, for colorimetric determination of carbon in steel (Fig. 25), 129 Carbonate in hicarbonate, 1553 Carlon steel, metallography of, 1713 Carborundum, silicon carbide, decomposition of, for silica det., 445 Carnes method for halogeus in organic matter, 145 Carney and Campbell on thorium, 423 Carnot's method, modified, for determining gold, 233 method for nickel, 336b Carnotite, uranium in, 582 Case hardening, steel metallography, 1720 Castor oil, constants, 1147, 1148 Caustic, free in soap, 1601 standard solution, 1496 Caustic soda, sodium tartrate m. for distinguishing copper compds., 210 Causticized ash, analysis of, 1555, 1783	estimation, gravimetrie methods, 134, 136 volumetric method, 136 estimation of cerium, 136 in presence of rare curths, 136, 137 in thoria, thorium nitrate, etc., 138 industrial application, 133 occurrence and properties, 133 preparation of the sample, 133 fusion method, 136 separation of the rare curths from other clements, 134, 135 from rare carth metals, 135 from thoria, 134 table of compositions, 1215 technical methods of analysis, 138 Chamber hurette (Fig. 79), 1497 Chancel's method for determining aluminium, 9 Chaucel degree for specific volume of 8, 519a Chapin's method for boric acid det., 87 Chapman and Thornton on iron det., 258 Character of copper deposits by electrolysis, 191 Characteristics of some animal and vegetable oils, 1148, 1149
in blood, detection of, 109, 1741 in gaseous mixtures, determination of, 1085 in illuminating gas, determination of, 1248 properties of, 1227d tetrachloride, bromine test with, 92 tubes, for colorimetric determination of carbon in steel (Fig. 25), 129 Carbonate in hicarbonate, 1553 Carbon steel, metallography of, 1713 Carborundum, silicon carbide, decomposition of, for silica det., 445 Carnis method for halogeus in organic matter, 145 Carney and Campbell on thorium, 423 Carnot's method, modified, for determining gold, 233 method for nickel, 336b Carnotite, uranium in, 582 Case hardening, steel metallography, 1720 Castor oil, constants, 1147, 1148 Caustic, free in soap, 1601 standard solution, 1496 Caustic soda, sodium tartrate m. for distinguishing copper compds., 210 Causticized ash, analysis of, 1555, 1783 Cellulose in rubber, 1595	estimation, gravimetrie methods, 134, 136 volumetric method, 136 estimation of cerium, 136 in presence of rare earths, 136, 137 in thoria, thorium nitrate, etc., 138 industrial application, 133 occurrence and properties, 133 preparation of the sample, 133 fusion method, 136 separation of the rare earths from other elements, 134, 135 from rare earth metals, 135 from thoria, 134 table of compositions, 1215 technical methods of analysis, 138 Chamber hurette (Fig. 79), 1497 Chancel's method for determining aluminium, 9 Chaucel degree for specific volume of 8, 519a Chapin's method for boric acid det., 87 Chapman and Thornton on iron det., 258 Character of copper deposits by electrolysis, 191 Characteristics of some animal and vegetable oils, 1148, 1149 of some fatty acids from oils, 1147
in blood, detection of, 109, 1741 in gaseous mixtures, determination of, 1085 in illuminating gas, determination of, 1248 properties of, 1227d tetrachloride, brominc test with, 92 tubes, for colorimetric determination of carbon in steel (Fig. 25), 129 Carbonate in hicarbonate, 1553 Carbon steel, metallography of, 1713 Carborundum, silicon carbide, decomposition of, for silica det., 445 Carnis method for halogens in organic matter, 145 Carney and Campbell on thorium, 423 Carnot's method, modified, for determining gold, 233 method for nickel, 336b Carnotite, uranium in, 582 Case hardening, steel metallography, 1720 Castor oil, constants, 1147, 1148 Caustic, free in soap, 1601 standard solution, 1496 Caustic soda, sodium tartrate m. for distinguishing copper compds., 210 Causticized ash, analysis of, 1555, 1783 Cellulose in rubber, 1595 Coment, analysis and testing of, 1202	estimation, gravimetrie methods, 134, 136 volumetric method, 136 estimation of cerium, 136 in presence of rare curths, 136, 137 in thoria, thorium nitrate, etc., 138 industrial application, 133 accurrence and properties, 133 preparation of the sample, 133 fusion method, 136 separation of the rare carths from other clements, 134, 135 from rare carth metals, 135 from thoria, 134 table of compositions, 1215 technical methods of analysis, 138 Chamber hurette (Fig. 79), 1497 Chancel's method for determining aluminium, 9 Chancel degree for specific volume of 8, 519a Chapman and Thornton on iron det., 258 Character of copper deposits by electrolysis, 191 Characteristics of some animal and vegetable oils, 1148, 1149 of some fatty acids from oils, 1147 of waxes, 1150
in blood, detection of, 109, 1741 in gaseous mixtures, determination of, 1085 in illuminating gas, determination of, 1248 properties of, 1227d tetrachloride, brominc test with, 92 tubes, for colorimetric determination of carbon in steel (Fig. 25), 129 Carbonate in hicarbonate, 1553 Carbon steel, metallography of, 1713 Carborundum, silicon carbide, decomposition of, for silica det., 445 Carnis method for halogens in organic matter, 145 Carney and Campbell on thorium, 423 Carnot's method, modified, for determining gold, 233 method for nickel, 336b Carnotite, uranium in, 582 Case hardening, steel metallography, 1720 Castor oil, constants, 1147, 1148 Caustic, free in soap, 1601 standard solution, 1496 Caustic soda, sodium tartrate m. for distinguishing copper compds., 210 Causticized ash, analysis of, 1555, 1783 Cellulose in rubber, 1595 Coment, analysis and testing of, 1202	estimation, gravimetrie methods, 134, 136 volumetric method, 136 estimation of cerium, 136 in presence of rare carths, 136, 137 in thoria, thorium nitrate, etc., 138 industrial application, 133 uccurrence and properties, 133 preparation of the sample, 133 fusion method, 136 separation of the rare carths from other elements, 134, 135 from rare carth metals, 135 from thoria, 134 table of compositions, 1215 technical methods of analysis, 138 Chamber hurette (Fig. 79), 1497 Chancel's method for determining aluminium, 9 Chaucel degree for specific volume of 8, 519a Chapman and Thornton on iron det., 258 Character of copper deposits by electrolysis, 191 Characteristics of some animal and vegetable oils, 1148, 1149 of some fatty acids from oils, 1147 of waxes, 1150 Charcoal in explosives, 1373, 1390, 1391
in blood, detection of, 109, 1741 in gaseous mixtures, determination of, 1085 in illuminating gas, determination of, 1248 properties of, 1227d tetrachloride, bromine test with, 92 tubes, for colorimetric determination of carbon in steel (Fig. 25), 129 Carbonate in hicarbonate, 1553 Carbon steel, metallography of, 1713 Carborundum, silicon carbide, decomposition of, for silica det., 445 Carnis method for halogeus in organic matter, 145 Carney and Campbell on thorium, 423 Carnot's method, modified, for determining gold, 233 method for nickel, 336b Carnotite, uranium in, 582 Case hardening, steel metallography, 1720 Castor oil, constants, 1147, 1148 Caustic, free in soap, 1601 standard solution, 1496 Caustic soda, sodium tartrate m. for distinguishing copper compds., 210 Causticized ash, analysis of, 1555, 1783 Cellulose in rubber, 1595	estimation, gravimetrie methods, 134, 136 volumetric method, 136 estimation of cerium, 136 in presence of rare curths, 136, 137 in thoria, thorium nitrate, etc., 138 industrial application, 133 accurrence and properties, 133 preparation of the sample, 133 fusion method, 136 separation of the rare carths from other clements, 134, 135 from rare carth metals, 135 from thoria, 134 table of compositions, 1215 technical methods of analysis, 138 Chamber hurette (Fig. 79), 1497 Chancel's method for determining aluminium, 9 Chancel degree for specific volume of 8, 519a Chapman and Thornton on iron det., 258 Character of copper deposits by electrolysis, 191 Characteristics of some animal and vegetable oils, 1148, 1149 of some fatty acids from oils, 1147 of waxes, 1150

Chemical tests of water, 1412	Chlorine, determination of free chlorine,
Chiddoy on cyanide solution assay, 486	151
Chili saltpeter. See Nitrate of Soda	in hydrochloric acid, 1501
under Nitrogen, 349	in nitric acid, 1512
Chimney flue gases, 1252	industrial application of methods, 143
China clay paint pigment, 1187	occurrence, 143
Chinese blue, analysis of, 1197	preparation and solution of the sample,
Chinese wood oil, analysis of, determin-	ores, cinders, rocks, water soluble,
	and insoluble chlorides, silver chlo-
ing acid number, iodine number,	
saponification number, specific grav-	nde, 144
ity, unsaponifiable matter, refrac-	organic matter, decomposition by
tive index, heating and Jelly tests,	Carius method, 145
1169-1170	decomposition by lime method,
Chlorate, test for, 143	146
determination of, 152	decomposition by sodium perox ₂
in presence of perchlorates, 153	ide method, 146
method for chromium in steel, 165	separation from iodine, 148
removal of, in sulphur det., 497	from cyanides, thiocyanates, 130
Chlorates in explosives, 1387	together with bromine from iodine,
Chloric acid. See Chlorate.	148
Chloride and cyanide, det. of, 154	halides from the heavy metals, 148
chlorate, perchlorate exam. of, 1385	halides from one another, 148
1397	halides from silver and from silver
eyanide, thiocyanate dot. of, 155	
	cyanide, 148, 155
detection of, 142	solubility of ehlorine and its salts, 143
in gases, 1505	traces, detection of, 142
in soap, 1602	Chlorine, free, liberation of bromine with,
method, for determining silver, 453	95
Chlorine, detection of free, 142	determination of, 151
combined chlorine, chloride by silver	water, decomposition of hydrohromic
nitrate test, 142	aeid, 342
test in presence of broinide and io-	Chloroform, det., 1728
dide, 142	Chloroplatinate method for determining
test in presence of cyanate and cya-	potassium, 410
nide, thiocyanate, 142	Hicks' modification, 411
test for free hydrochloric acid, 142	Chlorosulphonic acid, analysis of, 1540
test for chlorate, chlorite, hypochlo-	
11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Chromate, detection of parium with, 56
rite, perchlorate, 143	Chromate, detection of barium with, 56 method for determining barium as
rite, perchlorate, 143 estimation of combined ehlorine as	method for determining barium as
estimation of combined ehlorine as	method for determining barium as BaCrO ₄ , 63a
estimation of combined ehlorine as chloride, general methods:	method for determining barium as BaCrO ₄ , 63a volumetric method for determining
estimation of combined ehlorine as chloride, general methods: gravimetric method as silver ehloride,	method for determining barium as BaCrO ₄ , 63a volumetric method for determining barium, 65
estimation of combined ehlorine as chloride, general methods: gravimetric method as silver ehloride, 148a	method for determining barium as BaCrO ₄ , 63a volumetric method for determining barium, 65 method for determining chlorine, 150
estimation of combined ehlorine as chloride, general methods: gravimetric method as silver ehloride, 148a volumetric methods, silver chromate	method for determining barium as BaCrO ₄ , 63a volumetric method for determining barium, 65 method for determining chlorine, 150 method for determining lead, 275, 278
estimation of combined ehlorine as chloride, general methods: gravimetric method as silver ehloride, 148a volumetric methods, silver chromate method, in neutral solution, 150	method for determining barium as BaCrO ₄ , 63a volumetric method for determining barium, 65 method for determining chlorine, 150 method for determining lead, 275, 278 Chromate-ferrous-diphenylamine method
estimation of combined ehlorine as chloride, general methods: gravimetric method as silver ehloride, 148a volumetric methods, silver chromate method, in neutral solution, 150 silver thiocyanate method in acid	method for determining barium as BaCrO ₄ , 63a volumetric method for determining barium, 65 method for determining chlorine, 150 method for determining lead, 275, 278 Chromate-ferrous-diphenylamine method for lead, 278b
estimation of combined ehlorine as chloride, general methods: gravimetric method as silver ehloride, 148a, volumetric methods, silver chromate method, in neutral solution, 150 silver thiocyanate method in acid solution, 149	method for determining barium as BaCrO ₄ , 63a volumetric method for determining barium, 65 method for determining chlorine, 150 method for determining lead, 275, 278 Chromate-ferrous-diphenylamine method for lead, 278b Chrome green, 1198
estimation of combined ehlorine as chloride, general methods: gravimetric method as silver ehloride, 148a volumetric methods, silver chromate method, in neutral solution, 150 silver thiocyanate method in acid solution, 149 Chlorine, estimation of combined and	method for determining barium as BaCrO ₄ , 63a volumetric method for determining barium, 65 method for determining chlorine, 150 method for determining lead, 275, 278 Chromate-ferrous-diphenylamine method for lead, 278b Chromic acid, determination of, in pres-
estimation of combined ehlorine as chloride, general methods: gravimetric method as silver ehloride, 148a volumetric methods, silver chromate method, in neutral solution, 150 silver thiocyanate method in acid solution, 149 Chlorine, estimation of combined and free chlorine, special cases:	method for determining barium as BaCrO ₄ , 63a volumetric method for determining barium, 65 method for determining chlorine, 150 method for determining lead, 275, 278 Chromate-ferrous-diphenylamine method for lead, 278b Chrome green, 1198 Chromic acid, determination of, in presence of vanadic acid, 592
estimation of combined ehlorine as chloride, general methods: gravimetric method as silver chloride, 148a volumetric methods, silver chromate method, in ncutral solution, 150 silver thiocyanate method in acid solution, 149 Chlorine, estimation of combined and free chlorine, special cases: determination combined chlorine in	method for determining barium as BaCrO ₄ , 63a volumetric method for determining barium, 65 method for determining chlorine, 150 method for determining lead, 275, 278 Chromate-ferrous-diphenylamine method for lead, 278b Chrome green, 1198 Chromic acid, determination of, in presence of vanadie acid, 592 remoyal of, from nitrie acid, 342
estimation of combined ehlorine as chloride, general methods: gravimetric method as silver ehloride, 148a volumetric methods, silver chromate method, in neutral solution, 150 silver thiocyanate method in acid solution, 149 Chlorine, estimation of combined and free chlorine, special cases: determination combined chlorine in presence of bromine and iodine	method for determining barium as BaCrO ₄ , 63a volumetric method for determining barium, 65 method for determining chlorine, 150 method for determining lead, 275, 278 Chromate-ferrous-diphenylamine method for lead, 278b Chrome green, 1198 Chromic acid, determination of, in presence of vanadic acid, 592 removal of, from nitric acid, 342 hydroxide, precipitation of, 159
estimation of combined ehlorine as chloride, general methods: gravimetric method as silver ehloride, 148a volumetric methods, silver chromate method, in neutral solution, 150 silver thiocyanate method in acid solution, 149 Chlorine, estimation of combined and free chlorine, special cases: determination combined chlorine in presence of brounine and iodine (combined), 154	method for determining barium as BaCrO ₄ , 63a volumetric method for determining barium, 65 method for determining chlorine, 150 method for determining lead, 275, 278 Chromate-ferrous-diphenylamine method for lead, 278b Chromic acid, determination of, in presence of vauadie acid, 592 removal of, from nitrie acid, 342 hydroxide, precipitation of, 159 Chromite, chromium in, 164
estimation of combined ehlorine as chloride, general methods: gravimetric method as silver ehloride, 148a volumetric methods, silver chromate method, in neutral solution, 150 silver thiocyanate method in acid solution, 149 Chlorine, estimation of combined and free chlorine, special cases: determination combined chlorine in presence of bronnine and iodine (combined), 154 in presence of other acids, 154	method for determining barium as BaCrO ₄ , 63a volumetric method for determining barium, 65 method for determining chlorine, 150 method for determining lead, 275, 278 Chromate-ferrous-diphenylamine method for lead, 278b Chrome green, 1198 Chromic acid, determination of, in presence of vanadie acid, 592 removal of, from nitrie acid, 342 hydroxide, precipitation of, 159 Chromite, chromium in, 164 Chromium, detection of, tests with barium
estimation of combined ehlorine as chloride, general methods: gravimetric method as silver chloride, 148a volumetric methods, silver chromate method, in ncutral solution, 150 silver thiocyanate method in acid solution, 149 Chlorine, estimation of combined and free chlorine, special cases: determination combined chlorine in presence of bronnine and iodine (combined), 154 in presence of other acids, 154 in bleaching powder, 155	method for determining barium as BaCrO ₄ , 63a volumetric method for determining barium, 65 method for determining chlorine, 150 method for determining lead, 275, 278 Chromate-ferrous-diphenylamine method for lead, 278b Chrome green, 1198 Chromic acid, determination of, in presence of vanadic acid, 592 removal of, from nitric acid, 342 hydroxide, precipitation of, 159 Chromite, chromium in, 164 Chromium, detection of, tests with barium acetate, ether, lead acetate, mercurous
estimation of combined ehlorine as chloride, general methods: gravimetric method as silver ehloride, 148a volumetric methods, silver chromate method, in neutral solution, 150 silver thiocyanate method in acid solution, 149 Chlorine, estimation of combined and free chlorine, special cases: determination combined chlorine in presence of bromine and iodine (combined), 154 in presence of other acids, 154 in bleaching powder, 155 in brimstone, 519	method for determining barium as BaCrO ₄ , 63a volumetric method for determining barium, 65 method for determining chlorine, 150 method for determining lead, 275, 278 Chromate-ferrous-diphenylamine method for lead, 278b Chrome green, 1198 Chromic acid, determination of, in presence of vauadie acid, 592 removal of, from nitrie acid, 342 hydroxide, precipitation of, 159 Chromite, chromium in, 164 Chromium, detection of, tests with barium acetate, ether, lead acetate, mercurous nitrate, hydrogen peroxide, reducing
estimation of combined ehlorine as chloride, general methods: gravimetric method as silver ehloride, 148a volumetric methods, silver chromate method, in neutral solution, 150 silver thiocyanate method in acid solution, 149 Chlorine, estimation of combined and free chlorine, special cases: determination combined chlorine in presence of bromine and iodine (combined), 154 in presence of other acids, 154 in bleaching powder, 155 in brimstone, 519 in bromine, 97	method for determining barium as BaCrO ₄ , 63a volumetric method for determining barium, 65 method for determining chlorine, 150 method for determining lead, 275, 278 Chromate-ferrous-diphenylamine method for lead, 278b Chrome green, 1198 Chromic acid, determination of, in presence of vanadie acid, 592 removal of, from nitrie acid, 342 hydroxide, precipitation of, 159 Chromite, chromium in, 164 Chromium, detection of, tests with barium
estimation of combined ehlorine as chloride, general methods: gravimetric method as silver ehloride, 148a volumetric methods, silver chromate method, in neutral solution, 150 silver thiocyanate method in acid solution, 149 Chlorine, estimation of combined and free chlorine, special cases: determination combined chlorine in presence of bromine and iodine (combined), 154 in presence of other acids, 154 in bleaching powder, 155 in brimstone, 519 in bromine, 97 in cement copper and copper ores,	method for determining barium as BaCrO ₄ , 63a volumetric method for determining barium, 65 method for determining chlorine, 150 method for determining lead, 275, 278 Chromate-ferrous-diphenylamine method for lead, 278b Chrome green, 1198 Chromic acid, determination of, in presence of vauadie acid, 592 removal of, from nitrie acid, 342 hydroxide, precipitation of, 159 Chromite, chromium in, 164 Chromium, detection of, tests with barium acetate, ether, lead acetate, mercurous nitrate, hydrogen peroxide, reducing
estimation of combined ehlorine as chloride, general methods: gravimetric method as silver ehloride, 148a volumetric methods, silver chromate method, in neutral solution, 150 silver thiocyanate method in acid solution, 149 Chlorine, estimation of combined and free chlorine, special cases: determination combined chlorine in presence of bromine and iodine (combined), 154 in presence of other acids, 154 in pleaching powder, 155 in brimstone, 519 in bromine, 97 in cement copper and copper ores, 206	method for determining barium as BaCrO ₄ , 63a volumetric method for determining barium, 65 method for determining chlorine, 150 method for determining lead, 275, 278 Chromate-ferrous-diphenylamine method for lead, 278b Chrome green, 1198 Chromic acid, determination of, in presence of vanadie acid, 592 removal of, from nitrie acid, 342 hydroxide, precipitation of, 159 Chromite, chromium in, 164 Chromium, detection of, tests with barium acetate, ether, lead acetate, mercurous nitrate, hydrogen peroxide, reducing agents, diphenyl carbazide, 156 distinction between chromic and chro-
estimation of combined ehlorine as chloride, general methods: gravimetric method as silver ehloride, 148a volumetric methods, silver chromate method, in neutral solution, 150 silver thiocyanate method in acid solution, 149 Chlorine, estimation of combined and free chlorine, special cases: determination combined chlorine in presence of bromine and iodine (combined), 154 in presence of other acids, 154 in presence of other acids, 154 in bleaching powder, 155 in brimstone, 519 in bromine, 97 in cement copper and copper ores, 206 in gas, 147	method for determining barium as BaCrO ₄ , 63a volumetric method for determining barium, 65 method for determining chlorine, 150 method for determining lead, 275, 278 Chromate-ferrous-diphenylamine method for lead, 278b Chrome green, 1198 Chrome green, 1198 Chromic acid, determination of, in presence of vanadie acid, 592 removal of, from nitrie acid, 342 hydroxide, precipitation of, 159 Chromite, chromium in, 164 Chromium, detection of, tests with barium acetate, ether, lead acetate, mercurous nitrate, hydrogen peroxide, reducing agents, diphenyl carbazide, 156 distinction between chromic and chromous salts, 156
estimation of combined ehlorine as chloride, general methods: gravimetric method as silver ehloride, 148a volumetric methods, silver chromate method, in neutral solution, 150 silver thiocyanate method in acid solution, 149 Chlorine, estimation of combined and free chlorine, special cases: determination combined chlorine in presence of bromine and iodine (combined), 154 in presence of other acids, 154 in pleaching powder, 155 in brimstone, 519 in bromine, 97 in cement copper and copper ores, 206	method for determining barium as BaCrO ₄ , 63a volumetric method for determining barium, 65 method for determining chlorine, 150 method for determining lead, 275, 278 Chromate-ferrous-diphenylamine method for lead, 278b Chromic acid, 278b Chromic acid, determination of, in presence of vauadie acid, 592 removal of, from nitrie acid, 342 hydroxide, precipitation of, 159 Chromite, chromium in, 164 Chromium, detection of, tests with barium acetate, ether, lead acetate, mercurous nitrate, hydrogen peroxide, reducing agents, diphenyl carbazide, 156 distinction between chromic and chromous salts, 156 estimation, general procedures:
estimation of combined ehlorine as chloride, general methods: gravimetric method as silver ehloride, 148a volumetric methods, silver chromate method, in ncutral solution, 150 silver thiocyanate method in acid solution, 149 Chlorine, estimation of combined and free chlorine, special cases: determination combined chlorine in presence of bronnine and iodine (combined), 154 in presence of other acids, 154 in bleaching powder, 155 in brimstone, 519 in bromine, 97 in cement copper and copper ores, 206 in gas, 147 in nitric acid, 1511 in organic compounds, 145–146	method for determining barium as BaCrO ₄ , 63a volumetric method for determining barium, 65 method for determining chlorine, 150 method for determining lead, 275, 278 Chromate-ferrous-diphenylamine method for lead, 278b Chrome green, 1198 Chromic acid, determination of, in presence of vanadie acid, 592 removal of, from nitrie acid, 342 hydroxide, precipitation of, 159 Chromite, chromium in, 164 Chromium, detection of, tests with barium acetate, ether, lead acetate, mercurous nitrate, hydrogen peroxide, reducing agents, diphenyl carbazide, 156 distinction between chromic and chromous salts, 156 estimation, general procedures: gravimetric, determination as barium
estimation of combined ehlorine as chloride, general methods: gravimetric method as silver ehloride, 148a volumetric methods, silver chromate method, in neutral solution, 150 silver thiocyanate method in acid solution, 149 Chlorine, estimation of combined and free chlorine, special cases: determination combined chlorine in presence of bromine and iodine (combined), 154 in presence of other acids, 154 in bleaching powder, 155 in brimstone, 519 in bromine, 97 in cement copper and copper orcs, 2008 in gas, 147 in nitric acid, 1511	method for determining barium as BaCrO ₄ , 63a volumetric method for determining barium, 65 method for determining chlorine, 150 method for determining lead, 275, 278 Chromate-ferrous-diphenylamine method for lead, 278b Chrome green, 1198 Chromic acid, determination of, in presence of vanadie acid, 592 removal of, from nitrie acid, 342 hydroxide, precipitation of, 159 Chromite, chromium in, 164 Chromium, detection of, tests with barium acetate, ether, lead acetate, mercurous nitrate, hydrogen peroxide, reducing agents, diphenyl carbazide, 156 distinction between chromic and chromous salts, 156 estimation, general procedures: gravimetric, determination as barium ehromate, 160
estimation of combined ehlorine as chloride, general methods: gravimetric method as silver ehloride, 148a volumetric methods, silver chromate method, in ncutral solution, 150 silver thiocyanate method in acid solution, 149 Chlorine, estimation of combined and free chlorine, special cases: determination combined chlorine in presence of bronnine and iodine (combined), 154 in presence of other acids, 154 in bleaching powder, 155 in brimstone, 519 in bromine, 97 in cement copper and copper ores, 206 in gas, 147 in nitric acid, 1511 in organic compounds, 145–146	method for determining barium as BaCrO ₄ , 63a volumetric method for determining barium, 65 method for determining chlorine, 150 method for determining lead, 275, 278 Chromate-ferrous-diphenylamine method for lead, 278b Chrome green, 1198 Chromic acid, determination of, in presence of vanadie acid, 592 removal of, from nitrie acid, 342 hydroxide, precipitation of, 159 Chromite, chromium in, 164 Chromium, detection of, tests with barium acetate, ether, lead acetate, mercurous nitrate, hydrogen peroxide, reducing agents, diphenyl carbazide, 156 distinction between chromic and chromous salts, 156 estimation, general procedures: gravimetric, determination as barium

Chromium—volumetric, ferrous sulphate	Coal, calorific value, determination of, 1622
and permanganate method,	calorimeter, standardisation of, 1629
161, 1368f	carbon total in, 1646
chlorate method, 165	coke, 1041
diehromate diphenylamine meth-	composition of. See chapters on Fuel
od, 164a	and Coal.
iodine method, 161	conversion calculations, moisture, 1632
estimation, special procedures:	correction factors, 1639
determination in chromate, 164	definitions, 1651
in green paint pigments, 1196	Emerson bomb calorimeter, 1625
in niekel, 336e	fixed earbon, determination of, 1622
in orange and yellow paint pig-	fusibility of coal ash, 1630
ments, 1195	gasoline, 1642, 1658 Hoskins' cleetric furnace (Fig. 210),
in presence of vanadium, 593	1630
in steel, elect. method, 1677, 1678	
in steel, rapid method, 164, 1368f	noisture determination in coal, 1618
traces by diphenylcarbazide, 163	Parr calorimeter, 1634
industrial application of methods for, 156	petroleum oils, 1641, 1660
occurrence, 156	preparation of the sample, 1618
preparation and solution of the sample,	pyrophosphate method, 174
refraetory materials, materials	quartering (Fig. 204), 1617*
high in silica, chrome iron ores, 157	radiation corrections, 1652
iron and steel, 158	references, 1632
separations from alumina and iron, 158,	sampling coal, 1616
159	thermometer Hythread, 1645
solubility of the metal, 157	turbidimetrie sulphur table, 1620
traces, detection, 156	volatile comhustible matter, determina
estimation, 162-163	tion of, 1618
Chronium salts, comparison with vana-	volatile sulphur, determination of, 1619 1623
dium salts, 583	
Cinchonine method for det. tungsten, 560	oxygen bomb method, 1651 Cobalt detection of general procedure
Cinehouine potassium iodide method for	Cobalt, detection of, general procedure,
Cinehonine potassium iodide method for determining hismuth, 77	Cobalt, detection of, general procedure, 166
Cinehonine potassium iodide method for determining hismuth, 77 reagent for tungsten det., 560	Cobalt, detection of, general procedure, 166 ammonium sulphocyanate test for,
Cinehouine potassium iodide method for determining hismuth, 77 reagent for tungsten det., 560 Cinders, chlorine in, 144	Cobalt, detection of, general procedure, 166 ammonium sulphocyanate test for, 166
Cinehouine potassium iodide method for determining hismuth, 77 reagent for tungsten det., 560 Cinders, chlorine in, 144 Citrie acid, analysis of, 1549	Cobalt, detection of, general procedure, 166 ammonium sulphocyanate test for, 166 dicyandiamidine sulphate test for, 166
Cinehonine potassium iodide method for determining hismuth, 77 reagent for tungsten det., 560 Cinders, chlorine in, 144 Citrie acid, analysis of, 1549 reagent for calcium determination,	Cobalt, detection of, general procedure, 168 ammonium sulphocyanate test for, 166 dicyandiamidine sulphate test for, 166 potassium nitrite, potassium sulpho-
Cinehonine potassium iodide method for determining hismuth, 77 reagent for tungsten det., 560 Cinders, chlorine in, 144 Citrie acid, analysis of, 1549 reagent for calcium determination, 106	Cobalt, detection of, general procedure, 166 ammonium sulphocyanate test for, 166 dicyandiamidine sulphate test for, 166 potassium nitrite, potassium sulphocyanate tests, 166
Cinehonine potassium iodide method for determining hismuth, 77 reagent for tungsten det., 560 Cinders, chlorine in, 144 Citrie acid, analysis of, 1549 reagent for calcium determination, 106 Clark on tin, 525-536	Cobalt, detection of, general procedure, 168 ammonium sulphocyanate test for, 166 dieyandiamidine sulphate test for, 166 potassium nitrite, potassium sulphocyanate tests, 166 estimation, general procedures:
Cinehonine potassium iodide method for determining hismuth, 77 reagent for tungsten det., 560 Cinders, chlorine in, 144 Citrie acid, analysis of, 1549 reagent for calcium determination, 106 Clark on tin, 525-536 Clark's modification of Mohr's method	Cobalt, detection of, general procedure, 166 ammonium sulphocyanate test for, 166 dieyandiamidine sulphate test for, 166 potassium nitrite, potassium sulphocyanate tests, 166 estination, general procedures: gravimetric, deposition of the metal
Cinehonine potassium iodide method for determining hismuth, 77 reagent for tungsten det., 560 Cinders, chlorine in, 144 Citrie acid, analysis of, 1549 reagent for calcium determination, 106 Clark on tin, 525-536 Clark's modification of Mohr's method for antimony, 27	Cobalt, detection of, general procedure, 168 ammonium sulphocyanate test for, 166 dieyandiamidine sulphate test for, 166 potassium nitrite, potassium sulphocyanate tests, 166 estiniation, general procedures: gravimetric, deposition of the metal by electrolysis, 170
Cinchonine potassium iodide method for determining hismuth, 77 reagent for tungsten det., 560 Cinders, chlorine in, 144 Citrie acid, analysis of, 1549 reagent for calcium determination, 106 Clark on tin, 525–536 Clark's modification of Mohr's method for antimony, 27 method for separation of antimony	Cobalt, detection of, general procedure, 168 ammonium sulphocyanate test for, 166 dicyandiamidine sulphate test for, 166 potassium nitrite, potassium sulphocyanate tests, 166 estimation, general procedures: gravimetric, deposition of the metal by electrolysis, 170 nitro-beta-naphthol method, 169
Cinehonine potassium iodide method for determining hismuth, 77 reagent for tungsten det., 560 Cinders, chlorine in, 144 Citrie acid, analysis of, 1549 reagent for calcium determination, 106 Clark on tin, 525–536 Clark's modification of Mohr's method for antimony, 27 method for separation of antimony from tin, 22	Cobalt, detection of, general procedure, 168 ammonium sulphocyanate test for, 166 dieyandiamidine sulphate test for, 166 potassium nitrite, potassium sulphocyanate tests, 166 estination, general procedures: gravimetrie, deposition of the metal by electrolysis, 170 nitro-beta-naphthol method, 169 potassium nitrite method, 169
Cinehonine potassium iodide method for determining hismuth, 77 reagent for tungsten det., 560 Cinders, chlorine in, 144 Citrie acid, analysis of, 1549 reagent for calcium determination, 106 Clark on tin, 525-536 Clark's modification of Mohr's method for antimony, 27 method for separation of antimony from tin, 22 Classen, deposition of gold, 231	Cobalt, detection of, general procedure, 168 ammonium sulphocyanate test for, 166 dieyandiamidine sulphate test for, 166 potassium nitrite, potassium sulphocyanate tests, 166 estination, general procedures: gravimetric, deposition of the metal by electrolysis, 170 nitro-beta-naphthol method, 169 potassium nitrite method, 169 pyrophosphate method, 174
Cinehonine potassium iodide method for determining hismuth, 77 reagent for tungsten det., 560 Cinders, chlorine in, 144 Citrie acid, analysis of, 1549 reagent for calcium determination, 106 Clark on tin, 525-536 Clark's modification of Mohr's method for antimony, 27 method for separation of antimony from tin, 22 Classen, deposition of gold, 231 and Henz method for determining tin,	Cobalt, detection of, general procedure, 166 ammonium sulphocyanate test for, 166 dicyandiamidine sulphate test for, 166 potassium nitrite, potassium sulphocyanate tests, 166 estinuation, general procedures: gravimetric, deposition of the metal by electrolysis, 170 nitro-beta-naphthol method, 169 potassium nitrite method, 169 pyrophosphate method, 174 yolumetric method for, 175
Cinchonine potassium iodide method for determining hismuth, 77 reagent for tungsten det., 560 Cinders, chlorine in, 144 Citrie acid, analysis of, 1549 reagent for calcium determination, 106 Clark on tin, 525-536 Clark's modification of Mohr's method for antimony, 27 method for separation of antimony from tin, 22 Classen, deposition of gold, 231 and Henz method for determining tin, 536	Cobalt, detection of, general procedure, 168 ammonium sulphocyanate test for, 166 dieyandiamidine sulphate test for, 166 potassium nitrite, potassium sulphocyanate tests, 166 estimation, general procedures: gravimetric, deposition of the metal by electrolysis, 170 nitro-beta-naphthol method, 169 potassium nitrite method, 169 pyrophosphate method, 174 volumetric method for, 175 estimation, special procedures:
Cinehonine potassium iodide method for determining hismuth, 77 reagent for tungsten det., 560 Cinders, chlorine in, 144 Citrie acid, analysis of, 1549 reagent for calcium determination, 106 Clark on tin, 525-536 Clark's modification of Mohr's method for antimony, 27 method for separation of antimony from tin, 22 Classen, deposition of gold, 231 and Henz method for determining tin, 536 and Reiss method for determining anti-	Cobalt, detection of, general procedure, 168 ammonium sulphocyanate test for, 166 dieyandiamidine sulphate test for, 166 potassium nitrite, potassium sulphocyanate tests, 166 estination, general procedures: gravimetrie, deposition of the metal by electrolysis, 170 nitro-beta-naphthol method, 169 potassium nitrite method, 169 pyrophosphate method, 174 volumetrie method for, 175 estimation, special procedures: determination in cobalt oxide, 171
Cinehonine potassium iodide method for determining hismuth, 77 reagent for tungsten det., 560 Cinders, chlorine in, 144 Citrie acid, analysis of, 1549 reagent for calcium determination, 106 Clark on tin, 525-536 Clark's modification of Mohr's method for antimony, 27 method for separation of antimony from tin, 22 Classen, deposition of gold, 231 and Henz method for determining tin, 536 and Reiss method for determining antimony, 24	Cobalt, detection of, general procedure, 168 ammonium sulphocyanate test for, 166 dieyandiamidine sulphate test for, 166 potassium nitrite, potassium sulphocyanate tests, 166 estimation, general procedures: gravimetric, deposition of the metal by electrolysis, 170 nitro-beta-naphthol method, 169 potassium nitrite method, 169 pyrophosphate method, 174 volumetric method for, 175 estimation, special procedures:
Cinchonine potassium iodide method for determining hismuth, 77 reagent for tungsten det., 560 Cinders, chlorine in, 144 Citrie acid, analysis of, 1549 reagent for calcium determination, 106 Clark on tin, 525-536 Clark's modification of Mohr's method for antimony, 27 method for separation of antimony from tin, 22 Classen, deposition of gold, 231 and Henz method for determining tin, 536 and Reiss method for determining antimony, 24 Clay analysis, 1786-1788	Cobalt, detection of, general procedure, 168 ammonium sulphocyanate test for, 166 dieyandiamidine sulphate test for, 166 potassium nitrite, potassium sulphocyanate tests, 166 estination, general procedures: gravimetric, deposition of the metal by electrolysis, 170 nitro-beta-naphthol method, 169 potassium nitrite method, 169 pyrophosphate method, 174 volumetrie method for, 175 estimation, special procedures: determination in cobalt oxide, 171 in copper (metallic), 172
Cinehonine potassium iodide method for determining hismuth, 77 reagent for tungsten det., 560 Cinders, chlorine in, 144 Citrie acid, analysis of, 1549 reagent for calcium determination, 106 Clark on tin, 525-536 Clark's modification of Mohr's method for antimony, 27 method for separation of antimony from tin, 22 Classen, deposition of gold, 231 and Henz method for determining tin, 536 and Reiss method for determining antimony, 24 Clay analysis, 1786-1788 alkalies, 1787	Cobalt, detection of, general procedure, 168 ammonium sulphocyanate test for, 166 dieyandiamidine sulphate test for, 166 potassium nitrite, potassium sulphocyanate tests, 166 estimation, general procedures: gravimetric, deposition of the metal by electrolysis, 170 nitro-beta-naphthol method, 169 potassium nitrite method, 169 pyrophosphate method, 174 volumetric method for, 175 estimation, special procedures: determination in cobalt oxide, 171 in copper (metallie), 172 in enamels, 173 in ferro-cobalt, 172
Cinchonine potassium iodide method for determining hismuth, 77 reagent for tungsten det., 560 Cinders, chlorine in, 144 Citrie acid, analysis of, 1549 reagent for calcium determination, 106 Clark on tin, 525-536 Clark's modification of Mohr's method for antimony, 27 method for separation of antimony from tin, 22 Classen, deposition of gold, 231 and Henz method for determining tin, 536 and Reiss method for determining antimony, 24 Clay analysis, 1786-1788 alkalies, 1787 silica, state of, 1788 titanium, 1787	Cobalt, detection of, general procedure, 168 ammonium sulphocyanate test for, 166 dieyandiamidine sulphate test for, 166 potassium nitrite, potassium sulphocyanate tests, 166 estiniation, general procedures: gravimetric, deposition of the metal by electrolysis, 170 nitro-beta-naphthol method, 169 potassium nitrite method, 169 pyrophosphate method, 174 volumetric method for, 175 estimation, special procedures: determination in cobalt oxide, 171 in copper (metallic), 172 in enamels, 173
Cinchonine potassium iodide method for determining hismuth, 77 reagent for tungsten det., 560 Cinders, chlorine in, 144 Citrie acid, analysis of, 1549 reagent for calcium determination, 106 Clark on tin, 525-536 Clark's modification of Mohr's method for antimony, 27 method for separation of antimony from tin, 22 Classen, deposition of gold, 231 and Henz method for determining tin, 536 and Reiss method for determining antimony, 24 Clay analysis, 1786-1788 alkalies, 1787 silica, state of, 1788 titanium, 1787	Cobalt, detection of, general procedure, 168 ammonium sulphocyanate test for, 166 dieyandiamidine sulphate test for, 166 potassium nitrite, potassium sulphocyanate tests, 166 estination, general procedures: gravimetrie, deposition of the metal by electrolysis, 170 nitro-beta-naphthol method, 169 potassium nitrite method, 169 pyrophosphate method, 174 volumetrie method for, 175 estimation, special procedures: determination in cobalt oxide, 171 in copper (metallie), 172 in enamels, 173 in ferro-cobalt, 172 in lead (metallie), 172
Cinehonine potassium iodide method for determining hismuth, 77 reagent for tungsten det., 560 Cinders, chlorine in, 144 Citrie acid, analysis of, 1549 reagent for calcium determination, 106 Clark on tin, 525-536 Clark's modification of Mohr's method for antimony, 27 method for separation of antimony from tin, 22 Classen, deposition of gold, 231 and Henz method for determining tin, 536 and Reiss method for determining antimony, 24 Clay analysis, 1786-1788 alkalies, 1787 silica, state of, 1788	Cobalt, detection of, general procedure, 168 ammonium sulphocyanate test for, 166 dieyandiamidine sulphate test for, 166 potassium nitrite, potassium sulphocyanate tests, 166 estimation, general procedures: gravimetric, deposition of the metal by electrolysis, 170 nitro-beta-naphthol method, 169 potassium nitrite method, 174 volumetric method for, 175 estimation, special procedures: determination in cobalt oxide, 171 in copper (metallic), 172 in lead (metallic), 172 in lead (metallic), 172 in metallic cobalt, 172
Cinchonine potassium iodide method for determining hismuth, 77 reagent for tungsten det., 560 Cinders, chlorine in, 144 Citrie acid, analysis of, 1549 reagent for calcium determination, 106 Clark on tin, 525-536 Clark's modification of Mohr's method for antimony, 27 method for separation of antimony from tin, 22 Classen, deposition of gold, 231 and Henz method for determining tin, 536 and Reiss method for determining antimony, 24 Clay analysis, 1786-1788 alkalies, 1787 silica, state of, 1788 titanium, 1787 Cleveland cup for fire test of lubricating oils, 1120	Cobalt, detection of, general procedure, 168 ammonium sulphocyanate test for, 166 dieyandiamidine sulphate test for, 166 potassium nitrite, potassium sulphocyanate tests, 166 estination, general procedures: gravimetric, deposition of the metal by electrolysis, 170 nitro-beta-naphthol method, 169 potassium nitrite method, 174 volumetrie method for, 175 estimation, special procedures: determination in cobalt oxide, 171 in copper (metallie), 172 in enamels, 173 in ferro-cobalt, 172 in lead (metallie), 172 in metallic cobalt, 172 in metallic nickel, 173 in ores, 173 in steel, 174
Cinchonine potassium iodide method for deternining hismuth, 77 reagent for tungsten det., 560 Cinders, chlorine in, 144 Citrie acid, analysis of, 1549 reagent for calcium determination, 106 Clark on tin, 525-536 Clark's modification of Mohr's method for antimony, 27 method for separation of antimony from tin, 22 Classen, deposition of gold, 231 and Henz method for determining tin, 536 and Reiss method for determining antimony, 24 Clay analysis, 1786-1788 alkalies, 1787 silica, state of, 1788 titanium, 1787 Cleveland cup for fire test of lubricating oils, 1120 open cup app., 1118d Cloud and pour points, oil tests, 1118	Cobalt, detection of, general procedure, 168 ammonium sulphocyanate test for, 166 dieyandiamidine sulphate test for, 166 potassium nitrite, potassium sulphocyanate tests, 166 estiniation, general procedures: gravimetric, deposition of the metal by electrolysis, 170 nitro-beta-naphthol method, 169 potassium nitrite method, 169 pyrophosphate method, 174 volumetric method for, 175 estimation, special procedures: determination in cobalt oxide, 171 in copper (metallic), 172 in enamels, 173 in ferro-cobalt, 172 in lead (metallic), 172 in metallic cobalt, 172 in metallic nickel, 172 in ores, 173 in steel, 174 perborate method for, 175
Cinchonine potassium iodide method for deternining hismuth, 77 reagent for tungsten det., 560 Cinders, chlorine in, 144 Citrie acid, analysis of, 1549 reagent for calcium determination, 106 Clark on tin, 525-536 Clark's modification of Mohr's method for antimony, 27 method for separation of antimony from tin, 22 Classen, deposition of gold, 231 and Henz method for determining tin, 536 and Reiss method for determining antimony, 24 Clay analysis, 1786-1788 alkalies, 1787 silica, state of, 1788 titanium, 1787 Cleveland cup for fire test of lubricating oils, 1120 open cup app., 1118d Cloud and pour points, oil tests, 1118	Cobalt, detection of, general procedure, 168 ammonium sulphocyanate test for, 166 dieyandiamidine sulphate test for, 166 potassium nitrite, potassium sulphocyanate tests, 166 estination, general procedures: gravimetric, deposition of the metal by electrolysis, 170 nitro-beta-naphthol method, 169 potassium nitrite method, 174 volumetrie method for, 175 estimation, special procedures: determination in cobalt oxide, 171 in copper (metallie), 172 in enamels, 173 in ferro-cobalt, 172 in lead (metallie), 172 in metallic cobalt, 172 in metallic nickel, 173 in ores, 173 in steel, 174
Cinehonine potassium iodide method for determining hismuth, 77 reagent for tungsten det., 560 Cinders, chlorine in, 144 Citrie acid, analysis of, 1549 reagent for calcium determination, 106 Clark on tin, 525-536 Clark's modification of Mohr's method for antimony, 27 method for separation of antimony from tin, 22 Classen, deposition of gold, 231 and Henz method for determining tin, 536 and Reiss method for determining antimony, 24 Clay analysis, 1786-1788 alkalies, 1787 silica, state of, 1788 titanium, 1787 Cleveland cup for fire test of lubricating oils, 1120 open cup app., 1118d	Cobalt, detection of, general procedure, 168 ammonium sulphocyanate test for, 166 ammonium sulphocyanate test for, 166 dieyandiamidine sulphate test for, 166 potassium nitrite, potassium sulphocyanate tests, 166 estimation, general procedures: gravimetrie, deposition of the metal by electrolysis, 170 nitro-beta-naphthol method, 169 potassium nitrite method, 174 volumetrie method for, 175 estimation, special procedures: determination in cobalt oxide, 171 in copper (metallie), 172 in enamels, 173 in ferro-cobalt, 172 in metallic cobalt, 172 in metallic nickel, 172 in ores, 173 in steel, 174 perborate method for, 175 preparation and solution of the sample, metallic cobalt, nickel, and cobalt
Cinehonine potassium iodide method for determining hismuth, 77 reagent for tungsten det., 560 Cinders, chlorine in, 144 Citrie acid, analysis of, 1549 reagent for calcium determination, 106 Clark on tin, 525-536 Clark's modification of Mohr's method for antimony, 27 method for separation of antimony from tin, 22 Classen, deposition of gold, 231 and Henz method for determining tin, 536 and Reiss method for determining antimony, 24 Clay analysis, 1786-1788 alkalies, 1787 silica, state of, 1788 titanium, 1787 Cleveland cup for fire test of lubricating oils, 1120 open cup app., 1118d Cloud and pour points, oil tests, 1118 Coal and fuel, methods of analysis, 1616-	Cobalt, detection of, general procedure, 168 ammonium sulphocyanate test for, 166 dieyandiamidine sulphate test for, 166 potassium nitrite, potassium sulphocyanate tests, 166 estimation, general procedures: gravimetric, deposition of the metal by electrolysis, 170 nitro-beta-naphthol method, 169 potassium nitrite method, 174 volumetrie method for, 175 estimation, special procedures: determination in cobalt oxide, 171 in copper (metallic), 172 in enamels, 173 in ferro-cobalt, 172 in lead (metallic), 172 in metallic cobalt, 172 in metallic cobalt, 172 in steel, 174 perborate method for, 175 preparation and solution of the sample, metallic cobalt, nickel, and cobalt alloys, cobalt oxides, ores con-
Cinehouine potassium iodide method for determining hismuth, 77 reagent for tungsten det., 560 Cinders, chlorine in, 144 Citrie acid, analysis of, 1549 reagent for calcium determination, 106 Clark on tin, 525-536 Clark's modification of Mohr's method for antimony, 27 method for separation of antimony from tin, 22 Classen, deposition of gold, 231 and Henz method for determining tin, 536 and Reiss method for determining antimony, 24 Clay analysis, 1786-1788 alkalies, 1787 silica, state of, 1788 titanium, 1787 Cleveland cup for fire test of lubricating oils, 1120 open cup app., 1118d Cloud and pour points, oil tests, 1118 Coal and fuel, methods of analysis, 1616- 1660 ash, determination of, 1618 anthracite, 1641	Cobalt, detection of, general procedure, 168 ammonium sulphocyanate test for, 166 dieyandiamidine sulphate test for, 166 potassium nitrite, potassium sulphocyanate tests, 166 estimation, general procedures: gravimetric, deposition of the metal by electrolysis, 170 nitro-beta-naphthol method, 169 potassium nitrite method, 169 pyrophosphate method, 174 volumetric method for, 175 estimation, special procedures: determination in cobalt oxide, 171 in copper (metallic), 172 in enamels, 173 in ferro-cobalt, 172 in lead (metallic), 172 in metallic cobalt, 172 in metallic nickel, 172 in ores, 173 in steel, 174 perborate method for, 175 preparation and solution of the sample, metallic cobalt, nickel, and cobalt alloys, cobalt oxides, ores containing cobalt, 167
Cinehonine potassium iodide method for determining hismuth, 77 reagent for tungsten det., 560 Cinders, chlorine in, 144 Citrie acid, analysis of, 1549 reagent for calcium determination, 106 Clark on tin, 525-536 Clark's modification of Mohr's method for antimony, 27 method for separation of antimony from tin, 22 Classen, deposition of gold, 231 and Henz method for determining tin, 536 and Reiss method for determining antimony, 24 Clay analysis, 1786-1788 alkalics, 1787 silica, state of, 1788 titanium, 1787 Cleveland cup for fire test of lubricating oils, 1120 open cup app., 1118d Cloud and pour points, oil tests, 1118 Coal and fuel, methods of analysis, 1616- 1660 ash, determination of, 1618	Cobalt, detection of, general procedure, 168 ammonium sulphocyanate test for, 166 dieyandiamidine sulphate test for, 166 potassium nitrite, potassium sulphocyanate tests, 166 estimation, general procedures: gravimetric, deposition of the metal by electrolysis, 170 nitro-beta-naphthol method, 169 potassium nitrite method, 174 volumetrie method for, 175 estimation, special procedures: determination in cobalt oxide, 171 in copper (metallic), 172 in enamels, 173 in ferro-cobalt, 172 in lead (metallic), 172 in metallic cobalt, 172 in metallic cobalt, 172 in steel, 174 perborate method for, 175 preparation and solution of the sample, metallic cobalt, nickel, and cobalt alloys, cobalt oxides, ores con-

Cobalt, sep. ammonium sulphide group from alkaline carths and alkalics,	Conradson's method for carbon in oils
168 cobalt and nickel from manganese,	Constant temperature bath, 190 Constants of various oils, 1147-1149, 1173
168	of waxes, 1150
cobalt from nickel and from zinc,	Container for gas sample (Fig. 112), 1233 Conversion factors, Baumé to specific
Cocain, 1735	gravity, 701
Cochincul indicator, 744	of compounds, alphabetical arrange
Codein, 1736	ment, 679
Cohen and Inouyo app. for solubility det.,	Engler, Redwood, and Saybolt times—comparison, 1151
Cold test for lubricating oils, 1119	temperature, Centigrado to Fahren-
Color in hutter, detection of, 1144	heit, 700
Color comparitor or camera for det. car-	volume, weight and energy, 712-713
bon in steel (Fig. 26), 129	weights and measures customary and
Color, organic, in red and brown pig-	metric systems, 702
ments, 1191	Converter efficiency NH ₃ -NO ₂ , 361c
Color test in turpentine, 1173	Cooper-Hewitt mercury light (Fig. 44)
Color test of water, 1410	285
Colorimeter (Figs. 26a, 43, 69, 70), 165,	Copper anode slines, platinum and pal-
283, 546, 548	ladium in, 386
Colorimetric determination of aluminum,	antimony traces in, 32
14	Copper comb., distinction of, 208–210
of ammonia, 345	Conner dataction of general presculure
	Copper, detection of, general procedure
of bismuth, 78	hydrogen sulphide test, flame test
of carbon, 128	reduction tests, 177
of chromium, 162, 1368f	estimation, general procedures:
of copper, 197, 198, 199	gravimetric, copper oxide method, 183
of fluorine, 220	cuprous thiocyanate method, 181
of gold, 233	183
of iron 950 050 611	
of iron, 258, 259, 611	electrolytic methods, preliminary
of lead, 282	remarks, 185
of manganese, 305	rapid methods, 187
of titanium, 545, 547, 550	slow methods, 189
Columbium, detection of, 575	electrolysis, effect of impurities
estimation, procedure, 577	on, 191
occurrence, 475	precautions and notes on pro-
separation from antimony, silica, tin,	cedure, 191
tungsten, 577	removal of deposit, 191
isolation of columbium and tantalum	hydrogen reduction method, 205
oxides, 576	volumetrie methods, potassium cya-
Coltman and Cunningham on manganese	104
det., 303	mac procedure, 184
Combination methods, silver determina-	nide procedure, 194 colorimetric method Cu in steel
tion, 447	colorimetric method Cu in steel
	colorimetric method Cu in steel 1308d
	colorimetric method Cu in steel 1308d potassium iodide method, 17b
Combinations of copper, det. of, 208	colorimetric method Cu in steel 1308d potassium iodide method, 17b 193–195
hypothetical in water, 1441c	colorimetric method Cu in steel 1308d potassium iodide method, 17b 193-195 permanganate method, 195
	colorimetric method Cu in steel 1308d potassium iodide method, 17b 193–195
hypothetical in water, 1441c Combined sulphuric acid in aluminum	colorimetric method Cu in steel 1308d potassium iodide method, 17b 193-195 permanganate method, 195 Demorest's method for, 196
hypothetical in water, 1441c Combined sulphuric acid in aluminum salts, 12	colorimetric method Cu in steel 1308d potassium iodide method, 1719 193–195 permanganate method, 195 Demorest's method for, 196 Gerigue's method for, 196
hypothetical in water, 1441c Combined sulphuric acid in aluminum salts, 12 in soluble sulphates, 505	colorimetric method Cu in steel 1308d potassium iodide method, 171, 193–195 permanganate method, 195 Demorest's method for, 196 Gerigue's method for, 196 Volhard's method for, 196
hypothetical in water, 1441c Combined sulphuric acid in aluminum salts, 12 in soluble sulphates, 505 Combustion furnace for carbon determi-	colorimetric method Cu in steel 1308d potassium iodide method, 17b 193-195 permanganate method, 195 Demorest's method for, 196 Gerigue's method for, 196 Volhard's method for, 196 estimation, special procedures:
hypothetical in water, 1441c Combined sulphuric acid in aluminum salts, 12 in soluble sulphates, 505 Combustion furnace for carbon determi- tion, 112, 1352, 1356	colorimetric method Cu in steel 1308d potassium iodide method, 171s 193-195 permanganate method, 195 Demorest's method for, 196 Gerigue's method for, 196 Volhard's method for, 196 estimation, special procedures: determination of copper in alloys and
hypothetical in water, 1441c Combined sulphuric acid in aluminum salts, 12 in soluble sulphates, 505 Combustion furnace for carbon determition, 112, 1352, 1356 hinged type (Fig. 32a), 206	colorimetric method Cu in steel 1308d potassium iodide method, 171, 193-195 permanganate method, 195 Demorest's method for, 196 Gerigue's method for, 196 Volhard's method for, 196 estimation, special procedures: determination of copper in alloys and metals, brass and bronze, 1049
hypothetical in water, 1441c Combined sulphuric acid in aluminum salts, 12 in soluble sulphates, 505 Combustion furnace for earbon determition, 112, 1352, 1356 hinged type (Fig. 32a), 206 for assaying, 460	colorimetric method Cu in steel 1308d potassium iodide method, 171, 193-195 permanganate method, 195 Demorest's method for, 196 Gerigue's method for, 196 Volhard's method for, 196 estimation, special procedures: determination of copper in alloys and metals, brass and bronze, 1049
hypothetical in water, 1441c Combined sulphuric acid in aluminum salts, 12 in soluble sulphates, 505 Combustion furnace for earbon determition, 112, 1352, 1356 hinged type (Fig. 32a), 206 for assaying, 460	colorimetric method Cu in steel 1308d potassium iodide method, 171, 193–195 permanganate method, 195 Demorest's method for, 196 Gerigue's method for, 196 Volhard's method for, 196 estimation, special procedures: determination of copper in alloys and metals, brass and bronze, 1049 1053, 1058, 1067, 1071, 1076
hypothetical in water, 1441c Combined sulphuric acid in aluminum salts, 12 in soluble sulphates, 505 Combustion furnace for carbon determition, 112, 1352, 1356 hinged type (Fig. 32a), 206 for assaying, 480 heat of, 719	colorimetric method Cu in steel 1308d potassium iodide method, 17h 193-195 permanganate method, 195 Demorest's method for, 196 Gerigue's method for, 196 Volhard's method for, 196 estimation, special procedures: determination of copper in alloys and metals, brass and bronze, 1049 1053, 1058, 1067, 1071, 1076 1098, 1099, 1106, 1106)
hypothetical in water, 1441c Combined sulphuric acid in aluminum salts, 12 in soluble sulphates, 505 Combustion furnace for carbon determition, 112, 1352, 1356 hinged type (Fig. 32a), 206 for assaying, 460 heat of, 719 method for carbon determination, 112,	colorimetric method Cu in steel 1308d potassium iodide method, 171 193-195 permanganate method, 195 Demorest's method for, 196 Gerigue's method for, 196 Volhard's method for, 196 estimation, special procedures: determination of copper in alloys and metals, brass and bronze, 1049 1053, 1058, 1067, 1071, 1076 1098, 1099, 1106, 1106j in alloys, 1049, 1053, 1058, 1067
hypothetical in water, 1441c Combined sulphuric acid in aluminum salts, 12 in soluble sulphates, 505 Combustion furnace for carbon determi- tion, 112, 1352, 1356 hinged type (Fig. 32a), 206 for assaving, 460 heat of, 719 method for carbon determination, 112, 261, 1352, 1356	colorimetric method Cu in steel 1308d potassium iodide method, 171-193-195, permanganate method, 195 Demorest's method for, 196 Gerigue's method for, 196 Volhard's method for, 196 estimation, special procedures: determination of copper in alloys and metals, brass and bronze, 1049-1053, 1058, 1067, 1071, 1076-1098, 1099, 1106, 1106; in alloys, 1049, 1053, 1058, 1067, 1071, 1076, 1098, 1099, 1106
hypothetical in water, 1441c Combined sulphuric acid in aluminum salts, 12 in soluble sulphates, 505 Combustion furnace for earbon determition, 112, 1352, 1356 hinged type (Fig. 32a), 206 for assaying, 460 heat of, 719 method for carbon determination, 112, 261, 1352, 1356 train. See C det. in steel.	colorimetric method Cu in steel 1308d potassium iodide method, 171, 193–195 permanganate method, 195 Demorest's method for, 196 Gerigue's method for, 196 Volhard's method for, 196 estimation, special procedures: determination of copper in alloys and metals, brass and bronze, 1049 1053, 1058, 1067, 1071, 1076 1098, 1099, 1106, 1106j in alloys, 1049, 1053, 1058, 1067 1071, 1076, 1098, 1099, 1106 1106j
hypothetical in water, 1441c Combined sulphuric acid in aluminum salts, 12 in soluble sulphates, 505 Combustion furnace for carbon determition, 112, 1352, 1356 hinged type (Fig. 32a), 206 for assaying, 460 heat of, 719 method for carbon determination, 112, 261, 1352, 1356 train. See C det. in steel. Commercial aluminum ores, valuation of,	colorimetric method Cu in steel 1308d potassium iodide method, 17b 193-195 permanganate method, 195 Demorest's method for, 196 Gerigue's method for, 196 Volhard's method for, 196 estimation, special procedures: determination of copper in alloys and metals, brass and bronze, 1049 1053, 1058, 1067, 1071, 1076 1098, 1099, 1106, 1106j in alloys, 1049, 1053, 1058, 1067, 1071, 1076, 1098, 1099, 1106 1106j in babbit metal, 211
hypothetical in water, 1441c Combined sulphuric acid in aluminum salts, 12 in soluble sulphates, 505 Combustion furnace for earbon determition, 112, 1352, 1356 hinged type (Fig. 32a), 206 for assaying, 460 heat of, 719 method for carbon determination, 112, 261, 1352, 1356 train. See C det. in steel.	colorimetric method Cu in steel 1308d potassium iodide method, 171, 193–195 permanganate method, 195 Demorest's method for, 196 Gerigue's method for, 196 Volhard's method for, 196 estimation, special procedures: determination of copper in alloys and metals, brass and bronze, 1049 1053, 1058, 1067, 1071, 1076 1098, 1099, 1106, 1106j in alloys, 1049, 1053, 1058, 1067 1071, 1076, 1098, 1099, 1106 1106j

Copper, in brass, 211	Corning Glass Works method for Se In
in gun metal, A. S. T. M., 1058	glass, 440b
in lead, metallic, 290	Correction factors in calorimetry, 1640,
in manganese bronze, 1047	1652
in molybdenite, 326	Corrosion, acid waters, calculation of,
in ores, 193a	1441b
in refined copper, 205	tests of oils, 1126
in selenium, commercial, 439	Cottonseed oil, test for (see Oils), 1136
in slag, 1613	Coulomb, definition of, 708
in steel, 181, 1368c	Coye, J. S., electrometric methods, 1667
in tungsten ores and concentrates,	Craig's method, modified, for basic
568	alumina or free acid in aluminum
in water, 1437	salts, 12
in wulfcnite, 327	Crank case oil, constants, 1145
impurities in blister and refined cop-	Crawford-Lenher colorimetric method for
per:	titanium, 550
antimony, arsenic, selenium, and tel-	Crook's select methods of analysis (ref-
lurium, 202, 240c arsenic, 37, 202	erence), 138
arsenic, 37, 202	Crucible, Gooch, preparation of, 596d
bismuth and iron, 200	Crushers and grinders, 1011
chlorine in coment copper and copper	Culture media for water bacteria, 1456
ores, 206	Cunningham and Coltman on det. of
cobalt, lead, nickel and zinc, 201	manganese, 303
oxygen and sulphur, 204	Cupel in fire assay, 468
phosphorus, 205	Cupferron method for iron, 250
selenium and tellurium, 440c	reagent, 746
industrial application of methods, 177	Cupric-potassium-chloride reagent, prepa-
occurrence, 177	ration of, 111
preparation and solution of the sample,	Cupro-vanadium, 596
alloys, cast iron, steel, matte, slag,	Cuprous chloride, ammoniaeal and acid,
iron ores, and iron ore briquettes	preparation for gas analysis, 1278
and metals, sulphide ores, copper	-sulphocyanate method for determining
glance, copper pyrites, and iron	copper, 181, 184
pyrites, 178-181	Cynnide method for copper, 194
separations, deposition by a more posi-	Cyanide process for tin ores, 526
tive metal, 182a, 184	Cyanide, silver determination as, 455
precipitation as copper thiocyanate,	separation from chloride and thiocya-
181, 183	nate, 154
removal of members of subsequent	volunctric determination of silver, 456
groups, 182a removal of arsenic, antimony, bis-	Cyanide, Liebig's method for det., 131
	Volhard's method for det., 132
muth, lead, silver, tin, 182b	Cyanide and thiocyanate, det. of, 132
removal of cadmium, 182b	Cyanide solution, assay of, 486 Cyanogen, detection of, 131
removal of Se and Te, 182a	Cylinder oil, constants, 1145
solubility of the metal, 178	Cymiaci on, constants, 1140
traces, colorimetric methods for deter-	Davisson's scrubber-ammonia distill., 351
mining, 197–199 ammonia method, 198	Decomposition of sample, chapter on,
ferrocyanide method, 198	1032–1035b
hydrogen sulphide method, 199	reagents used, 1033
potassium ethyl xanthate method,	Definitions of special terms, 708, 1200
197	Dely weighing tube (Fig. 81), 1498
Copper bullion, assay of, 482	Demorest's method for det. copper, 196
Copper pyrites, 179	Deniges and Chelle bromine test, 92
sulphate for determining hydrocyanic	Denigés' cyanide method for determining
acid, 130	silver, 462
standard solutions (see also "rea-	Derby,
gents "), 193, 194, 198	chapter on gold, 228
Copper slimes, Au, Ag, Pd, Pt in, 386	chapter on silver, 439
Copper sulphate treatment of water, 1452	and Scott, chapter on copper, 177
Copper-zinc alloys, metallography of, 1710	Deshey's method for manganese in steel,
Corn oil, constants, 1148	266

Detonators, electric, analysis of, 1396	Earl of Berkeley solubility app., 1472
Devarda apparatus for determining ni-	Ebonite in rubber, 1580
trates (Fig. 51), 347	Edgar's method of reduction of vanadium
Devarda's method, modified determina-	with sulphur dioxide, 321
tion of nitrates by, 346	volumetric determination of vanadium,
Deville on iridium, 390	arsenic or antimony, in pres-
Diazo reaction, 1324	ence of one another, 592
Dichromate of potassium method for iron,	of vanadium and molybdenum, in
253, 255	presence of one another, 591
titration in determining chromium, 162,	of vanadium and chromium acids,
164a	in presence of one another, 593
Dicyandiamidine sulphate test for cobalt,	
	Edible fats (sec Oils), 1143
166 B: 18 (1 14 B) (2 2221	examination of, 1146
Dichl's method for PbO ₂ , 290d	Eggertz's method for carbon in steel, 130
Didymium in cerium salts, 138	Elaidin test for oils, 1126
Dictz and Margosches method for deter-	Electric Heating Apparatus Co., furnace,
mining iodine, 241	hinged design, 206
Diluting mixtures, formulæ for, 1496, 1533	
	Electricity, units of, 708
Dimethyl glyoxime method for nickel, 333	Electrolyte, test for copper in, after elec-
test for nickel, 329, 1368c, 1368d	trolysis, 191
Dioxide of manganese, separation of, by	Electrolytic determination of antimony, 24
means of bromine, 301	bismuth, 76
Diphenylamine in smokeless powder, 1405	cadmium, 102
Diphenylamine indicator in chromium	cobalt, 170
det., 164a	copper, 185
in iron det., 255, 257b	gold, 122
Diphenylamine test for nitrates, 338	lead, 275b
Diphenyl carbazide test for chromium	mercury, 310
(chromate), 156	nickel, 335
determination of chromium, 163	platinum, 381
preparation of, 163	silver, 436
Diphenyl-endo-anilo-hydro-triazole (ni-	
	tin, 536
tron) incthod for ultrates, 342, 345	zine, 599
Distillation of arsenous chloride, 38-39b	Electro Metallurgical Co. Methods, 280-
nicthod for separating selenium and tel-	282, 322
lurium, 432	Electrometric det., 1663–1682
method for dct. ethyl alcohol, 1743	description of Kelley app., 1669, 1673-
test for oils, 1111	1674
Distinction of copper compounds, 208	methods of analysis, 1677
Dittrich, small amounts of chromium, 162	
	method for chromium in steel, 1677
Dividing pipette (Figs. 30 and 42), 190,	for manganese in steel, 1680
271	for vanadium in steel, 1679
Dodge on the det. of red lead, 290d	for vanadium and chromium, 1681
Dolomites, 105, 110	oxidation potential, 1671
Dolc, field assay of water, 1441d	Electromotive force, definition of, 708
Dole, field assay of water, 1441d Donnan and White app. for solubility	series of elements, table of, 659
det., 1475	Elliott apparatus for gas analysis (Fig.
Dow's ductility test for bituminous sub.,	121), 1244
1302	Emcrson's calorimeter, 1625
Dowsett's factory test for gold, 234	Emulsions, bituminous, 1349
Drushel, W. A., Elston, C. M., on sulphur	Enamel, cobalt determination in, 173
det., 520	Engine oil, constants, 1145
Drying oils, list of, 1146	Engler flask and tests, 1112-1112d
Drying test of oils, 1141	Engler's method, dist. test of oil, 1111
Duboseq colorimeter, 165	
	viscosimeter, 1114
Dufty's sulphide pyrophosphate method	Engler and Haase on flash test of oil, 1109
for cobalt, 174	Eosin methylene blue agar, 1459
Du Pont's nitrometer, 354, 355	Erg, definition of, 708
Dupre's method for iodine, modified, 243	Erbium, 133
Dust, determination of in gas, 1763	Errors, causes of, in silica determination,
Dynamite, analysis of, 1374	442
Dyne, definition of, 709	in determining the alkaline carths, 57

	<u> </u>
Eschka's method for sulphur in coal, 495	Explosives, extraction with other, 1375,
Esters in alcohol, 1746	1278 1207 1200 1400 1405.
	1376, 1387, 1389, 1400, 1405
Etching test for fluorine (Fig. 33), 212	extraction with water, 1377, 1387, 1390
Ether-alcohol, 1400, 1405	melting point det., 1394
Ether, chromium detection by, 156	moisture in, 1372, 1375, 1381, 1386,
Ether method for separating iron from	1389, 1392, 1393, 1394, 1396, 1404,
sol., 248	1405
Ethyl acetate test for alcohol, 1743	pot. iodide-starch test for nitrocellulose,
alcohol analysis, 1743	1401
Ethylene, properties of, 1227c	sampling of, 1372, 1374, 1380, 1395,
Evaluation of bauxite, 15	1396, 1398, 1399
of fluorspar, 225	solidification point det., 1391, 1392
Evaporation test of Inbricating oils, 1117	stability tests, 1401, 1403, 1405
Evolution apparatus for sulphur deter-	surveillance test, 1406
minution 500 1987	
mination 500, 1367	Extraction of aluminum ores—evaluation
method for antimony, 28a	of, 14
method for sulphur, 500, 1368	
Exit gases, sulphur dioxide in, 1266	Fabrics, separated, examination of, 1344
Explosives, analysis of, 1372-1407	Factors, conversion, 685, 700. See also
ammonia dynamite, 1379	"Tables" in index.
ammonia picrate, 1393	Fairbanks cement testing machine, 1214
black powder, 1372	Fairbanks and Gooch method for molyl-
blasting caps and detonators, 1396	denum, 318
gelatine dynamite, 1380	Futs (see under Oils), 1146
low freezing dynamite, 1381	Fatty acids, table of, 1152
mercury fulminate, 1395	Fatty oils, test for, in lubricating oils, 1121
nitrocellulose, 1399	Febling's solution, 1185, 1188
nitrochlorhydrin, 1383	Ferguson's colorimetric method for bis-
nitroglycerin-dynamite, 1374	muth, 77
nitroglycerin smokeless powders, 1407	electrolytic method for copper, 189,
nitropolyglycerin, 1383	205
nitrostarch, 1389	tables of properties, see Part 11, Vol. 1
	Ferric-alom method for det. phosphorus,
nitrosugars, 1383	
nitrotoluenes, 1381 "permissible" explosives, 1384	1105 Funda ablanda atubing paget 1705
permissible explosives, 1384	Ferric chloride etching reagt., 1705
pierie acid, 1392	Ferric chloride oxidation of organie ni.,
primers, 1398	341
smokeless powder, 1404	for tin, 535
straight dynamite, 1374	reagent for tin, 536
tetryl, 1394	Ferric iron in aluminum salt, 12
	iron, determination with stannous chlo-
trinitrotoluene, 1391	
Explosive ingredients in,	ride, 257
ash in, 1378, 1389, 1392, 1394, 1395,	oxide, determination of iron as, 249
1401	in sand, 448
chlorates in, 1372, 1387	in zine oxide, 1185
chlorides in, 1396	salts, decomposition of iodides with, 241
diphenylamine in, 1405	salt, titanium determination with, 543,
min ambie in 1295 1299	544
gum arabic in, 1385, 1388	Demission and at at 100 1001
insoluble matter, 1378, 1389, 1390, 1393,	Ferrievanide, det. of, 132a, 1201
1394, 1395	Ferro-carbon titanium, determination of
nitrates in, 1373, 1377, 1387, 1390 nitrogen in, 1373, 1377, 1380, 1387,	titanium in, gravimetrie method,
nitrogen in. 1373, 1377, 1380, 1387,	543
1390, 1393, 1402, 1406	determination of titanium in, volu-
maging in 1377	metric method, 544
resins in, 1377	Karragunida solution standardization of
solids in, separation of, 1385	Ferrocyanide solution, standardization of,
starch in, 1378	600, 602, 604, 606b
sugar in, 1388	method for copper, 198
sulphur in, 1373, 1377	for lead, 276
Explosives, tests and sundries,	for zinc, 600-608
extraction with acctone, 1395, 1401,	Ferrocyanide, dct. of, 132a, 1201
1405	Ferromanganese, det. of Mn in, 303b
	Ferrosilicons, 445
extraction with acid, 1378, 1388	a orrosmoons, Tro

24

Ferrouranium, analysis of, 582a Fire test of lubricating oils, 1120 Ferrous amm. sulphate, method for det. for oils, 1110, 1118d, 1127-1128d patrick on antimony, 29 Mn, 1360 Fitzpatrick on antimony Ferrous iron in aluminum, 12 Fixed carbon in coal, 1622 Fixed oils, fats and waxes (see Oils, Fats, reduction of chlorates, 152 and Waxes), 1108 of chromates, 156 Fixed oils and resins in varnish, 1174 test for palladium, 382 Flame, coloration of, by barium, 56 test for platinum, 377 salts for reduction, chronium deterboron, 93 calcium, 104 mination, 161 sulphate method for determining nitric copper, 177 potassium, sodium, casium, lithium, acid, 1512 and rubidium, 401, 403 preparation of reagents, 1514-1516 strontium, 489 Ferrous sulphate method for nitric acid, temperature of, see table, 658 Flash test or point of burning oils, 1109 procedure for determining persulof lubricating oils, 1119 phates, 508 test for nitrates, 338 varnish, 1174 Fleining's gas absorption bulb, 114 Ferro-tungsten alloys, 558 Fluning's method for carbon in steel, typical analysis of, 555 Ferro-vanadium, det. vanadium in, 594, Flowers of sulphur in rubber, 1569, 1585, 1681? method by American Vanadium Co., 1588 see also brimstone, 519 594 Flue dust, Se and Tc in, 440a, 440b Fertilizers, mixed, 404 Fluc gases, 1252 nitrogen in, 339 Fluid measure, table of, 703 organic compounds, 405 Fluoride of potassium reagent, 12 phosphate in, 363 Fluoride of sodium, evaluation of, deterpotash salts in, 404 Fiber. See under Bituminous Sub. mining sodium fluoride, sodium sulphate, sodium thiosulphate, sodium Field assay of water, 1441d chloride, silica, volatile matter, Fillers and modifiers of rubber, 1571 water, 226 organic, in rubber goods, 1569 Filtration app., 1357 dct. of fluorine in, 224 Fluorides, effect on aluminum precipita-Fineness in cement testing, 1205 sulphur det., 519a Finn's method of basicity of white lead, silica determination in presence of, 444 Fluorine, detection of, etching, black filter and hanging drop tests, 212, 213 1182 Fire assay of gold and silver, 466-488 assay slags, 475 assay ton, 409 borax, amount of, 475 estimation, gravinietric, calcium fluoridc method, 216 lead chlorofluoride method, 217 metric methods, co method of Steiger, 220 colorimetrie crucible assay, 471 volumetric crucible charges, 477 calcium acetate method for, 223 cupillation, 478 silicon tetrafluoride method, Offercyanide solutions, 486 copper bullion, 482 definitions, 466 man's, 218 occurrence of, 214 furnaces and equipment, 468-469 preparation of the sample, calcium fluoride, hydrofluoric acid, organic fusing the charge, 476 general outline, 466 substances, siliceous ores and slags gold and silver bullion, 482-484 lead bullion, 482 soluble fluorides, fluorspar, 214, 215 separation, from boric, hydrochloric, phosphoric acids, 216 lead reduction with oxidized ores, 471 from silica, 215 lead reduction with sulphide ores, 472 solubility of salts, 216 Steiger-Merwin colorimetrio method, 220 litharge, amount, 473 parting, 480 reagents for, 466-468 sampling, 470 standard solutions, 220 traces, determination of, 224 scorification assay, 477 sodium carbonate amount, 474 Fluorine in barium ores, 66b weighing and mixing, 476 in alkali fluorides, 224, 226

Fluorspar, valuation of, determining calcium carbonate, calcium fluoride and sidica, 225 Fluosilicic acid, precipitation of barium with, 56 Foaming and priming of water, 1441b Foods, arsenic in, 51 Foot-candle, definition of, 709 Foot-pound, definition of, 709 Foots in linseed oil, 1165 Formaldehyde, detection and estimation of, 1754 Ford-Williams method for det. Mn, 306 Formic acid, analysis of, 1542 in acetic acid, 1545 test for iridium, 388 test for palladium, 383 test for platinum, 377 test for rhodium, 393 Formulæ for determining areas, 703 for diluting mixtures, 1533 for gas velocities, 707 fluorine determination, Merwin's, 222 heat value of coal, 1627. See chapter of gas, 1259, 1281, table 3 iodine value for SO2, Reich test, 1266 lime and soda value in water analysis, 1437 reduction of volume of gas to standard volume, 1265 Forrest's extraction of bit. matter, 1330-1331 Free acid in aluminum salts, 12-13 in presence of iron salts, 1541 test in oils, 1140 Freezing and boiling pt. enrves for H2SO4, 1524 French, D. K., chapter on water analysis, 1409 Frescnius, separation of magnesium and the alkalies (ref.), 407 method for separating barium, calcium, and strontium, 61, 108d method for determining iodine, 242 and Popp, borie acid in meat, 83 Friction test of lubricating oils, 1123 Friedrich's spiral gas washing bottle (Fig. 116), 1237 Fuel gases, 1255 oils, analysis of, 1127 Fuels, analysis of, 1616, 1634 Furning sulphuric acid, analysis of, 1529 equivalent (table), 1539 Furfurol in acetic acid, 1543, 1545 in alcohol, 1746 Furnace methods of assaying, 466 Fusel oil in cthyl alcohol, 1746 Fusibility of coal, 1630 Fusion, heat of, 721

Fusion method for arsenic ores, 35
for potassium bisulphate, 4
for silicon, 17a
for sodium carbonate, 4
for sulphur ores, 495
for titanium ores, 540
for tungsten minerals, 555
of ores with sodium hydroxide, 20
with sodium and potassium carbonate

with sodium and potassium carbonate, 248 Gaillard on NH₃ to HNO₃, 361c Gallon, grains per U. S., 1431 Gang mold for cement (Fig. 99), 1212 Gardner and Schaeffer, chapter on analysis of paints, 1161, 1199
Gas, analysis, 1231-1286 apparatus, absorption bulbs, pipettes, tubes, 1237 measurement of large quantities of gas: anemometer, caponieter, orifice meter, Pitot tube, rotameter, Thomas electric noter, wet meter, 1233, 1236 measurement of small quantities of Ilempel's gas burette, separatory funnel and graduate, 1236 apparatus, analytical, Elliott's apparatus, 1244 llempel's, 1245 Morehead, 1227a Orsat's, 1241 Orsat modified by Briggs and Scott, SO, determination, 1267 sampling tubes, pumps, containers, 1027, 1231–1233 application and interpretation of results, 1252 examination of gases, d tables of, 1238-1240 detection of, gases absorbed by silver nitrate, 1239 by sulphuric acid, 1238 by potassium hydroxide, 1239 unabsorbed, 1240

unabsorbed, 1240
acetylene, det. oxygen, hydrogen,
methane, nitrogene sulphur-containing gases, phosphoric, 1271
air, moisture, carbon dioxide, bacteria, carbon monoxide, ozone,
1273
sulphur dioxide in, 1283

sulphur dioxide in, 1283
chimney and flue gases, carbon dioxide, indicators, temperature determination of, 1252, 1253
electrolytic gas, chlorine and other gases, 1271
helium, analysis of, 1274g-1274i
illuminating gas, 1247
ammonia in, 1261
calorific value of, 1257

Gas—candle-power of, 1256 carbon dioxide in, 1228a, 1262 illuminants, oxygen in, 1228c, 1248 methane and hydrogen in, 1499 naphthalene in, 1262 naphthalene in, 1262 nitrogen in, 1282 nitrogen in, 1282 nitrogen in, 1282 nitrogen in, 1282 nitrogen in, 1282 nitrogen in, 1282 nitrogen in, 1282 sulphur and H.S. in, 1260, 1261 tar in, 1264 industrial gases, earbon dioxide in, 1270 moisture in gases, intrometer method, 1276 noisture in gases, intrometer method, 1276 noisture in gases, intrometer method, 1276 sulphure acid gases, burner gases, 1206 dust determination in, 1256 sulphure acid gases, burner gases, 1206 chorido in, 1765 dust in, 1763 nitrogen oxide in, 1270 solubility of, in liquids, 1487 sulphure acid mist in, 1765 sulphure acid mist in, 1765 sulphure acid mist in, 1765 sulphure dioxide in exit gases, 1266 in indet gases, 1267 Tyndall test of, 1763 general procedure with special apparatus: Elliott, determination of carbon monoxide, earbon dioxide, oxygen, 1244, 1245 by pyrogallato of potassium, 1246 junker's calorimeter, 1257 Orsat, determination of carbon monoxide, carbon dioxide, hydrocarbons, oxygen, 1241, 1243 tables, 1280, 1282 Gas velocity by Potot, formula for, 707 Gasoline, determination of carbon monoxide, earbon dioxide, hydrocarbons, oxygen, 1241, 1243 tables, 1280, 1282 Gas velocity by Potot, formula, 707 Gasoline, determination of carbon doxide determination, 112 Geslaine dynamite, analysis of, 1380 Generator for det. traces of antimony, 29 Gerhardt absorption bulb for carbon doxide determination, 112 Gelatine dynamite, analysis of, 1380 Generator for det. traces of antimony, 29 Gerhardt absorption bulb for carbon doxide determination, 112	w.	
carbon dioxide in, 1228a, 1262 illuminants, oxygen in, 1228c, 1248 methane and hydrogen in, Hempel's and Himman's methods, 1228a-1230, 1248, 1249 naphthalene in, 1262 nitrogen in, 1250 specific gravity of, 1262 sulphur and HsS in, 1260, 1261 tar in, 1264 industrial gases, analysis of, 1227-1230 mite gases, carbon dioxide in, 1270 moisture in gases, 1275 natural gases, 1274a-1274g nitrogen in gases, 1275 natural gases, 1274a-1274g nitrogen in gases, 1274a-1274g nitrogen in gases, 1275 atural gases, burner gases, 1266 dust determination ii, 1256 sulphurie acid gases, burner gases, 1264 dust determination ii, 1256 sulphurie acid mist in, 1765 chlorido in, 1765 dust in, 1763 mitrogen oxide in, 1270 solubility of, in liquids, 1487 sulphurie acid mist in, 1765 sulphure dioxide in exit gases, 1266 in inlet gases, 1267 Tyndall test of, 1763 general procedure with special apparatus: Elliott, determination of carbon monoxide, carbon dioxide, hydrogen combustion, 1247 by phosphorus method, 1246 junker's calorimeter, 1257 Orsat, determination of carbon monoxide, carbon dioxide, hydrogen combustion, 1246 illuminanting gas, 1246 Junker's calorimeter, 1257 Orsat, determination of carbon monoxide, carbon dioxide, hydrogen combustion, 1244 tables, 1280, 1282 Gas velocity by Potot, formula for, 707 Gasoliumes oversion formulæ, 707 Gasoline, determination of carbon monoxide, carbon dioxide, hydrogen carbon, oxygen, 1241, 1243 tables, 1280, 1282 Gas velocity by Potot, formula for, 707 Gasoliumes oversion formulæ, 707 Gasoline, determination of carbon monoxide, carbon dioxide, hydrogen combustion, 1264 1642 test for lubricating oils, 1222 test for lubricating oils, 1222 test for lubricating oils, 1222 test for lubricating oils, 1222 test for lubricating oils, 1222 test for lubricating oils, 1222 test for lubricating oils, 1222 test for lubricating oils, 1222 test for lubricating oils, 1222 test for lubricating oils, 1222 test for lubricating oils, 1222 test for lubricating oils, 1222 test for lubricating oils, 1222 test for lubric	Gas—candle-power of, 1256	Gerigue's method for copper, 196
illuminants, oxygen in, 1228c, 1248 methane and hydrogen in, Hempel's and Hinman's methods, 1228a-1230, 1248, 1249 naphthalene in, 1262 nitrogen in, 1250 specific gravity of, 1262 sulphur and H.S in, 1260, 1261 tar in, 1284 industrial gases, analysis of, 1227-1230 mite gases, carbon dioxide in, 1270 moisture in gases, 1274-1274g nitrogen in gases, 1274-1274g nitrogen in gases, 1276-1270 moisture in gases, 1276-1274g nitrogen in gases, 1276-1276 natural gases, 1274-1274g nitrogen in gases, 1276-1276 quit determination in, 1256 sulphur eacid gases, burner gases, 1266 chlorido in, 1765 dust in, 1763 nitrogen oxide in, 1270 solubility of, in liquids, 1487 sulphur ic acid mist in, 1765 sulphur dioxide in exit gases, 1266 in inlet gases, 1276 Tyndall test of, 1763 general procedure with special apparatus: Elliott, determination of carbon monoxide, carbon dioxide, oxygen, 1244, 1245 Hempel, determination of oxygen by hydrogen combustion, 1247 by phosphorus method, 1246 by pyrogallato of potassium, 1246 illuminating gas, 1246 Junker's calorimeter, 1257 Orsat, determination of carbon monoxide, carbon dioxide, hydrocarbon monoxide, carbon dioxide, by pyrogallato of potassium, 1246 illuminating gas, 1246 Junker's calorimeter, 1257 Orsat, determination of carbon monoxide, carbon dioxide, hydrocarbon monoxide, carbon dioxide, hydrocarbon monoxide, carbon dioxide, hydrocarbon monoxide, carbon dioxide, oxygen, 1241, 1243 tables, 1280, 1282 Cas velocity by Potot, formula for, 707 Gasoliumes conversion formula, 707 Gasoliumes conversion formula, 707 Gasoliumes conversion formula, 707 Gasoliumes conversion formula, 707 Gasoliumes conversion formula, 707 Gasoliumes conversion formula, 707 Gasoliumes conversion formula, 707 Gasoliumes conversion formula, 707 Gasoliumes conversion formula, 707 Gasoliumes conversion formula, 707 Gasoliumes conversion formula, 707 Gasoliumes conversion formula, 707 Gasoliumes conversion formula, 707 Gasoliumes conversion formula, 707 Gasoliumes conversion formula, 707 Gasoliumes conversion formula, 7		
pel's and Himman's methods, 1228a-1230, 1248, 1249 naphthalens in, 1262 nitrogen in, 1250 specific gravity of, 1262 sulphur and H.S in, 1260, 1261 tar in, 1284 industrial gases, analysis of, 1277-1230 mile gases, carbon dioxide in, 1270 moisture in gases, 1275 natural gases, 1274a-1274g mitrogen in gases, 1274a-1274g mitrogen in gases, 1275 natural gases, 1274a-1274g mitrogen in gases, nitrometer method, 1276 golden eric gases, 1266 dust determination in, 1256 sulphurie acid gases, burner gases, 1264 arsenic in, 1765 dust in, 1763 mitrogen oxide in, 1270 solubility of, in liquids, 1487 sulphurie acid mist in, 1763 mitrogen oxide in, 1276 sulphurie dioxide in exit gases, 1266 in inlet gases, 1267 Tyndall test of, 1763 general procedure with special apparatus: Ellictt, determination of carbon monoxide, carbon dioxide, oxygen, 1244, 1245 dby phosphorus method, 1246 by pyrogallato of potassium, 1246 liluminating gas, 1246, 2180, 1282 Gas volucity by Potot, formula for, 707 Cas volumes conversion formulae, 707 Gasoline, determination of carbon monoxide, carbon dioxide, hydrocarbons, oxygen, 1241, 1243 tables, 1280, 1282 Gas volucity by Potot, formula for, 707 Cas volumes conversion formulae, 707 Gasoline, determination of carbon determination, 112 Gelatine dynamite, analysis of, 1380 Generator on malysis of gas, 1231-1282 carbon monoxide in atmospheric air, 219, 1273 on use of sodium pyrogallate (note 1), oxygen in gas, 1240 Gilmore's needles (Fig. 95), 1211 Glass analysis, 1780-1793 density, 1789 determination of Al ₂ O ₄ , Fe ₇ O ₈ , CaO, 1770-1791 alkalics, 1791 Mol ₂ O ₈ , \$1792 BaO and Ca, separations, 1793 factors, 1793 fa	illuminants, oxygen in, 1228c, 1248	
i 1228a-1230, 1248, 1249 naphthalene in, 1262 nitrogen in, 1250 specific gravity of, 1262 sulphur and H.S. in, 1260, 1261 tar in, 1284 industrial gases, analysis of, 1227-1230 mine gases, carbon dioxide in, 1270 moisture in gases, 12745 natural gases, intrometer method, 1276 producer, fuel blast furnace gases, 1266 dust determination in, 1256 sulphure acid gases, burner gases, 1266 dust determination in, 1256 sulphure acid gases, burner gases, 1266 dust in, 1763 nitrogen oxide in, 1270 solubility of, in liquids, 1487 sulphuric acid mist in, 1765 sulphur dioxide in exit gases, 1266 in inlet gases, 1267 Tyndall test of, 1763 general procedure with special apparatus: Elliott, determination of carbon monoxide, carbon dioxide, oxygen, 1244, 1245 Hempel, determination of oxygen by hydrogen combustion, 1247 by phosphorus method, 1246 by pyrogallato of potassium, 1248 illuminating gas, 1246 Junker's calorimeter, 1257 Orsat, determination of carbon monoxide in atmospheric air, 229, 1282 Gas velocity by Potot, formula for, 707 Gas volumes; conversion formulae, 707 Gas volumes; conversion formulae, 707 Gas volumes; conversion formulae, 707 Gas volumes; conversion formulae, 707 Gas volumes; conversion formulae, 707 Geslein absorption bulb for carbon dioxide determination, 457 method for determining silver, 457 Geissler absorption bulb for carbon dioxide determination, 457 method for determining silver, 457 Geissler absorption bulb for carbon dioxide determination, 457 method for determining silver, 457 Geissler absorption bulb for carbon dioxide determination, 457 method for determining silver, 457 Geissler absorption bulb for carbon dioxide determination, 457 method for determining silver, 457 Geissler absorption bulb for carbon dioxide determination, 457 method for determining silver, 457 Geissler absorption bulb for carbon dioxide determination, 457 method for determining silver, 457 Geissler absorption bulb for carbon dioxide, pytrametric method, 231 permanganate method, 231 permanganate method, 231 permanganate method	methane and hydrogen in, Hem-	Gilchrist on iridium, 390
naphthalens in 1282 nitrogen in, 1250 specific gravity of, 1282 sulphur and H.S in, 1260, 1261 tar in, 1284 industrial gases, analysis of, 1227–1230 mise gases, carbon dioxide in, 1270 moisture in gases, 1274a–1274g, nitrogen in gases, 1274a–1274g, nitrogen in gases, 1274a–1274g, nitrogen in gases, parbon dioxide in, 1270 moisture in gases, 1274a–1274g, nitrogen in gases, parbon dioxide, producer, fuel blast furnace gases, 1266 dust determination in, 1256 sulphurie acid gases, burner gases, 1204 arsenic in, 1763 mitrogen oxide in, 1270 solubility of, in liquids, 1487 sulphurie acid mist in, 1763 sulphurie dioxide in exit gases, 1206 in inlet gases, 1267 Tyndall test of, 1763 general procedure with special apparatus: Elliott, determination of carbon monoxide, carbon dioxide, oxygen, 1244, 1245 Hempel, determination of oxygen by hydrogen combustion, 1247 by phosphorus method, 1246 by pyrogallato of potassium, 1246 Junker's calorimeter, 1257 Orsat, determination of carbon monoxide, carbon dioxide, hydrocarbons, oxygen, 1241, 1243 tables, 1280, 1282 Gas volucity by Potot, formula for, 707 Cas volumes; conversion formulue, 707 Gas volumes; conversion formulue, 707 Gas volumes conversion formulue, 707 Cas volucity for the formulue, 708 Cas volucity for the		
nitrogen in, 1250 specific gravity of, 1262 sulphur and H ₂ S in, 1260, 1261 tar in, 1264 industrial gases, analysis of, 1227–1230 mise gases, carbon dioxide in, 1270 moisture in gases, 1275 natural gases, 1274a–1274g nitrogen in gases, nitrometer method, 1276 producer, fuel blast furnace gases, 1266 dust determination iu, 1256 sulphurie acid gases, burner gases, 1264 arsenic in, 1765 dust in, 1763 arsenic in, 1765 dust in, 1763 sulphurie acid gases, burner gases, 1266 in inlet gases, 1267 Tyndall test of, 1763 general procedure with special apparatus: Elliott, determination of carbon monoxide, carbon dioxide, earbon dioxide, earbon dioxide, by pyrogallato of potassium, 1246 illuminating gas, 1246 Junker's calorimeter, 1257 Orsat, determination of carbon monoxide, carbon dioxide, hydrocarbons, oxygen, 1241, 1243 tables, 1280, 1282; Cas velocity by Potot, formula for, 707 Gasoline, determination of carbon monoxide, carbon dioxide, hydrocarbons, oxygen, 1241, 1243 tables, 1280, 1282; cast velocity by Potot, formula for, 707 Gasoline, determination of carbon monoxide, carbon dioxide, hydrocarbons, oxygen, 1241, 1243 tables, 1280, 1282; cast velocity by Potot, formula for, 707 Gasoline, determination of carbon dioxide, hydrocarbons, oxygen, 1241, 1243 tables, 1280, 1282; cast velocity by Potot, formula for, 707 Gasoline, determination of carbon dioxide determination, 457 method for determining silver, 457 Geissler absorption bulb for carbon dioxide determination, 457 method for determining silver, 457 Geissler absorption bulb for carbon dioxide determination, 457 method for determining silver, 457 Geissler absorption bulb for carbon dioxide determination, 457 method for determining silver, 457 Geissler absorption bulb for carbon dioxide determination, 457 method for determining silver, 457 Geissler absorption bulb for carbon dioxide determination, 457 method for determining silver, 457 Geissler absorption bulb for carbon dioxide determination, 457 method for determination of carbon dioxide determination, 457 method		chanter on analysis of gas. 1231–1282
specific gravity of, 1262 sulphur and H ₂ Sin, 1260, 1261 tar in, 1264 industrial gases, analysis of, 1227–1230 mine gases, carbon dioxide in, 1270 moisture in gases, 1275 natural gases, 1274a–1274g nitrogen in gases, 1274a–1274g nitrogen in gases, 1276-1274g nitrogen in gases, parhore gases, 1266 dust determination iu, 1256 sulphurie acid gases, burner gases, 1264 arsenic in, 1765 chlorido in, 1765 dust in, 1763 nitrogen oxide in, 1270 solubility of, in liquids, 1487 sulphurie acid mist in, 1765 dust in, 1763 nitrogen oxide in, 1270 solubility of, in liquids, 1487 sulphurie acid mist in, 1765 sulphur dioxide in exit gases, 1266 in inlet gases, 1267 Tyndall test of, 1763 general procedure with special applaratus: Elliott, determination of carbon monoxide, carbon dioxide, oxygen, 1244, 1245 Hempel, determination of oxygen by hydrogen combustion, 1247 by phosphorus method, 1246 by pyrogallato of potassium, 1246 Junker's calorimeter, 1257 Orsat, determination of carbon monoxide, carbon dioxide, hydrocarbon, oxygen, 1241, 1243 tables, 1280, 1282 Cas volocity by Potot, formula for, 707 Gasoline, determination of carbon monoxide determination of calorific value of, 1642 test for lubricating oils, 1222 tests of, 1123, 1127 Gay-Lussae apparatus (Fig. 59), for silver determination, 457 method for determining silver, 457 Geissler absorption bulb for carbon doxide determination, 457 method for determining silver, 457 Geissler absorption bulb for carbon doxide determination, 457 method for determining of calorific value of, 1642 test for lubricating oils, 1222 tests of, 1123, 1127 Gay-Lussae apparatus (Fig. 59), for silver determination, 457 method for determining oilver, 457 Geissler absorption bulb for carbon doxide determination, 457 method for determining oilver, 457 Geissler absorption bulb for carbon doxide determination, 457 method for determining oilver, 457 Gelatine dynamite, analysis of, 1380 Generator for det. traces of antimony, 29 Gerhardt absorption bulb for carbon dioxide, 424 solubility, 229 Gold bullion, f		carbon monoxide in atmospheric air,
sulphur and Hs in, 1280, 1261 tar in, 1264 industrial gases, analysis of, 1227-1230 mine gases, carbon dioxide in, 1270 moisture in gases, 12744-1274g nitrogen in gases, intrometer method, 1276 producer, fuel blast furnace gases, 1266 dust determination iu, 1256 sulphurie acid gases, burner gases, 1264 dust in, 1763 nitrogen oxide in, 1270 solubility of, in liquids, 1487 sulphurie acid mist in, 1765 sulphur dioxide in exit gases, 1286 in inlet gases, 1297 Tyndall test of, 1763 general procedure with special apparatus: Elliott, determination of carbon monoxide, carbon dioxide, oxygen, 1244, 1245 Hempel, determination of oxygen by hydrogen combustion, 1247 by phosphorus method, 1246 by pyrogallate of potassium, 1240 illuminating gas, 1246 Junker's calorimeter, 1257 Orsat, determination of carbon monoxide, carbon dioxide, hydrocarbons, oxygen, 1241, 1243 tables, 1280, 1282 Gas velocity by Potot, formula for, 707 Gas volumes conversion fornulæ, 707 Gasoline, determination of carbon monoxide, carbon dioxide, hydrocarbons, oxygen, 1241, 1243 tables, 1280, 1282 Cas velocity by Potot, formula for, 707 Gasoline, determination of carbon monoxide, carbon dioxide, hydrocarbons, oxygen, 1241, 1243 tables, 1280, 1282 Cas velocity by Potot, formula for, 707 Gasoline, determination of carbon dioxide determination, 457 method for determining silver, 457 Geissler absorption bulb for carbon dioxide determination, 457 method for determining silver, 457 Geissler absorption bulb for carbon dioxide determination, 457 method for determining silver, 457 Geissler absorption bulb for carbon dioxide determination, 457 method for determining silver, 457 Geissler absorption bulb for carbon dioxide determination, 457 method for determining silver, 457 Geissler absorption bulb for carbon dioxide determination, 457 method for determining silver, 457 Geissler absorption bulb for carbon dioxide determination, 457 method for determining silver, 457 Geissler absorption bulb for carbon dioxide, 452 Lenher's method, 231 permanganate method, 231 prep		
industrial gases, analysis of, 1227–1230 mine gases, carbon dioxide in, 1270 moisture in gases, 1275 natural gases, 1274a–1274g nitrogen in gases, intrometer method, 1276 dust determination iu, 1256 sulphurie acid gases, burner gases, 1264 darsenie in, 1765 chlorido in, 1765 dust in, 1763 mitrogen oxide in, 1270 solubility of, in liquids, 1487 sulphurie acid mist in, 1765 sulphur dioxide in exit gases, 1266 in inlet gases, 1267 Tyndall test of, 1763 general procedure with special apparatus: Elliott, determination of carbon monoxide, carbon dioxide, oxygen, 1244, 1245 Hempel, determination of oxygen by hydrogen combustion, 1247 by phosphorus method, 1246 by pyrogallato of potassium, 1246 illuminating gas, 1246 Junker's calorimeter, 1257 Orsat, determination of carbon monoxide, carbon dioxide, hydrocarbons, oxygen, 1241, 1243 tables, 1280, 1282 Cas velocity by Potot, formula for, 707 Gas olumes, conversion formula, 707 Gasoline, determination of carbond of, 1642 test for lubricating oils, 1222 tests of, 1123, 1127 Gay-Lussae apparatus (Fig. 59), for silver determination, 457 method for determining silver, 457 Geissler absorption bulb for carbon doxide determination, 112 Galatine dynamite, analysis of, 1204 laklicis, 1791 MnO2, St. 1792 BaO and Ca, separations, 1793 factors, 1793 Glass malysis, 1789–1791 alkalics, 1791 MnO2, S, 1792 BaO and Ca, separations, 1793 factors, 1793 Glass malysis, 1789–1791 alkalics, 1791 MnO2, S, 1792 BaO and Ca, separations, 1793 factors, 1793 Glass malysis, 1780–1791 alkalics, 1791 MnO2, St. 1792 BaO and Ca, separations, 1793 factors, 1793 Glass making materials, analysis of, 1794–1798 chlorides, moisture, potash, sulphates, 1796 calcium, line, 1797–1798 chlorides, moisture, potash, sulphates, 1796 calcium, line, 1797–1798 chlorides, moisture, potash, sulphates, 1796 Glucinum, detection of, 68 estimation of, 1755 determination of, in soap, 1607 Gold, detection of, in alloys, 228 benzidine acetate test, 229 phenylhydrazine acetate test, 220 phenylhydrazine acetate test, 220 phenylhydra	sulphur and H ₂ S in, 1260, 1261	on use of sodium pyrogallate (note 1),
milte gases, carfon dioxide in, 1270 moisture in gases, 1275 natural gases, 1274a-1274g nitrogen in gases, nitrometer method, 1276 producer, fuel blast furnace gases, 1260 dust determination in, 1256 sulphurie acid gases, burner gases, 1264 arsonic in, 1765 dust in, 1763 nitrogen oxide in, 1270 solubility of, in liquids, 1487 sulphure dioxide in exit gases, 1266 in inlet gases, 1267 sulphur dioxide in exit gases, 1266 in inlet gases, 1267 sulphur dioxide in exit gases, 1266 in inlet gases, 1267 sulphure dioxide in exit gases, 1266 in inlet gases, 1266 general procedure with special apparatus: Elliott, determination of carbon monoxide, carbon dioxide, oxygen, 1244, 1245 Hempel, determination of oxygen by hydrogen combustion, 1247 by phosphorus method, 1246 by pyrogallate of potassium, 1246 Junker's calorimeter, 1257 Orsat, determination of carbon monoxide, carbon dioxide, hydrocarbons, oxygen, 1241, 1243 tables, 1280, 1282 Gas velocity by Potot, formula for, 707 Gasoline, determination of calorific value of, 1642 test for lubricating oils, 1222 tests of, 1123, 1127 Gay-Lussac apparatus (Fig. 59), for silver determination, 457 method for determination, 112 Gelatine dynamite, analysis of, 1380 Generator for det. traces of antimony, 29 Gerhardt absorption bulb for carbon dioxide determination, bulb for carbon dioxide determination, 457 method for determination, 126 Glatine dynamite, analysis of, 1380 Generator for det. traces of antimony, 29 Gerhardt absorption bulb for carbon dioxide, premanganate method, 231 premanganate method, 231 preparation, of proof gold, 234 solubility, 229 Gold bar, platinum and palladium in, 385, 367 determination and palladium, 385, 361 billion, fire assay, of 484		Oxygen in gas, 1240
density, 1789 determination of Al ₂ O ₂ Fe ₂ O ₃ , CaO, 1276 producer, fuel blast furnace gases, 1266 dust determination in, 1256 sulphurie acid gases, burner gases, 1264 arsonic in, 1765 dust in, 1763 mitrogen oxide in, 1270 solubility of, in liquids, 1487 sulphure acid mist in, 1765 sulphure acid mist in, 1766 sulphure acid mist in, 1796 calcium, line, 1797–1798 chloriae, moisture acid in	industrial gases, analysis of, 1227-1230	
natural gases, 1274a-1274g nitrogen in gases, nitrometer method, 1276 producer, fuel blast furnace gases, 1266 dust determination in, 1256 sulphurie acid gases, burner gases, 1264 arsonic in, 1765 chlorido in, 1765 dust in, 1763 nitrogen oxide in, 1270 solubility of, in liquids, 1487 sulphurie acid mist in, 1765 sulphur dioxide in exit gases, 1206 in inlet gases, 1267 Tyndall test of, 1763 general procedure with special apparatus: Elliott, determination of carbon monoxide, carbon dioxide, oxygen, 1244, 1245 Hempel, determination of oxygen by hydrogen combustion, 1247 by phosphorus method, 1246 by pyrogallate of potassium, 1246 Junker's calorimeter, 1257 Orsat, determination of carbon monoxide, carbon dioxide, hydrocarbons, oxygen, 1241, 1243 tables, 1280, 1282 Gas velocity by Potot, formula for, 707 Gasolume, determination of calorific value of, 1642 test for lubricating oils, 1222 test of, 1123, 1127 Gay-lussae apparatus (Fig. 59), for silver determination, 457 method for determining silver, 457 Geissler absorption bulb for carbon dioxide determination, 457 method for determining silver, 457 Geissler absorption bulb for carbon dioxide determination, 112 Gelatine dynamite, analysis of, 1380 Generator for det. traces of antimony, 29 Gerhardt absorption bulb for carbon dioxide determination, bulb for carbon dioxide determination, 457 Gold bullion, fire assay, of 484		
nitrogen in gases, nitrometer method, 1276 producer, fuel blast furnace gases, 1266 dust determination in, 1256 sulphurie acid gases, burner gases, 1264 arsonic in, 1765 dust in, 1765 dust in, 1765 dust in, 1765 dust in, 1765 sulphurie acid mist in, 1793 sactors, 1793 sactors, 1793 sulphurie rabon acids,		determination of Al ₂ O ₃ Fe ₂ O ₃ , CaO,
dust determination in, 1256 sulphurie acid gases, burner gases, 1264 arsenie in, 1765 dust in, 1763 gand Ca, separations, 1793 factors, 1793 determination of: barium carbonate, separations, 1798 chlorides, moisture, potash, sulphates, 1796 china clay, kaolin, feldspar, 1795 delinime, 1797 description dioxide, hydrocaphorus method, 1246 by pyrogallato of potassium, 1246 dilluminating gas, 1246 Junker's calorimeter, 1257 Orsat, determination of carbon monoxide, carbon dioxide, hydrocaphorus method, 1246 by pyrogallato of potassium, 1246 dilluminating gas, 1246 Junker's calorimeter, 1257 Orsat, determination of carbon monoxide, carbon dioxide, hydrocaphorus method, 1246 by pyrogallato of potassium, 1246 dilluminating gas, 1246 Junker's calorimeter, 1257 Orsat, determination of carbon monoxide, carbon dioxide, hydrocaphorus method, 1246 by pyrogallato of potassium, 1247 clayounding gas, 1246 Junker's calorimeter, 1257 Orsat, determination of carbon dioxide, hydrocaphorus method, 1246 by pyrogallato of potassium, 1247 Clayounding gas, 1246 Junker's calorimeter, 1257 Orsat, determination of, in soap, 1607 Gasoline, determination of carbon dioxide, hydrocaphorus method, 230 determination of, in soap, 1607 Gold, detection of, in sloys, 228 benzidion garetal procedures: gravimetric electrolytic method, 230		MgO, PbO, SiO ₂ ,
dust determination in, 1256 sulphurie acid gases, burner gases, 1264 arsenic in, 1765 chlorido in, 1765 dust in, 1763 nitrogen oxide in, 1270 solubility of, in liquids, 1487 sulphurie acid mist in, 1765 sulphur dioxide in exit gases, 1266 in inlet gases, 1267 Tyndall test of, 1763 general procedure with special apparatus: Elliott, determination of carbon monoxide, carbon dioxide, oxygen, 1244, 1245 Hempel, determination of oxygen by hydrogen combustion, 1247 by phosphorus method, 1246 by pyrogallato of potassium, 1246 Junker's calorimeter, 1257 Orsat, determination of carbon monoxide, carbon dioxide, hydrocarbons, oxygen, 1241, 1243 tables, 1280, 1282 Gas velocity by Potot, formula for, 707 Gasoline, determination of carbon dioxide, determination of carbon for, 1642 test for lubricating oils, 1222 tests of, 1123, 1127 Gay-Lussac apparatus (Fig. 59), for silver determination, 457 method for determining silver, 457 Geissler absorption bulb for carbon dioxide determination, 112 Gelatine dynamite, analysis of, 1380 Generator for det. traces of antimony, 29 Gerhardt absorption bulb for carbon di-		
sulphurie acid gases, burner gases, 1204 arsonic in, 1765 chlorido in, 1765 dust in, 1763 mitrogen oxide in, 1270 solubility of, in liquids, 1487 sulphuric acid mist in, 1765 sulphur dioxide in exit gases, 1266 in inlet gases, 1267 Tyndall test of, 1763 general procedure with special apparatus: Elliott, determination of carbon monoxide, carbon dioxide, oxygen, 1244, 1245 Hempel, determination of oxygen by hydrogen combustion, 1247 by phosphorus method, 1246 by pyrogallato of potassium, 1246 Junker's calorimeter, 1257 Orsat, determination of carbon dioxide, carbon dioxide, hydrocarbons, oxygen, 1241, 1243 tables, 1280, 1282 Gas velocity by Potot, formula for, 707 Gas volumes; conversion formulæ, 707 Gas volumes; conversion formulæ, 707 Gas volumes; conversion formulæ, 707 Gas volumes; conversion formulæ, 707 Gas volude determination, 457 method for determining silver, 457 Geissler absorption bulb for carbon dioxide determination, 112 Gelatine dynamite, analysis of, 1380 Generator for det. traces of antimony, 29 Gerhardt absorption bulb for carbon dicarbon, oxide, analysis of, 1880 Generator for det. traces of antimony, 29 Gerhardt absorption bulb for carbon dicarbon, oxide, and procedures in the process of antimony, 29 Gerhardt absorption bulb for carbon dicarbon, oxide, and procedure and carbon doxide, hydrocarbons, oxygen, 1244, 1243 tables, 1280, 1282 Gas velocity by Potot, formula for, 707 Gas volumes; conversion formulæ, 707 Gas volumes; conversion formulæ, 707 Gas volumes; conversion formulæ, 707 Gas volumes; conversion formulæ, 707 Gas volumes; conversion formulæ, 707 Gas volumes; conversion formulæ, 707 Gas volumes; conversion formulæ, 707 Gas volumes; conversion formulæ, 707 Gas volumes; conversion formulæ, 707 Gas volumes; conversion formulæ, 707 Gas volumes; conversion formulæ, 707 Gas volumes; conversion formulæ, 707 Gas volumes; conversion formulæ, 707 Gas volumes; conversion formulæ, 707 Gas volumes; conversion formulæ, 707 Gas volumes; conversion formulæ, 707 Gas volumes; conversion formulæ, 707 G		
arsenic in, 1765 chlorido in, 1765 dust in, 1763 nitrogen oxide in, 1270 solubility of, in liquids, 1487 sulphur dioxide in exit guses, 1266 in inlet gases, 1267 Tyndall test of, 1763 general procedure with special apparatus: Elliott, determination of carbon monoxide, carbon dioxide, oxygen, 1244, 1245 Hempel, determination of oxygen by hydrogen combustion, 1247 by phosphorus method, 1246 by pyrogallato of potassium, 1246 illuminating gas, 1246 Junker's calorimeter, 1257 Orsat, determination of carbon oxide, carbon dioxide, hydrocarbons, oxygen, 1241, 1243 tables, 1280, 1282 Gas velocity by Potot, formula for, 707 Gasoline, determination of calorific value of, 1642 test for lubricating oils, 1222 test for lubricating oils, 1222 test of, 1123, 1127 Gay-Lussac apparatus (Fig. 59), for silver determination, 457 method for determining silver, 457 Geissler absorption bulb for carbon dioxide determination, 112 Gelatine dynamite, analysis of, 1380 Generator for det. traces of antimony, 29 Gerhardt absorption bulb for carbon di-		
chlorido in, 1765 dust in, 1763 nitrogen oxide in, 1270 solubility of, in liquids, 1487 sulphuric acid mist in, 1765 sulphur dioxide in exit guses, 1266 in inlet gases, 1267 Tyndall test of, 1763 general procedure with special apparatus: Elliott, determination of carbon monoxide, carbon dioxide, oxygen, 1244, 1245 Hempel, determination of oxygen by hydrogen combustion, 1247 by phosphorus method, 1246 by pyrogallato of potassium, 1246 illuminating gas, 1246 Junker's calorimeter, 1257 Orsat, determination of carbon monoxide, carbon dioxide, bydrocarbons, oxygen, 1241, 1243 tables, 1280, 1282 Gas velocity by Potot, formula for, 707 Gasoline, determination of calorific value of, 1642 test for lubricating oils, 1222 test for lubricating oils, 1222 test for lubricating oils, 1222 test of, 1123, 1127 Gay-Lussac apparatus (Fig. 59), for silver determination, 457 method for determining silver, 457 Geissler absorption bulb for carbon dioxide determination, 112 Gelatine dynamite, analysis of, 1794 lips making making, manterials, analysis of, 1794 lips making materials, analysis of, 1794 lips making materials, analysis of, 1794 lips making materials, analysis of, 1794 leactors, 1793 determination of: barium carbonate, separations, 1796 calcium, linc, 1797–1798 chlorides, moisture, potash, sulphates, 1796 calcium, linc, 1797–1798 chlorid	arsenic in. 1765	
nitrogen oxide in, 1270 solubility of, in liquids, 1487 sulphuric acid mist in, 1765 sulphur dioxide in exit gases, 1266 in inlet gases, 1267 Tyndall test of, 1763 general procedure with special apparatus: Elliott, determination of carbon monoxide, carbon dioxide, oxygen, 1244, 1245 Hempel, determination of oxygen by hydrogen combustion, 1247 by phosphorus method, 1246 by pyrogallato of potassium, 1246 illuminating gas, 1246 Junker's calorimeter, 1257 Orsat, determination of carbon nonoxide, carbon dioxide, hydrocarbons, oxygen, 1241, 1243 tables, 1280, 1282 Gas velocity by Potot, formula for, 707 Gasoline, determination of calorific value of, 1642 test for lubricating oils, 1222 test of, 1123, 1127 Gay-Lussac apparatus (Fig. 59), for silver determination, 457 method for determining silver, 457 Geissler absorption bulb for carbon dioxide determination, 112 Gelatine dynamite, analysis of, 1380 Generator for det. traces of antimony, 29 Gerhardt absorption bulb for carbon di- oxide determination, 112 Gelatine dynamite, analysis of, 1380 Generator for det. traces of antimony, 29 Gerhardt absorption bulb for carbon di- oxide determination, 127 Gold bullion, fire assay, of 484		
solubility of, in liquids, 1487 sulphuric acid mist in, 1765 sulphur dioxide in exit gases, 1266 in inlet gases, 1267 Tyndall test of, 1763 general procedure with special apparatus: Elliott, determination of carbon monoxide, carbon dioxide, oxygen, 1244, 1245 Hempel, determination of oxygen by hydrogen combustion, 1247 by phosphorus method, 1246 by pyrogallato of potassium, 1246 illuminating gas, 1246 Junker's calorimeter, 1257 Orsat, determination of carbon moxide, carbon dioxide, hydrocarbons, oxygen, 1241, 1243 tables, 1280, 1282 Gas volumes; conversion formula, 707 Gas volumes; conversion fo		
sulphuric acid mist in, 1765 sulphur dioxide in exit guses, 1266 in inlet gases, 1267 Tyndall test of, 1763 general procedure with special apparatus: Elliott, determination of carbon monoxide, carbon dioxide, oxygen, 1244, 1245 Hempel, determination of oxygen by hydrogen combustion, 1247 by phosphorus method, 1246 junker's calorimeter, 1257 Orsat, determination of carbon monoxide, carbon dioxide, hydrocarbons, oxygen, 1241, 1243 tables, 1280, 1282 Gas velocity by Potot, formula for, 707 Gasoline, determination of calorific value of, 1642 test for lubricating oils, 1222 tests of, 1123, 1127 Gay-Lussac apparatus (Fig. 59), for silver determination, 457 method for determination, 126 oxide determination, 457 Geissler absorption bulb for carbon dioxide determination, 112 Gelatine dynamite, analysis of, 1380 Generator for det. traces of antimony, 29 Gerhardt absorption bulb for carbon dioxide, carbon bulb for carbon dioxide, paper and phates, 1796 calcium, linc, 1797–1798 chlorides, moisture, potash, sulphates, 1796 china clay, kaolin, feldspar, 1795 clucinum, detection of, 08 estimation, gravimetric method, 69a-69b occurrence, 68, 69 separation from aluminum, ehromium, iron, manganese, zirconium, and yttrium, 60, 69b Glue, in rubber, determination of, 1593 Glycerol, boric acid titration in, 86, 87 determination of, in soap, 1607 Gold, detection of, in alloys, 228 benzidine acetate test, 229 phenylhydrazine acetate test, 229 phenylhydrazine acetate test, 229 test for, in minerals, 228 sestimation, general procedures: gravimetric, electronium, 60, 69b Glue, in rubber, determination of, 1593 Glycerol, boric acid titration in, 86, 87 determination of, in soap, 1607 Gold, detection of, in alloys, 228 benzidine acetate test, 229 phenylhydrazine acetate test, 229 test for, in minerals, 230, 488 volumetric method, 231 procedures of Cassell, Moir, Prister, 233 iodide method, 232 Lenher's method, 231 preparation for malum, iron, manganese, zirconium, determination of, 1755 determination of, in soap, 1607 Gold, detection of, i		
sulphur dioxide in exit guses, 1266 in inlet gases, 1267 Tyndall test of, 1763 general procedure with special apparatus: Elliott, determination of carbon monoxide, carbon dioxide, oxygen, 1244, 1245 Hempel, determination of oxygen by hydrogen combustion, 1247 by phosphorus method, 1246 by pyrogallato of potassium, 1248 Illuminating gas, 1246 Junker's calorimeter, 1257 Orsat, determination of carbon nonoxide, carbon dioxide, hydrocarbons, oxygen, 1241, 1243 tables, 1280, 1282 Gas velocity by Potot, formula for, 707 Gas volumes, conversion formulae, 707 Gas volumes, conversion formulae, 707 Gas volumes, conversion formulae, 707 Gas volumes, conversion formulae, 707 Gas-Lussac apparatus (Fig. 59), for silver determination, 457 method for determining silver, 457 Geissler absorption bulb for carbon dioxide determination, 112 Gelatine dynamite, analysis of, 1380 Generator for det. traces of antimony, 29 Gerhardt absorption bulb for carbon dioxide, bullion, fire assay, of 484		
Tyndall test of, 1763 general procedure with special apparatus: Elliott, determination of carbon monoxide, carbon dioxide, oxygen, 1244, 1245 Hempel, determination of oxygen by hydrogen combustion, 1247 by phosphorus method, 1246 illuminating gas, 1246 Junker's calorimeter, 1257 Orsat, determination of carbon monoxide, carbon dioxide, hydrocarbons, oxygen, 1241, 1243 tables, 1280, 1282 Gas velocity by Potot, formula for, 707 Gasoline, determination of calorific value of, 1642 test for lubricating oils, 1222 tests of, 1123, 1127 Gay-Lussac apparatus (Fig. 59), for silver determination, 457 method for determining silver, 457 Geissler absorption bulb for carbon dioxide determination, 112 Gelatine dynamite, analysis of, 1380 Generator for det. traces of antimony, 29 Gerhardt absorption bulb for carbon dioxide, procedure absorption bulb for carbon dioxide, platinum and palladium in, 385, 387 Gold bullion, fire assay, of 484		
general procedure with special apparatus: Elliott, determination of carbon monoxide, earbon dioxide, oxygen, 1244, 1245 Hempel, determination of oxygen by hydrogen combustion, 1247 by phosphorus method, 1246 by pyrogallato of potassium, 1248 illuminating gas, 1246 Junker's calorimeter, 1257 Orsat, determination of carbon monoxide, carbon dioxide, hydrocarbons, oxygen, 1241, 1243 tables, 1280, 1282 Gas volumes; conversion formula, 707 Gas volumes; conversion formula, 707 Gas volumes; conversion formula, 707 Gas volumes; conversion formula, 707 Gas volumes; conversion formula, 707 Gay-Lussac apparatus (Fig. 59), for silver determination, 457 method for determining silver, 457 Geissler absorption bulb for carbon dioxide determination, 112 Gelatine dynamite, analysis of, 1380 Generator for det. traces of antimony, 29 Gerhardt absorption bulb for carbon di-		
china clay, kaolin, feldspar, 1795 Elliott, determination of carbon monoxide, carbon dioxide, oxygen, 1244, 1245 Hempel, determination of oxygen by hydrogen combustion, 1247 by phosphorus method, 1246 by pyrogallato of potassium, 1246 Junker's calorimeter, 1257 Orsat, determination of carbon nonoxide, carbon dioxide, hydrocarbons, oxygen, 1241, 1243 tables, 1280, 1282 Gas volocity by Potot, formula for, 707 Gas volumes, conversion formulæ, 707 Gas volumes, conversion formulæ, 707 Gas volumes, conversion formulæ, 707 Gas volumes, conversion formulæ, 707 Gas volumes, conversion formulæ, 707 Gas-Lussac apparatus (Fig. 59), for silver determination, 457 method for determining silver, 457 Geissler absorption bulb for carbon dioxide determination, 112 Gelatine dynamite, analysis of, 1380 Generator for det. traces of antimony, 29 Gerhardt absorption bulb for carbon di-		
Elliott, determination of carbon monoxide, carbon dioxide, oxygen, 1244, 1245 Hempel, determination of oxygen by hydrogen combustion, 1247 by phosphorus method, 1246 by pyrogallato of potassium, 1248 illuminating gas, 1246 Junker's calorimeter, 1257 Orsat, determination of carbon monoxide, carbon dioxide, hydrocarbons, oxygen, 1241, 1243 tables, 1280, 1282 Gas velocity by Potot, formula for, 707 Gas volumes, conversion formulae, 707 Gasoline, determination of calorific value of, 1642 test for lubricating oils, 1222 tests of, 1123, 1127 Gay-Lussac apparatus (Fig. 59), for silver determination, 457 method for determining silver, 457 Geissler absorption bulb for carbon dioxide determination, 112 Gelatine dynamite, analysis of, 1380 Generator for det. traces of antimony, 29 Gerhardt absorption bulb for carbon di-		china clay, kaolin, feldspar, 1795
monoxide, carbon dioxide, oxygen, 1244, 1245 Hempel, determination of oxygen by hydrogen combustion, 1247 by phosphorus method, 1246 by pyrogallato of potassium, 1246 illuminating gas, 1246 Junker's calorimeter, 1257 Orsat, determination of carbon monoxide, carbon dioxide, hydrocarbons, oxygen, 1241, 1243 tables, 1280, 1282 Gas velocity by Potot, formula for, 707 Gas volumes; conversion formulae, 707 Gasoline, determination of calorific value of, 1642 test for lubricating oils, 1222 tests of, 1123, 1127 Gay-Lussac apparatus (Fig. 59), for silver determination, 457 method for determining silver, 457 Geissler absorption bulb for carbon dioxide determination, 112 Gelatine dynamite, analysis of, 1380 Generator for det. traces of antimony, 29 Gerhardt absorption bulb for carbon di-		
Hempel, determination of oxygen by hydrogen combustion, 1247 by phosphorus method, 1246 by pyrogallato of potassium, 1246 illuminating gas, 1246 Junker's calorimeter, 1257 Orsat, determination of carbon monoxide, carbon dioxide, hydrocarbons, oxygen, 1241, 1243 tables, 1280, 1282 Gas velocity by Potot, formula for, 707 Gasoline, determination of calorific value of, 1642 test for lubricating oils, 1222 tests of, 1123, 1127 Gay-Lussac apparatus (Fig. 59), for silver determination, 457 method for determining silver, 457 Geissler absorption bulb for carbon dioxide determination, 112 Gelatine dynamite, analysis of, 1380 Generator for det. traces of antimony, 29 Gerhardt absorption bulb for carbon di-	monoxide, carbon dioxide, oxy-	
hydrogen combustion, 1247 by phosphorus method, 1246 by pyrogallato of potassium, 1246 illuminating gas, 1246 Junker's calorimeter, 1257 Orsat, determination of carbon monoxide, carbon dioxide, hydrocarbons, oxygen, 1241, 1243 tables, 1280, 1282 Gas velocity by Potot, formula for, 707 Gasoline, determination of calorific value of, 1642 test for lubricating oils, 1222 tests of, 1123, 1127 Gay-Lussac apparatus (Fig. 59), for silver determination, 457 method for determining silver, 457 Geissler absorption bulb for carbon dioxide determination, 112 Gelatine dynamite, analysis of, 1380 Generator for det. traces of antimony, 29 Gerhardt absorption bulb for carbon di-	gen, 1244, 1245	
by phosphorus method, 1246 by pyrogallato of potassium, 1246 illuminating gas, 1246 Junker's calorimeter, 1257 Orsat, determination of carbon monoxide, carbons, oxygen, 1241, 1243 tables, 1280, 1282 Gas velocity by Potot, formula for, 707 Gas volumes; conversion formula, 707 Gasoline, determination of calorific value of, 1642 test for lubricating oils, 1222 tests of, 1123, 1127 Gay-Lussac apparatus (Fig. 59), for silver determination, 457 method for determining silver, 457 Geissler absorption bulb for carbon dioxide determination, 112 Gelatine dynamite, analysis of, 1380 Generator for det. traces of antimony, 29 Gerhardt absorption bulb for carbon di-		separation from aluminum, chromium,
by pyrogallato of potassium, 1246 Illuminating gas, 1246 Junker's calorimeter, 1257 Orsat, determination of carbon monoxide, carbon dioxide, hydrocarbons, oxygen, 1241, 1243 tables, 1280, 1282 Gas velocity by Potot, formula for, 707 Gas volumes, conversion formulae, 707 Gasoline, determination of calorific value of, 1642 test for lubricating oils, 1222 tests of, 1123, 1127 Gay-Lussac apparatus (Fig. 59), for silver determination, 457 method for determining silver, 457 Geissler absorption bulb for carbon dioxide determination, 112 Gelatine dynamite, analysis of, 1380 Generator for det. traces of antimony, 29 Gerhardt absorption bulb for carbon di- Glue, in rubber, determination of, 1593 Glycerol, boric acid titration in, 86, 87 determination of, in soap, 1607 Gold, detection of, in alloys, 228 benzidine acetate test, 229 phenylhydrazine acetate test, 229 phenylhydrazine acetate test, 229 test for, in minerals, 228 estimation, general procedures: gravimetric methods; colorimetric methods; colorimetric method, 233 procedures of Cassell, Moir, Prister, 233 iodide method, 231 permanganate method, 231 preparation of proof gold, 234 solubility, 229 Gold bar, platinum and palladium in, 385, 387 Gold bullion, fire assay, of 484		
illuminating gas, 1246 Junker's calorimeter, 1257 Orsat, determination of carbon monoxide, carbon dioxide, hydrocarbons, oxygen, 1241, 1243 tables, 1280, 1282 Gas velocity by Potot, formula for, 707 Gasoline, determination of calorific value of, 1642 test for lubricating oils, 1222 tests of, 1123, 1127 Gay-Lussac apparatus (Fig. 59), for silver determination, 457 method for determining silver, 457 Geissler absorption bulb for carbon dioxide determination, 112 Gelatine dynamite, analysis of, 1380 Generator for det. traces of antimony, 29 Gerhardt absorption bulb for carbon di-		yttrium, 69, 69b
Junker's calorimeter, 1257 Orsat, determination of carbon monoxide, carbon dioxide, hydrocarbons, oxygen, 1241, 1243 tables, 1280, 1282 Gas velocity by Potot, formula for, 707 Gas volumes, conversion formulæ, 707 Gasoline, determination of calorific value of, 1642 test for lubricating oils, 1222 tests of, 1123, 1127 Gay-Lussac apparatus (Fig. 59), for silver determination, 457 method for determining silver, 457 Geissler absorption bulb for carbon dioxide determination, 112 Gelatine dynamite, analysis of, 1380 Generator for det. traces of antimony, 29 Gerhardt absorption bulb for carbon di-		
Orsat, determination of carbon monoxide, earbon dioxide, hydrocarbons, oxygen, 1241, 1243 tables, 1280, 1282 Gas velocity by Potot, formula for, 707 Gasoline, determination of calorific value of, 1642 test for lubricating oils, 1222 tests of, 1123, 1127 Gay-Lussac apparatus (Fig. 59), for silver determination, 457 method for determining silver, 457 Geissler absorption bulb for carbon dioxide determination, 112 Gelatine dynamite, analysis of, 1380 Generator for det. traces of antimony, 29 Gerhardt absorption bulb for carbon di-		
oxide, carbon dioxide, hydrocarbons, oxygen, 1241, 1243 tables, 1280, 1282 Gas velocity by Potot, formula for, 707 Gas volumes, conversion formulae, 707 Gasoline, determination of calorific value of, 1642 test for lubricating oils, 1222 tests of, 1123, 1127 Gay-Lussac apparatus (Fig. 59), for silver determination, 457 method for determining silver, 457 Geissler absorption bulb for carbon dioxide determination, 112 Gelatine dynamite, analysis of, 1380 Generator for det. traces of antimony, 29 Gerhardt absorption bulb for carbon di-		
carbons, oxygen, 1241, 1243 tables, 1280, 1282 Gas velocity by Potot, formula for, 707 Gas volumes; conversion formula, 707 Gasoline, determination of calorific value of, 1642 test for lubricating oils, 1222 tests of, 1123, 1127 Gay-Lussac apparatus (Fig. 59), for silver determination, 457 method for determining silver, 457 Geissler absorption bulb for carbon dioxide determination, 112 Gelatine dynamite, analysis of, 1380 Generator for det. traces of antimony, 29 Gerhardt absorption bulb for carbon di-		
Gas velocity by Potot, formula for, 707 Gas volumes, conversion formulæ, 707 Gasoline, determination of calorific value of, 1642 test for lubricating oils, 1222 tests of, 1123, 1127 Gay-Lussac apparatus (Fig. 59), for silver determination, 457 method for determining silver, 457 Geissler absorption bulb for carbon dioxide determination, 112 Gelatine dynamite, analysis of, 1380 Generator for det. traces of antimony, 29 Gerhardt absorption bulb for carbon di- Gold bullion, fire assay, of 484	carbons, oxygen, 1241, 1243	
Gas volumes, conversion formulae, 707 Gasoline, determination of calorific value of, 1642 test for lubricating oils, 1222 tests of, 1123, 1127 Gay-Lussac apparatus (Fig. 59), for silver determination, 457 method for determining silver, 457 Geissler absorption bulb for carbon dioxide determination, 112 Gelatine dynamite, analysis of, 1380 Generator for det. traces of antimony, 29 Gerhardt absorption bulb for carbon di-	tables, 1280, 1282	
Gas volumes; conversion formula, 707 Gasoline, determination of calorific value of, 1642 test for lubricating oils, 1222 tests of, 1123, 1127 Gay-Lussac apparatus (Fig. 59), for silver determination, 457 method for determining silver, 457 Geissler absorption bulb for carbon dioxide determination, 112 Gelatine dynamite, analysis of, 1380 Generator for det. traces of antimony, 29 Gerhardt absorption bulb for carbon di-		
Gasoline, determination of calorific value of, 1642 test for lubricating oils, 1222 tests of, 1123, 1127 Gay-Lussac apparatus (Fig. 59), for silver determination, 457 method for determining silver, 457 Geissler absorption bulb for carbon dioxide determination, 112 Gelatine dynamite, analysis of, 1380 Generator for det. traces of antimony, 29 Gerhardt absorption bulb for carbon di-		gravimetric, electrolytic method, 230
test for lubricating oils, 1222 tests of, 1123, 1127 Gay-Lussac apparatus (Fig. 59), for silver determination, 457 method for determining silver, 457 Geissler absorption bulb for carbon dioxide determination, 112 Gelatine dynamite, analysis of, 1380 Generator for det. traces of antimony, 29 Gerhardt absorption bulb for carbon di-		wet assay of minerals, 230, 488
tests of, 1123, 1127 Gay-Lussac apparatus (Fig. 59), for silver determination, 457 method for determining silver, 457 Geissler absorption bulb for carbon dioxide determination, 112 Gelatine dynamite, analysis of, 1380 Generator for det. traces of antimony, 29 Gerhardt absorption bulb for carbon di-		
Gay-Lussac apparatus (Fig. 59), for silver determination, 457 method for determining silver, 457 Geissler absorption bulb for carbon dioxide determination, 112 Gelatine dynamite, analysis of, 1380 Generator for det. traces of antimony, 29 Gerhardt absorption bulb for carbon di-		
determination, 457 method for determining silver, 457 Geissler absorption bulb for carbon dioxide determination, 112 Gelatine dynamite, analysis of, 1380 Generator for det. traces of antimony, 29 Gerhardt absorption bulb for carbon di- Gold bullion, fire assay, of 484		Prister, 233
method for determining silver, 457 Geissler absorption bulb for carbon dioxide determination, 112 Gelatine dynamite, analysis of, 1380 Generator for det. traces of antimony, 29 Gerhardt absorption bulb for carbon di-		iodide method, 232
oxide determination, 112 Gelatine dynamite, analysis of, 1380 Generator for det. traces of antimony, 29 Gerhardt absorption bulb for carbon di-	method for determining silver, 457	
Gelatine dynamite, analysis of, 1380 Generator for det. traces of antimony, 29 Gerhardt absorption bulb for carbon di- Gold bullion, fire assay, of 484		permanganate method, 231 preparation of proof gold, 234
Generator for det. traces of antimony, 29 Gerhardt absorption bulb for carbon di- Gold bullion, fire assay, of 484	Gelatine dynamite, analysis of, 1380	solubility, 229
29 Gerhardt absorption bulb for carbon di- Gold bullion, fire assay, of 484	Generator for det. traces of antimony,	Gold bar, platinum and palladium in, 385,
	29	387
	oxido determination, 112	Gold, fire assay of, 466–488

Goldenberg's method for det. tartaric Halogens, separation and determination acid, 1551 in presence of one another, 155 Goods method for determining lithium, Halphen's test for cottonseed oil, 1136, 1143 414 for determining titanium, modified, Handy's volumetric method for magnesium, 294 542 and Blake's method for determining Hanging drop test for fluorine, 213 Hanus's method for iodine number of oils, 1128 bromates, 96 and Bosworth's method for determining silver, 463 method for oil, 1137 and Ensiger, separation of bromine solution, 1167 from iodine, 94 and Fairbanks' method for molyble-Hardened oils (see Oils, Fats, Waxes), 1145 num, 318 examination of, 1147 and Gruener, method for det. nitrate, 352 Hard lead, antimony, 25 decomposition of, 21, 25 and Jones, method for boron, 85 Hardness, determination of, in water, Gooch crucible, preparation of, 596d 1438 Graphite, carbon determination in, 130 determination of, in crude mineral, 130 in iron and steel, determination of, 115 Hawley, F. G., on silica det., 449, 450 Heat of fusion, table of, 720b Heat definitions, 708 Graphitic silicon in aluminum, determinaof fusion, table of, 720b tion of, 17a passing up chimney, calculation of, Gravimetric methods. See under element 1253 in question. Gravity. See Specific Gravity. test for oils, 1123 treatment of steel, 1719 Gray's method, carbon residue test in oil, 1122 Heating value in gas, 1288k Heath, permanent copper standard soludistillation flask (Fig. 91), 1122 Green pigments, analysis of, 1177, 1198 Greenwood, H. D., selenium and tellution (ref.), 199 Heath's solenoid, rapid deposition of rium, 430 eopper by, 187 Heavy hydrocarbons, 1227c Gregory, test for silver, 439 Hehner's test for formaldehyde, 1754 Grinders and crushers, 1011-1015 Gröger, decomposition of chromic oxide Helium in the atmosphere, 338 analysis of, 1274g-1274i (note), 158 Hempel apparatus, 1245 chromium determination (note), 161 apparatus, description (Figs. 122, 123), Gum arabic in explosives, 1388 1245, 1247 test for, 1385 Gun metal, analysis of, by A. S. T. M., 1058-1063 gas burette (Fig. 122), 1236 method for determining methane and hydrogen, 1249 Henrique's method in rubber analysis, Gunming test in lubricating oils, 1121 Guttapercha and Balata, analy., 1584 Gutbier and Hüller, method for zirco-1582 Henz and Classen method for tin, 536 nium, 521 Gutzeit apparatus, arsenic determination Herig automatic device for burette, 1497 (Fig. 6), 46 method for determining arsenic, modi-Herschel's demulsibility test for oils, 1123Herting, volumetric method for tungsten, 563 fied, 52 Grain growth in steel, metallography of Hesse's method for earbon dioxide in at-1719 mospheric air (Fig. 132), 1272 Gruener, H. W., on nitrates, 352 Hexabromide test for linseed oil, 1137, Gryory's method for determining antimony, 25 Gypsum, 105 1143 Hickman, chapter on platinum and platinum group, 376 A. S. T. M. methods for, 108b Hicks, chapter on potassium, sodium, and Hale, F. E., chapter on methods for analother alkalies, 401 chloroplatinate method for potassium, ysis of coal, 1616 soap test for hardness in water, 1436 411 starch, preparation of, 1432 Hillebrand, alkalies (ref.), 416 water analy., sanitary, 1442-1453 bacteriological, 1454-1468 on silica determination (ref.), 436 uranium det., 583

*	
Hinman's method for determining methane and hydrogen, 1248 and Jenkins, sulphur apparatus (Fig. 127), 1260 volumetric method for sulphur, 506 Hintz and Weber on sulphur precipitation, 497 Holde, caoutchoue in lubricating oils, 1121 Holladay, J. A., on molybdenum det., 313, 320, 322 on tungsten det., 554, 560	Hydrochloric acid, preparation of arsenic- free acid (Fig. 5), 48 standard solution, 1495 table, sp. gr., 1504 test for iron, 246 test for lead, 271 test for nercury, 308 Hydrocyanic acid, volumetric det. 131, 1727 detection, 1726 Hydrofluoric acid, analysis of, 1507 gravimetric estimation, preparation
Holloway-Eschka process for determining	of samples for, 215 decomposition of rareearth ores with, 136
mercury, 311 Holstein, L. S., on cadmium analy., 99 Hommel's process for separating molybdenum and tungsten, 558	method for alkalics, 417 hydrofluosilicie acid in, 1507 sulphuric acid in, 1507
Hooper's method for treatment of speisses,	sulphurous acid in, 1507
slags, mattes, etc., 20	Hydrofluosilicic acld in hydrofluoric acid,
Horse-power, definition of, 709	1507 Hydrogen chloride gas, generation of
Hoekins' electric furnace (Fig. 107), 1630 Hot water precipitation of tin, 520	(note), 10
Howard-Harrison, fusion of sulphide ores,	Hydrogen-ion concentration, det. of, 1430, 1663
Hübl's method for iodine number in oils,	Hydrogen combustion method for det.
1129	oxygen, 1247
for oil, 1138	determination in gas, 1248, 1249 generator, 1278
Hübner's method for estim. rubber, 1580 Humidity charts, air, 1288a, 1288b	in the atmosphere, 338
Hydrazine sulphate, decomposition of	properties of, 1227c
nitrous acid, 342	reduction method for copper, 205
reduction of chromic acid, 342	reduction of rhodium salts, 395 reduction of tin ores, 527
Hydrazine-hydrochloride-sulphur method for tellurium, 437	Hydrogen peroxide, chromium detection
Hydriodic acid, removal of, from nitric	by, 156
acid, 342 Hydrobromic acid, removal of, from nitrie	method for formaldehyde, 1754 method for iodine, 243
acid, 342	method for titanium, 545
Hydrocarbons in gas analysis, 1243	method for detecting vanadium 583
in illuminating gas, 1248	-phosphoric acid method for decom-
in natural gas, 1288n	posing iodides, 243 test for thorium, 522, 524
in rubber, 1594 in soap, 1608	Hydrogen peroxide, det. of, 1761
Hydrochloric acld, detection of free, 142	Hydrogen sulphide, evolution method, 503
analysis of, 1501	estimation of, 509 group, separation of, 168, 292, 405
estimation, gravimetric methods for, 148	in aumoniacal liquors, 345
free, det. of, 154	in gas, 1261
in acetic acid, 1547	in steel, 1368g
in ammoniacal liquors, 344	in water, 1435 method for det. iron, 611
in bichloride of tin, 530	method for ppt. Cu in steel, 1368c
in nitric acid, 1510 in presence of chloric and perchloric	precipitation of molybdenum, 317
acids, 153	reduction of chromates, 156
in sulphuric acid, 1528	reduction of ferric solutions, 251 test for copper, 177
volumetric methods, 149, 1501	test for iridium, 388
impurities in, arsenie, 35, 50, 1502	test for lead, 271
barium chloride in, 1502 chlorine, free, in, 1501	test for mercury, 308 test for nickel, 329
nitric acid and nitrates in, 1501	test for palladium, 382
silica and total solids in, 1502	test for platinum, 376
sulphuric acid and sulphates in, 1502	test for rhodium, 393

Hydrogen sulphide, test for ruthenium, 390b	Insol.—in composite white paint, 1189
	in orange and yellow pigments, 1195
test for vanadium, 583	in Portland cement, 1209
Hydrogen sulphide generator, 42	in sodium fluoride, 226
Hydrolysis of aluminum salt with am-	in sodium nitrate, 349
monia, 7	in zine oxide, 1184
method for tin, 528	Interpretation of results in gas analysis,
with thiosulphate, 9	1230, 1252
Hydrometer, Fig. 80a, 1502	in analysis of oil, 1158
Hydrometer for specific gravity of oils,	in mineral analysis of water, I44I
11II	
	in sanitary analysis of water, 1419
Hydrometer method for CO ₂ det., 125	Iodate, determination of, 244
sp. gr. of bituminous sub., 1295	and periodate in a mixture, 244
Hydrosulphite of sodium, det. of, 516	lodate method for det. arsenic, 44
Hydroxide of aluminum, precipitation,	Iodate of potassium, decomposition of
7. 9	iodide with, 241
effect of boiling, 8	lodide-chroniate method for lead, 278
hydroxylamine hydrochloride, 1427	Iodide method for antinony, 28
of bismuth, precipitation of, 74	for arsenie, 43
	for chromium determination, 161
of sodium and potassium, 1552–1556	
table, 1558	for eopper determination, 193, 193b
Hydroxylamine, det. of, 352	for determining tin, 532
Hypochlorite, test for, 143	for gold determination, 232
in presence of Cl, 151	for metabisulphites, sulphites, sul-
Hypochlorous acid, detection of, 143	phurous acid, thiosulphates, 131
determination of, 151	for peroxide determination, 1491
Hypophosphorous acid, test for, 362	Iodide of potassium, reduction of ferric
Hypotheses and chemical laws, 723	solutions with, 252
	lodide-phosphate method for Cu, 17b
Ignition toss in asbestine, china clay,	Iodine, detection of free, combined, iodate,
silien, silex, 1187	236
in barytes and blane fixe, 1188	estimation, general procedures:
in bauxite, 17h	gravimetrie as palladous iodide, 239
in gypsum, plaster of Paris, 1188	as silver iodide, 239
Illuminants in gas analysis, 1248	volumetric determination of hydriodic
properties of, 1227e	acid and soluble iodides, 239
Illuminating gas, analysis of, 1227, 1247,	liberation of jodine with chlorine
1256	(Mohr-Dupré), 243
Impurities suspended in gas, test for, 1763	of ferrie salts, 241
Incrusting solids in water, 1421	of hydrogen peroxide and phos-
Indicators, table of, 1491	phoric acid, 243
Indigo sol. titration of hydrosulphite, 516	of iodate of potassium, 241
Indirect method for determining sodium	of nitrous acid, Fresenius method
and potassium, 413	242
Indium, detection and determination of,	Volhard's method, 243
139	
	estimation, special procedures:
Industrial gases, analysis of, 1227-1230	in nitric acid, determination of, 1511
Inks, printing, analysis of, 1799–1803	occurrence, 236
determination of oil, 1799	preparation of the sample for estima-
separation from pigment, 1799	tion of iodine in iodides, iodates
pigment analysis, 1800	commercial iodine, minerals, or-
black inks, 1800	ganie substances, phosphates, wa-
blue inks, 1802	ter, 237
green inks, 1802	reagent, 0.1 N, preparation of, 28, 731
red inks, 1802	separation from heavy metals, from
physical examination, 1804	bromine and chlorine, 238, 239
Inlet gases, sulphur dioxide in, 1267	solubility of the element and its salts
	236
Insecticides, water-soluble arsenie in, 36	
Insoluble matter in asbestine, china clay,	Indine jelly test of paint vehicles, 1170
silica, silex, 1187	in mineral water and brines, 245
in aluminum hydrate, 17i	number (Hübl), in oil analysis, 1127
in commercial selehium, 440	I 169

Iodine number, linseed oil, 1166	Iron—in ores, 251
number (Hubel), 1169	in paper making materials, 1773
standard solution, 28, 1167	in paint pigments (iron oxides),
	1185, 1189, 1193, 1196
tung oil, 1170	
Iodoform test for alcohol, 1746	in phosphates, 372, 374
Iodometric det. of nitrates, Gooch and	in Portland cement, 1207
Gruener, 352	in sand, 448
Iridium, detection of, 388	in selenium, 432
by alk., KCl, NH4Cl, H2S, Zn, Pb, acet.,	in slag, 1611
Zn, K ₂ CO ₃ , formie a., etc., 382	in sodium nitrate, 322
estimation, 389	in spelter, H ₂ S and colorim. meth-
gravimetric methods, 390	ods, 611
ammonium iridium ehloride, 390	in sulphurie acid, 1526
ignition with ammonium salt, 390	in spent oxide, 519
method of Deville and Stas modi-	in titaniferous ores, 552
	in water as formula and farric
fied by Gilchrist, 390	in water, as ferrous and ferric
residue, obtained as, 390	iron, 1423
reduction by zine, 390	determination of, in presence of vana-
preparation and solution of sample, 389	dium, 589, 592
properties of, 389	industrial application of methods, 246
separations, from osminm, 389	occurrence, ores and minerals, carbon-
platinum, 389	ates, sulphides, 246, 247
Iron, detection of, tests with hydrochloric	preparation and solution of the sample,
acid, ferrocyanide, salicylic acid,	iron and steel, 248
sodium peroxide, sulphocyanate, 246	ores, soluble salts, silicates, etc., 247, 248
colorimetric method, 261	248
distinction between ferrous and ferrie	separations, ether method, 248
salts, 246	general procedure, 248
estimation, general procedures:	separation from chromium, 158
gravimetric, determination as ferrie	solubilities, general considerations, 247
oxide, Fo ₂ () ₃ , 249	traces, colorimetric methods, salicylic
ounfarron mothed 17k 950	
cupferron niethod, 17k, 250	acid method, 262
volumetrie methods, oxidation pro-	sulphocyanate method, 261
cedures, 251	Iron and steel analysis, decomposition of,
diphenylamine method, 255	for determining iron, 263, 1351
oxidation methods, 251	A. S. T. M. methods, 1351–1368
preliminary reduction with hydro-	determination of aluminimum, 16
gen sulphide, metal, potassium	arsenic in, 37
iodide, sulphurous acid, test	earbon in alloy steels, 1359
lead, zine, 251, 252	carbon in, combined, colorimetric
potassium dichromate method, 253,	determination, 128, 263, 1359
255	graphitic, 265
potassium permanganate method,	total, 95, 265, 1352, 1354
17b, 256, 257b	ehronium in, 158, 165, 1368f
reduction procedure with stannons	copper in, 181, 1368e
chloride, 260	by colorimetric method, 1368d
reduction with titanious salt, 258	cobalt in, 174
estimation, special procedures:	hydrogen in, 1368g
determination in alloys and metals:	manganese in, bismuthate method
in alloys, 1055, 1073, 1082, 1092,	for, 267, 301, 1360, 1362
1097, 1106j	Deshey's method, 266, 306
in aluminum, 17a	persulphate method, 266, 305
in aluminum hydrate, 17h	Valland's method 200
in bauxite, 15	Volhard's method, 302
in bronze, A. S. T. M., 1076	determination in alloy steels,
in calcined ore, 17k	1362
in copper, 200	Ford-William's method, 306
	method for cast iron, 1362
in glass, 1790	inolybdenum in, 314, 316
in ink pigments, 1800	nickel in, 331, 336a
in lead, 290a in manganese phosphorus bronze,	nitrogen in, 361a
	oxygen in, 1368i
1047	

•	
Iron—phosphorus in, 268, 269, 368-370b in alloy steels, 1365	Kelley, G. L., electrometric methods, 1663-1682
reagents used in steel analysis, 1351-1368	apparatus for electrom. mothods, 1547 Kempf's oxalic acid method for determi-
silicon in, 270, 449	nation of persulphates, 508
procedure for iron and steel, 445	Kerosene, analysis of, 1111-1112e
rapid foundry method of deter- mination, 1368a, 1368b	Kingzett's iodide method for det. peroxides, 1761
sulphur in, gravimetric, 269, 1366	Kjeldahl det. nitrogen in explosives, 1382
volumetric, 500-504, 1368	Kjeldahl digestion for nitrogen determi-
sulphur in alloy steel, 1368a	nation, 340, 350
titanium in, 547 tungsten in, 554, 556	Kneeland, decomposition of ores and slags, 214
uranium in, 582a	Knop's diphenylamine indicator for iron
vanadium in, 584, 591, 595	Het., 225
vanadium in, 584, 591, 595 zirconium in, 232, 268	Knorr arsenic distill. app., 39a, 365
specifications for elements in steel:	Knorr's persulphate method for deter-
carbon, 265, 1371 manganese, 267, 1371	mining manganese in water, 1426 apparatus, modified, for carbon dioxide
phosphorus, 268, 1371	ide determination, 122
silicon, 270, 1371	Kramer-Sarnow heat tests, bit. sub., 1305
sulphur, 269, 1371	Krypton in the atmosphere, 338
Iron ores and iron ore briquettes, copper	Yananda indiadan manandian at 744
determination in, 180	Lacmoid indicator, preparation of, 744, 1152
ore briquettes, reduction for sulphur determination, 502	uses of, 1492
sulphide, available H ₂ S in, 503, 509	Ladd, R. M., on pyridine in amm. nitrate,
Iron salts, free acid det, in 1541	360
Iron, nickel, cobalt and zinc in As ₂ O ₃ , 54	Landolt-Boernstein on heats of fusion,
Iron and alumina in barium ores, 67	720e
Irrigating waters, 1441c Ivanov on aluminum, 17	Landrum, cobalt in cobalt oxide, 171 cobalt in enamels, 173
Transfer ou within any ar	Lanthanum, 134, 135
Jaeger, F., on platinum and palladium	Lard, cottonseed oil in, 1144
det., 385	water in, 1144
Jackson's candle turbidimeter, 1620	Latent heat, definition of, 708 electrolitic dct. of, A. S. T. M., 1092
Jamieson's arsenous method for peroxide det., 1761	Lawrence Smith (J.), method for alkalies
Januasch method for separation of the	in silicates, 416
halogens, 238	Laws, chemical, 723
metallic test for palladium, 382	Leach's test for formaldehyde, 1754
for iodine (ref.) 147	Lead and copper in As ₂ O ₂ , 53 Lead, chromate-ferrous-dipbenylamine
for platinum, 377 for rbodium, 393	method for, 278b
precipitation of bismuth bydroxide 75,	detection of, tests with hydrochloric
Japanese wood oil. See Tung Oil.	acid, hydrogen, sulphide, potassium
Jenkin's apparatus for specific gravity of	dichromate and potassium chromate
gas (Fig. 129), 1263	271 cstimation, general procedures:
and Hinman gas-sulphur apparatus (Fig. 127), 1260	gravimetric method, determining a
Jones reductor apparatus (Fig. 40), 257	chromate, PbCrO ₄ , 275
method for iron determination, 257	as molybdate, PhMoO4, 275a as peroxide, PhO2, by electrolysis
method for molybdenum determina-	as peroxide, PbO ₂ , by electrolysis
tion, 319	275b as sulphate, PbSO ₄ , 274
method for phosphorus determina- tion, 369	volumetric methods, ferrocyanide ti
Joule, definition of, 709	tration, 276
Junker's calorimeter (Figs. 124, 125, 126),	chromate-iodide method, 277c
1257, 1258	ferrocyanide method, 276
77-1	molybdate method of Alexander
Kehrmann's separation of tungsten from	277b permanganate method of Low, 275
areenic and phosphorus, 558 59	harman@mana manana as mani me

Lead, estimation, special procedures:	Lead test for chromate, 156
determination in alloys and metals,	test paper, 49
1051, 1052, 1053, 1061, 1062,	Lead arsenate, arsenie determination in,
1067, 1070, 1071, 1080, 1081, 1108, 1106a, 1106b	36
1106, 1106a, 1106b	Lead basic carbonate, det. of, 228b
in basic carbonate of lead, 278b	Lead bullion, assay of, 482
in bronze, det. as PbSO ₄ , 1076	bismuth in, 79
in copper, 201	carbonate in sublimed blue lead, 1197
in corroded white lead (volumetric	zine in, 617a
and gravimetrie), 1181	chloro-fluorido method for fluorine
in gun metal, A. S. T. M., 1058	determination, 217
in niekel, 336d	method for determining molybdenum,
in paint pigments, chrome green	316
and yellow, 1198	Lead oxide, electrolytic method, 1184
in pierie acid, 1393	method for manganese in steel, 266
in red lead and orange mineral,	peroxide in red lead, 290f
290d, 290f, 1190	sulphate, decomposition of, for sulphur
in selenium, commercial, 439	determination, 340
in slag, 1615	in sublimed blue lead, 1197
in soft solders, 1080	sulphite in sublimed blue lead, 1197
in spelter (electrolytic and lead	Lead oxide, method for det. manganese,
acid methods), 609	263
in sublimed blue lead, 1197	Lead, pig, analysis of, 286-290e
in sublimed white lead, 1189	Leaks, tests for, 1368h
in sulphuric acid, 1525	Le Blane and Eckhardt's ferrous sulphate
in water, 1437	method for persulphates, 508
in yellow basic lead chromate, 1195	Le Chatelier's specific gravity apparatus,
in zine lead and leaded zinc, 1183	1205
Lead, estimation, determination in small	reagent for etching, 1705
quantities (see Traces in Water), 1433	Ledoux and Co. methods, 280, 322, 560
impurities in metallic lead:	for tungsten det., 560
antimony in hard lead, 25	Length, unit table, 702
bismuth in lead bullion, 79	Lenher, V., chapter on selenium and
complete analysis of pig, lead, deter-	tellurium, 430–440
mining bismuth, silver, arsenie,	Lenher's method for gold, 232
antimony, tin, iron, cobalt, nick-	-Crawford thymol method for titanium,
el, manganese, zine, 290-290e	550
industrial application of methods, 271	and Trogg, precautions on silica deter-
in minimum, 290d, 290q	mination, 447
occurrence, minerals, ores, alloys, etc.,	Lennsen's iodide method for tin, Baker's
271	modification, 532
preparation and solution of the samples	Lewkowitsch on oil tests, 1135
-minerals, ores, alloys, etc., 272	Liebermann-Storeli's test for rosin oil,
separations, isolation of lead as sul-	1139, 1144b
phate, 273	Liebig's absorption bulb, 111
extraction of the impure sulphate by	method for determining hydrocyanie
ammonium acetate, 273, 279	acid and cyanides, 131
separation from barium, 273	Liddell on dust in gas, 1256
solubilities of faetallic lead and its salts,	Lime, available, 108
271	analysis of, 1784
traces, determination of:	Lime, effect on siliea dehydration, 446
gravimetric, from large amounts of	and magnesia in barium ores, 67
substances:	method for halogens in organic matter,
a. acetate extraction, 279	146
b. occlusion by precipitate of an- other metal, 280	in sand, 448
a Scales Clauten method modi-	-value in water analysis, 1441
c. Seeker-Clayton method, modi- fied 281	ir. silicate of soda, 448
fied, 281 volumetric, colorimetric method, 282	in slag, 1610
Lead acetate cotton, 30	Lime and limestone determination in
Lead acetate method for precipitating	cement and analysis, 1220
vanadium, 588	water test for magnesium, 291

Limestone, lime, cement rock, analysis of, Magnesium, detection of, 291 estimation, methods for determining, Lindo-Gladding's method for potassium, general: 412 gravimetric, as magnesium pyrophos-phate, 17c, 293 Linseed oil, analysis of, 1165 specifications, 1168 volumetric, titration of ammonium Liquid fuels, analysis of, 1125 magnesium phosphate, 294 Liquids, sampling of. See Sampling. estimation, special methods: Litharge, 290 determination in alloys, 1106c charges in assaying. See chapter on. Lithium, detection of, 403 determination in gypsum, 1188 in sand, 448 in silicate of soda, 448 estimation, general procedures: as lithium chloride, 414 in sodium nitrate, 350 as lithium sulphate, 414 in water, 1425, 1436 det. in water, 1428 Gooch's method, 414 estimation, in composite white paint, 1190 in green pigments, 1196 in orange and yellow pigments, 1195 in Portland cement, 1217 Rammelsberg's method, 415 spectroscopic nicthod, 415 sodium and potassium determination in presence of one another, 416 with sodium and potassium in pres-enceofoncanother, estimation of, 200 Lithopone, analysis of, 1186 Litmus indicator, uses of, 744, 1492 occurrence, 291 Little-Cahen-Morgan, det. arsenic in orpreparation and solution of the sample -ores, 291 ganic matter, 36 separation from the hydrogen sulphide group, Cu, Pb, Cd, As, etc., 292 Logarithms, table of, 713 Loss of weight method for carbonates, from iron, aluminum, manganese, 124 and zinc, 292 on ignition aluminum hydrate, 17h bauxite, 17f from the alkaline earths, 59, 292 solubility, 291 on ignition in Portland cement, 1208 Low, A. H., electrolytic method for co-Magnesia inixture, preparation of, 328, 733 Magnesium ammonium phosphate method halt, 170 for phosphorus, 367 method for decomp. antimony ores, chloride in water, 1440 19 metallic, test for platinum, 377 pyroarsenate method for arsenie, 41 method for lead, 277 method for manganese, 307 pyrophosphate method for phosphorus, method for mercury, 312a 367 Low-freezing dynamite, analysis of, 1381 sulphate, arsenic in, 51 Lowenthal-Proctor on tannie acid, 1760 Maize oil, constants, 1148 Maletesta and De Nola, silver dct., 440 Lower oxides in nitrie acid, 1511 in oleum and mixed acids, 1530 Manganese-bronze, analysis of, A. S. T. M., 1047-1057 Lubricating oils (see under Oils, Fats, Waxes), 1115, 1148 Manganese, detection of, general procedure and head test, 295 Lundell and Knowles, on molybdenum, in soils, minerals, vegetables, etc., 295 Lunge-Marchlewski on carbon (ref.), 127 estimation, general methods: gravimetric, as manganese, pyrophos-Ray pipette for weighing of liquids, phate, 300 Ford-Williams method, 306 1498 Luteol indicator, 531 as manganese dioxide, 301 Lux, definition of, 708 volumetric, bismuthate method, 302a, 1360, 1362 McDaniel's app. for det. solubility of lead oxide method, 306 gases, 1488 persulphate method, 305 MacMichael's viscosimeter, 1116d sodium arsenate method, 17c Volhard's method, 302 Mackey's apparatus for spontaneous combustion-oils, 1140 estimation, special procedures: Magenta test for bromine, 92, 96 determination in alloys, 1056, 10 1093, 1100, 1101, 1106d, 1107 1057. Magnesia, effect on silica dehydration, 46 determination in iron and steel, 264 in slags, 1613 266, 1360, 1362

Manganese in bronze, det. of A. S. T. M.,	Mellor on precipitation of tungsten, 563
1047–1057	traces of lead, 282
in cast iron, 299	Melting temperature of elements, table of,
in ferro-manganese, 303b	658
in ferro-chrome, 299	Mene, ferric chloride method for tin, 535
	Mennick, chloric and perchloric acids, 153
in ferro-silicon, 299	Mercia, P. D., on nickel, 329, 336d
in ferro-tungsten and tung, metal, 573	Mercuric cyanide test for palladium, 382
in materials insoluble in acid, 299	
in metallic lead, 290	oxide method for separating magnesia
in metallic manganese, 304	from the alkalies, 407
in ores, 303, 307	Mcreurous nitrate method for chromium,
in slag, 1612	160
in spiegel iron, 306	method for precipitating molybde- num, 316
in steel, 266, 267, 1360	method for precipitating vanadium,
in steel, electrolytic method, 1680	587
in tungsten alloys, 514	
ores, 508	Moreover ableride namer for arrenia deter-
in tungsten ores and concentrates, 569	Moreury chloride paper, for arsenic deter-
preparation and solution of the sample,	mination, 47
alloys, ferro-aluminum, ferro-chro-	Mercury, cleaning of, 1279
mium, ferro-titanium, manganese,	detection of, 308 estimation, methods of procedure:
bronze, molybdenum and tungsten	gravimetric, electrolytic method, 310
alloys, silicon alloys; iron and steel; ores, iron ores, sulphides,	Halloway-Eschka method, 311
slags, 296	sulphide, precipitation, 310
separation from H ₂ S group, alkaline	volumetrie, by Seamon's process, 312
earths and alkalies, nickel and co-	thiocyanate method, 312a
balt, 298	occurrence, 308
from iron and alumina by basic acc-	preparation and solution of the sample.
tate, 298	ores, 308, 309
precipitation of manganese as dioxide,	purification of the reagent, 1279
MnO ₂ , 301	separation from members of subsequent
solubility of the metal and its oxides, 296	groups, 309
Manganese metal, Mn in, 304	from As, Sb, Sn, Pb, Bi, Cu, Cd, Se,
Manganese oxide in paint pigments, 1185	Te, 309
Mannitol, borie acid titration in, 86, 87	from organic substances, 309
Marsh, electrolysis of nickel, 335	solubility, 308
Marsh gas, det. of, 1227e-1248	Mercury, free, in fulminate, det. of, 1395,
Marsh test for arsenic, 47	1397
Martin, on absorption apparatus for CO ₂ ,	Mercury in organic matter, 312b
114	Mercury in rubber, 1581
Martin, H. E., on bauxite analy., 15	Mercury in zinc amalgam, 1107
Marvin, T., on vanadium, 596a	fulminate, analysis of, 1395
Masses, unit table of, 702	Merwin color screens, 402
Matte, copper, solution of, 179	and Stiegers' method for fluorine, 220
Mattes, decomposition of, 20	Messinger's method for acctone det., 1759
Maumene test for oils, 1126, 1135	Metabisulphite, gravimetric determina-
McDonnell and Roark arsenic separation,	tion, 511
37	volumetric iodine method for, 512
McDowell, method for hydrocyanic acid,	determination in presence of carbon-
131	ates, chlorides, sulphates, sulphites,
Meade, chapter on coments, 1202	thiosulphates, 514
Measuring apparatus vol., 1686	Metallic aluminum and its alloys, 5
Meat, arsenic in, 51	silicon and iron in, 17a
boron in, 83 Maiklaichn R M properties of com-	cobalt, cobalt in, 167, 172
Meiklejohn, R. M., properties of com- pounds, table XVII, 679–683	copper, 178 determination of gold, silver, lead,
conversion factors XVIII, 683-698	
volumetrie apparatus, 1685	bismuth, arsenic, antimony, se-
weights standardization, 1695	lenium, tellurium, iron, zinc, nickel, cobalt, oxygen, sulphur,
Mellor, calcium oxalate, decomposition of,	phosphorus, chlorine in, 199-206
107	gold, preparation of proof, 234
441	O-red brokenmen or broard age

Metallic Iron (and steel). See subject	Methyl violot test paper, preparation of,
determinations of carbon, manganese, phosphorus, silicon, sulphur in, 263– 270, 1351–1371d	1403 Metric and customary units, table XXI,
270, 1351–1371d chromium, cobalt, nickel, titanium,	Metzel and Vortman, method for anti-
tungsten, vanadium. See Iron and Steel Analysis.	mony, 24 Meyer's apparatus for zine determination
lead, determination of silver, bismuth,	(Figs. 72, 73, 74), 608
copper, cadmium, arsenic, anti-	Microchemical examination of crystals for
mony, tin, iron, cobalt, nickel, nian-	tantalic and columbic acids, 575
ganese, zinc in, 286-290c	Microscope, 1701
manganese, Mn in, 304	exam. of steel, 1701
nickel, aluminum in, 336d	Microscopical examination of water, 1442
	organisms in water, control of, 1451
bismuth in, 336c	identification of, 1449
cobalt in, 172 lead in, 336d	illustrations of, plate,
platinum, 380	list of, 1443, 1448
silver, preparation of pure, 448	Microscopical test of lubricating oils, 1123
tellurium and selenium in, 440	Microcosmic salt-reactions, table of, 627
zinc in zinc dust, 607	Milk, boron in, 83
impurities, lead, iron, cadmium in	Milliliter, def., 1694
spelter, 610	Mine gases, carbon dioxide in, 1270
Metallography, 1701-1722	Miner, H. S., on det. of thorum, 523a
carbon steel, microphotographs, 1713	Mineral acids. See Acids.
case hardening, 1720	analysis of water, 1421
copper-zinc alloys, metallography of,	matter in rubber, 1579
1710	oil, 1148
equilibrium diagrams, 1706	residue in water, 1434
etching sample for micro examination,	salts in burning oils, 1113 Minerals, decomposition of, for determina-
1705	tion of lead, 272
reagents for etching, 1705	detection of tungsten in, 554
ammonia ferric chloridc	list of common, 717
Le Chatelier No. 1	test for gold in, 228
nitric acid-alcohol	See list under dominating elements
nitric acid, concentrated, Sauveur	contained in Part I, also 717
picric acid-alcohol	Minium, lcad det., 290f
sodium picrate	Miscellancous, 1743
Yatsevitch's reagent	Mispickel, preparation for arsenic deter-
heat treatment of steel, 1719	mination, 37
influence of clements on iron and steel,	Mitscherlich's app. for N det., 351
1721	Mixed acid, analysis of, 1530 Mixtures, sodium and potassium carbon-
influence of mechanical work, 1716	ates and hydrates, 1556
iron-carbon alloys, 1711 iron, pure, microphotograph of, 1707	Modified sodas, analysis of, 1555
nucroscope, directions regarding, 1701	Mohr's alkalimeter, 124
photographic materials, 1703	method (modified) for antimony, 27
preparation of specimens, 1703	for arsenic, 43
Metals. See Metallic.	for chlorine, 150
Metaphosphoric acid, test for, 362	for iodine, 243
Meter, wet meter, rotameter, capoineter,	Moir's method for gold, 233
Thomas electric meter, orifice meter,	Moisture in air, 338, 1272, 1275, 1494
anemometer, 1233-1236	in arsenic, commercial, 53
Mcthane, determination of, 1248-1249	in bauxite, 15, 17f
properties of, 1227e	in brimstone, 519
Methyl alcohol, detection and determina-	in butter and fats, 1143-1144
tion, 1753	in coal, 1618
Methyl borate, distillation of boron, 84	in explosives. See subject.
Methyl orange indicator, 26, 347, 744,	in gases, 1275
1491	in nitrate of soda, 349
red indicator, uses of, 1491	in oils (burning), 1113, 1144

Moisture in paints and paint pigments, 1163, 1186, 1187, 1188, 1190, 1193, 1194,1195, 1196 in phosphate rock, 362 in silicate of soda, 448 in silicates, 443 in soap, 1600 in sodium fluoride, 226 in zine pulp, 598	Mortar, standard sand, water, percentage for (table), 1211 Moynahan, A. E., on silver, 458 Mulligan, J. J., on bismuth, 79 Muriatic acid, analysis of, 1501 Mustard cil, 1147, 1149 Myrtle wax, 1150 Narcetine, 1733
See also under special subjects	Naphtha solvent of rubber, 1573
throughout text.	Naphthalene in gas, 1262
Molybdate method for lead, gravinietrie,	Naphthylamine acetate reagent, 1414
275a	National Brass and Copper Tube Co.
velumetric, 277b	method for brass analysis, 206
Molybdate magnesia method for phos- phorus in iron and steel, 1363	National Lead Co. method (modified)
Melybdenite, comparison with graphite,	for metallic lead analysis, 286 Natural cement, U. S. Gov. specifications
313	for fluences, 1198
Molybdenite, molybdenum in, 322	Natural gas, analysis of, 1274a-
Molybdenum, dotection, general proced-	1274g
ure, 313	Neat's foot oil, constants, 1147, 1149
tests with sodium thicsulphate, sul-	Needle penetrometer, hardness test, 1214
phur dioxide, disodium phos-	Neon in the atmosphere, 338
phate, sulphurie acid, 313	Nephelometric method for silver, 463
estimation, general procedures: gravimetric, lead molybdate method,	Nessler jars for colorimetric titanium de- termination, 548
316	Nessler's method for animonia, 1413
mereurous nitrate, precipitation by,	test for ammonia, 337
316	New Jersey Zine Co., on barium ores
molyhdenum sulphide method, 317	analy., 66
volumetrie, iodometrie reduction	analysis of barytes, 60
method, 318	zine, 597
determination in presence of vana- dium, 321, 591	Neuman lines, metallography, 1718 Nowhall, C. A., on sulphur, 493, 517, 519
zinc reduction with Jones' re-	Newton, method for titanium, 543
ductor, 319	New York State Board of Health tester
occurrence, 313	for oil, 1109
preparation and solution of the sample	New York-Liverpool test for alkalies,
ores, 314	1552-1554
iron and steel, 314	Nickel, detection of, hydrogen sulphide
separation from iron, 314 from alkalies, alkaline carths, bis-	test, 329
muth, cadmium, copper, lead, ar-	As, Sb, Cr, Si, Sn, W, Zn, etc., in,
senic, titanium, vanadinm, tung-	336e-336f
ston, phosphoric acid, 315	bismuth in, 336e
ether extraction method, 315	dimethylglyoxime and alpha benzyldi-
solubilities, 314	oxime tests, 329
Molybdenum in molybdenum concen-	estimation, general procedures:
trates, 32.	gravimetric, alpha benzyldioxime method, 332
in ores—wulfenite, molybdenite, 322	Carnot's method, 336b
ores, analy. of, det. As, Cu, P, 325	dimethylglyoxime method, 333
Monazite, decomposition of, 522a	electrolytic method, 335
Moody and Leyson sol. app., 1470	volumetric method of Parr and
Morehead, J. M., analysis of industrial	Lindgren, 336, 1368e
gases, 1227 Morgan-Cahen-Little, arsenic det. in or-	potassium eyanide method, 336a,
ganic matter, 36	336b
Morphine, det., 1737	estimation, special procedures, nickel- plating solutions, 336
Morphine test for titanium, 538	determination in alloys, 336, 1083,
Morphine sulphate test for formaldchyde,	1094, 1106b
1754	in copper, 199, 202

Nickel in iron and steel, 1368d, 1368e in metallic lead, 290c lead in, 336d preparation and solution of the sample, general procedure for ores, 330 metallic nickel and its alloys, 330 separation from alkalics, alkalino earths, and members of the hydrogen sulphide group, 331 from aluminium, chromium, cobalt, iron, manganese, zinc, 331, 332 soluhilities, 330 Nickel-plating solution, determination of nickel in, 336 Nicotine, 1733 Niobium. See Columbium, 554 Nitrate, standard solution of, 1416 of soda, analysis of, moisture, insoluble matter, sodium sulphate, iron and aluminum oxides, linne, magnesia, sodium cloride, carbon dioxide, 349 Nitrates in black powder, 1373 in explosives, 1373, 1377 in nitrite salt, detection of, 359 Nitrates, removal of, in sulphur determination, 497 Nitrates in water, 1416, 1433 Nitric acid, complete analysis of, 1509-1512 conversion efficiency of NH ₃ conversion to, 361c determination of acidity, chlorine, hydrochloric acid, hodine, nitrous acid, sulphuric acid, 1509-1512 Nitric acid, det., arsenic in, 50 by ferrous sulphate method, 1512 free, determination of, ref., 357 etching acid, 1705 in arsenic acid, ferrous sulphate method, 1516 in hydrochloric acid, ferrous sulphate method, 1516 in phosphoric acid, ferrous sulphate method, 1516 in sulphuric acid, ferrous sulphate method, 1516 in phosphoric acid, ferrous sulphate method, 1516 in sulphuric acid, ferrous sulphate method, 1516 in sulphuric acid, ferrous sulphate method, 1516 in phosphoric acid, ferrous sulphate method, 1516 in phosphoric acid, ferrous sulphate method, 1516	Nitrocellulose, analysis of, 1399 in explosives, 1388 in gelatine dynamite, 1380 Nitrochorhydrin in explosives, 1383 Nitrocompounds, separat. from nitroglycerin, 1382 Nitrosulphuric acid method for silicon in steel, 1368a Nitrogen, detection of, combined as: aninonia, tests for, 337 Nitrogen, ammonia, Nessler's test, 317 nitric acid, copper test for, 338 diphenylamine test for, 338 ferrous sulphate test for, 338 nitrous acid, acetic acid test for, 338 permanganate test for, 338 organic nitrogen, 337 estimation, free, combined, and total nitrogen, 338 combined nitrogen, methods for: ammonia, gravimetric determination of, 342 combined and free, volumetric determination, 343, 1412, 1560 traces, 345, 1413, 1414 ammoniacal liquor, analysis of, determining carbon dioxide, hydrochloric acid, hydrogen sulphide, sulphuric acid, ammonia, 344, 345 nitrate of sods, 349 nitrates, Dovarda method modified, 346 as nitrate in water, 1415 as nitric acid, gravimetric method as nitro in trate, 346 as nitrate in water, 1414 as organic mitrogen in water, 1413 nitrogen in fertilizers, 330 in green pigments, 1196 in organic matter, nitrates being absent, 340 in organic matter in presence on intrates, 341 in rubber, 1503 in soil extracts, 350 in steel, 361a Kjeldahl method, 339 free nitrogen. See Gas Analysis, 125 per cent of, in air 338
in sulphuric acid, ferrous sulphate	in ruhber, 1593 in soil extracts, 350
mination, 368, 1364	Kieldahl method, 339
Nitric acid for etching, 1705 Nitrite (see also Nitrous Acid), 358	properties of, 1227f
detection of, 359	tetroxide in gas, 1270 occurrence, 338
estimation, 358	preparation of the sample, ammonius
gravimetric—Buovold's method, 358 volumetric—permanganate method,	salts and mixtures, 341
358, 1530	nitrates in soils, nitric acids ar mixed acids, 341
tables, 1517	organic substances in presence
Nitrite, in water, 1414	absence of nitrates, 340, 341

separations, ammonia, isolation of, 341 nitric acid, isolation of, 342	Oils—saponification value, 1140 unsaponifiable oils, detection of,
removal of impurities, nitrous chromic, hydrobromic, hydrobromic, hydri-	1140b Valenta test for, 1134
odic acids, 342 solubilities, 339	drying, semidrying and non-drying oils, 1149
special methods, nitrometer method for nitrates and nitrites, 353	special tests for certain oils, 1141
nitrometer of du Pont, 354	cottonseed oil, Becki's testfor, 1142 Halpen's test for, 1143
nitric acid in olcum, 357	drying on glass, 1144d
Nitroglycerin, determination of, 1376 dynamite, analysis of, 1374	free acid in, 1144c linseed oil, hexabromido test for,
smokoless powders, 1407 Nitropolyglycerin in explosives, 1383	1143 peanut oil, Renard's test for, 1144s
Nitrometer, 353, 354	rapeseed oil, Bach's test for,
gas analysis, Fig. 160, 1276 Nitron nitrate method for nitric acid, 342,	1144b rosin oil, Liebermann-Storch test
345	for, 1144b
Nitrosite method for rubber analy., 1568 Nitroso-beta-naphthol, precipitation of co-	sesamé oil, Baudoin's or Ca- moin's test, 1144b
balt with, 169 Nitrous acid, decomposing of iodides with,	spontaneous combustion test, Mackey's apparatus, 11440
242	titer test, 1145
and lower oxides in nitric acid, 1510 in oleum and mixed acids, 1531	Villa Vecchia test, 1144b fats, edible, 1146
gas, generation of, 94, 147	butter, 1146
permanganate method for, 358 removal of, from nitrio acid, 342	lard, 1147 hardened oils, 1147
oxide in gas, 1270	interpretation of tests, 1158–1160
Nitrostarch in explosives, 1388, 1390 test for, 1385	crude oils, gasoline, kerosene, lubri- cants, waxes, heavy oils and
Nitrosugars in explosives, 1383 Nitrotoluenes in dynamite, 1381	asphalts, shale oils, I158-1160 miscellaneous oils and lubricants, 1148
Non-drying oils, list of, 1149	paint oils (see under Paints and Paint
Normal consistency of cement, incthed of determination, 1206	Pigments), 1164 Chinese wood oil, tung oil (see sub-
Normal solutions. See Reagents. Norton apparatus for carbon det., 117	Chinese wood oil, tung oil (see subject under Paints), 1169, 1171
Noye's app. for det. solubility, 1471	paint, acid number, heating test, iodine jelly test, iodine number, re-
Occurrence. See under element in question.	fractivo index, saponification
Odor test of wator, 1411	number, unsaponifiable mat- ter, specific gravity, standards
Offerman's method for fluorine, 218 Ohm, definition of, 709	of, 1169–1171 petroleum products, 1109
Oils, fats, waxes, examination of unknown oil, 1108	burning oils, 1109
detection of oils in paint vehicles, 1164	acidity, detection of, 1113 color of, 1113
classified list, characteristics, and con- stants of oils (tables), 1152, 1154	distillation test, 1112e fire test, 1110
examination of	flash test, 1109
animal and vegetable oils, 1133 general test for, 1133	mineral salts in, 1113 specific gravity, 1111
acetyl value, 1141 antifluorescence, test for, 1141	sulphuric acid test, 1113 sulphur determination in, 1112e
bromine number, 1139	water in, 1113
elaidin test, 1135 iodino number, 1136	lubricating oils, 1115 carbon residue, test for in, 1122
Hanus's method, 1137	caoutchouc, test for in, 1121
Hübl's method, 1138 in oxidized oils, 1139	evaporation test of, 1116 fatty oils, test for in, 1121
Maumené test, 1135	fire test of, 1120 flash test of, 1118d
refractive index, 1134	addit wat ut, 11104

Petroleum friction test of, 1123	Organic matter, sodium peroxide method
gasoline test of, 1123	for halogens in, 146
gumming test of, 1121	fluorine, 214
microscopical test of, 1123	iodine, 237
soap, detection of in, 1121	determination of carbon in organic
specific gravity of, hydrometer	matter, 119-121
method, 1111	nitrogen, 339
Westphal balance method,	phosphorus in baking powder, 365
1111	potassium in soils, fertilizers,
viscosity, 1115	plants, 404
Engler's viscosimeter, 1112-	organie matter in water, 1417, 1419
1112d	Organic matter, destroyed by persulphate, 36
Saybolt viscosimeter, 1116	Organisms in water, classification, 1443,
Universal viscosimeter, 1116	1448
turpentine (see subjects under Paints),	identification of, 1449
1173, 1174	Ornice meter, 1236
color, distillation, polymerization,	Osmium, detection of, 396
refractive index, specific	by H.S., KOH, NH,OH, Zn, red.
gravity, standards of, 1173,	agts., KNO ₂ , 'Na ₂ SO ₃ , P, Hg, SnCl ₂ , etc., estimation of, 397
1174	SnCl ₂ , etc., esumation of, 397
U. S. Government specifications for	gravimetric determination of, 395
petroleum products, 1150-1151	occurrence, 396, 397
fuel oils, greases, 1150a	preparation and solution of sample, 397
gasoline, burning oils, 1150	properties, 396
Subricating oils, 1150b, 1151	separations, 397 Orsat apparatus (Fig. 120), modified
varnish (see subject), 1174, 1176 waxes, 1148	(Fig. 131), 1241, 1267
Oil in black pigments, 1196	Ottawa sand, standard, 1211
in water, 1435, 1436	Oulman's method for tartaric acid, 1551
Oils, reagents used in, 1157a	Ovens, drying, 1018-1020
tables of characteristics and constants,	Owen-Bradbury method for alkali car-
fatty acids, 1150-1154	bonates and hydrates in presence of
mineral oils, properties of, 1148	each other, 1556
vegetable and animal oils, 1152-1154	Oxalate method, separation of alkaline
viscosity conversion tables, 1156	earths from the alkalies and mag-
Saybolt, Engler, and Redwood	nesium, 59
Saybolt, Engler, and Redwood times, 1156	outline for separation of, 134
waxes, 1148	Oxalic acid, determination of, 1549
Oil shale valuation, 1350	method for manganese, 307
Olcum, complete analysis of, 1529	method for persulphates, 508
acidity, lower oxides, nitrie acid, sul-	Oxidation methods for det. iron, 251
phuric anhydride in, 1530	in platinum salts, 277
table of equivalents, 1539	test for methyl alcohol, 1753
Olsen, on analysis of alloys, 1071-1107	test for vanadium, 583 Oxide, determination of, aluminum, 7
test for fluorine, 213	bismuth, 74
Optical pyrometer (Fig. 107), 1228	cobalt, 167, 171
Orange pigments, analysis of, 1198	cobalt, 169
Ores. See under Preparation of Samples	copper, 179, 192
of Various Elements.	
Organic acids, analysis of, 1542	chromium, 159 iron, 248, 247
Organic matter, arsenie det. in, 36, 51	lead, 275b
decomposition of, for determination	manganese, 301
of antimony in, 21	tantalum and columbium, 577
for determining barium, 57	thorium, 524
boron, 83	tin, 531
bromide, 93	titanium, 542
chlorine and halogens, 145	tungsten, 558
Carius method for halogens	uranium, 581a
in, 145	vanadium, 587
lime method for halogens in,	zine, 599
146	zirconium, 618

	T 11 . 11
Oxidized oils, iodine number of, 1130, 1139	Palladium—detection of, 382
Oxygen, determination of, see Gas,	alk., NH4OH, SO2, CuCl, Hg(CN)2, KI,
Oxygen, properties of, 1227d	H ₂ S, KNU ₂ , FeSU ₄ , NH ₄ U ₁ , Sn,
Oxygen consumed in water (organic mat-	Cl ₂ , red. agts., etc., estimation,
ter in), 1417	382-383
Oxygen cylinders, illustrating method of	estimation in gold bar, 385
	in refined gold, 385, 387
eonneeting, 1224	in copper slimes, 386
determination of, in air, absorption with	
phosphorus, 1246	in silver, 386
potassium pyrogallate, 1247	gravimetrie methods, 384, 488
sodium pyrogallate (note), 1246	preparation and solution of sample, 383
in copper, 204	properties of, 382
in gas, 338, 1244, 1246, 1247, 1248	separation from platinum and iridium,
in steel, 1368i	383
dissolved in water, 1436	silver, gold, platinum, 383
dissolved in water, 1700	Palladous chloride reagent, 1191
explosion with hydrogen, 1247	iodide, method for determining iodine,
Paints and Paint Vehicles, analysis of	
(see Outline in Table of Contents),	239
1161	Palmer, L. A., on fire assay of gold and
pigments, elassification of, 1176	silver, 466
black pigments, analysis of, 1199	Palmer and Scibert, modified Gutzeit
blue pigments, analysis of, 1196	method for arsenic, 46
Prussian blue, Chinese blue, Ant-	Paper making materials, analysis of, 1773-
werp blue, 1197	1785
	aluminum sulphate, analysis of, 1773
sublimed blue lead, 1197	determination, Al ₂ O ₃ , Fe ₂ O ₃ , Fe,
ultramarine blue, 1196	SO ₃ , H ₂ SO ₄ , KF, insol.
green pigments, analysis of, 1198	
ehrome green, 1198	sampling of, 1773
red and brown pigments, 1190	bleaching powder, analysis of, 1779
iron oxides, 1196	determination of avail. Cl, total Cl,
red lead, orange mineral, 290f, 1190	ClO ₃ , bases, CaO, sand, grit,
vermillion, 1195	SiO ₃ , wood, etc.
yellow and orange pigments, chrome	quality test, 1780
yellow, American vermillion, ba-	sampling, 1779
sie lead ehromate, 1198	caustie soda, 1783
	alkalinity, sampling of, 1783
white pigments, 1176	lime, 1784
barytes and blane fixe, 1188	determination of, causticizing pow-
composite white paint, 1189	
eorroded white lead, 1181	er, impurities, lime, magnesia,
lithopone, 1186	mounture
silica, silex, China clay, asbestine,	rapid methods for lime, free CaO,
1187	CaCO _A , moisture, 1785
sublimed white lead, 1188	sampling, 1784
titanox, analysis of, 1190, 1192	rosin, 1773
whiting, Paris white, 1188	determination of acid number,
zine lead and leaded zine, 1182	ester, ash, dirt and foreign
zine oxide, 1183	matter, grade, saponification
	n., sizing, unsaponifiable mat-
vehicles, 1162	ter, 1775
liquid, percentage of, 1162	sampling, 1775
oils, detection of, iodine number, 1164	
Chinese wood oil, or tung oil (see	rosin size, 1776
under Oils, Fats, Waxes), 1169,	alkali, free and combined, insol.,
1170	moisture, rosin, 1776–1777
constants for various oils, 615,	sampling, 1776
1171, 1172	rosin, rapid methods, rosin, size, etc.,
other materials, 1175	1778
separation of components, 1163	soda ash, 1783
resinates, detection of, 1164	alkalinity, moisture, sampling
turpentine, examination of (see de-	starch and starch products, 1781
tails under Turpentine), 1172	determination of acidity, alkalinity,
	alkali, moisture, viscosity, etc.,
varnish, oxamination of, 1173-1173	1781
Paints in bituminous sub., 1346	1101

Paper making, starches, converted, 1782 acidity, alkalinity, added ma-	Permanganate, titration of, titanium, 544, 544a
terial, ash, moisture, etc., 1782 sulphuric acid, 1783	uranium, 581
determination of acidity, iron, sedi-	vanadium, 589, 591, 595 water for oxygen consumed, 1417
ment, sp. gr., etc., 1783	Permissible explosives, analy. of, 1384
Paraffin hydrocarbons in gas, 1288h	qualitative tests for, 1385
Paris white, paint pigment, 1188	Peroxide bomb, 1637
Parr, S. W., analysis of fuels, 1634–1662	determination of, 1755
and Lindgren's method for niekel, 236 calorimeter, 1634	method for ehromium, 157 formaldehyde, 1754
Parrodi-Mascazzini electrolytic method	lead as, 275b
for antimony, modified, 24	titanium, 545, 548
Parsons and Barnes' method for glueinum, 69a	Persulphate alkali titration, 508
Patterson, det. of manganese, 301	Persulphate of ammonium method for manganese, 266, 305
Peanut oil (see under Oils, Fats, Waxes),	Persulphate method for manganese in
1138	bronze, 1196
Pechard's process for separating molyl-	Persulphates, ferrous sulphate method for
denum from tungsten, 559 Pelouze, traces of lead, 281	determining, 508 oxalie acid method for determining,
Pelouze, traces of lead, 281 Penfield's method for CO ₂ , 109	508
Penski-Martins closed flash point test, 1314	Petroleum naphtha solubility test, 1319
Perborate method for cobalt det., 175	Petot formulæ for det. velocity of gases,
Percarbonate, determin. of, 126 Perchlorate, detection of, 143	707, 1235 Petroleum products (see under Oils, Futs,
determination of, 152	Waxes), 1109
method for determining potassium, 412	pH hydrogen ion concentration, 1430, 1457
Perchlorates in explosives, 1388	Phenacetolin indicator, 745
Perchlorie acid, determination of, 152 in presence of hydrochloric acid	Phenolphthalein indicator, 12, 745 preparation of, 12, 1152
and chloric acid, 153	uses of, 1491, 1492
Perchloric acid method for fluorine distill.,	Phenolsulphonie acid method for nitrates
215	in water, 1433
Periodates, determination of, 244 and iodates, determination of, in a	reagent, 1433 Phenyl, determn. of, 1549
mixture, 244	Phenylhydrazine method for aluminum in
Permanent standards for ammonia deter-	presence of iron in titaniferous ores,
mination in water, 1415	552
Permanganate method for det. copper, 195 for det. nitrites, 358	neetate test for gold, 229 Phloroglueid method for furfurol in
for det. oxalie acid, 1549	acetic acid, 1546
for det. peroxides, 1491	Phosphate baking powder, 365
Permanganate N/10 reagent, 255, 1360	effect on alkaline earth determinations,
test for nitrite, 138 titration of, antimony, 28a	Phosphate rock, decomposition of, 364
barium, 65	analysis of, 371
bismuth, 76	Phosphates in soap, 1606
ealeium, 17d, 108, 1425	Phosphates in water, 1424
ehromium, 161 formie acid, 1542	and phosphorie acid, arsenie in, 50 typical analyses of, 363
gold. 231	Phosphomolybdate method for vanadium,
iron, 17, 18, 256, 257, 257b, 374, 610,	596b
1207, 1423	Phosphorie acid and its salts, analysis of,
lead, 277 manganese, 264, 302, 304, 1426	1521 free, vol. det. of, 375
molybdenum, 319, 320	Phosphorie acid, effect on aluminum de-
nitrous oxides, 1511, 1516, 1530	termination, 8
peroxide, 1762	in phosphate rock, 372
phosphorus, 265, 369 solution standard, 369, 1360	removal of, from aluminum solutions,
tannie acid, 1760	tables, 667, 1523
· ·	•

Phosphorus, detection of hydrophosphor-	Platinum, detection of, 376
ous acid, 362	by KI, H.S, NH,Cl, KCl, FeSO, SnCl.
metaphosphorie acid, 362	NaOH, red. agts., etc., 376
orthophosphoric acid, 362	estimation of, 377
phosphorus acid, 362	gravimotric methods for—as met. Pt.
pyrophosphoric acid, 362	380, 488
estimation, methods of procedure, gen-	as ammonium salt, 381
cral, 363	electrolytic method, 381
gravimetric, direct precipitation of	occurrence, 377
ammonium magnesium phos-	ores, assay of, 399
phate, 376	preparation and solution of the sample,
as magnesium pyrophosphate, 367,	ores, 378
1363	platinum scrap, 378
as phosphomolybdate, 366	small amounts of platinum in presence
volumetric methods, alkali titration	of large amounts of iron, mag-
of phosphomolybdate, 368, 1364	nesia, etc., 378 properties of, 376
permanganate titration of reduced	properties of, 376
phosphate, 368b	separation from gold, 379
estimation, special methods, determina-	from iridium, 379
tion of, in iron and steel, 268,	from osmium, 380
* 364 * allows 1050 1069 1079 1094	from palladium, 379
in alloys, 1059, 1063, 1078, 1084 in alloy steel, 1365	from rhodium, 380
	from ruthenium, 380
in cast iron, 370a in copper alloys, 368a .	table of, 387b
in ferrosilicon, 370	solubility of the element, 377
in ferrotitanium, 370	reactions, table of, 400
in our metal 1060	special methods, platinum ores, 381 assay methods for platinum ores,
in gun metal, 1060 in steel, 258, 368a, 1363–1365	399
in tungsten alloys, 570	substances examined for platinum, 377
in tungsten ores, 564	Platinum metal group, 382
in vanadium steels, 370b, 1365	Platinum and palladium in gold bar (re-
occurrence, 363	fined), 385, 387
preparation of the sample, iron ores,	in copper anode slimes, 386
phosphato rock, minerals, titanium-	in silver (refined), 386
	wire, turbidity dct. in water, 1410
bearing ores, iron and steel, soluble phosphates, baking powder, 365	Poisons, detection and estimation, 1723-
separation of phosphorus as ammo-	1742
nium phosphomolybdate, 365	classification of, 1724
Phosphorus method for det. oxygen in	general procedure, 1724
gas, 1246	preparation of sample, 1723
pentoxide absorption bulb for moisture	Poisons, alkaloids, glucosides, etc., 1731
in gases (Fig. 134), 1275 Photometry, definitions, 708	acetanilid, 1732
Physical tests of mater 1410	bichromate-sulphuric a. phenyliso-
Physical tests of water, 1410	cyanide tests, 1732
Pieric acid-alcohol for etching, 1705 Pieric acid, examination of, 1392	atropine, 1735
Pig iron, arsenic in, 37	physiological, vitalis tests, 1735
Pig lead, analysis of, 286	brucine, detection, 1734 cocain, detection, 1735
Pigments with titanic oxide. 553	codein, 1736
Pigments of paint (see under Paint and	formaldehyde, Froehde, Marme's
Paint Pigments), 1176	reagt., nitric a. tests, 1736
Pipettes for gas analysis, 1237	morphine, 1737
standard, 1690	ferrie chloride, Froehde, formalde-
Pisani's method for silver, 463	hyde, iodic, Marme, nitric a.
Pitch. See Bituminous Substances.	tests, 1737
Pitch and bitumen in rubber, 1570	narcotine, 1736
carbon in coal tar, 1358	dil. sulphuric, Froehde, selenous-
Pitman on du Pont nitrometer (ref.), 354	H ₂ SO ₄ , sod. carb. tests, 1736-
Pitot tube (Fig. 113), 1234	1737
Plaster of Paris, 105	nicotine, detection, 1733
Platinum, care of, 723	opium, detection, 1738

Poisons, strychnine, 1734	Potassium, separation from hydrogen sul-
bichromate, Bloxom's, sulphocya-	phide and ammonium sulphide
nate tests, 1734	groups, 405
veronal, purification and detection,	alkali metals from one another, 408
1732	from aluminum, chromium, iron, ba-
	rium, calcium, strontium, phos-
carbolic acid, Millon's test, FcCl ₃ ,	
bromine, hypochlorite, nitrite tests,	phorie and sulphuric acids, etc.,
1730	in one operation, 407
carbon monoxide in air, 1740	from aluminum, chromium, iron,
in blood, 1741	titanium, uranium, phosphoric
chloral hydrate, detect. decomp., 1730	acid, 406
chloroform, 1728	from barium, calcium, strontium, 406
Nicoloux's t., phenylisocyanide,	from boric acid, 407
Schwarz's resorcinol tests, 1728	from magnesium ammonium phos-
cthyl alcohol, 1728	phate method, 408
chromic a., ethyl acetate, Licben's	barium hydroxide method, 407
iodoform, vitalis tests, 1728	mercuric oxide method, 407
hydrocyanic acid, 1725	from sodium and lithium, 408
estimation, 1727	from sulphates, 406
tests—prussian blue, Schonbein-	Potassium antimonyl tartrate standard
Pagenstecher, silver nitrate	solution, 29
and cyanide, sulphocyanate	broinate solution N/10, 26
tests, 1726	method for antimony, 26
metallic poisons, 1739	bromide, crude, analysis of, 96
arsenic, 1740	Potassium and sodium carbonates and
methyl alcohol (wood alcohol), 1728	hydrates, in presence of one an-
ptomaines, 1738	other, determination of, 1556
reagents, Froehde's, 1741	acid sulphate (bisulphate), fusion with,
iodo-potassium iodide, 1741	248, 330
Marme's, 1741	fusion of monasite, 522
Mayer's, 1742	carbonate, fusion with, 248
Millon's, 1741	chloride test for platinum, 376
selenious-sulphuric, 1741	test for iridium, 377
Plumbago. See Graphite.	cyanide method for copper, 194
Polymerization in analysis of turpentine,	evanide method for nickel, 336a
1173	dichromate method for iron, 253
Polymerized oils and resins, separation of,	0.1 N solution, 253, 734
1174	ethyl xanthate method for small
Portland cement, analysis of, 1216, 1219	amounts of copper, 197
rapid method of analysis, 1220	ferricyanide test for ferrous iron, 246
U. S. Gov. specifications for fineness,	ferrocyanide reagent, 600, 602, 604
1205	test for ferric iron, 246
Potash, 1576, 1579	fluoride method for alumina in alumi-
Potassium, detection of, 402	num salts, 12
estimation, general procedures:	reagent, 12
gravimetric, chlor-platinate method,	Potassium hydroxide, alcoholic ext. of
410	rubber, 1578
modified, 411	analysis of, 1553
	hydroxide test for iron, 246
indirect method, 413 Lindo-Gladding method, 412	test for rhodium, 390
perchlorate method, 412	test for ruthenium, 387
special methods, alkali determination	Potassium iodate det. of arsenic, 44
in silicates, J. Lawrence Smith	Potassium iodide starch test for nitro-
	cellulose, 1401
method, 416 lithium, potassium and sodium in	iodide method for antimony, 27
presence of one another, 416	iodide method for bismuth, 78
	iodide method for chromium, 161
magnesium, potassium and sodium	iodide method for copper, 193, 193b
in presence of, 418	iodide method for lead, 278
preparation of the sample, fertilizers,	for selenium, 436
soils, plant ash, saline residues, soluble salts, rocks and insoluble	test for palladium, 382
winord products 404 40K	for platinum, 376
mineral products, 404, 405	201 paramany 014

Potassium nitrite method for cobalt, 169	Radium, detection, 420
standard solution, 346	estimation, 420
test for cobalt, 166	alpha ray method, 421
for palladium, 385	emanation method, 421
for rhodium, 393	table, 428
permanganate. See Permanganate	Rammelsberg method for determining
method for phosphorus, 369	lithium, 415
N/10 solution, 369, 737, 1360	Rapeseed oil, 1139
reagent oxygen consumed in water,	Rapid method for cement analysis, 1220
1417	Rapid methods for copper (electrolytic
pyrogallate, det. oxygen with, 1247	Rare earths, detection of, 133
reagent for gas analysis, 1279 sodium and magnesium, determination	estimation, gravimetric, 134, 137
of, in presence of one another,	occurrence of, 133
413	preparation of the sample, 134
sulphate, estimation of potassium as,	separation, 134
410	from iron, aluminum, thorium, 134
sulphocyanate test for cobalt, 166	from other elements, 134, 135
for iron, 246	Rarer elements of the allied platinum
Powder—explosive. See Explosives.	metals, 389
Powell and Schoeller on cerium, indium,	Raschig's method for dct. hydroxylamine,
scandium, thallium, etc., 133, 139	352
Praseodymium, 133	method for sulphur, 507
Precipitation apparatus for sulphur de-	Reactions, tables of, 632, 653
termination (Figs. 61, 62), 497	Reagents: See also chapter on, Vol. 1, 725-746
Preliminary tests for alkaline earths,	acetaldchyde, 1745
Preparation and solution of the sample.	acetic acid, 726
See chapter on element in question.	acetic anhydride, 1755
Preservatives in butter, 1144	acid mixture for silica determination in
Price and Olsen, chapter on alloys, 1036-	aluminum, 16
1107	alcohol, 726
Primers, table of, 1398	alcohol for oil analysis, 1151
Priming of water, 1441b	aldehyde free, 1745
Pringsheim's method for halogens in	alizarine S for aluminum det., 14,
organie matter, 146	726
Prister's method for gold, 233	alkaline potassium permanganate for det. of albuminoid ammonia, 1413
Producer and fuel gases, 1230a, 1255	tartrate solution, lead det., 282
composition of, 1230a Proof gold, preparation of, 234	alpha-benzyldioxime, nickel det., 346
Properties of compounds, Part II table,	amino-nitrosophenyl-hydroxylamine sol.
683	for det. iron, 250
of elements and compounds. See chap-	ammonium acetate, lead extraction, 280,
ter of element in question.	726
Protein in rubber, 1567	ammonium carbonate, 726
Prussian blue, 1197	ammonium chloride solution for det. of
Ptomaines, 1738	ammonia in water, 726, 1412
Pulp, zinc, moisture in, 598	citrate solution, lcad det., 282
Pumps, suction, 1232	molybdate solution, vol. det. of lead,
Pycnometer, sp. gr. bitumin. sub., 1296	277, 726
sp. gr. dct., 1493, 1494 Pyridine in ammonium nitrate, 360	det. of phosphorus, 365, 726
Pyrite ores, 105, 178, 272, 296, 445	of phosphorus in water, 1424
Pyrogallate of potassium, reagent, 1279	oxalate solution, oxygen consumed
Pyrophosphate method for cobalt, 174	in water analysis, 1417
for thorium, 523	persulphate for manganese det., 200
Pyrophosphoric acid, test for, 362	phosphate, 727
- 11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	sulphovanete sol colorimetric
Qualitative tests, tables of, 625-654	sulphocyanate sol., colorimetric method for iron, 258, 610
Quartering coal (Fig. 103), 1617	antimonyl chloride solution, 25, 47
Dediction competion for 1859	antimony det. sols., 30, 727
Radiation, correction for, 1652	mentations and noming and that

基二

Reagents, etching steel for metallog. ex., 1705 Resgents, arsenite, N/10 solution, 28, 240, 727, 1360 arsenous acid solution, det. manganese, Fchling's solution, 730, 1159 306 ferric ammonium sulphate, for titanium Asolitmin solution, 1458 det., 544 barium chloride, 727 Sarium hydroxide, 1357 Baudisch's reagent for det. iron, 250 ferrie chloride solution for det. tin, 536, 730 chloride solution for det. tin, 586 benzidine hydrochloride for det. sulindicator for dct. chromates, 149 phates, 507, 728, 1427 in Volhard's method for silver, 442 benzyldioxime, alpha, 728 nitrate solution for zinc analysis, 602 benzoic acid standard, acidimetry and forricyanide of potassium indicator for alkalimetry, 1008 iron titration, 253 bismuth standard solution for det. bisferrocyanide of potassium standard somuth, 77, 78 lution, zinc analysis, 600, 602, 604, bismuthate of sodium for dct. man-ganese, 301 606h ferrous ammonium sulphate for iron in brilliant-green lactose-peptone bile, 1460 water, 731, 1423. bromine-potassium-bromide sol. for oxifor decomposition of substances, dizing sulphides, 498 bromine, 1151 1033-1035 for glycerol det., 1758 cadmium chloride sol. evolution method for manganese in steel, 1360 for sulphur, 345 for oil analysis, 1157a ferrous sulphate for nitric acid test, 337, 731 calcium chloride sol., det. hardness in water, 1434 calcium hydroxide, 728 N/10 sol., for det. barium, 65 carbon dioxide, preparation, acidimetry reagent for manganese det., 301 and alkalimetry, 1008 chlorine water standard solution for for det. nitric acid, 15b fluorine, standard solution for fluorine det. bromine, 95 det., 220 chromic acid for dct. SO2 in gas, 1267 fuchsin-sulphite, 1745 citric acid, solution for calcium det., 106 fuming sulphuric acid, 1278 cinchonine potassium iodide, cometric det. of bismuth, 77, 78 gus analysis reagents, list of, 1278 glacial acetic acid. See Oils, Fats, coloridet. tungsten, 497, 509 Waxes. Reagents, 1151 glycerol, dct. boric acid, 87 Hesse's agar, 1460 llydrochloric acid, preparation of arreagt. for tungsten det., 560, 728 cochineal indicator, 744 color solution for det. traces of lead, 282 color solution permanent standard for senic, free, 49 det. nitrites in water, 545 hydrochloric acid, standard sol., 1495 for det. fluorine, 220 0.1 N, 731 1357, 1495 copper standard solution, copper analysis, 165, 166, 193, 197, 198 for oil analysis N/2, 731, 1152 hydrogen, 730 copper sulphate standard solution, det. hydrogen peroxide for titanium det.. 546, 731 hydrocyanic acid, 131, 729 cupierron reagent for det. iron, 250 for gas analysis, 1278 for water analysis, 1426 hydrogen sulphide, 732 cupric potassium chloride for separation of carbon from steel, 111 iodate N/10 solution for det. iodine, cuprous chloride, acid, for det. CO in gas, 1268 ammoniacalfordet. CO in gas, 729, 1278 iodide sol. for det. oxygen in water, 1432 iodine N/10 reagent, 28, 731 Devarda alloy for reduction of nitrates, 346, 730 for oil analysis, 1152 dichromate of potassium N/10 and N/5 solution for dct. tin, 533 solutions for iron det., 252, 734-736 iodo-potassium iodide, 1741 dimethylglyoxime reagents for nickel det., 333, 730 iron standard solution for standardization of stannous chloride reagent, 257, 258, 730 diphenylcarbazide for chromium det., 132, 730 for col. method of iron in spelter, reducing mixture for sulphates, evo-611 lution method, 502 iron in water, 1423 Endow's medium, 1459 lead acetate cotton, antimony det., 30

Reagents, lead acetate for molybdenum Reagents, dichromate reagent for iron det., det., 316 253, 734-736 ethyl xanthate for det. copper, 197 reagent for oil analysis, 1152 acid solution, zinc analysis, 610 standard solution for col. det. of ferricyanide indicator for iron det., 253, 736 lead, 282, 733 ferrocyanide for det. copper, 186 subacetate, 1758 for zinc det., 602, 736 litmus indicator, 744 fluoride for free acid in aluminum salts, 12, 736 hydroxide for carbon det., 737 litmus-lactose agar, 1459 magnesia mixture for det. of phosphorus, 328, 367, 733 hydroxide for oil analysis, 1152 iodide for det. bismuth, 78 manganous sulphate solution for det. dissolved oxygen in water, 1431 nitrate standard, 346, 737 permanganate N/10 sol., 254, 369, 737 mannitol, boric acid det., 87 Marme's reagt., 1741
Mayer's reagt., 1742
mercuric chloride test paper for antimony det., 30, 733 proof gold, preparation of, 234 pyrogallate of potassium for oxygen det. in gas, 739, 1279 reducing agents, 70, 152, 156, 177, 251, 261, 420, 421 for arsenic det., 47 mercury for gas burettes, 1267, 1279 rosalic acid indicator, 744 methyl orange indicator, 26, 347, 744 Renard-Tolman test for oil, 1144a red indicator, 347, 744 Russell's media, 1460, 1468 methyl violet test paper, 1403 Millon's reagt., 1741 salicylic acid reagent for traces of iron det., 259 naphthylamine acetato solution for det. salt solution for chlorine det. in water, nitrites in water, 1414 739, 1417 Nessler's solution, ammonia det. in Schiff's fuchsin bisulphite, 739 selenious-H2SO4, 1741 water, 1412 nitrate standard solution, 734, 1416 silver carbonate, 1758 silver nitrate, N/10 solution, 149, 150, nitrie acid, N/10 solution, 368 nitric acid, pure, 149 740 nitrosulphonic acid for elaidin test of solution for det. chlorine in water. oils, 1152 1417 nitrous acid solution for decomposing silver nitrite, alkaline, 1745 iodides, 242 preparation of the pure metal, 448 nutrient agar, 1458 nutrient broth, 1457 standard solution, 442 soap standard solution for det. hardness nutrient gelatin, 1458 in water, 1434 oils, fats, and waxes, list of reagents for examination of, 1157 sodium arsenite. See Arsenous Acid. bismuthate for det. manganese, 17c, oxalic acid, 734 301, 740 palladous chloride, 734 carbonate standard solution for CO2 paraffin, 734 det. in water, 1429 permanganate solution for manganese preparation of pure salt, 1493 hydroxide N/10 solution, 368, 741, det., 301, 307, 1360 N/10 solution for det. of iron, 255. 1357, 1364 737 for Devarda method, 347 solution for det. of oxygen consumed potassium hydroxide reagents, in water, 1417 water analysis, 1416 peroxide solution for det. titanium, 548, metabisulphite, method of production, 285 phenolphthalein indicator, 12, 745, 1152 nitrite solution, nitrite det. in water, phenolsulphonic acid for det. of nitrates 1414 in water, 1415 hydroxide, det. nitrates in water, 1416 phosphate standard solution for phossulphide, 741 thiosulphate, 741 phates in water, 1424 potassium antimonyl tartrate solution stains, standard (colored plate), 46 antimony det., 31 arsenic det., 47 for det. antimony, 29 bromate N/10 solution antimony det., 25 sulphur det., 520 stannous chloride solution for det. chromate indicator, 1417 cyanide solution for copper det., 194 ferric iron, 253, 257, 743

Research solution 041 501 740	Dhadium detection of 1900
Reagents, starch solution, 241, 501, 743, 1152, 1279, 1432	Rhodium—detection of, 393
	by H.S. KOH, NH ₄ OH, KNO ₄ , Zn,
steel analysis reagents. See chapter on subacetate of lead, 1758	red. agts.
gulphanilia acid solution for det nitrites	estimation, 393
sulphanilic acid solution for det. nitrites	gravimetrie methods, 395b
in water, 1414	preparation and sol. of sample, 394
sulphocyanate for colorimetric det. of iron, 258, 611	separation from iridium, 394
	palladium, platinum and ruthenium,
sulphurie acid standard solution, 1495	Bishard's jet numn (Fig. 100) 1939
for ammonia det., 346 tannin indicator, Alexander's molyb-	Richard's jet pump (Fig. 109), 1232 Riche and Bardy method for det. methyl
date method for lead, 277	alcohol, 1753
	Rickett's overflow pipette, 444
tartrate, alkaline solution of, for det. traces of lead, 282, 743	Richlé automatio cement-testing machine
test reagts. for linseed oil, 1167	(Fig. 107), 1215
thioeyanate of ammonium or potassium	Riffle, sampling of copper, 190
N/10 solution, 149	Ring and ball method, fusing point, 1308
thiosulphate of sodium for det. of cop-	Roark and McDonnell, arsenic separation,
per, 208	37
N/100 solution, water analysis, 1432	Robert's analysis for copper and lead, 207
for pot. iodido method for copper,	Robert's L. D. Radium chapter, 419-429
193, 195	Robin's test for boron, 87
N/10 solution, 240, 742, 1152, 1279	Rock, phosphate, analysis of, 255
reagent for lead det., 278a	Roofings, exam. of, 1339
thymol solution for titanium det., 551	Rosalie acid, 745
tin, standard solution of, 533	Roscoe's lead acetate method for vana-
titanium, standard solution of, for	dium, 588
fluorine det., 220	Rose's method for determining bismuth,
for titanium det., 546, 548	76
turmeric indicator, 745	mercurous nitrate method for vana-
Wagner's solution, caleium det., 106	dium, 587
Red lead, lead peroxide in, 290f	Rosenbladt and Gooch, method for boron,
determination of, 290d	Pagemetainly mathed for culphyn in mul-
method for manganese, 266	Rosenstein's method for sulphur in rub-
Red pigments, 290d, 1176, 1190, 1196	ber, 1581 Dogin in wilder 1564 1567
Reduction of iron compounds, method	Rosin in rubber, 1564, 1567 in paper making materials, 1773, 1776,
for, 251	1778
method for nitrates, 341, 346 Reductor, Jones, 256, 319, 320	in soap, 1602
Redwood, viscosity of oils (note), 1115	oil (see subject under Oils, Fats, Waxes),
References, list of 747	1139
References, list of, 747 Refineries, Se and Te det., 439	Rotameter (Fig. 114), 1235
Refractive index, 1134	Rowell's method for antimony, 25
animal and vegetable oils, 1125	Rubber, analysis, 1563-1597
Chinese wood oil, 1169	acetone extraction of, 1576, 1585, 1587
turpentine, 1173	acidity in, 1570
Refractory materials, decomposition for	alcoholie KOH extraction of, 1578, 1585,
ehromium determination, 157, 257a,	1588
1032	analysis of, 1563, 1587
Refractometer, Abbé, 1125	Alexander's method, 1568
Refractory ores, decomposition of, 257a	Budde's method, 1568
Reich method for SO ₂ in gas, apparatus	Henrique's method, 1582
for (Fig. 130), 1265	Spence's method, 1567 antimony and mercury in, 1572, 1581,
Reichert-Meissl number, butter fat, 1143	1591, 1592
Renard's test for peanut oil, 1144a Residue, total solid, in water, 1419	barium carbonate in, 1595
Resinates in paint vehicles, 1163	barium sulphate in, 1591
Resins and polymerized oils, separation	bitumen and pitch in, 1570
of, 1175	ealculations, 1596-1597
Resins in explosives, 1377	earbon in, 1580, 1592
in rubber, 1567, 1582	cellulose in, 1595
Reverberatory slag analysis, 1610	chloroform extract of, 1585, 1588
60	

Rubber, commercial evaluation of, 1564	Sampling—special liquids, sampling of, 1025
compounding materials in, 1571 constituent, essential of, 1563	solids—apparatus for reduction and preparation, 1012
crude, analysis of, 1565	collection of gross sample, 1004
estimation—Hubner's method, 1580	cone and quartering of, 1010
of raw rubber, 1564	containers for shipment to lab.,
fillers—organic in, 1569 glue in, 1593	1018 drying ovens for moisture det.,
gutta percha and balata, 1584	1018
hydrocarbons in, 1594	long pile and alternate shovel
mechanical goods, 1582	method, 1009
mineral matter in, 1579 nitrogen in, 1593	mixing and dividing samples,
outline table of analysis, 1577, 1583	reduction and preparation of,
oxidation method, vulc. rub., 1578	1008
preparation of sample, 1586	sieves standard, 1016
protein in, 1567	unit of, 1003
reagents, 1586 rosin in, 1564, 1567	vacuum ovens, 1019 Sand, analysis of, 448
rubber det., 1585, 1594, 1597	silica in, 448
saponifiable matter in, 1569	Sanger, method for traces of antimony,
solutions, analy. of, 1580	modified, 28
solvents, examination, 1573 specific gravity of, 1574, 1587	Sanitary analysis of water, 1410, 1442–1453
sulphur free and combined in, 1569,	Saponifiable matter in rubber, 1569
1585, 1588	Saponification number in analysis of oil,
tackiness in, 1564	1131, 1169
unsaponifiable matter in, 1593	value in oils, 1140
vulcanized, examination of, 1575, 1576 waste and reclaim, analy. of, 1570	Savell, chapter on cobalt, 166 on nickel, 321
wet methods of analysis, 1597a	Saybolt viscosimeter, 1115-1116
Rubber goods, antimony in, 21, 1581, 1591	Saybolt to Engler times conversion table,
Rubldium, detection of, 402	1151
separations, 408 Rudorff's apparatus for carbon dioxide in	to Redwood times conversion table,
gas (Fig. 128), 1263	Scale in water, 1441b
gas (Fig. 128), 1263 Ruthenium, detection of, 390b	Scandium detection and determination,
by KOH, H ₂ S, (NH ₄) ₂ S, Zn, KCNS,	140
AgNO ₃ , HgNO ₃ , ZnCl ₂ , KI.	Schaeffer and Gardner, chapter on analy-
estimation, 390 gravimetric methods, 392	sis of paints, 1161 Scheelite, analysis of, 564
separations from iridium and plati-	Scheibler and Dietrich, determination of
num, 391	carbon (reference), 125
from rhodium, 392	Schmatolla, titration of aluminum sults
Saint Sernin's method for calcium, 108d	(ref.), 11 Schmitz, W., method for antimony in
Salas, L. E., on rubber analysis, 1563-1584	rubber goods, 21
tin, presence of, in silver det., 446	for magnesium determination, 293
Salicylic acid method for small amounts	Schoeller and Powell, chapter on cerium
of iron, 262 test for iron, 246	and the other rare earths, 133-138 chapter on indium, scandium and
Saline residues, preparation of, for alkali	thallium, 139–141
det., 405	Schroetter's alkalimeter, 124
Salt, standard solution, 1417	Schum on aluminum, 17
analysis of table, 419 Sampling—general methods of, 1003-1031	Scott, apparatus, hydrogen sulphide gen- erator, 42
Introduction, 1003	evolution, for sulphur determi-
Gases—apparatus, 1027	fiation in steel, 543
general considerations, 1028	(and Briggs), modified Orsat for
grab sample, taking of, 1029	SO ₂ gas determination, 1267 arsenic and chlorine in gas, 1765
Liquids, apparatus, 1021 in motion, sampling of, 1023	beam test of gases for det. dust, 1763
	and the same of th

Scott—chapters on Al, Sb, As, Ba, Bo, Br, Cd, Ca, C, Cl, Cr, Cu, F, I, Fc, Pb, Mg, Mn, Hg, Mo, N, P, Si, Sr, S, Ta, Sn, Ti, W, U, V,, acid-	Sellers, W. S., apparatus for tin det., 535 Semi-drying oils, list of, 1148
Pb, Mg, Mn, Hg, Mo, N, P, Si, Sr, S. Ta, Sn, Ti, W. H, V, acid-	Separations of copper compounds, 208 general procedure for iron, 248
imetry, decomposition methods,	of metals—qualitative table of, 628-629
iron and steel, slags, miscel-	Separatory funnel and graduate (Fig.
laneous, etc.	130), 1236
conversion tables—clements and com-	Sesamé oil (see under Oils, Fats, Waxes),
pounds XVIII, 683-698	1139
formulæ for gas velocity det., 707, 1235	Setting time for cement, 1210
formula for diluting solutions, 1533	Shale oil, valuation of shale, 1350
methods—calcium acetate m. for det.	Shelton's method for traces of autimony,
fluorine in fluorspar and alkali	29
fluorides, 223	Shields' formula, 1255
diphenylamine method for chro-	Shimer's combustion apparatus for deter-
minn, 164a	mining carbon, 116
diphenylamine method for iron,	method of analysis of coment rocks,
257b	1214
fluoride method for free acid in	Short iodide method for copper, 193b, 211
aluminium salts, 12	Sieves, standard, 1016 •
lead, det. by chromate-ferrous-di-	Silica, in arsenous oxide, 53
phenylamine method, 278b	in aluminum hydrato, 17h
lead, determination of traces by	in barium ores, 67
acetate extraction, 279	in bauxite, 17f
(and Bowman), nitric acid, de-	in calcined ore, 17j
termination of, with ferrous	in iron and steel, 445
sulphate, 1512	in hydrochlorie acid, 1502
sulphur, combustion method for, 547	in paint pigments, 1187 in Portland cement, 1216
Seamon's volumetric method for deter-	in sand, 448
mining mercury, 312	in slag, 1610
Sediment, determination in oils, 1132b	in soap, 1604
Sedgwick-Rafter water examination, 1445	in sodium fluoride, 226
Seeker-Clayton method, modified, for det.	in titaniferous ores, 552
traces of lead, 282	in ultramarine blue, 1193
Scidell, A., on det. solubility of sub., 1469	in water, 1422
Selenious acid ppt. of Zr, 622a	removal of, in sulphur det., 497
Selenite of soda, 440b Selenium, commercial, analysis of, 439	Silicates, alkalies in, J. Lawrence Smith method, 416
in sulphuric acid, det., 1527	decomposition of, for fluorine determi-
Selenium, detection of, 430, 431	nation, 214
estimation, gravimetric methods:	for iron determination, 248
by reduction with potassium inclide,	list of, acid-soluble and acid-insoluble.
436	443, 444
by reduction with SO ₂ , 433, 435	materials high in, decomposition for
volumetric method, 440a	chromium determination, 157
estimation, special methods in refined	Silicate of soda, analysis of, 447
copper, 202, 440a	Silico-fluoride test for potassium, 404
in commercial selenium, 439 in complex mixtures, 431	Silicon, detection of, 441 errors, causes of, 442
in glass, 440b	estimation, method of determination,
occurrence, 434	general procedure, 446
separation of selenium and tellurium	special procedures:
from iron, zinc and other members	determination in alloys, 1095, 1103
of the group, and from the alka-	in metallic aluminum, 16
lies and alkaline earths, 432	combined silicon in iron and
from tellurium by Keller's method	steel, 270, 445
and by distillation method, 432	graphitic silicon in aluminum, 17
and tellurium, determination of, in refineries, 439	tungsten metal and alloys, 572
in copper, 440c	occurrence, 441 preparation and solution of the sample,
apparatus for separating (Fig. 57), 433	general considerations, 442
	Q

Silicon, decomposition of silicates with acids, 443 fusion and solution methods, 17a	Silver-sulphate-sulphurous acid method for disting copper compounds, 208 Simpson's process for opening up titanif-
fusion methods for silicates not de-	erous minerals, 576
composed by acids, 444	Skinner and Baughman on iodine in
methods for decomposition of carbide and carborundum, ferrosilicon,	water, 245 Skinner, W. W., 97
iron and steel for silicon, slags	Skowronski, S., det. Pt and Pd in refined
and roasted ores, sulphides and	gold, 387
pyrites, chromium, molybdenum	Slag analysis, chapter on, 1609–1615
and tungsten steels, 445 in iron and steel, 270, 1368	decomposition of, 1610 Slag (matte), decomposition of, for copper
in metallic aluminum, 17a	determination, 179
in nickel, 336e	and silicious ores, decomposition of, for
Silicon alloys, analysis of, 17e carbide, 445	fluorine determination, 214 decomposition of, for manganese deter-
Silver arsenate method for det. arsenic, 45	mination, 296
Silver, detection of, 451	decomposition of, for silica determina-
estimation, general procedures: gravimetrie, by electrolytic deposi-	Slime, copper, Se and Tc in, 440a
tion, 455	Pb, Se and Te in, 440a
as silver chloride, 453	Sling psychrometer, 1272
as silver cyanide, 455 volumetric, combination methods,	Slip bands, metallography, 1717 Slow method for copper (electrolytic det.),
462	188
Denige's cyanide method, 462	Smith, E. F., electro analysis of plati-
Gay-Lussac method, 457 miscellaneous methods, 463	num, 329 Smith, F. H., method for analy. of phos-
ncphelometric incthod, 463-465	phoric compds., 1521
procedure for determining silver in lead, 286	Smith, J. L., alkali det., 416 Smoke in chimney gases, 1255
U. S. Mint method, 458	Smokeless powder, analy. of, 1404
U. S. Mint tables, 461	Smoot, A. M., on molybdenum, 313, 322
Volhard's method with thiocya- nate, 456	on tungsten, 554, 560 platinum, palladium, gold and silver
in ores, 466, 488	8888.V. 488
occurrence, 452	Snake weighing tube, 1499
preparation of pure silver, 463 Silver bullion, fire assay of, 484	Soap, detection of, in lubricating oil,
Silver, fire assay of, 566-588	Soap bar, liquid, powder and chips, 1598
Silver, recovery from residues, 461 Silver, refined, platinum and palladium	analysis of, 1598–1608 acid number of fatty acids, 1604
in, 386	alkali combined, neutral soaps, fatty
solubility, 452	anhydride, 1601
Silverarsenate, determining of, in arsenic, 45 bromide, precipitation of, 94	alkali free, free acid, free carb., sili- cate, borax, phosphate, starch,
carbonate reagent, 1758	etc., in, 1600-1607
chloride, precipitation of, 148a	alcohol insoluble, analy. of, 1600
ohromate method for chlorine, 150 eyanide, determination of silver as, 455	borax in, 1604 carbonates in, 1605
iodide method for iodine, 239	chloride in, 1602
nitrate detection of bromine, 92	glycerol in, 1607
method for chlorine, 148 for strentium, 492	moisture and volatile matter, 1600 phenolphthalein in, 1606
paper for traces of antimony, 29	rosin—Twitchell's and Wolff's meth-
standard solution, 1417 N/10 solution, 149, 150	ods, 1602
test for chlorine, 142	sampling of, 1598 silica in, 1604
volumetric method for alkalics, 418	starch in, 1607
nitrite reagent (alkaline), 1745 thiocyanate method for bromine, 95	sugar in, 1607 sulphates in, 1603, 1606
-ferrie alum method for chlorine, 149	titer test of, 1603
	· ·

F

Soap - unsaponified and unsaponifiable Sodium nitrite standard solution, 1414 matter, ether and gasoline methoxide, determination in silicate of soda, ods, 1602 437 volatile hydrocarbons in, 1608 in ultramarine bluo, 1193 water soluble and insoluble matter, peroxido chemical for calorimetry, 1635 1602 peroxido fusion from chrome iron ores, Soda asbestos for C det., 1354 157 Soda ash, analysis of, 1554, 1783 fusion of tin ores, 527 Soda, value for, in water analysis, 1441 method for halogens in organic mat-Sodium bicarbonate, 1554 ter, 146 Sodium, detection of, 401 estimation, general procedures: method for decomposition of organic matter, 146 difference method, 410 See also under Peroxide indirect method, 413 test for iron, 246 sodium chloride, determination as, 409 potassium and the other alkalies, chapsulphate, determination of, 409 ter on, 401 estimation, special procedures: potassium in water, 1427 sodium and potassium in water, 1427 potassium and lithium in presence of Sodium picrate for etching, 1705 pyroantimonate, test of sodium as, 401 one another, determination of, 416 pyrogallate, oxygen det. with (note), potassium and magnesium, in pres-1246salts in tetryl, 1395 ence of one another, determination of, 413 Sodium sclenite, analysis of, 440b preparation and solution of the sample, sulphate, estimation of sodium as, 408 404 in sodium fluoride, 223 separation from potassium, lithium, in sodium nitrate, 349 rubidium and casium, 405 test for strontium, 489 Sodium arsenite, method for det., 17e reagent, 240 sulphide, available H₂S in, 509 analysis of, 1762 sulphite, acid titration of, 412, 514 Sodium carbonate, analysis of, 1554-1556 fusion test of silicates, 431 determination of, in presence of carfusion with, 248 chlorides, metabisulbonates, in sodium fluorido, 223 phites, sulphates and thiosulor bicarbonate, fusion of silicates, 434 phates, 514 determination in presence of acids of thiosulphate, detection of aluminum sulphur, 515 with, 3 preparation of the pure salt, 1493 determination of aluminum with, 9 chloride, arsenie in, 51 effect of, in silica determination, 436 determination of, in presence of carbonates, chlorides, metabisulphites, sulphates and sulphites, 514 estimation of sodium as, 409 dct. in presence of S comps., 415 in silicate of soda, 438 standard solution for copper deterin table salt, 419 mination, 193 fluoride, analysis of, 226 in hydrosulphide, 413 in sodium fluoride, 224, 226 N/10 solution of, 240, 1152, 1190, 1194, 1279 test for molybdenum, 313 in sodium nitrate, 349 Softening of water, 1441b Soils, nitrogen in, 350 Sodium hydrosulphite, det. of, 516 Sodium hydroxide, alcoholic solution, 1168 Solder, antimony in, 28 analysis of, 1552 soft and white metal, analysis of, 1047specific gravity table, 676, 1558 standard solution of, 1167, 1351, 1364 1048 Solenoid apparatus, electrolysis of copper. hydroxide fusion of ores, 20 187 method of Heath for det. copper, 187 of tin ores, 527 Solidification points in explosives. See subj., 1391, 1392 test for platinum, 377 N/10 reagent for phosphorus determination, 368 Solid phase, identification of, 1480 table, 676, 1558 Solids in explosives, separation of, 1385 metabisulphite, alkali titration of, 513 in water, 1421 determination in presence of carbonmetals in acetic acid, 1547 ates, chlorides, sulphates, sul-phites, thiosulphates, 515 nou-volatile in nitric acid. 1512 sampling of, 1003

0.1.122	0
Solubilities, elements, their oxides and	Spectrum of potassium, 402
salts, given under Estimation. See	of rubidium, 403
chapters.	of sodium, 401
Solubility—chapter on, 1469-1490	of strontium, 489
qualitative table of, 654	of thallium, 522
McDaniel method, 1488	Speisses, decomposition of, 20
det. apparatus, 1470-1479, 1488	Spelter, impurities, determination of cad-
distribution coefficients, 1486	mium, iron, lead, 610
electrolytic conductivity method,	
1486	Spence's method for rubber analysis, 1567
	Spent oxide, evaluation of, 518
freezing point method, 1483	Sperm oil, 1147, 1149
of gases in liquids, 1487	Spicgel iron, manganese determination in,
saturated solution, analysis of, 1480	306
synthetic method, 1482	Spirits of winc, ethyl alcohol, 1521
solid phase identification of, 1480	Spontaneous combustion test of oils, 1140
separation of saturated sol. from	Stains, standard for arsenic dct., 47
solid, 1480	Standard acids, 1494
titration method, 1484	Standard reagents. See Reagents.
volume change method, 1484	Standards for Chinese wood oil, 1169
table of metallic compounds, 654	linseed oil, 1171
Solution nicthod for rubber, 1597a	turpentine, 1173
for silicon, 17a	Stannic acid method for tin in bichloride
Solvents of rubber, 1573	by hot water precipitation, 527
Soundness or constancy of volume of	Stannous chloride, action on hydrochlor-
cement, 1202	platinic acid, 377
Specific gravity—bituminous substances,	apparatus (Fig. 41), 373
1295–1297	method for iron, 260
cement, 1204	reduction for ferric solution, 253
charts of sulphuric acid, 1524	test for niercury, 308
definition and methods of det., 709,	Starch in explosives, 1378, 1390
1502	in paper making materials, 1781-1782
animal and vegetable oils, 1124	in soap, 1607
burning oils, 1111	Starch solution, preparation of, 241, 501,
lubricating oil, 1111	1432, 1557
turpentine, 1173	preservation of, 241
gases—table XXIII, 706, 1274e-	Stas overflow pipette, 444
1274g	on iridium, 390
hydrometer method, 1111, 1502	Stead's method for separation of arsenie, 37
of ecment, 1204	Steel, elements det. in. See Iron and
of gas, 1262, 1274a	Steel Analysis.
of oils, 1111	Steiger-Merwin method for determining
pycnometer method, 1493, 1494	fluorine, 220
rubber, 1574, 1578	Stephen's method for sulphur in rubber,
Westphal balance method, 1111	1579
Specific heat, definition of, 708	Stopcock grease, 1686
of gases, 1280	
Specific volume of degree Chancel of S, 519a	Storm, C. G., on explosives, 1372 Stromayer and Rose, separation of ba-
Specifications for cement, 1202-1214	rium from calcium and strontium, 60
for elements in steel, 1371–1371d	Strontium, detection of, general procedure,
for carbon, 261, 1371	flaine test, sodium sulphate test,
for manganese, 267, 1371a-1371d for phosphorus, 238, 1371a-1371d	spectrum, 489
for ellion 970 1271h 1271d	estimation, general procedures:
for silicon, 270, 1371b-1371d	gravimetric, as carbonate, 491 as oxide, 491
for sulphur, 269, 1371a-1371d	
Spectroscopio method for determining	as sulphate, 491
lithium, 414	volumetric, alkalimetric method, 491
Spectrum, detection of barium by means	chloride titration with AgNO ₃ , 492
of, 56	occurrence, ores and minerals, 489
of cadmium, 100	preparation and solution of the samplo,
of casium, 403	490
of calcium, 104	separation from alkalies and magne-
of lithium, 403	sium, 490

Strontium, sep. from barium, 490 from calcium, 61, 490	Sulphur, detection of, element, 493 sulphide, sulphites, sulphates, thio-
solubilities, 490	sulphates, 493
Strychnine, tests for, 1734	estimation, general procedures:
Subcarbonate of bismuth, precipitation	gravimetrie, as barium sulphate pre-
of bismuth as, 74	cipitated from hot solutions,
Suction ventilator (Fig. 103), 1217	497
Sugar in explosives, 1388	as barium sulphate precipitated
in soap, 1607	from cold solutions, large vol-
test for, in explosion, 1385 Sulphanilic acid reagent, 1414	ume, 498
Sulphate method for det. barium, 64	combustion method for sulphide
method for det. cadmium, 101	ores, 504
method for det. calcium, 108d	volumetric methods, titration with barium chloride, and potassium
method for det. lcad, 274	dichromate (Wildenstein's meth-
method for separating alkaline earths	od), 505
from the alkalies and magnesium,	barium chromate-iodine-thiosul-
60	phate method of Hinman, 506
for determining lead, 274	benzidine hydrochloride method,
for det. strontium, 491	507
Sulphates in gypsum, 108c, 1188	evolution method for S in iron
soluble in blanc fixe, 1189	and steel, 500, 502
in soap, 1606	iron ore briquettes, sodium
in sublimed white lead, 1180 in water, 1427	sulphide, 403
Sulphates and sulphides in presence of	estimation, special procedures:
one another, determination of, 511	availablo, in brimstone, 519 determination of sulphur in alloys,
determination of, in presence of other	1075, 1087, 1107
sulphur acids, 514	in ash of rubber, 1591
Sulphide, detection of, 493	in black powder and explosives,
determination of tin as, 529, 532	1373, 1377, 1389
in composite white paint, 1186	in eoal, 495, 1619, 1646
ores, evaluation of, by combustion	in copper, 204
method, 504	in ferberite, wolframite, schoelite,
solubility, 495	564
Sulphide stains for det. sulphur, 520	in ferro-tungsten and metal, 572
Sulphido and sulphate det. in presence of	in fucl oils, 1112
each other, 511 Sulphide and sulphohydrate in presence	in gas, 1260 in grain alcohol, 1747
of one another, determination of,	in iron and steel, 269, 1366, 1368
510	in materials high in sulphide sul-
Sulphide ores, decomposition of, 19, 35,	phur, determining available
57, 105, 178, 247, 272, 445, 495,	H ₂ S, 509
498	in mechanical ruhber goods, 1569,
Sulphido sulphur, dct. of traces, 520	1585, 1588–1591
Sulphites, iodine titration of, 512	in a mixture, 517
detection of, 493	in oils, 1130
Sulphites in presence of other sulphur	in oils and liquid fuels, 1112
acids, determination of, 514	in Portland cement, 1208
solubility, 495	in refined sulphurs, 519
sulphurous acid test for vanadium, 583	in rocks, silicates, insoluble sul-
Sulphocyanate (thiocyanate), 181, 184,	phates, 495
261	in rubber, 1569, 1585, 1588–1589
Sulphocyanate calorimetric method for	in spent oxide, 518
iron, 261	in sublimed blue lead, 1194
Sulphohydrate in presence of sulphide,	in steel, 269
det. of, 510	in thiocyanic acid and its salts,
Sulphur, amorphous det. of, 519a Sulphur chloride in rubber, 1571	511
Sulphur chloride in rubber, 1571 Sulphur dioxide, traces in atmosphere,	in ultramarine blue, 1193
1283	residual, in spent oxide, 519 Sulphur, refined analysis of 510
1800	Sulphur, refined analysis of, 519

· ·	•
Sulphur dioxide test for molybdenum, 313 in zinc lead and leaded zinc, 1182	Tables, Acids, qualitative separations, 530, 546-553
method for determining selenium, 435 tellurium, 437	acetic acid (Oudemans'), Table XII, 674, 1548
reduction of vanadium to V ₂ O ₄ , 588	melting-points of (Rudorff)
test for titanium, 538 Sulphurie acid, analysis of, 1524, 1528.	Table XIII, 674 hydrochloric acid (Ferguson), Table V, 660, 661, 1504
1783 arsenous acid in, 35	(Lunge and Marchlewski), 662
combined, in silicate of soda, 438 gases, 1264	eonstant boiling-points of, 662 nitric acid (Ferguson), Table VII,
free, det. of, 507 mercury method for disting. copper	663, 664, 1517 nitric acid (Lunge and Rey), Table
compds., 211	VIII, 665, 666 phosphorie acid (Hager), Table IX,
mist in gases, det., 1763 normal solution of, 1168, 1491	667, 1517
Sulphuric acid in aluminium salts, 12 in ammoniacal liquor, 345	sulphuric acid (Ferguson and Tal- bot), Table X, 668-671, 1534-
in arsenous acid, 53 in acetic acid, 1545	1539 (Bishop), Table XI, 672, 1051
in hydroehloric acid, 1501	approximate boiling-points, 669
in hydrofluorie acid, 1508 in nitric acid, 1510	charts of sp. gr. and b. p., 1524
(anhydride) in oleum and mixed acids, 1530	alcoholic sp. gr., 1748-1752 alkalies:
in paint pigments, 1180, 1184, 1188, 1189, 1190, 1194, 1195, 1196	aqua ammonia (Ferguson), Table XIV, 675, 1559
in rubber, 1569, 1585, 1588–1591 in standard solution, preparation of,	coefficient of expansion, 675 sodium hydroxido (Lunge), Table
1494-1495	XV, 676, 1558
for Devarda's alloy, 346 specific gravity table, 1534	alloys, list of, 1037–1039 atomic weights. See front cover of
strength for equilibrium with atmos- pheric moisture, 1494	book. Baumé degrees and specific gravity comparison, Table XX, 701
test for oils, 11123 test for selenium, 430	comparison, Table XX, 701 bituminous substances, 1290–1292, 1294
Sulphuric acid method for Si in steel, 1368b	buoyancy constants, 1692 Centigrade and Fahrenheit degrees.
Sulphurous acid m. for det. copper compds., 208	Centigrade and Fahrenheit degrees, comparison, Table XIX, 700 compounds, inorganic, useful data
free or combined, in sulphites, acid	(Meiklejohn), Table XVII, 679-
sulphites, metabisulphites and thiosulphates, determination of,	conversion factors (Scott and Meikle-
gravimetric, 511 free or combined in sulphites, acid	john), Table XVIII, 683-698 density of water, 1693
sulphites, metabisulphites and thiosulphates, volumetric meth-	Clectromotive arrangement of elements, Table IV, 659
od with iodine, 512	Engler, Redwood, and Saybolt times, comparison table, 1151
free or combined in sulphites, acid sulphites, metabisulphites and	fatty acids, characteristics of, 1147
thiosulphates, acidimetric and alkalimetric methods, 513	fluorine chart, apparent per cent TiO ₂ and grams F., 221
in acetic acid, 1547 in hydrofluoric acid, 1508	gases, aqueous vapor in air, 1280 chimney or flue, table of calculation,
reduction of ferrie solution, 252	1254 detection of, property tables, 1234
of chlorate, 152 Sumae extract. See Tannic Acid.	efficiency and loss chart, 1194 specific heat of, 1280
Sunflower oil constants, 1147, 1149, 1172 Surveillance test of powder, 1406	sulphur dioxide, iodine values for, in Reich method, 1265, 1266
Sutton, permanganate titration of cal-	table of constants, 704, 705
eium oxalate, 108	hardness in water, 1439

Laures, near or compounds, Tar. See Bituminous Substances, 1289 719 Tartar emetic, antimony in, 33 heat of fusion of elements and com-Tartaric acid, Goldenberg's method for, pounds, 721 1551 indicators and their uses, 1491 Oulman's method for, 1550 Thomson's table, 1492 oxidation of, in titanium determina-tion, 542 Jackson's candle turbidimeter, 1620 logarithms and antilogarithms, 713-716 Tellurium, detection, general procedure, melting-points of the elements, Table II. 658 430 test for, in complex mixtures, 431 metric and customary units, 702 estimation, 437 minerals, list of common, 717 oil, characteristics of, 1552 gravimetric, determination as dioxide, 437 permanent standards, ammonia hydrazine hydrochloride SO: methwater, 1414 od, 437 qualitative tests, 525-653 reduction with sulphur dioxide, 438 rare earth elements, 133 volumetric method, 427, 440d separation of Pt group elements, 387b occurrence, 421, 434 special procedures, 440 silver, tables of wts., U.S. Mint, 461-462 specifications for elements in steel: separations (see Selenium), 432 carbon in steel, 265 and sclenium, determination of, in copper, 440a, 440c manganese in steel, 267 phosphorus in steel, 268 in fluc dust, 440a silicon in steel, 270 in lead slimes, 440a apparatus for separation of (Fig. 57), sulphur in steel, 269 temperature, standards of 432 ment, 658, 659 from color of heated metal, 659 Tellurium and selenium in refineries, 439 Temperature determination of flue gas, of flames, 658 1253 constants, 659 estimation of, by color of heated metal, turbidimeter sulphur table, 1620 659 vapor tension of water in min. Hg at Temperature of flames, 658 — C. (Regnault, Broch and Weibe), Table XVI, 678 Tension strength of cement, test for, 1212 Terminal case (Fig. 27), electrolytic determination of corper, 185
Test lead method for reducing ferricwater, density of, 1693 water, weight of, 1694 water, outline of procedure for analysis, salts, 251, 253 Test paper for antimony stains, 30 Tetrabromide in rubber analysis, 1568 standards of purity table of Illinois State Geological Survey, 1420 Tetryl, analysis of, 1394 Thallium detection and determination, waxes, characteristics of, 1150 weights and measures, comparison of metric with customary units, Table 140b-141 Thallium protoxide test for platinum, 377 Thermometer, uniting thread in, 1645 XXI, 702 Thiocyanato pption. of chlorine, 149 pption. of copper, 181, 183 (Volhard) for silver, 456 Talbot's method for separating tungsten from tin and antimony, 558 Tallow, constants of, 1147, 1149 Tannates and tannic acid, analysis of, 1760 method for determining iron, 261 Thiocyanic acid, sulphur in, 511 Tannin in Al(OH), precipitation, 1773 Thiosulphate of sodium, N/10 solution of, Tantaliferous minerals, 575 opening up of, 576

Tantalum, detection of, 575 determination of, in presence of sulestimation, method for determining, 575 phide and sulphohydrate, 510 occurrence, ores and minerals, 575 detection of, 493 preparation and solution of the sample, gravimetric method for, 511 method for separating Th, 523a 576 tantaliferous minerals, 576 precipitation of Cu in steel, 1368c separation, isolation of tantalum oxide, reagent for iodine number in oils, 1128 solubility, 495 removal of antimony and tin, tungvolumetric iodine method for, 512, 742 standard solution, 742, 1167 sten and silica, 577 solubilities, 576 Thomas electric gas meter, 1235

Thomson, boric acid in milk, 83	Titaniferous ores, analysis of, determi-
method for iron, 258	nation of titanium, aluminum, iron,
Thomson's table of indicators, 1491	silica, phosphorus, 551, 553
Thornton and Chapman on iron det., 258	slags, decomposition of, 540
Thoria, sep. from other rare earths, 134	Titanium Alloy Manufacturing Company,
	methods of, 542, 547-550, 551
Cerium in, 138 Therita decomposition of 522	Titanium, detection of, 538
Thorite, decomposition of, 522	
Thorium, detection of, 522	application and occurrence, 538
estimation, gravimetric method, 524	estimation, general procedures:
minute amounts of, 524	gravimetric, Gooch-Thornton meth-
preparation and solution of the sample,	od, modified, 542
monazite, thorianite, gas mantle	ferro-carbon titaninm, 543
residues, 522a-522b	volumetrie, by reduction and direct
separations, pyrophosphate and thio-	titration with ferric salt, 544
sulphate methods, 523, 523b	by zinc reduction, addition of
Thresh's method for bismuth, 78	excess ferrie salt and titration
Thymol method for titanium, 550	with permanganate, 544a
Tln, detection of, 525	hydrogen peroxide colorimetric
	method, 545
estimation, general procedures:	
gravimetric, by electrolytic method,	estimation, special procedures:
536	in alloys, 1096, 1103
by hydrolysis and ignition to oxide,	in banxite, 17g
528	in steel treated with ferro-carbon, 547
as sulphide, 529	hydrochloric acid-insoluble titanium,
volumetric, iodine method of Lens-	549
sen, modified by Baker, 532	-soluble titanium, 548
iodine method for, 536a	occurrence, ores and minerals, 538
estimations, special procedures:	preparation and solution of the sample,
determination of, in alloys, brass and	alloys, element, ores, oxides, salts,
bronze, 536a, 832	steel, titaniferous slags, 538-539
in alloys, general, 1054, 1059, 1060,	separation from alkaline earths, 541
1072, 1077, 1079, 1105	from aluminum, iron, copper, 541
in highlarida of tin 530	
in biehloride of tin, 530	from bivalent metals, cobalt, nickel,
in bronze, A. S. T. M., 1043	inanganese, zinc, 541
in canned food products, 536	standard thymol solution, 478
in canned goods, 537	Titanium pigments, analysis of, 553
in gun metal, A. S. T. M., 1059	Titanous salt in det. iron, 258
in metallie lead, 288	Titanox, analysis of, 1190, 1192
in niekel, 336e	Titer test for oils, 1142
in soft solder, 1047	standard solution of, 551
in tungsten ores and concentrates,	test for soap, 1603
566	Titration of acids and alkalies, 1497
in type metal, 1046	TNT. See Trinitrotoluene, 1391
in water, 1437	Tolerances in weights, 1698
preparation of the sample, opening up	Topf method for MnO ₂ , 290d
tin ores, 525	Traces. See under estimation of element
cynnide process, 526	in question.
hydrogen reduction, 527	aluminum, detection of, with alizarine
Sellers apparatus for detection, 535	8, 3
sodium carbonate methods, 527	determination of, with alizarine S, 14
hydroxide method, 527	anmonia, 345, 1412
peroxide method, 527	antimony, detection of, 18
separation, general procedure, 527	determination of, 28
from aluminum, antimony, 528	arsenic, detection of, 34
in water, 1433	determination of, in acids, sulphuric,
from antimony in alloys, 1092	hydrochloric, nitrie, phosphoric,
from arsenic, 39	in alumina and iron ores, phos-
from arsenie in alloys, 1044	phates, salts, baking powder,
from copper, lead, 527	canned goods, meat, etc., 45, 52
from phosphorus, tungstic acid, 548	barium, detection by flame and spec-
standard solution of, 533	trum, 56
Time required in gas analysis, 1251	beryllium, 68
-	•

	· ·
Traces, bismuth, colorimetric procedures	Traces, silicon, detection of, 441
for estimation of, 77, 78	silver, detection of, 451
boron, tests for, 79	determination of small amounts, 463
calcium, detection by flame and spec-	sodium, detection of, 401
trum, 100, 104	strontium, detection of, 489
carbon, colorimetric estimation of, 128	determination of small amounts, evo-
cerium, and the other rare carths.	lution method, 500
detection of, 133	sulphur, combined and free, detection
chlorine, detection of, 142	of, 493
chromium, detection of, 156	tantalum and columbium, detection of,
determination of, 162	575
cobalt, detection, 168	tellurium, detection of, 431
determination by nitroso-beta-naph-	thallium, detection of, 140h
thol, 169	thorium, detection of, 522
columbium. See Tantalum.	tin, detection of, 525, 1433
copper, detection of, 177	determination of, in canned food prod-
determination in small amounts, 197	uets, 536
in water, 1433	titanium, detection of, 538
fluorine, detection of, 212, 213	colorimetric method, 545, 547, 550
estimation of, 227	tungsten, detection of, 554
glucinum, detection of, 68	uranium, detection of, 578
gold, detection of, 228	vanadium, detection of, 583
determination of small amounts, 232	determination of small amounts, 591,
indium, 139	595
iodine, detection of, 236	zinc, detection of, 597
iron, detection of, 246	determination of small amounts, 607
determination of small amounts, 261,	zirconium, detection of, 618
262	Treadwell and Hall, see page references
lead, detection of, 271, 1433	Transition temperatures, 1480
determination of small amounts, gra-	Trinitrotoluene, examination of, 1391
vimetrie, 279	Trisulphide of antimony, determination
eolorimetrie, 281	of antimony as, 23
lithium, detection of, 403	arsenic, determination of arsenic as, 40
magnesium, detection of, 291	Trogg and Lenher, precautions on silica
manganese, detection of, 295	determination, 447
determination of small amounts, 305 mercury, detection of, 308	True silica, estimation of, 446 Tung oil (Chinese wood oil), examination
	of, 1169–1170
molybdenim, detection of, 313 nickel, detection of, 329	A. S. T. M. specifications, 1170
determination of small amounts, 332,	Tungstate method for calcium, 108d
333	Tungsten, detection of, in alloys and steel,
nitrogen, ammonia, Nessler's test for,	554
337	in minerals, 554
determination. See Ammonia under	estimation, gravinietrie, 558
Traces.	isolation of, by cinchonine method, 561
nitric acid, detection, 337	aqua regia method of Watts, 564
determination of small amounts,	volumetric method, 564
1512	estimation, special procedures, 558
nitrous acid, test for, 337	tungsten bronzes, 557
estimation of, 1516	occurrence, ores and minerals, 555
phosphorus, detection of, 362	ores and concentrates, 561
platinum, detection of, 376	analysis of, 561
platinum metals, detection of iridium	impurities in, 563
388	arsenic in, 566
osmium, 396	copper in, 567
palladium, 382	manganese in, 570
rhodium, 393	phosphorus in, 565
ruthenium, 390b	sulphur in, 565
potassium, detection of, 401	tin in, 567
rubidium, detection of, 403	powder, typical analysis of, 555
selenium, detection of, 431	preparation and solution of the sample,
scandium, detection of, 140	555

Tungsten alloys, steel minorals, ferro-	U. S. Bureau of Standards
tungsten, tungsten bronzes, 555-557	Government specifications for petro-
reagent cinchonine, 561	leum products, 1150-1151
separation from antimony, tin, 556	Mint method for silver, 458
from arsenic and phosphorus, 556	Vacuum oven, 1020
from iron, titanium, vanadium, 556	Valenta test of oils, 1134
from molybdenum by Hommell's and	Valuation of aluminum ores, 4
Pechard's methods, 558, 559	of fluorspar, 215, 222
from silica, tin, 557	Vamari-Mitscherlich-Devarda method for
solubilities of acids and oxides, 555	nitrogen in soils, 350
steel and alloys, tungsten in, 336e, 558	Vanadium, detection, test with ammonium
	sulphide, hydrogen sulphide, hydro-
technical uses of, 555	
Tungstic acid, det. of tungsten as, 561	gen peroxide, reducing agents, 583 -chromium in ferro-vanadium, 1681
Turbidimetric sulphur table, 1620–1621 Turbidity tests of water, 540	comparison of chromium and vanadium
Turmeric indicator, 745	salts, 583
	test for, in steel, 584
test for bismuth, 81 Turpentine, analysis of, determination of	estimation, general procedures:
	gravimetric, lead acetate method, 588
color, specific gravity, refractive in-	
dex; distillation, polymerization,	mercurous nitrate method, 587
standards of, 1172	volumetric, H ₂ O or SO ₂ reduction to
Tyndall test for dust in gas (modified by	V ₂ O ₄ , and titration with KMnO ₄ , 589
Scott), 1763 Turce's apparentus for solubility det 1470	
Tyror's apparatus for solubility dct., 1479	ether extraction method for, 596c
Illeimate standards, 1400	phosphomolybdate method for,
Ultimate standards, 1493	596b
Ultramarine blue, analysis of, 1196	zinc reduction to V ₂ O ₂ and titra-
Units—metric and customary—tables of,	tion with KMnO ₄ , 590
702	estimation, special methods:
Universal viscosimeter, 1115	determination of vanadium in pres-
Unsaponifiable matter in linseed oil, 1165	ence of antimony or arsenie, 592
in oil, identification of, 1133, 1169	in cupro-vanadium, brasses and
in rubber, 1593	bronzes, 596a
in soap, 1602	in ferro-vanadium, 596
oils, detection and determination of,	in mine and mill products, 596a
1132 Transium detection of 579	in ores, 596a in presence of chromic acid, 593
Uranium, detection of, 578	in presence of iron, 592
uranous and uranyl salts, 578	in presence of molybdenum, 591
estimation, gravimetric method as oxide,	
· U ₂ O ₃ , 581	in steel in presence or absence of
in carnotite, 582	chromium, 591, 595 in presence of chromium, 596
in ferro-uranium, 582a	
in iron and steel, 582a	electrometric method, 1079
volumetric method, 581	in vanadium ores, 595, 596 industrial application, 584
occurrence, 578 preparation and solution of the sample,	occurrence, minerals and ores, 584
ores, 579	Vanier absorption bulb, 112 Vanino and Treubert, reduction of bis-
separation from H ₂ S group elements, copper, bismuth, lead, arsenic,	muth salt, 76
antimony, 579	Van Nostrand Chem. Annual, Olsen, 104,
from iron and metals having water-	109, 143, 246, 291, 308
insoluble carbonates, 579	Vapor tension of sulphuric acid, 1494
from vanadium, 579, 580	Varnish, analysis of, determination of
solubilities, 579	acid number, ash, fixed oils and res-
uranous salts, detection of, 578	ins, flash point, separation of poly-
uranyl salts, detection of, 578	merized oils and resins, 1173, 1176
uses, 578	Varnishes in bituminous substances, 1346
Uranium oxide, purity test of, 581	Varrentrapp and Will bulbs (Fig. 117)
Urbasch's hydrogen sulphide generator, 42	1237
Useful data—inorganic compounds, table	Vegetable oils (see Oils, Fats, Waxes), 1123
XVII, 679	or animal oils, test for, 1134
memoranda 767	detection of management in 205

Vehicles, paint analysis, 1162	Water analysis, general considerations, 1409
liquid percentage of, 1162	mineral analysis, 1421
separation of components, 1163	abstract of general scheme of
Velocity det. of gas flow, 707, 1235	analysis, 1421
Vermilion, analysis of, 1195	acidity, dotermination of, 1429
Veronal, det., 1732	alkalinity, determination of, 1429
Vicat needle for testing cement, 1207	alumina, determination of, 1422
Victor Meyer app. for solubility det.,	 ammonia, determination of, 1431
1474	bromine in, 83
	calcium, determination of, 1424
preparation and solution of the sample:	calcium culphate determination of
decomposition of alloys, iron and	calcium sulphate, determination of,
steel, 586	1441
ores, general procedure, ores high in	earbonic acid, determination of,
silica, ores low in silica, 585	1429
separation from arsenie, molybdenum,	chlorine, determination of, 1433
phosphoric acid, 586	combinations, hypothetical, 1441c
chromium, 587	corrosion, acid waters, determi-
solubilities, clement, oxides and salts,	nation of, 1441b
585	field assay, 1441d
Villavecchia test for oil, 1144b	foaming and priming, 1441b
Virgini, arsenie determination, 41	hardness in, 1438
Viscosity of bituminous substances, 1297	hydrogen ion concentration, det. of,
in centipoises of sugar tables, 1117	1430, 1457
in oils, determination of, 1114, 1156	hydrogen sulphide in, 1435
Viscosimeters for determining viscosity in	
oils 1114 1115	iodide or iodine in, 238
oils, 1114, 1115	iron, determination of, 1423
Vogel's modification of Pisani's method	
for silver, 463	irrigating waters, 1441c
Volatile combustible matter in coal, ap-	lead, zinc, copper and tin, det. of, in,
paratus for, (104), 1618	1437
method for det. in coal, 1618	lime value of, 1441
hydrocarbons in soap, 1608	lithium det. in, 1428
matter in sodium fluoride, 224	magnesium in, 1425
in paint, distillation of, 1163	ehloride, 1440
sulphur in coal, 1619	manganese, bismuthate method of
Volhard's method for determining bro-	determining, 1426
mine, 95	Knorre's persulphate method,
chlorine, 149	1426
copper, 196	mineral residue in water, 1434
eyanide, 130	nitrates, determination of 1433
iodine, 243	oil, determination of, 1435
manganese, 302	oxygen dissolved, determination of,
nilston ASS	1436
silver, 456	phosphates, determination of, 1424
Volt, definition of, 709	preparation of solutions, 1439
Volumes, formulæ for determining, 703,	residue, total mineral, determina-
707	tion of, 1431
unit table of, 702	seale, determination of, 1441b
Volumetric apparatus, calibration of, 1685	
Volumetric methods. See under element	silica, determination of, 1422
in question.	soda, value for, 1441
Vortmann and Metzel method for deter-	sodium and potassium, determina-
mining antimony, 23	tion of, 1427 softening of, 1441b
Vulcanization, coefficient of, 1575, 1576	softening of, 1441b
	sulphates, determination as barium
Wagner's solution, 106	sulphate, by benzidine method,
Walton and Jud, app. for det. solubility,	1427
1474	traces of impurities, copper, lead,
Warrington, traces of lead, 281	tin and zine, 1433
Warwick and Kyle on oxalate method for	sanitary analysis, 1410, 1442
bismuth, 78	ammonia, albuminoid in, 1413
Washing soda, analysis of, 1555	free, determination of, 1412
Waste and reclaim in rubber, 1570	chemical tests, 1412
TIRRU BULL TOURNER IN THOUGH, AUTO	·

	*
Water, chlorine determination in (present	Welsbach mantles, cerium determination
as chloride), 1417 color test, 1410	in, 138 West hal halange spatter hit out, 1908
interpretation of analysis, 1419	Westphal halance, sp. gr. bit. sub., 1295 sp. gr. of oils, nethod for, 1111
nitrogen as nitrate, 1415	Wet combustion process for carbon deter-
as nitrite, 1414	mination, 120
organic, 1413 odor test, 1412	gold assay of minerals, 230 Wet meter, 1234
oxygen consumed, 1417	tests for copper, 177
physical tests, 1410	Whale oil, constants, 1147, 1149
residue, total solids in, 1418 turbidity test, 1410	Whitby's method for silver detection and
Water, sanitary microscopical examina-	estimation, 452 White lead, corroded, analysis of, 278h,
tion of, 1442–1453	1181
control of organisms, 1451	sublimed, analysis of, 1177
organisms in (sanitary exam.), 1447 organisms in (sanitary exam.), 1443,	White metals, analysis of, 1047–1048 whiting paint pigment, analysis of, 1176
1448	Whitmer and Cain's method for vanadium
identification of, 1449	in steel, 591
Sedgwick-Rafter method, 1445 Weter hesteriological examination 1454	Wiborg's method for determining carbon
Water, bacteriological examination, 1454- 1468	(reference), 127 Wildenstein's volumetric method for sul-
apparatus and materials for exam., 1455	phur, 505
azolitmin solution, 1458	Wilkie, colorimetric method for traces of
bacteria, total in, 1461 brilliant-green lactose-peptone bile, 1460	lead, 281 Williams - Ford, method for manganese,
B. coli, examination of, 1462	306
B. typhi, examination of, 1467	Wilson, L. A., on cadmium det. and
subclassification of, 1463	analy., 99
Endo's medium, 1459 Hesse agar, 1460	on zinc analy., 597 Wilson, N. F., Jr., on heat of combustion,
litmus-lactose agar, 1459	719
nutrient agar, 1458	Winkler, titration of ammonia in borie
nutrient hroth, 1457 preparation of culture media, 1456	acid, 340 Winkler's spiral absorption apparatus for
routine procedure, 1465	gas (Fig. 118), 1237
Russell's media, 1460, 1468	gas (Fig. 118), 1237 Winterstein and Herzfeld, iodine libera-
sampling for examination, 1444, 1454	tion with peroxide, 243 Withcrite, analysis of, 66
sterilization of, 1457 Widal test for B. typhi, 1467	commercial valuation of, 66
Water, direct determination of, 1770	Wolff's absorption tube (Fig. 118), 1237
determination in oils, 1131, 1132d	Wolff's method for rosin in soap, 1602
Water in burning oils, 1113, 1131 in paint vehicles, 1163	Wood alcohol (methyl alcohol), 1753
percentage required in standard sand	Wurster's method for ozone, 1241
mortar (table), 1201	Wulfenite, molybdenum det. in, 322
vapor in air, 1280 Water gas, composition and analysis,	Xenon in the atmospheric air, 338
1229d	renon in the atmospheric air, 656
Watt, definition of, 709	Yatsevitch's reagent for etching, 1705
Watt's method for tungsten, 564	Yellow pigments, analysis of, 1177, 1198
Waxes, 1148 analysis of, 1148	Ytterbium, 133, 135, 137
analysis of, 1148 Weber and Hintz on sulphur precipita-	Ytterbium group, 137
tion, 497	The detection of FOR
Weighing tubes for acids (Figs. 80, 81, 82, 83), 1498, 1500	Zinc, detection of, 597 estimation, general procedure, 597
Weights, standardization of, 1695	gravimetric determination by elec-
Weiss, separating zinc as sulphide, 605	trolysis, 599
Welch-Weber method for detecting tin, 525	as the oxide, ZnO, 17c, 599 as the sulphate, ZnSO ₄ , 592
Weller's determination of antimony, 27	rapid method, 606a
• • • • • • • • • • • • • • • • • • • •	

IND	EX 55
Zinc, volumetric methods, ferrocyanide titration: in acid solution, 600, 603 in alkaline solution, 601 estimation, special procedures: determination in ulloys, in brass and bronze, 1063, 1085, 1094, 1106e in copper (metallie), 203 in lead (metallie), 209 in lead (metallie), 290a, 617a in soft solder, 1048 in sulphuric acid, 1527 in water, 1437 in zinc metal, A. S. T. M., 1103 in zinc dust, 607 determination in composite white paint, 1190 in nickel, 336f in orange and yellow pigments, 1198 in white lead (sublimed), 1179 determination in material containing	Zinc metal, preparation of pure, for arsenie determination, 48 metallie, test for iridinm, 382 for palladium, 383 for platinum, 377 for rhodium, 393 for ruthenium, 390b for titanium, 538 for vanadium, 463, 583 Zinc arsenite, determination of arsenic, soluble and insoluble in, 36 Zinc lead and leaded zinc, analysis of, 1182 oxide, determination of zinc as, 590 impurities in, 610, 1183 in the commercial product, 1186 reduction method for determining iridium, 383 of chlorates, 152 of iron salts, 252 of phosphoroglybelate for phosphorus
eadmium, 602 in material containing insoluble zine, 605 in presence of carbonaceous matter, 602 in presence of metallics, 602 determination in ores copper-bear ing, 601 in water, 1433, 1434 in zine dust, 607 moisture determination in pulp, 598 preparation of the sample, 598 separation from antimony, arsenie, bismuth, cadmium, copper, lend, 598 from aluminum, iron, manganese, cobalt and nickel, 598–599 from irou, 1048 sulphide precipitation of zine, 603–605 Zine spelter, determination of impurities in, 610 cadmium in, electrolytic and sulphide methods, 612 iron in, hydrogen sulphide and colorimetric methods, 611 lead in, electrolytic and lead acid methods, 610–611 "traces," determination of small amounts of zine, 607	of phosphomolyldate for phosphorus determination, 368b of vamadium sults, 590 sulphate in zinc lead and leaded zinc, 1183 in lithopone, 1186 weighing zinc as, 599 sulphide in lithopone, 1186 Ziuc chloride, analysis of, 614-616 fused analysis of, 617 Zinc oxide method for Zn, 17c Zirconium, detection of, 618 estimation, gravimetric precipitating as hydroxide, 622 as oxide in presence of iron oxide, 622b as phosphate, 622a occurrence, 618 precipitation with selenious acid, 622a preparation of sample, 619 preparation and solution of the sample, materials high in silica, 619 mineral oxides, 619 separation from cerium and the iron groups, 621 from iron, titunium, and thorium, 621, 622

